

# **FY 2015 – 2019 FIVE-YEAR CAPITAL PLAN**

## **FINAL REPORT**

**SEPTEMBER 2019**



**Bill de Blasio  
Mayor**





# Table of Contents

<b>EXECUTIVE SUMMARY</b>	<b>5</b>
<b>Background</b>	<b>7</b>
<b>Introduction</b>	<b>7</b>
<b>CAPACITY</b>	<b>11</b>
Capacity	13
<b>Introduction</b>	<b>13</b>
<b>New Capacity Program</b>	<b>13</b>
<b>Early Education Initiatives: Pre-K and 3-K for All</b>	<b>18</b>
<b>Class Size Reduction Program</b>	<b>18</b>
<b>Facility Replacement Program</b>	<b>19</b>
<b>CAPITAL INVESTMENT</b>	<b>21</b>
Capital Investment	23
Introduction	23
Capital Improvement Program	23
Exteriors	24
Interiors	25
School Enhancement Projects	29
<b>Technology Enhancements</b>	<b>29</b>
<b>Facility Enhancements</b>	<b>31</b>
Facility Restructuring	32
Safety and Security	33
Science Lab Upgrades	34
Accessibility	34
Physical Fitness Upgrades	34
Library Upgrades	35
Auditorium Upgrades	35
<b>Mandated Programs</b>	<b>39</b>
Introduction	39
Asbestos Abatement	40
Lead Paint Abatement	41
Emergency Lighting	41
Code Compliance	42
Building Condition Surveys	42
Wrap-Up Insurance	42
Prior Plan Completion Cost	43
Emergency, Unspecified & Miscellaneous	43
<b>FINANCING STRATEGY</b>	<b>45</b>
<b>Capital Plan Funding</b>	<b>47</b>
<b>APPENDICES TABLE OF CONTENTS</b>	<b>49</b>



# EXECUTIVE SUMMARY

---



## Background

The New York City School Construction Authority (SCA) and the New York City Department of Education's (DOE) Five-Year Capital Plan for Fiscal Years 2015–2019, approved by the City Council in June 2014, became effective for the Fiscal Year that began on July 1, 2014.

Annual amendments were issued and then adopted by the City Council in June of each year. Each annual amendment incorporated additional funding from City Council and Borough Presidents and included recognition of new Mayoral Initiatives as well as added funding for existing programs.

Also through our annual amendment process, Community Education Councils (CECs) played an important part in the development of the Capital Plan. Beginning in the 2005–2006 school year, the DOE established a process by which CECs could provide input on specific school conditions. This input has become a vital part in developing and amending the Capital Plan, and as a result of CEC and City Council input, capital projects were reviewed and incorporated into the FY2015-2019 Capital Plan and its amendments. We appreciate the participation of our Councils and the enormous effort expended throughout the process.

## Introduction

The SCA and DOE are pleased to release the Final Report to the FY2015–2019 Five Year Capital Plan. This Plan, which ended on June 30, 2019, totaled \$15.9 billion and made great strides in reducing overcrowding through new capacity and successfully improved the quality of our existing facilities. Along with new Mayoral initiatives and generous support from the City Council and Borough Presidents, The FY2015-2019 Plan continued our advancement in providing state of the art learning facilities for New York City's more than one million school children.

This Capital Plan outlined an aggressive program of new capacity to target overcrowding in districts across the city. Through our Capacity Program, 24,789 seats were constructed or are currently in process. Of the almost 25,000 seats, more than 21,600 will serve our elementary and middle school students, and more than 3,100 seats were created for high school students throughout the five boroughs.

Access to early education seats and the reduction of overcrowded classrooms, continue to be, key priorities for the current Administration. The inclusion of targeted funds in the Capital Plan for class size reduction and the pre-Kindergarten (Pre-K) and 3-K for All initiatives collectively supported these efforts. In 2014, Pre-K for All was launched and in 2017, 3-K for All was launched and at the end of this Plan, over 10,000 Pre-K and 3-K seats were created through these Initiatives for our youngest students.

Improvement projects in our existing buildings touched upon the major components to our learning environments, including exterior work to secure watertight conditions of our roofs, parapets and masonry, internet-protocol digital video surveillance systems (IPDVS) installations

to ensure safety, low-voltage electrical systems such as fire alarms and public address systems, enhancements to common areas such as auditoriums and gymnasiums and significant investments towards enhancing instructional technology in our schools.

In April 2017, Mayor de Blasio announced that the City would fund air conditioning (A/C) for every classroom in New York City by 2022. The FY15-19 Five-Year Capital Plan included \$76 million in order to provide the needed electrical infrastructure upgrades at certain buildings to support the installation of air conditioners. The general scope of work may include installation/replacement of switchboards, electrical panels, receptacles, grounding work, additional electrical service, and the distribution of the electrical service. Additional capital funding by the City has been provided for Fiscal Years 2020 and 2021 to complete the Mayor's initiative by 2021, a year ahead of schedule.

In June 2017, Mayor de Blasio announced a Universal Physical Education initiative to ensure all students have access to indoor space for physical education. In this first phase of the initiative, the SCA explored options to construct new gymnasiums, enhance playgrounds, or convert existing space for schools that did not currently have sufficient access to indoor physical education space. As a result of this analysis, 19 schools will receive a new standalone gym annex funded in this Capital Plan, as well as two schools that will receive upgraded outdoor playground facilities, and three schools that will have interior spaces modified to allow for improved physical education instruction and functionality. These 24 projects have been awarded and are currently in construction. Additional funding is allocated in the FY20-24 Five Year Capital Plan for the remaining sites identified as a part of Phase 1.

The DOE/SCA continued its commitment to remove Transportable Classroom Units (TCUs) across the City. Through allocation of TCU removal and capacity funding, this Plan achieved the removal of 205 TCUs and identified removal plans for an additional 75 units.

This Final Report, which will outline the investments and accomplishment over the last five years, maintains the same format as the February 2018 Adopted Amendment and is divided into three main categories: Capacity, Capital Investment, and Mandated Programs.

- **\$4.9 billion for Capacity.** The Capacity Program includes four elements:
  - **\$3.6 billion for New Capacity** — funded 24,789 new seats in 50 projects. The New Capacity funding in this Plan helped to alleviate existing overcrowding, respond to ongoing pockets of growth in certain neighborhoods, and support our goal to remove all TCUs. In addition, the SCA secured opportunities to include new public school facilities across the City within several major, predominantly residential development projects undertaken by private developers in areas of existing or projected overcrowding.
  - **\$849 million for Early Education Initiatives** — funded a robust and comprehensive approach to increase early education capacity including Pre-K for four-year-old children and 3-K for three-year-olds. In addition to expanding the pre-kindergarten capacity within new buildings, these funds



also focused on identifying new locations that created over 10,000 Pre-K and 3-K seats.

- **\$192 million for Class Size Reduction** — provided additional resources to areas without seats funded through the New Capacity Program. This funding allowed us to make a significant investment to further fulfill the commitment to reduce class size system-wide.
- **\$282 million for Facility Replacement Program** — funded the development of seats for schools that were relocated during this Plan whether it was from an expired, non-renewable lease or in other instances, facilitated the relocation of students from sites that were no longer appropriate. Funds in this category covered the costs to construct a new building or to build a new leased location for the students.
- **\$7.8 billion for Capital Investment.** The Capital Investment portion of this Plan is comprised of three categories:
  - **\$5.4 billion for the Capital Improvement Program (CIP)** — included exterior and interior building upgrades and other necessary capital repairs to our buildings.
  - **\$1.6 billion for School Enhancement Projects** — provided enhanced educational opportunities for our children. This category includes funding to support technology and existing school facility upgrades and enhancements. Also included in this category are some targeted investment areas including, but not limited to, the Physical Education initiative, the Air Conditioning Initiative, bathroom upgrades, science labs, and accessibility projects.
  - The FY15-19 Plan also included \$812 million allocated by through the City Council and Borough Presidents and we thank our partners in government for their continued support of our schools.
- **\$3.2 billion for Mandated Programs.** This program provided funding to meet requirements of local law, City agency mandates and other required elements such as remediation and building code compliance projects, insurance, and emergencies. Under this program, all remaining light fixtures containing polychlorinated biphenyls (PCBs) in school buildings were replaced well ahead of schedule at the end of December 2016, rather than the original target of 2021. In addition, funding was allocated to continue boiler conversions as required by the NYC Department of Environmental Protection's (DEP) regulation to phase out the use of Number 4 oil by 2030. The phase out of Number 6 oil was completed in 2015.



# CAPACITY

---



# Capacity

## Introduction

SUMMARY
Final Report
<b>\$4,914.1 mm</b>
2018 Adopted Amendment
\$6,446.5 mm

The **Capacity Category** encompasses all aspects of creating new seats necessary to provide for the expansion of our system. This new capacity provided the infrastructure necessary to continue advancing our goals of growth, sustainability, equity, and resilience. By building new capacity, the City will meet local enrollment demands, strategically grow facilities to meet future demand, and eliminate our reliance on temporary facilities.

As part of the Capacity Category, the DOE/SCA dedicated \$849 million, specifically for the support and development of early childhood education seats under the Pre-K for All and 3-K for All Initiatives. These initiatives supported capital investment for the creation of new seats for three and four-year old children and helped close the access gap to early education programs in neighborhoods throughout the city.

In addition to anticipating future needs, another aspect of the capacity program is to reduce current overcrowding. To achieve this goal, the DOE/SCA invested \$192 million in the Class Size Reduction Program.

Finally, the DOE/SCA funded \$282 million towards the development of seats for schools that were relocated during this Plan whether it was from an expired, non-renewable lease or in other instances, facilitated the relocation of students from sites that were no longer appropriate. Funds in the Facility Replacements Program covered the costs to construct a new building or to build a new leased location for the students.

## New Capacity Program


SUMMARY
Final Report
<b>\$3,591.2 mm</b>
2018 Adopted Amendment
\$4,797.5 mm

This Plan devoted \$3.6 billion to New Capacity projects. Through this program, 24,789 new seats were created. Funding also facilitated the continued removal of TCUs which will continue into the next Plan.

The FY15-19 Plan created new seats in every borough. This includes projects for PS, PS/IS, IS or HS school buildings: three in Manhattan, five in the Bronx, 14 in Brooklyn, 24 in Queens, and four in Staten Island.

## New Capacity Program Overview

The following chart provides the latest information on the completion schedule for the almost 25,000 seats that have been created through this Capital Plan.



The following chart lists seats completed or in process by district and sub-district:

<b>District</b>	<b>Sub-District</b>	<b>Number of Seats Completed or In Process</b>
<b>2</b>	Tribeca / Village	1,016
<b>3</b>	Upper West Side	692
<b>5</b>	West Harlem	245
<b>8</b>	Throgs Neck	344
<b>10</b>	Kingsbridge / Norwood / Bedford Park	796
	University Heights	388
<b>11</b>	Van Nest / Pelham Parkway	548
<b>13</b>	DUMBO/ Navy Yard / Fort Greene	333
<b>15</b>	Sunset Park	997
	Park Slope	782
	Carroll Gardens / Gowanus / Red Hook	436
<b>19</b>	Cypress Hills / East New York	1,000
<b>20</b>	Owls Head Park / Bay Ridge	976
	Dyker Heights	364
<b>21</b>	Gravesend	924
<b>22</b>	Mill Basin	416
<b>24</b>	North Corona / South Corona / Lefrak City / Elmhurst	2,477
	Maspeth / South of Woodside	728
	Middle Village	773
<b>25</b>	Beechhurst / College Point / Whitestone	548
	Flushing / Murray Hill / Willets Point	600
<b>26</b>	Bayside / Auburndale	760
<b>27</b>	Howard Beach / Lindenwood	516
	Ozone Park / South Ozone Park / Richmond Hill / Woodhaven	124
<b>28</b>	Rego Park / Forest Hills / Kew Gardens / Jamaica	1,716
<b>30</b>	East Elmhurst / Jackson Heights	476
	Woodside / Sunnyside	725
	Long Island City / Ravenswood	612
<b>31</b>	North Shore	1,306
<b>Queens High School</b>		<b>2,826</b>
<b>Staten Island High School</b>		<b>345</b>
<b>Total</b>		<b>24,789</b>

### New Capacity Summary by Borough

DISTRICT	SMALL PS			PS/IS			IS/HS			TOTAL		
	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST
<b>MANHATTAN</b>												
1	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
2	0	0	\$0.00	1	1,016	\$131.18	0	0	\$0.00	1	1,016	\$131.18
3	0	0	\$0.00	1	692	\$99.49	0	0	\$0.00	1	692	\$99.49
4	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
5	1	245	\$12.20	0	0	\$0.00	0	0	\$0.00	1	245	\$12.20
6	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
<b>MANHATTAN TOTAL</b>	<b>1</b>	<b>245</b>	<b>\$12.20</b>	<b>2</b>	<b>1,708</b>	<b>\$230.67</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>	<b>3</b>	<b>1,953</b>	<b>\$242.87</b>
<b>BRONX</b>												
7	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
8	1	344	\$63.92	0	0	\$0.00	0	0	\$0.00	1	344	\$63.92
9	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
10	3	1,184	\$199.63	0	0	\$0.00	0	0	\$0.00	3	1,184	\$199.63
11	1	548	\$64.26	0	0	\$0.00	0	0	\$0.00	1	548	\$64.26
12	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
HS	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
<b>BRONX TOTAL</b>	<b>5</b>	<b>2,076</b>	<b>\$327.81</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>	<b>5</b>	<b>2,076</b>	<b>\$327.81</b>
<b>BROOKLYN</b>												
13	0	0	\$0.00	1	333	\$34.63	0	0	\$0.00	1	333	\$34.63
14	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
15	6	1,837	\$345.53	1	378	\$22.24	0	0	\$0.00	7	2,215	\$367.77
16	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
17	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
18	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
19	0	0	\$0.00	1	1,000	\$105.64	0	0	\$0.00	1	1,000	\$105.64
20	2	1,340	\$185.36	0	0	\$0.00	0	0	\$0.00	2	1,340	\$185.36
21	2	924	\$133.68	0	0	\$0.00	0	0	\$0.00	2	924	\$133.68
22	1	416	\$49.48	0	0	\$0.00	0	0	\$0.00	1	416	\$49.48
23	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
32	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
HS	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
<b>BROOKLYN TOTAL</b>	<b>11</b>	<b>4,517</b>	<b>\$714.05</b>	<b>3</b>	<b>1,711</b>	<b>\$162.51</b>	<b>0</b>	<b>0</b>	<b>\$0.00</b>	<b>14</b>	<b>6,228</b>	<b>\$876.56</b>



**New Capacity Summary by Borough (cont.)**

DISTRICT	SMALL PS			PS/IS			IS/HS			TOTAL		
	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST
<b>QUEENS</b>												
24	5	2,604	\$285.28	2	1,374	\$193.50	0	0	\$0.00	7	3,978	\$478.78
25	2	1,148	\$151.08	0	0	\$0.00	0	0	\$0.00	2	1,148	\$151.08
26	2	760	\$100.45	0	0	\$0.00	0	0	\$0.00	2	760	\$100.45
27	2	640	\$129.23	0	0	\$0.00	0	0	\$0.00	2	640	\$129.23
28	4	1,716	\$227.02	0	0	\$0.00	0	0	\$0.00	4	1,716	\$227.02
29	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
30	2	1,088	\$155.69	1	725	\$89.15	0	0	\$0.00	3	1,813	\$244.84
HS	0	0	\$0.00	0	0	\$0.00	4	2,826	\$219.87	4	2,826	\$219.87
<b>QUEENS TOTAL</b>	<b>17</b>	<b>7,956</b>	<b>\$1,048.75</b>	<b>3</b>	<b>2,099</b>	<b>\$282.65</b>	<b>4</b>	<b>2,826</b>	<b>\$219.87</b>	<b>24</b>	<b>12,881</b>	<b>\$1,551.27</b>
<b>STATEN ISLAND</b>												
31	2	997	\$129.73	1	309	\$14.85	0	0	\$0.00	3	1,306	\$144.58
HS	0	0	\$0.00	0	0	\$0.00	1	345	\$93.42	1	345	\$93.42
<b>STATEN ISLAND TOTAL</b>	<b>2</b>	<b>997</b>	<b>\$129.73</b>	<b>1</b>	<b>309</b>	<b>\$14.85</b>	<b>1</b>	<b>345</b>	<b>\$93.42</b>	<b>4</b>	<b>1,651</b>	<b>\$238.00</b>
<b>CITYWIDE TOTAL</b>	<b>36</b>	<b>15,791</b>	<b>\$2,232.54</b>	<b>9</b>	<b>5,827</b>	<b>\$690.68</b>	<b>5</b>	<b>3,171</b>	<b>\$313.29</b>	<b>50</b>	<b>24,789</b>	<b>\$3,236.51</b>
<b>OTHER SITE ACQUISITION COSTS *</b>											<b>\$183.42</b>	
<b>GRAND TOTAL INCLUDING SITE ACQUISITION</b>											<b>\$3,419.93</b>	

\* Refers to site acquisition costs for Pre-K, 3K and capacity projects to be constructed in the FY2020-2024 Capital Plan.

Notes: All dollar amounts represented in millions.

Excludes \$171.27 mm for obligations for capacity projects to be constructed in the FY2020-2024 Capital Plan.

## Early Education Initiatives: Pre-K and 3-K for All

<b>SUMMARY</b>
Final Report
<b>\$849.3 mm</b>
2018 Adopted Amendment
\$872.0 mm

The Capital Plan recognized the commitment and desire to implement a universal early childhood education program for three- and four-year-old children. The DOE/SCA has identified the major expansion and enhancement to the existing pre-Kindergarten program as a critical objective. In order to support this goal, the Pre-K for All and 3-K for All Initiatives addressed the capital investments needed citywide to increase the number of seats for full-day, early childhood education.

The Pre-K and 3-K for All Initiatives provided for the creation of seats in every borough, opening high-quality opportunities, and closing the access gap for neighborhoods throughout the City. The list of these early childhood education centers can be found in the appendices.

## Class Size Reduction Program

<b>SUMMARY</b>
Final Report
<b>\$192.1 mm</b>
2018 Adopted Amendment
\$490.0 mm

The Class Size Reduction Program recognizes the need for targeted investments to build additions or new buildings near schools that would significantly benefit from additional capacity. The \$192.1 million spent in the FY15-19 Plan continues the City's significant investment and commitment to reducing class size system-wide.

A multi-disciplinary group comprised of representatives from the Office of Space Management, the Office of Student Enrollment, the Division of Operations, and the School Construction Authority discussed and evaluated school buildings that would benefit most from funding in this category. Some of the criteria considered included:

1. High rate of overutilization per enrollment and capacity figures established by the latest Enrollment, Capacity, and Utilization Report
2. Unfunded seat need in the sub-district where school building is located
3. Use of Transportable Classroom Units
4. Geographic isolation

The list of Class Size Reduction projects can be found in the appendices.

# Facility Replacement Program

<b>SUMMARY</b>
Final Report
<b>\$281.5 mm</b>
2018 Adopted Amendment
\$287.0 mm

The Facility Replacement Program allocated \$281.5 million to provide for the development of seats for schools were relocated usually due to an unrenovable expiring lease. In these instances, or when it is determined that a site with an expiring lease is in unsatisfactory condition, we pursued a replacement site. The replacement site could be either another lease or a newly constructed building.



# CAPITAL INVESTMENT

---



# Capital Investment

## Introduction

---

<b>SUMMARY</b>
Final Report
<b>\$7,786.7 mm</b>
2018 Adopted Amendment
\$6,623.6 mm

The Capital Investment Category includes three elements: the Capital Improvement Program (CIP), School Enhancement Projects, and projects funded by the City Council and Borough Presidents. The CIP projects consisted of a wide range of construction projects, including building repairs, system replacements, and reconfiguration of existing school buildings. School Enhancement Projects provide upgrades to existing facilities to support modern instructional models.

This Final Report summarizes the \$7.8 billion for Capital Investment made in the FY2015-2019 Five-Year Capital Plan for existing buildings.

Any potentially dangerous building condition was referred to the SCA for further evaluation. If necessary, sidewalk bridging was installed as a safeguard and if immediate action was required, capital funding from the Plan's Emergency, Unspecified category was used to remedy the condition.

## Capital Improvement Program

<b>SUMMARY</b>
Final Report
<b>\$5,390.1 mm</b>
2018 Adopted Amendment
\$3,781.2 mm

Efforts to improve the quality of school buildings have been effective under this Capital Plan, but the size and age of our inventory drives the continuing need to invest primarily in exterior building elements. This Plan emphasized exterior projects that safeguarded existing buildings from water infiltration and, because of the size and age of our inventory, this effort will continue in future capital plans.

The FY2015-2109 Capital Plan allocated \$5.4 billion for CIP projects. This funding allowed us to address the most critical building systems with elements rated a "5" (poor) by the Building Condition Assessment Survey (BCAS). In addition, a number of building elements that were rated "3" (fair) or "4" (fair to poor), but had deficiencies that may impact safety or the structure of the building, were included. In addition to addressing deficiencies in our existing buildings, CIP funding supported the removal of TCUs as well as athletic field upgrades.

Capital Improvement Program Overview		
Program	Final Report	2018 Adopted Amendment
Exterior	\$4,214.4 mm	\$2,706.1 mm
Interior	\$820.4 mm	\$765.1 mm
Other	\$111.0 mm	\$77.2 mm
TCU Removal and Playground Redevelopment	\$117.5 mm	\$395.0 mm
Athletic Field Upgrades	\$126.8 mm	\$125.0 mm
<b>TOTAL</b>	<b>\$5,390.1 mm</b>	<b>\$4,068.4 mm</b>

## Exteriors

SUMMARY
Final Report
<b>\$4,214.4 mm</b>
2018 Adopted Amendment
\$2,706.1 mm

Water infiltration is the single greatest cause of accelerated deterioration of existing facilities which is why the Plan focused on making school buildings watertight. The costs stemming from water infiltration include measures to correct damage to interior walls, floors and ceilings, and related asbestos and lead abatement.

The major components of building exteriors are roofs, parapets, windows, and masonry. If the BCAS ratings for any school indicated that any of these four major components were below “fair to poor” condition, then all the major exterior components rated “3” or worse were included in the project.

The funding allocated for exterior components is summarized below:

Exteriors Overview		
Program	Final Report	2018 Adopted Amendment
Flood Elimination	\$490.0 mm	\$370.9 mm
Reinforcing Support Elements	\$39.1mm	\$25.3 mm
Reinforcing Cinder Concrete Slabs	\$19.3 mm	\$17.4 mm
Roofs	\$904.7 mm	\$496.2 mm
Parapets	\$718.8 mm	\$459.4 mm
Exterior Masonry	\$1,653.2 mm	\$1,081.4 mm
Windows	\$389.3 mm	\$255.5 mm
<b>TOTAL</b>	<b>\$4,214.4 mm</b>	<b>\$2,706.1 mm</b>



## Interiors

<b>SUMMARY</b>
Final Report
<b>\$820.4 mm</b>
2018 Adopted Amendment
\$765.1 mm

The Five-Year Plan for interiors included capital work identified by a building's BCAS and work required to fulfill educational needs.

Components of the interior program included electrical upgrades, plumbing, low-voltage electrical systems, and mechanical systems that were replaced rather than repaired based on age, condition and future ability to maintain. Funding was dedicated to replace antiquated fire alarms, install building-wide public address systems, upgrade school kitchens, and install new elevators.

The major interior systems addressed in this plan are summarized below:

<b>Interiors Overview</b>		
<b>Program</b>	<b>Final Report</b>	<b>2018 Adopted Amendment</b>
Climate Control (excludes Mandated Program)	\$43.1 mm	\$58.0 mm
Boiler Conversions (excludes Mandated Program)	\$28.7 mm	\$31.1 mm
Low-Voltage Electrical System	\$181.9 mm	\$158.5 mm
Lighting Fixtures (excludes Mandated Program)	\$37.4 mm	\$41.5 mm
Interior Spaces	\$65.2 mm	\$56.0 mm
Air Conditioning Retrofit	\$4.7 mm	\$4.2 mm
Elevators & Escalators	\$43.4 mm	\$15.9 mm
Floors	\$4.2 mm	\$7.2 mm
Electrical Systems (excludes AC Initiative)	\$44.5 mm	\$52.3 mm
Heating Plant Upgrade	\$268.3 mm	\$276.5 mm
Domestic Piping (excludes Mandated Program)	\$65.3 mm	\$56.7 mm
Kitchen Areas	\$23.4 mm	\$0.0 mm
Safety Systems	\$10.3 mm	\$7.2 mm
<b>TOTAL</b>	<b>\$820.4 mm</b>	<b>\$765.1 mm</b>

## Transportable Classroom Unit Removal/ Playground Redevelopment

<b>SUMMARY</b>
Final Report
<b>\$117.5 mm</b>
2018 Adopted Amendment
\$395.0 mm

The DOE/SCA continued its commitment to remove TCUs across the City by allocating \$118 million in this category.

This funding, coupled with several new capacity projects, allowed for the removal of 205 TCUs and identification of removal plans for 75 additional units.

## TCUs Removed

DISTRICT	BUILDING NAME	NO OF TCUS
3	P.S. 163 TRANSPORTABLE - M	2
6	P.S. 48 TRANSPORTABLE - MANHATTAN	2
6	P.S. 5 TRANSPORTABLE - M	2
8	ADLAI E. STEVENSON HS TRANSPORTABLE - X	2
8	P.S. 14 TRANSPORTABLE - X	2
9	I.S. 117 TRANSPORTABLE - X	1
9	P.S. 28 TRANSPORTABLE - X	1
10	I.S. 80/P.S. 280 TRANSPORTABLE - X	4
10	J.F. KENNEDY HS TRANSPORTABLE - X	2
11	P.S. 106 TRANSPORTABLE - X	5
11	P.S. 96 TRANSPORTABLE - X	11
11	P.S. 97 TRANSPORTABLE - X	4
12	P.S. 6 TRANSPORTABLE - X	6
15	P.S. 32 TRANSPORTABLE - K	7
18	P.S. 135 TRANSPORTABLE - K	2
18	P.S. 208 TRANSPORTABLE - K	4
18	P.S. 219 TRANSPORTABLE - K	1
18	P.S. 235 TRANSPORTABLE - K	2
18	P.S. 235 TRANSPORTABLE - K	2
18	P.S. 268 TRANSPORTABLE - K	1
18	P.S. 272 TRANSPORTABLE - K	3
18	P.S. 276 TRANSPORTABLE - K	8
19	EAST NY FAMILY ACADEMY TRANSPORTABLE - K	6
19	I.S. 302 TRANSPORTABLE - K	3
19	P.S. 214 TRANSPORTABLE - K	7
19	P.S. 290 TRANSPORTABLE - K	1
20	P.S. 112 TRANSPORTABLE - K	1
20	P.S. 170 TRANSPORTABLE - K	2
21	P.S. 97 TRANSPORTABLE - K	2
22	P.S. 152 TRANSPORTABLE - K	2
22	P.S. 193 TRANSPORTABLE - K	2
22	P.S. 194 TRANSPORTABLE - K	1
22	P.S. 198 TRANSPORTABLE - K	2
22	P.S. 236 TRANSPORTABLE - K	2
24	I.S. 125 TRANSPORTABLE - Q	4
24	P.S. 143 TRANSPORTABLE - Q	3
24	P.S. 19 TRANSPORTABLE - Q	5
24	P.S. 81 TRANSPORTABLE - Q	3
25	JOHN BOWNE HS TRANSPORTABLE - Q	1
25	P.S. 129 TRANSPORTABLE - Q	2
25	P.S. 163 TRANSPORTABLE - Q	2
25	P.S. 24 TRANSPORTABLE - Q	2
26	B. N. CARDOZO HS TRANSPORTABLE - Q	2
26	BAYSIDE HS TRANSPORTABLE - QUEENS	2

TCUs Removed (cont.)

DISTRICT	BUILDING NAME	NO OF TCUS
27	I.S. 226 TRANSPORTABLE - Q	1
27	JOHN ADAMS HS TRANSPORTABLE-Q	5
27	P.S. 155 TRANSPORTABLE - Q	2
27	RICHMOND HILL HS TRANSPORTABLE - Q	11
28	P.S. 121 TRANSPORTABLE - Q	1
28	P.S. 140 TRANSPORTABLE - Q	4
28	P.S. 40 TRANSPORTABLE - Q	3
28	P.S. 55 TRANSPORTABLE - Q	3
29	P.S. 131 TRANSPORTABLE - Q	3
29	P.S. 132 TRANSPORTABLE - Q	2
29	P.S. 156 TRANSPORTABLE - Q	2
29	P.S. 176 TRANSPORTABLE - Q	2
29	P.S. 33 TRANSPORTABLE - Q	1
29	P.S. 35 TRANSPORTABLE - Q	2
29	P.S. 38 TRANSPORTABLE - Q	3
29	P.S. 52 TRANSPORTABLE - Q	1
30	P.S. 11 TRANSPORTABLE - Q	4
30	P.S. 151 TRANSPORTABLE - Q	11
30	P.S. 70 TRANSPORTABLE - Q	2
30	P.S. 92 TRANSPORTABLE - Q	2
30	WILLIAM BRYANT HS TRANSPORTABLE-Q	3
31	CURTIS HS TRANSPORTABLE - S.I.	2
31	P.S. 37 TRANSPORTABLE - S.I.	2
31	PORT RICHMOND HS TRANSPORTABLE - S.I.	2
TOTAL # OF UNITS REMOVED		205

## TCUs with Removal Plan Identified

DISTRICT	BUILDING NAME	NO OF TCUS
7	SOUTH BRONX HS TRANSPORTABLE - X	2
7	CROTONA ACADEMY TRANSPORTABLE - X	8
8	JANE ADDAMS HS TRANSPORTABLE - X	3
8	P.S. 119 TRANSPORTABLE - X	2
8	P.S. 71 TRANSPORTABLE - X	2
11	P.S. 16 TRANSPORTABLE1 - X	2
11	P.S. 16 TRANSPORTABLE2 - X	2
11	P.S. 87 TRANSPORTABLE - X	4
12	P.S. 67 TRANSPORTABLE - X	2
19	P.S. 7 TRANSPORTABLE - K	3
19	P.S. 159 TRANSPORTABLE - K	2
19	P.S. 202 TRANSPORTABLE - K	4
25	P.S. 79 TRANSPORTABLE - Q	2
25	P.S. 193 TRANSPORTABLE - Q	1
25	P.S. 22 TRANSPORTABLE - Q	1
26	P.S. 41 TRANSPORTABLE - Q	2
26	FRANCIS LEWIS HS TRANSPORTABLE - Q	4
26	B. N. CARDOZO HS TRANSPORTABLE - Q	2
27	P.S. 43 TRANSPORTABLE - Q	5
27	P.S. 56 TRANSPORTABLE - Q	1
27	P.S. 66 TRANSPORTABLE - Q	1
27	P.S. 146 TRANSPORTABLE - Q	1
28	AUX. SERV.- JAM. LEARN CT TR - Q	1
28	P.S. 30 TRANSPORTABLE - Q	2
28	P.S. 144 TRANSPORTABLE - Q	1
28	P.S. 206 TRANSPORTABLE - Q	2
11	P.S. 108 TRANSPORTABLE - X	4
30	P.S. 85 TRANSPORTABLE - Q	4
30	PRE-K CENTER @ 5-14/16 49TH AVENUE - Q	1
31	P.S. 25 TRANSPORTABLE - S.I.	2
31	P.S. 37 TRANSPORTABLE - S.I.	2
TOTAL # OF UNITS IN PROCESS OF BEING REMOVED		75
TOTAL # OF UNITS REMOVED AND IN PROCESS		280

## Athletic Field Upgrades

SUMMARY
Final Report
<b>\$126.8 mm</b>
2018 Adopted Amendment
\$125.0 mm

The DOE/SCA expanded the physical fitness opportunities for our school children by undertaking a new initiative to upgrade existing athletic fields. The DOE/SCA evaluated the condition of all existing athletic fields and dedicated \$126.8 million in this category which funded the renovation of several athletic fields.

## School Enhancement Projects

<b>SUMMARY</b>
Final Report
<b>\$1,583.9 mm</b>
2018 Adopted Amendment
\$1,628.8 mm

Technology and Facility Enhancement Programs were included under School Enhancement Projects in this Plan.

<b>School Enhancement Projects</b>		
<b>Program</b>	<b>Final Report</b>	<b>2018 Adopted Amendment</b>
Technology	\$557.2 mm	\$654.4 mm
Facility Enhancements	\$1,026.7 mm	\$974.4 mm
<b>TOTAL</b>	<b>\$1,583.9 mm</b>	<b>\$1,628.8 mm</b>

## Technology Enhancements

<b>SUMMARY</b>
Final Report
<b>\$557.2 mm</b>
2018 Adopted Amendment
\$654.4 mm

The FY 2015–2019 Capital Plan supported the NYCDOE’s initiative to increase bandwidth connectivity to all school buildings. All school buildings received a minimum of 100Mbps data circuit that will increase the capacity of each classroom ability to support ever-more widespread and intensive use of web-enabled devices to access a range of digital learning tools. This aligns with the new generally accepted standard from the New York State Education Department (NYSED) and Federal Communications Commission in E-Rate Modernization Order is 100 Mbps per 1,000 students. It also meets Chancellor Richard A. Carranza’s goal of Equity, Excellence for All which entails making information equally, and easily accessible to all students, parents and teachers as long as they possess a device connected to the Internet.

With today’s instructional classrooms extending far beyond the physical school, and exists in the form of virtual schools and online and blended learning, it is essential that networks are reliable. In addition, computer based testing, the proliferation of mobile devices, and one-to-one computer-student ratio are all instructional initiatives that will require a growth in the existing network to support them.

Upgrading the infrastructure to support these tools align with the goals of the Smart Schools Bond Act (SSBA) which provide learning opportunities beyond the classroom through technology and address the educational needs of all students, including students with disabilities, English Language Learners, and those who have not succeeded in traditional classroom settings. These new learning technologies place demands on the network infrastructure that have never existed before.

The demand for fast and reliable connectivity has also increased as slow, manual instructional and administrative processes are being automated into robust application services to gain efficiencies, reduce administrative burden, and free up more “face time” for teachers with their students. Because of this effort to bring advanced connectivity to the DOE's community of users in a school setting, the Classroom Connectivity initiative is also enhancing the telecommunication capabilities of its administrative users.

Upgrades of the Wireless/Wide and Local Area Network (W/LAN) enable higher connection speeds with intensive concurrent users in the schools. The new high-speed digital links turned modern classroom into an always connected learning atmosphere. The core network infrastructure is one that is resilient, scalable, robust, and effectively supports the digital educational goals of today and of the future.

Connected schools offer more innovative, digital content that can provide a more engaging learning experience and improve test score outcomes. Supporting digital learning and teaching initiatives require that our school buildings have the ability to accommodate the ancillary devices and components that allow students and educators to connect to the Internet or servers where digital resources reside.

Through planned building electrical upgrades, we are able to increase the electrical capacity necessary to power the digital learning environment.

In addition, this Plan also invested in various business-oriented initiatives that strengthened the DOE's ability to deliver and support school level operations. The initiatives included the expansion of the student enrollment system to include Pre-K students and the expansion of the digital timekeeping system to include school-based personnel.

Technological Enhancements Summary		
Enhancement	Final Report	2018 Adopted Amendment
Next Generation Voice and Data Upgrade	\$141.9mm	\$246.9mm
Next Generation Access Points Upgrade	\$266.8mm	\$101.8mm
Next Generation School Data Wiring Upgrades		\$46.8mm
School Electrification Upgrades	\$10.0mm	\$64.6mm
Ancillary Technology Facilities Upgrade	\$0.0mm	\$44.5mm
Non-Infrastructure Projects	\$135.7mm	\$145.4mm
Technology – SESIS	\$2.8mm	\$4.4mm
<b>TOTAL</b>	<b>\$557.2mm</b>	<b>\$654.4mm</b>

## Facility Enhancements

SUMMARY
Final Report
<b>\$1,026.7 mm</b>
2018 Adopted Amendment
\$974.4 mm

The Facilities Enhancement Program funded facility adjustments that enable changes to instructional spaces. This program complements new capacity investment by ensuring that space already in service is aligned with the goals of meeting demand, improving learning conditions, using resources efficiently, and improving student achievement.

In addition, this program enhances safety and security systems, expands the functional accessibility of facilities, and upgrade science, library, auditorium, bathroom, and physical fitness facilities.

Facility Enhancements Overview		
Program	Final Report	2018 Adopted Amendment
Facility Restructuring	\$368.3 mm	\$388.1 mm
Air Conditioning Initiative	\$75.7 mm	\$50.0 mm
Physical Education Initiative	\$169.0 mm	\$0.0 mm
Safety & Security	\$81.6 mm	\$100.0 mm
Science Lab Upgrades	\$52.0 mm	\$50.0 mm
Accessibility	\$121.0 mm	\$127.6 mm
Physical Fitness Upgrades	\$31.9 mm	\$29.9 mm
Library Upgrades	\$3.5 mm	\$2.6 mm
Auditorium Upgrades	\$20.4 mm	\$20.7 mm
Bathroom Upgrades	\$103.3 mm	\$100.0 mm
<b>TOTAL</b>	<b>\$1,026.7 mm</b>	<b>\$974.4 mm</b>

## ***Facility Restructuring***

---

<b>SUMMARY</b>
Final Report
<b>\$368.3 mm</b>
2018 Adopted Amendment
\$388.1 mm

In this Capital Plan, the restructuring of existing buildings included:

- Creation of appropriate science lab facilities in buildings with middle and high school students where possible
- Creation and expansion of school based health centers
- Electrical upgrades to traditionally under-enrolled buildings seeing large increases in utilization rates that tax their electrical systems
- Conversion of defunct shops/extra-large classrooms to create more capacity
- A program to renovate cafeterias to support the Office of School Food & Nutrition Services mission to promote healthy and attractive food choices to students while serving students more quickly and efficiently

## ***Air Conditioning Initiative***

---

<b>SUMMARY</b>
Final Report
<b>\$75.7 mm</b>
2018 Adopted Amendment
\$50.0 mm

In April 2017, Mayor de Blasio announced that the City would fund air conditioning for every classroom in New York City by 2022. This Plan included \$76 million in order to provide the needed electrical infrastructure upgrades at certain buildings to support the installation of air conditioners. The general scope of work may include installation/replacement of switchboards, electrical panels, receptacles, grounding work, additional electrical service, and the distribution of the electrical service. Additional capital funding by the City has been provided for Fiscal Years 2020 and 2021 to complete the Mayor's initiative by 2021, a year ahead of schedule.

## ***Universal Physical Education Initiative***

---

<b>SUMMARY</b>
Final Report
<b>\$169.0 mm</b>
2018 Adopted Amendment
\$105.5 mm

In June 2017, Mayor de Blasio announced a Universal Physical Education initiative to ensure all students have access to indoor space for physical education. In this first phase of the initiative, the SCA explored options to construct new gymnasiums, enhance playgrounds, or convert existing space for schools that did not currently have sufficient access to indoor physical education space. As a result, 19 schools will receive a new standalone gym annex funded in this Capital Plan, as well as two schools that will receive upgraded outdoor playground facilities, and three schools that will have interior spaces modified to allow for improved physical education instruction and functionality.



## Safety and Security

---

SUMMARY
Final Report
<b>\$81.6 mm</b>
2018 Adopted Amendment
\$100.0 mm

The DOE, in partnership with the New York City Police Department (NYPD) and the Mayor’s Office of the Criminal Justice Coordinator (CJC), has implemented a comprehensive strategy to promote and sustain a climate of safety in all New York City public schools. A key component of this strategy is to equip schools with state-of-the-art security technology. Enhancements have been implemented through the FY 2005–2009, FY 2010–2014, and FY 2015-2019 Plans in the areas of network-based video surveillance, ID-card access control, radio communications, and metal detection.

The FY2015–2019 Plan focused on continued capital investment in digital video surveillance systems. Upon completion of the Plan in June 2019, Internet Protocol Digital Video Surveillance (IPDVS) had been successfully implemented in 735 buildings serving 1,157 schools with a total of 30,624 cameras online. The IPDVS application allows authorized school officials to view live and archived camera images directly on their computer stations and provides remote viewing capability to authorized personnel from borough and central offices.

During the Plan period, the SCA has undertaken a complete technical refresh of 140 IPDVS systems that have been in use for more than ten years and thus have reached the end of their useful lives. The complete technical refresh upgrade projects have included replacement of all of the existing analog cameras with megapixel digital cameras that provide much greater image quality than cameras installed in earlier years, replacement of the servers and main viewing stations, and a software upgrade. These projects also have included changes to the number and/or placement of cameras to increase surveillance coverage. Whenever feasible, existing cabling and conduits have been re-utilized. In addition, over 220 sites with IPDVS that have been in use for 8-10 years have received a limited upgrade to improve system performance including lifecycle replacement of the video surveillance server(s) and main viewing station, and installation of a software version compatible with current Windows operating systems. The limited upgrades have not included camera replacements or modifications.

The 2015-2019 also included lifecycle replacement of metal detection equipment. The plan provided the NYPD School Safety Division with a total of 144 baggage X-ray machines and 52 walk-through magnetometers to replace antiquated equipment at existing scanning sites.

## ***Science Lab Upgrades***

---

<b>SUMMARY</b>
Final Report
<b>\$52.0 mm</b>
2018 Adopted Amendment
\$50.0 mm

The 2015–19 Capital Plan, continued efforts to provide quality instruction in the sciences so that all middle schools and high schools, where possible, have access to appropriate science facilities.

## ***Accessibility***

---

<b>SUMMARY</b>
Final Report
<b>\$121.0 mm</b>
2018 Adopted Amendment
\$127.6 mm

The DOE strives to offer a physical environment that is accessible for people with mobility impairments or other disabilities. In keeping with prior Plans, the DOE/SCA continued the program to provide additional accessible facilities throughout the City. 22 buildings were addressed under the accessibility program in this Plan.

## ***Physical Fitness Upgrades***

---

<b>SUMMARY</b>
Final Report
<b>\$31.9 mm</b>
2018 Adopted Amendment
\$29.9 mm

The DOE/SCA understands the importance of incorporating physical fitness into the daily routine of school children. As such, this Plan allocated funding to swimming pools and gymnasium upgrades as specified below. Other physical fitness upgrades included TCU Removals/Playground Redevelopment and Athletic Field Upgrades under Capital Improvements.

<b>Physical Education Upgrades Overview</b>		
<b>Program</b>	<b>Final Report</b>	<b>2018 Adopted Amendment</b>
Swimming Pools	\$15.3 mm	\$14.8 mm
Gymnasium Upgrades	\$16.6 mm	\$15.1 mm
<b>TOTAL</b>	<b>\$31.9 mm</b>	<b>\$29.9 mm</b>

## ***Library Upgrades***

---

<b>SUMMARY</b>
Final Report
<b>\$3.5 mm</b>
2018 Adopted Amendment
\$2.6 mm

Library upgrades included work related to refurbishing existing library facilities within schools. School libraries complement New York City public school reforms and provide direct resources to support curriculum, instruction, and specialized efforts geared toward improving student literacy.

## ***Auditorium Upgrades***

---

<b>SUMMARY</b>
Final Report
<b>\$20.4 mm</b>
2018 Adopted Amendment
\$20.6 mm

Auditorium upgrade projects included improvements to stage and auditorium lighting, sound systems, seating, stage curtains, rigging, and the stage. These spaces serve as an important central gathering place for the school and often serve as a vital community resource for the surrounding neighborhood as well. As such, resources identified in this category were applied strategically to ensure the maximum benefit possible.

## ***Bathroom Upgrades***

---

<b>SUMMARY</b>
Final Report
<b>\$103.3 mm</b>
2018 Adopted Amendment
\$100.0 mm

As our large inventory of buildings age, the need to upgrade certain facilities within our buildings becomes more pressing. Bathroom upgrades are frequently requested. Although bathrooms are functional, some may be outdated. Under this Plan, the DOE/SCA continued the program to upgrade student bathrooms.



MANDATED

---



# Mandated Programs

## Introduction

<b>SUMMARY</b>
Final Report
<b>\$3,154.2 mm</b>
2018 Adopted Amendment
\$3,391.7 mm

This category represents a number of items that were previously included in the Capital Investment category such as lighting replacements, boiler conversions, asbestos remediation, lead paint abatement, funding for projects mandated by local law or City agency mandates, performing building condition surveys, emergency lighting, code compliance, and insurance.

<b>Mandated Programs Overview</b>		
<b>Program</b>	<b>Final Report</b>	<b>2018 Adopted Amendment</b>
Lighting Replacements	\$330.0 mm	\$330.0 mm
Boiler Conversions and associated Climate Control	\$715.9 mm	\$750.0 mm
Asbestos Remediation	\$192.4 mm	\$183.8 mm
Lead Paint Removal	\$6.7 mm	\$8.4 mm
Emergency Lighting	\$4.9 mm	\$8.2 mm
Code Compliance	\$45.4 mm	\$77.7 mm
Building Condition Surveys	\$69.6 mm	\$76.3 mm
Wrap-Up Insurance	\$903.4 mm	\$894.7 mm
Prior Plan Completion	\$588.4 mm	\$659.2 mm
DOE Administration	\$25.9 mm	\$0.0 mm
Emergency, Unspecified & Miscellaneous	\$271.6 mm	\$403.4 mm
<b>TOTAL</b>	<b>\$ 3,154.2 mm</b>	<b>\$ 3,391.7 mm</b>

## ***Lighting Replacements***

---

<b>SUMMARY</b>
Final Report
<b>\$330.0 mm</b>
2018 Adopted Amendment
\$330.0 mm

On May 21, 2013, the City entered into an agreement to accelerate the original 10-year plan that started in 2011 to remove all PCB-containing light fixtures by December 31, 2016. This Five-Year Capital Plan allocated \$330 million to remove all PCB-containing light fixtures from New York City public school buildings, which was achieved as of December 2016. Funding was also included to ensure replacement of older High Intensity Discharge (HID) lighting within our buildings.

The list of buildings that had comprehensive lighting replacement projects completed can be found at:

[DOE Buildings with Completed Lighting Replacement Projects](#)

## ***Boiler Conversions***

---

<b>SUMMARY</b>
Final Report
<b>\$715.9 mm</b>
2018 Adopted Amendment
\$750.0 mm

The DOE/SCA will continue to phase out use of Number 4 oil which is mandated to be eliminated by 2030. The DOE/SCA has allocated \$716 million to convert boilers at approximately 95 of 350 buildings using Number 4 oil. Eliminating the use of heavy oils and transitioning to the cleanest fuels will comply with this mandate.

## ***Asbestos Abatement***

---

<b>SUMMARY</b>
Final Report
<b>\$192.4 mm</b>
2018 Adopted Amendment
\$183.8 mm

The DOE's Asbestos Abatement program is federally mandated by the Asbestos Hazard Emergency Response Act (AHERA) of 1986. The Act requires that every public and private school building, Kindergarten–Grade 12, be inspected once every three years, with a semi-annual surveillance. The location of any asbestos must be documented and a plan developed for the continuous management of the asbestos in the building.

Asbestos abatement removes the potential health hazard presented by airborne asbestos fibers. Asbestos is found most commonly in pipe and boiler insulation, plaster, floor tiles, and spray-on insulation. Only asbestos in a loosely bound or “friable” condition is dangerous and must be removed. Asbestos must be removed from construction areas prior to being disturbed during construction or maintenance activities.



The cost of asbestos abatement is included in the individual project costs for building modernizations and individual interior and exterior upgrades where asbestos is present. This funding category provided for abatement of disturbed asbestos in buildings where no related major capital projects were planned.

## ***Lead Paint Abatement***

---

<b>SUMMARY</b>
Final Report
<b>\$6.7 mm</b>
2018 Adopted Amendment
\$8.4 mm

Lead paint abatement is mandated by U.S. Environmental Protection Agency and the New York City Department of Health and Mental Hygiene (DOHMH) regulations. The targeted population for this program includes 3-K, Pre-K, Kindergarten, first grade, daycare in schools and special education. The DOE continues remediating areas identified by lead inspections and DOHMH referrals.

Lead abatement is included as an integral part of individual capital projects that affect surfaces that may contain lead paint, e.g., window replacement and the removal of paint from exterior walls prior to re-pointing. This funding provided for lead paint abatement in buildings where no related major capital projects are planned.

## ***Emergency Lighting***

---

<b>SUMMARY</b>
Final Report
<b>\$4.9 mm</b>
2018 Adopted Amendment
\$8.2 mm

This category funded the DOE's program to bring school buildings into compliance with the emergency lighting requirements of Local Law 41/78 (Fire Safety in Places of Public Assembly), and Local Law 16/84 (Fire Safety in Buildings). These laws established minimum standards for emergency lighting, exit lighting, emergency power and elevator safety and apply retroactively to most school buildings.

## Code Compliance

---

SUMMARY
Final Report
<b>\$45.4 mm</b>
2018 Adopted Amendment
\$77.7 mm

Similar to emergency lighting, this category is an ongoing program to bring all school buildings into compliance with safety-related regulations. Although many DOE schools are old enough to pre-date the New York City Building Code, code requirements relating to life and fire safety systems apply retroactively so buildings that are not in compliance must be retrofitted accordingly. Local Law 10 (Owners' Inspection of Building Facades) and its successor legislation, Local Law 11, require that the exterior masonry for buildings over a certain height be inspected every five years. If hazardous conditions are discovered during an inspection, a sidewalk shed must be installed immediately and plans developed for the necessary repairs.

Local Law 5 (Fire Safety in High Rise Buildings) mandates the installation of fire alarm systems in buildings over a certain height so that the fire department can override the elevators' operations in the event of an emergency. Other Code-related capital-eligible projects were also included in this category.

## Building Condition Surveys

---

SUMMARY
Final Report
<b>\$69.6 mm</b>
2018 Adopted Amendment
\$76.3 mm

Keeping the baseline data of building conditions in school facilities up-to-date is essential to the DOE's ability to program capital improvement projects. This allocation allowed BCAS inspections to be performed on a yearly basis.

## Wrap-Up Insurance

---

SUMMARY
Final Report
<b>\$903.4 mm</b>
2018 Adopted Amendment
\$894.7 mm

Since 1990, the SCA has maintained an Owner Controlled Insurance Program (OCIP) that provides insurance coverage for the SCA, contractors, and subcontractors working on SCA projects. Rather than the traditional approach of having each contractor and subcontractor procure its own insurance, the SCA negotiates and purchases coverage for workers compensation and employers liability, general liability, excess liability, and builder's risk.

## ***Prior Plan Completion Cost***

---

<b>SUMMARY</b>
Final Report
<b>\$588.4 mm</b>
2018 Adopted Amendment
\$659.2 mm

Many projects funded in the last Plan (FY 2010–2014) were still in progress during this Five-Year Plan period, and this category accounts for costs associated with completing those projects.

## ***Emergency, Unspecified & Miscellaneous***

---

<b>SUMMARY</b>
Final Report
<b>\$271.6 mm</b>
2018 Adopted Amendment
\$403.4 mm

This lump sum funding allowed the DOE/SCA to respond to emergencies and unforeseeable needs without having to divert funds from other projects in the borough or district in which the emergencies occurred. By law, funding in this category cannot exceed five percent of the total estimated cost of the Five Year Plan.



# FINANCING STRATEGY

---



## Capital Plan Funding

The FY2015 – 2019 Five-Year Capital Plan was financed by a combination of City, State and Federal funds, inclusive of the New York State Smart Schools Bond Act. To complement Plan funding, both City and State elected officials allocated additional capital funds for specific projects at individual schools. These funds were targeted towards the needs of our schools in areas such as technology, science laboratories, sports/athletic fields, playgrounds, and other quality-of-life facility upgrades/enhancements.

The Plan's total appropriation of \$15.9 billion during its five-year term supported the DOE/SCA's goals of improving educational performance and sustaining its diverse portfolio of existing facilities in good repair. Thirty-one percent is for the creation of 24,789 seats in 50 new facilities, as well as 3-K and pre-Kindergarten centers, seats under the Class Size Reduction and Replacements Programs.

Forty-nine percent of the total funding is targeted toward capital investment in basic facility needs and enhancing school facilities — both system-wide and to support specific instructional programs. These programs include technology improvements, safety enhancements and other general improvements to the learning environments. The remaining twenty percent is dedicated to mandated programs.





## APPENDICES TABLE OF CONTENTS

<b>Plan Summary</b> _____	<b>C-1</b>
<b>Citywide Categories</b> _____	<b>C-5</b>
<b>Capacity Projects</b> _____	<b>C-7</b>
<b>Capacity Program Site Locations</b> _____	<b>C-10</b>
<b>Pre-Kindergarten Projects</b> _____	<b>C-13</b>
<b>Pre-Kindergarten Site Locations</b> _____	<b>C-18</b>
<b>3-K Projects</b> _____	<b>C-21</b>
<b>3-K Site Locations</b> _____	<b>C-22</b>
<b>Class Size Reduction</b> _____	<b>C-23</b>
<b>Class Size Reduction Site Locations</b> _____	<b>C-24</b>
<b>Facility Replacement Program</b> _____	<b>C-25</b>
<b>Facility Replacement Site Locations</b> _____	<b>C-26</b>
<b>Projects Advanced to FY 2014</b> _____	<b>C-27</b>
<b>Added Projects</b> _____	<b>C-31</b>
<b>Cancelled Projects</b> _____	<b>C-170</b>
<b>Borough of Manhattan</b>	
<b>Borough Summary</b> _____	<b>M-1</b>
<b>Capacity Projects</b> _____	<b>M-5</b>
<b>Pre-Kindergarten Projects</b> _____	<b>M-6</b>
<b>Facility Replacement Program</b> _____	<b>M-7</b>
<b>School Based Program</b> _____	<b>M-8</b>
<b>Borough of Bronx</b>	
<b>Borough Summary</b> _____	<b>X-1</b>
<b>Capacity Projects</b> _____	<b>X-5</b>
<b>Pre-Kindergarten Projects</b> _____	<b>X-6</b>
<b>3-K Projects</b> _____	<b>X-7</b>
<b>Class Size Reduction</b> _____	<b>X-8</b>
<b>Facility Replacement Program</b> _____	<b>X-9</b>
<b>School Based Program</b> _____	<b>X-10</b>

**Borough of Brooklyn**

<b>Borough Summary</b> _____	<b>K-1</b>
<b>Capacity Projects</b> _____	<b>K-5</b>
<b>Pre-Kindergarten Projects</b> _____	<b>K-6</b>
<b>3-K Projects</b> _____	<b>K-8</b>
<b>Class Size Reduction</b> _____	<b>K-9</b>
<b>School Based Program</b> _____	<b>K-10</b>

**Borough of Queens**

<b>Borough Summary</b> _____	<b>Q-1</b>
<b>Capacity Projects</b> _____	<b>Q-5</b>
<b>Pre-Kindergarten Projects</b> _____	<b>Q-7</b>
<b>3-K Projects</b> _____	<b>Q-9</b>
<b>Class Size Reduction</b> _____	<b>Q-10</b>
<b>Facility Replacement Program</b> _____	<b>Q-11</b>
<b>School Based Program</b> _____	<b>Q-12</b>

**Borough of Staten Island**

<b>Borough Summary</b> _____	<b>R-1</b>
<b>Capacity Projects</b> _____	<b>R-5</b>
<b>Pre-Kindergarten Projects</b> _____	<b>R-6</b>
<b>3-K Projects</b> _____	<b>R-7</b>
<b>Facility Replacement Program</b> _____	<b>R-8</b>
<b>School Based Program</b> _____	<b>R-9</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.01	0.00	0.00	0.00	0.01
2. Interior Modernizations	0.02	0.00	0.00	0.00	0.00	0.02
3. Exterior Modernizations	0.08	0.03	(0.07)	(0.01)	(0.01)	0.02
C. Building Upgrade						
1. Asbestos	39.77	37.82	36.18	40.32	38.31	192.40
2. Boiler Conversion	75.62	88.65	131.79	123.94	159.14	579.13
3. Climate Control	40.47	22.44	41.28	54.31	50.07	208.58
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	62.03	28.55	24.68	29.45	37.22	181.94
7. Lighting Fixtures	203.92	145.89	13.02	3.13	1.47	367.44
8. Elevators and Escalators	2.71	2.26	0.70	17.27	20.48	43.42
9. Reinforcing Cinder Concrete Slabs	8.21	1.06	5.82	3.21	1.03	19.33
10. Flood Elimination	138.00	44.50	85.49	93.47	128.50	489.95
11. Air Conditioning Retrofit	2.01	0.89	1.13	0.61	0.02	4.66
12. Lead Paint Abatement	1.10	1.19	0.10	1.80	2.50	6.69
13. Reinforcing Support Elements	2.32	6.72	6.87	11.28	11.89	39.08
14. Interior Spaces	27.03	10.53	10.69	13.81	3.15	65.21
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	35.80	32.84	21.96	18.62	17.55	126.77
2. Playground Redevelopment	15.10	16.54	35.64	24.89	25.30	117.47
3. Swimming Pools	0.46	0.30	12.90	0.77	0.87	15.30
E. System Replacements						
1. Roofs	124.80	104.96	134.72	270.18	270.03	904.69
2. Parapets	113.85	98.07	124.74	205.57	176.60	718.83
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	53.59	19.51	65.98	102.31	147.92	389.31
5. Exterior Masonry	216.34	166.00	330.74	502.90	437.17	1,653.15
6. Electrical Systems	31.90	7.35	13.10	15.56	52.25	120.16
7. Heating Plant Upgrade	104.75	34.44	37.18	49.84	42.07	268.28
8. Domestic Piping	22.15	12.05	4.46	26.82	14.00	79.48

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Plan Summary**  
(in millions)

<b>Category</b>	<b>FY15</b>	<b>FY16</b>	<b>FY17</b>	<b>FY18</b>	<b>FY19</b>	<b>Total</b>
9. Toilets - Students	4.97	30.17	7.64	18.05	42.44	103.27
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.98	0.31	1.20	1.40	0.30	4.20
12. Paved Area - Blacktop	5.23	4.60	4.25	1.18	0.67	15.93
13. Paved Area - Concrete	6.28	4.11	7.63	8.11	8.58	34.71
14. Fencing	0.05	0.12	0.06	1.96	0.73	2.92
15. Kitchen Areas	3.10	4.76	6.46	1.74	7.32	23.37
16. Containerization	0.03	0.00	0.00	0.00	1.68	1.72
17. Auditorium Upgrade	5.21	3.25	2.76	6.65	2.52	20.40
18. Gymnasium Upgrade	5.17	2.23	2.17	4.26	2.76	16.59
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.37	0.51	0.18	4.85	13.26	19.16
<b>I. State of Good Repair Yearly Totals:</b>	<b>1,353.41</b>	<b>932.66</b>	<b>1,171.47</b>	<b>1,658.25</b>	<b>1,717.80</b>	
						<b>I. State of Good Repair Total: 6,833.60</b>
<b>II. System Expansion</b>						
<b>A. New Construction-Additional Capacity</b>						
1. New Schools	223.28	162.64	380.42	466.77	443.07	1,676.18
2. Building Additions	39.73	436.35	621.80	289.53	227.02	1,614.43
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	30.68	25.38	27.23	24.37	29.46	137.12
4. Transportables	0.00	(0.00)	0.00	0.00	0.00	(0.00)
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	261.29	284.68	67.87	70.91	13.87	698.61
9. 3-K Initiative	0.00	0.00	0.00	0.33	150.35	150.68
<b>B. New Construction-Common-Facilities-Additions</b>						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	24.03	144.91	168.95
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
<b>C. New Physical Education Facilities</b>						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	1.74	4.01	3.04	8.96	29.27	47.03

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Plan Summary**  
(in millions)

<b>Category</b>	<b>FY15</b>	<b>FY16</b>	<b>FY17</b>	<b>FY18</b>	<b>FY19</b>	<b>Total</b>
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	39.15	(1.87)	59.44	152.34	106.50	355.56
F. Replacements						
1. Replacements - New	3.59	12.06	6.54	76.99	87.33	186.51
2. Replacements - Addition	0.11	6.84	0.49	0.67	32.35	40.46
3. Replacements - Lease	27.36	3.44	16.68	2.33	4.75	54.55
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<b>II. System Expansion Yearly Totals:</b>	<b>626.93</b>	<b>933.53</b>	<b>1,183.51</b>	<b>1,117.22</b>	<b>1,268.89</b>	
						<b>II. System Expansion Total: 5,130.08</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	62.20	11.70	11.70	90.60	381.04	557.24
2. Room Conversions / Partitioning	27.81	78.22	65.34	34.50	37.90	243.77
3. Accessibility	3.20	24.20	43.40	19.14	31.12	121.06
4. School Improvement and Restructuring	18.65	27.91	25.84	21.62	11.39	105.41
5. Science Lab Upgrades	4.95	15.46	13.65	9.04	8.87	51.96
6. Library Upgrade	0.13	0.77	0.89	0.98	0.71	3.47
7. Charter/Innovative Schools	0.00	0.00	0.00	(0.00)	0.00	(0.00)
<b>III. Educational Enhancements Yearly Totals:</b>	<b>116.94</b>	<b>158.26</b>	<b>160.81</b>	<b>175.88</b>	<b>471.02</b>	
						<b>III. Educational Enhancements Total: 1,082.91</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	2.96	0.18	2.69	3.75	0.76	10.33
1a. School Safety	10.35	3.20	9.32	27.04	31.70	81.62
2. Emergency Lighting and Fire Safety Retrofits	1.94	0.47	0.54	0.49	1.43	4.87
3. Code Compliance	1.08	0.95	3.71	11.12	14.30	31.17
<b>IV. Safety and Security Yearly Totals:</b>	<b>16.33</b>	<b>4.80</b>	<b>16.27</b>	<b>42.40</b>	<b>48.19</b>	
						<b>IV. Safety and Security Total: 127.99</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.06	0.06	0.01	4.00	4.58	8.71
<i>V. Ancillary Facilities Yearly Totals:</i>						
	0.06	0.06	0.01	4.00	4.58	
<b>V. Ancillary Facilities Total:</b>						8.71
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	12.01	15.10	13.20	12.90	16.40	69.61
C. DOE Administration						
1. DOE Administration	0.00	9.60	5.50	5.20	5.60	25.90
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	222.77	205.92	148.94	212.71	113.07	903.41
E. Emergency Unspecified						
1. Emergency Unspecified	34.65	43.26	69.22	33.40	26.06	206.59
2. Emergency Stabilization	7.64	14.47	11.11	13.79	18.03	65.04
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	259.46	190.31	104.21	59.10	(24.68)	588.39
G. Resolution A						
1. City Council	87.46	86.09	119.97	133.91	107.42	534.85
2. Borough President	17.58	26.12	56.55	87.63	86.58	274.46
H. Mayor/Council Program						
1. Mayor/Council Program	0.97	1.22	0.26	0.53	0.43	3.42
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>						
	642.55	592.08	528.95	559.17	348.92	
<b>VI. Emergency, Unspecified and Misc. Total:</b>						2,671.67
<hr/>						
<b>Yearly Totals:</b>	2,756.22	2,621.39	3,061.01	3,556.93	3,859.40	
<b>Grand Total:</b>						<b>\$15,854.95</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Citywide Categories**

<b>Program Category</b>	<b>Code</b>	<b>FY15</b>	<b>FY16</b>	<b>FY17</b>	<b>FY18</b>	<b>FY19</b>	<b>Total</b>
ASBESTOS	1C1	39.77	37.82	36.18	40.32	38.31	192.40
KITCHEN CONVERSION	1C5	0.00	0.00	0.00	0.00	0.00	0.00
LEAD PAINT ABATEMENT	1C12	1.10	1.19	0.10	1.80	2.50	6.69
KITCHEN AREAS	1E15	3.10	4.76	6.46	1.74	7.32	23.37
CIP RESPONSE	1E20	0.00	0.00	0.00	0.00	0.00	0.00
TRANSPORTABLES	2A4	0.00	(0.00)	0.00	0.00	0.00	(0.00)
PRE-KINDERGARTEN INITIATIVE	2A8	261.29	284.68	67.87	70.91	13.87	698.61
3-K INITIATIVE	2A9	0.00	0.00	0.00	0.33	150.35	150.68
TECHNOLOGY	3A1	62.20	11.70	11.70	90.60	381.04	557.24
ROOM CONVERSIONS / PARTITIONING	3A2	27.81	78.22	65.34	34.50	37.90	243.77
ACCESSIBILITY	3A3	3.20	24.20	43.40	19.14	31.12	121.06
SCHOOL IMPROVEMENT AND RESTRUCTURING	3A4	18.65	27.91	25.84	21.62	11.39	105.41
SCIENCE LAB UPGRADES	3A5	4.95	15.46	13.65	9.04	8.87	51.96
LIBRARY UPGRADE	3A6	0.13	0.77	0.89	0.98	0.71	3.47
CHARTER/INNOVATIVE SCHOOLS	3A7	0.00	0.00	0.00	(0.00)	0.00	(0.00)
SCHOOL SAFETY	4A1a	10.35	3.20	9.32	27.04	31.70	81.62
EMERGENCY LIGHTING AND FIRE SAFETY RETROFITS	4A2	1.94	0.47	0.54	0.49	1.43	4.87
CODE COMPLIANCE	4A3	1.08	0.95	3.71	11.12	14.30	31.17
ADMINISTRATIVE SUPPORT	5A1	0.06	0.06	0.01	4.00	4.58	8.71
BUILDING CONDITION SURVEYS	6A1	12.01	15.10	13.20	12.90	16.40	69.61
DOE ADMINISTRATION	6C1	0.00	9.60	5.50	5.20	5.60	25.90

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Citywide Categories**

<b>Program Category</b>	<b>Code</b>	<b>FY15</b>	<b>FY16</b>	<b>FY17</b>	<b>FY18</b>	<b>FY19</b>	<b>Total</b>
WRAP-UP INSURANCE	6D1	222.77	205.92	148.94	212.71	113.07	903.41
EMERGENCY UNSPECIFIED	6E1	34.65	43.26	69.22	33.40	26.06	206.59
EMERGENCY STABILIZATION	6E2	7.64	14.47	11.11	13.79	18.03	65.04
EMERGENCY RESPONSE	6E3	0.00	0.00	0.00	0.00	0.00	0.00
PRIOR PLAN COMPLETION COST	6F1	259.46	190.31	104.21	59.10	(24.68)	588.39
CITY COUNCIL	6G1	87.46	86.09	119.97	133.91	107.42	534.85
MAYOR/COUNCIL PROGRAM	6H1	0.97	1.22	0.26	0.53	0.43	3.42
<b>Grand Total</b>		<b>1,060.59</b>	<b>1,057.36</b>	<b>757.41</b>	<b>805.16</b>	<b>997.71</b>	<b>4,678.23</b>



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	02	DSF0000798235	M	1,016	Aug-13	Feb-15	Jun-18	177.08	44.10	131.18	1.80
*	03	DSF0000730952	M	692	Apr-11	Jun-16	Sep-17	103.10	3.61	99.49	0.00
* L	05	DSF0000866751	M	245	Aug-17	May-18	Sep-19	12.71	0.00	12.20	0.51
*	08	DSF0000798233	X	344	Feb-15	Jul-16	Sep-18	66.16	0.18	63.92	2.06
*	10	DSF0000798175	X	500	Feb-15	Dec-16	Jun-19	120.08	0.07	98.36	21.66
*	10	DSF0000798177	X	388	Aug-17	Feb-19	Aug-21	61.99	0.02	49.15	12.82
*	10	DSF0000798176	X	296	Aug-17	Mar-19	Sep-21	66.59	0.02	52.12	14.46
*	11	DSF0000798178	X	548	Feb-17	Jun-18	Sep-21	82.12	0.11	64.26	17.75
*	13	DSF0000687093	K	333	May-12	May-15	Jul-16	38.20	3.57	34.63	0.00
*	15	DSF0000798185	K	436	Mar-15	Jun-17	Jul-20	102.67	0.09	83.74	18.85
* L	15	DSF0000798184	K	378	Mar-16	Jul-17	Sep-17	27.53	0.00	22.24	5.29
		§ Total Estimated Cost									
* L	15	DSF0000799396	K	113	Jan-14	Jul-14	Jul-16	11.54	0.12	11.42	0.00
*	15	DSF0000798182	K	332	Jun-17	Jun-19	Jun-22	99.22	0.00	79.74	19.48
*	15	DSF0000843828	K	404	Aug-17	Apr-19	Apr-21	95.01	0.00	75.53	19.49
* L	15	DSF0000866093	K	224	Oct-17	Jun-18	Sep-18	15.16	0.00	14.23	0.93
*	15	DSF0000798183	K	328	Aug-17	Apr-19	Sep-21	95.31	0.04	80.87	14.40
*	19	DSF0000822081	K	1,000	Jul-16	Jun-18	Sep-20	133.16	0.00	105.64	27.52
*	20	DSF0000798189	K	364	Feb-17	Jul-18	Aug-21	79.67	0.00	64.05	15.61

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	20	DSF0000798186	P.S. @ 270 59TH STREET	K	976	Apr-15	Jun-17	Mar-20	143.45	0.10	121.31	22.04
*	21	DSF0000798193	P.S. 97 ADDITION	K	468	Mar-17	Jun-18	Jun-21	71.39	0.00	54.86	16.53
*	21	DSF0000798192	P.S. 101 ADDITION	K	456	May-15	Nov-16	Jun-19	87.08	0.00	78.82	8.25
*	22	DSF0000798194	P.S. 254 ADDITION	K	416	Aug-17	Apr-19	Jun-21	69.23	0.00	49.48	19.75
*	24	DSF0000798568	P.S. 19 ADDITION	Q	640	Mar-15	Jul-16	Sep-18	100.58	0.01	97.57	2.99
*	24	DSF0000798200	P.S. 49 ADDITION	Q	333	Mar-14	Dec-15	Sep-17	40.80	0.13	40.67	0.00
*	24	DSF0000798199	I.S. 125 ADDITION	Q	728	Feb-14	Dec-15	Sep-17	101.71	0.30	97.59	3.81
*	24	DSF0000798195	P.S. 143 ADDITION	Q	980	Jan-16	Jul-17	Sep-20	121.85	0.07	102.21	19.57
*	24	DSF0000821576	P.S. 128 ADDITION	Q	440	Mar-16	Jun-17	Jun-20	43.21	0.00	37.21	6.00
*	24	DSF0000798196	I.S. 419	Q	646	Sep-16	May-18	Jun-21	117.70	0.14	95.91	21.65
* L	24	DSF0000798197	P.S. 143 ANNEX	Q	211	Dec-15	Jul-17	Sep-18	8.42	0.00	7.62	0.80
*	25	DSF0000798203	P.S. 24 ADDITION	Q	600	Dec-14	Jul-16	Sep-18	103.69	0.05	98.11	5.52
*	25	DSF0000843833	P.S. 129 ADDITION	Q	548	Sep-16	Apr-18	Sep-20	63.09	0.00	52.97	10.12
*	26	DSF0000798205	BAYSIDE HILLS SCHOOL OF EXCELLENCE	Q	468	Feb-14	Aug-15	Sep-17	90.93	6.85	84.08	0.00
* L	26	DSF0000889304	P.S. @ 56-10 214 STREET	Q	292	Aug-18	Jun-19	Sep-20	19.84	0.00	16.37	3.47
*	27	DSF0000801039	P.S. 66 ADDITION	Q	124	Aug-15	Jun-17	Sep-19	43.17	0.00	38.69	4.48
*	27	DSF0000417420	CENTREVILLE EDUCATIONAL BUILDING	Q	516	Sep-13	Jul-15	Sep-17	104.79	6.25	90.54	8.00
*	28	DSF0000798208	P.S. 303 ADDITION	Q	484	Feb-15	Jan-17	Sep-19	97.67	0.00	84.23	13.45
*	28	DSF0000798209	P.S. 144 ADDITION	Q	590	Dec-15	Jul-17	Sep-19	71.51	0.00	61.72	9.80
*	28	DSF0000843834	P.S. 196 ADDITION	Q	250	Jun-18	Jun-19	Jun-21	50.94	0.00	38.78	12.16
*	28	DSF0000888762	P.S. 206 ADDITION	Q	392	Mar-18	Jun-19	Jun-22	55.58	0.00	42.29	13.29

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	30	DSF0000843984	Q	612	Apr-16	Jul-17	Jun-21	92.53	0.00	75.45	17.07
*	30	DSF0000798210	Q	476	Jun-15	Mar-17	Jun-19	92.50	0.00	80.24	12.26
*	30	DSF0000843825	Q	725	Jan-18	Jun-19	Jun-22	109.85	0.00	89.15	20.70
*L	31	DSF0000821684	R	224	Jun-14	Dec-14	Sep-16	23.20	0.00	21.20	2.00
		FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX									
*	31	DSF0000843832	R	773	Jun-17	Jan-19	Mar-22	134.66	0.00	108.53	26.13
*L	31	DSF0000798214	R	309	Nov-15	Nov-16	Jun-17	15.19	0.01	14.85	0.32
*L	78Q	DSF0000798226	Q	507	Oct-13	Jul-16	Sep-18	28.20	0.45	26.95	0.80
		THE COLLEGE POINT COLLABORATIVE EDUCATIONAL BUILDING									
*	78Q	DSF0000821799	Q	555	Apr-17	Jul-18	Jul-21	63.07	0.00	51.58	11.48
*	78Q	DSF0000888760	Q	795	Jun-18	Jun-19	Jun-22	63.30	0.00	49.35	13.95
*	78Q	DSF0000798215	Q	969	Jul-16	May-18	Jun-21	111.70	0.02	91.99	19.69
*	78R	DSF0000798232	R	345	Apr-14	Sep-15	Jul-17	94.88	0.14	93.42	1.32
		CURTIS HIGH SCHOOL ANNEX									

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019 Capacity Program  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
2	I.S. 323	M	75 MORTON STREET
3	THE RIVERSIDE SCHOOL	M	300 WEST 61ST STREET
5	TEACHER'S COLLEGE COMMUNITY SCHOOL ANNEX	M	223-233 WEST 132 STREET
8	P.S. 14 ADDITION	X	3041 BRUCKNER BOULEVARD
10	P.S. 46 ADDITION	X	279 EAST 196 STREET
10	P.S. 340 ANNEX	X	25 WEST 195TH STREET
10	P.S. 33 ANNEX	X	2424 JEROME AVENUE
11	P.S. 97 ADDITION	X	1375 MACE AVENUE
13	THE DOCK STREET EDUCATIONAL COMPLEX	K	19 DOCK STREET
15	P.S. @ 4513 8TH AVENUE	K	4513 8TH AVENUE
15	P.S. @ 4302 4TH AVENUE	K	4302 4TH AVENUE
15	EDUCATIONAL CAMPUS @ 500 19TH STREET	K	500 19TH STREET
15	P.S. 32 ADDITION	K	317 HOYT STREET
15	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL	K	4222 4TH AVENUE
15	P.S. @ 836-841 5TH AVENUE	K	836-841 5TH AVENUE
15	P.S. @ 736 48TH STREET	K	736 48TH STREET
19	P.S./I.S. @ 3269 ATLANTIC AVENUE	K	3269 ATLANTIC AVENUE
20	P.S. @ 270 59TH STREET	K	270 59TH STREET
20	P.S. 127 ADDITION	K	7805 7TH AVENUE
21	P.S. 101 ADDITION	K	2360 BENSON AVENUE
21	P.S. 97 ADDITION	K	1855 STILLWELL AVENUE
22	P.S. 254 ADDITION	K	1801 AVENUE Y
24	P.S. 143 ADDITION	Q	34-74 113TH STREET

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019 Capacity Program  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
24	I.S. 419	Q	111-10 ASTORIA BOULEVARD
24	P.S. 143 ANNEX	Q	98-07 38TH AVENUE
24	I.S. 125 ADDITION	Q	46-02 47TH AVENUE
24	P.S. 49 ADDITION	Q	63-60 80TH STREET
24	P.S. 19 ADDITION	Q	98-02 ROOSEVELT AVENUE
24	P.S. 128 ADDITION	Q	69-10 65TH DRIVE
25	P.S. 24 ADDITION	Q	141-11 HOLLY AVENUE
25	P.S. 129 ADDITION	Q	128-02 7TH AVENUE
26	BAYSIDE HILLS SCHOOL OF EXCELLENCE	Q	210-21 48TH AVENUE
26	P.S. @ 56-10 214 STREET	Q	56-10 214 STREET
27	CENTREVILLE EDUCATIONAL BUILDING	Q	150-15 RALEIGH STREET
27	P.S. 66 ADDITION	Q	85-11 102ND STREET
28	P.S. 303 ADDITION	Q	108-55 69TH AVENUE
28	P.S. 144 ADDITION	Q	93-02 69TH AVENUE
28	P.S. 196 ADDITION	Q	71-25 113 STREET
28	P.S. 206 ADDITION	Q	61-21 97TH PLACE
30	I.S. @ 47-10 BARNETT AVENUE	Q	47-10 BARNETT AVENUE
30	P.S. 398	Q	69-01 34TH AVENUE
30	P.S. @ PARCEL F	Q	2ND STREET BETWEEN 56TH AND 57TH AVENUE
31	I.S. 82	R	104 GORDON STREET
31	FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	R	1625 FOREST AVENUE
31	P.S. @ 357 TARGEE STREET	R	357 TARGEE STREET
78Q	THE COLLEGE POINT OF COLLABORATIVE	Q	124-06 14TH AVENUE

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019 Capacity Program  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
78Q	ACADEMY OF AMERICAN STUDIES	Q	28-01 41ST AVENUE
78Q	FRANCIS LEWIS HS ANNEX	Q	58-20 UTOPIA PARKWAY
78Q	CARDOZO HS ANNEX	Q	57-00 223 STREET
78R	CURTIS HS ANNEX	R	105B HAMILTON AVENUE

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	02	DSF0000800052		108	Jun-14	Jan-15	Sep-15	12.57	0.01	12.56	0.00
* L	02	DSF0000865846		72	Dec-16	Nov-18	Jun-19	7.77	0.00	7.77	0.00
*	02	DSF0000821653		36	Oct-14	Jul-15	Aug-16	7.98	0.00	7.98	0.00
* L	02	DSF0000866155		180	Apr-17	May-18	Jun-19	21.46	0.00	21.46	0.00
* L	02	DSF0000866268		144	May-17	Jan-18	Jun-18	9.54	0.00	9.54	0.00
* L	02	DSF0000867184		90	Sep-17	Feb-18	Aug-18	9.44	0.00	9.44	0.00
* L	07	DSF0000800054		90	Jun-14	Dec-14	Jul-15	7.95	0.00	7.95	0.00
* L	07	DSF0000800055		180	Jun-14	Dec-14	Jul-15	11.83	0.00	11.83	0.00
* L	09	DSF0000801087		90	Oct-14	Mar-15	Aug-15	9.33	0.00	9.33	0.00
* L	10	DSF0000821711		90	Dec-14	Sep-15	Sep-16	7.20	0.00	7.20	0.00
* L	10	DSF0000821828		54	Apr-15	Feb-16	Sep-16	5.55	0.00	5.55	0.00
* L	10	DSF0000821875		198	Apr-15	Feb-16	Sep-17	15.24	0.00	15.24	0.00
* L	10	DSF0000821874		36	Apr-15	Dec-15	Sep-16	4.84	0.00	4.84	0.00
* L	10	DSF0000822032		36	May-15	Mar-16	Sep-16	13.44	0.00	13.44	0.00
* L	10	DSF0000822030		234	May-15	Jul-15	Sep-15	0.21	0.00	0.21	0.00
* L	13	DSF0000821675		72	Dec-14	May-15	Jul-16	5.84	0.00	5.84	0.00
* L	15	DSF0000821918		288	Feb-15	Mar-15	Aug-15	5.30	0.00	5.30	0.00
§ Total Estimated Cost											

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Pre-Kindergarten Initiative Projects**  
(in millions)

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete		
* L	15	DSF0000822214		PRE-K CENTER @ 219 25TH STREET	K	72	Jul-15	Apr-16	Sep-17	10.74	0.00	10.74	0.00
* L	15	DSF0000821832		PRE-K CENTER @ 305-307 THIRD AVENUE	K	54	Mar-15	Nov-15	Aug-16	9.69	0.00	9.69	0.00
* L	15	DSF0000821928		PRE-K CENTER @ 173 25TH STREET	K	108	Mar-15	May-15	Aug-15	8.24	0.00	8.24	0.00
		§ Total Estimated Cost											
* L	15	DSF0000822084		PRE-K CENTER @ 131 UNION STREET	K	36	Jun-15	Feb-16	Sep-16	7.28	0.00	7.28	0.00
*	20	DSF0000821654		PRE-K CENTER @ 8501 5TH AVENUE	K	18	Oct-14	Apr-15	Sep-15	5.53	0.00	5.53	0.00
* L	20	DSF0000821713		PRE-K CENTER @ 2165 71ST STREET	K	90	Dec-14	May-15	Aug-16	17.21	0.00	17.42	-0.21
* L	20	DSF0000800304		PRE-K CENTER @ 550 59TH STREET	K	162	Jul-14	Dec-15	Aug-16	9.16	0.00	9.16	0.00
*	20	DSF0000821813		PRE-K CENTER @ 369 93RD STREET	K	252	Feb-15	Jun-16	Mar-18	38.94	0.00	38.94	0.00
*	20	DSF0000821967		PRE-K CENTER @ 140A 58TH STREET	K	126	Apr-15	Jun-15	Sep-15	14.57	0.00	14.57	0.00
* L	20	DSF0000821958		PRE-K CENTER @ 1423 62ND STREET	K	324	Apr-15	May-16	Aug-17	32.86	0.00	32.86	0.00
* L	20	DSF0000800123		PRE-K CENTER @ 1258 65TH STREET	K	126	Jun-14	Dec-14	Jul-15	12.31	0.00	12.31	0.00
* L	20	DSF0000822082		PK/3K CENTER @ 21 BAY 11TH STREET	K	54	Apr-15	Jan-16	Sep-16	11.09	0.00	11.09	0.00
* L	20	DSF0000822014		PK/3K CENTER @ 21 BAY 11TH STREET	K	234	Jan-15	Aug-15	Sep-15	0.57	0.00	0.57	0.00
* L	20	DSF0000800057		PRE-K CENTER @ 1355 84TH STREET	K	90	Jun-14	Jan-15	Sep-15	12.13	0.00	12.13	0.00
* L	20	DSF0000822162		PRE-K CENTER @ 1355 84TH STREET	K	72	May-15	Aug-15	Sep-16	0.40	0.00	0.40	0.00
* L	20	DSF0000800047		PRE-K CENTER @ 1668 46TH STREET	K	180	Jun-14	Nov-14	Jul-15	6.77	0.02	6.74	0.00
* L	20	DSF0000822086		PRE-K CENTER @ 7401 FORT HAMILTON PARKWAY	K	270	May-15	Jul-15	Sep-15	13.11	0.00	12.45	0.65
		§ Total Estimated Cost											
* L	21	DSF0000800230		PRE-K CENTER @ 2202 60TH STREET	K	108	Jun-14	Jan-15	Jul-15	5.16	0.00	5.16	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Pre-Kindergarten Initiative Projects**  
(in millions)

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	21	DSF0000822037 § Total Estimated Cost	K	126	Apr-15	May-15	Sep-15	3.98	0.00	3.98	0.00
* L	21	DSF0000821960 PRE-K CENTER @ 1223 CONEY ISLAND AVENUE	K	72	Apr-15	Jan-16	Jul-17	10.13	0.00	10.12	0.01
* L	21	DSF0000821873 PRE-K CENTER @ 10 BOUCK COURT	K	180	Mar-15	Jan-16	Aug-16	15.62	0.00	15.62	0.00
* L	21	DSF0000800303 PRE-K CENTER @ 1215 AVENUE X	K	108	Jul-14	Dec-14	Aug-15	5.42	0.00	5.42	0.00
* L	22	DSF0000822024 § Total Estimated Cost	K	144	Mar-15	May-15	Sep-15	13.08	0.00	13.08	0.00
* L	22	DSF0000822027 § Total Estimated Cost	K	252	Mar-15	May-15	Sep-15	14.07	0.00	14.07	0.00
* L	22	DSF0000800113 PRE-K CENTER @ 1139 CONEY ISLAND AVENUE	K	144	Jun-14	Dec-14	Jul-15	12.18	0.00	12.18	0.00
* L	24	DSF0000822186 PRE-K CENTER @ 70-24 47TH AVENUE	Q	90	Jun-15	Apr-16	Sep-17	4.11	0.00	4.11	0.00
* L	24	DSF0000822111 § Total Estimated Cost	Q	162	May-15	Jul-15	Sep-15	6.65	0.00	6.65	0.00
* L	24	DSF0000844691 PRE-K CENTER @ 54-25 101ST STREET	Q	54	Sep-16	Jan-18	Jul-18	4.38	0.00	4.38	0.00
* L	24	DSF0000844698 PRE-K CENTER @ 104-14 ROOSEVELT AVENUE	Q	72	Aug-16	May-17	Sep-17	11.31	0.00	10.93	0.38
*	24	DSF0000866312 PRE-K CENTER @ 104-04 CORONA AVENUE	Q	18	Jun-17	Mar-18	Sep-18	5.02	0.00	4.77	0.25
* L	24	DSF0000800114 PRE-K CENTER @ 46-16 76TH STREET	Q	108	Jun-14	Dec-14	Aug-15	13.62	0.00	13.62	0.00
* L	24	DSF0000800248 PRE-K CENTER @ 44-15 JUDGE STREET	Q	144	Jun-14	Dec-14	Jun-15	6.05	0.00	6.05	0.00
* L	24	DSF0000800282 PRE-K CENTER @ 68-20 MYRTLE AVENUE	Q	180	Jul-14	Dec-14	Jul-15	6.90	0.00	6.90	0.00
* L	24	DSF0000822099 PRE-K CENTER @ 107-17 NORTHERN BOULEVARD	Q	77	Jun-15	Jan-16	Jul-16	5.41	0.00	5.41	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Pre-Kindergarten Initiative Projects**  
(in millions)

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
* L	24	DSF0000822098		Q	36	Jun-15	Feb-16	Aug-16	3.85	0.00	3.85	0.00
		PRE-K CENTER @ 106-02 NORTHERN BOULEVARD										
* L	24	DSF0000845581		Q	54	Oct-16	Mar-18	Sep-18	6.34	0.00	6.34	0.00
		PRE-K CENTER @ 108-18 ROOSEVELT AVENUE										
* L	24	DSF0000844747		Q	36	Sep-16	Jun-17	Sep-17	5.89	0.00	5.89	0.00
		PRE-K CENTER @ 57-06 99TH STREET										
* L	24	DSF0000865849		Q	54	Jan-17	Apr-17	Sep-17	1.90	0.00	1.90	0.00
		PRE-K CENTER @ 98-22 55 AVENUE										
* L	25	DSF0000821980		Q	108	Apr-15	Jan-16	Jul-16	3.74	0.00	3.74	0.00
		PRE-K CENTER @ 14-45 143RD STREET										
* L	25	DSF0000821868		Q	144	Feb-15	Dec-15	Sep-17	6.63	0.00	6.63	0.00
		PRE-K CENTER @ 123-07 22ND AVENUE										
* L	28	DSF0000800117		Q	72	Jun-14	Dec-14	Jun-15	7.40	0.00	7.40	0.00
		PRE-K CENTER @ 89-14 PARSONS BOULEVARD										
* L	28	DSF0000800124		Q	90	Jun-14	Dec-14	Jun-15	10.94	0.00	10.94	0.00
		PRE-K CENTER @ 132-10 JAMAICA AVENUE										
* L	28	DSF0000801086		Q	72	Sep-14	Mar-15	Aug-15	7.35	0.00	7.35	0.00
		PRE-K CENTER @ 83-30 KEW GARDENS ROAD										
* L	29	DSF0000800116		Q	126	Jun-14	Dec-14	Jun-15	15.40	0.00	15.40	0.00
		PRE-K CENTER @ 168-42 JAMAICA AVENUE										
* L	29	DSF0000801025		Q	162	Aug-14	Dec-14	Jul-15	8.06	0.00	8.06	0.00
		PRE-K CENTER @ 100-01 SPRINGFIELD BOULEVARD										
* L	30	DSF0000800058		Q	108	Jun-14	Dec-14	Jun-15	10.64	0.01	10.63	0.00
		PRE-K CENTER @ 96-10 23RD AVENUE										
* L	30	DSF0000821858		Q	126	Apr-15	Jul-16	Jul-17	9.75	0.00	9.75	0.00
		PRE-K CENTER @ 32-52 37TH STREET										
* L	30	DSF0000822015		Q	270	Apr-15	Aug-15	Sep-15	0.65	0.00	0.65	0.00
		PRE-K CENTER @ 32-52 37TH STREET										
* L	30	DSF0000843935		Q	180	Jan-16	Dec-16	Sep-17	10.08	0.00	9.77	0.31
		PRE-K CENTER @ 27-35 JACKSON AVENUE										
* L	31	DSF0000800050		R	90	Jun-14	Dec-14	Sep-15	20.20	0.01	20.19	0.00
		FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX										
* L	31	DSF0000800328		R	144	Aug-14	Dec-14	Sep-15	13.43	0.00	13.43	0.00
		THE RICHMOND PRE-K CENTER @ 1 TELEPORT DRIVE										

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
(in millions)**

	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	31	DSF0000800267	PRE-K CENTER @ 120 STUYVESANT PLACE	R	108	Jul-14	Jan-15	Aug-15	16.73	0.00	16.73	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019  
Pre-Kindergarten Initiative Projects  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
2	PRE-K CENTER @ 2-26 WASHINGTON ST	M	2-26 WASHINGTON STREET
2	DISTRICT 2 PRE-K CENTER @ 606 WEST 57TH STREET	M	606 WEST 57TH STREET
2	PRE-K CENTER @ 2 LAFAYETTE STREET	M	2 LAFAYETTE STREET
2	PRE-K CENTER @ 355 EAST 76 STREET	M	355 EAST 76 STREET
2	PRE-K CENTER @ 252 EAST 57 STREET	M	252 EAST 57 STREET
2	PRE-K CENTER @ 1683 3RD AVENUE	M	1683 3RD AVENUE
7	PRE-K CENTER @ 105 WILLIS AVENUE	X	105 WILLIS AVENUE
7	PRE-K CENTER @ 535 UNION AVENUE	X	535 UNION AVENUE
9	PRE-K CENTER @ 1434 OGDEN AVENUE	X	1434 OGDEN AVENUE
10	PRE-K CENTER @ 3560 WEBSTER AVENUE	X	3560 WEBSTER AVENUE
10	PRE-K CENTER @ 5500 BROADWAY	X	5500 BROADWAY
10	PRE-K CENTER @ 2490-2500 WEBSTER AVENUE	X	2490-2500 WEBSTER AVENUE
10	PRE-K CENTER @ 3605 SEDGWICK AVENUE	X	3605 SEDGWICK AVENUE
10	PRE-K CENTER @ 2510 MARION AVENUE	X	2510 MARION AVENUE
13	THE DOCK STREET EDUCATIONAL COMPLEX	K	19 DOCK STREET
15	EDUCATIONAL CAMPUS @ 500 19TH STREET	K	500 19TH STREET
15	PRE-K CENTER @ 219 25TH STREET	K	219 25TH STREET
15	PRE-K CENTER @ 305-307 THIRD AVENUE	K	305-307 THIRD AVENUE
15	PRE-K CENTER @ 173 25TH STREET	K	173 25TH STREET
15	PRE-K CENTER @ 131 UNION STREET	K	131 UNION STREET
20	PRE-K CENTER @ 8501 5TH AVENUE	K	8501 5TH AVENUE
20	PRE-K CENTER @ 2165 71ST STREET	K	2165 71ST STREET
20	PRE-K CENTER @ 550 59TH STREET	K	550 59TH STREET

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019  
Pre-Kindergarten Initiative Projects  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
20	PRE-K CENTER @ 369 93RD STREET	K	369 93RD STREET
20	PRE-K CENTER @ 140A 58TH STREET	K	140A 58TH STREET
20	PRE-K CENTER @ 1423 62ND STREET	K	1423 62ND STREET
20	PRE-K CENTER @ 1258 65TH STREET	K	1258 65TH STREET
20	PRE-K CENTER @ 21 BAY 11TH STREET	K	21 BAY 11TH STREET
20	PRE-K CENTER @ 1355 84TH STREET	K	1355 84TH STREET
20	PRE-K CENTER @ 1668 46TH STREET	K	1668 46TH STREET
20	PRE-K CENTER @ 7401 FORT HAMILTON PARKWAY	K	7401 FORT HAMILTON PARKWAY
21	PRE-K CENTER @ 2202 60TH STREET	K	2202 60TH STREET
21	PRE-K CENTER @ 385 AVENUE W	K	385 AVENUE W
21	PRE-K CENTER @ 1223 CONEY ISLAND AVENUE	K	1223 CONEY ISLAND AVENUE
21	PRE-K CENTER @ 10 BOUCK COURT	K	10 BOUCK COURT
21	PRE-K CENTER @ 1215 AVENUE X	K	1215 AVENUE X
22	PRE-K CENTER @ 3610 GLENWOOD ROAD	K	3610 GLENWOOD ROAD
22	PRE-K CENTER @ 1340 EAST 29TH STREET	K	1340 EAST 29TH STREET
22	PRE-K CENTER @ 1139 CONEY ISLAND AVENUE	K	1139 CONEY ISLAND AVENUE
24	PRE-K CENTER @ 70-24 47TH AVENUE	Q	70-24 47TH AVENUE
24	PRE-K CENTER @ 56-01 61ST STREET	Q	56-01 61ST STREET
24	PRE-K CENTER @ 54-25 101ST STREET	Q	54-25 101ST STREET
24	PRE-K CENTER @ 104-14 ROOSEVELT AVENUE	Q	104-14 ROOSEVELT AVENUE
24	PRE-K CENTER @ 104-04 CORONA AVENUE	Q	104-04 CORONA AVENUE
24	PRE-K CENTER @ 46-16 76TH STREET	Q	46-16 76TH STREET
24	PRE-K CENTER @ 44-15 JUDGE STREET	Q	44-15 JUDGE STREET

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019  
Pre-Kindergarten Initiative Projects  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
24	PRE-K CENTER @ 68-20 MYRTLE AVENUE	Q	68-20 MYRTLE AVENUE
24	PRE-K CENTER @ 107-17 NORTHERN BOULEVARD	Q	107-17 NORTHERN BOULEVARD
24	PRE-K CENTER @ 106-02 NORTHERN BOULEVARD	Q	106-02 NORTHERN BOULEVARD
24	PRE-K CENTER @ 108-18 ROOSEVELT AVENUE	Q	108-18 ROOSEVELT AVENUE
24	PRE-K CENTER @ 57-06 99TH STREET	Q	57-06 99TH STREET
24	PRE-K CENTER @ 98-22 55 AVENUE	Q	98-22 55 AVENUE
25	PRE-K CENTER @ 14-45 143RD STREET	Q	14-45 143RD STREET
25	PRE-K CENTER @ 123-07 22ND AVENUE	Q	123-07 22ND AVENUE
28	PRE-K CENTER @ 89-14 PARSONS BOULEVARD	Q	89-14 PARSONS BOULEVARD
28	PRE-K CENTER @ 132-10 JAMAICA AVENUE	Q	132-10 JAMAICA AVENUE
28	PRE-K CENTER @ 83-30 KEW GARDENS ROAD	Q	83-30 KEW GARDENS ROAD
29	PRE-K CENTER @ 168-42 JAMAICA AVENUE	Q	168-42 JAMAICA AVENUE
29	PRE-K CENTER @ 100-01 SPRINGFIELD BOULEVARD	Q	100-01 SPRINGFIELD BOULEVARD
30	PRE-K CENTER @ 96-10 23RD AVENUE	Q	96-10 23RD AVENUE
30	PRE-K CENTER @ 32-52 37TH STREET	Q	32-52 37TH STREET
30	PRE-K CENTER @ 27-35 JACKSON AVENUE	Q	27-35 JACKSON AVENUE
31	FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	R	1625 FOREST AVENUE
31	PRE-K CENTER @ 1 TELEPORT DRIVE	R	1 TELEPORT DRIVE
31	PRE-K CENTER @ 120 STUYVESANT PLACE	R	120 STUYVESANT PLACE

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
3-K Initiative Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	12	DSF0000891031	X	105	Nov-18	Jun-19	Aug-20	8.66	0.00	8.66	0.00
* L	20	DSF0000889666	K	45	Oct-18	Jun-19	Apr-20	10.11	0.00	10.11	0.00
* L	27	DSF0000889652	Q	165	Aug-18	Feb-19	Jul-19	16.07	0.00	16.07	0.00
* L	27	DSF0000889334	Q	165	Jul-18	Jan-19	Jul-19	15.40	0.00	15.40	0.00
* L	27	DSF0000889347	Q	120	Jun-18	Jul-18	Aug-18	9.95	0.00	9.95	0.00
* L	27	DSF0000889573	Q	120	Jun-18	Jan-19	Jul-19	10.09	0.00	10.09	0.00
* L	27	DSF0000891039	Q	45	Oct-18	May-19	Aug-19	7.85	0.00	7.85	0.00
* L	29	DSF0000890627	Q	420	Jun-18	Jun-19	Sep-20	15.74	0.00	15.74	0.00
* L	31	DSF0000889335	R	225	Jul-18	Jan-19	Sep-19	16.06	0.00	16.06	0.00
* L	31	DSF0000889336	R	105	Jul-18	Feb-19	Sep-19	12.29	0.00	12.29	0.00
* L	31	DSF0000889338	R	75	Jun-18	Mar-19	Jun-19	9.79	0.00	9.79	0.00
* L	31	DSF0000889339	R	75	Jul-18	Jan-19	Sep-19	11.46	0.00	11.46	0.00
* L	31	DSF0000889340	R	60	Jul-18	Mar-19	Aug-19	4.70	0.00	4.70	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019  
3K Initiative Projects  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
12	3K CENTER @ 1939 WEST FARMS ROAD	X	1939 WEST FARMS ROAD
20	PK/3K CENTER @ 21 BAY 11TH STREET	K	21 BAY 11TH STREET
27	DISTRICT 27 PRE-K CENTER @ 101-49 WOODHAVEN BOULEVARD	Q	101-49 WOODHAVEN BOULEVARD
27	DISTRICT 27 PRE-K CENTER @ 100-02 ROCKAWAY BOULEVARD	Q	100-02 ROCKAWAY BOULEVARD
27	3K CENTER @ 104-06 101 AVENUE	Q	104-06 101 AVENUE
27	DISTRICT 27 PRE-K CENTER @ 87-40 88 STREET	Q	87-40 88 STREET
27	DISTRICT 27 PRE-K CENTER @ 160-06 CROSS BAY BOULEVARD	Q	160-06 CROSS BAY BOULEVARD
29	3K CENTER @ 92-80 220TH STREET	Q	92-80 220TH STREET
31	THE RICHMOND PRE-K CENTER @ 1535 RICHMOND AVENUE	R	1535 RICHMOND AVENUE
31	THE RICHMOND PRE-K CENTER @ 20 EBBITTS STREET	R	20 EBBITTS STREET
31	THE RICHMOND PRE-K CENTER @ 2530 VICTORY BOULEVARD	R	2530 VICTORY BOULEVARD
31	THE RICHMOND PRE-K CENTER @ 104 HOUSMAN AVENUE	R	104 HOUSMAN AVENUE
31	3K CENTER @ 1 TELEPORT DRIVE	R	1 TELEPORT DRIVE



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Class Size Reduction Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	11	DSF0000821591	X	400	May-16	Jun-17	Jul-20	70.70	0.00	58.69	12.00
*	29	DSF0000843904	Q	384	Mar-17	Jun-18	Jul-21	68.32	0.00	53.86	14.47
*	78K	DSF0000844038	K	602	Apr-17	Aug-18	Sep-21	99.60	0.00	79.53	20.07

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
FY 2015 - FY 2019  
Class Size Reduction Programs  
Site Location**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
11	P.S. 19 ADDITION	X	4318 KATONAH AVENUE
29	P.S. 131 ADDITION	Q	170-45 84TH AVENUE
78K	EAST NY FAMILY ACADEMY	K	180 6TH AVENUE

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Replacement Projects  
(in millions)**

District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
* L	10	DSF0000775874	JEROME PARK EDUCATIONAL BUILDING	X	Replacement	Sep-13	Mar-15	May-17	20.21	0.49	19.67	0.05
*	24	DSF0000798568	P.S. 19 MINISCHOOL	Q	Replacement	Mar-15	Jul-16	Sep-18	12.56	0.00	12.19	0.37
*	25	DSF0000798203	P.S. 24 ADDITION	Q	Replacement	Dec-14	Jul-16	Sep-18	8.47	0.00	8.01	0.45
*	30	DSF0000888778	P.S. 2 MINISCHOOL	Q	Replacement	Feb-18	May-19	Sep-21	43.69	0.00	32.58	11.11
*	75Q	DSF0000843866	P.S. 256 ANNEX	Q	Replacement	Apr-16	Jul-18	Sep-20	52.35	0.00	37.41	14.94
*	75R	DSF0000844161	I.S./H.S. @ 715 OCEAN TERRACE	R	Replacement	Sep-17	May-19	Sep-21	106.15	0.00	83.75	22.39
*	75R	DSF0000821871	D75 REPLACEMENT @ 15 FAIRFIELD STREET	R	Replacement	Sep-16	Mar-18	Sep-20	60.42	0.00	51.95	8.47
* L	78M	DSF0000800279 Phase 2	WEST END SECONDARY SCHOOL	M	Replacement	Jun-14	Jan-17	May-19	23.43	0.00	22.23	1.20
* L	78X	DSF0000800056	SOUTHERN BOULEVARD COMMUNITY CAMPUS	X	Replacement	Sep-14	Jul-15	Jul-16	10.01	0.00	10.01	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**FY 2015 - FY 2019**  
**Replacement Programs**  
**Site Locations**

<b>DISTRICT</b>	<b>SCHOOL</b>	<b>BOROUGH</b>	<b>LOCATION</b>
10	JEROME PARK EDUCATIONAL BUILDING	X	2865 CLAFLIN AVENUE
24	P.S. 19 MINISCHOOL	Q	98-02 ROOSEVELT AVENUE
25	P.S. 24 ADDITION	Q	45-57 UNION STREET
30	P.S. 2 ADDITION	Q	75-10 21 AVENUE
75Q	P.S. 256 ANNEX	Q	445 BEACH 135 STREET
75R	I.S./H.S. @ 715 OCEAN TERRACE	R	715 OCEAN TERRACE
75R	D75 REPLACEMENT @ 15 FAIRFIELD STREET	R	15 FAIRFIELD STREET
78M	WEST END SECONDARY SCHOOL	M	227-243 WEST 61 STREET
78X	SOUTHERN BOULEVARD COMMUNITY CAMPUS	X	1211 SOUTHERN BLVD

**New York City School Construction Authority  
New York City Department of Education  
Final Five Year Capital Plan Report  
Fiscal Years 2015 - 2019  
PROJECTS ADVANCED TO FY 2014**

<b>District</b>	<b>Building ID</b>	<b>School</b>	<b>Borough</b>	<b>Project Description</b>
1	M110	P.S. 110	M	Toilets-Students
2	M011	P.S. 11	M	Swimming Pools
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	IP Digital Video Surveillance System
2	M116	P.S. 116	M	Boiler Conversion
2	M116	P.S. 116	M	Climate Control
2	M116	P.S. 116	M	Boiler Conversion
2	M116	P.S. 116	M	Climate Control
2	M124	P.S. 124 (ECF)	M	IP Digital Video Surveillance System
2	M167	I.S. 167	M	Heating Plant Upgrade
2	M198	P.S. 198	M	Boiler Conversion
2	M198	P.S. 198	M	Climate Control
2	M198	P.S. 198	M	Boiler Conversion
2	M198	P.S. 198	M	Climate Control
4	M101	P.S. 101	M	IP Digital Video Surveillance System
5	M125	P.S. 125	M	PA System
6	M008	P.S. 8	M	Heating Plant Upgrade
7	X161	P.S. 161	X	Heating Plant Upgrade
8	X036	P.S. 36	X	IP Digital Video Surveillance System
8	X069	P.S. 69	X	IP Digital Video Surveillance System
8	X072	P.S. 72	X	IP Digital Video Surveillance System
9	X011	P.S. 11	X	IP Digital Video Surveillance System
10	X026	P.S. 396	X	Boiler Conversion
10	X026	P.S. 396	X	Climate Control
10	X033	P.S. 33	X	Toilets-Students
10	X832	P.S. 32 MINISCHOOL	X	Ventilation
10	X122	P.S. 310	X	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five Year Capital Plan Report  
Fiscal Years 2015 - 2019  
PROJECTS ADVANCED TO FY 2014**

<b>District</b>	<b>Building ID</b>	<b>School</b>	<b>Borough</b>	<b>Project Description</b>
10	X368	M.S./H.S. 368	X	IP Digital Video Surveillance System
11	X127	I.S. 127	X	Heating Plant Upgrade
11	X021	P.S. 21	X	IP Digital Video Surveillance System
11	X178	P.S. 178	X	IP Digital Video Surveillance System
12	X129	I.S. 129 (PAIRED W P234)	X	Kitchen Areas
14	K017	P.S. 17	K	Floors
14	K126	J.H.S. 126	K	Heating Plant Upgrade
14	K126	J.H.S. 126	K	Heating Plant Upgrade
15	K015	P.S. 15	K	Lighting Fixtures
15	K088	I.S. 88	K	Lighting Fixtures
16	K035	I.S. 35	K	Parapets
16	K035	I.S. 35	K	Roofs
17	K241	P.S. 241	K	Toilets-Students
17	K246	I.S. 246	K	Air Conditioning Retrofit
17	K889	P.S. 189 MINISCHOOL	K	Ventilation
18	K285	I.S. 285	K	Toilets-Students
18	K276	P.S. 276	K	Climate Control
18	K276	P.S. 276	K	Low-Voltage Electrical System
18	K276	P.S. 276	K	Flood Elimination
18	K276	P.S. 276	K	Interior Spaces
18	K276	P.S. 276	K	Roofs
18	K276	P.S. 276	K	Exterior Masonry
18	K276	P.S. 276	K	Heating Plant Upgrade
18	K276	P.S. 276	K	Paved Area - Blacktop
19	K214	P.S. 214	K	Toilets-Students
19	K108	P.S. 108	K	Domestic Piping

**New York City School Construction Authority  
New York City Department of Education  
Final Five Year Capital Plan Report  
Fiscal Years 2015 - 2019  
PROJECTS ADVANCED TO FY 2014**

<b>District</b>	<b>Building ID</b>	<b>School</b>	<b>Borough</b>	<b>Project Description</b>
20	K048	P.S. 48	K	Flood Elimination
20	K062	I.S. 62	K	Heating Plant Upgrade
20	K229	P.S. 229	K	Domestic Piping
20	K807	P.S./ I.S. 163	K	Domestic Piping
22	K139	P.S. 139	K	Roofs
22	K206	P.S. 206	K	Toilets-Students
22	K207	P.S. 207	K	Domestic Piping
22	K269	P.S. 269	K	Toilets-Students
23	K073	P.S. 73	K	Electrical Systems
23	K275	I.S. 275	K	Auditorium Upgrade
23	K356	P.S. 156	K	Heating Plant Upgrade
25	Q107	P.S. 107	Q	Flood Elimination
25	Q022	P.S. 22	Q	Lighting Fixtures
25	Q185	J.H.S. 185	Q	Lighting Fixtures
26	Q098	P.S. 98	Q	Auditorium Upgrade
26	Q158	J.H.S. 158	Q	IP Digital Video Surveillance System
27	Q106	P.S. 106	Q	Low-Voltage Electrical Systems
27	Q180	I.S. 323 (OLD IS 180)	Q	Climate Control
27	Q180	I.S. 323 (OLD IS 180)	Q	Flood Elimination
27	Q180	I.S. 323 (OLD IS 180)	Q	Interior Spaces
27	Q180	I.S. 323 (OLD IS 180)	Q	Electrical Systems
27	Q180	I.S. 323 (OLD IS 180)	Q	Heating Plant Upgrade
27	Q207	P.S. 207	Q	Boiler Conversion
27	Q207	P.S. 207	Q	Climate Control
27	Q207	P.S. 207	Q	Low-Voltage Electrical System
27	Q207	P.S. 207	Q	Flood Elimination

**New York City School Construction Authority  
New York City Department of Education  
Final Five Year Capital Plan Report  
Fiscal Years 2015 - 2019  
PROJECTS ADVANCED TO FY 2014**

<b>District</b>	<b>Building ID</b>	<b>School</b>	<b>Borough</b>	<b>Project Description</b>
27	Q207	P.S. 207	Q	Interior Spaces
27	Q207	P.S. 207	Q	Paved Area - Blacktop
27	Q207	P.S. 207	Q	IP Digital Video Surveillance System
27	Q232	P.S. 232	Q	IP Digital Video Surveillance System
29	Q195	P.S. 195	Q	Boiler Conversion
29	Q195	P.S. 195	Q	Climate Control
29	Q195	P.S. 195	Q	Flood Elimination
29	Q195	P.S. 195	Q	Reinforcing Support Elements
29	Q195	P.S. 195	Q	Interior Spaces
29	Q195	P.S. 195	Q	Electrical Systems
30	Q148	P.S. 148	Q	IP Digital Video Surveillance System
30	Q230	I.S. 230	Q	IP Digital Video Surveillance System
31	R061	I.S. 61	R	Domestic Piping
31	R075	I.S. 75	R	Emergency Lighting and Fire Safety Retrofits
31	R069	P.S. 69	R	Heating Plant Upgrade
32	K384	P.S. 384	K	Auditorium Upgrade
75X	X084	P.S. 811 (OLD I84)	X	Air Conditioning Retrofit
75X	X155	P.S. 754 (OLD IS155)	X	Heating Plant Upgrade
78K	K455	BOYS & GIRLS HS	K	Auditorium Upgrade
78K	K460	JOHN JAY HS	K	Auditorium Upgrade
78K	K485	TELECOM. ARTS & TECH.	K	Roofs
78K	K485	TELECOM. ARTS & TECH.	K	Windows
78K	K500	CANARSIE HS	K	Toilets-Students
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Domestic Piping
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Gymnasium Upgrade
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Auditorium Upgrade



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**PROJECTS ADVANCED TO FY 2014**

<b>District</b>	<b>Building ID</b>	<b>School</b>	<b>Borough</b>	<b>Project Description</b>
78K	K865	SECOND OPPORTUNITY SCHOOL	K	Code Compliance
78M	M460	WASHINGTON IRVING HS	M	Toilets-Students
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Toilets-Students
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Toilets-Students
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Roofs
78M	M645	OLD MANHATTAN VOC/TECH HS	M	IP Digital Video Surveillance System
78M	M661	MNHT COMP NIGHT&DAY (OL BACN X)	M	IP Digital Video Surveillance System
78Q	Q405	BAYSIDE HS	Q	Lighting Fixtures
78Q	Q411	BEACH CHANNEL AF	Q	Athletic Fields
78Q	Q859	H.S. 859	Q	Exterior Masonry
78R	R455	TOTTENVILLE HS	R	Emergency Lighting and Fire Safety Retrofits

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
1	M015	P.S. 15	M	Domestic Piping
1	M015	P.S. 15	M	Heating Plant Upgrade
1	M015	P.S. 15	M	Student Toilets
1	M019	P.S. 19	M	Lighting Fixtures
1	M019	P.S. 19	M	Student Toilets
1	M022	N.E.S.T (OLD J22)	M	Electrical Systems
1	M022	N.E.S.T (OLD J22)	M	New/Retrofit Telephone/Intercom System
1	M025	J.H.S. 25	M	Electrical Systems
1	M025	J.H.S. 25	M	Heating Plant Upgrade
1	M025	J.H.S. 25	M	Heating Plant Upgrade
1	M025	J.H.S. 25	M	Lighting Fixtures
1	M025	J.H.S. 25	M	Toilets - Students
1	M034	P.S. 34	M	Electrical Systems
1	M034	P.S. 34	M	Heating Plant Upgrade
1	M034	P.S. 34	M	IP Digital Video Surveillance System
1	M056	J.H.S. 56	M	Classroom Connectivity
1	M056	J.H.S. 56	M	IP Digital Video Surveillance System
1	M056	J.H.S. 56	M	Heating Plant Upgrade
1	M060	J.H.S. 60	M	Exterior Masonry
1	M060	J.H.S. 60	M	Heating Plant Upgrade
1	M060	J.H.S. 60	M	Student Toilets
1	M061	P.S. 61	M	Electrical Systems
1	M061	P.S. 61	M	Exterior Masonry
1	M061	P.S. 61	M	Student Toilets
1	M063	P.S. 63	M	Student Toilets
1	M064	P.S. 64 (OLD 71)	M	Electrical Systems
1	M064	P.S. 64 (OLD 71)	M	Heating Plant Upgrade
1	M064	P.S. 64 (OLD 71)	M	IP Digital Video Surveillance System
1	M064	P.S. 64 (OLD 71)	M	Student Toilets
1	M110	P.S. 110	M	Student Toilets

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
1	M110	P.S. 110	M	Heating Plant Upgrade
1	M134	P.S. 134	M	New/Retrofit Telephone/Intercom System
1	M134	P.S. 134	M	Safety Systems
1	M134	P.S. 134	M	Student Toilets
1	M134	P.S. 134	M	Roofs
1	M134	P.S. 134	M	Parapets
1	M134	P.S. 134	M	Windows
1	M134	P.S. 134	M	Exterior Masonry
1	M134	P.S. 134	M	Heating Plant Upgrade
1	M134	P.S. 134	M	Accessibility
1	M134	P.S. 134	M	Safety Systems
1	M137	P.S. 137	M	Climate Control
1	M137	P.S. 137	M	Heating Plant Upgrade
1	M137	P.S. 137	M	Heating Plant Upgrade
1	M137	P.S. 137	M	Paved Area-Blacktop
1	M137	P.S. 137	M	Student Toilets
1	M137	P.S. 137	M	Playgrounds
1	M140	P.S. 140	M	Classroom Connectivity
1	M140	P.S. 140	M	Lighting Fixtures
1	M142	P.S. 142	M	Lighting Fixtures
1	M142	P.S. 142	M	Heating Plant Upgrade
1	M188	P.S. 188	M	Lighting Fixtures
1	M188	P.S. 188	M	Student Toilets
1	M188	P.S. 188	M	IP Digital Video Surveillance System
2	M001	P.S. 1	M	Electrical Systems
2	M001	P.S. 1	M	Kitchen Areas
2	M001	P.S. 1	M	Student Toilets
2	M001	P.S. 1	M	Flood Elimination
2	M001	P.S. 1	M	Roofs
2	M001	P.S. 1	M	Windows

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
2	M001	P.S. 1	M	Exterior Masonry
2	M002	P.S. 2	M	Lighting Fixtures
2	M002	P.S. 2	M	Student Toilets
2	M002	P.S. 2	M	Heating Plant Upgrade
2	M002	P.S. 2	M	Playgrounds
2	M003	P.S. 3	M	Lighting Fixtures
2	M003	P.S. 3	M	Student Toilets
2	M003	P.S. 3	M	Emergency Lighting and Fire Safety Retrofits
2	M006	P.S. 6	M	Lighting Fixtures
2	M006	P.S. 6	M	Electrical Systems
2	M011	P.S. 11	M	Electrical Systems
2	M011	P.S. 11	M	Student Toilets
2	M011	P.S. 11	M	Swimming Pools
2	M011	P.S. 11	M	Parapets
2	M017	I.S. 17	M	Heating Plant Upgrade
2	M017	I.S. 17	M	Lighting Fixtures
2	M017	I.S. 17	M	New/Retrofit Telephone/Intercom System
2	M017	I.S. 17	M	Student Toilets
2	M017	I.S. 17	M	Windows
2	M033	P.S. 33	M	Electrical Systems
2	M033	P.S. 33	M	Heating Plant Upgrade
2	M033	P.S. 33	M	Student Toilets
2	M040	P.S. 40	M	Student Toilets
2	M040	P.S. 40	M	IP Digital Video Surveillance System
2	M041	P.S. 41	M	Student Toilets
2	M042	P.S. 42	M	Electrical Systems
2	M042	P.S. 42	M	Student Toilets
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	Exterior Masonry
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	IP Digital Video Surveillance System
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	Parapets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	Student Toilets
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	Student Toilets
2	M047	J.H.S. 47 (SCH FOR THE DEAF)	M	Windows
2	M070	I.S. 70	M	Electrical Systems
2	M070	I.S. 70	M	Heating Plant Upgrade
2	M070	I.S. 70	M	Heating Plant Upgrade
2	M070	I.S. 70	M	Low-Voltage Electrical Systems
2	M070	I.S. 70	M	Student Toilets
2	M089	P.S./I.S. 89	M	Gymnasium Upgrade
2	M089	P.S./I.S. 89	M	Heating Plant Upgrade
2	M104	I.S. 104	M	Heating Plant Upgrade
2	M104	I.S. 104	M	Student Toilets
2	M104	I.S. 104	M	IP Digital Video Surveillance System
2	M111	P.S. 111	M	Student Toilets
2	M111	P.S. 111	M	Roofs
2	M111	P.S. 111	M	Parapets
2	M111	P.S. 111	M	Exterior Masonry
2	M111	P.S. 111	M	Electrical Systems
2	M114	EAST SIDE MIDDLE SCHOOL	M	IP Digital Video Surveillance System
2	M116	P.S. 116	M	Boiler Conversion
2	M116	P.S. 116	M	Boiler Conversion
2	M116	P.S. 116	M	Climate Control
2	M116	P.S. 116	M	Climate Control
2	M116	P.S. 116	M	Lighting Fixtures
2	M116	P.S. 116	M	Student Toilets
2	M116	P.S. 116	M	Paved Area - Concrete
2	M124	P.S. 124 (ECF)	M	IP Digital Video Surveillance System
2	M124	P.S. 124 (ECF)	M	Waste System
2	M126	P.S. 126	M	Domestic Piping
2	M126	P.S. 126	M	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
2	M126	P.S. 126	M	Heating Plant Upgrade
2	M130	P.S. 130	M	Heating Plant Upgrade
2	M130	P.S. 130	M	New/Retrofit Telephone/Intercom System
2	M130	P.S. 130	M	Toilets - Students
2	M131	I.S. 131	M	Cafeteria / Multipurpose Room Upgrade
2	M131	I.S. 131	M	Student Toilets
2	M131	I.S. 131	M	Accessibility
2	M158	P.S. 158	M	Electrical Systems
2	M158	P.S. 158	M	Heating Plant Upgrade
2	M158	P.S. 158	M	Playgrounds
2	M158	P.S. 158	M	Science Lab Upgrades
2	M167	I.S. 167	M	Cafeteria / Multipurpose Room Upgrade
2	M167	I.S. 167	M	Electrical Systems
2	M167	I.S. 167	M	Exterior Masonry
2	M167	I.S. 167	M	Flood Elimination
2	M167	I.S. 167	M	Parapets
2	M167	I.S. 167	M	Paved Area-Concrete
2	M167	I.S. 167	M	Roofs
2	M167	I.S. 167	M	Student Toilets
2	M167	I.S. 167	M	Windows
2	M167	I.S. 167	M	IP Digital Video Surveillance System
2	M183	P.S. 183	M	Exterior Masonry
2	M183	P.S. 183	M	Flood Elimination
2	M183	P.S. 183	M	Heating Plant Upgrade
2	M183	P.S. 183	M	Lighting Fixtures
2	M183	P.S. 183	M	Lighting Fixtures
2	M183	P.S. 183	M	Parapets
2	M183	P.S. 183	M	Roofs
2	M190	P.S. 290	M	Climate Control
2	M190	P.S. 290	M	Flood Elimination

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
2	M190	P.S. 290	M	New/Retrofit Telephone/Intercom System
2	M190	P.S. 290	M	Parapets
2	M190	P.S. 290	M	Roofs
2	M190	P.S. 290	M	Toilets - Students
2	M198	P.S. 198	M	Boiler Conversion
2	M198	P.S. 198	M	Boiler Conversion
2	M198	P.S. 198	M	Climate Control
2	M198	P.S. 198	M	Climate Control
2	M198	P.S. 198	M	Toilets - Students
2	M267	P.S. 59 (MEETH)	M	Roofs
2	M267	P.S. 59 (MEETH)	M	Exterior Masonry
2	M267	P.S. 59 (MEETH)	M	IP Digital Video Surveillance System
2	M276	P.S./I.S. 276	M	IP Digital Video Surveillance System
2	M660	SCHL OF THE FUTURE (OLD BACON)	M	Electrical Systems
2	M660	SCHL OF THE FUTURE (OLD BACON)	M	Student Toilets
2	M777	FIT	M	Domestic Piping
2	M777	FIT	M	Heating Plant Upgrade
2	M777	FIT	M	Room Conversions/Partitioning
2	M777	FIT	M	Ventilation
2	M777	FIT	M	Ventilation
2	M777	FIT	M	Ventilation
2	M777	FIT	M	Ventilation
2	M816	P.S. 527 - EAST SIDE SCHOOL FOR SOCIAL /	M	Heating Plant Upgrade
3	M009	P.S. 9	M	Lighting Fixtures
3	M009	P.S. 9	M	New/Retrofit Telephone/Intercom System
3	M009	P.S. 9	M	IP Digital Video Surveillance System
3	M044	I.S. 44	M	Student Toilets
3	M054	I.S. 54	M	Electrical Systems
3	M054	I.S. 54	M	Lighting Fixtures
3	M054	I.S. 54	M	Boiler Conversion

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
3	M054	I.S. 54	M	Climate Control
3	M075	P.S. 75	M	Boiler Conversion
3	M075	P.S. 75	M	Climate Control
3	M075	P.S. 75	M	Lighting Fixtures
3	M075	P.S. 75	M	Student Toilets
3	M076	P.S. 76	M	Student Toilets
3	M084	P.S. 84	M	IP Digital Video Surveillance System
3	M084	P.S. 84	M	Waste System
3	M084	P.S. 84	M	Toilets - Students
3	M087	P.S. 87	M	Gymnasium Upgrade
3	M087	P.S. 87	M	Student Toilets
3	M087	P.S. 87	M	Boiler Conversion
3	M087	P.S. 87	M	Climate Control
3	M087	P.S. 87	M	Roofs
3	M087	P.S. 87	M	Parapets
3	M087	P.S. 87	M	Windows
3	M087	P.S. 87	M	Exterior Masonry
3	M087	P.S. 87	M	Domestic Piping
3	M087	P.S. 87	M	Safety Systems
3	M088	I.S. 88	M	Accessibility
3	M088	I.S. 88	M	Auditorium Upgrade
3	M088	I.S. 88	M	Climate Control
3	M088	I.S. 88	M	Gymnasium Upgrade
3	M088	I.S. 88	M	IP Digital Video Surveillance System
3	M088	I.S. 88	M	Lighting Fixtures
3	M088	I.S. 88	M	Science Lab Upgrades
3	M088	I.S. 88	M	Electrical Systems
3	M113	P.S. 241	M	Boiler Conversion
3	M113	P.S. 241	M	Climate Control
3	M113	P.S. 241	M	Electrical Systems



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
3	M113	P.S. 241	M	Lighting Fixtures
3	M113	P.S. 241	M	Student Toilets
3	M118	I.S. 118	M	Accessibility
3	M118	I.S. 118	M	Exterior Masonry
3	M118	I.S. 118	M	Lighting Fixtures
3	M118	I.S. 118	M	Parapets
3	M118	I.S. 118	M	Roofs
3	M118	I.S. 118	M	Elevators and Escalators
3	M144	P.S. 242 (OLD P144)	M	Heating Plant Upgrade
3	M145	P.S. 145	M	Auditorium Upgrade
3	M145	P.S. 145	M	Electrical Systems
3	M149	P.S. 149 (TANDEM M207)	M	Student Toilets
3	M149	P.S. 149 (TANDEM M207)	M	Student Toilets
3	M163	P.S. 163	M	Electrical Systems
3	M163	P.S. 163	M	Lighting Fixtures
3	M163	P.S. 163	M	Playground Redevelopment and TCU Removal
3	M163	P.S. 163	M	Science Lab Upgrades
3	M165	P.S. 165	M	Electrical Systems
3	M165	P.S. 165	M	New/Retrofit Telephone/Intercom System
3	M165	P.S. 165	M	Roofs
3	M165	P.S. 165	M	Student Toilets
3	M165	P.S. 165	M	Emergency Lighting and Fire Safety Retrofits
3	M165	P.S. 165	M	IP Digital Video Surveillance System
3	M166	P.S. 166	M	Electrical Systems
3	M166	P.S. 166	M	IP Digital Video Surveillance System
3	M166	P.S. 166	M	Lighting Fixtures
3	M166	P.S. 166	M	Lighting Fixtures
3	M166	P.S. 166	M	Toilets - Students
3	M180	P.S. 180	M	Classroom Connectivity
3	M185	P.S. 185 (TANDEM M208)	M	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
3	M191	P.S. 191	M	Heating Plant Upgrade
3	M191	P.S. 191	M	Toilets - Students
3	M199	P.S. 199	M	Lighting Fixtures
3	M199	P.S. 199	M	Ventilation
3	M207	P.S. 207 (TANDEM M149)	M	Electrical Systems
3	M207	P.S. 207 (TANDEM M149)	M	Toilets - Students
3	M208	P.S. 208 (TANDEM M185)	M	Electrical Systems
3	M208	P.S. 208 (TANDEM M185)	M	Windows
3	M342	THE RIVERSIDE SCHOOL	M	Paved Area - Concrete
4	M007	P.S. 7	M	Student Toilets
4	M007	P.S. 7	M	IP Digital Video Surveillance System
4	M013	I.S. 13	M	Electrical Systems
4	M013	I.S. 13	M	IP Digital Video Surveillance System
4	M045	I.S. 45	M	Electrical Systems
4	M045	I.S. 45	M	Student Toilets
4	M045	I.S. 45	M	IP Digital Video Surveillance System
4	M050	P.S. 50 (UDC & ECF)	M	Exterior Masonry
4	M050	P.S. 50 (UDC & ECF)	M	Paved Area-Concrete
4	M050	P.S. 50 (UDC & ECF)	M	Student Toilets
4	M057	P.S. 57	M	Electrical Systems
4	M072	P.S. 72	M	Auditorium Upgrade
4	M072	P.S. 72	M	Playground Redevelopment
4	M072	P.S. 72	M	Roofs
4	M072	P.S. 72	M	Science Lab Upgrades
4	M072	P.S. 72	M	Heating Plant Upgrade
4	M083	P.S. 83	M	Boiler Conversion
4	M083	P.S. 83	M	Heating Plant Upgrade
4	M083	P.S. 83	M	Student Toilets
4	M096	P.S. 96	M	Student Toilets
4	M099	I.S. 99	M	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
4	M099	I.S. 99	M	Heating Plant Upgrade
4	M099	I.S. 99	M	Room Conversions/Partitioning
4	M099	I.S. 99	M	Student Toilets
4	M099	I.S. 99	M	IP Digital Video Surveillance System
4	M101	P.S. 101	M	Electrical Systems
4	M101	P.S. 101	M	IP Digital Video Surveillance System
4	M102	P.S. 102	M	Heating Plant Upgrade
4	M102	P.S. 102	M	Roofs
4	M102	P.S. 102	M	Parapets
4	M102	P.S. 102	M	Windows
4	M102	P.S. 102	M	Exterior Masonry
4	M108	P.S. 108	M	Classroom Connectivity
4	M108	P.S. 108	M	Kitchen Areas
4	M108	P.S. 108	M	Low-Voltage Electrical Systems
4	M117	J.H.S. 117	M	Exterior Masonry
4	M117	J.H.S. 117	M	Science Lab Upgrades
4	M117	J.H.S. 117	M	Gymnasium Upgrade
4	M117	J.H.S. 117	M	Electrical Systems
4	M117	J.H.S. 117	M	IP Digital Video Surveillance System
4	M121	P.S. 38 (OLD M121)	M	Student Toilets
4	M121	P.S. 38 (OLD M121)	M	Parapets
4	M121	P.S. 38 (OLD M121)	M	Heating Plant Upgrade
4	M146	P.S. 146	M	Classroom Connectivity
4	M146	P.S. 146	M	Electrical Systems
4	M146	P.S. 146	M	New/Retrofit Telephone/Intercom System
4	M146	P.S. 146	M	Student Toilets
4	M155	P.S. 155	M	Electrical Systems
4	M155	P.S. 155	M	Heating Plant Upgrade
4	M155	P.S. 155	M	Student Toilets
4	M171	P.S. 171	M	Exterior Masonry

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
4	M171	P.S. 171	M	Flood Elimination
4	M171	P.S. 171	M	Heating Plant Upgrade
4	M171	P.S. 171	M	Student Toilets
4	M171	P.S. 171	M	Windows
4	M206	P.S. 206 (TANDEM M112)	M	Electrical Systems
5	M010	I.S. 10 (TANDEM M200)	M	Heating Plant Upgrade
5	M010	I.S. 10 (TANDEM M200)	M	Lighting Fixtures
5	M010	I.S. 10 (TANDEM M200)	M	Science Lab Upgrades
5	M010	I.S. 10 (TANDEM M200)	M	Electrical Systems
5	M010	I.S. 10 (TANDEM M200)	M	IP Digital Video Surveillance System
5	M030	P.S. 30	M	Auditorium Upgrade
5	M030	P.S. 30	M	Electrical Systems
5	M030	P.S. 30	M	IP Digital Video Surveillance System
5	M036	P.S. 36	M	Student Toilets
5	M036	P.S. 36	M	Flood Elimination
5	M036	P.S. 36	M	Exterior Masonry
5	M043	I.S. 172 (OLD 43)	M	Cafeteria / Multipurpose Room Upgrade
5	M043	I.S. 172 (OLD 43)	M	Electrical Systems
5	M043	I.S. 172 (OLD 43)	M	Gymnasium Upgrade
5	M043	I.S. 172 (OLD 43)	M	Heating Plant Upgrade
5	M043	I.S. 172 (OLD 43)	M	IP Digital Video Surveillance System
5	M043	I.S. 172 (OLD 43)	M	School Improvement and Restructuring
5	M043	I.S. 172 (OLD 43)	M	Toilets - Students
5	M046	P.S. 46	M	Lighting Fixtures
5	M092	P.S. 92	M	Accessibility
5	M092	P.S. 92	M	Student Toilets
5	M092	P.S. 92	M	Code Compliance
5	M123	P.S. 123	M	Electrical Systems
5	M123	P.S. 123	M	Student Toilets
5	M123	P.S. 123	M	Code Compliance

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
5	M125	P.S. 125	M	Accessibility
5	M125	P.S. 125	M	Heating Plant Upgrade
5	M125	P.S. 125	M	Flood Elimination
5	M125	P.S. 125	M	Roofs
5	M125	P.S. 125	M	Parapets
5	M125	P.S. 125	M	Exterior Masonry
5	M129	P.S. 129	M	Science Lab Upgrades
5	M129	P.S. 129	M	Student Toilets
5	M129	P.S. 129	M	IP Digital Video Surveillance System
5	M133	P.S. 133	M	Electrical Systems
5	M133	P.S. 133	M	Student Toilets
5	M161	P.S. 161	M	Electrical Systems
5	M161	P.S. 161	M	Heating Plant Upgrade
5	M161	P.S. 161	M	Toilets - Students
5	M161	P.S. 161	M	Code Compliance
5	M175	P.S. 175	M	Heating Plant Upgrade
5	M175	P.S. 175	M	IP Digital Video Surveillance System
5	M194	P.S. 194	M	Classroom Connectivity
5	M194	P.S. 194	M	Student Toilets
5	M195	TERENCE D. TOLBERT EDUCATION COMPLE	M	Electrical Systems
5	M195	TERENCE D. TOLBERT EDUCATION COMPLE	M	Roofs
5	M197	P.S. 197	M	Electrical Systems
5	M197	P.S. 197	M	Student Toilets
5	M200	P.S. 200 (TANDEM M010)	M	Student Toilets
5	M916	TEACHERS COLLEGE COMMUNITY SCHOOL	M	IP Digital Video Surveillance System
6	M004	P.S. 4	M	Exterior Masonry
6	M004	P.S. 4	M	Gymnasium Upgrade
6	M004	P.S. 4	M	Accessibility
6	M004	P.S. 4	M	Science Lab Upgrades
6	M005	P.S. 5	M	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
6	M005	P.S. 5	M	Playground Redevelopment and TCU Removal
6	M005	P.S. 5	M	Playgrounds
6	M005	P.S. 5	M	Windows
6	M008	P.S. 8	M	Heating Plant Upgrade
6	M008	P.S. 8	M	Toilets - Students
6	M028	P.S. 28	M	Lighting Fixtures
6	M028	P.S. 28	M	Boiler Conversion
6	M028	P.S. 28	M	Climate Control
6	M028	P.S. 28	M	Domestic Piping
6	M048	P.S. 48	M	Code Compliance
6	M048	P.S. 48	M	Domestic Piping
6	M048	P.S. 48	M	Low-Voltage Electrical Systems
6	M048	P.S. 48	M	Playground Redevelopment and TCU Removal
6	M052	I.S. 52	M	Exterior Masonry
6	M052	I.S. 52	M	School Improvement and Restructuring
6	M052	I.S. 52	M	Student Toilets
6	M052	I.S. 52	M	IP Digital Video Surveillance System
6	M090	I.S. 90	M	Accessibility
6	M090	I.S. 90	M	Climate Control
6	M090	I.S. 90	M	Heating Plant Upgrade
6	M090	I.S. 90	M	Heating Plant Upgrade
6	M090	I.S. 90	M	Student Toilets
6	M090	I.S. 90	M	IP Digital Video Surveillance System
6	M093	P.S./I.S. 210	M	IP Digital Video Surveillance System
6	M093	P.S./I.S. 210	M	Accessibility
6	M115	P.S. 115	M	Heating Plant Upgrade
6	M115	P.S. 115	M	Lighting Fixtures
6	M115	P.S. 115	M	Student Toilets
6	M115	P.S. 115	M	Reinforcing Support Elements
6	M128	P.S. 128	M	Boiler Conversion

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
6	M128	P.S. 128	M	Climate Control
6	M128	P.S. 128	M	Student Toilets
6	M128	P.S. 128	M	Heating Plant Upgrade
6	M132	P.S. 132	M	Heating Plant Upgrade
6	M132	P.S. 132	M	Electrical Systems
6	M143	I.S. 143	M	Science Lab Upgrades
6	M143	I.S. 143	M	Student Toilets
6	M143	I.S. 143	M	Electrical Systems
6	M152	P.S. 152	M	Electrical Systems
6	M152	P.S. 152	M	Lighting Fixtures
6	M152	P.S. 152	M	Student Toilets
6	M153	P.S. 153	M	Heating Plant Upgrade
6	M164	I.S. 164	M	IP Digital Video Surveillance System
6	M164	I.S. 164	M	Lighting Fixtures
6	M164	I.S. 164	M	Student Toilets
6	M173	P.S. 173	M	Electrical Systems
6	M173	P.S. 173	M	Exterior Masonry
6	M173	P.S. 173	M	Flood Elimination
6	M173	P.S. 173	M	Heating Plant Upgrade
6	M173	P.S. 173	M	Parapets
6	M173	P.S. 173	M	Paved Area-Concrete
6	M173	P.S. 173	M	Roofs
6	M178	P.S. 178	M	Heating Plant Upgrade
6	M187	P.S./I.S. 187	M	Student Toilets
6	M189	P.S. 189	M	Flood Elimination
6	M189	P.S. 189	M	Heating Plant Upgrade
6	M189	P.S. 189	M	Parapets
6	M189	P.S. 189	M	Roofs
6	M189	P.S. 189	M	Student Toilets
6	M189	P.S. 189	M	Exterior Masonry

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
6	M189	P.S. 189	M	Playgrounds
6	M192	P.S. 192	M	Classroom Connectivity
6	M192	P.S. 192	M	New/Retrofit Telephone/Intercom System
6	M192	P.S. 192	M	Science Lab Upgrades
6	M218	I.S. 218	M	Electrical Systems
6	M218	I.S. 218	M	Heating Plant Upgrade
6	M218	I.S. 218	M	IP Digital Video Surveillance System
6	M233	ALTERNATIVE LEARNING CENTER	M	Electrical Systems
6	M263	P.S./I.S. 263	M	Classroom Connectivity
6	M263	P.S./I.S. 263	M	IP Digital Video Surveillance System
6	M528	I.S. 528	M	Classroom Connectivity
6	M528	I.S. 528	M	Windows
6	M814	THE COMMUNITY HEALTH ACADEMY OF THI	M	Gymnasium Upgrade
6	M814	THE COMMUNITY HEALTH ACADEMY OF THI	M	Accessibility
6	M847	P.S. 178 MINISCHOOL	M	Low-Voltage Electrical Systems
6	M847	P.S. 178 MINISCHOOL	M	Playgrounds
6	M847	P.S. 178 MINISCHOOL	M	Playgrounds
6	M848	P.S. 192 MINISCHOOL	M	Student Toilets
6	M859	I.S. 143 MINISCHOOL	M	Student Toilets
6	M898	P.S. 18	M	Student Toilets
6	M965	I.S. 349	M	Cafeteria / Multipurpose Room Upgrade
7	X001	P.S. 1	X	Heating Plant Upgrade
7	X001	P.S. 1	X	Lighting Fixtures
7	X005	P.S. 5	X	Heating Plant Upgrade
7	X018	P.S. 18	X	Student Toilets
7	X018	P.S. 18	X	Electrical Systems
7	X018	P.S. 18	X	Emergency Lighting and Fire Safety Retrofits
7	X025	P.S. 25	X	Student Toilets
7	X025	P.S. 25	X	Heating Plant Upgrade
7	X027	P.S. 277	X	Electrical Systems



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
7	X027	P.S. 277	X	Student Toilets
7	X027	P.S. 277	X	Flood Elimination
7	X027	P.S. 277	X	Roofs
7	X027	P.S. 277	X	Exterior Masonry
7	X029	P.S. 29	X	Exterior Masonry
7	X029	P.S. 29	X	Flood Elimination
7	X029	P.S. 29	X	Parapets
7	X029	P.S. 29	X	IP Digital Video Surveillance System
7	X030	P.S. 30	X	Electrical Systems
7	X030	P.S. 30	X	Heating Plant Upgrade
7	X030	P.S. 30	X	Heating Plant Upgrade
7	X043	P.S. 43	X	Classroom Connectivity
7	X043	P.S. 43	X	Electrical Systems
7	X043	P.S. 43	X	Heating Plant Upgrade
7	X049	P.S. 49	X	Classroom Connectivity
7	X049	P.S. 49	X	Student Toilets
7	X049	P.S. 49	X	Electrical Systems
7	X065	P.S. 65	X	Electrical Systems
7	X065	P.S. 65	X	Heating Plant Upgrade
7	X065	P.S. 65	X	Student Toilets
7	X065	P.S. 65	X	Roofs
7	X065	P.S. 65	X	Parapets
7	X065	P.S. 65	X	Exterior Masonry
7	X139	J.H.S. 222	X	Electrical Systems
7	X139	J.H.S. 222	X	Heating Plant Upgrade
7	X139	J.H.S. 222	X	IP Digital Video Surveillance System
7	X139	J.H.S. 222	X	New/Retrofit Telephone/Intercom System
7	X139	J.H.S. 222	X	Student Toilets
7	X149	J.H.S. 149	X	Science Lab Upgrades
7	X149	J.H.S. 149	X	Roofs

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
7	X149	J.H.S. 149	X	Emergency Lighting and Fire Safety Retrofits
7	X151	I.S. 151	X	Student Toilets
7	X151	I.S. 151	X	Containerization
7	X154	P.S. 154	X	Electrical Systems
7	X154	P.S. 154	X	Heating Plant Upgrade
7	X156	P.S. 156	X	Electrical Systems
7	X156	P.S. 156	X	New/Retrofit Telephone/Intercom System
7	X156	P.S. 156	X	Student Toilets
7	X156	P.S. 156	X	Roofs
7	X156	P.S. 156	X	Parapets
7	X156	P.S. 156	X	Exterior Masonry
7	X156	P.S. 156	X	Science Lab Upgrades
7	X157	P.S. 157	X	Student Toilets
7	X157	P.S. 157	X	Windows
7	X157	P.S. 157	X	Electrical Systems
7	X157	P.S. 157	X	Emergency Lighting and Fire Safety Retrofits
7	X161	P.S. 161	X	Heating Plant Upgrade
7	X161	P.S. 161	X	Heating Plant Upgrade
7	X161	P.S. 161	X	Heating Plant Upgrade
7	X161	P.S. 161	X	Low-Voltage Electrical System
7	X161	P.S. 161	X	Accessibility
7	X162	I.S. 162	X	Cafeteria / Multipurpose Room Upgrade
7	X162	I.S. 162	X	Gymnasium Upgrade
7	X162	I.S. 162	X	Heating Plant Upgrade
7	X162	I.S. 162	X	Elevators and Escalators
7	X162	I.S. 162	X	IP Digital Video Surveillance System
7	X183	J.H.S. 203	X	Flood Elimination
7	X183	J.H.S. 203	X	Parapets
7	X183	J.H.S. 203	X	Roofs
7	X183	J.H.S. 203	X	Exterior Masonry

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
7	X183	J.H.S. 203	X	Toilets - Students
7	X183	J.H.S. 203	X	IP Digital Video Surveillance System
7	X184	I.S. 184	X	Electrical Systems
7	X184	I.S. 184	X	Heating Plant Upgrade
7	X184	I.S. 184	X	Student Toilets
7	X184	I.S. 184	X	Student Toilets
7	X184	I.S. 184	X	IP Digital Video Surveillance System
7	X478	P.S. 65 GYM ANNEX	X	Gymnasiums
7	X855	P.S. 30 ANNEX	X	Electrical Systems
7	X855	P.S. 30 ANNEX	X	New/Retrofit Telephone/Intercom System
8	X014	P.S. 14	X	Exterior Masonry
8	X014	P.S. 14	X	Flood Elimination
8	X014	P.S. 14	X	Parapets
8	X014	P.S. 14	X	Windows
8	X014	P.S. 14 ADDITION	X	Roofs
8	X036	P.S. 36	X	Exterior Masonry
8	X036	P.S. 36	X	IP Digital Video Surveillance System
8	X036	P.S. 36	X	Parapets
8	X036	P.S. 36	X	Roofs
8	X036	P.S. 36	X	Safety Systems
8	X036	P.S. 36	X	Windows
8	X036	P.S. 36	X	Electrical Systems
8	X048	P.S. 48	X	Flood Elimination
8	X048	P.S. 48	X	Roofs
8	X052	I.S. 302	X	Lighting Fixtures
8	X052	I.S. 302	X	IP Digital Video Surveillance System
8	X060	P.S. 333	X	Heating Plant Upgrade
8	X060	P.S. 333	X	New/Retrofit Telephone/Intercom System
8	X062	P.S. 62	X	Heating Plant Upgrade
8	X062	P.S. 62	X	Parapets

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
8	X062	P.S. 62	X	Student Toilets
8	X062	P.S. 62	X	Domestic Piping
8	X069	P.S. 69	X	Classroom Connectivity
8	X069	P.S. 69	X	IP Digital Video Surveillance System
8	X071	P.S. 71	X	Exterior Masonry
8	X071	P.S. 71	X	Flood Elimination
8	X071	P.S. 71	X	Lighting Fixtures
8	X071	P.S. 71	X	Parapets
8	X071	P.S. 71	X	Roofs
8	X071	P.S. 71	X	Student Toilets
8	X071	P.S. 71	X	Student Toilets
8	X072	P.S. 72	X	Heating Plant Upgrade
8	X072	P.S. 72	X	IP Digital Video Surveillance System
8	X072	P.S. 72	X	New/Retrofit Telephone/Intercom System
8	X072	P.S. 72	X	Electrical Systems
8	X072	P.S. 72	X	Emergency Lighting and Fire Safety Retrofits
8	X074	I.S. 201	X	Heating Plant Upgrade
8	X074	I.S. 201	X	Lighting Fixtures
8	X074	I.S. 201	X	Accessibility
8	X075	P.S. 75	X	Interior Spaces
8	X075	P.S. 75	X	Playground Redevelopment
8	X075	P.S. 75	X	Playgrounds
8	X075	P.S. 75	X	Electrical Systems
8	X093	P.S. 93	X	Electrical Systems
8	X093	P.S. 93	X	Playground Redevelopment
8	X093	P.S. 93	X	Roofs
8	X093	P.S. 93	X	Parapets
8	X093	P.S. 93	X	Exterior Masonry
8	X100	P.S. 100	X	Heating Plant Upgrade
8	X101	I.S. 101	X	Domestic Piping

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
8	X101	I.S. 101	X	Lighting Fixtures
8	X101	I.S. 101	X	Student Toilets
8	X101	I.S. 101	X	Roofs
8	X101	I.S. 101	X	Exterior Masonry
8	X107	P.S. 107	X	Heating Plant Upgrade
8	X107	P.S. 107	X	Lighting Fixtures
8	X107	P.S. 107	X	Student Toilets
8	X119	P.S. 119	X	Parapets
8	X119	P.S. 119	X	Electrical Systems
8	X119	P.S. 119	X	Heating Plant Upgrade
8	X119	P.S. 119	X	Playground Redevelopment
8	X120	I.S. 301	X	Electrical Systems
8	X120	I.S. 301	X	Heating Plant Upgrade
8	X120	I.S. 301	X	Roofs
8	X120	I.S. 301	X	Parapets
8	X120	I.S. 301	X	Exterior Masonry
8	X123	I.S. 123	X	Boiler Conversion
8	X123	I.S. 123	X	Climate Control
8	X123	I.S. 123	X	Heating Plant Upgrade
8	X123	I.S. 123	X	Electrical Systems
8	X123	I.S. 123	X	IP Digital Video Surveillance System
8	X125	I.S. 125	X	Lighting Fixtures
8	X125	I.S. 125	X	Student Toilets
8	X125	I.S. 125	X	Boiler Conversion
8	X125	I.S. 125	X	Climate Control
8	X125	I.S. 125	X	Low-Voltage Electrical System
8	X125	I.S. 125	X	Electrical Systems
8	X125	I.S. 125	X	IP Digital Video Surveillance System
8	X130	P.S. 130	X	Classroom Connectivity
8	X130	P.S. 130	X	Exterior Masonry

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
8	X130	P.S. 130	X	Flood Elimination
8	X130	P.S. 130	X	Heating Plant Upgrade
8	X130	P.S. 130	X	New/Retrofit Telephone/Intercom System
8	X130	P.S. 130	X	Parapets
8	X130	P.S. 130	X	Roofs
8	X131	I.S. 131	X	Electrical Systems
8	X131	I.S. 131	X	Exterior Masonry
8	X131	I.S. 131	X	Heating Plant Upgrade
8	X131	I.S. 131	X	Student Toilets
8	X138	P.S. 138	X	Auditorium Upgrade
8	X138	P.S. 138	X	IP Digital Video Surveillance System
8	X140	P.S. 140	X	Heating Plant Upgrade
8	X152	P.S. 152	X	Toilets - Students
8	X174	I.S. 174	X	Cafeteria / Multipurpose Room Upgrade
8	X174	I.S. 174	X	Exterior Masonry
8	X174	I.S. 174	X	Flood Elimination
8	X174	I.S. 174	X	Heating Plant Upgrade
8	X174	I.S. 174	X	IP Digital Video Surveillance System
8	X174	I.S. 174	X	Lighting Fixtures
8	X174	I.S. 174	X	Parapets
8	X174	I.S. 174	X	Paved Area-Concrete
8	X174	I.S. 174	X	Roofs
8	X174	I.S. 174	X	Student Toilets
8	X182	P.S. 182	X	Electrical Systems
8	X182	P.S. 182	X	Lighting Fixtures
8	X182	P.S. 182	X	Reinforcing Support Elements
8	X182	P.S. 182	X	Roofs
8	X182	P.S. 182	X	Paved Area - Concrete
8	X182	P.S. 182	X	Exterior Masonry
8	X182	P.S. 182	X	Domestic Piping

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
8	X192	I.S. 192	X	Exterior Masonry
8	X192	I.S. 192	X	Heating Plant Upgrade
8	X192	I.S. 192	X	Parapets
8	X192	I.S. 192	X	Student Toilets
8	X192	I.S. 192	X	Electrical Systems
8	X848	P.S. 48 AX (HNTS PNT ECC1)	X	Electrical Systems
8	X848	P.S. 48 AX (HNTS PNT ECC1)	X	Parapets
8	X848	P.S. 48 AX (HNTS PNT ECC1)	X	Roofs
8	X848	P.S. 48 AX (HNTS PNT ECC1)	X	Windows
8	X880	P.S. 69 ANNEX	X	Electrical Systems
9	X002	MORRISANIA SEC ED COMPLEX	X	Electrical Systems
9	X002	MORRISANIA SEC ED COMPLEX	X	Heating Plant Upgrade
9	X002	MORRISANIA SEC ED COMPLEX	X	School Improvement and Restructuring
9	X004	P.S. 4	X	Electrical Systems
9	X004	P.S. 4	X	Heating Plant Upgrade
9	X004	P.S. 4	X	New/Retrofit Telephone/Intercom System
9	X004	P.S. 4	X	IP Digital Video Surveillance System
9	X011	P.S. 11	X	Electrical Systems
9	X011	P.S. 11	X	IP Digital Video Surveillance System
9	X011	P.S. 11	X	Student Toilets
9	X022	I.S. 22	X	IP Digital Video Surveillance System
9	X022	I.S. 22	X	Lighting Fixtures
9	X022	I.S. 22	X	Student Toilets
9	X028	P.S. 28	X	Heating Plant Upgrade
9	X028	P.S. 28	X	Playground Redevelopment and TCU Removal
9	X028	P.S. 28	X	Student Toilets
9	X028	P.S. 28	X	Electrical Systems
9	X028	P.S. 28	X	Emergency Lighting and Fire Safety Retrofits
9	X035	P.S. 35	X	Parapets
9	X035	P.S. 35	X	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
9	X042	P.S. 42	X	Exterior Masonry
9	X042	P.S. 42	X	Flood Elimination
9	X042	P.S. 42	X	Parapets
9	X042	P.S. 42	X	Roofs
9	X053	P.S. 53	X	Heating Plant Upgrade
9	X053	P.S. 53	X	Parapets
9	X053	P.S. 53	X	Exterior Masonry
9	X055	P.S. 55	X	Heating Plant Upgrade
9	X055	P.S. 55	X	Student Toilets
9	X055	P.S. 55	X	Low-Voltage Electrical System
9	X058	P.S. 58	X	Lighting Fixtures
9	X058	P.S. 58	X	Student Toilets
9	X063	P.S. 63	X	Classroom Connectivity
9	X063	P.S. 63	X	Student Toilets
9	X064	P.S. 64	X	Electrical Systems
9	X064	P.S. 64	X	New/Retrofit Telephone/Intercom System
9	X070	P.S. 70	X	Parapets
9	X070	P.S. 70	X	Roofs
9	X073	P.S. 73	X	Exterior Masonry
9	X073	P.S. 73	X	Flood Elimination
9	X073	P.S. 73	X	Lighting Fixtures
9	X073	P.S. 73	X	Parapets
9	X073	P.S. 73	X	Student Toilets
9	X073	P.S. 73	X	Containerization
9	X082	I.S. 232	X	Domestic Piping
9	X082	I.S. 232	X	Flood Elimination
9	X082	I.S. 232	X	Heating Plant Upgrade
9	X082	I.S. 232	X	Student Toilets
9	X082	I.S. 232	X	Low-Voltage Electrical System
9	X082	I.S. 232	X	Parapets



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
9	X082	I.S. 232	X	Exterior Masonry
9	X082	I.S. 232	X	IP Digital Video Surveillance System
9	X090	P.S. 90	X	New/Retrofit Telephone/Intercom System
9	X104	P.S. 199	X	Flood Elimination
9	X109	P.S. 109	X	Electrical Systems
9	X109	P.S. 109	X	Exterior Masonry
9	X109	P.S. 109	X	Flood Elimination
9	X109	P.S. 109	X	Heating Plant Upgrade
9	X109	P.S. 109	X	Heating Plant Upgrade
9	X109	P.S. 109	X	Heating Plant Upgrade
9	X109	P.S. 109	X	Lighting Fixtures
9	X109	P.S. 109	X	Parapets
9	X109	P.S. 109	X	Roofs
9	X109	P.S. 109	X	Student Toilets
9	X110	P.S. 110	X	Electrical Systems
9	X114	P.S. 114	X	Heating Plant Upgrade
9	X114	P.S. 114	X	Student Toilets
9	X114	P.S. 114	X	Boiler Conversion
9	X114	P.S. 114	X	Climate Control
9	X117	I.S. 117	X	Cafeteria / Multipurpose Room Upgrade
9	X117	I.S. 117	X	Student Toilets
9	X126	P.S. 126 (ECF)	X	Heating Plant Upgrade
9	X132	P.S. 132	X	Heating Plant Upgrade
9	X132	P.S. 132	X	Student Toilets
9	X132	P.S. 132	X	Accessibility
9	X132	P.S. 132	X	IP Digital Video Surveillance System
9	X145	I.S. 145	X	Electrical Systems
9	X145	I.S. 145	X	Heating Plant Upgrade
9	X145	I.S. 145	X	Emergency Lighting and Fire Safety Retrofits
9	X147	I.S. 339 (OLD 147)	X	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
9	X147	I.S. 339 (OLD 147)	X	Exterior Masonry
9	X147	I.S. 339 (OLD 147)	X	Student Toilets
9	X147	I.S. 339 (OLD 147)	X	Windows
9	X147	I.S. 339 (OLD 147)	X	IP Digital Video Surveillance System
9	X148	I.S. 219 (OLD 148)	X	Heating Plant Upgrade
9	X148	I.S. 219 (OLD 148)	X	IP Digital Video Surveillance System
9	X148	I.S. 219 (OLD 148)	X	Electrical Systems
9	X166	I.S. 166	X	Heating Plant Upgrade
9	X166	I.S. 166	X	Toilets - Students
9	X166	I.S. 166	X	IP Digital Video Surveillance System
9	X170	P.S. 170 (ECC)	X	Classroom Connectivity
9	X170	P.S. 170 (ECC)	X	New/Retrofit Telephone/Intercom System
9	X170	P.S. 170 (ECC)	X	Exterior Masonry
9	X171	P.S. 4 ANNEX (P171 ECC)	X	Heating Plant Upgrade
9	X172	P.S. 11 ANNEX (P172 ECC)	X	Flood Elimination
9	X172	P.S. 11 ANNEX (P172 ECC)	X	New/Retrofit Telephone/Intercom System
9	X229	P.S. 230/I.S. 229 (UDC)	X	Domestic Piping
9	X229	P.S. 230/I.S. 229 (UDC)	X	Lighting Fixtures
9	X229	P.S. 230/I.S. 229 (UDC)	X	Low-Voltage Electrical Systems
9	X229	P.S. 230/I.S. 229 (UDC)	X	IP Digital Video Surveillance System
9	X235	P.S./I.S. 218	X	Accessibility
9	X235	P.S./I.S. 218	X	Domestic Piping
9	X235	P.S./I.S. 218	X	Domestic Piping
9	X235	P.S./I.S. 218	X	Heating Plant Upgrade
9	X235	P.S./I.S. 218	X	Lighting Fixtures
9	X338	MORRIS HEIGHTS EDUCATIONAL COMPLEX	X	Accessibility
9	X338	MORRIS HEIGHTS EDUCATIONAL COMPLEX	X	IP Digital Video Surveillance System
9	X862	P.S. 63 MINISCHOOL	X	Low-Voltage Electrical Systems
9	X980	P.S. 204 ANNEX	X	Electrical Systems
10	X003	P.S. 3	X	Heating Plant Upgrade

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
10	X003	P.S. 3	X	Paved Area-Concrete
10	X003	P.S. 3	X	Roofs
10	X003	P.S. 3	X	Ventilation
10	X007	P.S. 7	X	Electrical Systems
10	X007	P.S. 7	X	Lighting Fixtures
10	X008	P.S. 8	X	Electrical Systems
10	X009	P.S. 9 (OLD 115)	X	Boiler Conversion
10	X009	P.S. 9 (OLD 115)	X	Climate Control
10	X009	P.S. 9 (OLD 115)	X	Lighting Fixtures
10	X015	P.S. 15	X	Flood Elimination
10	X020	P.S. 20	X	Auditorium Upgrade
10	X020	P.S. 20	X	Gymnasium Upgrade
10	X020	P.S. 20	X	Heating Plant Upgrade
10	X020	P.S. 20	X	Roofs
10	X024	P.S. 24	X	Lighting Fixtures
10	X026	P.S. 396	X	Heating Plant Upgrade
10	X026	P.S. 396	X	Student Toilets
10	X032	P.S. 32	X	Heating Plant Upgrade
10	X033	P.S. 33	X	Lighting Fixtures
10	X033	P.S. 33	X	Student Toilets
10	X037	P.S. 37	X	Flood Elimination
10	X037	P.S. 37	X	Heating Plant Upgrade
10	X037	P.S. 37	X	New/Retrofit Telephone/Intercom System
10	X045	I.S. 45	X	Student Toilets
10	X046	P.S. 46 ADDITION	X	Heating Plant Upgrade
10	X046	P.S. 46	X	Student Toilets
10	X059	P.S. 59	X	Student Toilets
10	X079	P.S. 79	X	Cafeteria / Multipurpose Room Upgrade
10	X079	P.S. 79	X	Exterior Masonry
10	X079	P.S. 79	X	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
10	X080	I.S. 80/P.S. 280	X	Accessibility
10	X080	I.S. 80/P.S. 280	X	Electrical Systems
10	X080	I.S. 80/P.S. 280	X	Heating Plant Upgrade
10	X080	I.S. 80/P.S. 280	X	Lighting Fixtures
10	X080	I.S. 80/P.S. 280	X	Playground Redevelopment and TCU Removal
10	X081	P.S. 81	X	Exterior Masonry
10	X081	P.S. 81	X	Flood Elimination
10	X081	P.S. 81	X	Heating Plant Upgrade
10	X081	P.S. 81	X	Roofs
10	X081	P.S. 81	X	Student Toilets
10	X085	P.S. 85	X	Classroom Connectivity
10	X085	P.S. 85	X	Flood Elimination
10	X085	P.S. 85	X	Lighting Fixtures
10	X085	P.S. 85	X	Parapets
10	X085	P.S. 85	X	Playgrounds
10	X085	P.S. 85	X	Roofs
10	X085	P.S. 85	X	Safety Systems
10	X085	P.S. 85	X	Student Toilets
10	X086	P.S. 86	X	Electrical Systems
10	X086	P.S. 86	X	Student Toilets
10	X091	P.S. 91	X	Floors
10	X091	P.S. 91	X	Heating Plant Upgrade
10	X091	P.S. 91	X	Lighting Fixtures
10	X091	P.S. 91	X	Student Toilets
10	X094	P.S. 94	X	Student Toilets
10	X095	P.S. 95	X	Exterior Masonry
10	X095	P.S. 95	X	Parapets
10	X115	I.S. 399 (OLD X HS/115)	X	Accessibility
10	X115	I.S. 399 (OLD X HS/115)	X	Heating Plant Upgrade
10	X115	I.S. 399 (OLD X HS/115)	X	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
10	X115	I.S. 399 (OLD X HS/115)	X	New/Retrofit Telephone/Intercom System
10	X115	I.S. 399 (OLD X HS/115)	X	Roofs
10	X122	P.S. 310	X	IP Digital Video Surveillance System
10	X122	P.S. 310	X	Lighting Fixtures
10	X137	I.S. 391 (UDC)	X	Accessibility
10	X137	I.S. 391 (UDC)	X	IP Digital Video Surveillance System
10	X141	M.S./H.S. 141	X	Accessibility
10	X141	M.S./H.S. 141	X	IP Digital Video Surveillance System
10	X143	I.S. 143	X	Exterior Masonry
10	X143	I.S. 143	X	Flood Elimination
10	X143	I.S. 143	X	Lighting Fixtures
10	X143	I.S. 143	X	Parapets
10	X143	I.S. 143	X	Roofs
10	X143	I.S. 143	X	Student Toilets
10	X205	P.S. 205A (ECF)	X	New/Retrofit Telephone/Intercom System
10	X206	I.S. 206B	X	Heating Plant Upgrade
10	X206	I.S. 206B	X	Student Toilets
10	X254	I.S. 254	X	Classroom Connectivity
10	X254	I.S. 254	X	Exterior Masonry
10	X254	I.S. 254	X	Roofs
10	X279	P.S. 279	X	Classroom Connectivity
10	X279	P.S. 279	X	New/Retrofit Telephone/Intercom System
10	X306	P.S. 306	X	Heating Plant Upgrade
10	X360	P.S. 360	X	Heating Plant Upgrade
10	X368	M.S./H.S. 368	X	Exterior Masonry
10	X368	M.S./H.S. 368	X	IP Digital Video Surveillance System
10	X826	P.S. 226 MINISCHOOL	X	Classroom Connectivity
10	X826	P.S. 226 MINISCHOOL	X	Exterior Masonry
10	X826	P.S. 226 MINISCHOOL	X	Flood Elimination
10	X826	P.S. 226 MINISCHOOL	X	New/Retrofit Telephone/Intercom System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
10	X826	P.S. 226 MINISCHOOL	X	Roofs
10	X832	P.S. 32 MINISCHOOL	X	Heating Plant Upgrade
10	X843	P.S. 246 (POE CENTER)	X	Elevators and Escalators
10	X843	P.S. 246 (POE CENTER)	X	Exterior Masonry
10	X843	P.S. 246 (POE CENTER)	X	Flood Elimination
10	X843	P.S. 246 (POE CENTER)	X	Parapets
10	X843	P.S. 246 (POE CENTER)	X	Paved Area-Concrete
10	X843	P.S. 246 (POE CENTER)	X	Roofs
11	X016	P.S. 16	X	Flood Elimination
11	X016	P.S. 16	X	Lighting Fixtures
11	X016	P.S. 16	X	Low-Voltage Electrical Systems
11	X016	P.S. 16	X	Paved Area-Concrete
11	X016	P.S. 16	X	Student Toilets
11	X021	P.S. 21	X	Heating Plant Upgrade
11	X021	P.S. 21	X	IP Digital Video Surveillance System
11	X041	P.S. 41	X	Boiler Conversion
11	X041	P.S. 41	X	Climate Control
11	X041	P.S. 41	X	Heating Plant Upgrade
11	X041	P.S. 41	X	Lighting Fixtures
11	X041	P.S. 41	X	Student Toilets
11	X068	P.S. 68	X	Auditorium Upgrade
11	X068	P.S. 68	X	Electrical Systems
11	X068	P.S. 68	X	Flood Elimination
11	X068	P.S. 68	X	Heating Plant Upgrade
11	X068	P.S. 68	X	Student Toilets
11	X076	P.S. 76	X	Heating Plant Upgrade
11	X076	P.S. 76	X	Playground Redevelopment
11	X078	P.S. 78	X	Playground Redevelopment
11	X078	P.S. 78	X	Student Toilets
11	X083	P.S. 83	X	Domestic Piping

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
11	X083	P.S. 83	X	Heating Plant Upgrade
11	X083	P.S. 83	X	Heating Plant Upgrade
11	X083	P.S. 83	X	New/Retrofit Telephone/Intercom System
11	X083	P.S. 83	X	New/Retrofit Telephone/Intercom System
11	X087	P.S. 87	X	Electrical Systems
11	X087	P.S. 87	X	New/Retrofit Telephone/Intercom System
11	X087	P.S. 87	X	Student Toilets
11	X089	P.S. 89	X	Electrical Systems
11	X089	P.S. 89	X	Flood Elimination
11	X089	P.S. 89	X	Heating Plant Upgrade
11	X089	P.S. 89	X	Lighting Fixtures
11	X096	P.S. 96	X	Electrical Systems
11	X097	P.S. 97	X	New/Retrofit Telephone/Intercom System
11	X097	P.S. 97	X	Playground Redevelopment
11	X103	P.S. 103	X	Lighting Fixtures
11	X105	P.S. 105	X	Low-Voltage Electrical Systems
11	X105	P.S. 105	X	Parapets
11	X105	P.S. 105	X	Student Toilets
11	X108	P.S. 108	X	New/Retrofit Telephone/Intercom System
11	X108	P.S. 108	X	Playground Redevelopment
11	X111	P.S. 111	X	Heating Plant Upgrade
11	X111	P.S. 111	X	Lighting Fixtures
11	X112	P.S. 112	X	Electrical Systems
11	X112	P.S. 112	X	Lighting Fixtures
11	X113	I.S. 113	X	Cafeteria / Multipurpose Room Upgrade
11	X113	I.S. 113	X	IP Digital Video Surveillance System
11	X113	I.S. 113	X	New/Retrofit Telephone/Intercom System
11	X113	I.S. 113	X	Student Toilets
11	X121	P.S. 121	X	Heating Plant Upgrade
11	X121	P.S. 121	X	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
11	X121	P.S. 121	X	Student Toilets
11	X127	I.S. 127	X	Accessibility
11	X127	I.S. 127	X	Electrical Systems
11	X127	I.S. 127	X	Heating Plant Upgrade
11	X127	I.S. 127	X	Lighting Fixtures
11	X135	I.S. 135	X	Electrical Systems
11	X135	I.S. 135	X	Heating Plant Upgrade
11	X135	I.S. 135	X	Interior Spaces
11	X135	I.S. 135	X	Student Toilets
11	X142	I.S. 142	X	Flood Elimination
11	X142	I.S. 142	X	Heating Plant Upgrade
11	X142	I.S. 142	X	IP Digital Video Surveillance System
11	X144	I.S. 144	X	Boiler Conversion
11	X144	I.S. 144	X	Climate Control
11	X144	I.S. 144	X	Heating Plant Upgrade
11	X160	P.S. 160	X	Low-Voltage Electrical Systems
11	X169	THE WILLIE ELLA PASCHAL BOWMAN CAMP	X	Low-Voltage Electrical Systems
11	X175	P.S. 175	X	Heating Plant Upgrade
11	X178	P.S. 178	X	Domestic Piping
11	X178	P.S. 178	X	IP Digital Video Surveillance System
11	X178	P.S. 178	X	Windows
11	X189	P.S./I.S. 189 (@STEENWICK AVE)	X	IP Digital Video Surveillance System
11	X194	P.S./I.S. 194	X	Gymnasium Upgrade
11	X498	THE LT. CURTIS MEYRAN AND JOHN BELLEV	X	Accessibility
11	X498	THE LT. CURTIS MEYRAN AND JOHN BELLEV	X	Low-Voltage Electrical Systems
11	XADY	SAINT LUCY ELEMENTARY SCHOOL	X	Technology
12	X044	P.S. 44	X	IP Digital Video Surveillance System
12	X044	P.S. 44	X	Parapets
12	X044	P.S. 44	X	Roofs
12	X047	P.S. 47	X	Exterior Masonry



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
12	X047	P.S. 47	X	Flood Elimination
12	X047	P.S. 47	X	Heating Plant Upgrade
12	X047	P.S. 47	X	Lighting Fixtures
12	X047	P.S. 47	X	Parapets
12	X047	P.S. 47	X	Roofs
12	X050	P.S. 50	X	Student Toilets
12	X057	P.S. 57	X	Classroom Connectivity
12	X057	P.S. 57	X	Heating Plant Upgrade
12	X057	P.S. 57	X	Student Toilets
12	X066	P.S. 66	X	Heating Plant Upgrade
12	X067	P.S. 67	X	Heating Plant Upgrade
12	X067	P.S. 67	X	Heating Plant Upgrade
12	X067	P.S. 67	X	Student Toilets
12	X077	P.S. 195	X	Electrical Systems
12	X092	P.S. 92	X	Lighting Fixtures
12	X092	P.S. 92	X	Parapets
12	X098	I.S. 98	X	Heating Plant Upgrade
12	X098	I.S. 98	X	Student Toilets
12	X102	P.S. 102	X	Accessibility
12	X102	P.S. 102	X	Heating Plant Upgrade
12	X102	P.S. 102	X	Lighting Fixtures
12	X102	P.S. 102	X	Roofs
12	X116	I.S. 216	X	Electrical Systems
12	X129	I.S. 129 (PAIRED W P234)	X	Accessibility
12	X129	I.S. 129 (PAIRED W P234)	X	Cafeteria / Multipurpose Room Upgrade
12	X129	I.S. 129 (PAIRED W P234)	X	Classroom Connectivity
12	X129	I.S. 129 (PAIRED W P234)	X	Heating Plant Upgrade
12	X150	P.S. 150	X	Heating Plant Upgrade
12	X158	I.S. 158	X	Accessibility
12	X158	I.S. 158	X	Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
12	X158	I.S. 158	X	IP Digital Video Surveillance System
12	X158	I.S. 158	X	New/Retrofit Telephone/Intercom System
12	X158	I.S. 158	X	Student Toilets
12	X167	P.S. 214	X	Lighting Fixtures
12	X167	P.S. 214	X	Student Toilets
12	X193	P.S. 211	X	Accessibility
12	X193	P.S. 211	X	Lighting Fixtures
13	K003	P.S. 3	K	Low-Voltage Electrical Systems
13	K003	P.S. 3	K	Student Toilets
13	K009	P.S. 9	K	Heating Plant Upgrade
13	K009	P.S. 9	K	Playground Redevelopment
13	K011	P.S. 11	K	Lighting Fixtures
13	K020	P.S. 20	K	Gymnasium Upgrade
13	K020	P.S. 20	K	Heating Plant Upgrade
13	K020	P.S. 20	K	Student Toilets
13	K020	P.S. 20	K	Waste System
13	K044	P.S. 44	K	Electrical Systems
13	K044	P.S. 44	K	Low-Voltage Electrical Systems
13	K046	P.S. 46	K	Auditorium Upgrade
13	K054	P.S. 54	K	Heating Plant Upgrade
13	K054	P.S. 54	K	New/Retrofit Telephone/Intercom System
13	K056	P.S. 56	K	Lighting Fixtures
13	K067	P.S. 67	K	Heating Plant Upgrade
13	K067	P.S. 67	K	Lighting Fixtures
13	K067	P.S. 67	K	Student Toilets
13	K093	P.S. 93	K	Electrical Systems
13	K093	P.S. 93	K	Heating Plant Upgrade
13	K093	P.S. 93	K	Lighting Fixtures
13	K113	I.S. 113	K	Climate Control
13	K113	I.S. 113	K	Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
13	K113	I.S. 113	K	Student Toilets
13	K117	I.S. 117	K	Cafeteria / Multipurpose Room Upgrade
13	K117	I.S. 117	K	Parapets
13	K117	I.S. 117	K	Roofs
13	K258	I.S. 258	K	Electrical Systems
13	K258	I.S. 258	K	Low-Voltage Electrical Systems
13	K265	I.S. 265	K	Heating Plant Upgrade
13	K270	P.S. 270	K	Heating Plant Upgrade
13	K270	P.S. 270	K	Lighting Fixtures
13	K270	P.S. 270	K	Lighting Fixtures
13	K282	P.S. 282	K	Student Toilets
13	K287	P.S. 287	K	Electrical Systems
13	K287	P.S. 287	K	Exterior Masonry
13	K287	P.S. 287	K	Lighting Fixtures
13	K287	P.S. 287	K	Parapets
13	K287	P.S. 287	K	Roofs
13	K305	P.S. 305	K	Electrical Systems
13	K305	P.S. 305	K	Student Toilets
13	K307	P.S. 307	K	Electrical Systems
13	K307	P.S. 307	K	Heating Plant Upgrade
13	K307	P.S. 307	K	Parapets
13	K307	P.S. 307	K	Roofs
13	K307	P.S. 307	K	Student Toilets
14	K016	P.S. 16	K	Flood Elimination
14	K016	P.S. 16	K	Student Toilets
14	K017	P.S. 17	K	Floors
14	K017	P.S. 17	K	Heating Plant Upgrade
14	K017	P.S. 17	K	Heating Plant Upgrade
14	K017	P.S. 17	K	Lighting Fixtures
14	K017	P.S. 17	K	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
14	K017	P.S. 17	K	Student Toilets
14	K018	P.S. 18	K	New/Retrofit Telephone/Intercom System
14	K018	P.S. 18	K	Student Toilets
14	K019	P.S. 19	K	Climate Control
14	K023	P.S. 23	K	Accessibility
14	K023	P.S. 23	K	Heating Plant Upgrade
14	K031	P.S. 31 (OLD 126)	K	Electrical Systems
14	K031	P.S. 31 (OLD 126)	K	Student Toilets
14	K033	I.S. 33	K	Mobile Science Cart
14	K033	I.S. 33	K	Student Toilets
14	K034	P.S. 34	K	Student Toilets
14	K049	I.S. 49	K	IP Digital Video Surveillance System
14	K049	I.S. 49	K	Student Toilets
14	K050	J.H.S. 50	K	Electrical Systems
14	K050	J.H.S. 50	K	Technology
14	K059	P.S. 59	K	Climate Control
14	K071	I.S. 71	K	Electrical Systems
14	K071	I.S. 71	K	Heating Plant Upgrade
14	K071	I.S. 71	K	Student Toilets
14	K084	P.S. 84	K	Electrical Systems
14	K120	P.S. 120	K	Electrical Systems
14	K120	P.S. 120	K	Student Toilets
14	K120	P.S. 120	K	Technology
14	K126	J.H.S. 126	K	Electrical Systems
14	K126	J.H.S. 126	K	Heating Plant Upgrade
14	K147	P.S. 147	K	Roofs
14	K147	P.S. 147	K	Student Toilets
14	K157	P.S. 157	K	Student Toilets
14	K196	P.S. 196	K	Electrical Systems
14	K196	P.S. 196	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
14	K196	P.S. 196	K	IP Digital Video Surveillance System
14	K196	P.S. 196	K	Student Toilets
14	K250	P.S. 250	K	Electrical Systems
14	K250	P.S. 250	K	Student Toilets
14	K257	P.S. 257	K	Student Toilets
14	K297	P.S. 297	K	Electrical Systems
14	K297	P.S. 297	K	Heating Plant Upgrade
14	K297	P.S. 297	K	Room Conversions/Partitioning
14	K297	P.S. 297	K	Student Toilets
14	K318	I.S. 318	K	Electrical Systems
14	K318	I.S. 318	K	Heating Plant Upgrade
14	K318	I.S. 318	K	Lighting Fixtures
14	K319	P.S. 319	K	Lighting Fixtures
14	K380	P.S. 380	K	Heating Plant Upgrade
14	K673	P.S. 18 GYM ANNEX	K	Gymnasiums
15	K010	P.S. 10	K	Electrical Systems
15	K010	P.S. 10	K	Lighting Fixtures
15	K015	P.S. 15	K	Domestic Piping
15	K015	P.S. 15	K	Heating Plant Upgrade
15	K015	P.S. 15	K	Student Toilets
15	K024	P.S. 24	K	Accessibility
15	K024	P.S. 24	K	Heating Plant Upgrade
15	K027	P.S. 27	K	Electrical Systems
15	K027	P.S. 27	K	Exterior Masonry
15	K027	P.S. 27	K	Parapets
15	K027	P.S. 27	K	Student Toilets
15	K029	P.S. 29	K	Electrical Systems
15	K029	P.S. 29	K	Student Toilets
15	K032	P.S. 32 ADDITION	K	Student Toilets
15	K038	P.S. 38	K	Lighting Fixtures

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
15	K038	P.S. 38	K	Student Toilets
15	K051	I.S. 51	K	Electrical Systems
15	K051	I.S. 51	K	Student Toilets
15	K088	I.S. 88	K	Boiler Conversion
15	K088	I.S. 88	K	Climate Control
15	K088	I.S. 88	K	Lighting Fixtures
15	K088	I.S. 88	K	Student Toilets
15	K088	I.S. 88	K	Student Toilets
15	K094	P.S. 94	K	Heating Plant Upgrade
15	K107	P.S. 107	K	Electrical Systems
15	K107	P.S. 107	K	Student Toilets
15	K124	P.S. 124	K	Electrical Systems
15	K124	P.S. 124	K	Exterior Masonry
15	K124	P.S. 124	K	Flood Elimination
15	K124	P.S. 124	K	Parapets
15	K124	P.S. 124	K	Roofs
15	K124	P.S. 124	K	Student Toilets
15	K130	P.S. 130	K	Electrical Systems
15	K130	P.S. 130	K	Heating Plant Upgrade
15	K130	P.S. 130	K	Parapets
15	K130	P.S. 130	K	Roofs
15	K130	P.S. 130	K	Student Toilets
15	K131	P.S. 131	K	Flood Elimination
15	K131	P.S. 131	K	Lighting Fixtures
15	K131	P.S. 131	K	Parapets
15	K131	P.S. 131	K	Roofs
15	K136	I.S. 136	K	Domestic Piping
15	K136	I.S. 136	K	Flood Elimination
15	K136	I.S. 136	K	IP Digital Video Surveillance System
15	K136	I.S. 136	K	Low-Voltage Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
15	K142	J.H.S. 142	K	Electrical Systems
15	K142	J.H.S. 142	K	Exterior Masonry
15	K142	J.H.S. 142	K	Flood Elimination
15	K142	J.H.S. 142	K	Windows
15	K154	P.S. 154	K	Electrical Systems
15	K154	P.S. 154	K	Interior Spaces
15	K154	P.S. 154	K	Student Toilets
15	K169	P.S. 169	K	Heating Plant Upgrade
15	K172	P.S. 172	K	Heating Plant Upgrade
15	K230	P.S. 230	K	Electrical Systems
15	K293	J.H.S. 293	K	Library Upgrade
15	K293	J.H.S. 293	K	Parapets
15	K293	J.H.S. 293	K	Student Toilets
15	K321	P.S. 321	K	IP Digital Video Surveillance System
15	K321	P.S. 321	K	Lighting Fixtures
15	K321	P.S. 321	K	Low-Voltage Electrical Systems
15	K321	P.S. 321	K	Playground Redevelopment
15	K321	P.S. 321	K	Student Toilets
15	K763	P.S. 118 MAURICE SENDAK COMMUNITY SCI	K	Electrical Systems
15	K763	P.S. 118 MAURICE SENDAK COMMUNITY SCI	K	Lighting Fixtures
15	K763	P.S. 118 MAURICE SENDAK COMMUNITY SCI	K	Lighting Fixtures
15	K812	P.S. 1 ANNEX	K	Electrical Systems
15	K845	P.S. 295	K	Exterior Masonry
15	K845	P.S. 295	K	Floors
15	K845	P.S. 295	K	Gymnasium Upgrade
15	K845	P.S. 295	K	Parapets
15	K845	P.S. 295	K	Reinforcing Support Elements
15	K845	P.S. 295	K	Roofs
15	K908	P.S. 230 ANNEX	K	Lighting Fixtures
16	K005	P.S. 5	K	Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
16	K005	P.S. 5	K	Heating Plant Upgrade
16	K005	P.S. 5	K	Playground Redevelopment
16	K005	P.S. 5	K	Student Toilets
16	K021	P.S. 21	K	Heating Plant Upgrade
16	K021	P.S. 21	K	IP Digital Video Surveillance System
16	K021	P.S. 21	K	Student Toilets
16	K025	P.S. 25	K	Electrical Systems
16	K025	P.S. 25	K	Exterior Masonry
16	K025	P.S. 25	K	Parapets
16	K025	P.S. 25	K	Roofs
16	K025	P.S. 25	K	Safety Systems
16	K026	P.S. 26	K	Low-Voltage Electrical Systems
16	K028	P.S. 28	K	Electrical Systems
16	K035	I.S. 35	K	Lighting Fixtures
16	K040	P.S. 40	K	Accessibility
16	K040	P.S. 40	K	Electrical Systems
16	K040	P.S. 40	K	Lighting Fixtures
16	K057	J.H.S. 57	K	Lighting Fixtures
16	K057	J.H.S. 57	K	Lighting Fixtures
16	K057	J.H.S. 57	K	New/Retrofit Telephone/Intercom System
16	K081	P.S. 81	K	IP Digital Video Surveillance System
16	K081	P.S. 81	K	Student Toilets
16	K243	P.S. 243	K	Electrical Systems
16	K243	P.S. 243	K	Heating Plant Upgrade
16	K243	P.S. 243	K	Technology
16	K262	P.S. 262	K	Student Toilets
16	K304	P.S. 304	K	Exterior Masonry
16	K304	P.S. 304	K	Student Toilets
16	K308	P.S. 308	K	Climate Control
16	K308	P.S. 308	K	Student Toilets



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
16	K309	P.S. 309	K	Lighting Fixtures
16	K309	P.S. 309	K	Lighting Fixtures
16	K309	P.S. 309	K	Playground Redevelopment
16	K324	I.S. 324	K	Climate Control
16	K324	I.S. 324	K	Electrical Systems
16	K324	I.S. 324	K	Student Toilets
16	K335	P.S. 335	K	New/Retrofit Telephone/Intercom System
16	K335	P.S. 335	K	Student Toilets
16	KBBY	BROOKLYN CHILDREN CENTER	K	Technology
17	K002	I.S. 2	K	Accessibility
17	K002	I.S. 2	K	Climate Control
17	K002	I.S. 2	K	Heating Plant Upgrade
17	K002	I.S. 2	K	Heating Plant Upgrade
17	K002	I.S. 2	K	Safety Systems
17	K006	P.S. 6	K	Accessibility
17	K006	P.S. 6	K	Heating Plant Upgrade
17	K006	P.S. 6	K	Low-Voltage Electrical Systems
17	K012	P.S. 12	K	Accessibility
17	K022	P.S. 22	K	Climate Control
17	K022	P.S. 22	K	Electrical Systems
17	K061	I.S. 61	K	Student Toilets
17	K091	P.S. 91	K	Reinforcing Support Elements
17	K092	P.S. 92	K	Climate Control
17	K092	P.S. 92	K	Lighting Fixtures
17	K092	P.S. 92	K	Low-Voltage Electrical Systems
17	K138	P.S. 138	K	Electrical Systems
17	K138	P.S. 138	K	Heating Plant Upgrade
17	K138	P.S. 138	K	Lighting Fixtures
17	K138	P.S. 138	K	Student Toilets
17	K161	P.S. 161	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
17	K167	P.S. 167	K	Safety Systems
17	K181	P.S. 181	K	New/Retrofit Telephone/Intercom System
17	K189	P.S. 189	K	Electrical Systems
17	K189	P.S. 189	K	Student Toilets
17	K191	P.S. 191	K	Lighting Fixtures
17	K191	P.S. 191	K	Student Toilets
17	K191	P.S. 191	K	Technology
17	K191	P.S. 191	K	Technology
17	K210	I.S. 394	K	Electrical Systems
17	K210	I.S. 394	K	Flood Elimination
17	K210	I.S. 394	K	Lighting Fixtures
17	K210	I.S. 394	K	Student Toilets
17	K221	P.S. 221	K	Air Conditioning Split System
17	K221	P.S. 221	K	Heating Plant Upgrade
17	K241	P.S. 241	K	Lighting Fixtures
17	K241	P.S. 241	K	Lighting Fixtures
17	K241	P.S. 241	K	Student Toilets
17	K246	I.S. 246	K	Air Conditioning Retrofit
17	K246	I.S. 246	K	Student Toilets
17	K246	I.S. 246	K	Technology
17	K246	I.S. 246	K	Technology
17	K246	I.S. 246	K	Technology
17	K246	I.S. 246	K	Technology
17	K249	P.S. 249	K	Heating Plant Upgrade
17	K249	P.S. 249	K	Student Toilets
17	K289	P.S. 289	K	Accessibility
17	K289	P.S. 289	K	Lighting Fixtures
17	K289	P.S. 289	K	Lighting Fixtures
17	K289	P.S. 289	K	New/Retrofit Telephone/Intercom System
17	K289	P.S. 289	K	Waste System

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
17	K316	P.S. 316	K	Roofs
17	K320	P.S. 375	K	Heating Plant Upgrade
17	K390	I.S. 390	K	Electrical Systems
17	K390	I.S. 390	K	Heating Plant Upgrade
17	K390	I.S. 390	K	Heating Plant Upgrade
17	K390	I.S. 390	K	IP Digital Video Surveillance System
17	K390	I.S. 390	K	Library Upgrade
17	K390	I.S. 390	K	Lighting Fixtures
17	K391	I.S. 391	K	Heating Plant Upgrade
17	K391	I.S. 391	K	Lighting Fixtures
17	K391	I.S. 391	K	Student Toilets
17	K398	P.S. 398 (UDC)	K	Heating Plant Upgrade
17	K398	P.S. 398 (UDC)	K	Lighting Fixtures
17	K398	P.S. 398 (UDC)	K	Student Toilets
17	K398	P.S. 398 (UDC)	K	Waste System
17	K399	P.S. 399	K	Heating Plant Upgrade
17	K874	I.S. 340 (OLD 249 AX)	K	Flood Elimination
17	K889	P.S. 189 MINISCHOOL	K	Heating Plant Upgrade
18	K068	I.S. 68	K	Air Conditioning Split System
18	K068	I.S. 68	K	Heating Plant Upgrade
18	K068	I.S. 68	K	Heating Plant Upgrade
18	K068	I.S. 68	K	IP Digital Video Surveillance System
18	K114	P.S. 114	K	Heating Plant Upgrade
18	K114	P.S. 114	K	IP Digital Video Surveillance System
18	K114	P.S. 114	K	Student Toilets
18	K115	P.S. 115	K	Student Toilets
18	K135	P.S. 135	K	Student Toilets
18	K208	P.S. 208	K	Flood Elimination
18	K208	P.S. 208	K	Roofs
18	K208	P.S. 208	K	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
18	K208	P.S. 208	K	Windows
18	K211	I.S. 211	K	IP Digital Video Surveillance System
18	K211	I.S. 211	K	Student Toilets
18	K219	P.S. 219	K	Exterior Masonry
18	K219	P.S. 219	K	New/Retrofit Telephone/Intercom System
18	K219	P.S. 219	K	Parapets
18	K219	P.S. 219	K	Playground Redevelopment and TCU Removal
18	K219	P.S. 219	K	Roofs
18	K232	I.S. 232	K	Exterior Masonry
18	K232	I.S. 232	K	New/Retrofit Telephone/Intercom System
18	K232	I.S. 232	K	Parapets
18	K232	I.S. 232	K	Student Toilets
18	K233	P.S. 233	K	Student Toilets
18	K235	P.S. 235	K	Playground Redevelopment and TCU Removal
18	K235	P.S. 235	K	Student Toilets
18	K242	P.S. 235 ANNEX	K	Reinforcing Support Elements
18	K242	P.S. 235 ANNEX	K	Student Toilets
18	K244	P.S. 244	K	Flood Elimination
18	K244	P.S. 244	K	Lighting Fixtures
18	K244	P.S. 244	K	Parapets
18	K244	P.S. 244	K	Roofs
18	K244	P.S. 244	K	Windows
18	K252	I.S. 252	K	Electrical Systems
18	K252	I.S. 252	K	Student Toilets
18	K268	P.S. 268	K	Playground Redevelopment and TCU Removal
18	K272	P.S. 272	K	Exterior Masonry
18	K272	P.S. 272	K	Flood Elimination
18	K272	P.S. 272	K	Heating Plant Upgrade
18	K272	P.S. 272	K	Heating Plant Upgrade
18	K272	P.S. 272	K	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
18	K272	P.S. 272	K	New/Retrofit Telephone/Intercom System
18	K272	P.S. 272	K	Parapets
18	K272	P.S. 272	K	Playground Redevelopment and TCU Removal
18	K272	P.S. 272	K	Roofs
18	K272	P.S. 272	K	Student Toilets
18	K276	P.S. 276	K	Exterior Masonry
18	K276	P.S. 276	K	Lighting Fixtures
18	K276	P.S. 276	K	Paved Area-Blacktop
18	K276	P.S. 276	K	Playground Redevelopment and TCU Removal
18	K279	P.S. 279	K	Domestic Piping
18	K279	P.S. 279	K	Elevators and Escalators
18	K279	P.S. 279	K	Heating Plant Upgrade
18	K279	P.S. 279	K	Lighting Fixtures
18	K279	P.S. 279	K	Low-Voltage Electrical Systems
18	K279	P.S. 279	K	Playground Redevelopment
18	K279	P.S. 279	K	Student Toilets
18	K285	I.S. 285	K	Student Toilets
18	K860	P.S. 219 ANNEX	K	Electrical Systems
18	K860	P.S. 219 ANNEX	K	Heating Plant Upgrade
19	K007	P.S. 7	K	Accessibility
19	K007	P.S. 7	K	Auditorium Upgrade
19	K007	P.S. 7	K	Domestic Piping
19	K007	P.S. 7	K	Heating Plant Upgrade
19	K007	P.S. 7	K	Lighting Fixtures
19	K007	P.S. 7	K	Technology
19	K013	P.S. 13	K	Electrical Systems
19	K013	P.S. 13	K	Heating Plant Upgrade
19	K013	P.S. 13	K	Lighting Fixtures
19	K013	P.S. 13	K	Lighting Fixtures
19	K072	P.S. 72	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
19	K072	P.S. 72	K	Student Toilets
19	K108	P.S. 108	K	Heating Plant Upgrade
19	K108	P.S. 108	K	Playgrounds
19	K108	P.S. 108	K	Student Toilets
19	K108	P.S. 108	K	Technology
19	K149	P.S. 149	K	Heating Plant Upgrade
19	K158	P.S. 158	K	Auditorium Upgrade
19	K158	P.S. 158	K	Lighting Fixtures
19	K158	P.S. 158	K	Low-Voltage Electrical Systems
19	K158	P.S. 158	K	Playgrounds
19	K158	P.S. 158	K	Student Toilets
19	K158	P.S. 158	K	Technology
19	K159	P.S. 159	K	Student Toilets
19	K166	I.S. 166	K	IP Digital Video Surveillance System
19	K166	I.S. 166	K	Student Toilets
19	K171	I.S. 171	K	IP Digital Video Surveillance System
19	K171	I.S. 171	K	Student Toilets
19	K171	I.S. 171	K	Technology
19	K171	I.S. 171	K	Technology
19	K171	I.S. 171	K	Technology
19	K174	P.S. 174	K	Heating Plant Upgrade
19	K174	P.S. 174	K	Lighting Fixtures
19	K174	P.S. 174	K	Student Toilets
19	K190	P.S. 190	K	Electrical Systems
19	K190	P.S. 190	K	Lighting Fixtures
19	K190	P.S. 190	K	New/Retrofit Telephone/Intercom System
19	K202	P.S. 202	K	Lighting Fixtures
19	K202	P.S. 202	K	Student Toilets
19	K213	P.S. 213	K	Electrical Systems
19	K213	P.S. 213	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
19	K213	P.S. 213	K	New/Retrofit Telephone/Intercom System
19	K214	P.S. 214	K	Gymnasium Upgrade
19	K214	P.S. 214	K	Heating Plant Upgrade
19	K214	P.S. 214	K	Lighting Fixtures
19	K214	P.S. 214	K	Playground Redevelopment and TCU Removal
19	K214	P.S. 214	K	Student Toilets
19	K214	P.S. 214	K	Technology
19	K214	P.S. 214	K	Technology
19	K218	I.S. 218	K	Cafeteria / Multipurpose Room Upgrade
19	K218	I.S. 218	K	Exterior Masonry
19	K218	I.S. 218	K	Student Toilets
19	K224	P.S. 224	K	Heating Plant Upgrade
19	K224	P.S. 224	K	Lighting Fixtures
19	K224	P.S. 224	K	Lighting Fixtures
19	K273	P.S. 273	K	Climate Control
19	K273	P.S. 273	K	Heating Plant Upgrade
19	K273	P.S. 273	K	Lighting Fixtures
19	K290	P.S. 290	K	Heating Plant Upgrade
19	K290	P.S. 290	K	IP Digital Video Surveillance System
19	K290	P.S. 290	K	Parapets
19	K290	P.S. 290	K	Playground Redevelopment and TCU Removal
19	K290	P.S. 290	K	Technology
19	K290	P.S. 290	K	Windows
19	K292	I.S. 292	K	Electrical Systems
19	K292	I.S. 292	K	Heating Plant Upgrade
19	K292	I.S. 292	K	Lighting Fixtures
19	K292	I.S. 292	K	Lighting Fixtures
19	K292	I.S. 292	K	Technology
19	K302	I.S. 302	K	Auditorium Upgrade
19	K302	I.S. 302	K	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
19	K302	I.S. 302	K	Playground Redevelopment and TCU Removal
19	K302	I.S. 302	K	Science Lab Upgrades
19	K302	I.S. 302	K	Technology
19	K302	I.S. 302	K	Technology
19	K306	P.S. 306	K	Heating Plant Upgrade
19	K306	P.S. 306	K	Lighting Fixtures
19	K306	P.S. 306	K	New/Retrofit Telephone/Intercom System
19	K306	P.S. 306	K	Student Toilets
19	K328	P.S. 328	K	Heating Plant Upgrade
19	K328	P.S. 328	K	Playground Redevelopment
19	K345	P.S. 345	K	Classroom Connectivity
19	K345	P.S. 345	K	Gymnasium Upgrade
19	K345	P.S. 345	K	Playground Redevelopment
19	K345	P.S. 345	K	Student Toilets
19	K345	P.S. 345	K	Technology
19	K346	P.S. 346	K	Accessibility
19	K346	P.S. 346	K	Heating Plant Upgrade
19	K346	P.S. 346	K	Lighting Fixtures
19	K798	CESIAH TORO MULLANE SCHOOL	K	Lighting Fixtures
19	K798	CESIAH TORO MULLANE SCHOOL	K	Science Lab Upgrades
19	K798	CESIAH TORO MULLANE SCHOOL	K	Technology
19	K814	CYPRESS HILLS COMMUNITY SCHOOL	K	Lighting Fixtures
19	K814	CYPRESS HILLS COMMUNITY SCHOOL	K	Technology
19	K848	P.S. 149 ANNEX	K	Electrical Systems
19	K848	P.S. 149 ANNEX	K	Lighting Fixtures
20	K048	P.S. 48	K	Electrical Systems
20	K048	P.S. 48	K	Flood Elimination
20	K048	P.S. 48	K	Flood Elimination
20	K048	P.S. 48	K	Student Toilets
20	K062	I.S. 62	K	Electrical Systems



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
20	K062	I.S. 62	K	New/Retrofit Telephone/Intercom System
20	K102	P.S. 102	K	Electrical Systems
20	K102	P.S. 102	K	Student Toilets
20	K104	P.S. 104	K	Electrical Systems
20	K104	P.S. 104	K	IP Digital Video Surveillance System
20	K105	P.S. 105	K	Exterior Masonry
20	K105	P.S. 105	K	Flood Elimination
20	K105	P.S. 105	K	Heating Plant Upgrade
20	K105	P.S. 105	K	Roofs
20	K112	P.S. 112	K	Playground Redevelopment and TCU Removal
20	K127	P.S. 127	K	Boiler Conversion
20	K127	P.S. 127	K	Boiler Conversion
20	K127	P.S. 127	K	Climate Control
20	K160	P.S. 160	K	Exterior Masonry
20	K160	P.S. 160	K	Flood Elimination
20	K160	P.S. 160	K	Parapets
20	K163	P.S. 163	K	Student Toilets
20	K164	P.S. 164	K	Climate Control
20	K164	P.S. 164	K	Electrical Systems
20	K164	P.S. 164	K	Parapets
20	K164	P.S. 164	K	Roofs
20	K170	P.S. 170	K	Air Conditioning Split System
20	K170	P.S. 170	K	Heating Plant Upgrade
20	K176	P.S. 176	K	Heating Plant Upgrade
20	K176	P.S. 176	K	Lighting Fixtures
20	K179	P.S. 179	K	Student Toilets
20	K180	P.S. 180	K	Lighting Fixtures
20	K180	P.S. 180	K	Student Toilets
20	K185	P.S. 185	K	Heating Plant Upgrade
20	K186	P.S. 186	K	Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
20	K186	P.S. 186	K	Heating Plant Upgrade
20	K186	P.S. 186	K	Low-Voltage Electrical Systems
20	K192	P.S. 192	K	Climate Control
20	K192	P.S. 192	K	Flood Elimination
20	K192	P.S. 192	K	Parapets
20	K192	P.S. 192	K	Roofs
20	K192	P.S. 192	K	Student Toilets
20	K204	P.S. 204	K	Electrical Systems
20	K204	P.S. 204	K	Heating Plant Upgrade
20	K204	P.S. 204	K	Lighting Fixtures
20	K204	P.S. 204	K	Lighting Fixtures
20	K205	P.S. 205	K	Domestic Piping
20	K205	P.S. 205	K	Electrical Systems
20	K205	P.S. 205	K	Flood Elimination
20	K205	P.S. 205	K	Heating Plant Upgrade
20	K205	P.S. 205	K	Lighting Fixtures
20	K205	P.S. 205	K	Parapets
20	K220	I.S. 220	K	Heating Plant Upgrade
20	K220	I.S. 220	K	Science Lab Upgrades
20	K223	I.S. 223	K	Accessibility
20	K223	I.S. 223	K	Heating Plant Upgrade
20	K223	I.S. 223	K	Playground Redevelopment
20	K223	I.S. 223	K	Science Lab Upgrades
20	K223	I.S. 223	K	Waste System
20	K227	I.S. 227	K	IP Digital Video Surveillance System
20	K229	P.S. 229	K	Electrical Systems
20	K229	P.S. 229	K	Lighting Fixtures
20	K229	P.S. 229	K	Lighting Fixtures
20	K237	LUCRETIA MARCIGLIANO CAMPUS	K	Playgrounds
20	K247	P.S. 247	K	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
20	K259	I.S. 259	K	Accessibility
20	K259	I.S. 259	K	Electrical Systems
20	K259	I.S. 259	K	Parapets
20	K259	I.S. 259	K	Roofs
20	K259	I.S. 259	K	Student Toilets
20	K314	P.S. 314	K	Accessibility
20	K314	P.S. 314	K	Heating Plant Upgrade
20	K314	P.S. 314	K	Lighting Fixtures
20	K314	P.S. 314	K	New/Retrofit Telephone/Intercom System
20	K314	P.S. 314	K	Parapets
20	K314	P.S. 314	K	Roofs
20	K314	P.S. 314	K	Student Toilets
20	K314	P.S. 314	K	Ventilation
20	K331	P.S./I.S. 30 MARY WHITE OVINGTON	K	Accessibility
20	K486	I.S. 187	K	Electrical Systems
20	K486	I.S. 187	K	Heating Plant Upgrade
20	K486	I.S. 187	K	IP Digital Video Surveillance System
20	K486	I.S. 187	K	Student Toilets
20	K940	I.S. 30	K	Heating Plant Upgrade
20	K971	P.S. 971	K	Lighting Fixtures
21	K043	I.S. 98	K	Electrical Systems
21	K043	I.S. 98	K	Student Toilets
21	K090	P.S. 90	K	Heating Plant Upgrade
21	K090	P.S. 90	K	Roofs
21	K090	P.S. 90	K	Student Toilets
21	K095	P.S. 95	K	Electrical Systems
21	K095	P.S. 95	K	IP Digital Video Surveillance System
21	K095	P.S. 95	K	Student Toilets
21	K096	I.S. 96	K	Electrical Systems
21	K096	I.S. 96	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
21	K097	P.S. 97	K	Electrical Systems
21	K097	P.S. 97	K	Heating Plant Upgrade
21	K097	P.S. 97	K	Student Toilets
21	K099	P.S. 99	K	Exterior Masonry
21	K099	P.S. 99	K	Parapets
21	K099	P.S. 99	K	Roofs
21	K099	P.S. 99	K	Safety Systems
21	K099	P.S. 99	K	Student Toilets
21	K100	P.S. 100	K	Lighting Fixtures
21	K100	P.S. 100	K	Student Toilets
21	K101	P.S. 101	K	Electrical Systems
21	K101	P.S. 101	K	Exterior Masonry
21	K101	P.S. 101	K	Heating Plant Upgrade
21	K101	P.S. 101	K	Lighting Fixtures
21	K101	P.S. 101	K	Parapets
21	K101	P.S. 101	K	Roofs
21	K121	P.S. 121	K	Electrical Systems
21	K121	P.S. 121	K	Lighting Fixtures
21	K128	P.S. 128 (TANDEM BROOKLYN STUDIO)	K	Emergency Lighting and Fire Safety Retrofits
21	K128	P.S. 128 (TANDEM BROOKLYN STUDIO)	K	Exterior Masonry
21	K128	P.S. 128 (TANDEM BROOKLYN STUDIO)	K	Windows
21	K153	P.S. 153	K	New/Retrofit Telephone/Intercom System
21	K153	P.S. 153	K	Student Toilets
21	K188	P.S. 188	K	Heating Plant Upgrade
21	K188	P.S. 188	K	Low-Voltage Electrical Systems
21	K199	P.S. 199	K	Electrical Systems
21	K209	P.S. 209	K	Heating Plant Upgrade
21	K209	P.S. 209	K	Student Toilets
21	K212	P.S. 212	K	Parapets
21	K212	P.S. 212	K	Roofs

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
21	K212	P.S. 212	K	Windows
21	K215	P.S. 215	K	Electrical Systems
21	K215	P.S. 215	K	Exterior Masonry
21	K215	P.S. 215	K	Flood Elimination
21	K215	P.S. 215	K	Parapets
21	K216	P.S. 216	K	Student Toilets
21	K225	P.S. 225	K	Electrical Systems
21	K225	P.S. 225	K	Flood Elimination
21	K225	P.S. 225	K	Lighting Fixtures
21	K225	P.S. 225	K	Roofs
21	K225	P.S. 225	K	Student Toilets
21	K228	I.S. 228	K	Cafeteria / Multipurpose Room Upgrade
21	K228	I.S. 228	K	Domestic Piping
21	K228	I.S. 228	K	Student Toilets
21	K228	I.S. 228	K	Student Toilets
21	K238	P.S. 238	K	Electrical Systems
21	K238	P.S. 238	K	Parapets
21	K238	P.S. 238	K	Student Toilets
21	K239	I.S. 239	K	Lighting Fixtures
21	K239	I.S. 239	K	Student Toilets
21	K253	P.S. 253	K	Paved Area-Blacktop
21	K281	I.S. 281	K	Cafeteria / Multipurpose Room Upgrade
21	K281	I.S. 281	K	Flood Elimination
21	K281	I.S. 281	K	IP Digital Video Surveillance System
21	K281	I.S. 281	K	Lighting Fixtures
21	K281	I.S. 281	K	Low-Voltage Electrical Systems
21	K288	P.S. 288	K	Student Toilets
21	K303	I.S. 303	K	Heating Plant Upgrade
21	K303	I.S. 303	K	Library Upgrade
21	K303	I.S. 303	K	Lighting Fixtures

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
21	K303	I.S. 303	K	Student Toilets
21	K329	P.S. 329	K	Lighting Fixtures
21	K329	P.S. 329	K	Playground Redevelopment
21	K329	P.S. 329	K	Student Toilets
22	K014	I.S. 14	K	Domestic Piping
22	K014	I.S. 14	K	Flood Elimination
22	K014	I.S. 14	K	Lighting Fixtures
22	K014	I.S. 14	K	Student Toilets
22	K014	I.S. 14	K	Waste System
22	K052	P.S. 52	K	Electrical Systems
22	K052	P.S. 52	K	Exterior Masonry
22	K052	P.S. 52	K	IP Digital Video Surveillance System
22	K052	P.S. 52	K	Parapets
22	K052	P.S. 52	K	Roofs
22	K052	P.S. 52	K	Student Toilets
22	K078	I.S. 78	K	Auditorium Upgrade
22	K078	I.S. 78	K	Electrical Systems
22	K078	I.S. 78	K	IP Digital Video Surveillance System
22	K078	I.S. 78	K	Room Conversions/Partitioning
22	K078	I.S. 78	K	Student Toilets
22	K119	P.S. 119	K	Student Toilets
22	K139	P.S. 139	K	Roofs
22	K139	P.S. 139	K	Student Toilets
22	K152	P.S. 152	K	Heating Plant Upgrade
22	K152	P.S. 152	K	Lighting Fixtures
22	K152	P.S. 152	K	Lighting Fixtures
22	K152	P.S. 152	K	Playground Redevelopment and TCU Removal
22	K193	P.S. 193	K	Playground Redevelopment and TCU Removal
22	K193	P.S. 193	K	Student Toilets
22	K194	P.S. 194	K	Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
22	K194	P.S. 194	K	Exterior Masonry
22	K194	P.S. 194	K	Parapets
22	K194	P.S. 194	K	Playground Redevelopment and TCU Removal
22	K194	P.S. 194	K	Roofs
22	K194	P.S. 194	K	Windows
22	K195	P.S. 195	K	Climate Control
22	K195	P.S. 195	K	Heating Plant Upgrade
22	K195	P.S. 195	K	Heating Plant Upgrade
22	K197	P.S. 197	K	Exterior Masonry
22	K197	P.S. 197	K	Flood Elimination
22	K197	P.S. 197	K	Heating Plant Upgrade
22	K197	P.S. 197	K	Lighting Fixtures
22	K197	P.S. 197	K	Parapets
22	K197	P.S. 197	K	Roofs
22	K197	P.S. 197	K	Student Toilets
22	K197	P.S. 197	K	Windows
22	K198	P.S. 198	K	Elevators and Escalators
22	K198	P.S. 198	K	Exterior Masonry
22	K198	P.S. 198	K	Heating Plant Upgrade
22	K198	P.S. 198	K	Playground Redevelopment and TCU Removal
22	K198	P.S. 198	K	Windows
22	K203	P.S. 203	K	Lighting Fixtures
22	K203	P.S. 203	K	New/Retrofit Telephone/Intercom System
22	K206	P.S. 206	K	Low-Voltage Electrical Systems
22	K206	P.S. 206	K	Student Toilets
22	K207	P.S. 207	K	Student Toilets
22	K217	P.S. 217	K	Flood Elimination
22	K217	P.S. 217	K	Heating Plant Upgrade
22	K217	P.S. 217	K	Lighting Fixtures
22	K217	P.S. 217	K	New/Retrofit Telephone/Intercom System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
22	K217	P.S. 217	K	Parapets
22	K217	P.S. 217	K	Student Toilets
22	K217	P.S. 217	K	Windows
22	K222	P.S. 222	K	New/Retrofit Telephone/Intercom System
22	K222	P.S. 222	K	Student Toilets
22	K234	I.S. 234	K	Heating Plant Upgrade
22	K234	I.S. 234	K	IP Digital Video Surveillance System
22	K236	P.S. 236	K	Exterior Masonry
22	K236	P.S. 236	K	Fencing
22	K236	P.S. 236	K	New/Retrofit Telephone/Intercom System
22	K236	P.S. 236	K	Playground Redevelopment and TCU Removal
22	K240	I.S. 240	K	Auditorium Upgrade
22	K240	I.S. 240	K	Cafeteria / Multipurpose Room Upgrade
22	K251	P.S. 251	K	Exterior Masonry
22	K251	P.S. 251	K	Lighting Fixtures
22	K251	P.S. 251	K	Parapets
22	K251	P.S. 251	K	Roofs
22	K251	P.S. 251	K	Safety Systems
22	K251	P.S. 251	K	Windows
22	K254	P.S. 254	K	Climate Control
22	K254	P.S. 254	K	Heating Plant Upgrade
22	K254	P.S. 254	K	Roofs
22	K254	P.S. 254	K	Roofs
22	K255	P.S. 255	K	Lighting Fixtures
22	K269	P.S. 269	K	Lighting Fixtures
22	K269	P.S. 269	K	Student Toilets
22	K277	P.S. 277	K	Heating Plant Upgrade
22	K278	I.S. 278	K	Auditorium Upgrade
22	K278	I.S. 278	K	Waste System
22	K312	P.S. 312	K	Electrical Systems



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
22	K312	P.S. 312	K	Heating Plant Upgrade
22	K395	P.S./I.S. 395	K	Lighting Fixtures
22	K395	P.S./I.S. 395	K	Parapets
22	K395	P.S./I.S. 395	K	Roofs
22	K729	P.S. 207 ANNEX	K	New/Retrofit Telephone/Intercom System
22	K849	P.S. 134	K	Electrical Systems
22	K849	P.S. 134	K	Exterior Masonry
22	K849	P.S. 134	K	Lighting Fixtures
22	K849	P.S. 134	K	Parapets
22	K849	P.S. 134	K	Student Toilets
22	K852	P.S. 326	K	Student Toilets
22	K864	P.S. 361 (OLD 89)	K	Student Toilets
22	K905	DISTRICT 22 ECOLOGY CENTER	K	Windows
22	K995	LEARNING SUPPORT CENTER	K	Heating Plant Upgrade
22	K995	LEARNING SUPPORT CENTER	K	Lighting Fixtures
23	K041	P.S. 41	K	Heating Plant Upgrade
23	K041	P.S. 41	K	Heating Plant Upgrade
23	K041	P.S. 41	K	Student Toilets
23	K055	I.S. 55	K	Accessibility
23	K055	I.S. 55	K	Electrical Systems
23	K073	P.S. 73	K	Flood Elimination
23	K073	P.S. 73	K	Heating Plant Upgrade
23	K073	P.S. 73	K	Parapets
23	K073	P.S. 73	K	Roofs
23	K073	P.S. 73	K	School Improvement and Restructuring
23	K073	P.S. 73	K	Student Toilets
23	K073	P.S. 73	K	Technology
23	K073	P.S. 73	K	Technology
23	K137	P.S. 137	K	Electrical Systems
23	K137	P.S. 137	K	Student Toilets

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
23	K150	P.S. 150	K	Electrical Systems
23	K150	P.S. 150	K	Heating Plant Upgrade
23	K150	P.S. 150	K	Heating Plant Upgrade
23	K150	P.S. 150	K	Student Toilets
23	K150	P.S. 150	K	Student Toilets
23	K155	P.S. 155	K	Heating Plant Upgrade
23	K155	P.S. 155	K	Library Upgrade
23	K155	P.S. 155	K	Student Toilets
23	K155	P.S. 155	K	Technology
23	K165	P.S. 165	K	Heating Plant Upgrade
23	K165	P.S. 165	K	Playground Redevelopment
23	K165	P.S. 165	K	Reinforcing Support Elements
23	K165	P.S. 165	K	Student Toilets
23	K178	P.S. 178	K	Electrical Systems
23	K178	P.S. 178	K	Exterior Masonry
23	K178	P.S. 178	K	Flood Elimination
23	K178	P.S. 178	K	Heating Plant Upgrade
23	K178	P.S. 178	K	Parapets
23	K178	P.S. 178	K	Playground Redevelopment
23	K178	P.S. 178	K	Windows
23	K183	P.S. 183	K	Electrical Systems
23	K183	P.S. 183	K	Exterior Masonry
23	K183	P.S. 183	K	Playground Redevelopment
23	K184	P.S. 184	K	Heating Plant Upgrade
23	K263	P.S./I.S. 323	K	Cafeteria / Multipurpose Room Upgrade
23	K263	P.S./I.S. 323	K	Heating Plant Upgrade
23	K263	P.S./I.S. 323	K	Playground Redevelopment
23	K271	I.S. 271	K	Electrical Systems
23	K271	I.S. 271	K	Heating Plant Upgrade
23	K275	I.S. 275	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
23	K275	I.S. 275	K	Heating Plant Upgrade
23	K275	I.S. 275	K	Student Toilets
23	K284	P.S. 284	K	Electrical Systems
23	K284	P.S. 284	K	Heating Plant Upgrade
23	K284	P.S. 284	K	Interior Spaces
23	K298	P.S. 298	K	Auditorium Upgrade
23	K298	P.S. 298	K	Heating Plant Upgrade
23	K298	P.S. 298	K	Playgrounds
23	K298	P.S. 298	K	Technology
23	K298	P.S. 298	K	Technology
23	K327	P.S. 327 (TANDEM K396-D75)	K	Accessibility
23	K327	P.S. 327 (TANDEM K396-D75)	K	Air Conditioning Split System
23	K327	P.S. 327 (TANDEM K396-D75)	K	Electrical Systems
23	K327	P.S. 327 (TANDEM K396-D75)	K	Heating Plant Upgrade
23	K327	P.S. 327 (TANDEM K396-D75)	K	Student Toilets
23	K332	P.S. 332	K	Heating Plant Upgrade
23	K332	P.S. 332	K	New/Retrofit Telephone/Intercom System
23	K332	P.S. 332	K	Technology
23	K356	P.S. 156	K	Climate Control
23	K356	P.S. 156	K	Heating Plant Upgrade
23	K854	P.S. 178 AX (BED STUY ECC 1)	K	Playground Redevelopment
24	Q005	I.S. 5	Q	Heating Plant Upgrade
24	Q005	I.S. 5	Q	Low-Voltage Electrical Systems
24	Q007	P.S. 7	Q	Domestic Piping
24	Q007	P.S. 7	Q	Heating Plant Upgrade
24	Q007	P.S. 7	Q	IP Digital Video Surveillance System
24	Q012	P.S. 12	Q	Electrical Systems
24	Q012	P.S. 12	Q	Playground Redevelopment
24	Q012	P.S. 12	Q	Student Toilets
24	Q013	P.S. 13	Q	Lighting Fixtures

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
24	Q014	P.S. 14	Q	IP Digital Video Surveillance System
24	Q014	P.S. 14	Q	Student Toilets
24	Q019	P.S. 19	Q	Electrical Systems
24	Q049	P.S./I.S. 49 ADDITION	Q	Lighting Fixtures
24	Q049	P.S. 49	Q	Student Toilets
24	Q058	P.S. 58	Q	Accessibility
24	Q058	P.S. 58	Q	IP Digital Video Surveillance System
24	Q058	P.S. 58	Q	Student Toilets
24	Q068	P.S. 68	Q	Auditorium Upgrade
24	Q068	P.S. 68	Q	IP Digital Video Surveillance System
24	Q071	P.S. 71	Q	Exterior Masonry
24	Q071	P.S. 71	Q	New/Retrofit Telephone/Intercom System
24	Q071	P.S. 71	Q	Parapets
24	Q071	P.S. 71	Q	Student Toilets
24	Q073	I.S. 73	Q	Electrical Systems
24	Q073	I.S. 73	Q	Lighting Fixtures
24	Q073	I.S. 73	Q	Student Toilets
24	Q081	P.S. 81	Q	Electrical Systems
24	Q081	P.S. 81	Q	Playground Redevelopment and TCU Removal
24	Q081	P.S. 81	Q	Student Toilets
24	Q087	P.S. 87	Q	Accessibility
24	Q087	P.S. 87	Q	Electrical Systems
24	Q087	P.S. 87	Q	Student Toilets
24	Q088	P.S. 88	Q	Domestic Piping
24	Q088	P.S. 88	Q	Heating Plant Upgrade
24	Q089	P.S. 89	Q	IP Digital Video Surveillance System
24	Q089	P.S. 89	Q	Student Toilets
24	Q091	P.S. 91	Q	Classroom Connectivity
24	Q091	P.S. 91	Q	IP Digital Video Surveillance System
24	Q091	P.S. 91	Q	Playground Redevelopment

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
24	Q091	P.S. 91	Q	Student Toilets
24	Q093	I.S. 93	Q	Cafeteria / Multipurpose Room Upgrade
24	Q093	I.S. 93	Q	IP Digital Video Surveillance System
24	Q093	I.S. 93	Q	Parapets
24	Q102	P.S./I.S. 102	Q	Playground Redevelopment
24	Q119	I.S. 119	Q	Electrical Systems
24	Q119	I.S. 119	Q	Student Toilets
24	Q125	I.S. 125	Q	Heating Plant Upgrade
24	Q125	I.S. 125 ADDITION	Q	Lighting Fixtures
24	Q143	P.S. 143	Q	Heating Plant Upgrade
24	Q143	P.S. 143	Q	Student Toilets
24	Q153	P.S. 153	Q	IP Digital Video Surveillance System
24	Q153	P.S. 153	Q	Lighting Fixtures
24	Q153	P.S. 153	Q	Windows
24	Q199	P.S. 199	Q	IP Digital Video Surveillance System
24	Q199	P.S. 199	Q	Playground Redevelopment and TCU Removal
24	Q229	P.S. 229	Q	IP Digital Video Surveillance System
24	Q229	P.S. 229	Q	Student Toilets
24	Q239	P.S. 239	Q	Accessibility
24	Q239	P.S. 239	Q	IP Digital Video Surveillance System
24	Q247	P.S. 128	Q	Accessibility
24	Q260	P.S. 307	Q	Accessibility
24	Q342	P.S. 81 GYM ANNEX	Q	Gymnasiums
24	Q721	P.S. 16 (OLD Q721 SPED)	Q	Lighting Fixtures
24	Q721	P.S. 16 (OLD Q721 SPED)	Q	Student Toilets
24	Q848	P.S. 81 ANNEX (OLD 75)	Q	Student Toilets
24	Q877	51ST AVENUE ACADEMY	Q	IP Digital Video Surveillance System
24	Q878	P.S. 128 ANNEX	Q	New/Retrofit Telephone/Intercom System
25	Q020	P.S. 20	Q	Accessibility
25	Q020	P.S. 20	Q	Flood Elimination

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
25	Q020	P.S. 20	Q	Low-Voltage Electrical Systems
25	Q021	P.S. 21	Q	IP Digital Video Surveillance System
25	Q022	P.S. 22	Q	Electrical Systems
25	Q022	P.S. 22	Q	Heating Plant Upgrade
25	Q022	P.S. 22	Q	Lighting Fixtures
25	Q022	P.S. 22	Q	Student Toilets
25	Q024	P.S. 24	Q	Electrical Systems
25	Q024	P.S. 24	Q	IP Digital Video Surveillance System
25	Q024	P.S. 24	Q	Lighting Fixtures
25	Q025	J.H.S. 25	Q	Accessibility
25	Q025	J.H.S. 25	Q	Electrical Systems
25	Q025	J.H.S. 25	Q	Student Toilets
25	Q029	P.S. 29	Q	Electrical Systems
25	Q029	P.S. 29	Q	Flood Elimination
25	Q029	P.S. 29	Q	Roofs
25	Q032	P.S. 32	Q	Lighting Fixtures
25	Q032	P.S. 32	Q	Student Toilets
25	Q079	P.S. 79	Q	Heating Plant Upgrade
25	Q079	P.S. 79	Q	Playground Redevelopment and TCU Removal
25	Q107	P.S. 107	Q	Flood Elimination
25	Q107	P.S. 107	Q	Student Toilets
25	Q120	P.S. 120	Q	IP Digital Video Surveillance System
25	Q120	P.S. 120	Q	Lighting Fixtures
25	Q129	P.S. 129	Q	Electrical Systems
25	Q129	P.S. 129	Q	IP Digital Video Surveillance System
25	Q129	P.S. 129	Q	Student Toilets
25	Q130	P.S. 130	Q	Exterior Masonry
25	Q130	P.S. 130	Q	Flood Elimination
25	Q130	P.S. 130	Q	Heating Plant Upgrade
25	Q130	P.S. 130	Q	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
25	Q130	P.S. 130	Q	Parapets
25	Q130	P.S. 130	Q	Roofs
25	Q130	P.S. 130	Q	Student Toilets
25	Q154	P.S. 154	Q	Lighting Fixtures
25	Q164	P.S. 164	Q	Domestic Piping
25	Q164	P.S. 164	Q	Student Toilets
25	Q165	P.S. 165	Q	Electrical Systems
25	Q168	J.H.S. 168	Q	Waste System
25	Q169	P.S. 169	Q	Student Toilets
25	Q185	J.H.S. 185	Q	Accessibility
25	Q185	J.H.S. 185	Q	IP Digital Video Surveillance System
25	Q185	J.H.S. 185	Q	Lighting Fixtures
25	Q185	J.H.S. 185	Q	Student Toilets
25	Q189	J.H.S. 189	Q	Heating Plant Upgrade
25	Q189	J.H.S. 189	Q	IP Digital Video Surveillance System
25	Q193	P.S. 193	Q	IP Digital Video Surveillance System
25	Q193	P.S. 193	Q	Playground Redevelopment and TCU Removal
25	Q194	J.H.S. 194	Q	Heating Plant Upgrade
25	Q194	J.H.S. 194	Q	Heating Plant Upgrade
25	Q200	P.S. 200	Q	Electrical Systems
25	Q209	P.S. 209	Q	New/Retrofit Telephone/Intercom System
25	Q214	P.S. 214	Q	Exterior Masonry
25	Q214	P.S. 214	Q	Flood Elimination
25	Q214	P.S. 214	Q	Parapets
25	Q214	P.S. 214	Q	Roofs
25	Q219	P.S. 219	Q	Heating Plant Upgrade
25	Q219	P.S. 219	Q	Kitchen Areas
25	Q219	P.S. 219	Q	Lighting Fixtures
25	Q219	P.S. 219	Q	Roofs
25	Q237	J.H.S. 237	Q	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
25	Q237	J.H.S. 237	Q	Student Toilets
25	Q242	P.S. 242 - (ECC)	Q	IP Digital Video Surveillance System
25	Q242	P.S. 242 - (ECC)	Q	Roofs
25	Q499	P.S./I.S. 499	Q	Accessibility
25	Q499	P.S./I.S. 499	Q	IP Digital Video Surveillance System
26	Q018	P.S. 18	Q	Boiler Conversion
26	Q026	P.S. 26	Q	Flood Elimination
26	Q041	P.S. 41	Q	New/Retrofit Telephone/Intercom System
26	Q041	P.S. 41	Q	Student Toilets
26	Q046	P.S. 46	Q	Student Toilets
26	Q067	J.H.S. 67	Q	Electrical Systems
26	Q067	J.H.S. 67	Q	Heating Plant Upgrade
26	Q067	J.H.S. 67	Q	Student Toilets
26	Q074	I.S. 74	Q	Accessibility
26	Q074	I.S. 74	Q	Electrical Systems
26	Q074	I.S. 74	Q	Student Toilets
26	Q094	P.S. 94	Q	Electrical Systems
26	Q094	P.S. 94	Q	New/Retrofit Telephone/Intercom System
26	Q094	P.S. 94	Q	Student Toilets
26	Q094	P.S. 94	Q	Student Toilets
26	Q098	P.S. 98	Q	Electrical Systems
26	Q098	P.S. 98	Q	Student Toilets
26	Q115	P.S. 115	Q	Student Toilets
26	Q133	P.S. 133	Q	Student Toilets
26	Q158	J.H.S. 158	Q	IP Digital Video Surveillance System
26	Q158	J.H.S. 158	Q	Student Toilets
26	Q159	P.S. 159	Q	Flood Elimination
26	Q159	P.S. 159	Q	Student Toilets
26	Q162	P.S. 162	Q	Exterior Masonry
26	Q162	P.S. 162	Q	Flood Elimination



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
26	Q162	P.S. 162	Q	Roofs
26	Q172	J.H.S. 172	Q	Heating Plant Upgrade
26	Q173	P.S. 173	Q	Student Toilets
26	Q178	P.S. 178	Q	Electrical Systems
26	Q179	P.S. 179	Q	Heating Plant Upgrade
26	Q186	P.S. 186	Q	Electrical Systems
26	Q186	P.S. 186	Q	Heating Plant Upgrade
26	Q188	P.S. 188	Q	Emergency Lighting and Fire Safety Retrofits
26	Q188	P.S. 188	Q	New/Retrofit Telephone/Intercom System
26	Q191	P.S. 191	Q	Lighting Fixtures
26	Q203	P.S. 203	Q	New/Retrofit Telephone/Intercom System
26	Q203	P.S. 203	Q	Windows
26	Q205	P.S. 205	Q	Flood Elimination
26	Q205	P.S. 205	Q	Heating Plant Upgrade
26	Q205	P.S. 205	Q	Heating Plant Upgrade
26	Q205	P.S. 205	Q	Lighting Fixtures
26	Q205	P.S. 205	Q	New/Retrofit Telephone/Intercom System
26	Q205	P.S. 205	Q	Parapets
26	Q205	P.S. 205	Q	Roofs
26	Q213	P.S. 213	Q	Heating Plant Upgrade
26	Q216	J.H.S. 216	Q	Cafeteria / Multipurpose Room Upgrade
26	Q216	J.H.S. 216	Q	Heating Plant Upgrade
26	Q216	J.H.S. 216	Q	Lighting Fixtures
26	Q216	J.H.S. 216	Q	Student Toilets
26	Q858	P.S. 188 ANNEX	Q	Electrical Systems
27	Q042	P.S. 42	Q	Electrical Systems
27	Q042	P.S. 42	Q	Lighting Fixtures
27	Q043	P.S. 43	Q	Playground Redevelopment and TCU Removal
27	Q045	P.S. 45	Q	Student Toilets
27	Q047	P.S. 47	Q	Climate Control

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
27	Q047	P.S. 47	Q	Heating Plant Upgrade
27	Q053	I.S. 53	Q	Accessibility
27	Q053	I.S. 53	Q	Exterior Masonry
27	Q053	I.S. 53	Q	Flood Elimination
27	Q053	I.S. 53	Q	Floors
27	Q053	I.S. 53	Q	New/Retrofit Telephone/Intercom System
27	Q053	I.S. 53	Q	Parapets
27	Q053	I.S. 53	Q	Roofs
27	Q053	I.S. 53	Q	Student Toilets
27	Q053	I.S. 53	Q	Windows
27	Q056	P.S. 56 (OLD R HILL AX)	Q	Exterior Masonry
27	Q056	P.S. 56 (OLD R HILL AX)	Q	New/Retrofit Telephone/Intercom System
27	Q056	P.S. 56 (OLD R HILL AX)	Q	Roofs
27	Q056	P.S. 56 (OLD R HILL AX)	Q	Student Toilets
27	Q060	P.S. 60	Q	Student Toilets
27	Q063	P.S. 63	Q	Auditorium Upgrade
27	Q063	P.S. 63	Q	Exterior Masonry
27	Q063	P.S. 63	Q	IP Digital Video Surveillance System
27	Q063	P.S. 63	Q	Parapets
27	Q063	P.S. 63	Q	Roofs
27	Q063	P.S. 63	Q	Student Toilets
27	Q064	P.S. 64	Q	Climate Control
27	Q064	P.S. 64	Q	Heating Plant Upgrade
27	Q064	P.S. 64	Q	Low-Voltage Electrical Systems
27	Q064	P.S. 64	Q	Student Toilets
27	Q066	P.S. 66	Q	Electrical Systems
27	Q066	P.S. 66	Q	New/Retrofit Telephone/Intercom System
27	Q066	P.S. 66	Q	Student Toilets
27	Q090	P.S. 90	Q	Cafeteria / Multipurpose Room Upgrade
27	Q090	P.S. 90	Q	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
27	Q096	P.S. 96	Q	Electrical Systems
27	Q100	P.S. 100	Q	Accessibility
27	Q100	P.S. 100	Q	Elevators and Escalators
27	Q100	P.S. 100	Q	Heating Plant Upgrade
27	Q100	P.S. 100	Q	Student Toilets
27	Q100	P.S. 100	Q	Student Toilets
27	Q104	P.S. 104	Q	Boiler Conversion
27	Q105	P.S. 105	Q	Classroom Connectivity
27	Q105	P.S. 105	Q	Interior Spaces
27	Q105	P.S. 105	Q	Paved Area-Blacktop
27	Q105	P.S. 105	Q	Student Toilets
27	Q105	P.S. 105	Q	Ventilation
27	Q106	P.S. 106	Q	Student Toilets
27	Q108	P.S. 108	Q	Electrical Systems
27	Q108	P.S. 108	Q	Student Toilets
27	Q114	P.S. 114	Q	Domestic Piping
27	Q114	P.S. 114	Q	Heating Plant Upgrade
27	Q123	P.S. 123	Q	Playground Redevelopment and TCU Removal
27	Q123	P.S. 123	Q	Student Toilets
27	Q124	P.S. 124	Q	Student Toilets
27	Q137	M.S. 137	Q	Heating Plant Upgrade
27	Q137	M.S. 137	Q	IP Digital Video Surveillance System
27	Q146	P.S. 146	Q	Lighting Fixtures
27	Q146	P.S. 146	Q	Student Toilets
27	Q155	P.S. 155	Q	IP Digital Video Surveillance System
27	Q155	P.S. 155	Q	Lighting Fixtures
27	Q155	P.S. 155	Q	Playground Redevelopment and TCU Removal
27	Q155	P.S. 155	Q	Student Toilets
27	Q180	I.S. 323 (OLD IS 180)	Q	Student Toilets
27	Q183	P.S. 183	Q	IP Digital Video Surveillance System

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
27	Q183	P.S. 183	Q	Student Toilets
27	Q197	P.S. 197	Q	Exterior Masonry
27	Q197	P.S. 197	Q	Roofs
27	Q197	P.S. 197	Q	Student Toilets
27	Q198	I.S. 198	Q	Lighting Fixtures
27	Q202	I.S. 202	Q	Domestic Piping
27	Q202	I.S. 202	Q	Heating Plant Upgrade
27	Q207	P.S. 207	Q	IP Digital Video Surveillance System
27	Q207	P.S. 207	Q	Paved Area-Blacktop
27	Q210	I.S. 210	Q	Cafeteria / Multipurpose Room Upgrade
27	Q210	I.S. 210	Q	Heating Plant Upgrade
27	Q210	I.S. 210	Q	IP Digital Video Surveillance System
27	Q210	I.S. 210	Q	Student Toilets
27	Q215	P.S. 215	Q	Student Toilets
27	Q223	P.S. 223	Q	Heating Plant Upgrade
27	Q225	P.S. 225	Q	Electrical Systems
27	Q225	P.S. 225	Q	Interior Spaces
27	Q225	P.S. 225	Q	Lighting Fixtures
27	Q226	I.S. 226	Q	Low-Voltage Electrical Systems
27	Q226	I.S. 226	Q	Playground Redevelopment and TCU Removal
27	Q232	P.S. 232	Q	IP Digital Video Surveillance System
27	Q232	P.S. 232	Q	Lighting Fixtures
27	Q232	P.S. 232	Q	Student Toilets
27	Q253	P.S. 253	Q	New/Retrofit Telephone/Intercom System
27	Q254	P.S. 254	Q	Exterior Masonry
27	Q254	P.S. 254	Q	Parapets
27	Q254	P.S. 254	Q	Paved Area-Concrete
27	Q907	P.S. 43 ANNEX	Q	Flood Elimination
27	Q907	P.S. 43 ANNEX	Q	Interior Spaces
27	Q907	P.S. 43 ANNEX	Q	New/Retrofit Telephone/Intercom System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
28	Q003	P.S. 303	Q	Lighting Fixtures
28	Q008	J.H.S. 8	Q	Heating Plant Upgrade
28	Q030	P.S. 30	Q	Heating Plant Upgrade
28	Q030	P.S. 30	Q	Lighting Fixtures
28	Q030	P.S. 30	Q	Playground Redevelopment and TCU Removal
28	Q030	P.S. 30	Q	Student Toilets
28	Q040	P.S. 40	Q	Flood Elimination
28	Q040	P.S. 40	Q	Playground Redevelopment and TCU Removal
28	Q040	P.S. 40	Q	Student Toilets
28	Q048	P.S. 48	Q	Flood Elimination
28	Q054	P.S. 54	Q	Student Toilets
28	Q055	P.S. 55	Q	New/Retrofit Telephone/Intercom System
28	Q055	P.S. 55	Q	Playground Redevelopment and TCU Removal
28	Q072	J.H.S. 72	Q	Science Lab Upgrades
28	Q080	P.S. 80	Q	Heating Plant Upgrade
28	Q080	P.S. 80	Q	Student Toilets
28	Q082	P.S. 82	Q	Classroom Connectivity
28	Q099	P.S. 99	Q	Boiler Conversion
28	Q099	P.S. 99	Q	Heating Plant Upgrade
28	Q099	P.S. 99	Q	Heating Plant Upgrade
28	Q099	P.S. 99	Q	New/Retrofit Telephone/Intercom System
28	Q117	P.S. 117	Q	IP Digital Video Surveillance System
28	Q117	P.S. 117	Q	New/Retrofit Telephone/Intercom System
28	Q121	P.S. 121	Q	Playground Redevelopment and TCU Removal
28	Q121	P.S. 121	Q	Reinforcing Cinder Concrete Slabs
28	Q139	P.S. 139	Q	Playgrounds
28	Q139	P.S. 139	Q	Roofs
28	Q140	P.S. 140	Q	Student Toilets
28	Q144	P.S. 144	Q	Electrical Systems
28	Q144	P.S. 144	Q	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
28	Q144	P.S. 144	Q	New/Retrofit Telephone/Intercom System
28	Q144	P.S. 144	Q	Student Toilets
28	Q157	J.H.S. 157	Q	Student Toilets
28	Q160	P.S. 160	Q	Climate Control
28	Q160	P.S. 160	Q	Flood Elimination
28	Q160	P.S. 160	Q	Heating Plant Upgrade
28	Q160	P.S. 160	Q	New/Retrofit Telephone/Intercom System
28	Q160	P.S. 160	Q	Parapets
28	Q160	P.S. 160	Q	Roofs
28	Q174	P.S. 174	Q	Heating Plant Upgrade
28	Q174	P.S. 174	Q	Lighting Fixtures
28	Q175	P.S. 175	Q	Exterior Masonry
28	Q190	J.H.S. 190	Q	Accessibility
28	Q190	J.H.S. 190	Q	IP Digital Video Surveillance System
28	Q190	J.H.S. 190	Q	Roofs
28	Q196	P.S. 196	Q	Exterior Masonry
28	Q196	P.S. 196	Q	Heating Plant Upgrade
28	Q196	P.S. 196	Q	Parapets
28	Q196	P.S. 196	Q	Roofs
28	Q206	P.S. 206	Q	Heating Plant Upgrade
28	Q217	I.S. 217	Q	Student Toilets
28	Q220	P.S. 220	Q	Student Toilets
28	Q278	PS 182 ANNEX	Q	Lighting Fixtures
28	Q278	PS 182 ANNEX	Q	New/Retrofit Telephone/Intercom System
28	Q814	P.S. 82 ANNEX	Q	Electrical Systems
29	Q033	P.S. 33	Q	Exterior Masonry
29	Q033	P.S. 33	Q	Parapets
29	Q033	P.S. 33	Q	Playground Redevelopment and TCU Removal
29	Q034	P.S. 34	Q	Student Toilets
29	Q036	P.S. 36	Q	Student Toilets

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
29	Q037	P.S. 37	Q	Elevators and Escalators
29	Q037	P.S. 37	Q	Heating Plant Upgrade
29	Q037	P.S. 37	Q	Low-Voltage Electrical Systems
29	Q038	P.S. 38	Q	New/Retrofit Telephone/Intercom System
29	Q038	P.S. 38	Q	Playground Redevelopment and TCU Removal
29	Q052	P.S. 52	Q	Parapets
29	Q052	P.S. 52	Q	Playground Redevelopment and TCU Removal
29	Q052	P.S. 52	Q	Student Toilets
29	Q059	I.S. 59	Q	Heating Plant Upgrade
29	Q059	I.S. 59	Q	IP Digital Video Surveillance System
29	Q095	P.S. 95	Q	Lighting Fixtures
29	Q095	P.S. 95	Q	Student Toilets
29	Q109	I.S. 109	Q	Lighting Fixtures
29	Q116	P.S. 116	Q	Heating Plant Upgrade
29	Q116	P.S. 116	Q	Parapets
29	Q116	P.S. 116	Q	Reinforcing Cinder Concrete Slabs
29	Q116	P.S. 116	Q	Roofs
29	Q116	P.S. 116	Q	Student Toilets
29	Q118	P.S. 118	Q	Heating Plant Upgrade
29	Q118	P.S. 118	Q	Student Toilets
29	Q131	P.S. 131	Q	Exterior Masonry
29	Q131	P.S. 131	Q	Parapets
29	Q131	P.S. 131	Q	Roofs
29	Q131	P.S. 131	Q	Student Toilets
29	Q132	P.S. 132	Q	Electrical Systems
29	Q136	P.S. 136	Q	Student Toilets
29	Q138	P.S. 138	Q	Auditorium Upgrade
29	Q138	P.S. 138	Q	New/Retrofit Telephone/Intercom System
29	Q138	P.S. 138	Q	Student Toilets
29	Q147	P.S. 147	Q	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
29	Q156	P.S. 156	Q	Playground Redevelopment and TCU Removal
29	Q176	P.S. 176	Q	Classroom Connectivity
29	Q176	P.S. 176	Q	Electrical Systems
29	Q181	P.S. 181	Q	Electrical Systems
29	Q181	P.S. 181	Q	Exterior Masonry
29	Q181	P.S. 181	Q	Flood Elimination
29	Q181	P.S. 181	Q	Parapets
29	Q181	P.S. 181	Q	Roofs
29	Q195	P.S. 195	Q	Student Toilets
29	Q208	P.S./I.S. 208	Q	Climate Control
29	Q231	I.S. 231 (TANDEM Q251)	Q	Lighting Fixtures
29	Q238	I.S. 238	Q	Accessibility
29	Q238	I.S. 238	Q	Cafeteria / Multipurpose Room Upgrade
29	Q238	I.S. 238	Q	Lighting Fixtures
29	Q238	I.S. 238	Q	Student Toilets
29	Q263	P.S. /I.S 295	Q	IP Digital Video Surveillance System
29	Q268	P.S. 268	Q	Accessibility
29	Q270	P.S. 270	Q	Roofs
29	Q836	P.S. 36 MINISCHOOL	Q	Roofs
30	Q002	P.S. 2	Q	Student Toilets
30	Q010	I.S. 10	Q	IP Digital Video Surveillance System
30	Q011	P.S. 11	Q	Heating Plant Upgrade
30	Q069	P.S. 69	Q	Lighting Fixtures
30	Q076	P.S. 76	Q	Student Toilets
30	Q084	P.S. 84	Q	IP Digital Video Surveillance System
30	Q084	P.S. 84	Q	Student Toilets
30	Q085	P.S. 85	Q	Electrical Systems
30	Q085	P.S. 85	Q	IP Digital Video Surveillance System
30	Q085	P.S. 85	Q	New/Retrofit Telephone/Intercom System
30	Q085	P.S. 85	Q	Student Toilets



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
30	Q111	P.S. 111	Q	Electrical Systems
30	Q111	P.S. 111	Q	Student Toilets
30	Q112	P.S. 112	Q	Exterior Masonry
30	Q112	P.S. 112	Q	Parapets
30	Q112	P.S. 112	Q	Roofs
30	Q112	P.S. 112	Q	Student Toilets
30	Q122	P.S. 122	Q	IP Digital Video Surveillance System
30	Q126	I.S. 126	Q	Heating Plant Upgrade
30	Q126	I.S. 126	Q	IP Digital Video Surveillance System
30	Q126	I.S. 126	Q	Lighting Fixtures
30	Q126	I.S. 126	Q	Student Toilets
30	Q127	P.S. 127	Q	Exterior Masonry
30	Q127	P.S. 127	Q	Parapets
30	Q127	P.S. 127	Q	Student Toilets
30	Q141	I.S. 141	Q	Lighting Fixtures
30	Q141	I.S. 141	Q	Student Toilets
30	Q148	P.S. 148	Q	Heating Plant Upgrade
30	Q148	P.S. 148	Q	IP Digital Video Surveillance System
30	Q148	P.S. 148	Q	Student Toilets
30	Q149	P.S. 149	Q	Accessibility
30	Q149	P.S. 149	Q	Electrical Systems
30	Q149	P.S. 149	Q	Lighting Fixtures
30	Q150	P.S. 150	Q	Student Toilets
30	Q151	P.S. 151	Q	Classroom Connectivity
30	Q151	P.S. 151	Q	Electrical Systems
30	Q151	P.S. 151	Q	Exterior Masonry
30	Q151	P.S. 151	Q	IP Digital Video Surveillance System
30	Q151	P.S. 151	Q	Lighting Fixtures
30	Q151	P.S. 151	Q	Parapets
30	Q151	P.S. 151	Q	Playground Redevelopment and TCU Removal

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
30	Q151	P.S. 151	Q	Roofs
30	Q151	P.S. 151	Q	Student Toilets
30	Q152	P.S. 152	Q	Student Toilets
30	Q171	P.S. 171	Q	IP Digital Video Surveillance System
30	Q204	I.S. 204	Q	Heating Plant Upgrade
30	Q204	I.S. 204	Q	IP Digital Video Surveillance System
30	Q204	I.S. 204	Q	Student Toilets
30	Q227	I.S. 227	Q	Lighting Fixtures
30	Q230	I.S. 230	Q	Cafeteria / Multipurpose Room Upgrade
30	Q230	I.S. 230	Q	Heating Plant Upgrade
30	Q230	I.S. 230	Q	IP Digital Video Surveillance System
30	Q234	P.S. 234	Q	Accessibility
30	Q234	P.S. 234	Q	Heating Plant Upgrade
30	Q234	P.S. 234	Q	IP Digital Video Surveillance System
30	Q234	P.S. 234	Q	IP Digital Video Surveillance System
30	Q292	P.S. 92	Q	Lighting Fixtures
30	Q292	P.S. 92	Q	Windows
31	R001	P.S. 1	R	Heating Plant Upgrade
31	R001	P.S. 1	R	Parapets
31	R001	P.S. 1	R	Roofs
31	R001	P.S. 1	R	Windows
31	R002	I.S. 2	R	Lighting Fixtures
31	R002	I.S. 2	R	Lighting Fixtures
31	R002	I.S. 2	R	Student Toilets
31	R004	P.S. 4	R	Electrical Systems
31	R004	P.S. 4	R	Heating Plant Upgrade
31	R006	P.S. 6	R	Heating Plant Upgrade
31	R006	P.S. 6	R	IP Digital Video Surveillance System
31	R006	P.S. 6	R	Lighting Fixtures
31	R007	I.S. 7	R	Cafeteria / Multipurpose Room Upgrade

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R007	I.S. 7	R	Lighting Fixtures
31	R008	P.S. 8	R	Domestic Piping
31	R008	P.S. 8	R	Lighting Fixtures
31	R008	P.S. 8	R	Student Toilets
31	R011	P.S. 11	R	Student Toilets
31	R014	P.S. 14	R	IP Digital Video Surveillance System
31	R014	P.S. 14	R	Student Toilets
31	R016	P.S. 16	R	Electrical Systems
31	R016	P.S. 16	R	Student Toilets
31	R018	P.S. 18	R	Electrical Systems
31	R018	P.S. 18	R	Student Toilets
31	R019	P.S. 19	R	Electrical Systems
31	R019	P.S. 19	R	Exterior Masonry
31	R019	P.S. 19	R	Flood Elimination
31	R019	P.S. 19	R	Lighting Fixtures
31	R019	P.S. 19	R	Parapets
31	R019	P.S. 19	R	Roofs
31	R019	P.S. 19	R	Windows
31	R021	P.S. 21	R	Electrical Systems
31	R021	P.S. 21	R	Heating Plant Upgrade
31	R021	P.S. 21	R	Student Toilets
31	R022	P.S. 22	R	Student Toilets
31	R023	P.S. 23	R	Lighting Fixtures
31	R023	P.S. 23	R	New/Retrofit Telephone/Intercom System
31	R024	I.S. 24	R	Cafeteria / Multipurpose Room Upgrade
31	R024	I.S. 24	R	Heating Plant Upgrade
31	R026	P.S. 26	R	Student Toilets
31	R027	I.S. 27	R	Heating Plant Upgrade
31	R027	I.S. 27	R	Student Toilets
31	R029	P.S. 29	R	Climate Control

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R029	P.S. 29	R	Electrical Systems
31	R029	P.S. 29	R	Heating Plant Upgrade
31	R029	P.S. 29	R	Lighting Fixtures
31	R030	P.S. 30	R	Electrical Systems
31	R031	P.S. 31	R	Lighting Fixtures
31	R032	P.S. 32	R	Exterior Masonry
31	R032	P.S. 32	R	IP Digital Video Surveillance System
31	R032	P.S. 32	R	Roofs
31	R032	P.S. 32	R	Student Toilets
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Accessibility
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Heating Plant Upgrade
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Lighting Fixtures
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Low-Voltage Electrical Systems
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Science Lab Upgrades
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Waste System
31	R035	P.S. 35	R	Climate Control
31	R035	P.S. 35	R	Electrical Systems
31	R035	P.S. 35	R	Student Toilets
31	R036	P.S. 36	R	Auditorium Upgrade
31	R036	P.S. 36	R	Exterior Masonry
31	R036	P.S. 36	R	Flood Elimination
31	R036	P.S. 36	R	Heating Plant Upgrade
31	R036	P.S. 36	R	Heating Plant Upgrade
31	R036	P.S. 36	R	IP Digital Video Surveillance System
31	R036	P.S. 36	R	Lighting Fixtures
31	R036	P.S. 36	R	New/Retrofit Telephone/Intercom System
31	R036	P.S. 36	R	Roofs
31	R036	P.S. 36	R	Windows
31	R041	P.S. 41	R	Lighting Fixtures
31	R041	P.S. 41	R	Low-Voltage Electrical Systems

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R041	P.S. 41	R	Student Toilets
31	R042	P.S. 42	R	Heating Plant Upgrade
31	R043	JEROME PARKER CAMPUS	R	Heating Plant Upgrade
31	R044	P.S. 44	R	Exterior Masonry
31	R044	P.S. 44	R	Lighting Fixtures
31	R044	P.S. 44	R	Parapets
31	R044	P.S. 44	R	Roofs
31	R044	P.S. 44	R	Windows
31	R045	P.S. 45	R	Exterior Masonry
31	R045	P.S. 45	R	Flood Elimination
31	R045	P.S. 45	R	Heating Plant Upgrade
31	R045	P.S. 45	R	IP Digital Video Surveillance System
31	R045	P.S. 45	R	Lighting Fixtures
31	R046	P.S. 46	R	Electrical Systems
31	R046	P.S. 46	R	Heating Plant Upgrade
31	R046	P.S. 46	R	Student Toilets
31	R049	I.S. 49	R	Cafeteria / Multipurpose Room Upgrade
31	R049	I.S. 49	R	IP Digital Video Surveillance System
31	R049	I.S. 49	R	Student Toilets
31	R050	P.S. 50	R	Electrical Systems
31	R050	P.S. 50	R	IP Digital Video Surveillance System
31	R051	I.S. 51	R	Domestic Piping
31	R051	I.S. 51	R	Electrical Systems
31	R051	I.S. 51	R	IP Digital Video Surveillance System
31	R052	P.S. 52	R	Lighting Fixtures
31	R053	P.S. 53	R	Heating Plant Upgrade
31	R053	P.S. 53	R	Heating Plant Upgrade
31	R053	P.S. 53	R	IP Digital Video Surveillance System
31	R054	P.S. 54	R	Heating Plant Upgrade
31	R054	P.S. 54	R	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R055	P.S. 55	R	Electrical Systems
31	R055	P.S. 55	R	Heating Plant Upgrade
31	R055	P.S. 55	R	Heating Plant Upgrade
31	R055	P.S. 55	R	Lighting Fixtures
31	R056	P.S. 56	R	Accessibility
31	R056	P.S. 56	R	Climate Control
31	R057	P.S. 57	R	Student Toilets
31	R058	P.S. 58	R	Accessibility
31	R058	P.S. 58	R	Heating Plant Upgrade
31	R058	P.S. 58	R	IP Digital Video Surveillance System
31	R058	P.S. 58	R	Lighting Fixtures
31	R059	THE HARBOR VIEW SCHOOL	R	Student Toilets
31	R060	P.S. 60	R	Electrical Systems
31	R060	P.S. 60	R	Parapets
31	R061	I.S. 61	R	Cafeteria / Multipurpose Room Upgrade
31	R061	I.S. 61	R	Domestic Piping
31	R061	I.S. 61	R	Electrical Systems
31	R061	I.S. 61	R	Lighting Fixtures
31	R061	I.S. 61	R	Student Toilets
31	R069	P.S. 69	R	Heating Plant Upgrade
31	R069	P.S. 69	R	Lighting Fixtures
31	R072	I.S. 72	R	Heating Plant Upgrade
31	R072	I.S. 72	R	Lighting Fixtures
31	R072	I.S. 72	R	Student Toilets
31	R075	I.S. 75	R	Electrical Systems
31	R075	I.S. 75	R	Heating Plant Upgrade
31	R075	I.S. 75	R	IP Digital Video Surveillance System
31	R802	P.S. 1 ANNEX	R	Electrical Systems
31	R826	P.S. 3 ANNEX	R	Electrical Systems
31	R829	ARTHUR D. PHILLIPS SCHOOL	R	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R831	P.S. 16 ANNEX	R	Air Conditioning Split System
31	R831	P.S. 74	R	Electrical Systems
31	R844	P.S. 36 ANNEX	R	Electrical Systems
31	R848	P.S. 42 ANNEX	R	Electrical Systems
31	R848	P.S. 42 ANNEX	R	Student Toilets
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	Electrical Systems
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	Heating Plant Upgrade
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	Student Toilets
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	Technology
31	R885	P.S. 80 AX(PETR COMPL-BLDG D)	R	Electrical Systems
31	R886	P.S. 80 AX(PETR COMPL-BLDG C)	R	Electrical Systems
32	K045	P.S. 45	K	Heating Plant Upgrade
32	K045	P.S. 45	K	Lighting Fixtures
32	K045	P.S. 45	K	Lighting Fixtures
32	K045	P.S. 45	K	Student Toilets
32	K075	P.S. 75	K	New/Retrofit Telephone/Intercom System
32	K086	P.S. 86	K	Electrical Systems
32	K086	P.S. 86	K	Student Toilets
32	K106	P.S. 106	K	Electrical Systems
32	K106	P.S. 106	K	Heating Plant Upgrade
32	K106	P.S. 106	K	Student Toilets
32	K111	I.S. 111	K	Cafeteria / Multipurpose Room Upgrade
32	K111	I.S. 111	K	Electrical Systems
32	K111	I.S. 111	K	Lighting Fixtures
32	K116	P.S. 116	K	Lighting Fixtures
32	K116	P.S. 116	K	Lighting Fixtures
32	K123	P.S. 123	K	Domestic Piping
32	K123	P.S. 123	K	Flood Elimination
32	K123	P.S. 123	K	Floors
32	K123	P.S. 123	K	Heating Plant Upgrade

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
32	K123	P.S. 123	K	IP Digital Video Surveillance System
32	K123	P.S. 123	K	Lighting Fixtures
32	K123	P.S. 123	K	Low-Voltage Electrical Systems
32	K123	P.S. 123	K	Paved Area-Concrete
32	K123	P.S. 123	K	Roofs
32	K145	P.S. 145	K	Accessibility
32	K145	P.S. 145	K	Heating Plant Upgrade
32	K145	P.S. 145	K	Lighting Fixtures
32	K145	P.S. 145	K	New/Retrofit Telephone/Intercom System
32	K145	P.S. 145	K	Playground Redevelopment
32	K145	P.S. 145	K	Student Toilets
32	K151	P.S. 151	K	Playgrounds
32	K151	P.S. 151	K	Student Toilets
32	K162	I.S. 162	K	New/Retrofit Telephone/Intercom System
32	K274	P.S. 274	K	Electrical Systems
32	K274	P.S. 274	K	Exterior Masonry
32	K274	P.S. 274	K	Parapets
32	K291	I.S. 291	K	IP Digital Video Surveillance System
32	K291	I.S. 291	K	Student Toilets
32	K296	I.S. 296	K	Electrical Systems
32	K296	I.S. 296	K	IP Digital Video Surveillance System
32	K299	P.S. 299	K	Playground Redevelopment
32	K376	P.S. 376A	K	Accessibility
32	K376	P.S. 376A	K	Heating Plant Upgrade
32	K377	P.S. 377	K	Auditorium Upgrade
32	K377	P.S. 377	K	Exterior Masonry
32	K377	P.S. 377	K	Lighting Fixtures
32	K377	P.S. 377	K	Roofs
32	K383	I.S. 383	K	Accessibility
32	K384	P.S. 384	K	Domestic Piping



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
32	K842	P.S. 45 AX (OLD BS RDGWD ECC1)	K	Ventilation
32	K865	SECOND OPPORTUNITY SCHOOL	K	Code Compliance
02	M011	P.S. 11	M	Heating Plant Upgrade
03	M144	P.S. 242 (OLD P144)	M	Boiler Conversion
03	M144	P.S. 242 (OLD P144)	M	Climate Control
08	X060	P.S. 333	X	Electrical Systems
08	X119	P.S. 119	X	Boiler Conversion
08	X119	P.S. 119	X	Climate Control
10	X003	P.S. 3	X	Accessibility
10	X007	P.S. 7	X	Roofs
10	X009	P.S. 9 (OLD 115)	X	Roofs
10	X009	P.S. 9 (OLD 115)	X	Parapets
10	X009	P.S. 9 (OLD 115)	X	Exterior Masonry
10	X009	P.S. 9 (OLD 115)	X	Ventilation
10	X015	P.S. 15	X	Low-Voltage Electrical System
10	X015	P.S. 15	X	Accessibility
10	X023	P.S. 23	X	Heating Plant Upgrade
10	X026	P.S. 396	X	Cafeteria / Multipurpose Room Upgrade
10	X026	P.S. 396	X	Domestic Piping
10	X026	P.S. 396	X	IP Digital Video Surveillance System
10	X033	P.S. 33	X	Electrical Systems
10	X033	P.S. 33	X	IP Digital Video Surveillance System
10	X045	I.S. 45	X	Electrical Systems
10	X045	I.S. 45	X	Science Lab Upgrades
10	X045	I.S. 45	X	IP Digital Video Surveillance System
10	X059	P.S. 59	X	Containerization
10	X059	P.S. 59	X	Heating Plant Upgrade
10	X079	P.S. 79	X	Toilets - Students
10	X079	P.S. 79	X	IP Digital Video Surveillance System
10	X080	I.S. 80/P.S. 280	X	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
10	X085	P.S. 85	X	Containerization
10	X085	P.S. 85	X	Cafeteria / Multipurpose Room Upgrade
10	X085	P.S. 85	X	Electrical Systems
10	X091	P.S. 91	X	Low-Voltage Electrical System
10	X094	P.S. 94	X	Roofs
10	X095	P.S. 95	X	IP Digital Video Surveillance System
10	X118	I.S. 118	X	Flood Elimination
10	X118	I.S. 118	X	Roofs
10	X118	I.S. 118	X	Parapets
10	X118	I.S. 118	X	Exterior Masonry
10	X137	I.S. 391 (UDC)	X	Containerization
10	X141	M.S./H.S. 141	X	Roofs
10	X141	M.S./H.S. 141	X	Parapets
10	X141	M.S./H.S. 141	X	Exterior Masonry
10	X141	M.S./H.S. 141	X	Electrical Systems
10	X143	I.S. 143	X	IP Digital Video Surveillance System
10	X177	THE NORWOOD EAST CAMPUS	X	IP Digital Video Surveillance System
10	X205	P.S. 205A (ECF)	X	Containerization
10	X209	P.S. 209	X	Flood Elimination
10	X209	P.S. 209	X	Roofs
10	X209	P.S. 209	X	Parapets
10	X209	P.S. 209	X	Exterior Masonry
10	X279	P.S. 279	X	Ventilation
10	X279	P.S. 279	X	IP Digital Video Surveillance System
10	X306	P.S. 306	X	Accessibility
10	X361	P.S. 94 ANNEX	X	IP Digital Video Surveillance System
10	X472	P.S. 246 (POE CENTER)	X	Gymnasiums
10	X481	P.S. 205A (ECF)	X	Gymnasiums
10	X819	P.S. 207	X	Electrical Systems
11	X016	P.S. 16	X	Playground Redevelopment

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
11	X019	P.S. 19 ADDITION	X	IP Digital Video Surveillance System
11	X021	P.S. 21	X	Electrical Systems
11	X041	P.S. 41	X	Flood Elimination
11	X041	P.S. 41	X	Roofs
11	X041	P.S. 41	X	Parapets
11	X041	P.S. 41	X	Windows
11	X041	P.S. 41	X	Exterior Masonry
11	X076	P.S. 76	X	Flood Elimination
11	X076	P.S. 76	X	Parapets
11	X076	P.S. 76	X	Exterior Masonry
11	X078	P.S. 78	X	Parapets
11	X078	P.S. 78	X	Exterior Masonry
11	X083	P.S. 83	X	Toilets - Students
11	X083	P.S. 83	X	Playgrounds
11	X089	P.S. 89	X	Playgrounds
11	X089	P.S. 89	X	IP Digital Video Surveillance System
11	X103	P.S. 103	X	Flood Elimination
11	X103	P.S. 103	X	Parapets
11	X103	P.S. 103	X	Exterior Masonry
11	X103	P.S. 103	X	IP Digital Video Surveillance System
11	X105	P.S. 105	X	Electrical Systems
11	X106	P.S. 106	X	Electrical Systems
11	X121	P.S. 121	X	Flood Elimination
11	X121	P.S. 121	X	Roofs
11	X121	P.S. 121	X	Parapets
11	X121	P.S. 121	X	Exterior Masonry
11	X135	I.S. 135	X	IP Digital Video Surveillance System
11	X142	I.S. 142	X	Electrical Systems
11	X142	I.S. 142	X	Emergency Lighting and Fire Safety Retrofits
11	X144	I.S. 144	X	Toilets - Students

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
11	X144	I.S. 144	X	IP Digital Video Surveillance System
11	X153	P.S. 153	X	Electrical Systems
11	X153	P.S. 153	X	Toilets - Students
11	X178	P.S. 178	X	Electrical Systems
11	X180	I.S. 180	X	Toilets - Students
11	X498	THE LT. CURTIS MEYRAN AND JOHN BELLEV	X	IP Digital Video Surveillance System
12	X006	P.S. 6	X	Electrical Systems
12	X061	P.S. 61	X	Flood Elimination
12	X061	P.S. 61	X	Roofs
12	X061	P.S. 61	X	Parapets
12	X061	P.S. 61	X	Exterior Masonry
12	X061	P.S. 61	X	IP Digital Video Surveillance System
12	X067	P.S. 67	X	Flood Elimination
12	X067	P.S. 67	X	Roofs
12	X067	P.S. 67	X	Paved Area - Concrete
12	X067	P.S. 67	X	Parapets
12	X067	P.S. 67	X	Cafeteria / Multipurpose Room Upgrade
12	X067	P.S. 67	X	Windows
12	X067	P.S. 67	X	Exterior Masonry
12	X067	P.S. 67	X	Playground Redevelopment
12	X092	P.S. 92	X	Electrical Systems
12	X092	P.S. 92	X	Toilets - Students
12	X098	I.S. 98	X	Electrical Systems
12	X116	I.S. 216	X	IP Digital Video Surveillance System
12	X129	I.S. 129 (PAIRED W P234)	X	IP Digital Video Surveillance System
12	X134	P.S. 134	X	Playgrounds
12	X198	P.S. 198	X	Heating Plant Upgrade
12	X449	P.S. 6 GYM ANNEX	X	Gymnasiums
12	X834	P.S. 134 MINISCHOOL	X	Reinforcing Cinder Concrete Slabs
13	K003	P.S. 3	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
13	K009	P.S. 9	K	Accessibility
13	K011	P.S. 11	K	Flood Elimination
13	K011	P.S. 11	K	Roofs
13	K011	P.S. 11	K	Parapets
13	K011	P.S. 11	K	Exterior Masonry
13	K020	P.S. 20	K	Electrical Systems
13	K044	P.S. 44	K	Toilets - Students
13	K046	P.S. 46	K	Heating Plant Upgrade
13	K046	P.S. 46	K	Toilets - Students
13	K056	P.S. 56	K	Roofs
13	K056	P.S. 56	K	Parapets
13	K117	I.S. 117	K	IP Digital Video Surveillance System
13	K258	I.S. 258	K	IP Digital Video Surveillance System
13	K265	I.S. 265	K	IP Digital Video Surveillance System
13	K282	P.S. 282	K	Electrical Systems
13	K282	P.S. 282	K	Heating Plant Upgrade
13	K282	P.S. 282	K	Emergency Lighting and Fire Safety Retrofits
14	K016	P.S. 16	K	Roofs
14	K016	P.S. 16	K	Parapets
14	K016	P.S. 16	K	Exterior Masonry
14	K033	I.S. 33	K	Boiler Conversion
14	K033	I.S. 33	K	Climate Control
14	K033	I.S. 33	K	IP Digital Video Surveillance System
14	K049	I.S. 49	K	Electrical Systems
14	K071	I.S. 71	K	Domestic Piping
14	K071	I.S. 71	K	IP Digital Video Surveillance System
14	K126	J.H.S. 126	K	Toilets - Students
14	K196	P.S. 196	K	Flood Elimination
14	K196	P.S. 196	K	Roofs
14	K196	P.S. 196	K	Roofs

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
14	K196	P.S. 196	K	Exterior Masonry
14	K315	P.S. 17 GYM ANNEX	K	Gymnasiums
14	K745	P.S. 132 GYM ANNEX	K	Gymnasiums
15	K001	P.S. 1	K	Low-Voltage Electrical System
15	K001	P.S. 1	K	Toilets - Students
15	K024	P.S. 24	K	Electrical Systems
15	K038	P.S. 38	K	Roofs
15	K038	P.S. 38	K	Parapets
15	K038	P.S. 38	K	Exterior Masonry
15	K051	I.S. 51	K	Roofs
15	K051	I.S. 51	K	Parapets
15	K051	I.S. 51	K	Exterior Masonry
15	K088	I.S. 88	K	Low-Voltage Electrical System
15	K088	I.S. 88	K	Electrical Systems
15	K088	I.S. 88	K	Accessibility
15	K088	I.S. 88	K	Science Lab Upgrades
15	K094	P.S. 94	K	Roofs
15	K136	I.S. 136	K	Parapets
15	K136	I.S. 136	K	Exterior Masonry
15	K136	I.S. 136	K	Emergency Lighting and Fire Safety Retrofits
15	K280	EDUCATIONAL CAMPUS @ 500 19TH STREET	K	Playgrounds
15	K293	J.H.S. 293	K	Electrical Systems
15	K293	J.H.S. 293	K	IP Digital Video Surveillance System
15	K442	I.S. 442	K	Toilets - Students
15	K477	P.S. 172 GYM ANNEX	K	Gymnasiums
15	K749	PRE-K CENTER @ 173 25TH STREET	K	Toilets - Students
15	K845	P.S. 295	K	Electrical Systems
16	K025	P.S. 25	K	Heating Plant Upgrade
16	K025	P.S. 25	K	IP Digital Video Surveillance System
16	K026	P.S. 26	K	Containerization

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
16	K026	P.S. 26	K	Electrical Systems
16	K026	P.S. 26	K	IP Digital Video Surveillance System
16	K035	I.S. 35	K	Electrical Systems
16	K035	I.S. 35	K	Heating Plant Upgrade
16	K035	I.S. 35	K	IP Digital Video Surveillance System
16	K057	J.H.S. 57	K	Electrical Systems
16	K057	J.H.S. 57	K	IP Digital Video Surveillance System
16	K308	P.S. 308	K	Heating Plant Upgrade
16	K308	P.S. 308	K	IP Digital Video Surveillance System
16	K309	P.S. 309	K	Toilets - Students
16	K324	I.S. 324	K	Lighting Fixtures
16	K324	I.S. 324	K	Accessibility
16	K324	I.S. 324	K	IP Digital Video Surveillance System
17	K002	I.S. 2	K	Student Toilets
17	K002	I.S. 2	K	IP Digital Video Surveillance System
17	K022	P.S. 22	K	Ventilation
17	K022	P.S. 22	K	Accessibility
17	K022	P.S. 22	K	IP Digital Video Surveillance System
17	K091	P.S. 91	K	Student Toilets
17	K091	P.S. 91	K	Heating Plant Upgrade
17	K092	P.S. 92	K	Student Toilets
17	K092	P.S. 92	K	Roofs
17	K092	P.S. 92	K	Parapets
17	K092	P.S. 92	K	Exterior Masonry
17	K092	P.S. 92	K	Electrical Systems
17	K092	P.S. 92	K	Emergency Lighting and Fire Safety Retrofits
17	K138	P.S. 138	K	IP Digital Video Surveillance System
17	K161	P.S. 161	K	Heating Plant Upgrade
17	K161	P.S. 161	K	IP Digital Video Surveillance System
17	K189	P.S. 189	K	Science Lab Upgrades

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
17	K191	P.S. 191	K	Playgrounds
17	K221	P.S. 221	K	Roofs
17	K221	P.S. 221	K	Electrical Systems
17	K246	I.S. 246	K	Accessibility
17	K246	I.S. 246	K	IP Digital Video Surveillance System
17	K249	P.S. 249	K	Toilets - Students
17	K249	P.S. 249	K	Accessibility
17	K289	P.S. 289	K	Student Toilets
17	K289	P.S. 289	K	Heating Plant Upgrade
17	K289	P.S. 289	K	Heating Plant Upgrade
17	K316	P.S. 316	K	IP Digital Video Surveillance System
17	K390	I.S. 390	K	Playgrounds
17	K390	I.S. 390	K	Playgrounds
17	K391	I.S. 391	K	Electrical Systems
17	K391	I.S. 391	K	Accessibility
17	K397	P.S. 397	K	Toilets - Students
17	K399	P.S. 399	K	Boiler Conversion
17	K707	P.S. 189 GYM ANNEX	K	Gymnasiums
17	K874	I.S. 340 (OLD 249 AX)	K	Playgrounds
18	K066	P.S. 66	K	Toilets - Students
18	K068	I.S. 68	K	Electrical Systems
18	K068	I.S. 68	K	Toilets - Students
18	K068	I.S. 68	K	Emergency Lighting and Fire Safety Retrofits
18	K114	P.S. 114	K	Electrical Systems
18	K115	P.S. 115	K	Playgrounds
18	K115	P.S. 115	K	Playgrounds
18	K115	P.S. 115	K	Playgrounds
18	K135	P.S. 135	K	Roofs
18	K135	P.S. 135	K	Parapets
18	K135	P.S. 135	K	Exterior Masonry



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
18	K232	I.S. 232	K	Playgrounds
18	K232	I.S. 232	K	Playgrounds
18	K232	I.S. 232	K	Playgrounds
18	K232	I.S. 232	K	Roofs
18	K232	I.S. 232	K	IP Digital Video Surveillance System
18	K235	P.S. 235	K	Roofs
18	K244	P.S. 244	K	Electrical Systems
18	K252	I.S. 252	K	Roofs
18	K252	I.S. 252	K	IP Digital Video Surveillance System
18	K268	P.S. 268	K	Electrical Systems
18	K268	P.S. 268	K	Toilets - Students
18	K268	P.S. 268	K	Emergency Lighting and Fire Safety Retrofits
18	K272	P.S. 272	K	Electrical Systems
18	K272	P.S. 272	K	Emergency Lighting and Fire Safety Retrofits
18	K276	P.S. 276	K	IP Digital Video Surveillance System
18	K285	I.S. 285	K	Electrical Systems
18	K285	I.S. 285	K	Emergency Lighting and Fire Safety Retrofits
18	K285	I.S. 285	K	IP Digital Video Surveillance System
18	K855	P.S. 135/P.S. 235 ANNEX	K	Heating Plant Upgrade
19	K013	P.S. 13	K	Playgrounds
19	K072	P.S. 72	K	Lighting Fixtures
19	K158	P.S. 158	K	Flood Elimination
19	K158	P.S. 158	K	Paved Area - Concrete
19	K158	P.S. 158	K	Gymnasium Upgrade
19	K158	P.S. 158	K	Parapets
19	K158	P.S. 158	K	Windows
19	K158	P.S. 158	K	Electrical Systems
19	K158	P.S. 158	K	Technology
19	K159	P.S. 159	K	Playground Redevelopment and TCU Removal
19	K171	I.S. 171	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
19	K174	P.S. 174	K	Roofs
19	K174	P.S. 174	K	Electrical Systems
19	K174	P.S. 174	K	Emergency Lighting and Fire Safety Retrofits
19	K202	P.S. 202	K	Playground Redevelopment and TCU Removal
19	K213	P.S. 213	K	Playgrounds
19	K213	P.S. 213	K	Playgrounds
19	K213	P.S. 213	K	Boiler Conversion
19	K213	P.S. 213	K	Climate Control
19	K213	P.S. 213	K	Heating Plant Upgrade
19	K214	P.S. 214	K	Roofs
19	K218	I.S. 218	K	IP Digital Video Surveillance System
19	K260	P.S. 260	K	Electrical Systems
19	K292	I.S. 292	K	IP Digital Video Surveillance System
19	K306	P.S. 306	K	Electrical Systems
19	K306	P.S. 306	K	Emergency Lighting and Fire Safety Retrofits
19	K328	P.S. 328	K	Roofs
19	K328	P.S. 328	K	Parapets
19	K328	P.S. 328	K	Exterior Masonry
19	K328	P.S. 328	K	Electrical Systems
19	K345	P.S. 345	K	Boiler Conversion
19	K345	P.S. 345	K	Climate Control
19	K346	P.S. 346	K	Toilets - Students
19	K346	P.S. 346	K	Toilets - Students
19	K368	P.S. 159 GYM ANNEX	K	Gymnasiums
19	K478	P.S. 190 GYM ANNEX	K	Gymnasiums
19	K798	CESIAH TORO MULLANE SCHOOL	K	IP Digital Video Surveillance System
19	K814	CYPRESS HILLS COMMUNITY SCHOOL	K	IP Digital Video Surveillance System
19	K814	CYPRESS HILLS COMMUNITY SCHOOL	K	Technology
19	K848	P.S. 149 ANNEX	K	Roofs
19	K848	P.S. 149 ANNEX	K	Parapets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
19	K848	P.S. 149 ANNEX	K	Exterior Masonry
20	K062	I.S. 62	K	Boiler Conversion
20	K062	I.S. 62	K	Climate Control
20	K062	I.S. 62	K	IP Digital Video Surveillance System
20	K069	P.S. 69	K	Roofs
20	K069	P.S. 69	K	Kitchen Areas
20	K069	P.S. 69	K	Exterior Masonry
20	K069	P.S. 69	K	Heating Plant Upgrade
20	K105	P.S. 105	K	Cafeteria / Multipurpose Room Upgrade
20	K112	P.S. 112	K	IP Digital Video Surveillance System
20	K160	P.S. 160	K	Electrical Systems
20	K163	P.S. 163	K	Heating Plant Upgrade
20	K186	P.S. 186	K	IP Digital Video Surveillance System
20	K200	P.S. 200	K	Parapets
20	K200	P.S. 200	K	Domestic Piping
20	K204	P.S. 204	K	Domestic Piping
20	K205	P.S. 205	K	Roofs
20	K205	P.S. 205	K	Exterior Masonry
20	K220	I.S. 220	K	Electrical Systems
20	K220	I.S. 220	K	IP Digital Video Surveillance System
20	K223	I.S. 223	K	Flood Elimination
20	K223	I.S. 223	K	Roofs
20	K223	I.S. 223	K	Parapets
20	K223	I.S. 223	K	Exterior Masonry
20	K223	I.S. 223	K	Electrical Systems
20	K223	I.S. 223	K	IP Digital Video Surveillance System
20	K227	I.S. 227	K	Heating Plant Upgrade
20	K227	I.S. 227	K	Accessibility
20	K229	P.S. 229	K	Flood Elimination
20	K229	P.S. 229	K	Roofs

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
20	K229	P.S. 229	K	Paved Area - Blacktop
20	K229	P.S. 229	K	Parapets
20	K229	P.S. 229	K	Exterior Masonry
20	K229	P.S. 229	K	IP Digital Video Surveillance System
20	K247	P.S. 247	K	Flood Elimination
20	K247	P.S. 247	K	Roofs
20	K247	P.S. 247	K	Parapets
20	K247	P.S. 247	K	Exterior Masonry
20	K259	I.S. 259	K	IP Digital Video Surveillance System
20	K314	P.S. 314	K	Ventilation
20	K693	P.S. 112 GYM ANNEX	K	Gymnasiums
20	K807	P.S./ I.S. 163	K	Domestic Piping
20	K807	P.S./ I.S. 163	K	IP Digital Video Surveillance System
20	K971	P.S. 971	K	IP Digital Video Surveillance System
21	K096	I.S. 96	K	Floors
21	K096	I.S. 96	K	IP Digital Video Surveillance System
21	K128	P.S. 128 (TANDEM BROOKLYN STUDIO)	K	Electrical Systems
21	K128	P.S. 128 (TANDEM BROOKLYN STUDIO)	K	IP Digital Video Surveillance System
21	K188	P.S. 188	K	Exterior Masonry
21	K225	P.S. 225	K	IP Digital Video Surveillance System
21	K226	P.S. 226	K	Accessibility
21	K228	I.S. 228	K	IP Digital Video Surveillance System
21	K253	P.S. 253	K	Roofs
21	K253	P.S. 253	K	Parapets
21	K253	P.S. 253	K	Electrical Systems
21	K281	I.S. 281	K	Domestic Piping
21	K303	I.S. 303	K	Floors
22	K014	I.S. 14	K	IP Digital Video Surveillance System
22	K052	P.S. 52	K	Domestic Piping
22	K078	I.S. 78	K	Heating Plant Upgrade

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
22	K078	I.S. 78	K	Heating Plant Upgrade
22	K078	I.S. 78	K	Domestic Piping
22	K139	P.S. 139	K	Electrical Systems
22	K152	P.S. 152	K	Electrical Systems
22	K193	P.S. 193	K	Heating Plant Upgrade
22	K195	P.S. 195	K	Toilets - Students
22	K197	P.S. 197	K	Domestic Piping
22	K203	P.S. 203	K	Electrical Systems
22	K217	P.S. 217	K	Paved Area - Concrete
22	K234	I.S. 234	K	Electrical Systems
22	K234	I.S. 234	K	Emergency Lighting and Fire Safety Retrofits
22	K240	I.S. 240	K	Flood Elimination
22	K240	I.S. 240	K	Roofs
22	K240	I.S. 240	K	Windows
22	K240	I.S. 240	K	Exterior Masonry
22	K240	I.S. 240	K	Toilets - Students
22	K251	P.S. 251	K	Boiler Conversion
22	K251	P.S. 251	K	Climate Control
22	K251	P.S. 251	K	Toilets - Students
22	K255	P.S. 255	K	Roofs
22	K255	P.S. 255	K	Parapets
22	K255	P.S. 255	K	Windows
22	K255	P.S. 255	K	Exterior Masonry
22	K255	P.S. 255	K	Toilets - Students
22	K277	P.S. 277	K	Boiler Conversion
22	K277	P.S. 277	K	Climate Control
22	K277	P.S. 277	K	Electrical Systems
22	K395	P.S./I.S. 395	K	Heating Plant Upgrade
22	K729	P.S. 207 ANNEX	K	Electrical Systems
22	K735	P.S. 245	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
22	K735	P.S. 245	K	Emergency Lighting and Fire Safety Retrofits
22	K839	P.S. 134 MINISCHOOL	K	Toilets - Students
23	K041	P.S. 41	K	Boiler Conversion
23	K041	P.S. 41	K	Climate Control
23	K041	P.S. 41	K	Electrical Systems
23	K055	I.S. 55	K	Heating Plant Upgrade
23	K137	P.S. 137	K	Heating Plant Upgrade
23	K165	P.S. 165	K	Electrical Systems
23	K178	P.S. 178	K	Toilets - Students
23	K184	P.S. 184	K	Roofs
23	K184	P.S. 184	K	Parapets
23	K184	P.S. 184	K	Exterior Masonry
23	K263	P.S./I.S. 323	K	Electrical Systems
23	K271	I.S. 271	K	IP Digital Video Surveillance System
23	K275	I.S. 275	K	IP Digital Video Surveillance System
23	K298	P.S. 298	K	Electrical Systems
23	K298	P.S. 298	K	Emergency Lighting and Fire Safety Retrofits
23	K356	P.S. 156	K	Playgrounds
24	Q005	I.S. 5	Q	Heating Plant Upgrade
24	Q013	P.S. 13	Q	Electrical Systems
24	Q013	P.S. 13	Q	IP Digital Video Surveillance System
24	Q014	P.S. 14	Q	Electrical Systems
24	Q019	P.S. 19 ADDITION	Q	Heating Plant Upgrade
24	Q058	P.S. 58	Q	Ventilation
24	Q061	I.S. 61	Q	IP Digital Video Surveillance System
24	Q068	P.S. 68	Q	Electrical Systems
24	Q071	P.S. 71	Q	Roofs
24	Q073	I.S. 73	Q	Boiler Conversion
24	Q073	I.S. 73	Q	Climate Control
24	Q073	I.S. 73	Q	Emergency Lighting and Fire Safety Retrofits

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
24	Q073	I.S. 73	Q	IP Digital Video Surveillance System
24	Q081	P.S. 81	Q	Heating Plant Upgrade
24	Q081	P.S. 81	Q	Heating Plant Upgrade
24	Q087	P.S. 87	Q	IP Digital Video Surveillance System
24	Q088	P.S. 88	Q	Ventilation
24	Q089	P.S. 89	Q	Electrical Systems
24	Q089	P.S. 89	Q	Ventilation
24	Q091	P.S. 91	Q	Electrical Systems
24	Q091	P.S. 91	Q	Science Lab Upgrades
24	Q102	P.S./I.S. 102	Q	Flood Elimination
24	Q102	P.S./I.S. 102	Q	Roofs
24	Q102	P.S./I.S. 102	Q	Parapets
24	Q102	P.S./I.S. 102	Q	Windows
24	Q102	P.S./I.S. 102	Q	Exterior Masonry
24	Q102	P.S./I.S. 102	Q	Toilets - Students
24	Q113	P.S./I.S. 113	Q	IP Digital Video Surveillance System
24	Q125	I.S. 125 ADDITION	Q	Electrical Systems
24	Q143	P.S. 143 ADDITION	Q	Electrical Systems
24	Q153	P.S. 153	Q	Toilets - Students
24	Q229	P.S. 229	Q	Low-Voltage Electrical System
24	Q229	P.S. 229	Q	Windows
24	Q229	P.S. 229	Q	Electrical Systems
24	Q229	P.S. 229	Q	Heating Plant Upgrade
24	Q229	P.S. 229	Q	Emergency Lighting and Fire Safety Retrofits
24	Q239	P.S. 239	Q	Heating Plant Upgrade
24	Q245	P.S. 245 ECC (@ SENECA AVE)	Q	IP Digital Video Surveillance System
24	Q260	P.S. 307	Q	IP Digital Video Surveillance System
24	Q721	P.S. 16 (OLD Q721 SPED)	Q	Heating Plant Upgrade
24	Q721	P.S. 16 (OLD Q721 SPED)	Q	Heating Plant Upgrade
24	Q849	I.S. 77	Q	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
24	Q849	I.S. 77	Q	IP Digital Video Surveillance System
25	Q020	P.S. 20	Q	Roofs
25	Q020	P.S. 20	Q	Parapets
25	Q020	P.S. 20	Q	Exterior Masonry
25	Q022	P.S. 22	Q	Playground Redevelopment and TCU Removal
25	Q025	J.H.S. 25	Q	Air Conditioning Split System
25	Q025	J.H.S. 25	Q	Heating Plant Upgrade
25	Q025	J.H.S. 25	Q	IP Digital Video Surveillance System
25	Q032	P.S. 32	Q	Electrical Systems
25	Q079	P.S. 79	Q	Electrical Systems
25	Q154	P.S. 154	Q	Toilets - Students
25	Q163	P.S. 163	Q	Electrical Systems
25	Q163	P.S. 163	Q	Emergency Lighting and Fire Safety Retrofits
25	Q168	J.H.S. 168	Q	Roofs
25	Q168	J.H.S. 168	Q	Parapets
25	Q168	J.H.S. 168	Q	Exterior Masonry
25	Q168	J.H.S. 168	Q	Electrical Systems
25	Q169	P.S. 169	Q	Electrical Systems
25	Q185	J.H.S. 185	Q	Electrical Systems
25	Q185	J.H.S. 185	Q	Heating Plant Upgrade
25	Q185	J.H.S. 185	Q	Heating Plant Upgrade
25	Q189	J.H.S. 189	Q	Toilets - Students
25	Q193	P.S. 193	Q	Boiler Conversion
25	Q193	P.S. 193	Q	Climate Control
25	Q193	P.S. 193	Q	Electrical Systems
25	Q193	P.S. 193	Q	Heating Plant Upgrade
25	Q201	P.S. 201	Q	Boiler Conversion
25	Q201	P.S. 201	Q	Climate Control
25	Q201	P.S. 201	Q	Electrical Systems
25	Q201	P.S. 201	Q	Emergency Lighting and Fire Safety Retrofits



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
25	Q209	P.S. 209	Q	Electrical Systems
25	Q242	P.S. 242 - (ECC)	Q	Playgrounds
25	Q244	P.S. 244 ECC (@ FRANKLIN AVE)	Q	IP Digital Video Surveillance System
26	Q018	P.S. 18	Q	Toilets - Students
26	Q026	P.S. 26	Q	Boiler Conversion
26	Q026	P.S. 26	Q	Climate Control
26	Q026	P.S. 26	Q	Toilets - Students
26	Q046	P.S. 46 ADDITION	Q	Boiler Conversion
26	Q046	P.S. 46 ADDITION	Q	Climate Control
26	Q046	P.S. 46	Q	Roofs
26	Q098	P.S. 98	Q	Exterior Masonry
26	Q158	J.H.S. 158	Q	Low-Voltage Electrical System
26	Q158	J.H.S. 158	Q	Electrical Systems
26	Q158	J.H.S. 158	Q	Emergency Lighting and Fire Safety Retrofits
26	Q162	P.S. 162	Q	Electrical Systems
26	Q173	P.S. 173	Q	Electrical Systems
26	Q188	P.S. 188	Q	Toilets - Students
26	Q191	P.S. 191	Q	Flood Elimination
26	Q191	P.S. 191	Q	Roofs
26	Q191	P.S. 191	Q	Parapets
26	Q191	P.S. 191	Q	Exterior Masonry
26	Q203	P.S. 203	Q	Electrical Systems
26	Q205	P.S. 205	Q	Auditorium Upgrade
26	Q213	P.S. 213	Q	Toilets - Students
26	Q216	J.H.S. 216	Q	Roofs
26	Q216	J.H.S. 216	Q	Parapets
26	Q216	J.H.S. 216	Q	Windows
26	Q216	J.H.S. 216	Q	Exterior Masonry
26	Q216	J.H.S. 216	Q	Electrical Systems
26	Q216	J.H.S. 216	Q	Emergency Lighting and Fire Safety Retrofits

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
26	Q221	P.S. 221	Q	Heating Plant Upgrade
26	Q221	P.S. 221	Q	Toilets - Students
26	Q266	P.S./I.S. 266	Q	IP Digital Video Surveillance System
27	Q042	P.S. 42	Q	IP Digital Video Surveillance System
27	Q042	P.S. 42	Q	Technology
27	Q043	P.S. 43	Q	Playground Redevelopment and TCU Removal
27	Q043	P.S. 43	Q	Technology
27	Q043	P.S. 43	Q	Technology
27	Q045	P.S. 45	Q	Flood Elimination
27	Q045	P.S. 45	Q	Roofs
27	Q045	P.S. 45	Q	Parapets
27	Q045	P.S. 45	Q	Exterior Masonry
27	Q047	P.S. 47	Q	Gymnasium Upgrade
27	Q053	I.S. 53	Q	Boiler Conversion
27	Q053	I.S. 53	Q	Climate Control
27	Q053	I.S. 53	Q	IP Digital Video Surveillance System
27	Q053	I.S. 53	Q	Technology
27	Q056	P.S. 56 (OLD R HILL AX)	Q	Playground Redevelopment
27	Q062	P.S. 62	Q	Heating Plant Upgrade
27	Q062	P.S. 62	Q	Toilets - Students
27	Q090	P.S. 90	Q	Electrical Systems
27	Q097	P.S. 97	Q	Heating Plant Upgrade
27	Q105	P.S. 105	Q	IP Digital Video Surveillance System
27	Q105	P.S. 105	Q	Technology
27	Q106	P.S. 106	Q	Domestic Piping
27	Q108	P.S. 108	Q	Flood Elimination
27	Q108	P.S. 108	Q	Roofs
27	Q108	P.S. 108	Q	Parapets
27	Q108	P.S. 108	Q	Windows
27	Q108	P.S. 108	Q	Exterior Masonry

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
27	Q108	P.S. 108	Q	Heating Plant Upgrade
27	Q146	P.S. 146	Q	Accessibility
27	Q146	P.S. 146	Q	Playground Redevelopment
27	Q183	P.S. 183	Q	Technology
27	Q197	P.S. 197	Q	Electrical Systems
27	Q197	P.S. 197	Q	Heating Plant Upgrade
27	Q197	P.S. 197	Q	Technology
27	Q202	I.S. 202	Q	Electrical Systems
27	Q207	P.S. 207	Q	Toilets - Students
27	Q223	P.S. 223	Q	Ventilation
27	Q223	P.S. 223	Q	Toilets - Students
27	Q226	I.S. 226	Q	Flood Elimination
27	Q226	I.S. 226	Q	Parapets
27	Q226	I.S. 226	Q	Exterior Masonry
27	Q226	I.S. 226	Q	Heating Plant Upgrade
27	Q226	I.S. 226	Q	Toilets - Students
27	Q226	I.S. 226	Q	IP Digital Video Surveillance System
27	Q232	P.S. 232	Q	Flood Elimination
27	Q232	P.S. 232	Q	Boiler Conversion
27	Q232	P.S. 232	Q	Climate Control
27	Q232	P.S. 232	Q	Low-Voltage Electrical System
27	Q232	P.S. 232	Q	Exterior Masonry
27	Q253	P.S. 253	Q	Technology
27	Q254	P.S. 254	Q	Heating Plant Upgrade
27	Q254	P.S. 254	Q	Accessibility
27	Q262	P.S. 262	Q	IP Digital Video Surveillance System
27	Q273	P.S. 273	Q	IP Digital Video Surveillance System
28	Q003	P.S. 303 ADDITION	Q	IP Digital Video Surveillance System
28	Q008	J.H.S. 8	Q	IP Digital Video Surveillance System
28	Q048	P.S. 48	Q	Domestic Piping

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
28	Q055	P.S. 55	Q	Boiler Conversion
28	Q055	P.S. 55	Q	Climate Control
28	Q055	P.S. 55	Q	Heating Plant Upgrade
28	Q072	J.H.S. 72	Q	Electrical Systems
28	Q072	J.H.S. 72	Q	Toilets - Students
28	Q072	J.H.S. 72	Q	IP Digital Video Surveillance System
28	Q082	P.S. 82	Q	Heating Plant Upgrade
28	Q101	P.S. 101	Q	Electrical Systems
28	Q117	P.S. 117	Q	Electrical Systems
28	Q117	P.S. 117	Q	Heating Plant Upgrade
28	Q117	P.S. 117	Q	Heating Plant Upgrade
28	Q121	P.S. 121	Q	Flood Elimination
28	Q121	P.S. 121	Q	Roofs
28	Q121	P.S. 121	Q	Fencing
28	Q121	P.S. 121	Q	Parapets
28	Q121	P.S. 121	Q	Windows
28	Q121	P.S. 121	Q	Exterior Masonry
28	Q121	P.S. 121	Q	Toilets - Students
28	Q121	P.S. 121	Q	Safety Systems
28	Q139	P.S. 139	Q	Heating Plant Upgrade
28	Q139	P.S. 139	Q	Heating Plant Upgrade
28	Q139	P.S. 139	Q	Toilets - Students
28	Q160	P.S. 160	Q	Heating Plant Upgrade
28	Q161	P.S. 161	Q	Science Lab Upgrades
28	Q175	P.S. 175	Q	Electrical Systems
28	Q175	P.S. 175	Q	Heating Plant Upgrade
28	Q175	P.S. 175	Q	Emergency Lighting and Fire Safety Retrofits
28	Q217	I.S. 217	Q	Accessibility
28	Q217	I.S. 217	Q	IP Digital Video Surveillance System
28	Q276	THE WILLIAM WORDSWORTH EDUCATIONAL	Q	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
28	Q277	PS 182 SAMANTHA SMITH	Q	Accessibility
28	Q277	PS 182 SAMANTHA SMITH	Q	IP Digital Video Surveillance System
29	Q015	P.S. 15	Q	Roofs
29	Q034	P.S. 34	Q	Roofs
29	Q034	P.S. 34	Q	Windows
29	Q034	P.S. 34	Q	Exterior Masonry
29	Q034	P.S. 34	Q	Air Conditioning Split System
29	Q035	P.S. 35	Q	Electrical Systems
29	Q036	P.S. 36	Q	Electrical Systems
29	Q059	I.S. 59	Q	Electrical Systems
29	Q095	P.S. 95	Q	Electrical Systems
29	Q109	I.S. 109	Q	IP Digital Video Surveillance System
29	Q116	P.S. 116	Q	Heating Plant Upgrade
29	Q132	P.S. 132	Q	Toilets - Students
29	Q138	P.S. 138	Q	Electrical Systems
29	Q138	P.S. 138	Q	Emergency Lighting and Fire Safety Retrofits
29	Q147	P.S. 147	Q	Heating Plant Upgrade
29	Q156	P.S. 156	Q	Toilets - Students
29	Q156	P.S. 156	Q	Library Upgrade
29	Q156	P.S. 156	Q	Technology
29	Q176	P.S. 176	Q	Emergency Lighting and Fire Safety Retrofits
29	Q181	P.S. 181	Q	Technology
29	Q208	P.S./I.S. 208	Q	Heating Plant Upgrade
29	Q208	P.S./I.S. 208	Q	IP Digital Video Surveillance System
29	Q238	I.S. 238	Q	Electrical Systems
29	Q251	P.S. 251 (TANDEM Q231)	Q	IP Digital Video Surveillance System
29	Q270	P.S. 270	Q	Toilets - Students
29	Q270	P.S. 270	Q	Technology
29	Q357	P.S. 36 GYM ANNEX	Q	Gymnasiums
30	Q002	P.S. 2 MINISCHOOL	Q	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
30	Q010	I.S. 10	Q	Roofs
30	Q010	I.S. 10	Q	Electrical Systems
30	Q010	I.S. 10	Q	Science Lab Upgrades
30	Q011	P.S. 11	Q	Electrical Systems
30	Q112	P.S. 112	Q	Electrical Systems
30	Q112	P.S. 112	Q	Heating Plant Upgrade
30	Q122	P.S. 122	Q	Heating Plant Upgrade
30	Q141	I.S. 141	Q	Roofs
30	Q141	I.S. 141	Q	Heating Plant Upgrade
30	Q145	I.S. 145	Q	Accessibility
30	Q145	I.S. 145	Q	IP Digital Video Surveillance System
30	Q148	P.S. 148	Q	Roofs
30	Q148	P.S. 148	Q	Exterior Masonry
30	Q150	P.S. 150	Q	Electrical Systems
30	Q166	P.S. 166	Q	Electrical Systems
30	Q171	P.S. 171	Q	Heating Plant Upgrade
30	Q204	I.S. 204	Q	Gymnasium Upgrade
30	Q204	I.S. 204	Q	Electrical Systems
30	Q204	I.S. 204	Q	Science Lab Upgrades
30	Q222	P.S. 222 (ECC)	Q	Domestic Piping
30	Q222	P.S. 222 (ECC)	Q	Playgrounds
30	Q227	I.S. 227	Q	Toilets - Students
30	Q280	P.S. 280	Q	Interior Spaces
30	Q397	PRE-K CENTER @ 32-52 37TH STREET	Q	Air Conditioning Split System
30	Q397	PRE-K CENTER @ 32-52 37TH STREET	Q	Toilets - Students
31	R001	P.S. 1	R	Electrical Systems
31	R003	P.S. 3	R	Heating Plant Upgrade
31	R007	I.S. 7	R	Exterior Masonry
31	R007	I.S. 7	R	IP Digital Video Surveillance System
31	R008	P.S. 8	R	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R013	P.S. 13	R	Roofs
31	R019	P.S. 19	R	Science Lab Upgrades
31	R022	P.S. 22	R	Electrical Systems
31	R022	P.S. 22	R	IP Digital Video Surveillance System
31	R026	P.S. 26	R	Heating Plant Upgrade
31	R030	P.S. 30	R	Roofs
31	R030	P.S. 30	R	Parapets
31	R030	P.S. 30	R	Exterior Masonry
31	R031	P.S. 31	R	Electrical Systems
31	R032	P.S. 32	R	Heating Plant Upgrade
31	R032	P.S. 32	R	Domestic Piping
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Roofs
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Parapets
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Windows
31	R034	I.S. 34 (OLD TOTTENVILLE)	R	Exterior Masonry
31	R038	P.S. 38	R	Heating Plant Upgrade
31	R044	P.S. 44	R	Flood Elimination
31	R051	I.S. 51	R	Accessibility
31	R052	P.S. 52	R	IP Digital Video Surveillance System
31	R053	P.S. 53	R	Domestic Piping
31	R054	P.S. 54	R	Electrical Systems
31	R054	P.S. 54	R	Emergency Lighting and Fire Safety Retrofits
31	R057	P.S. 57	R	Paved Area - Concrete
31	R057	P.S. 57	R	Electrical Systems
31	R061	I.S. 61	R	Roofs
31	R061	I.S. 61	R	Parapets
31	R061	I.S. 61	R	Windows
31	R061	I.S. 61	R	Exterior Masonry
31	R061	I.S. 61	R	Heating Plant Upgrade
31	R061	I.S. 61	R	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
31	R071	P.S./I.S. 48	R	Heating Plant Upgrade
31	R071	P.S./I.S. 48	R	Accessibility
31	R072	I.S. 72	R	Boiler Conversion
31	R072	I.S. 72	R	Climate Control
31	R072	I.S. 72	R	Electrical Systems
31	R072	I.S. 72	R	Emergency Lighting and Fire Safety Retrofits
31	R072	I.S. 72	R	IP Digital Video Surveillance System
31	R098	P.S. 20 GYM ANNEX	R	Gymnasiums
31	R099	P.S. 39 GYM ANNEX	R	Gymnasiums
31	R700	P.S. 74 GYM ANNEX	R	Gymnasiums
31	R701	P.S. 1 GYM ANNEX	R	Gymnasiums
31	R702	P.S. 54 GYM ANNEX	R	Gymnasiums
31	R829	ARTHUR D. PHILLIPS SCHOOL	R	IP Digital Video Surveillance System
31	R831	P.S. 74	R	Heating Plant Upgrade
31	R848	P.S. 42 ANNEX	R	Roofs
31	R848	P.S. 42 ANNEX	R	Exterior Masonry
31	R861	ELIZABETH A. CONNELLY CAMPUS	R	IP Digital Video Surveillance System
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	Accessibility
31	R880	P.S. 80 (PETR COMPL-BLDG B)	R	IP Digital Video Surveillance System
32	K075	P.S. 75	K	Flood Elimination
32	K075	P.S. 75	K	Roofs
32	K075	P.S. 75	K	Exterior Masonry
32	K086	P.S. 86	K	Electrical Systems
32	K145	P.S. 145	K	Electrical Systems
32	K151	P.S. 151	K	Heating Plant Upgrade
32	K162	I.S. 162	K	IP Digital Video Surveillance System
32	K376	P.S. 376A	K	Exterior Masonry
32	K376	P.S. 376A	K	Lighting Fixtures
32	K377	P.S. 377	K	Playgrounds
32	K383	I.S. 383	K	Containerization



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
32	K384	P.S. 384	K	Electrical Systems
32	K384	P.S. 384	K	IP Digital Video Surveillance System
33K	K801	CENT HEADQTRS (65 COURT)	K	Climate Control
33K	K801	CENT HEADQTRS (65 COURT)	K	Domestic Piping
33K	K801	CENT HEADQTRS (65 COURT)	K	Elevators and Escalators
33K	K801	CENT HEADQTRS (65 COURT)	K	Lighting Fixtures
33K	K801	CENT HEADQTRS (65 COURT)	K	Lighting Fixtures
33K	K801	CENT HEADQTRS (65 COURT)	K	Windows
33K	K986	DIV. OF INSTR. & INFO. TECH.	K	Lighting Fixtures
33Q	Q800	DOE ADMINISTRATIVE / STUDENT SERVICES	Q	Technology
33Q	Q801	OSSS / DSF	Q	Elevators and Escalators
33Q	Q801	OSSS / DSF	Q	Fire System Sprinklers
33Q	Q801	OSSS / DSF	Q	Low-Voltage Electrical Systems
33R	R080	REGION 7/ ROC F	R	Electrical Systems
75K	K085	P.S. 753 (OLD P85/STERLING HS)	K	Heating Plant Upgrade
75K	K085	P.S. 753 (OLD P85/STERLING HS)	K	IP Digital Video Surveillance System
75K	K085	P.S. 753 (OLD P85/STERLING HS)	K	Low-Voltage Electrical Systems
75K	K085	P.S. 753 (OLD P85/STERLING HS)	K	Electrical Systems
75K	K148	P.S. 373 (OLD P148)	K	Exterior Masonry
75K	K148	P.S. 373 (OLD P148)	K	Flood Elimination
75K	K148	P.S. 373 (OLD P148)	K	IP Digital Video Surveillance System
75K	K148	P.S. 373 (OLD P148)	K	Lighting Fixtures
75K	K148	P.S. 373 (OLD P148)	K	Lighting Fixtures
75K	K148	P.S. 373 (OLD P148)	K	Parapets
75K	K148	P.S. 373 (OLD P148)	K	Reinforcing Support Elements
75K	K148	P.S. 373 (OLD P148)	K	Student Toilets
75K	K148	P.S. 373 (OLD P148)	K	Student Toilets
75K	K148	P.S. 373 (OLD P148)	K	Electrical Systems
75K	K286	P.S. 811 (OLD P286)	K	Elevators and Escalators
75K	K286	P.S. 811 (OLD P286)	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
75K	K286	P.S. 811 (OLD P286)	K	Heating Plant Upgrade
75K	K286	P.S. 811 (OLD P286)	K	Ventilation
75K	K286	P.S. 811 (OLD P286)	K	Toilets - Students
75K	K370	P.S. 370	K	IP Digital Video Surveillance System
75K	K370	P.S. 370	K	Lighting Fixtures
75K	K371	P.S. 371 (OLD 615)	K	IP Digital Video Surveillance System
75K	K371	P.S. 371 (OLD 615)	K	Paved Area-Blacktop
75K	K371	P.S. 371 (OLD 615)	K	Student Toilets
75K	K722	P.S. 721 OTC	K	Heating Plant Upgrade
75K	K722	P.S. 721 OTC	K	Student Toilets
75K	K834	P.S. 372 (OUR LADY OF PEACE)	K	Low-Voltage Electrical Systems
75K	K834	P.S. 372 (OUR LADY OF PEACE)	K	New/Retrofit Telephone/Intercom System
75K	K834	P.S. 372 (OUR LADY OF PEACE)	K	Student Toilets
75K	K902	P.S. 77 ANNEX	K	Air Conditioning Split System
75K	K902	P.S. 77 ANNEX	K	Exterior Masonry
75K	K902	P.S. 77 ANNEX	K	Lighting Fixtures
75K	K902	P.S. 77 ANNEX	K	Low-Voltage Electrical Systems
75K	K902	P.S. 77 ANNEX	K	Parapets
75K	K902	P.S. 77 ANNEX	K	Paved Area-Concrete
75K	K902	P.S. 77 ANNEX	K	Roofs
75K	K902	P.S. 77 ANNEX	K	Safety Systems
75K	K902	P.S. 77 ANNEX	K	Ventilation
75K	K902	P.S. 77 ANNEX	K	Windows
75K	K902	P.S. 77 ANNEX	K	Toilets - Students
75M	M058	P.S. 35 (OLD 58/MNHT HS)	M	Electrical Systems
75M	M058	P.S. 35 (OLD 58/MNHT HS)	M	IP Digital Video Surveillance System
75M	M058	P.S. 35 (OLD 58/MNHT HS)	M	Lighting Fixtures
75M	M058	P.S. 35 (OLD 58/MNHT HS)	M	Student Toilets
75M	M079	P.S. 79 (MULT. HANDICAP)	M	Electrical Systems
75M	M079	P.S. 79 (MULT. HANDICAP)	M	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
75M	M079	P.S. 79 (MULT. HANDICAP)	M	Heating Plant Upgrade
75M	M079	P.S. 79 (MULT. HANDICAP)	M	Toilets - Students
75M	M169	P.S. 169 (ECF)	M	Elevators and Escalators
75M	M169	P.S. 169 (ECF)	M	Roofs
75M	M169	P.S. 169 (ECF)	M	IP Digital Video Surveillance System
75M	M751	P.S. 751 (CAR.DEV/OLD 25)	M	IP Digital Video Surveillance System
75M	M751	P.S. 751 (CAR.DEV/OLD 25)	M	Student Toilets
75M	M751	P.S. 751 (CAR.DEV/OLD 25)	M	Toilets - Students
75M	M841	P.S. 811 (OLD P148/LIVINGS HS)	M	Electrical Systems
75M	M841	P.S. 811 (OLD P148/LIVINGS HS)	M	Lighting Fixtures
75M	M841	P.S. 811 (OLD P148/LIVINGS HS)	M	Exterior Masonry
75M	M875	P.S. 226 (FIRST PRESB CHURCH)	M	Electrical Systems
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Accessibility
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Electrical Systems
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Exterior Masonry
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Flood Elimination
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Low-Voltage Electrical Systems
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Parapets
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Roofs
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Heating Plant Upgrade
75Q	Q075	P.S. 75 (R PEARY SCHOOL)	Q	Heating Plant Upgrade
75Q	Q142	P.S. 752 (OLD J142)	Q	Electrical Systems
75Q	Q142	P.S. 752 (OLD J142)	Q	Heating Plant Upgrade
75Q	Q177	P.S. 177	Q	Heating Plant Upgrade
75Q	Q177	P.S. 177	Q	Student Toilets
75Q	Q177	P.S. 177	Q	Flood Elimination
75Q	Q177	P.S. 177	Q	Roofs
75Q	Q177	P.S. 177	Q	Parapets
75Q	Q177	P.S. 177	Q	Windows
75Q	Q177	P.S. 177	Q	Exterior Masonry

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
75Q	Q667	SKILLMAN HIGH SCHOOL	Q	IP Digital Video Surveillance System
75Q	Q722	P.S. 721 (OTC)	Q	Heating Plant Upgrade
75Q	Q722	P.S. 721 (OTC)	Q	Roofs
75Q	Q811	P.S. 811 (OLD 187)	Q	Toilets - Students
75Q	Q816	P.S. 256 ANNEX	Q	Playground Redevelopment
75R	R025	P.S. 25 ANNEX (OLD 4)	R	Heating Plant Upgrade
75R	R025	P.S. 25 ANNEX (OLD 4)	R	Student Toilets
75R	R025	P.S. 25 ANNEX (OLD 4)	R	Playground Redevelopment
75R	R040	P.S. 373 (OLD P40)	R	Exterior Masonry
75R	R040	P.S. 373 (OLD P40)	R	Flood Elimination
75R	R040	P.S. 373 (OLD P40)	R	IP Digital Video Surveillance System
75R	R040	P.S. 373 (OLD P40)	R	Student Toilets
75R	R722	P.S. 722 (OTC)	R	Accessibility
75R	R722	P.S. 722 (OTC)	R	Air Conditioning Retrofit
75R	R722	P.S. 722 (OTC)	R	Domestic Piping
75R	R722	P.S. 722 (OTC)	R	Domestic Piping
75R	R722	P.S. 722 (OTC)	R	Domestic Piping
75R	R722	P.S. 722 (OTC)	R	Exterior Masonry
75R	R722	P.S. 722 (OTC)	R	Heating Plant Upgrade
75R	R722	P.S. 722 (OTC)	R	Lighting Fixtures
75R	R722	P.S. 722 (OTC)	R	Parapets
75R	R722	P.S. 722 (OTC)	R	Roofs
75R	R722	P.S. 722 (OTC)	R	Safety Systems
75R	R722	P.S. 722 (OTC)	R	Windows
75R	R825	P.S. 25 (MOUNT LORETTO)	R	Electrical Systems
75R	R825	P.S. 25 (MOUNT LORETTO)	R	Lighting Fixtures
75R	R840	P.S. 37 ( OLD I24X)	R	Electrical Systems
75R	R840	P.S. 37 ( OLD I24X)	R	Heating Plant Upgrade
75R	R840	P.S. 37 ( OLD I24X)	R	New/Retrofit Telephone/Intercom System
75R	R840	P.S. 37 ( OLD I24X)	R	Toilets - Students

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
75R	R884	P.S. 373 AX (PTR COMP-BLDG J)	R	Electrical Systems
75X	X012	P.S. 12	X	Electrical Systems
75X	X012	P.S. 12	X	Parapets
75X	X012	P.S. 12	X	Playground Redevelopment
75X	X012	P.S. 12	X	Windows
75X	X034	P.S. 34	X	New/Retrofit Telephone/Intercom System
75X	X034	P.S. 34	X	Flood Elimination
75X	X034	P.S. 34	X	Roofs
75X	X034	P.S. 34	X	Parapets
75X	X034	P.S. 34	X	Exterior Masonry
75X	X084	P.S. 811 (OLD 184)	X	Air Conditioning Retrofit
75X	X084	P.S. 811 (OLD 184)	X	New/Retrofit Telephone/Intercom System
75X	X136	P.S. 186 (OLD J136)	X	Electrical Systems
75X	X136	P.S. 186 (OLD J136)	X	Exterior Masonry
75X	X136	P.S. 186 (OLD J136)	X	Flood Elimination
75X	X136	P.S. 186 (OLD J136)	X	Parapets
75X	X136	P.S. 186 (OLD J136)	X	Roofs
75X	X136	P.S. 186 (OLD J136)	X	Student Toilets
75X	X155	P.S. 754 (OLD IS155)	X	Electrical Systems
75X	X155	P.S. 754 (OLD IS155)	X	Heating Plant Upgrade
75X	X155	P.S. 754 (OLD IS155)	X	Toilets - Students
75X	X155	P.S. 754 (OLD IS155)	X	IP Digital Video Surveillance System
75X	X701	P.S. 723	X	Ventilation
75X	X722	P.S. 721 (OTC)	X	Exterior Masonry
75X	X722	P.S. 721 (OTC)	X	Flood Elimination
75X	X722	P.S. 721 (OTC)	X	Parapets
75X	X722	P.S. 721 (OTC)	X	Roofs
75X	X722	P.S. 721 (OTC)	X	Windows
75X	X722	P.S. 721 (OTC)	X	Ventilation
75X	X722	P.S. 721 (OTC)	X	Toilets - Students

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K175	TEACHERS PREP HS(OL REDIRECTION)	K	Accessibility
78K	K175	TEACHERS PREP HS(OL REDIRECTION)	K	Toilets - Students
78K	K175	TEACHERS PREP HS(OL REDIRECTION)	K	IP Digital Video Surveillance System
78K	K313	ADAMS STREET EDUCATIONAL CAMPUS	K	Accessibility
78K	K313	ADAMS STREET EDUCATIONAL CAMPUS	K	IP Digital Video Surveillance System
78K	K400	LAFAYETTE HS	K	Domestic Piping
78K	K400	LAFAYETTE EDUCATIONAL CAMPUS	K	Electrical Systems
78K	K401	LAFAYETTE HS AF	K	Athletic Fields
78K	K405	MIDWOOD HS	K	Auditorium Upgrade
78K	K405	MIDWOOD HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K405	MIDWOOD HS	K	IP Digital Video Surveillance System
78K	K405	MIDWOOD HS	K	Lighting Fixtures
78K	K405	MIDWOOD HS	K	Low-Voltage Electrical Systems
78K	K406	MIDWOOD AF (MAIN)	K	Athletic Fields
78K	K406	MIDWOOD AF (MAIN)	K	Reinforcing Support Elements
78K	K410	ABRAHAM LINCOLN HS	K	Heating Plant Upgrade
78K	K410	ABRAHAM LINCOLN HS	K	IP Digital Video Surveillance System
78K	K410	ABRAHAM LINCOLN HS	K	Lighting Fixtures
78K	K410	ABRAHAM LINCOLN HS	K	Reinforcing Cinder Concrete Slabs
78K	K410	ABRAHAM LINCOLN HS	K	Windows
78K	K411	LINCOLN AF	K	Low-Voltage Electrical Systems
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Electrical Systems
78K	K415	SAMUEL J. TILDEN HS	K	IP Digital Video Surveillance System
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Flood Elimination
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Roofs
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Parapets
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Exterior Masonry
78K	K415	SAMUEL J. TILDEN EDUCATIONAL CAMPUS	K	Emergency Lighting and Fire Safety Retrofits
78K	K422	SPRING CREEK EDUCATIONAL CAMPUS	K	Lighting Fixtures
78K	K425	JAMES MADISON HS	K	Auditorium Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K425	JAMES MADISON HS	K	Electrical Systems
78K	K425	JAMES MADISON HS	K	Heating Plant Upgrade
78K	K425	JAMES MADISON HS	K	IP Digital Video Surveillance System
78K	K425	JAMES MADISON HS	K	Lighting Fixtures
78K	K425	JAMES MADISON HS	K	Low-Voltage Electrical Systems
78K	K425	JAMES MADISON HS	K	Swimming Pools
78K	K425	JAMES MADISON HS	K	Domestic Piping
78K	K425	JAMES MADISON HS	K	Toilets - Students
78K	K430	BROOKLYN TECH HS	K	Accessibility
78K	K430	BROOKLYN TECH HS	K	Boiler Conversion
78K	K430	BROOKLYN TECH HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K430	BROOKLYN TECH HS	K	Heating Plant Upgrade
78K	K430	BROOKLYN TECH HS	K	IP Digital Video Surveillance System
78K	K430	BROOKLYN TECH HS	K	Kitchen Areas
78K	K430	BROOKLYN TECH HS	K	Lighting Fixtures
78K	K430	BROOKLYN TECH HS	K	Low-Voltage Electrical Systems
78K	K430	BROOKLYN TECH HS	K	Student Toilets
78K	K430	BROOKLYN TECH HS	K	Ventilation
78K	K430	BROOKLYN TECH HS	K	Interior Spaces
78K	K430	BROOKLYN TECH HS	K	Climate Control
78K	K430	BROOKLYN TECH HS	K	Electrical Systems
78K	K430	BROOKLYN TECH HS	K	Science Lab Upgrades
78K	K435	THOMAS JEFFERSON HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K435	THOMAS JEFFERSON HS	K	Heating Plant Upgrade
78K	K435	THOMAS JEFFERSON HS	K	IP Digital Video Surveillance System
78K	K435	THOMAS JEFFERSON HS	K	Playground Redevelopment
78K	K435	THOMAS JEFFERSON HS	K	Electrical Systems
78K	K440	PROSPECT HEIGHTS HS	K	Auditorium Upgrade
78K	K440	PROSPECT HEIGHTS HS	K	Climate Control
78K	K440	PROSPECT HEIGHTS HS	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K440	PROSPECT HEIGHTS HS	K	New/Retrofit Telephone/Intercom System
78K	K440	PROSPECT HEIGHTS HS	K	Low-Voltage Electrical System
78K	K440	PROSPECT HEIGHTS HS	K	Heating Plant Upgrade
78K	K440	PROSPECT HEIGHTS HS	K	Heating Plant Upgrade
78K	K445	NEW UTRECHT HS	K	Electrical Systems
78K	K445	NEW UTRECHT HS	K	Flood Elimination
78K	K445	NEW UTRECHT HS	K	Heating Plant Upgrade
78K	K445	NEW UTRECHT HS	K	IP Digital Video Surveillance System
78K	K445	NEW UTRECHT HS	K	Lighting Fixtures
78K	K445	NEW UTRECHT HS	K	Waste System
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Cafeteria / Multipurpose Room Upgrade
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Heating Plant Upgrade
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Heating Plant Upgrade
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Lighting Fixtures
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Playground Redevelopment
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Roofs
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Windows
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Parapets
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Exterior Masonry
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	Electrical Systems
78K	K450	GRAND STREET CAMPUS (OLD E.D.HS)	K	IP Digital Video Surveillance System
78K	K455	BOYS & GIRLS HS	K	Auditorium Upgrade
78K	K455	BOYS & GIRLS HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K455	BOYS & GIRLS HS	K	Electrical Systems
78K	K455	BOYS & GIRLS HS	K	Technology
78K	K455	BOYS & GIRLS HS	K	Accessibility
78K	K457	BOYS HS AF (OLD)	K	Heating Plant Upgrade
78K	K458	BOYS HS (OLD)	K	Electrical Systems
78K	K458	BOYS HS (OLD)	K	Exterior Masonry
78K	K458	BOYS HS (OLD)	K	Flood Elimination



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K458	BOYS HS (OLD)	K	IP Digital Video Surveillance System
78K	K458	BOYS HS (OLD)	K	Lighting Fixtures
78K	K458	BOYS HS (OLD)	K	Parapets
78K	K458	BOYS HS (OLD)	K	Roofs
78K	K458	BOYS HS (OLD)	K	Heating Plant Upgrade
78K	K460	JOHN JAY HS	K	Auditorium Upgrade
78K	K460	JOHN JAY HS	K	Lighting Fixtures
78K	K460	JOHN JAY HS	K	School Improvement and Restructuring
78K	K460	JOHN JAY HS	K	Student Toilets
78K	K460	JOHN JAY EDUCATIONAL CAMPUS	K	Electrical Systems
78K	K460	JOHN JAY EDUCATIONAL CAMPUS	K	Heating Plant Upgrade
78K	K460	JOHN JAY EDUCATIONAL CAMPUS	K	Accessibility
78K	K465	ERASMUS HALL CAMPUS	K	Cafeteria / Multipurpose Room Upgrade
78K	K465	ERASMUS HALL CAMPUS	K	Heating Plant Upgrade
78K	K465	ERASMUS HALL CAMPUS	K	IP Digital Video Surveillance System
78K	K465	ERASMUS HALL CAMPUS	K	Student Toilets
78K	K465	ERASMUS HALL CAMPUS	K	Waste System
78K	K466	ERASMUS HALL HS AF	K	Heating Plant Upgrade
78K	K470	GEORGE W. WINGATE HS	K	Exterior Masonry
78K	K470	GEORGE W. WINGATE HS	K	IP Digital Video Surveillance System
78K	K470	GEORGE W. WINGATE HS	K	New/Retrofit Telephone/Intercom System
78K	K470	GEORGE W. WINGATE HS	K	Student Toilets
78K	K470	GEORGE W. WINGATE HS	K	Electrical Systems
78K	K470	GEORGE W. WINGATE HS	K	Accessibility
78K	K480	BUSHWICK EDUCATIONAL CAMPUS	K	Accessibility
78K	K480	BUSHWICK HS	K	Heating Plant Upgrade
78K	K480	BUSHWICK EDUCATIONAL CAMPUS	K	IP Digital Video Surveillance System
78K	K480	BUSHWICK EDUCATIONAL CAMPUS	K	Parapets
78K	K480	BUSHWICK EDUCATIONAL CAMPUS	K	Roofs
78K	K480	BUSHWICK EDUCATIONAL CAMPUS	K	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K485	TELECOM. ARTS & TECH.	K	Code Compliance
78K	K485	TELECOM. ARTS & TECH.	K	IP Digital Video Surveillance System
78K	K485	TELECOM. ARTS & TECH.	K	Lighting Fixtures
78K	K485	TELECOM. ARTS & TECH.	K	Lighting Fixtures
78K	K485	TELECOM. ARTS & TECH.	K	Roofs
78K	K485	TELECOM. ARTS & TECH.	K	Windows
78K	K485	TELECOM. ARTS & TECH.	K	Electrical Systems
78K	K485	TELECOM. ARTS & TECH.	K	Ventilation
78K	K485	TELECOM. ARTS & TECH.	K	Heating Plant Upgrade
78K	K485	TELECOM. ARTS & TECH.	K	Toilets - Students
78K	K490	FORT HAMILTON HS	K	Electrical Systems
78K	K490	FORT HAMILTON HS	K	IP Digital Video Surveillance System
78K	K490	FORT HAMILTON HS	K	Student Toilets
78K	K495	SHEEPSHEAD BAY HS	K	Heating Plant Upgrade
78K	K495	SHEEPSHEAD BAY HS	K	IP Digital Video Surveillance System
78K	K495	SHEEPSHEAD BAY HS	K	Lighting Fixtures
78K	K495	FRANK J. MACCHIAROLA EDUCATIONAL COI	K	New/Retrofit Telephone/Intercom System
78K	K496	SHEEPSHEAD BAY HS AF	K	Athletic Fields
78K	K500	CANARSIE HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K500	CANARSIE HS	K	Flood Elimination
78K	K500	CANARSIE HS	K	IP Digital Video Surveillance System
78K	K500	CANARSIE HS	K	Lighting Fixtures
78K	K500	CANARSIE HS	K	Student Toilets
78K	K505	FRANKLIN D. ROOSEVELT HS	K	Heating Plant Upgrade
78K	K505	FRANKLIN D. ROOSEVELT HS	K	Lighting Fixtures
78K	K505	FRANKLIN D. ROOSEVELT HS	K	Lighting Fixtures
78K	K505	FRANKLIN D. ROOSEVELT HS	K	Student Toilets
78K	K515	SOUTH SHORE HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K515	SOUTH SHORE HS	K	IP Digital Video Surveillance System
78K	K515	SOUTH SHORE HS	K	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K515	SOUTH SHORE EDUCATIONAL COMPLEX	K	Mobile Science Cart
78K	K515	SOUTH SHORE EDUCATIONAL COMPLEX	K	Student Toilets
78K	K515	SOUTH SHORE EDUCATIONAL COMPLEX	K	Electrical Systems
78K	K516	SOUTH SHORE HS AF	K	Athletic Fields
78K	K520	PACIFIC ALT HS	K	Lighting Fixtures
78K	K520	PACIFIC ALT HS	K	Low-Voltage Electrical Systems
78K	K525	EDWARD R. MURROW HS	K	Air Conditioning Split System
78K	K525	EDWARD R. MURROW HS	K	Cafeteria / Multipurpose Room Upgrade
78K	K525	EDWARD R. MURROW HS	K	Electrical Systems
78K	K525	EDWARD R. MURROW HS	K	Heating Plant Upgrade
78K	K525	EDWARD R. MURROW HS	K	IP Digital Video Surveillance System
78K	K525	EDWARD R. MURROW HS	K	Lighting Fixtures
78K	K525	EDWARD R. MURROW HS	K	Toilets - Students
78K	K540	JOHN DEWEY HS	K	IP Digital Video Surveillance System
78K	K540	JOHN DEWEY HS	K	Lighting Fixtures
78K	K564	SUNSET PARK HS	K	IP Digital Video Surveillance System
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Exterior Masonry
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Flood Elimination
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Library Upgrade
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Parapets
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Roofs
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Science Lab Upgrades
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Electrical Systems
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Accessibility
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	Emergency Lighting and Fire Safety Retrofits
78K	K580	GEORGE WESTINGHOUSE VOC HS	K	IP Digital Video Surveillance System
78K	K590	MIDDLE COLLEGE HS	K	Accessibility
78K	K590	MIDDLE COLLEGE HS	K	Elevators and Escalators
78K	K600	CLARA BARTON HS	K	Electrical Systems
78K	K600	CLARA BARTON HS	K	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K600	CLARA BARTON HS	K	New/Retrofit Telephone/Intercom System
78K	K600	CLARA BARTON HS	K	Accessibility
78K	K600	CLARA BARTON HS	K	IP Digital Video Surveillance System
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Domestic Piping
78K	K610	AUTOMOTIVE TRADES VOC HS	K	IP Digital Video Surveillance System
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Flood Elimination
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Roofs
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Parapets
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Windows
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Exterior Masonry
78K	K610	AUTOMOTIVE TRADES VOC HS	K	Electrical Systems
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Auditorium Upgrade
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Electrical Systems
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	IP Digital Video Surveillance System
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Library Upgrade
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	New/Retrofit Telephone/Intercom System
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Student Toilets
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Technology
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Playgrounds
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Technology
78K	K620	WILLIAM E. GRADY VOC HS	K	Athletic Fields
78K	K620	WILLIAM E. GRADY VOC HS	K	IP Digital Video Surveillance System
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Electrical Systems
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Gymnasium Upgrade
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Lighting Fixtures
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Lighting Fixtures
78K	K625	ROBESON HS COMP&BUS TC (A HML)	K	Ventilation
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Exterior Masonry
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	IP Digital Video Surveillance System
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Parapets
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Ventilation
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Windows
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Electrical Systems
78K	K650	HARRY VANARSDALE VOC HS(WHITNEY)	K	Toilets - Students
78K	K655	BKLYN HS OF THE ARTS (OL S J HL)	K	Electrical Systems
78K	K655	BKLYN HS OF THE ARTS (OL S J HL)	K	Lighting Fixtures
78K	K655	BKLYN HS OF THE ARTS (OL S J HL)	K	Roofs
78K	K656	BKLYN HS OF THE ARTS AX (S J HL)	K	Heating Plant Upgrade
78K	K660	WILLIAM MAXWELL CTE HS	K	IP Digital Video Surveillance System
78K	K660	WILLIAM MAXWELL CTE HS	K	Library Upgrade
78K	K660	WILLIAM MAXWELL CTE HS	K	Lighting Fixtures
78K	K660	WILLIAM MAXWELL CTE HS	K	Lighting Fixtures
78K	K660	WILLIAM MAXWELL CTE HS	K	Room Conversions/Partitioning
78K	K660	WILLIAM MAXWELL CTE HS	K	Room Conversions/Partitioning
78K	K660	WILLIAM MAXWELL CTE HS	K	Room Conversions/Partitioning
78K	K660	WILLIAM MAXWELL CTE HS	K	Roofs
78K	K660	WILLIAM MAXWELL CTE HS	K	Parapets
78K	K660	WILLIAM MAXWELL CTE HS	K	Windows
78K	K660	WILLIAM MAXWELL CTE HS	K	Exterior Masonry
78K	K660	WILLIAM MAXWELL CTE HS	K	Electrical Systems
78K	K721	BROOKLYN STUDIO (TANDEM K128)	K	Emergency Lighting and Fire Safety Retrofits
78K	K721	BROOKLYN STUDIO (TANDEM K128)	K	Roofs
78K	K721	BROOKLYN STUDIO (TANDEM K128)	K	Windows
78K	K721	BROOKLYN STUDIO (TANDEM K128)	K	Electrical Systems
78K	K728	LIBERATION DIPLOMA PLUS H.S.	K	Lighting Fixtures
78K	K778	EL PUENTE HS	K	Electrical Systems
78K	K779	ALL CITY LEADERSHIP SCHOOL	K	IP Digital Video Surveillance System
78K	K781	WEST BROOKLYN COMMUNITY HS	K	Lighting Fixtures
78K	K781	WEST BROOKLYN COMMUNITY HS	K	New/Retrofit Telephone/Intercom System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78K	K799	BUSHWICK LEADERS HS FOR ACAD EXL	K	Parapets
78K	K799	BUSHWICK LEADERS HS FOR ACAD EXL	K	Roofs
78K	K799	BUSHWICK LEADERS HS FOR ACAD EXL	K	Windows
78K	K804	COBBLE HILL SCL OF AMR STD (OL6)	K	Electrical Systems
78K	K804	COBBLE HILL SCL OF AMR STD (OL6)	K	Student Toilets
78K	K804	COBBLE HILL SCL OF AMR STD (OL6)	K	Heating Plant Upgrade
78K	K805	WATERS EDGE EDUCATIONAL COMPLEX	K	New/Retrofit Telephone/Intercom System
78K	K805	WATERS EDGE EDUCATIONAL COMPLEX	K	Student Toilets
78K	K805	WATERS EDGE EDUCATIONAL COMPLEX	K	Accessibility
78K	K806	METROPOLITAN CORPORATE ACAD.	K	Electrical Systems
78K	K806	METROPOLITAN CORPORATE ACAD.	K	Student Toilets
78K	K806	METROPOLITAN CORPORATE ACAD.	K	Heating Plant Upgrade
78K	K806	METROPOLITAN CORPORATE ACAD.	K	IP Digital Video Surveillance System
78K	K813	DIST. OFFICE #13 (OLD 9 AX)	K	Electrical Systems
78K	K819	EAST NY FAMILY ACADEMY	K	Heating Plant Upgrade
78K	K819	EAST NY FAMILY ACADEMY	K	Low-Voltage Electrical Systems
78K	K865	SECOND OPPORTUNITY SCHOOL	K	Electrical Systems
78K	K907	BROWNSVILLE DIPLOMA PLUS HS	K	Electrical Systems
78K	K907	BROWNSVILLE DIPLOMA PLUS HS	K	Lighting Fixtures
78K	K907	BROWNSVILLE DIPLOMA PLUS HS	K	IP Digital Video Surveillance System
78K	K909	ACORN COMMUNITY HS	K	IP Digital Video Surveillance System
78K	K914	BENJAMIN BANNEKER ACADEMY	K	Lighting Fixtures
78K	K932	HIGH SCHOOL SUSPENSION CENTER	K	Student Toilets
78K	K994	BEDFORD ACADEMY	K	IP Digital Video Surveillance System
78M	M066	RICHARD R GREEN HS OF TEACHING	M	IP Digital Video Surveillance System
78M	M081	MID MAN ADULT LRNG CTR (81)	M	Heating Plant Upgrade
78M	M081	MID MAN ADULT LRNG CTR (81)	M	Reinforcing Support Elements
78M	M081	MID MAN ADULT LRNG CTR (81)	M	Exterior Masonry
78M	M097	BARD COLLEGE HS (OLD M097)	M	Flood Elimination
78M	M097	BARD COLLEGE HS (OLD M097)	M	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M097	BARD COLLEGE HS (OLD M097)	M	Parapets
78M	M097	BARD COLLEGE HS (OLD M097)	M	Roofs
78M	M097	BARD COLLEGE HS (OLD M097)	M	Student Toilets
78M	M107	THE HERITAGE SCHOOL	M	Student Toilets
78M	M136	I.S. 136	M	Heating Plant Upgrade
78M	M136	I.S. 136	M	Lighting Fixtures
78M	M136	I.S. 136	M	Playgrounds
78M	M136	I.S. 136	M	Student Toilets
78M	M136	I.S. 136	M	IP Digital Video Surveillance System
78M	M435	MANHTN CT FOR MATH & SCI. HS	M	Cafeteria / Multipurpose Room Upgrade
78M	M435	MANHTN CT FOR MATH & SCI. HS	M	Student Toilets
78M	M435	MANHTN CT FOR MATH & SCI. HS	M	IP Digital Video Surveillance System
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	Heating Plant Upgrade
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	Lighting Fixtures
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	Lighting Fixtures
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	Student Toilets
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	Waste System
78M	M440	BAYARD RUSTIN EDUCATIONAL COMP	M	IP Digital Video Surveillance System
78M	M445	SEWARD PARK HS	M	Cafeteria / Multipurpose Room Upgrade
78M	M445	SEWARD PARK HS	M	Electrical Systems
78M	M445	SEWARD PARK HS	M	Heating Plant Upgrade
78M	M445	SEWARD PARK HS	M	IP Digital Video Surveillance System
78M	M445	SEWARD PARK HS	M	Lighting Fixtures
78M	M445	SEWARD PARK HS	M	Lighting Fixtures
78M	M445	SEWARD PARK HS	M	Containerization
78M	M446	UNIVERSITY NEIGHBORHOOD	M	Student Toilets
78M	M446	UNIVERSITY NEIGHBORHOOD	M	Heating Plant Upgrade
78M	M451	LIBERTY HS	M	Lighting Fixtures
78M	M451	LIBERTY HS	M	Heating Plant Upgrade
78M	M460	WASHINGTON IRVING HS	M	Cafeteria / Multipurpose Room Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M460	WASHINGTON IRVING HS	M	Electrical Systems
78M	M460	WASHINGTON IRVING HS	M	Exterior Masonry
78M	M460	WASHINGTON IRVING HS	M	Flood Elimination
78M	M460	WASHINGTON IRVING HS	M	Gymnasium Upgrade
78M	M460	WASHINGTON IRVING HS	M	Heating Plant Upgrade
78M	M460	WASHINGTON IRVING HS	M	IP Digital Video Surveillance System
78M	M460	WASHINGTON IRVING HS	M	Lighting Fixtures
78M	M460	WASHINGTON IRVING HS	M	Lighting Fixtures
78M	M460	WASHINGTON IRVING HS	M	Low-Voltage Electrical Systems
78M	M460	WASHINGTON IRVING HS	M	Parapets
78M	M460	WASHINGTON IRVING HS	M	Roofs
78M	M460	WASHINGTON IRVING HS	M	Student Toilets
78M	M460	WASHINGTON IRVING HS	M	Technology
78M	M460	WASHINGTON IRVING HS	M	Ventilation
78M	M460	WASHINGTON IRVING HS	M	Windows
78M	M460	WASHINGTON IRVING HS	M	Toilets - Students
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Heating Plant Upgrade
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Heating Plant Upgrade
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	IP Digital Video Surveillance System
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Lighting Fixtures
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Student Toilets
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Roofs
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Parapets
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Windows
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Exterior Masonry
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Electrical Systems
78M	M465	G. WASHINGTON HS EDUC. CAMPUS	M	Accessibility
78M	M470	LOUIS D. BRANDEIS HS	M	Accessibility
78M	M470	LOUIS D. BRANDEIS HS	M	Heating Plant Upgrade
78M	M470	LOUIS D. BRANDEIS HS	M	IP Digital Video Surveillance System



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M475	HEALTH PROFESSIONS HS (OL STY)	M	Heating Plant Upgrade
78M	M475	HEALTH PROFESSIONS HS (OL STY)	M	Lighting Fixtures
78M	M475	HEALTH PROFESSIONS HS (OL STY)	M	IP Digital Video Surveillance System
78M	M477	STUYVESANT HS (NEW)	M	IP Digital Video Surveillance System
78M	M480	JULIA RICHMAN ED. COMPLEX	M	Cafeteria / Multipurpose Room Upgrade
78M	M480	JULIA RICHMAN ED. COMPLEX	M	Lighting Fixtures
78M	M480	JULIA RICHMAN ED. COMPLEX	M	New/Retrofit Telephone/Intercom System
78M	M480	JULIA RICHMAN ED. COMPLEX	M	Toilets - Students
78M	M480	JULIA RICHMAN ED. COMPLEX	M	Accessibility
78M	M485	FIORIELLO LAGUARDIA HS	M	Air Conditioning Split System
78M	M485	FIORIELLO LAGUARDIA HS	M	Exterior Masonry
78M	M485	FIORIELLO LAGUARDIA HS	M	IP Digital Video Surveillance System
78M	M486	J. K. ONASSIS HS FOR INT CAREERS	M	Toilets - Students
78M	M488	MIDTOWN EAST CAMPUS	M	Accessibility
78M	M488	MIDTOWN EAST CAMPUS	M	IP Digital Video Surveillance System
78M	M490	MARTIN LUTHER KING, JR. HS	M	Accessibility
78M	M490	MARTIN LUTHER KING, JR. HS	M	Domestic Piping
78M	M490	MARTIN LUTHER KING, JR. HS	M	IP Digital Video Surveillance System
78M	M490	MARTIN LUTHER KING, JR. HS	M	Lighting Fixtures
78M	M490	MARTIN LUTHER KING, JR. HS	M	Electrical Systems
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Exterior Masonry
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Heating Plant Upgrade
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Student Toilets
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Student Toilets
78M	M506	EDWARD A. REYNOLDS WEST SIDE HS	M	Accessibility
78M	M506	EDWARD A. REYNOLDS WEST SIDE HS	M	Roofs
78M	M506	EDWARD A. REYNOLDS WEST SIDE HS	M	Parapets
78M	M506	EDWARD A. REYNOLDS WEST SIDE HS	M	Exterior Masonry
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Auditorium Upgrade
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Classroom Connectivity

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Heating Plant Upgrade
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Student Toilets
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Flood Elimination
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Roofs
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Parapets
78M	M510	FORSYTH HS (AUXSVC-OLD 91)	M	Exterior Masonry
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Elevators and Escalators
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Floors
78M	M520	MURRY BERGTRAUM HS (ECF)	M	IP Digital Video Surveillance System
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Low-Voltage Electrical Systems
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Science Lab Upgrades
78M	M520	MURRY BERGTRAUM HS (ECF)	M	Student Toilets
78M	M535	PARK WEST HS (ECF)	M	Cafeteria / Multipurpose Room Upgrade
78M	M535	PARK WEST HS (ECF)	M	Exterior Masonry
78M	M535	PARK WEST HS (ECF)	M	Heating Plant Upgrade
78M	M535	PARK WEST HS (ECF)	M	IP Digital Video Surveillance System
78M	M535	PARK WEST HS (ECF)	M	Elevators and Escalators
78M	M535	PARK WEST HS (ECF)	M	Toilets - Students
78M	M540	A. PHILLIP RANDOLPH HS	M	Exterior Masonry
78M	M540	A. PHILLIP RANDOLPH HS	M	Flood Elimination
78M	M540	A. PHILLIP RANDOLPH HS	M	Lighting Fixtures
78M	M540	A. PHILLIP RANDOLPH HS	M	Parapets
78M	M540	A. PHILLIP RANDOLPH HS	M	Roofs
78M	M540	A. PHILLIP RANDOLPH HS	M	Science Lab Upgrades
78M	M540	A. PHILLIP RANDOLPH HS	M	Electrical Systems
78M	M540	A. PHILLIP RANDOLPH HS	M	Heating Plant Upgrade
78M	M540	A. PHILLIP RANDOLPH HS	M	Accessibility
78M	M600	FASHION INDUSTRIES VOC HS	M	Accessibility
78M	M600	FASHION INDUSTRIES VOC HS	M	Flood Elimination
78M	M600	FASHION INDUSTRIES VOC HS	M	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M600	FASHION INDUSTRIES VOC HS	M	Parapets
78M	M600	FASHION INDUSTRIES VOC HS	M	Electrical Systems
78M	M600	FASHION INDUSTRIES VOC HS	M	IP Digital Video Surveillance System
78M	M615	CHELSEA VOC HS	M	Ansul Systems
78M	M615	CHELSEA VOC HS	M	Domestic Piping
78M	M615	CHELSEA VOC HS	M	Heating Plant Upgrade
78M	M615	CHELSEA VOC HS	M	Low-Voltage Electrical Systems
78M	M615	CHELSEA VOC HS	M	Toilets - Students
78M	M615	CHELSEA VOC HS	M	IP Digital Video Surveillance System
78M	M620	NORMAN THOMAS HS (ECF)	M	Electrical Systems
78M	M620	NORMAN THOMAS HS (ECF)	M	Heating Plant Upgrade
78M	M620	NORMAN THOMAS HS (ECF)	M	IP Digital Video Surveillance System
78M	M620	NORMAN THOMAS HS (ECF)	M	Science Lab Upgrades
78M	M620	NORMAN THOMAS HS (ECF)	M	Low-Voltage Electrical System
78M	M620	NORMAN THOMAS HS (ECF)	M	Air Conditioning Split System
78M	M620	NORMAN THOMAS HS (ECF)	M	Domestic Piping
78M	M620	NORMAN THOMAS HS (ECF)	M	Domestic Piping
78M	M620	NORMAN THOMAS HS (ECF)	M	Accessibility
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Auditorium Upgrade
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Boiler Conversion
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Climate Control
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Parapets
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Roofs
78M	M625	HS OF GRAPHIC COMMUNICATION ARTS	M	Accessibility
78M	M641	CITY AS SCHOOL (OLD 95)	M	Waste System
78M	M645	OLD MANHATTAN VOC/TECH HS	M	Exterior Masonry
78M	M645	OLD MANHATTAN VOC/TECH HS	M	Heating Plant Upgrade
78M	M645	OLD MANHATTAN VOC/TECH HS	M	IP Digital Video Surveillance System
78M	M645	OLD MANHATTAN VOC/TECH HS	M	Roofs
78M	M645	OLD MANHATTAN VOC/TECH HS	M	Toilets - Students

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78M	M646	SCL COOP TECH ED (MNH VOC HS)	M	Electrical Systems
78M	M661	MNHT COMP NIGHT&DAY (OL BACN X)	M	Heating Plant Upgrade
78M	M661	MNHT COMP NIGHT&DAY (OL BACN X)	M	IP Digital Video Surveillance System
78M	M661	MNHT COMP NIGHT&DAY (OL BACN X)	M	Lighting Fixtures
78M	M833	HS FOR ECONOMICS & FINANCE	M	Heating Plant Upgrade
78M	M833	HS FOR ECONOMICS & FINANCE	M	Gymnasium Upgrade
78M	M833	HS FOR ECONOMICS & FINANCE	M	Toilets - Students
78M	M834	HS FOR ENVIRONMENTAL STUDIES	M	Air Conditioning Split System
78M	M834	HS FOR ENVIRONMENTAL STUDIES	M	Floors
78M	M834	HS FOR ENVIRONMENTAL STUDIES	M	Gymnasium Upgrade
78M	M837	ISHS @ M837	M	Lighting Fixtures
78M	M837	WEST END SECONDARY SCHOOL	M	New/Retrofit Telephone/Intercom System
78M	M868	THE CLINTON SCHOOL	M	Accessibility
78M	M876	GREGORIO LUPERON PREP. SCHOOL	M	IP Digital Video Surveillance System
78M	M877	NEW YORK HARBOR SCHOOL	M	IP Digital Video Surveillance System
78M	M883	LEGACY HS FOR INTEGR. STUDIES	M	IP Digital Video Surveillance System
78M	M894	HS FOR LEADERSHIP & PUBLIC SER	M	Elevators and Escalators
78M	M894	HS FOR LEADERSHIP & PUBLIC SER	M	Heating Plant Upgrade
78M	M894	HS FOR LEADERSHIP & PUBLIC SER	M	Heating Plant Upgrade
78M	M894	HS FOR LEADERSHIP & PUBLIC SER	M	Heating Plant Upgrade
78M	M896	NYC PUBLIC SCHOOL REPERTORY CO	M	Classroom Connectivity
78M	M896	NYC PUBLIC SCHOOL REPERTORY CO	M	Electrical Systems
78M	M896	NYC PUBLIC SCHOOL REPERTORY CO	M	New/Retrofit Telephone/Intercom System
78M	M911	HARLEM RENAISSANCE HS (OLD M24)	M	Electrical Systems
78M	M911	HARLEM RENAISSANCE HS (OLD M24)	M	IP Digital Video Surveillance System
78Q	K420	FRANKLIN K. LANE HS	Q	Accessibility
78Q	K420	FRANKLIN K. LANE HS	Q	Auditorium Upgrade
78Q	K420	FRANKLIN K. LANE HS	Q	Heating Plant Upgrade
78Q	K420	FRANKLIN K. LANE HS	Q	IP Digital Video Surveillance System
78Q	K420	FRANKLIN K. LANE HS	Q	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	K420	FRANKLIN K. LANE HS	Q	Student Toilets
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Technology
78Q	K420	FRANKLIN K. LANE HS	Q	Flood Elimination
78Q	K420	FRANKLIN K. LANE HS	Q	Roofs
78Q	K420	FRANKLIN K. LANE HS	Q	Parapets
78Q	K420	FRANKLIN K. LANE HS	Q	Exterior Masonry
78Q	K420	FRANKLIN K. LANE HS	Q	Electrical Systems
78Q	K420	FRANKLIN K. LANE HS	Q	Emergency Lighting and Fire Safety Retrofits
78Q	Q023	QUEENS ACADEMY HS	Q	Electrical Systems
78Q	Q023	QUEENS ACADEMY HS	Q	Exterior Masonry
78Q	Q023	QUEENS ACADEMY HS	Q	Roofs
78Q	Q023	QUEENS ACADEMY HS	Q	Waste System
78Q	Q400	AUGUST MARTIN HS	Q	IP Digital Video Surveillance System
78Q	Q400	AUGUST MARTIN HS	Q	Library Upgrade
78Q	Q400	AUGUST MARTIN HS	Q	Student Toilets
78Q	Q400	AUGUST MARTIN HS	Q	Electrical Systems
78Q	Q405	BAYSIDE HS	Q	Heating Plant Upgrade
78Q	Q405	BAYSIDE HS	Q	IP Digital Video Surveillance System
78Q	Q405	BAYSIDE HS	Q	Lighting Fixtures
78Q	Q405	BAYSIDE HS	Q	Playground Redevelopment and TCU Removal
78Q	Q405	BAYSIDE HS	Q	Electrical Systems
78Q	Q405	BAYSIDE HS	Q	Emergency Lighting and Fire Safety Retrofits
78Q	Q410	BEACH CHANNEL HS	Q	Athletic Fields
78Q	Q410	BEACH CHANNEL HS	Q	Interior Spaces
78Q	Q410	BEACH CHANNEL HS	Q	IP Digital Video Surveillance System
78Q	Q410	BEACH CHANNEL HS	Q	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q410	BEACH CHANNEL EDUCATIONAL CAMPUS	Q	Room Conversions/Partitioning
78Q	Q410	BEACH CHANNEL HS	Q	Student Toilets
78Q	Q410	BEACH CHANNEL EDUCATIONAL CAMPUS	Q	Exterior Masonry
78Q	Q411	BEACH CHANNEL AF	Q	Athletic Fields
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	Accessibility
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	Air Conditioning Split System
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	IP Digital Video Surveillance System
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	Lighting Fixtures
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	Playground Redevelopment and TCU Removal
78Q	Q415	BENJAMIN N. CARDOZO HS	Q	Heating Plant Upgrade
78Q	Q416	CARDOZO AF	Q	Athletic Fields
78Q	Q420	SPRINGFIELD GARDENS HS	Q	IP Digital Video Surveillance System
78Q	Q420	SPRINGFIELD GARDENS HS	Q	Lighting Fixtures
78Q	Q420	SPRINGFIELD GARDENS HS	Q	Paved Area-Concrete
78Q	Q420	SPRINGFIELD GARDENS HS	Q	Roofs
78Q	Q420	SPRINGFIELD GARDENS HS	Q	Toilets - Students
78Q	Q420	SPRINGFIELD GARDENS HS	Q	Science Lab Upgrades
78Q	Q421	SPRINGFIELD GDNS HS AF	Q	Paved Area-Concrete
78Q	Q425	JOHN BOWNE HS	Q	Boiler Conversion
78Q	Q425	JOHN BOWNE HS	Q	Exterior Masonry
78Q	Q425	JOHN BOWNE HS	Q	Heating Plant Upgrade
78Q	Q425	JOHN BOWNE HS	Q	IP Digital Video Surveillance System
78Q	Q425	JOHN BOWNE HS	Q	Lighting Fixtures
78Q	Q425	JOHN BOWNE HS	Q	Lighting Fixtures
78Q	Q425	JOHN BOWNE HS	Q	Ventilation
78Q	Q425	JOHN BOWNE HS	Q	Roofs
78Q	Q430	FRANCIS LEWIS HS	Q	Electrical Systems
78Q	Q430	FRANCIS LEWIS HS	Q	IP Digital Video Surveillance System
78Q	Q430	FRANCIS LEWIS HS	Q	Lighting Fixtures
78Q	Q430	FRANCIS LEWIS HS	Q	Heating Plant Upgrade

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q435	MARTIN VAN BUREN HS	Q	Electrical Systems
78Q	Q435	MARTIN VAN BUREN HS	Q	Flood Elimination
78Q	Q435	MARTIN VAN BUREN HS	Q	IP Digital Video Surveillance System
78Q	Q435	MARTIN VAN BUREN HS	Q	Lighting Fixtures
78Q	Q435	MARTIN VAN BUREN HS	Q	Low-Voltage Electrical Systems
78Q	Q435	MARTIN VAN BUREN HS	Q	Accessibility
78Q	Q440	FOREST HILLS HS	Q	Accessibility
78Q	Q440	FOREST HILLS HS	Q	Auditorium Upgrade
78Q	Q440	FOREST HILLS HS	Q	Exterior Masonry
78Q	Q440	FOREST HILLS HS	Q	Heating Plant Upgrade
78Q	Q440	FOREST HILLS HS	Q	IP Digital Video Surveillance System
78Q	Q440	FOREST HILLS HS	Q	Lighting Fixtures
78Q	Q440	FOREST HILLS HS	Q	Parapets
78Q	Q440	FOREST HILLS HS	Q	Roofs
78Q	Q440	FOREST HILLS HS	Q	Safety Systems
78Q	Q440	FOREST HILLS HS	Q	Windows
78Q	Q440	FOREST HILLS HS	Q	Electrical Systems
78Q	Q440	FOREST HILLS HS	Q	Electrical Systems
78Q	Q441	FOREST HILLS AF	Q	Athletic Fields
78Q	Q445	WILLIAM C. BRYANT HS	Q	Gymnasium Upgrade
78Q	Q445	WILLIAM C. BRYANT HS	Q	IP Digital Video Surveillance System
78Q	Q445	WILLIAM C. BRYANT HS	Q	Lighting Fixtures
78Q	Q445	WILLIAM C. BRYANT HS	Q	Playground Redevelopment and TCU Removal
78Q	Q445	WILLIAM C. BRYANT HS	Q	Student Toilets
78Q	Q445	WILLIAM C. BRYANT HS	Q	Electrical Systems
78Q	Q445	WILLIAM C. BRYANT HS	Q	Electrical Systems
78Q	Q445	WILLIAM C. BRYANT HS	Q	Heating Plant Upgrade
78Q	Q445	WILLIAM C. BRYANT HS	Q	Emergency Lighting and Fire Safety Retrofits
78Q	Q446	BRYANT AF	Q	Athletic Fields
78Q	Q450	NEWCOMERS HIGH SCHOOL (OLD LIC)	Q	Boiler Conversion

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q450	NEWCOMERS HIGH SCHOOL (OLD LIC)	Q	Electrical Systems
78Q	Q450	NEWCOMERS HIGH SCHOOL (OLD LIC)	Q	Heating Plant Upgrade
78Q	Q450	NEWCOMERS HIGH SCHOOL (OLD LIC)	Q	Roofs
78Q	Q451	ACADEMY OF AMERICAN STUD HS AX	Q	Air Conditioning Split System
78Q	Q452	LONG ISLAND CITY HS (NEW)	Q	Exterior Masonry
78Q	Q452	LONG ISLAND CITY HS (NEW)	Q	Flood Elimination
78Q	Q452	LONG ISLAND CITY HS (NEW)	Q	IP Digital Video Surveillance System
78Q	Q452	LONG ISLAND CITY HS (NEW)	Q	Low-Voltage Electrical Systems
78Q	Q452	LONG ISLAND CITY HS (NEW)	Q	Roofs
78Q	Q455	NEWTOWN HS	Q	Heating Plant Upgrade
78Q	Q455	NEWTOWN HS	Q	IP Digital Video Surveillance System
78Q	Q455	NEWTOWN HS	Q	Lighting Fixtures
78Q	Q455	NEWTOWN HS	Q	Lighting Fixtures
78Q	Q455	NEWTOWN HS	Q	School Improvement and Restructuring
78Q	Q455	NEWTOWN HS	Q	Student Toilets
78Q	Q455	NEWTOWN HS	Q	Electrical Systems
78Q	Q455	NEWTOWN HS	Q	Emergency Lighting and Fire Safety Retrofits
78Q	Q456	HS FOR ARTS AND BUS. (OL NUTN X)	Q	New/Retrofit Telephone/Intercom System
78Q	Q460	FLUSHING HS	Q	Exterior Masonry
78Q	Q460	FLUSHING HS	Q	Heating Plant Upgrade
78Q	Q460	FLUSHING HS	Q	Heating Plant Upgrade
78Q	Q460	FLUSHING HS	Q	IP Digital Video Surveillance System
78Q	Q460	FLUSHING HS	Q	Lighting Fixtures
78Q	Q460	FLUSHING HS	Q	Parapets
78Q	Q460	FLUSHING HS	Q	Student Toilets
78Q	Q460	FLUSHING HS	Q	Roofs
78Q	Q460	FLUSHING HS	Q	Electrical Systems
78Q	Q465	FAR ROCKAWAY HS	Q	Cafeteria / Multipurpose Room Upgrade
78Q	Q465	FAR ROCKAWAY HS	Q	Exterior Masonry
78Q	Q465	FAR ROCKAWAY HS	Q	Heating Plant Upgrade



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q465	FAR ROCKAWAY HS	Q	IP Digital Video Surveillance System
78Q	Q465	FAR ROCKAWAY HS	Q	Lighting Fixtures
78Q	Q465	FAR ROCKAWAY HS	Q	Parapets
78Q	Q465	FAR ROCKAWAY HS	Q	Reinforcing Support Elements
78Q	Q465	FAR ROCKAWAY HS	Q	Roofs
78Q	Q465	FAR ROCKAWAY HS	Q	Student Toilets
78Q	Q465	FAR ROCKAWAY HS	Q	Windows
78Q	Q465	FAR ROCKAWAY HS	Q	Electrical Systems
78Q	Q470	JAMAICA HS	Q	Cafeteria / Multipurpose Room Upgrade
78Q	Q470	JAMAICA HS	Q	Domestic Piping
78Q	Q470	JAMAICA HS	Q	Exterior Masonry
78Q	Q470	JAMAICA HS	Q	IP Digital Video Surveillance System
78Q	Q470	JAMAICA HS	Q	Student Toilets
78Q	Q470	JAMAICA HS	Q	Athletic Fields
78Q	Q470	JAMAICA HS	Q	Gymnasium Upgrade
78Q	Q470	JAMAICA HS	Q	Electrical Systems
78Q	Q475	RICHMOND HILL HS	Q	Cafeteria / Multipurpose Room Upgrade
78Q	Q475	RICHMOND HILL HS	Q	Code Compliance
78Q	Q475	RICHMOND HILL HS	Q	Heating Plant Upgrade
78Q	Q475	RICHMOND HILL HS	Q	IP Digital Video Surveillance System
78Q	Q475	RICHMOND HILL HS	Q	Lighting Fixtures
78Q	Q475	RICHMOND HILL HS	Q	Playground Redevelopment and TCU Removal
78Q	Q475	RICHMOND HILL HS	Q	School Improvement and Restructuring
78Q	Q475	RICHMOND HILL HS	Q	Student Toilets
78Q	Q475	RICHMOND HILL HS	Q	Electrical Systems
78Q	Q480	JOHN ADAMS HS	Q	Heating Plant Upgrade
78Q	Q480	JOHN ADAMS HS	Q	IP Digital Video Surveillance System
78Q	Q480	JOHN ADAMS HS	Q	Lighting Fixtures
78Q	Q480	JOHN ADAMS HS	Q	Playground Redevelopment and TCU Removal
78Q	Q480	JOHN ADAMS HS	Q	Flood Elimination

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q480	JOHN ADAMS HS	Q	Roofs
78Q	Q480	JOHN ADAMS HS	Q	Parapets
78Q	Q480	JOHN ADAMS HS	Q	Windows
78Q	Q480	JOHN ADAMS HS	Q	Electrical Systems
78Q	Q485	GROVER CLEVELAND HS	Q	Accessibility
78Q	Q485	GROVER CLEVELAND HS	Q	Heating Plant Upgrade
78Q	Q485	GROVER CLEVELAND HS	Q	IP Digital Video Surveillance System
78Q	Q485	GROVER CLEVELAND HS	Q	Lighting Fixtures
78Q	Q485	GROVER CLEVELAND HS	Q	Electrical Systems
78Q	Q485	GROVER CLEVELAND HS	Q	Toilets - Students
78Q	Q488	CLEVELAND AF NO. 2	Q	Athletic Fields
78Q	Q490	CAMPUS MAGNET HS (JACKSON)	Q	Heating Plant Upgrade
78Q	Q490	CAMPUS MAGNET HS (JACKSON)	Q	IP Digital Video Surveillance System
78Q	Q490	CAMPUS MAGNET HS (JACKSON)	Q	Electrical Systems
78Q	Q505	HILLCREST HS	Q	Accessibility
78Q	Q505	HILLCREST HS	Q	Cafeteria / Multipurpose Room Upgrade
78Q	Q505	HILLCREST HS	Q	Heating Plant Upgrade
78Q	Q505	HILLCREST HS	Q	IP Digital Video Surveillance System
78Q	Q505	HILLCREST HS	Q	Electrical Systems
78Q	Q515	TOWNSEND HARRIS HS	Q	Accessibility
78Q	Q515	TOWNSEND HARRIS HS	Q	Climate Control
78Q	Q515	TOWNSEND HARRIS HS	Q	New/Retrofit Telephone/Intercom System
78Q	Q515	TOWNSEND HARRIS HS	Q	Ventilation
78Q	Q515	TOWNSEND HARRIS HS	Q	Heating Plant Upgrade
78Q	Q515	TOWNSEND HARRIS HS	Q	Domestic Piping
78Q	Q520	MIDDLE COLLEGE CAMPUS	Q	IP Digital Video Surveillance System
78Q	Q566	QNS HS OF TEACH., LIB. ARTS&SCI	Q	Accessibility
78Q	Q566	QNS HS OF TEACH., LIB. ARTS&SCI	Q	New/Retrofit Telephone/Intercom System
78Q	Q566	QNS HS OF TEACH., LIB. ARTS&SCI	Q	Gymnasium Upgrade
78Q	Q567	GLEN OAKS CAMPUS FACILITY	Q	Athletic Fields

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q570	FRANK SINATRA HIGH SCHOOL	Q	Accessibility
78Q	Q570	FRANK SINATRA HIGH SCHOOL	Q	Heating Plant Upgrade
78Q	Q585	MASPETH HIGH SCHOOL	Q	Accessibility
78Q	Q595	AUX. SERV. - JAMAICA LEARN CT	Q	Playground Redevelopment and TCU Removal
78Q	Q595	AUX. SERV. - JAMAICA LEARN CT	Q	Student Toilets
78Q	Q595	AUX. SERV. - JAMAICA LEARN CT	Q	Electrical Systems
78Q	Q595	AUX. SERV. - JAMAICA LEARN CT	Q	Emergency Lighting and Fire Safety Retrofits
78Q	Q600	QUEENS VOC HS	Q	Lighting Fixtures
78Q	Q600	QUEENS VOC HS	Q	Roofs
78Q	Q610	AVIATION HS	Q	Elevators and Escalators
78Q	Q610	AVIATION HS	Q	Exterior Masonry
78Q	Q610	AVIATION HS	Q	Fire System Sprinklers
78Q	Q610	AVIATION HS	Q	Flood Elimination
78Q	Q610	AVIATION HS	Q	Gymnasium Upgrade
78Q	Q610	AVIATION HS	Q	Parapets
78Q	Q610	AVIATION HS	Q	Roofs
78Q	Q610	AVIATION HS	Q	Windows
78Q	Q610	AVIATION HS	Q	Electrical Systems
78Q	Q620	THOMAS A. EDISON VOC HS	Q	Electrical Systems
78Q	Q620	THOMAS A. EDISON VOC HS	Q	Heating Plant Upgrade
78Q	Q620	THOMAS A. EDISON VOC HS	Q	IP Digital Video Surveillance System
78Q	Q620	THOMAS A. EDISON VOC HS	Q	Lighting Fixtures
78Q	Q620	THOMAS A. EDISON VOC HS	Q	Roofs
78Q	Q650	HS FOR CONST. TRADES, ENGG., & ARCH	Q	Accessibility
78Q	Q680	YOUNG WOMENS' LEADERSHIP SCHOOL	Q	Electrical Systems
78Q	Q680	YOUNG WOMENS' LEADERSHIP SCHOOL	Q	Exterior Masonry
78Q	Q680	YOUNG WOMENS' LEADERSHIP SCHOOL	Q	Heating Plant Upgrade
78Q	Q686	METROPOLITAN AVENUE CAMPUS	Q	Accessibility
78Q	Q686	METROPOLITAN AVENUE CAMPUS	Q	IP Digital Video Surveillance System
78Q	Q690	HS FOR LAW ENFORCEMENT	Q	IP Digital Video Surveillance System

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78Q	Q695	QUEENS GATEWAY TO HEALTH SCIENCES €	Q	Accessibility
78Q	Q695	QUEENS GATEWAY TO HEALTH SCIENCES €	Q	IP Digital Video Surveillance System
78Q	Q707	R. F. KENNEDY COMM. MIDDLE/HS	Q	New/Retrofit Telephone/Intercom System
78Q	Q725	HS FOR INFORMATION TECH	Q	Heating Plant Upgrade
78Q	Q725	HS FOR INFORMATION TECH	Q	Lighting Fixtures
78Q	Q725	HS FOR INFORMATION TECH	Q	IP Digital Video Surveillance System
78Q	Q739	YOUNG WOMEN'S LEADERSHIP ACADEMY	Q	Electrical Systems
78Q	Q744	ELMHURST EDUCATIONAL CAMPUS	Q	IP Digital Video Surveillance System
78Q	Q781	JOHN ADAMS HS ANNEX	Q	Lighting Fixtures
78Q	Q792	NORTH QUEENS COMMUNITY HS	Q	Electrical Systems
78Q	Q792	NORTH QUEENS COMMUNITY HS	Q	New/Retrofit Telephone/Intercom System
78Q	Q798	BACCALAUREATE SCL FOR GLOBAL ED	Q	Heating Plant Upgrade
78Q	Q799	CAMBRIA HEIGHTS ACADEMY	Q	Classroom Connectivity
78Q	Q799	CAMBRIA HEIGHTS ACADEMY	Q	Heating Plant Upgrade
78Q	Q859	REGION 3 / ROC C	Q	Air Conditioning Split System
78Q	Q859	REGION 3 / ROC C	Q	Heating Plant Upgrade
78Q	Q859	REGION 3 / ROC C	Q	Lighting Fixtures
78R	R043	JEROME PARKER CAMPUS	R	Accessibility
78R	R435	NEW DORP HS (NEW)	R	Climate Control
78R	R435	NEW DORP HS (NEW)	R	Gymnasium Upgrade
78R	R435	NEW DORP HS (NEW)	R	Heating Plant Upgrade
78R	R435	NEW DORP HS (NEW)	R	IP Digital Video Surveillance System
78R	R435	NEW DORP HS (NEW)	R	Lighting Fixtures
78R	R435	NEW DORP HS (NEW)	R	Student Toilets
78R	R440	STATEN ISLAND TECHNICAL HS	R	Auditorium Upgrade
78R	R440	STATEN ISLAND TECHNICAL HS	R	Heating Plant Upgrade
78R	R440	STATEN ISLAND TECHNICAL HS	R	Student Toilets
78R	R440	STATEN ISLAND TECHNICAL HS	R	Parapets
78R	R440	STATEN ISLAND TECHNICAL HS	R	Exterior Masonry
78R	R445	PORT RICHMOND HS	R	Flood Elimination

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78R	R445	PORT RICHMOND HS	R	Heating Plant Upgrade
78R	R445	PORT RICHMOND HS	R	IP Digital Video Surveillance System
78R	R445	PORT RICHMOND HS	R	Lighting Fixtures
78R	R445	PORT RICHMOND HS	R	Parapets
78R	R445	PORT RICHMOND HS	R	Playground Redevelopment and TCU Removal
78R	R445	PORT RICHMOND HS	R	Roofs
78R	R446	PORT RICHMOND HS AF	R	Heating Plant Upgrade
78R	R450	CURTIS HS	R	Electrical Systems
78R	R450	CURTIS HS	R	Heating Plant Upgrade
78R	R450	CURTIS HS ADDITION	R	Lighting Fixtures
78R	R450	CURTIS HS	R	Safety Systems
78R	R450	CURTIS HS	R	Student Toilets
78R	R451	CURTIS HS AF	R	Athletic Fields
78R	R451	CURTIS HS AF	R	Athletic Fields
78R	R455	TOTTENVILLE HS	R	Heating Plant Upgrade
78R	R455	TOTTENVILLE HS	R	IP Digital Video Surveillance System
78R	R455	TOTTENVILLE HS	R	Student Toilets
78R	R460	SUSAN E. WAGNER HS	R	Elevators and Escalators
78R	R460	SUSAN E. WAGNER HS	R	Exterior Masonry
78R	R460	SUSAN E. WAGNER HS	R	Heating Plant Upgrade
78R	R460	SUSAN E. WAGNER HS	R	Heating Plant Upgrade
78R	R460	SUSAN E. WAGNER HS	R	IP Digital Video Surveillance System
78R	R460	SUSAN E. WAGNER HS	R	Lighting Fixtures
78R	R460	SUSAN E. WAGNER HS	R	Lighting Fixtures
78R	R460	SUSAN E. WAGNER HS	R	Safety Systems
78R	R460	SUSAN E. WAGNER HS	R	Safety Systems
78R	R460	SUSAN E. WAGNER HS	R	Electrical Systems
78R	R460	SUSAN E. WAGNER HS	R	Ventilation
78R	R460	SUSAN E. WAGNER HS	R	Accessibility
78R	R470	CONCORD HS (OLD 12)	R	Toilets - Students

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78R	R600	RALPH MCKEE VOC HS	R	Electrical Systems
78R	R600	RALPH MCKEE VOC HS	R	Heating Plant Upgrade
78R	R600	RALPH MCKEE VOC HS	R	Lighting Fixtures
78R	R600	RALPH MCKEE VOC HS	R	Elevators and Escalators
78R	R600	RALPH MCKEE VOC HS	R	Accessibility
78R	R600	RALPH MCKEE VOC HS	R	IP Digital Video Surveillance System
78X	X039	NEW SCH FOR ARTS AND SCIENCE	X	Electrical Systems
78X	X039	NEW SCH FOR ARTS AND SCIENCE	X	Heating Plant Upgrade
78X	X039	NEW SCH FOR ARTS AND SCIENCE	X	IP Digital Video Surveillance System
78X	X039	NEW SCH FOR ARTS AND SCIENCE	X	Student Toilets
78X	X099	REV. J.A. POLITE AVE SCHOOL CAMPUS	X	Heating Plant Upgrade
78X	X099	REV. J.A. POLITE AVE SCHOOL CAMPUS	X	Accessibility
78X	X211	P.U.L.S.E. HS	X	Classroom Connectivity
78X	X211	P.U.L.S.E. HS	X	Electrical Systems
78X	X362	I.S./H.S. 362	X	Accessibility
78X	X362	I.S./H.S. 362	X	IP Digital Video Surveillance System
78X	X392	THE CASITA MARIA CENTER FOR ARTS AND	X	Heating Plant Upgrade
78X	X392	THE CASITA MARIA CENTER FOR ARTS AND	X	IP Digital Video Surveillance System
78X	X400	MORRIS HS	X	Flood Elimination
78X	X400	MORRIS HS	X	Heating Plant Upgrade
78X	X400	MORRIS HS	X	Interior Spaces
78X	X400	MORRIS HS	X	IP Digital Video Surveillance System
78X	X400	MORRIS HS	X	Lighting Fixtures
78X	X400	MORRIS HS	X	Lighting Fixtures
78X	X400	MORRIS HS	X	Paved Area-Concrete
78X	X400	MORRIS HS	X	Roofs
78X	X400	MORRIS HS	X	Student Toilets
78X	X400	MORRIS HS	X	Windows
78X	X400	MORRIS HS	X	Electrical Systems
78X	X401	BRONX REGIONAL HS (OLD 133)	X	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78X	X405	HERBERT H. LEHMAN HS	X	Air Conditioning Split System
78X	X405	HERBERT H. LEHMAN HS	X	Domestic Piping
78X	X405	HERBERT H. LEHMAN HS	X	Interior Spaces
78X	X405	HERBERT H. LEHMAN HS	X	IP Digital Video Surveillance System
78X	X405	HERBERT H. LEHMAN HS	X	Lighting Fixtures
78X	X405	HERBERT H. LEHMAN HS	X	Student Toilets
78X	X405	HERBERT H. LEHMAN HS	X	Ventilation
78X	X405	HERBERT H. LEHMAN HS	X	Heating Plant Upgrade
78X	X410	WILLIAM H. TAFT HS	X	Electrical Systems
78X	X410	WILLIAM H. TAFT HS	X	Exterior Masonry
78X	X410	WILLIAM H. TAFT HS	X	IP Digital Video Surveillance System
78X	X410	WILLIAM H. TAFT HS	X	Parapets
78X	X410	WILLIAM H. TAFT HS	X	Paved Area-Concrete
78X	X410	WILLIAM H. TAFT HS	X	Student Toilets
78X	X410	WILLIAM H. TAFT HS	X	Windows
78X	X410	WILLIAM H. TAFT HS	X	Roofs
78X	X410	WILLIAM H. TAFT HS	X	Containerization
78X	X415	CHRISTOPHER COLUMBUS HS	X	Cafeteria / Multipurpose Room Upgrade
78X	X415	CHRISTOPHER COLUMBUS HS	X	Electrical Systems
78X	X415	CHRISTOPHER COLUMBUS HS	X	Exterior Masonry
78X	X415	CHRISTOPHER COLUMBUS HS	X	IP Digital Video Surveillance System
78X	X415	CHRISTOPHER COLUMBUS HS	X	Parapets
78X	X415	CHRISTOPHER COLUMBUS HS	X	Student Toilets
78X	X415	CHRISTOPHER COLUMBUS HS	X	Heating Plant Upgrade
78X	X420	JAMES MONROE CAMPUS	X	Cafeteria / Multipurpose Room Upgrade
78X	X420	JAMES MONROE CAMPUS	X	Climate Control
78X	X420	JAMES MONROE CAMPUS	X	Flood Elimination
78X	X420	JAMES MONROE CAMPUS	X	Heating Plant Upgrade
78X	X420	JAMES MONROE CAMPUS	X	IP Digital Video Surveillance System
78X	X420	JAMES MONROE CAMPUS	X	Lighting Fixtures

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78X	X420	JAMES MONROE CAMPUS	X	Parapets
78X	X420	JAMES MONROE CAMPUS	X	Roofs
78X	X420	JAMES MONROE CAMPUS	X	Windows
78X	X420	JAMES MONROE CAMPUS	X	Electrical Systems
78X	X420	JAMES MONROE CAMPUS	X	Heating Plant Upgrade
78X	X423	JAMES MONROE HS CAMPUS ANNEX	X	Accessibility
78X	X423	JAMES MONROE HS CAMPUS ANNEX	X	IP Digital Video Surveillance System
78X	X425	EVANDER CHILDS HS	X	Accessibility
78X	X425	EVANDER CHILDS HS	X	Heating Plant Upgrade
78X	X425	EVANDER CHILDS HS	X	IP Digital Video Surveillance System
78X	X425	EVANDER CHILDS HS	X	Lighting Fixtures
78X	X425	EVANDER CHILDS HS	X	Playground Redevelopment
78X	X425	EVANDER CHILDS HS	X	Student Toilets
78X	X425	EVANDER CHILDS HS	X	Ventilation
78X	X425	EVANDER CHILDS HS	X	Electrical Systems
78X	X430	WALTON HS	X	Accessibility
78X	X430	WALTON HS	X	Electrical Systems
78X	X430	WALTON HS	X	IP Digital Video Surveillance System
78X	X430	WALTON HS	X	Emergency Lighting and Fire Safety Retrofits
78X	X435	THEODORE ROOSEVELT HS	X	IP Digital Video Surveillance System
78X	X435	THEODORE ROOSEVELT HS	X	Student Toilets
78X	X435	THEODORE ROOSEVELT EDUCATIONAL CAI	X	Paved Area - Concrete
78X	X435	THEODORE ROOSEVELT EDUCATIONAL CAI	X	Containerization
78X	X435	THEODORE ROOSEVELT EDUCATIONAL CAI	X	Heating Plant Upgrade
78X	X440	DEWITT CLINTON HS	X	Elevators and Escalators
78X	X440	DEWITT CLINTON HS	X	Exterior Masonry
78X	X440	DEWITT CLINTON HS	X	Flood Elimination
78X	X440	DEWITT CLINTON HS	X	IP Digital Video Surveillance System
78X	X440	DEWITT CLINTON HS	X	Lighting Fixtures
78X	X440	DEWITT CLINTON HS	X	Parapets



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78X	X440	DEWITT CLINTON HS	X	Roofs
78X	X440	DEWITT CLINTON HS	X	Student Toilets
78X	X440	DEWITT CLINTON HS	X	Electrical Systems
78X	X440	DEWITT CLINTON HS	X	Heating Plant Upgrade
78X	X445	BRONX HS OF SCIENCE	X	Heating Plant Upgrade
78X	X445	BRONX HS OF SCIENCE	X	IP Digital Video Surveillance System
78X	X445	BRONX HS OF SCIENCE	X	Lighting Fixtures
78X	X445	BRONX HS OF SCIENCE	X	Lighting Fixtures
78X	X445	BRONX HS OF SCIENCE	X	Parapets
78X	X445	BRONX HS OF SCIENCE	X	Accessibility
78X	X450	ADLAI E. STEVENSON HS	X	Exterior Masonry
78X	X450	ADLAI E. STEVENSON HS	X	Gymnasium Upgrade
78X	X450	ADLAI E. STEVENSON HS	X	Heating Plant Upgrade
78X	X450	ADLAI E. STEVENSON HS	X	IP Digital Video Surveillance System
78X	X450	ADLAI E. STEVENSON HS	X	Kitchen Areas
78X	X450	ADLAI E. STEVENSON HS	X	Lighting Fixtures
78X	X450	ADLAI E. STEVENSON HS	X	Playground Redevelopment and TCU Removal
78X	X450	ADLAI E. STEVENSON HS	X	Roofs
78X	X450	ADLAI E. STEVENSON HS	X	Safety Systems
78X	X450	ADLAI E. STEVENSON HS	X	Student Toilets
78X	X450	ADLAI E. STEVENSON EDUCATIONAL CAMPI	X	Interior Spaces
78X	X450	ADLAI E. STEVENSON EDUCATIONAL CAMPI	X	Electrical Systems
78X	X451	STEVENSON HS AF	X	Athletic Fields
78X	X455	HARRY S. TRUMAN HS	X	Air Conditioning Split System
78X	X455	HARRY S. TRUMAN HS	X	Domestic Piping
78X	X455	HARRY S. TRUMAN HS	X	Exterior Masonry
78X	X455	HARRY S. TRUMAN HS	X	IP Digital Video Surveillance System
78X	X455	HARRY S. TRUMAN HS	X	Lighting Fixtures
78X	X455	HARRY S. TRUMAN HS	X	Parapets
78X	X455	HARRY S. TRUMAN HS	X	Student Toilets

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78X	X460	HS OF LAW, GOV'T & JUSTICE	X	Accessibility
78X	X460	HS OF LAW, GOV'T & JUSTICE	X	Electrical Systems
78X	X465	EAGLE ACADEMY FOR YOUNG MEN	X	IP Digital Video Surveillance System
78X	X470	SOUTH BRONX EDUCATIONAL CAMPUS	X	Electrical Systems
78X	X470	SOUTH BRONX EDUCATIONAL CAMPUS	X	IP Digital Video Surveillance System
78X	X470	SOUTH BRONX HS (OLD 38)	X	Lighting Fixtures
78X	X470	SOUTH BRONX HS (OLD 38)	X	Student Toilets
78X	X475	JOHN F. KENNEDY HS	X	Flood Elimination
78X	X475	JOHN F. KENNEDY HS	X	Heating Plant Upgrade
78X	X475	JOHN F. KENNEDY HS	X	IP Digital Video Surveillance System
78X	X475	JOHN F. KENNEDY HS	X	Lighting Fixtures
78X	X475	JOHN F. KENNEDY HS	X	Lighting Fixtures
78X	X475	JOHN F. KENNEDY HS	X	Parapets
78X	X475	JOHN F. KENNEDY HS	X	Playground Redevelopment and TCU Removal
78X	X475	JOHN F. KENNEDY HS	X	Roofs
78X	X475	JOHN F. KENNEDY HS	X	Student Toilets
78X	X476	KENNEDY AF	X	Athletic Fields
78X	X600	ALFRED E. SMITH HS	X	Cafeteria / Multipurpose Room Upgrade
78X	X600	ALFRED E. SMITH HS	X	Heating Plant Upgrade
78X	X600	ALFRED E. SMITH HS	X	Heating Plant Upgrade
78X	X600	ALFRED E. SMITH HS	X	Student Toilets
78X	X600	ALFRED E. SMITH HS	X	Electrical Systems
78X	X650	JANE ADDAMS HS	X	Auditorium Upgrade
78X	X650	JANE ADDAMS HS	X	Electrical Systems
78X	X650	JANE ADDAMS HS	X	Heating Plant Upgrade
78X	X650	JANE ADDAMS HS	X	Accessibility
78X	X655	SAMUEL GOMPERS VOC HS	X	Toilets - Students
78X	X660	GRACE H. DODGE VOC HS	X	IP Digital Video Surveillance System
78X	X660	GRACE H. DODGE VOC HS	X	Lighting Fixtures
78X	X660	GRACE H. DODGE VOC HS	X	Containerization

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**ADDED PROJECTS**

<b>District</b>	<b>Bldg ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>
78X	X660	GRACE H. DODGE VOC HS	X	Electrical Systems
78X	X790	MOTT HAVEN EDUCATIONAL CAMPUS	X	IP Digital Video Surveillance System
78X	X790	MOTT HAVEN EDUCATIONAL CAMPUS	X	Containerization
78X	X884	HEALTH OPPORTUNITIES HS	X	IP Digital Video Surveillance System
78X	X963	CROTONA ACADEMY	X	Playground Redevelopment and TCU Removal
78X	X965	REGION 2 SUSPENSION CENTER	X	Electrical Systems
78X	X972	SOUNDVIEW EDUCATIONAL CAMPUS	X	IP Digital Video Surveillance System
78X	X973	M.S./H.S. 270	X	IP Digital Video Surveillance System
84Q	Q781	JOHN ADAMS HS ANNEX	Q	Electrical Systems

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
1	M022	N.E.S.T (OLD J22)	M	Electrical Systems	No Capital Work Required
1	M061	P.S. 61	M	Electrical Systems	No Capital Work Required
1	M110	P.S. 110	M	Lighting Fixtures	No Capital Work Required
2	M011	P.S. 11	M	Heating Plant Upgrade	No Capital Work Required
2	M070	I.S. 70	M	Electrical Systems	No Capital Work Required
2	M089	P.S./I.S. 89	M	Heating Plant Upgrade	No Capital Work Required
2	M126	P.S. 126	M	Electrical Systems	No Capital Work Required
2	M131	I.S. 131	M	Cafeteria / Multipurpose Room Upgrade	Alternate Project Prioritized
2	M158	P.S. 158	M	Electrical Systems	No Capital Work Required
2	M167	I.S. 167	M	Electrical Systems	No Capital Work Required
2	M660	SCHL OF THE FUTURE (OLD BACON)	M	Electrical Systems	No Capital Work Required
3	M054	I.S. 54	M	Electrical Systems	No Capital Work Required
3	M113	P.S. 241	M	Electrical Systems	No Capital Work Required
3	M163	P.S. 163	M	Electrical Systems	No Capital Work Required
3	M207	P.S. 207 (TANDEM M149)	M	Electrical Systems	No Capital Work Required
3	M208	P.S. 208 (TANDEM M185)	M	Electrical Systems	No Capital Work Required
4	M057	P.S. 57	M	Electrical Systems	No Capital Work Required
4	M099	I.S. 99	M	Electrical Systems	No Capital Work Required
4	M101	P.S. 101	M	Electrical Systems	No Capital Work Required
4	M112	P.S. 112 (TANDEM M206)	M	Electrical Systems	No Capital Work Required
5	M030	P.S. 30	M	Electrical Systems	No Capital Work Required
5	M043	I.S. 172 (OLD 43)	M	Electrical Systems	No Capital Work Required
5	M195	TERENCE D. TOLBERT EDUCATION COM	M	Electrical Systems	No Capital Work Required
6	M132	P.S. 132	M	Low-Voltage Electrical Systems	No Capital Work Required
6	M132	P.S. 132	M	Heating Plant Upgrade	No Capital Work Required
6	M173	P.S. 173	M	Electrical Systems	No Capital Work Required
6	M847	P.S. 178 MINISCHOOL	M	Low-Voltage Electrical Systems	No Capital Work Required
7	X027	P.S. 277	X	Electrical Systems	No Capital Work Required
7	X030	P.S. 30	X	Electrical Systems	No Capital Work Required
7	X139	J.H.S. 222	X	Electrical Systems	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
7	X154	P.S. 154	X	Electrical Systems	No Capital Work Required
7	X156	P.S. 156	X	Electrical Systems	No Capital Work Required
7	X184	I.S. 184	X	Electrical Systems	No Capital Work Required
7	X855	P.S. 30 ANNEX	X	Lighting Fixtures	Reclassified
7	X855	P.S. 30 ANNEX	X	Electrical Systems	No Capital Work Required
8	X048	P.S. 48	X	Lighting Fixtures	Reclassified
8	X071	P.S. 71	X	Student Toilets	Alternate Project Prioritized
8	X075	P.S. 75	X	Playgrounds	Alternate Project Prioritized
8	X131	I.S. 131	X	Electrical Systems	No Capital Work Required
8	X869	P.S. 69 MINISCHOOL	X	Lighting Fixtures	Work Previously Completed
8	X880	P.S. 69 ANNEX	X	Electrical Systems	No Capital Work Required
9	X002	MORRISANIA SEC ED COMPLEX	X	Electrical Systems	No Capital Work Required
9	X004	P.S. 4	X	Electrical Systems	Alternate Project Prioritized
9	X011	P.S. 11	X	Electrical Systems	No Capital Work Required
9	X028	P.S. 28	X	Heating Plant Upgrade	No Capital Work Required
9	X035	P.S. 35	X	Parapets	No Capital Work Required
9	X053	P.S. 53	X	Lighting Fixtures	No Capital Work Required
9	X053	P.S. 53	X	Heating Plant Upgrade	No Capital Work Required
9	X064	P.S. 64	X	Electrical Systems	No Capital Work Required
9	X082	I.S. 232	X	Student Toilets	Alternate Project Prioritized
9	X109	P.S. 109	X	Electrical Systems	Alternate Project Prioritized
9	X109	P.S. 109	X	Heating Plant Upgrade	Work Previously Completed
9	X145	I.S. 145	X	Electrical Systems	No Capital Work Required
9	X235	P.S./I.S. 218	X	Domestic Piping	Reclassified
9	X870	P.S. 70 MINISCHOOL	X	Lighting Fixtures	Reclassified
10	X008	P.S. 8	X	Electrical Systems	No Capital Work Required
10	X059	P.S. 59	X	Lighting Fixtures	No Capital Work Required
10	X080	I.S. 80/P.S. 280	X	Electrical Systems	No Capital Work Required
10	X086	P.S. 86	X	Electrical Systems	No Capital Work Required
10	X091	P.S. 91	X	Heating Plant Upgrade	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
10	X306	P.S. 306	X	Heating Plant Upgrade	No Capital Work Required
11	X068	P.S. 68	X	Electrical Systems	No Capital Work Required
11	X076	P.S. 76	X	Playgrounds	No Capital Work Required
11	X078	P.S. 78	X	Playgrounds	No Capital Work Required
11	X083	P.S. 83	X	Heating Plant Upgrade	Work Previously Completed
11	X089	P.S. 89	X	Electrical Systems	Reclassified
11	X089	P.S. 89	X	Electrical Systems	No Capital Work Required
11	X097	P.S. 97 ADDITION	X	Playgrounds	No Capital Work Required
11	X127	I.S. 127	X	Heating Plant Upgrade	No Capital Work Required
11	X189	P.S./I.S. 189 (@STEENWICK AVE)	X	Exterior Masonry	No Capital Work Required
12	X077	P.S. 195	X	Electrical Systems	No Capital Work Required
12	X098	I.S. 98	X	Lighting Fixtures	No Capital Work Required
12	X116	I.S. 216	X	Electrical Systems	No Capital Work Required
13	K044	P.S. 44	K	Boiler Conversion	Reclassified
13	K044	P.S. 44	K	Climate Control	Reclassified
13	K056	P.S. 56	K	Boiler Conversion	Reclassified
13	K056	P.S. 56	K	Climate Control	Reclassified
13	K113	I.S. 113	K	Electrical Systems	No Capital Work Required
13	K258	I.S. 258	K	Electrical Systems	No Capital Work Required
13	K287	P.S. 287	K	Electrical Systems	No Capital Work Required
14	K071	I.S. 71	K	Electrical Systems	No Capital Work Required
14	K084	P.S. 84	K	Electrical Systems	No Capital Work Required
14	K120	P.S. 120	K	Electrical Systems	No Capital Work Required
14	K196	P.S. 196	K	Electrical Systems	No Capital Work Required
14	K250	P.S. 250	K	Electrical Systems	No Capital Work Required
15	K010	P.S. 10	K	Electrical Systems	No Capital Work Required
15	K029	P.S. 29	K	Electrical Systems	No Capital Work Required
15	K124	P.S. 124	K	Electrical Systems	No Capital Work Required
15	K136	I.S. 136	K	Flood Elimination	Reclassified
15	K763	P.S. 118 MAURICE SENDAK COMMUNITY	K	Lighting Fixtures	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
15	K763	P.S. 118 MAURICE SENDAK COMMUNITY	K	Electrical Systems	No Capital Work Required
15	K812	P.S. 1 ANNEX	K	Electrical Systems	No Capital Work Required
16	K005	P.S. 5	K	Electrical Systems	No Capital Work Required
16	K005	P.S. 5	K	Heating Plant Upgrade	No Capital Work Required
16	K028	P.S. 28	K	Electrical Systems	No Capital Work Required
17	K022	P.S. 22	K	Electrical Systems	No Capital Work Required
17	K161	P.S. 161	K	Electrical Systems	No Capital Work Required
17	K210	I.S. 394	K	Electrical Systems	No Capital Work Required
17	K390	I.S. 390	K	Electrical Systems	No Capital Work Required
18	K219	P.S. 219	K	Lighting Fixtures	Reclassified
18	K242	P.S. 235 ANNEX	K	Lighting Fixtures	Reclassified
18	K276	P.S. 276	K	Electrical Systems	No Capital Work Required
18	K279	P.S. 279	K	Reinforcing Support Elements	No Capital Work Required
18	K860	P.S. 219 ANNEX	K	Electrical Systems	No Capital Work Required
19	K013	P.S. 13	K	Electrical Systems	No Capital Work Required
19	K190	P.S. 190	K	Electrical Systems	No Capital Work Required
19	K848	P.S. 149 ANNEX	K	Electrical Systems	No Capital Work Required
20	K164	P.S. 164	K	Electrical Systems	No Capital Work Required
20	K186	P.S. 186	K	Electrical Systems	Reclassified
20	K204	P.S. 204	K	Electrical Systems	No Capital Work Required
20	K259	I.S. 259	K	Electrical Systems	No Capital Work Required
20	K314	P.S. 314	K	Lighting Fixtures	No Capital Work Required
21	K043	I.S. 98	K	Low-Voltage Electrical Systems	Reclassified
21	K043	I.S. 98	K	Domestic Piping	Reclassified
21	K043	I.S. 98	K	Electrical Systems	No Capital Work Required
21	K095	P.S. 95	K	Electrical Systems	No Capital Work Required
21	K096	I.S. 96	K	Electrical Systems	No Capital Work Required
21	K097	P.S. 97 ADDITION	K	Electrical Systems	No Capital Work Required
21	K188	P.S. 188	K	Reinforcing Cinder Concrete Slabs	No Capital Work Required
21	K188	P.S. 188	K	Electrical Systems	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
21	K199	P.S. 199	K	Electrical Systems	No Capital Work Required
21	K215	P.S. 215	K	Electrical Systems	No Capital Work Required
21	K216	P.S. 216	K	Electrical Systems	No Capital Work Required
21	K239	I.S. 239	K	Climate Control	No Capital Work Required
21	K239	I.S. 239	K	Lighting Fixtures	No Capital Work Required
21	K253	P.S. 253	K	Climate Control	No Capital Work Required
21	K253	P.S. 253	K	Interior Spaces	No Capital Work Required
21	K281	I.S. 281	K	Room Conversions/Partitioning	Work Previously Completed
21	K288	P.S. 288	K	Playground Redevelopment	No Capital Work Required
21	K329	P.S. 329	K	Reinforcing Cinder Concrete Slabs	No Capital Work Required
22	K152	P.S. 152	K	Lighting Fixtures	Reclassified
22	K194	P.S. 194	K	Electrical Systems	No Capital Work Required
22	K195	P.S. 195	K	Heating Plant Upgrade	No Capital Work Required
22	K240	I.S. 240	K	Cafeteria / Multipurpose Room Upgrade	Alternate Project Prioritized
22	K254	P.S. 254	K	Climate Control	No Capital Work Required
22	K254	P.S. 254	K	Interior Spaces	No Capital Work Required
23	K055	I.S. 55	K	Electrical Systems	No Capital Work Required
23	K183	P.S. 183	K	Electrical Systems	No Capital Work Required
23	K284	P.S. 284	K	Electrical Systems	No Capital Work Required
24	Q068	P.S. 68	Q	Auditorium Upgrade	Alternate Project Prioritized
24	Q071	P.S. 71	Q	Student Toilets	Alternate Project Prioritized
24	Q071	P.S. 71	Q	Staff Toilets	Alternate Project Prioritized
24	Q102	P.S./I.S. 102	Q	Playgrounds	No Capital Work Required
25	Q024	P.S. 24 ADDITION	Q	Electrical Systems	No Capital Work Required
25	Q168	J.H.S. 168	Q	Boiler Conversion	Work Previously Completed
25	Q168	J.H.S. 168	Q	Climate Control	Work Previously Completed
26	Q031	P.S. 31	Q	Boiler Conversion	Reclassified
26	Q031	P.S. 31	Q	Climate Control	Reclassified
26	Q074	I.S. 74	Q	Electrical Systems	Alternate Project Prioritized
26	Q094	P.S. 94	Q	Electrical Systems	No Capital Work Required



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
26	Q098	P.S. 98	Q	Electrical Systems	No Capital Work Required
26	Q178	P.S. 178	Q	Electrical Systems	No Capital Work Required
26	Q179	P.S. 179	Q	Heating Plant Upgrade	No Capital Work Required
26	Q186	P.S. 186	Q	Electrical Systems	No Capital Work Required
27	Q042	P.S. 42	Q	Reinforcing Cinder Concrete Slabs	No Capital Work Required
27	Q043	P.S. 43	Q	Playgrounds	No Capital Work Required
27	Q047	P.S. 47	Q	Heating Plant Upgrade	No Capital Work Required
27	Q106	P.S. 106	Q	Climate Control	No Capital Work Required
27	Q106	P.S. 106	Q	Electrical Systems	No Capital Work Required
27	Q108	P.S. 108	Q	Electrical Systems	No Capital Work Required
27	Q114	P.S. 114	Q	Auditorium Upgrade	No Capital Work Required
27	Q146	P.S. 146	Q	Domestic Piping	No Capital Work Required
27	Q183	P.S. 183	Q	Climate Control	No Capital Work Required
27	Q210	I.S. 210	Q	Cafeteria / Multipurpose Room Upgrade	Alternate Project Prioritized
27	Q907	P.S. 43 ANNEX	Q	Elevators and Escalators	No Capital Work Required
27	Q920	P.S. 43 TRANSPORTABLE	Q	Exterior Masonry	No Capital Work Required
27	Q920	P.S. 43 TRANSPORTABLE	Q	Electrical Systems	No Capital Work Required
27	Q920	P.S. 43 TRANSPORTABLE	Q	Interior Spaces	No Capital Work Required
28	Q160	P.S. 160	Q	Climate Control	No Capital Work Required
28	Q160	P.S. 160	Q	Heating Plant Upgrade	No Capital Work Required
28	Q175	P.S. 175	Q	Exterior Masonry	Work Previously Completed
28	Q278	PS 182 ANNEX	Q	Lighting Fixtures	Work Previously Completed
28	Q814	P.S. 82 ANNEX	Q	Electrical Systems	No Capital Work Required
29	Q116	P.S. 116	Q	Heating Plant Upgrade	No Capital Work Required
29	Q131	P.S. 131	Q	Flood Elimination	Reclassified
29	Q138	P.S. 138	Q	Auditorium Upgrade	Alternate Project Prioritized
29	Q176	P.S. 176	Q	Electrical Systems	Reclassified
30	Q151	P.S. 151	Q	Electrical Systems	No Capital Work Required
30	Q234	P.S. 234	Q	School Safety	Reclassified
31	R002	I.S. 2	R	Heating Plant Upgrade	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
31	R004	P.S. 4	R	Electrical Systems	No Capital Work Required
31	R019	P.S. 19	R	Electrical Systems	No Capital Work Required
31	R021	P.S. 21	R	Electrical Systems	No Capital Work Required
31	R029	P.S. 29	R	Electrical Systems	No Capital Work Required
31	R029	P.S. 29	R	Heating Plant Upgrade	No Capital Work Required
31	R030	P.S. 30	R	Electrical Systems	No Capital Work Required
31	R035	P.S. 35	R	Electrical Systems	No Capital Work Required
31	R051	I.S. 51	R	Electrical Systems	No Capital Work Required
31	R055	P.S. 55	R	Electrical Systems	No Capital Work Required
31	R060	P.S. 60	R	Electrical Systems	No Capital Work Required
31	R848	P.S. 42 ANNEX	R	Lighting Fixtures	Reclassified
31	R848	P.S. 42 ANNEX	R	Electrical Systems	No Capital Work Required
31	R885	P.S. 80 AX(PETR COMPL-BLDG D)	R	Electrical Systems	No Capital Work Required
31	R886	P.S. 80 AX(PETR COMPL-BLDG C)	R	Electrical Systems	No Capital Work Required
32	K045	P.S. 45	K	Lighting Fixtures	Reclassified
32	K086	P.S. 86	K	Electrical Systems	No Capital Work Required
32	K106	P.S. 106	K	Electrical Systems	No Capital Work Required
32	K145	P.S. 145	K	Playgrounds	No Capital Work Required
32	K296	I.S. 296	K	Electrical Systems	No Capital Work Required
32	K299	P.S. 299	K	Playgrounds	No Capital Work Required
32	K383	I.S. 383	K	Boiler Conversion	Work Previously Completed
32	K383	I.S. 383	K	Climate Control	Work Previously Completed
33K	K801	CENT HEADQTRS (65 COURT)	K	Heating Plant Upgrade	Alternate Project Prioritized
33K	K801	CENT HEADQTRS (65 COURT)	K	Lighting Fixtures	No Capital Work Required
75M	M058	P.S. 35 (OLD 58/MNHT HS)	M	Electrical Systems	No Capital Work Required
75M	M751	P.S. 751 (CAR.DEV/OLD 25)	M	Student Toilets	No Capital Work Required
75M	M841	P.S. 811 (OLD P148/LIVINGS HS)	M	Lighting Fixtures	No Capital Work Required
75M	M841	P.S. 811 (OLD P148/LIVINGS HS)	M	Electrical Systems	No Capital Work Required
75Q	Q009	P.S. 9 (W REED SCHOOL)	Q	Electrical Systems	No Capital Work Required
75Q	Q816	P.S. 256 ANNEX	Q	Climate Control	Reclassified

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
75Q	Q816	P.S. 256 ANNEX	Q	Flood Elimination	Reclassified
75Q	Q816	P.S. 256 ANNEX	Q	Interior Spaces	Reclassified
75Q	Q816	P.S. 256 ANNEX	Q	Electrical Systems	Reclassified
75Q	Q816	P.S. 256 ANNEX	Q	Heating Plant Upgrade	Reclassified
75Q	Q816	P.S. 256 ANNEX	Q	Gymnasium Upgrade	Reclassified
75Q	Q816	P.S. 256 ANNEX	Q	Playgrounds	Reclassified
75R	R825	P.S. 25 (MOUNT LORETTO)	R	Electrical Systems	No Capital Work Required
75R	R840	P.S. 37 ( OLD I24X)	R	Electrical Systems	No Capital Work Required
75R	R884	P.S. 373 AX (PTR COMP-BLDG J)	R	Electrical Systems	No Capital Work Required
75X	X012	P.S. 12	X	Electrical Systems	No Capital Work Required
75X	X012	P.S. 12	X	Playgrounds	No Capital Work Required
75X	X136	P.S. 186 (OLD J136)	X	Electrical Systems	No Capital Work Required
75X	X701	P.S. 723	X	Ventilation	No Capital Work Required
78K	K400	LAFAYETTE HS	K	Climate Control	No Capital Work Required
78K	K410	ABRAHAM LINCOLN HS	K	Reinforcing Support Elements	Work Previously Completed
78K	K430	BROOKLYN TECH HS	K	Heating Plant Upgrade	No Capital Work Required
78K	K458	BOYS HS (OLD)	K	Electrical Systems	No Capital Work Required
78K	K500	CANARSIE HS	K	Boiler Conversion	Reclassified
78K	K500	CANARSIE HS	K	Climate Control	Reclassified
78K	K525	EDWARD R. MURROW HS	K	Electrical Systems	No Capital Work Required
78K	K540	JOHN DEWEY HS	K	Electrical Systems	No Capital Work Required
78K	K615	E NY VOC HS OF TRANSIT TECH.	K	Electrical Systems	No Capital Work Required
78K	K620	WILLIAM E. GRADY VOC HS	K	Interior Spaces	No Capital Work Required
78K	K778	EL PUENTE HS	K	Electrical Systems	No Capital Work Required
78K	K804	COBBLE HILL SCL OF AMR STD (OL6)	K	Electrical Systems	No Capital Work Required
78K	K806	METROPOLITAN CORPORATE ACAD.	K	Electrical Systems	No Capital Work Required
78K	K907	BROWNSVILLE DIPLOMA PLUS HS	K	Electrical Systems	No Capital Work Required
78M	M445	SEWARD PARK HS	M	Heating Plant Upgrade	Work Previously Completed
78M	M445	SEWARD PARK HS	M	Lighting Fixtures	Work Previously Completed
78M	M501	ARTHUR SCHOMBURG HS (IS 201)	M	Heating Plant Upgrade	No Capital Work Required

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
CANCELLED PROJECTS**

<b>District</b>	<b>Bld ID</b>	<b>School</b>	<b>Boro</b>	<b>Program Category</b>	<b>Reason</b>
78M	M646	SCL COOP TECH ED (MNH VOC HS)	M	Lighting Fixtures	No Capital Work Required
78M	M837	ISHS @ M837	M	Lighting Fixtures	No Capital Work Required
78M	M911	HARLEM RENAISSANCE HS (OLD M24)	M	Electrical Systems	No Capital Work Required
78Q	Q023	QUEENS ACADEMY HS	Q	Electrical Systems	No Capital Work Required
78Q	Q410	BEACH CHANNEL HS	Q	Heating Plant Upgrade	No Capital Work Required
78Q	Q410	BEACH CHANNEL HS	Q	Athletic Fields	Reclassified
78Q	Q430	FRANCIS LEWIS HS	Q	Electrical Systems	No Capital Work Required
78Q	Q441	FOREST HILLS HS AF	Q	Athletic Fields	Work Previously Completed
78Q	Q446	BRYANT HS AF	Q	Athletic Fields	Alternate Project Prioritized
78Q	Q450	NEWCOMERS HIGH SCHOOL (OLD LIC)	Q	Electrical Systems	No Capital Work Required
78Q	Q739	YOUNG WOMEN'S LEADERSHIP ACADEM	Q	Electrical Systems	No Capital Work Required
78Q	Q781	JOHN ADAMS HS ANNEX	Q	Lighting Fixtures	No Capital Work Required
78Q	Q792	NORTH QUEENS COMMUNITY HS	Q	Electrical Systems	Alternate Project Prioritized
78R	R450	CURTIS HS	R	Safety Systems	No Capital Work Required
78R	R451	CURTIS HS AF	R	Athletic Fields	Reclassified
78R	R600	RALPH MCKEE VOC HS	R	Electrical Systems	No Capital Work Required
78X	X400	MORRIS HS	X	Heating Plant Upgrade	No Capital Work Required
78X	X405	HERBERT H. LEHMAN HS	X	Reinforcing Cinder Concrete Slabs	No Capital Work Required
78X	X430	WALTON HS	X	Electrical Systems	Reclassified
78X	X440	DEWITT CLINTON HS	X	Lighting Fixtures	Reclassified
78X	X451	STEVENSON AF	X	Athletic Fields	Alternate Project Prioritized
78X	X600	ALFRED E. SMITH HS	X	Lighting Fixtures	No Capital Work Required
78X	X965	REGION 2 SUSPENSION CENTER	X	Electrical Systems	No Capital Work Required
84Q	Q781	JOHN ADAMS HS ANNEX	Q	Electrical Systems	No Capital Work Required

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Manhattan Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.01	0.00	0.00	0.00	0.01
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.06	0.02	0.01	-0.01	0.00	0.08
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	1.93	20.62	13.98	8.46	25.01	70.00
3. Climate Control	0.89	4.72	4.29	2.60	8.47	20.97
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	14.20	6.32	8.91	2.15	8.33	39.91
7. Lighting Fixtures	38.98	20.56	1.97	1.07	-0.10	62.48
8. Elevators and Escalators	0.09	0.03	0.31	0.01	8.02	8.45
9. Reinforcing Cinder Concrete Slabs	0.07	0.03	0.03	0.03	0.00	0.16
10. Flood Elimination	7.54	11.51	10.61	15.15	9.11	53.91
11. Air Conditioning Retrofit	0.03	0.04	0.08	0.07	0.00	0.23
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.13	1.23	1.13	0.15	4.83	7.48
14. Interior Spaces	0.98	0.09	2.22	1.07	0.11	4.48
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playground Redevelopment	1.55	0.27	4.20	4.18	0.48	10.67
3. Swimming Pools	0.30	0.19	0.14	0.06	0.02	0.70
E. System Replacements						
1. Roofs	15.70	7.42	18.17	43.97	58.24	143.50
2. Parapets	14.32	10.17	28.26	32.65	16.05	101.45
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	5.98	4.37	18.46	14.38	52.99	96.17
5. Exterior Masonry	53.68	29.37	79.36	103.02	74.04	339.48
6. Electrical Systems	2.00	0.95	5.63	3.82	9.18	21.58
7. Heating Plant Upgrade	5.44	9.78	7.79	7.65	7.15	37.81
8. Domestic Piping	1.30	1.80	0.35	3.94	9.72	17.10
9. Toilets - Students	4.37	6.21	2.18	3.41	7.75	23.92

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Manhattan Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
E. System Replacements						
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.02	0.00	0.67	0.29	0.00	0.99
12. Paved Area - Blacktop	0.05	0.18	2.77	0.37	0.02	3.39
13. Paved Area - Concrete	0.16	1.02	0.20	2.08	0.53	3.98
14. Fencing	0.01	0.11	0.04	1.73	0.16	2.06
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.14	0.14
17. Auditorium Upgrade	0.37	1.45	0.51	0.12	0.32	2.77
18. Gymnasium Upgrade	1.25	0.25	1.04	0.71	0.60	3.84
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.09	0.30	0.02	0.03	2.30	2.74
<hr/>						
<i>I. State of Good Repair Yearly Totals:</i>	171.49	139.04	213.33	253.16	303.47	
					<b><i>I. State of Good Repair Total:</i></b>	<b>1,080.48</b>
<b>II. System Expansion</b>						
A. New Construction-Additional Capacity						
1. New Schools	106.88	75.39	17.72	61.39	12.32	273.71
2. Building Additions	0.00	0.00	0.00	0.00	0.00	0.00
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	0.01	0.00	0.00	4.88	8.23	13.11
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
9. 3-K Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.03	0.60	0.63
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.51	0.63	0.05	5.34	7.75	14.28

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Manhattan Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>II. System Expansion</b>						
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	8.12	0.22	0.28	42.88	-0.01	51.48
F. Replacements						
1. Replacements - New	3.02	1.77	0.62	0.27	0.08	5.75
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Lease	3.95	0.09	14.59	1.18	4.65	24.45
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<i>II. System Expansion Yearly Totals:</i>	122.49	78.11	33.25	115.96	33.62	
						<b>II. System Expansion Total: 383.41</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions / Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrade	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
<i>III. Educational Enhancements Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>III. Educational Enhancements Total: 0.00</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	0.01	0.00	0.00	0.00	0.42	0.43
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
<i>IV. Safety and Security Yearly Totals:</i>	0.01	0.00	0.00	0.00	0.42	
						<b>IV. Safety and Security Total: 0.43</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Manhattan Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>V. Ancillary Facilities Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>V. Ancillary Facilities Total: 0.00</b>
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	2.83	5.19	10.63	15.80	14.72	49.17
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>	2.83	5.19	10.63	15.80	14.72	
						<b>VI. Emergency, Unspecified and Misc. Total: 49.17</b>
<hr/>						
<b>Yearly Totals for Manhattan</b>	296.81	222.33	257.21	384.93	352.22	
						<b>Manhattan Grand Total: \$1,513.50</b>



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Capacity Projects**  
**Borough of Manhattan**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	02	DSF0000798235	I.S. 323	1,016	Aug-13	Feb-15	Jun-18	177.08	44.10	131.18	1.80
*	03	DSF0000730952	THE RIVERSIDE SCHOOL	692	Apr-11	Jun-16	Sep-17	103.10	3.61	99.49	0.00
* L	05	DSF0000866751	TEACHER'S COLLEGE COMMUNITY SCHOOL ANNEX	245	Aug-17	May-18	Sep-19	12.71	0.00	12.20	0.51

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
Borough of Manhattan  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	02	DSF0000800052 PRE-K CENTER @ 2-26 WASHINGTON ST	108	Jun-14	Jan-15	Sep-15	12.57	0.01	12.56	0.00
* L	02	DSF0000865846 DISTRICT 2 PRE-K CENTER @ 606 WEST 57TH STREET	72	Dec-16	Nov-18	Jun-19	7.77	0.00	7.77	0.00
*	02	DSF0000821653 PRE-K CENTER @ 2 LAFAYETTE STREET	36	Oct-14	Jul-15	Aug-16	7.98	0.00	7.98	0.00
* L	02	DSF0000866155 DISTRICT 2 PRE-K CENTER @ 355 EAST 76 STREET	180	Apr-17	May-18	Jun-19	21.46	0.00	21.46	0.00
* L	02	DSF0000866268 PRE-K CENTER @ 252 EAST 57 STREET	144	May-17	Jan-18	Jun-18	9.54	0.00	9.54	0.00
* L	02	DSF0000867184 PRE-K CENTER @ 1683 3RD AVENUE	90	Sep-17	Feb-18	Aug-18	9.44	0.00	9.44	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Replacement Projects**  
**Borough of Manhattan**  
 (in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	78M DSF0000800279 Phase 2	WEST END SECONDARY SCHOOL	Replacement	Jun-14	Jan-17	May-19	23.43	0.00	22.23	1.20

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
 L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
01	Manhattan	M015		<b>P.S. 15</b>				
			M015	DSF0000866159		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	42,350
				DSF0000798364		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	806,265
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000739189		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,564,514
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		
			M015	DSF0000843821		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	57,195
			M015	DSF0000784791		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
				DSF0000808159		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	102,760
			M015	DSF0000808160		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	64,438
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting Fixture - Incandescent		
							<b>P.S. 15 Total:</b>	\$2,669,202
01	Manhattan	M019		<b>P.S. 19</b>				
					DSF0000808194	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	929,666
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting Fixture - Fluorescent		
			M019		DSF0000852256	<b>State of Good Repair - System Replacements - Roofs</b>	2019	4,486,289
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
					DSF0000808201	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	398,780
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							<b>P.S. 19 Total:</b>	\$5,814,735
01	Manhattan	M022		<b>N.E.S.T (OLD J22)</b>				
						<b>Other</b>		
			M539		DSF0000867124	New/Retrofit Telephone/Intercom Systems	2018	299,180
							<b>N.E.S.T (OLD J22) Total:</b>	\$299,180

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
01	Manhattan	M025		<b>J.H.S. 25</b>				
					DSF0000822234	<i>Miscellaneous</i>	2015	1,043,132
					DSF0000808252	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	1,996,383
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000866865	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	3,000
					DSF0000808257	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	290,110
			M515		DSF0000822662	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	116,301
			M378		DSF0000874996	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	400,444
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						<b>Other</b>		
			M515		DSF0000843786	Classroom Connectivity	2016	146,146
							<b>J.H.S. 25 Total:</b>	<b>\$3,995,516</b>
01	Manhattan	M034		<b>P.S. 34</b>				
					DSF0000866868	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	3,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000808331	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
						<b>Other</b>		
			M034		DSF0000889444	IP Surveillance Camera Installation	2019	37,766
							<b>P.S. 34 Total:</b>	<b>\$185,552</b>
01	Manhattan	M056		<b>J.H.S. 56</b>				
			M292		DSF0000822689	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,867,515
					DSF0000785220	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	2,088,550
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M080		DSF0000875283	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating		
			M080		DSF0000852643	<b>State of Good Repair - System Replacements - Roofs</b>	2018	6,057,663
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			M292		DSF0000866194	Classroom Connectivity	2017	48,516

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M292		DSF0000889179	New/Retrofit Telephone/Intercom Systems	2018	314,245
					DSF0000868082	IP Surveillance Camera Installation	2019	406,285
							<b>J.H.S. 56 Total:</b>	<b>\$11,975,274</b>
01	Manhattan	M060		<b>J.H.S. 60</b>				
			M450		DSF0000785275	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	1,488,343
					DSF0000762652	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	5,346,673
			M450		DSF0000866117	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M450		DSF0000785277	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2015	846,063
			M450		DSF0000799353	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,910,346
					DSF0000912294	<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,246,348
			M330		DSF0000808643	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	109,723



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
FIXTURES:STUDENT:Lavatory/Sink								
							<b>J.H.S. 60 Total:</b>	\$11,025,186
01	Manhattan	M061		<b>P.S. 61</b>				
					DSF0000785290	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,065,914
			M315		DSF0000762665	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	2,055,462
					DSF0000775645	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2016	778,882
					DSF0000785297	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2016	855,149
			M361		DSF0000843975	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	172,072

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M315		DSF0000808659	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	108,191
							<b>P.S. 61 Total:</b>	\$5,035,670
01	Manhattan	M063		<b>P.S. 63</b>				
			M063		DSF0000808675	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	76,064
							<b>P.S. 63 Total:</b>	\$76,064
01	Manhattan	M064		<b>P.S. 64 (OLD 71)</b>				
					DSF0000866876	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	9,000
			M064		DSF0000866118	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M064		DSF0000785332	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	342,319

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
			M064	DSF0000865997		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			M839	DSF0000822021		New/Retrofit Telephone/Intercom Systems	2015	210,552
			M064	DSF0000776052		IP Surveillance Camera Installation	2015	546,422
							<b>P.S. 64 (OLD 71) Total:</b>	<b>\$1,338,712</b>
01	Manhattan	M110		<b>P.S. 110</b>				
				DSF0000911881		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	40,000
				DSF0000809086		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	245,459
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			M110	DSF0000866003		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	195,596
						<b>Other</b>		
			M110	DSF0000889177		New/Retrofit Telephone/Intercom Systems	2018	170,121
							<b>P.S. 110 Total:</b>	<b>\$651,176</b>
01	Manhattan	M134		<b>P.S. 134</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000911918	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	372,306
					DSF0000831482	<b>Safety and Security - Safety and Security - Safety Systems</b>	2016	100,000
					DSF0000798307	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	935,877
					DSF0000876065	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	10,836,143
			M134		DSF0000876066	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
					DSF0000876063	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING	2019	2,466,418
					DSF0000876062	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	7,912,892
			M134		DSF0000809418	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000876064	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	8,342,876
			M134		DSF0000867086	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	244,033
							<b>P.S. 134 Total:</b>	<b>\$31,504,396</b>
01	Manhattan	M137		<b>P.S. 137</b>				
			M184		DSF0000853493	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	62,920
			M184		DSF0000786134	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000799815	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	242,204
			M184		DSF0000786136	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	466,988
			M184		DSF0000809459	FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	101,351

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
					DSF0000876108	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	1,764,813
			M184		DSF0000889282	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
			M184		DSF0000889283	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
						<b>Other</b>		
			M184		DSF0000889178	New/Retrofit Telephone/Intercom Systems	2018	196,846
							<b>P.S. 137 Total:</b>	<b>\$2,866,802</b>
01	Manhattan	M140		<b>P.S. 140</b>				
					DSF0000799775	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	51,547
					DSF0000866077	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			M140		DSF0000866196	Classroom Connectivity	2017	22,121
							<b>P.S. 140 Total:</b>	<b>\$288,460</b>
01	Manhattan	M142		<b>P.S. 142</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799587	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	130,180
			M142		DSF0000891078	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube HEATING:Unit Heater/Cabinet Heater	2019	192,500
			M142		DSF0000809493	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b> SITE:PAVING - STUDENT USE:Asphalt	2017	3,347,910
							<b>P.S. 142 Total:</b>	<b>\$3,670,590</b>
01	Manhattan	M188		<b>P.S. 188</b>				
					DSF0000777498	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	164,158
					DSF0000912317	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY DC STANDBY BATTERY POWER EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	94,283
					DSF0000799593	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	150,411

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000809940	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	165,158
			M188		DSF0000843783	<b>Other</b> Classroom Connectivity	2016	233,060
			M188		DSF0000889458	IP Surveillance Camera Installation	2019	40,181
							<b>P.S. 188 Total:</b>	<b>\$847,251</b>
02	Manhattan	M001		<b>P.S. 1</b>				
					DSF0000874691	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	4,906,836
					DSF0000784576	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	761,711
			M001		DSF0000761938	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	1,334,028



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000775641	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	756,518
					DSF0000866861	DOMESTIC WATER SYSTEM <b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	11,313
					DSF0000874694	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	13,401,205
					DSF0000784587	EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Kitchen Areas</b>	2016	333,361
					DSF0000912459	KITCHEN <b>State of Good Repair - System Replacements - Roofs</b>	2019	1,992,895
					DSF0000807952	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	115,315
			M001		DSF0000874693	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Windows</b>	2019	9,959,912

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
EXTERIOR:WINDOWS								
							<b>P.S. 1 Total:</b>	\$33,573,094
02	Manhattan	M002		<b>P.S. 2</b>				
					DSF0000799701	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	222,401
			M002		DSF0000874712	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating		
			M002		DSF0000807970	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	61,598
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			M002		DSF0000889284	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
							<b>P.S. 2 Total:</b>	\$476,499
02	Manhattan	M003		<b>P.S. 3</b>				
					DSF0000912316	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	70,717
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXIT LIGHT EXIT/EMERGENCY LIGHT		
					DSF0000799772	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	89,565
			M003		DSF0000807990	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	69,274
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							<b>P.S. 3 Total:</b>	<b>\$229,556</b>
02	Manhattan	M006		<b>P.S. 6</b>				
					DSF0000821593	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	831,063
					DSF0000889286	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	36,820
			M006		DSF0000865907	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	167,932
							<b>P.S. 6 Total:</b>	<b>\$1,035,815</b>
02	Manhattan	M011		<b>P.S. 11</b>				
			M011		DSF0000762105	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,944,527

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000866862	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	8,525
		M011			DSF0000853806	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	18,429,879
		M011			DSF0000874870	<b>State of Good Repair - System Replacements - Parapets</b>	2019	17,731,538
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000821721	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	378,884
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
<b>P.S. 11 Total:</b>								<b>\$38,493,353</b>
02	Manhattan	M017		<b>I.S. 17</b>				
			M408		DSF0000822005	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Auditorium Upgrade	2017	3,854,043
			M408		DSF0000830259	<b>Low-Voltage Electrical System</b>	2017	1,031,148
			M212		DSF0000808176	FIRE ALARM SYSTEM <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	2,625,949

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799773	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	95,678
			M212		DSF0000808180	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,176,692
						EXTERIOR:EXTERIOR WALLS		
					DSF0000823573	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
						EXTERIOR:PARAPETS		
			M212		DSF0000822122	<b>State of Good Repair - System Replacements - Roofs</b>	2017	1,173,524
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			M212		DSF0000784813	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	140,800
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
			M212		DSF0000808181	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	107,827
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000822121	FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2017	399,132
			M212		DSF0000867104	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	280,549
							<b>I.S. 17 Total:</b>	<b>\$12,231,435</b>
02	Manhattan	M033		<b>P.S. 33</b>				
					DSF0000866867	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	22,488
					DSF0000799808	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	168,763
			M033		DSF0000784943	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	153,344
					DSF0000808310	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	673,711

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 33 Total:</b>	\$1,018,306
02	Manhattan	M040		<b>P.S. 40</b>				
					DSF0000798365	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	866,665
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M040		DSF0000865995	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			M040		DSF0000822045	New/Retrofit Telephone/Intercom Systems	2015	201,694
			M040		DSF0000912225	IP Surveillance Camera Installation	2019	69,914
							<b>P.S. 40 Total:</b>	\$1,291,002
02	Manhattan	M041		<b>P.S. 41</b>				
			M041		DSF0000808375	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M041		DSF0000889180	New/Retrofit Telephone/Intercom Systems	2018	227,891
							<b>P.S. 41 Total:</b>	<b>\$329,242</b>
02	Manhattan	M042		<b>P.S. 42</b>				
					DSF0000866869	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	6,262
			M042		DSF0000808393	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	156,560
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			M042		DSF0000865996	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	305,460
						<i>Other</i>		
			M042		DSF0000822065	New/Retrofit Telephone/Intercom Systems	2015	240,989
							<b>P.S. 42 Total:</b>	<b>\$709,271</b>
02	Manhattan	M047		<b>J.H.S. 47 (SCH FOR THE DEAF)</b>				
					DSF0000785113	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,690,080
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000785119	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	672,486
			M047		SCA0000030133	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,880,449
			M047		DSF0000808489	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			M047		DSF0000823645	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351
					DSF0000801088	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2017	1,275,808
<b>J.H.S. 47 (SCH FOR THE DEAF) Total:</b>								<b>\$5,770,174</b>
02	Manhattan	M070		<b>I.S. 70</b>				
			M412		SCA0000056465	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	TBD
			M414		DSF0000821970	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	1,359,960
					DSF0000798359	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	660,129

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M312		DSF0000808720	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	1,297,229
					DSF0000799809	FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	112,797
			M312		DSF0000799864	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	265,864
			M312		DSF0000865998	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	628,993
							<b>I.S. 70 Total:</b>	<b>\$4,324,972</b>
02	Manhattan	M089		<b>P.S./I.S. 89</b>				
			M089		DSF0000842684	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2016	173,280
					DSF0000823574	INTERIOR:GYMNASIUM:Floor Finish <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
							<b>P.S./I.S. 89 Total:</b>	<b>\$243,003</b>
02	Manhattan	M104		<b>I.S. 104</b>				
					DSF0000785700	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,475,975

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M104		DSF0000785705	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	416,951
			M104		DSF0000866001	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			M104		DSF0000889450	IP Surveillance Camera Installation	2019	39,577
							<b>I.S. 104 Total:</b>	<b>\$2,085,232</b>
02	Manhattan	M111		<b>P.S. 111</b>				
					DSF0000868208	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	215,626
					DSF0000898653	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	5,438,652
			M111		DSF0000890999	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,108,502
						EXTERIOR:PARAPETS		
			M111		DSF0000875756	<b>State of Good Repair - System Replacements - Roofs</b>	2019	4,579,481
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			M111		DSF0000809099	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	113,785
						FIXTURES:STUDENT:Lavatory/Sink		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 111 Total:</b>	\$11,456,046
02	Manhattan	M114		<b>EAST SIDE MIDDLE SCHOOL</b>				
						<i>Other</i>		
			M114	DSF0000889451		IP Surveillance Camera Installation	2019	41,187
							<b>EAST SIDE MIDDLE SCHOOL Total:</b>	\$41,187
02	Manhattan	M116		<b>P.S. 116</b>				
				DSF0000799583		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	156,076
				DSF0000912372		<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	702,815
						SITE:Drainage System for Concrete		
						SITE:RETAINING WALLS		
							<b>P.S. 116 Total:</b>	\$858,891
02	Manhattan	M124		<b>P.S. 124 (ECF)</b>				
				DSF0000785900		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,443,726
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M124		DSF0000831317	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2016	70,459
							<b>P.S. 124 (ECF) Total:</b>	\$1,514,185
02	Manhattan	M126		<b>P.S. 126</b>				
			M126		DSF0000843773	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	35,401
					DSF0000898820	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	160,000
							<b>P.S. 126 Total:</b>	\$195,401
02	Manhattan	M130		<b>P.S. 130</b>				
					DSF0000786009	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE	2017	1,670,355
					DSF0000799814	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	225,557
			M130		DSF0000889607	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M130		DSF0000867088	New/Retrofit Telephone/Intercom Systems	2018	188,288
							<b>P.S. 130 Total:</b>	\$2,298,992
02	Manhattan	M131		<b>I.S. 131</b>				
			M131		DSF0000889360	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	224,074
					DSF0000777497	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	125,715
			M131		DSF0000786035	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2015	78,698
							<b>I.S. 131 Total:</b>	\$428,487
02	Manhattan	M158		<b>P.S. 158</b>				
					DSF0000775978	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2015	966,174
					DSF0000763742	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1,927,544

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					SCA0000024913	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	18,736,495
			M158		DSF0000866121	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000763744	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	3,577,555
					DSF0000763743	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,483,399
					DSF0000777440	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	3,589,518
					DSF0000876316	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	4,019,696
			M158		DSF0000865910	<b>Other</b> Classroom Connectivity	2017	267,525
							<b>P.S. 158 Total:</b>	<b>\$35,645,596</b>
02	Manhattan	M167		<b>I.S. 167</b>				
					DSF0000786448	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	966,534

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821602	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2017	464,773
					SCA0000024953	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2016	6,003,846
					DSF0000786449	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,645,450
					DSF0000786456	<i>State of Good Repair - System Replacements - Paved Area - Concrete</i> SITE:PAVING - STUDENT NON-USE:Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways	2016	335,708
			M167		DSF0000853820	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2016	1,379,713
					DSF0000809787	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	219,229
			M167		DSF0000866004	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
			M167		DSF0000866007	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	107,936
					DSF0000799887	<i>State of Good Repair - System Replacements - Windows</i>	2016	543,440



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
EXTERIOR:WINDOWS								
<i>Other</i>								
			M167		DSF0000889455	IP Surveillance Camera Installation	2019	40,248
<b>I.S. 167 Total:</b>								\$12,921,669
02	Manhattan	M183		<b>P.S. 183</b>				
					DSF0000844146	<b>Domestic Piping</b> DOMESTIC WATER SYSTEM	2017	169,540
					DSF0000798268	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	5,138,636
					DSF0000798269	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,339,041
					DSF0000777289	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	327,944
					DSF0000786577	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	17,587
					DSF0000799592	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	15,951
					DSF0000753130	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	13,194,250

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M183		DSF0000853963	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork	2018	73,065
					DSF0000777290	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	900,307
					DSF0000799938	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	837,584
						<b>Other</b>		
			M183		DSF0000889181	New/Retrofit Telephone/Intercom Systems	2018	141,647
							<b>P.S. 183 Total:</b>	<b>\$22,155,552</b>
02	Manhattan	M190		<b>P.S. 290</b>				
			M290		DSF0000854019	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	42,350
			M290		DSF0000889610	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			M290		DSF0000867125	New/Retrofit Telephone/Intercom Systems	2018	185,429
							<b>P.S. 290 Total:</b>	<b>\$442,571</b>
02	Manhattan	M198		<b>P.S. 198</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000786769	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	340,692
					DSF0000786768	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	443,012
			M198		DSF0000889612	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000786770	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2017	8,917,681
							<b>P.S. 198 Total:</b>	\$9,916,177
02	Manhattan	M234		<b>P.S. 234</b>				
			M234		SCA0000027772	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2016	1,133,052
							<b>P.S. 234 Total:</b>	\$1,133,052
02	Manhattan	M267		<b>P.S. 59 (MEETH)</b>				
					DSF0000911378	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	2,920,429
			M267		DSF0000889083	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	936,794
							<b>Other</b>	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M267	DSF0000889182		New/Retrofit Telephone/Intercom Systems	2018	152,270
			M267	DSF0000889460		IP Surveillance Camera Installation	2019	38,571
							<b>P.S. 59 (MEETH) Total:</b>	<b>\$4,048,064</b>
02	Manhattan	M276		<b>P.S./I.S. 276</b>				
						<i>Other</i>		
			M276	DSF0000889461		IP Surveillance Camera Installation	2019	37,856
							<b>P.S./I.S. 276 Total:</b>	<b>\$37,856</b>
02	Manhattan	M660		<b>SCHL OF THE FUTURE (OLD BACON)</b>				
				DSF0000810787		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	152,027
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			M413	DSF0000866013		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>SCHL OF THE FUTURE (OLD BACON) Total:</b>	<b>\$304,756</b>
02	Manhattan	M777		<b>FIT</b>				
				DSF0000844033		<b>Educational Enhancements - Educational Enhancements - Library Upgrade</b>	2016	654,729
				DSF0000866165		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	627,255

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000844034	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	257,815
					DSF0000843923	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	8,309,515
			M000		DSF0000843776	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	482,230
			M000		DSF0000843775	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	2,831,627
						Ventilation		
			M000		DSF0000843777	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	395,676
						Ventilation		
			M000		DSF0000843778	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	2,204,268
						Ventilation		
					DSF0000843779	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	234,250
			M000		DSF0000843780	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	449,231
						Ventilation		
					DSF0000844030	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	748,000
						Air Conditioning Split System		
					DSF0000844031	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	964,459

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Ventilation		
					DSF0000844035	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	4,356,606
						Ventilation		
					DSF0000866164	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	537,869
						Ventilation		
					DSF0000868070	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	7,356,918
						Air Conditioning Split System		
<b>FIT Total:</b>								\$30,410,448
02	Manhattan	M816		<b>P.S. 527 - EAST SIDE SCHOOL FOR SOCIAL ACTION</b>				
			M527		DSF0000911437	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	761,905
						HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube		
<b>P.S. 527 - EAST SIDE SCHOOL FOR SOCIAL ACTION Total:</b>								\$761,905
03	Manhattan	M009		<b>P.S. 9</b>				
					DSF0000799578	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	143,644
						<b>Other</b>		
			M009		DSF0000867126	New/Retrofit Telephone/Intercom Systems	2018	242,651

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M009		DSF0000889441	IP Surveillance Camera Installation	2019	39,443
							<b>P.S. 9 Total:</b>	\$425,738
03	Manhattan	M044		<b>I.S. 44</b>				
			M452		DSF0000821820	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	867,202
					DSF0000798300	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,196,462
			M245		DSF0000739460	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	1,939,710
			M245		DSF0000808430	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
							<b>I.S. 44 Total:</b>	\$4,153,374
03	Manhattan	M054		<b>I.S. 54</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M054		DSF0000890592	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2019	11,598,808
			M054		DSF0000890594	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2019	3,005,262
					DSF0000808563	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	1,063,440
					DSF0000785205	<i>State of Good Repair - System Replacements - Exterior Masonry</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	1,763,978
							<b>I.S. 54 Total:</b>	<b>\$17,431,488</b>
03	Manhattan	M075		<b>P.S. 75</b>				
			M075		DSF0000823602	<i>Heating Plant Upgrade</i>	2016	1,691,702
					DSF0000775607	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2016	7,966,335
					DSF0000775608	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2016	1,051,778
					DSF0000822223	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,118,491



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M075		DSF0000785406	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	112,451
							<b>P.S. 75 Total:</b>	\$11,940,757
03	Manhattan	M076		<b>P.S. 76</b>				
			M076		DSF0000785426	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	74,279
			M076		DSF0000808779	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	89,111
							<b>P.S. 76 Total:</b>	\$163,390
03	Manhattan	M084		<b>P.S. 84</b>				
			M084		DSF0000830924	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	73,208

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M084		DSF0000889606	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			M084		DSF0000822054	New/Retrofit Telephone/Intercom Systems	2015	225,628
			M084		DSF0000776053	IP Surveillance Camera Installation	2015	471,079
							<b>P.S. 84 Total:</b>	<b>\$984,707</b>
03	Manhattan	M087		<b>P.S. 87</b>				
					DSF0000898428	<b>Safety and Security - Safety and Security - Safety Systems</b>	2019	440,530
						EXTERIOR:DOORS:DOORS AND FRAMES		
			M087		DSF0000890595	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	9,422,908
						HEATING PLANT:Boiler Auxiliaries		
			M087		DSF0000890596	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	3,929,009
						CLIMATE CONTROL SYSTEM		
			M087		DSF0000890584	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	646,962
					DSF0000898420	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,315,525
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000830939	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2016	75,569

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000898418	INTERIOR:GYMNASIUM:Ceiling <b>State of Good Repair - System Replacements - Parapets</b>	2019	496,600
					DSF0000898417	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	4,393,693
			M087		DSF0000808861	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	167,877
			M087		DSF0000889086	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal <b>State of Good Repair - System Replacements - Windows</b>	2019	8,241,409
						EXTERIOR:WINDOWS		
<b>P.S. 87 Total:</b>								\$29,130,082
03	Manhattan	M088		<b>I.S. 88</b>				
					DSF0000865894	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	186,453
			M415		DSF0000776027	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	639,474
			M415		DSF0000843672	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	912,530

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000843673	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Gymnasium Upgrade	2016	101,351
			M415		DSF0000843874	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> INTERIOR:GYMNASIUM:Seating	2016	392,199
			M860		DSF0000843875	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	499,784
					DSF0000843677	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2018	1,740,383
			M415		DSF0000852922	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	111,328
					DSF0000799581	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	95,049
			M415		DSF0000865809	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2019	420,405
					DSF0000830960	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System	2016	126,514

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump		
					DSF0000912201	DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	934,281
					DSF0000867041	<b>Other</b> IP Surveillance Camera Installation	2019	472,388
							<b>I.S. 88 Total:</b>	<b>\$6,632,139</b>
03	Manhattan	M113		<b>P.S. 241</b>				
					DSF0000731099	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2016	5,170,017
					DSF0000718946	HEATING PLANT:BOILER AUXILIARIES <b>State of Good Repair - Building Upgrade - Climate Control</b>	2016	1,259,965
			M241		DSF0000866160	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	76,230
			M241		DSF0000785769	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	2,085,019
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799582	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	199,910
			M241		DSF0000823647	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	194,952
							<b>P.S. 241 Total:</b>	<b>\$8,986,093</b>
03	Manhattan	M118		<b>I.S. 118</b>				
					DSF0000844706	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	246,266
					DSF0000866278	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	466,500
					DSF0000821969	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	374,849
					DSF0000912171	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2019	8,555,170
					DSF0000799584	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	414,959
					DSF0000763233	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	7,772,311
						EXTERIOR:EXTERIOR WALLS		
					DSF0000763232	<i>State of Good Repair - System Replacements - Parapets</i>	2017	3,342,338
						EXTERIOR:PARAPETS		
					DSF0000763231	<i>State of Good Repair - System Replacements - Roofs</i>	2017	4,495,300
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 118 Total:</b>	<b>\$25,667,693</b>
03	Manhattan	M144		<b>P.S. 242 (OLD P144)</b>				
					DSF0000799959	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2016	467,654
			M242		DSF0000798379	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2019	7,202,271
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			M242		DSF0000798381	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2019	1,409,868
						CLIMATE CONTROL SYSTEM		
			M242		DSF0000786204	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	33,808
						<i>Other</i>		
			M242		DSF0000865909	Classroom Connectivity	2017	247,985
							<b>P.S. 242 (OLD P144) Total:</b>	<b>\$9,361,586</b>
03	Manhattan	M145		<b>P.S. 145</b>				
					DSF0000866886	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	3,630
							<b>P.S. 145 Total:</b>	<b>\$3,630</b>
03	Manhattan	M149		<b>P.S. 149 (TANDEM M207)</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M811		DSF0000843671	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	849,159
			M149		DSF0000843760	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	594,792
			M149		DSF0000865763	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	137,450
						Technology		
			M149		DSF0000865765	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	301,720
						Technology		
			M811		DSF0000865766	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	217,282
						Technology		
			M811		DSF0000865767	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	155,000
						Technology		
			M811		DSF0000865768	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	55,000
						Technology		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000786253	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	871,362
			M149		DSF0000822115	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			M149		DSF0000823650	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	304,792
<b>P.S. 149 (TANDEM M207) Total:</b>								<b>\$3,636,557</b>
03	Manhattan	M163		<b>P.S. 163</b>				
					DSF0000799702	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	137,412
			M163		DSF0000822265	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	3,479,613
			M163		DSF0000865807	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	130,046
<b>P.S. 163 Total:</b>								<b>\$3,747,071</b>
03	Manhattan	M165		<b>P.S. 165</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000912365	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	101,566
					DSF0000866892	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	273,120
					DSF0000777681	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	8,666,394
					DSF0000799928	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	1,380,739
			M165		DSF0000888806	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	16,962,848
			M165		DSF0000866006	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			M165		DSF0000866239	New/Retrofit Telephone/Intercom Systems	2017	239,037
			M165		DSF0000889454	IP Surveillance Camera Installation	2019	40,047
							<b>P.S. 165 Total:</b>	<b>\$27,816,480</b>
03	Manhattan	M166		<b>P.S. 166</b>				
					DSF0000786434	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	79,709
					DSF0000799590	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	208,023

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000752875	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,473,249
						FIRE ALARM SYSTEM		
					DSF0000866893	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	13,734
			M166		DSF0000889609	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			M166		DSF0000776057	IP Surveillance Camera Installation	2015	551,248
							<b>P.S. 166 Total:</b>	<b>\$2,540,755</b>
03	Manhattan	M180		<b>P.S. 180</b>				
						<b>Other</b>		
			M180		DSF0000866198	Classroom Connectivity	2017	40,040
							<b>P.S. 180 Total:</b>	<b>\$40,040</b>
03	Manhattan	M185		<b>P.S. 185 (TANDEM M208)</b>				
			M185		DSF0000866008	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			M185		DSF0000843698	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	3,079,891
							<b>P.S. 185 (TANDEM M208) Total:</b>	<b>\$3,294,683</b>
03	Manhattan	M191		<b>P.S. 191</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M191		DSF0000786671	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
					DSF0000809992	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	205,521
			M191		DSF0000889611	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 191 Total:</b>	<b>\$451,993</b>
03	Manhattan	M199		<b>P.S. 199</b>				
					DSF0000799594	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	574,570
					DSF0000899620	<i>State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation</i>	2019	526,446
						<i>Other</i>		
			M199		DSF0000889185	New/Retrofit Telephone/Intercom Systems	2018	176,005
							<b>P.S. 199 Total:</b>	<b>\$1,277,021</b>
03	Manhattan	M207		<b>P.S. 207 (TANDEM M149)</b>				
					DSF0000798362	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	1,156,271
			M149		DSF0000889613	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 207 (TANDEM M149) Total:</b>	<b>\$1,371,063</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
03	Manhattan	M208		<b>P.S. 208 (TANDEM M185)</b>				
					DSF0000764203	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2015	3,488,193
					DSF0000764202	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2015	2,903,934
					DSF0000764201	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	4,868,039
					DSF0000799479	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	847,711
<b>P.S. 208 (TANDEM M185) Total:</b>								<b>\$12,107,877</b>
03	Manhattan	M342		<b>THE RIVERSIDE SCHOOL</b>				
					DSF0000891082	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	453,000
<b>THE RIVERSIDE SCHOOL Total:</b>								<b>\$453,000</b>
04	Manhattan	M007		<b>P.S. 7</b>				
			M007		DSF0000865994	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M007		DSF0000889440	IP Surveillance Camera Installation	2019	37,900
							<b>P.S. 7 Total:</b>	\$190,629
04	Manhattan	M013		<b>I.S. 13</b>				
					DSF0000866863	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	21,421
						<i>Other</i>		
			M555		DSF0000889442	IP Surveillance Camera Installation	2019	40,413
							<b>I.S. 13 Total:</b>	\$61,834
04	Manhattan	M045		<b>I.S. 45</b>				
			M138		DSF0000823630	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	3,244,981
			M409		DSF0000844114	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,190,189
			M409		DSF0000808442	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,282,737
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000785076	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,831,470
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866871	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	3,392
		M409			DSF0000830519	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	365,996
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS		
		M045			DSF0000808446	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	160,910
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			M409		DSF0000889445	IP Surveillance Camera Installation	2019	40,181
							<b>I.S. 45 Total:</b>	<b>\$8,119,856</b>
04	Manhattan	M050		<b>P.S. 50 (UDC &amp; ECF)</b>				
			M050		DSF0000821759	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2015	138,385

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
					DSF0000785154	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,335,519
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M050		DSF0000830601	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	13,051,971
						EXTERIOR:LOUVER		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			M050		DSF0000830600	<b>State of Good Repair - System Replacements - Parapets</b>	2018	1,614,944
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
			M050		DSF0000852590	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2018	585,441
						SITE:SITE WALLS (NOT RETAINING WALLS)		
			M050		DSF0000830599	<b>State of Good Repair - System Replacements - Roofs</b>	2018	5,054,854
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
			M050		DSF0000808528	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	122,755
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 50 (UDC &amp; ECF) Total:</b>	\$21,903,869
04	Manhattan	M072		<b>P.S. 72</b>				
					DSF0000821804	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2017	1,285,239
					DSF0000762771	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	240,592
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000785379	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	944,403
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M072		DSF0000739811	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2016	1,656,309
						AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent		
						AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent		
						AUDITORIUM:LOCAL SOUND SYSTEM		
						AUDITORIUM:PROJECTION SYSTEM		
						AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Window Curtains/Shades/Blinds		
					DSF0000762786	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2016	356,661
						CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent CAFETERIA:LOCAL SOUND SYSTEM INTERIOR:CAFETERIA:Fixed Equipment INTERIOR:CAFETERIA:Floor Finish		
					DSF0000762773	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	12,105,691
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			M072		DSF0000875431	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	286,907
						GAS SERVICE:Gas Distribution Piping HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube		
					DSF0000762772	<b>State of Good Repair - System Replacements - Parapets</b>	2016	2,697,398
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000801023	<b>State of Good Repair - System Replacements - Roofs</b>	2016	724,605
						EXTERIOR:ROOFING:Roofing		
					DSF0000801070	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2016	666,207

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 72 Total:</b>	\$20,964,012
04	Manhattan	M083		<b>P.S. 83</b>				
					DSF0000822096	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	11,295,763
			M083		DSF0000739877	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2015	1,807,439
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			M083		DSF0000830899	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	102,460
			M083		DSF0000808827	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	138,795
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						<b>Other</b>		
			M083		DSF0000822061	New/Retrofit Telephone/Intercom Systems	2015	207,083
							<b>P.S. 83 Total:</b>	\$13,551,540
04	Manhattan	M096		<b>P.S. 96</b>				
					DSF0000821841	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	786,077
			M096		DSF0000866000	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 96 Total:</b>	\$938,806
04	Manhattan	M099		<b>I.S. 99</b>				
			M224	DSF0000867099		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,049,517
			M224	DSF0000865769		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	193,892
						Technology		
			M385	DSF0000822240		<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2017	2,754,347
						INTERIOR:STAIRS/RAMPS: INTERIOR		
			M433	DSF0000866119		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
						DSF0000911879		
						<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	75,000
						DSF0000808993		
						<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	92,553
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						<b>Other</b>		
			M635	DSF0000822062		New/Retrofit Telephone/Intercom Systems	2015	188,176
			M224	DSF0000889449		IP Surveillance Camera Installation	2019	43,239

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 99 Total:</b>	\$4,474,414
04	Manhattan	M101		<b>P.S. 101</b>				
			M811	DSF0000844090		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	464,393
			M811	DSF0000821758		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	154,123
						Technology		
			M375	DSF0000843877		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	98,035
						Technology		
			M811	DSF0000845620		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	152,617
						Technology		
			M811	DSF0000865764		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	158,093
						Technology		
							<b>P.S. 101 Total:</b>	\$1,027,261
04	Manhattan	M102		<b>P.S. 102</b>				
				DSF0000798366		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	845,727

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M102	DSF0000809022		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2017	1,031,754
				DSF0000875686		INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	8,048,914
			M102	DSF0000785684		EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	53,115
				DSF0000875684		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	3,113,210
				DSF0000875683		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,065,688
				DSF0000875685		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	4,909,397
							<b>P.S. 102 Total:</b>	<b>\$22,067,805</b>
04	Manhattan	M108		<b>P.S. 108</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798339	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	6,093,951
					DSF0000798341	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,573,954
					DSF0000831121	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2017	1,045,285
					DSF0000853110	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,504,257
					DSF0000844074	<b>State of Good Repair - System Replacements - Kitchen Areas</b>	2017	387,021
						<b>Other</b>		
			M108		DSF0000866195	Classroom Connectivity	2017	40,040
			M108		DSF0000889186	New/Retrofit Telephone/Intercom Systems	2018	196,338
							<b>P.S. 108 Total:</b>	<b>\$10,840,846</b>
04	Manhattan	M112		<b>P.S. 112 (TANDEM M206)</b>				
					DSF0000752353	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,077,959
					DSF0000799443	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,039,247

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799440	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,176,649
					DSF0000799442	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	578,439
					DSF0000799441	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	5,872,165
<b>P.S. 112 (TANDEM M206) Total:</b>								<b>\$12,744,459</b>
04	Manhattan	M117		<b>J.H.S. 117</b>				
			M138		DSF0000844094	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	43,570
					DSF0000785833	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:EMERGENCY GAS SHUT-OFF VALVE SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2017	2,018,086



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798304	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,595,544
					DSF0000868286	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	3,139
					DSF0000799469	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	1,590,905
					DSF0000875832	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Ceiling	2019	1,453,412
					DSF0000763210	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2015	4,358,761
					DSF0000763209	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	4,999,249
						<b>Other</b>		
			M012		DSF0000822063	New/Retrofit Telephone/Intercom Systems	2015	268,821
			M012		DSF0000889452	IP Surveillance Camera Installation	2019	40,565
<b>J.H.S. 117 Total:</b>								<b>\$16,372,052</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
04	Manhattan	M121		<b>P.S. 38 (OLD M121)</b>				
					DSF0000785861	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	678,427
			M038		DSF0000875866	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
					DSF0000898756	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	2,004,316
			M038		DSF0000809210	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	150,000
							<b>P.S. 38 (OLD M121) Total:</b>	<b>\$3,025,243</b>
04	Manhattan	M146		<b>P.S. 146</b>				
					DSF0000866887	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	15,933
					DSF0000809566	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	168,952

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			M146		DSF0000823649	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	138,788
						INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			M146		DSF0000866197	Classroom Connectivity	2017	40,040
			M146		DSF0000867083	New/Retrofit Telephone/Intercom Systems	2018	257,306
							<b>P.S. 146 Total:</b>	\$621,019
04	Manhattan	M155		<b>P.S. 155</b>				
					DSF0000866888	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	14,765
			M155		DSF0000786334	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	37,142
			M155		DSF0000809665	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	145,041
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 155 Total:</b>	\$196,948
04	Manhattan	M171		<b>P.S. 171</b>				
			M171	DSF0000876454		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	2,899,090
			M171	DSF0000876458		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS	2018	10,075,132
			M171	DSF0000844009		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	50,108
			M171	DSF0000876460		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Pressure Booster HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2018	1,248,196

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M171		DSF0000786496	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2015	111,095
					DSF0000821722	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2015	50,675
			M171		DSF0000876457	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	7,219,396
							<b>P.S. 171 Total:</b>	\$21,653,692
04	Manhattan	M206		<b>P.S. 206 (TANDEM M112)</b>				
					DSF0000866897	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	7,836
						<b>Other</b>		
			M206		DSF0000843785	Classroom Connectivity	2016	52,261
							<b>P.S. 206 (TANDEM M112) Total:</b>	\$60,097
05	Manhattan	M010		<b>I.S. 10 (TANDEM M200)</b>				
					DSF0000762099	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2016	5,801,274

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CENTRAL ACID WASTE NEUTRALIZING TANK		
						INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment		
						INTERIOR:SCIENCE LAB:Fixed Equipment		
						INTERIOR:SCIENCE PREP ROOM:Fixed Equipment		
						SCIENCE DEMO ROOM		
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent		
						SCIENCE LAB		
						SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent		
						SCIENCE PREP ROOM		
						SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000799579	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	712,187
					DSF0000868206	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,109,913
					DSF0000799807	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	327,217
						<b>Other</b>		
			M499		DSF0000889538	IP Surveillance Camera Installation	2019	40,516
							<b>I.S. 10 (TANDEM M200) Total:</b>	<b>\$7,991,107</b>
05	Manhattan	M030		<b>P.S. 30</b>				
			M138		DSF0000777288	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	431,029

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M138		DSF0000821750	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	95,972
			M030		DSF0000843867	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	138,070
			M138		DSF0000843872	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	241,539
			M030		DSF0000865854	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	273,528
					DSF0000798360	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,739,060
			M030		DSF0000875024	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES	2018	1,398,232

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M030		DSF0000852355	EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Roofs</b>	2018	4,243,718
			M030		DSF0000889443	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties  <b>Other</b> IP Surveillance Camera Installation	2019	39,309
							<b>P.S. 30 Total:</b>	<b>\$8,600,457</b>
05	Manhattan	M036		<b>P.S. 36</b>				
			M036		DSF0000875065	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	814,956
					DSF0000798361	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	914,867
			M036		DSF0000897961	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	611,942
			M036		DSF0000808345	EXTERIOR:CHIMNEY <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink	2017	143,443



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			M036		DSF0000866096	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	668,248
							<b>P.S. 36 Total:</b>	\$3,153,456
05	Manhattan	M043		<b>I.S. 172 (OLD 43)</b>				
			M286		DSF0000821821	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	652,782
			M367		DSF0000821822	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	719,381
			M410		DSF0000821824	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	718,629
			M286		DSF0000844156	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	219,256
			M286		DSF0000888919	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	209,000
			M369		DSF0000888920	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	209,185
			M367		DSF0000888921	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	172,682

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799483	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,829,145
			M286		DSF0000821760	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	46,512
			M369		DSF0000821761	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	46,512
			M286		DSF0000845584	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	111,350
			M367		DSF0000865727	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	188,703

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M367		DSF0000865728	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	133,714
			M369		DSF0000865772	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	63,900
			M369		DSF0000865773	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	236,150
			M369		DSF0000867185	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	140,000
			M369		DSF0000888789	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	100,000
					DSF0000821613	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2015	304,054
			M286		DSF0000852470	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY	2018	4,795,831

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS		
					DSF0000739453	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2015	1,345,285
						FIXTURES:STUDENT:Locker Room Shower GYMNASIUM:LIGHTING:Lighting Fixture - HID GYMNASIUM:SCOREBOARD INTERIOR:GYMNASIUM:Floor Finish		
			M367		DSF0000866116	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M369		DSF0000898025	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	60,400
						GAS SERVICE:Gas Distribution Piping HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube		
			M286		DSF0000868146	<b>State of Good Repair - System Replacements - Parapets</b>	2018	1,092,750
			M286		DSF0000852467	<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,855,967
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			M367		DSF0000889604	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			M286		DSF0000852469	<b>State of Good Repair - System Replacements - Windows</b>	2018	8,276,148
						EXTERIOR:WINDOWS		
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000867040	IP Surveillance Camera Installation	2018	456,485
							<b>I.S. 172 (OLD 43) Total:</b>	<b>\$26,276,303</b>
05	Manhattan	M046		<b>P.S. 46</b>				
					DSF0000799580	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	181,996
							<b>P.S. 46 Total:</b>	<b>\$181,996</b>
05	Manhattan	M092		<b>P.S. 92</b>				
					DSF0000865895	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	196,299
					DSF0000866280	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	450,762
			M092		DSF0000823646	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	562,622
			M092		DSF0000801028	<i>Interior Spaces</i> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2018	5,860,485
					DSF0000889314	<i>Safety and Security - Safety and Security - Code Compliance</i>	2019	145,792
			M092		DSF0000808919	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	150,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
							<b>P.S. 92 Total:</b>	\$7,365,960
05	Manhattan	M123		<b>P.S. 123</b>				
			M123	DSF0000888854		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	864,642
				DSF0000889315		<i>Safety and Security - Safety and Security - Code Compliance</i>	2019	144,014
			M123	DSF0000785880		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	7,147,864
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000867115		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	6,221
			M123	DSF0000823648		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	186,676
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 123 Total:</b>	\$8,349,417
05	Manhattan	M125		<b>P.S. 125</b>				
				DSF0000844705		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	190,956

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M362	DSF0000798164		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,362,069
			M362	DSF0000890995		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	2,285,762
			M125	DSF0000875906		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	428,801
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSF0000785922		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	864,261
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			M125	DSF0000875912		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,168,803
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
				DSF0000799813		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	384,991
			M125	DSF0000809264		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
				DSF0000875913		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	255,775
						GAS SERVICE:Gas Distribution Piping		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000853308	HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube <b>State of Good Repair - System Replacements - Kitchen Areas</b>	2019	7,792,035
			M125		DSF0000875910	INTERIOR:KITCHEN:Ceiling INTERIOR:KITCHEN:Door(s) INTERIOR:KITCHEN:Floor Finish INTERIOR:KITCHEN:Walls KITCHEN KITCHEN:Lighting:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Parapets</b>	2018	970,036
			M125		DSF0000875909	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK	2018	4,921,634
							<b>P.S. 125 Total:</b>	\$24,769,909
05	Manhattan	M129		<b>P.S. 129</b>				
					DSF0000821657	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2017	1,349,632
			M129		DSF0000809324	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink	2017	175,066



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<i>Other</i>		
			M129		DSF0000889453	IP Surveillance Camera Installation	2019	39,175
							<b>P.S. 129 Total:</b>	<b>\$1,563,873</b>
05	Manhattan	M133		<b>P.S. 133</b>				
			M133		DSF0000763455	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,200,250
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000866885	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	32,272
							<b>P.S. 133 Total:</b>	<b>\$1,232,522</b>
05	Manhattan	M161		<b>P.S. 161</b>				
					DSF0000889316	<b>Safety and Security - Safety and Security - Code Compliance</b>	2019	133,191
					DSF0000866890	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	4,474
			M161		DSF0000786370	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M161		DSF0000889608	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 161 Total:</b>	<b>\$384,137</b>
05	Manhattan	M175		<b>P.S. 175</b>				
					DSF0000786534	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,277,292
					DSF0000799817	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	181,735
			M175		DSF0000809867	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
						<i>Other</i>		
			M175		DSF0000889457	IP Surveillance Camera Installation	2019	38,974
							<b>P.S. 175 Total:</b>	<b>\$1,642,787</b>
05	Manhattan	M194		<b>P.S. 194</b>				
					DSF0000786707	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	607,558

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M194	DSF0000866009		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			M194	DSF0000866200		<b>Other</b> Classroom Connectivity	2017	22,121
							<b>P.S. 194 Total:</b>	<b>\$844,471</b>
05	Manhattan	M195		<b>TERENCE D. TOLBERT EDUCATION COMPLEX</b>				
			M514	DSF0000844165		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,025,944
							<b>TERENCE D. TOLBERT EDUCATION COMPLEX Total:</b>	<b>\$1,025,944</b>
05	Manhattan	M197		<b>P.S. 197</b>				
				DSF0000764120		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,577,072
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000764126		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,776,638
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M197	DSF0000810070		SWITCHBOARD <i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	105,702
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 197 Total:</b>	\$3,459,412
05	Manhattan	M200		<b>P.S. 200 (TANDEM M010)</b>				
			M200	DSF0000866010		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 200 (TANDEM M010) Total:</b>	\$214,792
05	Manhattan	M916		<b>TEACHERS COLLEGE COMMUNITY SCHOOL</b>				
						<i>Other</i>		
			M517	DSF0000912224		IP Surveillance Camera Installation	2019	69,114
							<b>TEACHERS COLLEGE COMMUNITY SCHOOL Total:</b>	\$69,114
06	Manhattan	M004		<b>P.S. 4</b>				
				DSF0000911919		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	1,097,794
			M004	DSF0000912477		<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2019	200,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777247	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	3,084,708
		M004			DSF0000874755	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Floor Finish	2019	530,354
					DSF0000784636	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	2,037,929
					DSF0000784635	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	1,429,093
							<b>P.S. 4 Total:</b>	<b>\$8,379,878</b>
06	Manhattan	M005		<b>P.S. 5</b>				
					DSF0000808017	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	2016	45,453
					DSF0000823572	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000800299	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	5,469,276
					DSF0000800300	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	4,625,324

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821734	<b>State of Good Repair - System Replacements - Windows</b>	2016	3,282,038
			M005		DSF0000866168	EXTERIOR:WINDOWS <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2016	4,720,959
			M005		DSF0000889188	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	226,617
							<b>P.S. 5 Total:</b>	\$18,439,390
06	Manhattan	M008		<b>P.S. 8</b>				
			M008		DSF0000889603	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 8 Total:</b>	\$214,792
06	Manhattan	M028		<b>P.S. 28</b>				
			M028		DSF0000890600	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	6,740,195
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Fuel System HEATING:Steam Heating		
			M028		DSF0000878933	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	2,607,781
						CLIMATE CONTROL SYSTEM		
					DSF0000808268	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,051,327

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M028	DSF0000912179		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	507,940
			M028	DSF0000889189		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	184,773
							<b>P.S. 28 Total:</b>	\$11,092,016
06	Manhattan	M048		<b>P.S. 48</b>				
				DSF0000821791		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	5,181,493
			M048	DSF0000821954		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	3,896,237
			M048	DSF0000844690		<b>Safety and Security - Safety and Security - Code Compliance</b>	2019	2,399,253
			M048	DSF0000821796		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	2,027,324
			M048	DSF0000865720		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	43,233
							<b>P.S. 48 Total:</b>	\$13,547,540
06	Manhattan	M052		<b>I.S. 52</b>				
			M052	DSF0000800194		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	953,072

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799484	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2016	2,271,009
					DSF0000785181	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,456,315
					DSF0000785179	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,097,696
					DSF0000785184	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	1,270,967
			M052		DSF0000808550	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2015	101,351



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			M052		DSF0000889446	IP Surveillance Camera Installation	2019	40,096
							<b>I.S. 52 Total:</b>	<b>\$8,190,506</b>
06	Manhattan	M090		<b>I.S. 90</b>				
					DSF0000844707	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	130,226
			M319		DSF0000821762	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	31,539
			M324		DSF0000821763	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	26,943
			M138		DSF0000821764	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	31,539
					DSF0000844130	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	90,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M319		DSF0000844136	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	272,355
			M319		DSF0000845597	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	90,869
					DSF0000852940	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	638,969
					DSF0000799955	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK	2019	351,235
					DSF0000808901	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			M319		DSF0000865999	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,940
			M319		DSF0000889448	<b>Other</b> IP Surveillance Camera Installation	2019	41,187
							<b>I.S. 90 Total:</b>	<b>\$1,927,525</b>
06	Manhattan	M093			<b>P.S./I.S. 210</b>			

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M210		DSF0000889359	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	338,882
						<b>Other</b>		
			M210		DSF0000843782	Classroom Connectivity	2016	170,802
			M210		DSF0000889191	New/Retrofit Telephone/Intercom Systems	2018	178,762
					DSF0000868085	IP Surveillance Camera Installation	2019	316,516
							<b>P.S./I.S. 210 Total:</b>	<b>\$1,004,962</b>
06	Manhattan	M098		<b>P.S. 98</b>				
					DSF0000785618	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	443,919
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 98 Total:</b>	<b>\$443,919</b>
06	Manhattan	M115		<b>P.S. 115</b>				
			M115		DSF0000799499	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	935,746
					DSF0000809132	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	905,637
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000898690	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2019	769,345

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
					DSF0000809139	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	308,282
			M115		DSF0000809140	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	150,000
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			M115		DSF0000822066	New/Retrofit Telephone/Intercom Systems	2015	170,969
							<b>P.S. 115 Total:</b>	<b>\$3,239,979</b>
06	Manhattan	M128		<b>P.S. 128</b>				
					DSF0000775601	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	8,558,270
					DSF0000763346	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	2,443,832
						CLIMATE CONTROL SYSTEM		
					DSF0000898834	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	60,000
			M128		DSF0000866005	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M128		DSF0000889190	New/Retrofit Telephone/Intercom Systems	2018	233,993
							<b>P.S. 128 Total:</b>	\$11,510,887
06	Manhattan	M132		<b>P.S. 132</b>				
			M132		DSF0000853418	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	6,677,808
					DSF0000868317	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	212,569
			M132		DSF0000809387	<b>State of Good Repair - System Replacements - Fencing</b> SITE:FENCES	2018	2,261,584
					DSF0000823575	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000888992	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	2,204,840
					DSF0000786055	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	4,991,984

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 132 Total:</b>	<b>\$16,418,508</b>
06	Manhattan	M143		<b>I.S. 143</b>				
					DSF0000763579	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM:EMERGENCY SHUT-OFF POWER SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2016	3,069,714
					DSF0000786181	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	2,064,366
					DSF0000868287	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	642,890
			M143		DSF0000786187	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	251,634

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
			M143		DSF0000809511	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	307,658
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
			M143		DSF0000822067	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	282,827
							<b>I.S. 143 Total:</b>	<b>\$6,619,089</b>
06	Manhattan	M152		<b>P.S. 152</b>				
			M152		DSF0000876243	<b>Auditorium Upgrade</b>	2019	787,500
						INTERIOR:AUDITORIUM:Fixed Seating		
			M152		DSF0000786275	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	2,727,186
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799588	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	275,253
			M152		DSF0000740683	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY	2015	1,665,545
					DSF0000853636	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2018	1,003,512
			M152		DSF0000809604	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	186,280
							<b>P.S. 152 Total:</b>	<b>\$6,645,276</b>
06	Manhattan	M153		<b>P.S. 153</b>				
					DSF0000786294	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,672,752



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799816	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	132,895
							<b>P.S. 153 Total:</b>	\$1,805,647
06	Manhattan	M164		<b>I.S. 164</b>	DSF0000799589	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	235,267
			M326		DSF0000809737	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	262,590
			M326		DSF0000843784	<b>Other</b> Classroom Connectivity	2016	434,129
					DSF0000868088	IP Surveillance Camera Installation	2019	445,729
							<b>I.S. 164 Total:</b>	\$1,377,715
06	Manhattan	M173		<b>P.S. 173</b>	M173 DSF0000876476	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	405,241

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			M173		DSF0000876479	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	9,803,640
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			M173		DSF0000866122	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M173		DSF0000876478	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,072,067
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000809852	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2016	66,436
			M173		DSF0000876485	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	395,265
						SITE:RETAINING WALLS		
			M173		DSF0000889082	<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,340,372
						EXTERIOR:ROOF:Roofing		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M173		DSF0000822059	New/Retrofit Telephone/Intercom Systems	2015	235,850
							<b>P.S. 173 Total:</b>	<b>\$13,396,561</b>
06	Manhattan	M178		<b>P.S. 178</b>				
					DSF0000821714	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2016	44,859
					DSF0000823576	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			M178		DSF0000891079	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
							<b>P.S. 178 Total:</b>	<b>\$307,082</b>
06	Manhattan	M187		<b>P.S./I.S. 187</b>				
					DSF0000786591	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	568,049
			M187		DSF0000809923	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	294,059

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S./I.S. 187 Total:</b>	\$862,108
06	Manhattan	M189		<b>P.S. 189</b>				
			M189	DSF0000876592		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	2,475,839
			M189	DSF0000866353		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	77,996
				DSF0000876596		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	3,003,374
			M189	DSF0000821906		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS FIRED FURNACE GAS SERVICE:GAS DISTRIBUTION PIPING HEATING	2015	73,793
			M189	DSF0000876595		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	4,610,869
			M189	DSF0000876594		<b>State of Good Repair - System Replacements - Roofs</b>	2019	4,410,714

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M189		DSF0000809958	EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	157,952
					DSF0000889278	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	912,646
							<b>P.S. 189 Total:</b>	\$15,723,183
06	Manhattan	M192		<b>P.S. 192</b>				
			M192		DSF0000821879	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	412,170
					DSF0000821805	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2017	1,388,955
					DSF0000786685	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	992,275
			M325		DSF0000866199	<b>Other</b> Classroom Connectivity	2017	40,040

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M325		DSF0000866240	New/Retrofit Telephone/Intercom Systems	2017	277,325
							<b>P.S. 192 Total:</b>	\$3,110,765
06	Manhattan	M218		<b>I.S. 218</b>				
					DSF0000866900	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	3,442
			M218		DSF0000810159	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
						<i>Other</i>		
			M293		DSF0000889540	IP Surveillance Camera Installation	2019	40,230
							<b>I.S. 218 Total:</b>	\$188,458
06	Manhattan	M233		<b>ALTERNATIVE LEARNING CENTER</b>				
					DSF0000866901	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	15,000
							<b>ALTERNATIVE LEARNING CENTER Total:</b>	\$15,000
06	Manhattan	M263		<b>P.S./I.S. 263</b>				
						<i>Other</i>		
			M366		DSF0000866201	Classroom Connectivity	2017	22,121
			M366		DSF0000889459	IP Surveillance Camera Installation	2019	39,644
							<b>P.S./I.S. 263 Total:</b>	\$61,765
06	Manhattan	M528		<b>I.S. 528</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000764641	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	1,186,526
			M528		DSF0000866203	<b>Other</b> Classroom Connectivity	2017	22,121
							<b>I.S. 528 Total:</b>	<b>\$1,208,647</b>
06	Manhattan	M814		<b>THE COMMUNITY HEALTH ACADEMY OF THE HEIGHTS</b>				
					DSF0000911913	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	327,278
					DSF0000866099	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2018	800,337
			M346		DSF0000865912	<b>Other</b> Classroom Connectivity	2017	78,260
							<b>THE COMMUNITY HEALTH ACADEMY OF THE HEIGHTS Total:</b>	<b>\$1,205,875</b>
06	Manhattan	M847		<b>P.S. 178 MINISCHOOL</b>				
					DSF0000888968	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	1,792,975
					DSF0000912306	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	5,145,451
							<b>P.S. 178 MINISCHOOL Total:</b>	<b>\$6,938,426</b>
06	Manhattan	M848		<b>P.S. 192 MINISCHOOL</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M325		DSF0000866014	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>P.S. 192 MINISCHOOL Total:</b>	\$152,729
06	Manhattan	M859		<b>I.S. 143 MINISCHOOL</b>				
			M348		DSF0000866015	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
						<i>Other</i>		
			M971		DSF0000843781	Classroom Connectivity	2016	164,862
							<b>I.S. 143 MINISCHOOL Total:</b>	\$379,654
06	Manhattan	M898		<b>P.S. 18</b>				
					DSF0000787656	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	498,022
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			M018		DSF0000823653	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 18 Total:</b>	\$599,373
75M	Manhattan	M058		<b>P.S. 35 (OLD 58/MNHT HS)</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799774	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	39,540
					DSF0000808623	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	270,270
						<b>Other</b>		
					DSF0000868084	IP Surveillance Camera Installation	2019	381,275
<b>P.S. 35 (OLD 58/MNHT HS) Total:</b>								<b>\$691,085</b>
75M	Manhattan	M079		<b>P.S. 79 (MULT. HANDICAP)</b>				
					DSF0000777495	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2016	97,337
					DSF0000785434	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,095,020
					DSF0000866878	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,000
			M079		DSF0000785442	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799810	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	142,916
			M079		DSF0000889605	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
<b>P.S. 79 (MULT. HANDICAP) Total:</b>								<b>\$1,587,745</b>
75M	Manhattan	M169		<b>P.S. 169 (ECF)</b>				
					DSF0000876434	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2018	751,038
						CONVEYING:Elevator		
					DSF0000786468	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	977,872
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			M169		DSF0000889263	New/Retrofit Telephone/Intercom Systems	2018	278,602
			M169		DSF0000889456	IP Surveillance Camera Installation	2019	44,644
<b>P.S. 169 (ECF) Total:</b>								<b>\$2,052,156</b>
75M	Manhattan	M751		<b>P.S. 751 (CAR.DEV/OLD 25)</b>				
					DSF0000787504	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	606,168

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
			M751		DSF0000877431	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2019	200,221	
			M751		DSF0000868095	<b>Other</b> IP Surveillance Camera Installation	2019	347,498	
<b>P.S. 751 (CAR.DEV/OLD 25) Total:</b>								\$1,153,887	
75M	Manhattan	M841		<b>P.S. 811 (OLD P148/LIVINGS HS)</b>					
			M811		DSF0000877454	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	1,233,684	
			M811		DSF0000877456	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR SOFFITS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR <b>Other</b>	2019	7,043,369	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M811	DSF0000889264		New/Retrofit Telephone/Intercom Systems	2018	198,903
<b>P.S. 811 (OLD P148/LIVINGS HS) Total:</b>								<b>\$8,475,956</b>
75M	Manhattan	M875		<b>P.S. 226 (FIRST PRESB CHURCH)</b>				
				DSF0000866907		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	15,000
<b>P.S. 226 (FIRST PRESB CHURCH) Total:</b>								<b>\$15,000</b>
78M	Manhattan	M066		<b>RICHARD R GREEN HS OF TEACHING</b>				
				DSF0000785343		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	701,895
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						<i>Other</i>		
			M151	DSF0000889447		IP Surveillance Camera Installation	2019	45,646
<b>RICHARD R GREEN HS OF TEACHING Total:</b>								<b>\$747,541</b>
78M	Manhattan	M081		<b>MID MAN ADULT LRNG CTR (81)</b>				
				DSF0000799500		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	792,363
			K755	DSF0000799521		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	551,421
			K755	DSF0000799950		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	638,112

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M984		DSF0000822215	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	3,501,663
			K755		DSF0000845616	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,224,293
					DSF0000898376	<i>State of Good Repair - Building Upgrade - Reinforcing Support Elements</i>	2019	5,419,709
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
					DSF0000875488	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	6,572,193
						EXTERIOR:AREAWAY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000799811	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	264,645
					DSF0000808808	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	54,348
						HEATING PLANT:BOILER SYSTEM		
<b>MID MAN ADULT LRNG CTR (81) Total:</b>								<b>\$19,018,747</b>
78M	Manhattan	M097		<b>BARD COLLEGE HS (OLD M097)</b>				
					DSF0000808949	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2016	2,901,960
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798378	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	849,168
					DSF0000798565	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	2,449,347
					DSF0000821636	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	2,711,094
					DSF0000808952	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	1,344,257
					DSF0000808951	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,435,315
			M696		DSF0000808955	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	101,351
			M696		DSF0000776054	<b>Other</b> IP Surveillance Camera Installation	2015	496,871

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>BARD COLLEGE HS (OLD M097) Total:</b>								\$13,289,363
78M	Manhattan	M107		<b>THE HERITAGE SCHOOL</b>				
			M680	DSF0000866002		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			M680	DSF0000865908		Classroom Connectivity	2017	179,408
			M680	DSF0000889187		New/Retrofit Telephone/Intercom Systems	2018	153,473
<b>THE HERITAGE SCHOOL Total:</b>								\$547,673
78M	Manhattan	M136		<b>I.S. 136</b>				
				DSF0000799586		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	127,172
				DSF0000821612		<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	457,059
			M302	DSF0000866120		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M148	DSF0000786109		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	107,041
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M302	DSF0000889539		IP Surveillance Camera Installation	2019	39,626
							<b>I.S. 136 Total:</b>	<b>\$808,588</b>
78M	Manhattan	M435		<b>MANHTN CT FOR MATH &amp; SCI. HS</b>				
				DSF0000821616		<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	479,066
			M435	DSF0000810214		<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	89,600
			M435	DSF0000889462		<i>Other</i> IP Surveillance Camera Installation	2019	44,531
							<b>MANHTN CT FOR MATH &amp; SCI. HS Total:</b>	<b>\$613,197</b>
78M	Manhattan	M440		<b>BAYARD RUSTIN EDUCATIONAL COMP</b>				
				DSF0000777499		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	116,091
				DSF0000799595		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	416,366
				DSF0000799776		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	75,874
			M313	DSF0000832320		<i>State of Good Repair - System Replacements - Domestic Piping</i>	2016	99,655



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
		M313		DSF0000876866		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	133,027
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
				DSF0000822656		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	390,491
		M437		DSF0000866123		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
		M437		DSF0000866011		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
		M437		DSF0000889463		IP Surveillance Camera Installation	2019	48,443
<b>BAYARD RUSTIN EDUCATIONAL COMP Total:</b>								<b>\$1,510,366</b>
78M	Manhattan	M445		<b>SEWARD PARK HS</b>				
				DSF0000799777		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	201,282

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821619	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2017	503,009
					DSF0000889018	<b>State of Good Repair - System Replacements - Containerization</b>	2019	191,111
					DSF0000866902	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	6,132
					DSF0000832328	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	71,897
						HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam supplied by External Sources		
			M543		DSF0000899763	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	131,075
						HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam supplied by External Sources		
			M294		DSF0000889183	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	451,541
					DSF0000867043	IP Surveillance Camera Installation	2018	494,030
							<b>SEWARD PARK HS Total:</b>	<b>\$2,050,077</b>
78M	Manhattan	M446			<b>UNIVERSITY NEIGHBORHOOD</b>			
			M448		DSF0000741361	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	2,645,162
						FIRE ALARM SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M448		DSF0000786971	PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2016	2,039,314
			M448		DSF0000876891	MOTOR STARTER/CONTACTOR VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			M448		DSF0000786964	HEATING:Steam Heating <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	92,520
<b>UNIVERSITY NEIGHBORHOOD Total:</b>								<b>\$4,969,496</b>
78M	Manhattan	M451		<b>LIBERTY HS</b>				
					DSF0000799597	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	106,716
			M550		DSF0000876911	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	110,119

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>LIBERTY HS Total:</b>	\$216,835
78M	Manhattan	M460		<b>WASHINGTON IRVING HS</b>				
			M374	DSF0000775870		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	530,215
			M460	DSF0000798601		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	8,311,394
			M460	DSF0000799936		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	652,263
			M460	DSF0000799937		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	662,368
			M374	DSF0000844086		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,750,059
			M438	DSF0000866756		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	97,685
						Technology		
				DSF0000799953		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	1,167,163
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000799598		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	612,578
				DSF0000799778		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	341,299

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000810292	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2017	2,122,075
					DSF0000821608	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2015	474,046
			M374		DSF0000832371	<b>State of Good Repair - System Replacements - Electrical Systems</b> PANEL BOARD TRANSFORMER	2017	6,448,345
					DSF0000764372	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	27,211,693
					DSF0000821658	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Floor Finish	2017	1,393,307
			M174		DSF0000786997	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000810308	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2015	95,270
					DSF0000786994	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	10,742,598
					DSF0000786993	<b>State of Good Repair - System Replacements - Roofs</b>	2017	5,696,674

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
						EXTERIOR:ROOFING:Roofing			
			M374	DSF0000889614		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792	
				DSF0000799952		<i>State of Good Repair - System Replacements - Windows</i>	2017	12,045,100	
						EXTERIOR:WINDOWS			
						<i>Other</i>			
				DSF0000843852		IP Surveillance Camera Installation	2017	849,545	
<b>WASHINGTON IRVING HS Total:</b>								<b>\$81,450,149</b>	
78M	Manhattan	M465		<b>G. WASHINGTON HS EDUC. CAMPUS</b>					
			M468	DSF0000889361		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	429,870	
			M468	DSF0000889346		<i>Interior Spaces</i>	2019	91,206	
				DSF0000777500		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	260,846	
				DSF0000799599		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	527,265	
			M463	DSF0000787010		<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2016	120,339	
						FIRE ALARM SYSTEM			
				DSF0000821611		<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	760,057	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M468		DSF0000868064	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain	2019	1,367,494
					DSF0000868318	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	328,589
					DSF0000876944	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	5,712,792
			M462		DSF0000787021	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000799818	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	103,825
					DSF0000810324	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	233,904
			M468		DSF0000911941	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	126,312
					DSF0000876942	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	3,669,977
					DSF0000876941	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	9,578,546

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M468	DSF0000866012		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			M468	DSF0000876947		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
			M462	DSF0000876943		<b>State of Good Repair - System Replacements - Windows</b>	2019	26,668,922
						EXTERIOR:WINDOWS		
						<b>Other</b>		
				DSF0000868089		IP Surveillance Camera Installation	2019	591,499
<b>G. WASHINGTON HS EDUC. CAMPUS Total:</b>								<b>\$51,218,359</b>
78M	Manhattan	M470		<b>LOUIS D. BRANDEIS HS</b>				
				DSF0000865896		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	298,082
				DSF0000866279		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	140,707
				DSF0000764420		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	2,412,012
						DOMESTIC WATER SYSTEM		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000764431	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2019	1,090,391	
						<b>Other</b>			
					DSF0000867044	IP Surveillance Camera Installation	2019	574,386	
<b>LOUIS D. BRANDEIS HS Total:</b>								<b>\$4,515,578</b>	
78M	Manhattan	M475		<b>HEALTH PROFESSIONS HS (OL STY)</b>					
					DSF0000800337	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	668,998	
			M420		DSF0000890631	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	849,729	
					DSF0000777501	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	277,853	
					DSF0000799600	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	343,915	
			M407		DSF0000787067	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680	
						<b>Other</b>			
			M420		DSF0000889464	IP Surveillance Camera Installation	2019	40,431	
<b>HEALTH PROFESSIONS HS (OL STY) Total:</b>								<b>\$2,212,606</b>	
78M	Manhattan	M477		<b>STUYVESANT HS (NEW)</b>					

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000822667	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	127,652	
			M475		DSF0000889465	<b>Other</b> IP Surveillance Camera Installation	2019	43,602	
<b>STUYVESANT HS (NEW) Total:</b>								\$171,254	
78M	Manhattan	M480		<b>JULIA RICHMAN ED. COMPLEX</b>					
					DSF0000911917	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	405,379	
					DSF0000799601	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	441,826	
			M565		DSF0000888934	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	450,000	
			M225		DSF0000877036	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2019	400,444	
			M225		DSF0000867089	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	515,030	
<b>JULIA RICHMAN ED. COMPLEX Total:</b>								\$2,212,679	
78M	Manhattan	M485		<b>FIORIELLO LAGUARDIA HS</b>					

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M485		DSF0000867085	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	4,308,707
					DSF0000911916	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	345,831
			M485		DSF0000865805	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	100,000
			M485		DSF0000741529	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2016	3,252,659
						FIRE ALARM SYSTEM		
					DSF0000741533	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	5,779,061
						EXTERIOR:EXTERIOR WALLS		
			M485		DSF0000832506	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	1,032,844
						Air Conditioning Split System		
						AIR CONDITIONING:Cooling Tower		
						<i>Other</i>		
			M485		DSF0000868090	IP Surveillance Camera Installation	2019	566,257
<b>FIORIELLO LAGUARDIA HS Total:</b>								<b>\$15,385,359</b>
78M	Manhattan	M486		<b>J. K. ONASSIS HS FOR INT CAREERS</b>				
			M529		DSF0000888783	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	327,676
			M529		DSF0000877073	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	400,444

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
<b>J. K. ONASSIS HS FOR INT CAREERS Total:</b>								\$728,120
78M	Manhattan	M488		<b>MIDTOWN EAST CAMPUS</b>				
					DSF0000844704	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2016	191,152
						<b>Other</b>		
					DSF0000799890	IP Surveillance Camera Installation	2016	115,145
<b>MIDTOWN EAST CAMPUS Total:</b>								\$306,297
78M	Manhattan	M490		<b>MARTIN LUTHER KING, JR. HS</b>				
					DSF0000865897	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	233,865
					DSF0000799602	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	758,278
			M494		DSF0000844150	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	136,289
						DOMESTIC WATER SYSTEM		
					DSF0000899980	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	300,000
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWITCHBOARD		
			M494		DSF0000832537	<b>State of Good Repair - System Replacements - Roofs</b>	2018	17,304,952
						EXTERIOR:PLAZA DECK		
			M494		DSF0000877090	<b>State of Good Repair - System Replacements - Windows</b>	2018	598,387
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			M494		DSF0000822038	New/Retrofit Telephone/Intercom Systems	2015	577,636
					DSF0000867046	IP Surveillance Camera Installation	2019	695,920
<b>MARTIN LUTHER KING, JR. HS Total:</b>								<b>\$20,605,327</b>
78M	Manhattan	M495		<b>PARK EAST HS</b>				
					DSF0000787172	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	536,875
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			M495		DSF0000865911	Classroom Connectivity	2017	222,689
<b>PARK EAST HS Total:</b>								<b>\$759,564</b>
78M	Manhattan	M501		<b>ARTHUR SCHOMBURG HS (IS 201)</b>				
			M157		DSF0000844115	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,175,919

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798316	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	510,235
					DSF0000888807	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	10,130,091
			M469		DSF0000832581	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation AIR CONDITIONING:Chilled Water System:Central Station Air Handler MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork	2016	141,081
			M157		DSF0000854533	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete SITE:PAVING:Student Use:Concrete	2018	1,630,901
			M157		DSF0000821723	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	317,237

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
<b>ARTHUR SCHOMBURG HS (IS 201) Total:</b>								\$13,905,464
78M	Manhattan	M506		<b>EDWARD A. REYNOLDS WEST SIDE HS</b>				
					DSF0000865898	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	136,569
					DSF0000877143	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	328,209
						EXTERIOR:EXTERIOR WALLS		
					DSF0000877142	<i>State of Good Repair - System Replacements - Parapets</i>	2019	198,122
						EXTERIOR:COPING		
					DSF0000877141	<i>State of Good Repair - System Replacements - Roofs</i>	2019	6,958,396
						EXTERIOR:PLAZA DECK		
						EXTERIOR:ROOF:Roofing		
<b>EDWARD A. REYNOLDS WEST SIDE HS Total:</b>								\$7,621,296
78M	Manhattan	M510		<b>FORSYTH HS (AUXSVC-OLD 91)</b>				
					DSF0000821670	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	882,520
			M458		DSF0000877154	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2018	1,333,176
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000787219	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	858,805
			M650		DSF0000865813	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2017	234,748
			M458		DSF0000877158	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2018	5,146,055
					DSF0000822657	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	205,521
			M650		DSF0000866124	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000877157	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	4,021,153
			M458		DSF0000877156	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	2,215,745
			M458		DSF0000810542	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	150,000



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			M650	DSF0000822064		New/Retrofit Telephone/Intercom Systems	2015	239,755
			M650	DSF0000866202		Classroom Connectivity	2017	40,040
<b>FORSYTH HS (AUXSVC-OLD 91) Total:</b>								<b>\$15,405,208</b>
78M	Manhattan	M520		<b>MURRY BERGTRAUM HS (ECF)</b>				
			M520	DSF0000775972		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,257,537
				DSF0000821817		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,248,635
				DSF0000821819		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	999,640
			M520	DSF0000787251		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2017	3,429,413
						Library Upgrade INTERIOR:LIBRARY:Built-in Furnishing INTERIOR:LIBRARY:Ceiling INTERIOR:LIBRARY:Floor Finish INTERIOR:LIBRARY:Walls LIBRARY:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000810567	LIBRARY:RACEWAY WITH RECEPTACLES <b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Science Lab Upgrades CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE LAB:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:EMERGENCY GAS SHUT-OFF VALVE SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Incandescent SCIENCE DEMO ROOM:POWER SUPPLY SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE LAB:EMERGENCY SHUT-OFF POWER SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Incandescent SCIENCE LAB:POWER SUPPLY SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2017	9,542,958

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000877174	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:Elevator INTERCOM SYSTEM:Elevator	2018	396,225
			M520		DSF0000832617	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly	2017	991,298
			M520		DSF0000888912	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2019	2,687,995
					DSF0000866308	<b>State of Good Repair - System Replacements - Floors</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2018	2,260,724
						<b>Other</b>		
					DSF0000868092	IP Surveillance Camera Installation	2019	396,617
<b>MURRY BERGTRAUM HS (ECF) Total:</b>								<b>\$24,211,042</b>
78M	Manhattan	M535		<b>PARK WEST HS (ECF)</b>				
			M288		DSF0000798653	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,739,677
			M138		DSF0000844093	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	43,749

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
					DSF0000900100	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2019	200,000
						CONVEYING:Elevator		
					DSF0000821623	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	479,066
					SCA0000019673	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	2,478,282
			M288		DSF0000787281	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			M288		DSF0000877213	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	400,444
						FIXTURES:Student:Lavatory/Sink		
						<i>Other</i>		
					DSF0000867047	IP Surveillance Camera Installation	2018	709,143
							<b>PARK WEST HS (ECF) Total:</b>	<b>\$7,082,041</b>
78M	Manhattan	M540		<b>A. PHILLIP RANDOLPH HS</b>				
					DSF0000911915	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	261,805
					DSF0000821667	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	656,782
					DSF0000832675	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2018	3,064,993

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000822224	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,581,765
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000868288	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	573,763
					DSF0000775750	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	52,664,624
			M540		DSF0000877233	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	135,998
					DSF0000844100	<b>State of Good Repair - System Replacements - Parapets</b>	2018	19,134,532
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000832677	<b>State of Good Repair - System Replacements - Roofs</b>	2018	7,920,375
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
<b>A. PHILLIP RANDOLPH HS Total:</b>								<b>\$85,994,637</b>
78M	Manhattan	M600				<b>FASHION INDUSTRIES VOC HS</b>		
					DSF0000822154	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	4,170,752
					DSF0000832702	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	870,584

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M600		DSF0000741739	INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	3,164,736
					DSF0000868211	PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	169,990
					DSF0000787330	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	14,278,473
			M600		DSF0000810647	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
					DSF0000787328	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	5,853,329
			M600		DSF0000889466	<b>Other</b> IP Surveillance Camera Installation	2019	51,940
<b>FASHION INDUSTRIES VOC HS Total:</b>								<b>\$28,704,590</b>
78M	Manhattan	M615		<b>CHELSEA VOC HS</b>				
			M615		DSF0000810662	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	3,725,731

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000775646	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	1,289,011
			M615		DSF0000866125	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			M615		DSF0000889615	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			M615		DSF0000889467	IP Surveillance Camera Installation	2019	40,516
			M615		DSF0000822211	Ansul Systems	2017	517,172
						<b>CHELSEA VOC HS Total:</b>		<b>\$5,864,912</b>
78M	Manhattan	M620		<b>NORMAN THOMAS HS (ECF)</b>				
			M432		DSF0000889362	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	591,638
			M432		DSF0000799488	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	499,022
			M427		DSF0000800277	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	822,395
			M500		DSF0000800278	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	863,041

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821880	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	699,879
			M500		DSF0000821757	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2015	39,096
						Technology		
			M432		DSF0000867098	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	84,173
						Technology		
					DSF0000800280	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2017	2,325,294
					DSF0000798363	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,140,713
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000877293	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	5,120,980
						FIRE ALARM SYSTEM		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly		
					DSF0000877313	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	9,385,572
						Fire System Sprinklers		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SPRINKLERS, STANDPIPE, FIRE SYSTEM: Dry Sprinkler Alarm Valve Assembly		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM: Fire Booster Pump Assembly		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM: Sprinkler Head		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM: Sprinkler Piping		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM: Standpipe System		
					DSF0000889047	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	60,000
					DSF0000832752	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	6,538,396
						EMERGENCY GENERATOR SET		
					DSF0000866187	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	396,372
			M427		DSF0000787375	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			M500		DSF0000877310	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System	2018	3,113,395
						<b>Other</b>		
					DSF0000867050	IP Surveillance Camera Installation	2018	714,499

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>NORMAN THOMAS HS (ECF) Total:</b>	<b>\$32,426,145</b>
78M	Manhattan	M625		<b>HS OF GRAPHIC COMMUNICATION ARTS</b>				
					DSF0000911914	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	322,152
			M625		DSF0000798598	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	684,903
					DSF0000799492	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	532,897
			M507		DSF0000799519	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	530,269
			M393		DSF0000799520	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	518,485
					DSF0000821668	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	471,528
					DSF0000821669	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	863,493
			M139		DSF0000844116	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	1,608,982
			M625		DSF0000777537	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	5,896,449
						Cafeteria / Multipurpose Room Upgrade		
					DSF0000752355	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2016	9,252,972

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000752354	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2016	3,571,484
			M507		DSF0000865811	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2017	104,870
					DSF0000810708	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,643,280
					DSF0000844141	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2018	3,077,354
					DSF0000844140	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2018	2,732,132
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
<b>HS OF GRAPHIC COMMUNICATION ARTS Total:</b>								\$35,811,250
78M	Manhattan	M641		<b>CITY AS SCHOOL (OLD 95)</b>				
			M560		DSF0000832800	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	98,841
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
			M560		DSF0000889184	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	524,984
<b>CITY AS SCHOOL (OLD 95) Total:</b>								\$623,825

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78M	Manhattan	M645		<b>OLD MANHATTAN VOC/TECH HS</b>				
					DSF0000787432	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	815,060
					DSF0000866156	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	3,792,138
					DSF0000854763	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube HEATING:Unit Heater/Cabinet Heater	2019	192,394
					DSF0000888927	<b>State of Good Repair - System Replacements - Roofs</b>	2018	81,327
			M655		DSF0000889616	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
<b>OLD MANHATTAN VOC/TECH HS Total:</b>								<b>\$5,095,711</b>
78M	Manhattan	M661		<b>MNHT COMP NIGHT&amp;DAY (OL BACN X)</b>				
					DSF0000799604	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	161,280

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Manhattan  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M575	DSF0000799789		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
<b>MNHT COMP NIGHT&amp;DAY (OL BACN X) Total:</b>								\$192,960
78M	Manhattan	M833		<b>HS FOR ECONOMICS &amp; FINANCE</b>				
				DSF0000787523		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	1,018,941
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000891024		<i>State of Good Repair - System Replacements - Gymnasium Upgrade</i>	2019	145,000
						INTERIOR:LOCKER ROOM:Floor Finish		
			M489	DSF0000787531		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			M489	DSF0000889617		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
<b>HS FOR ECONOMICS &amp; FINANCE Total:</b>								\$1,410,413
78M	Manhattan	M834		<b>HS FOR ENVIRONMENTAL STUDIES</b>				
				DSF0000821944		<i>Safety and Security - Safety and Security - Code Compliance</i>	2017	2,641,976
				DSF0000832931		<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2017	2,435,702
						FIRE ALARM SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000832947	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> GYMNASIUM:Lighting:Lighting Fixture - Fluorescent GYMNASIUM:Local Sound System INTERIOR:GYMNASIUM:Ceiling INTERIOR:GYMNASIUM:Seating INTERIOR:GYMNASIUM:Walls	2017	57,186	
					DSF0000832950	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Cooling Tower	2017	353,637	
<b>HS FOR ENVIRONMENTAL STUDIES Total:</b>								\$5,488,501	
78M	Manhattan	M837		<b>WEST END SECONDARY SCHOOL</b>					
			M479		DSF0000731146	<b>Code Compliance</b>	2015	1,376,272	
						<b>Other</b>			
			M479		DSF0000866227	New/Retrofit Telephone/Intercom Systems	2017	243,971	
<b>WEST END SECONDARY SCHOOL Total:</b>								\$1,620,243	
78M	Manhattan	M868		<b>THE CLINTON SCHOOL</b>					
			M260		DSF0000889363	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	105,754	
<b>THE CLINTON SCHOOL Total:</b>								\$105,754	
78M	Manhattan	M876		<b>GREGORIO LUPERON PREP. SCHOOL</b>					

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M552	DSF0000843958		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	756,724
			M552	DSF0000843957		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	284,664
			M552	DSF0000889468		<b>Other</b> IP Surveillance Camera Installation	2019	39,712
<b>GREGORIO LUPERON PREP. SCHOOL Total:</b>								\$1,081,100
78M	Manhattan	M877		<b>NEW YORK HARBOR SCHOOL</b>				
			M551	DSF0000889469		<b>Other</b> IP Surveillance Camera Installation	2019	38,460
<b>NEW YORK HARBOR SCHOOL Total:</b>								\$38,460
78M	Manhattan	M883		<b>LEGACY HS FOR INTEGR. STUDIES</b>				
			M534	DSF0000889470		<b>Other</b> IP Surveillance Camera Installation	2019	37,082
<b>LEGACY HS FOR INTEGR. STUDIES Total:</b>								\$37,082
78M	Manhattan	M894		<b>HS FOR LEADERSHIP &amp; PUBLIC SER</b>				
			M425	DSF0000810975		<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR	2015	601,634

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M425	DSF0000787642		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
				DSF0000799820		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	130,557
			M425	DSF0000867178		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING: Cooling Tower	2018	681,522
<b>HS FOR LEADERSHIP &amp; PUBLIC SER Total:</b>								\$1,445,393
78M	Manhattan	M896		<b>NYC PUBLIC SCHOOL REPERTORY CO</b>				
				DSF0000866908		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	4,774
						<b>Other</b>		
			M531	DSF0000866204		Classroom Connectivity	2017	186,157
			M531	DSF0000867090		New/Retrofit Telephone/Intercom Systems	2018	140,510
<b>NYC PUBLIC SCHOOL REPERTORY CO Total:</b>								\$331,441
78M	Manhattan	M911		<b>HARLEM RENAISSANCE HS (OLD M24)</b>				
				DSF0000787678		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Incandescent	2016	682,464



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Manhattan**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			M285		DSF0000889471	IP Surveillance Camera Installation	2019	38,705
						<b>HARLEM RENAISSANCE HS (OLD M24) Total:</b>		\$721,169
78M	Manhattan	M920		<b>SATELLITE ACADEMY</b>				
					DSF0000821788	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,106,736
						<b>SATELLITE ACADEMY Total:</b>		\$1,106,736
84M	Manhattan	M908		<b>HARLEM PROMISE ACADEMY CHARTER</b>				
			M284		DSF0000822180	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	2,000,000
						<b>HARLEM PROMISE ACADEMY CHARTER Total:</b>		\$2,000,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Bronx Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.02	0.00	0.00	0.00	0.00	0.02
3. Exterior Modernizations	0.00	0.00	0.00	0.00	0.00	0.01
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	17.80	24.10	22.50	24.12	18.88	107.41
3. Climate Control	4.69	6.06	9.22	9.69	5.10	34.75
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	4.79	1.92	0.71	4.81	6.59	18.83
7. Lighting Fixtures	56.05	30.08	2.37	-0.07	-0.09	88.33
8. Elevators and Escalators	0.14	2.01	0.08	0.34	0.91	3.49
9. Reinforcing Cinder Concrete Slabs	0.37	0.12	5.08	0.24	0.58	6.40
10. Flood Elimination	26.03	8.45	16.94	21.85	37.90	111.17
11. Air Conditioning Retrofit	0.26	0.34	0.80	0.12	0.00	1.52
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.55	0.05	0.08	8.74	6.22	15.65
14. Interior Spaces	0.17	2.89	2.38	1.41	0.42	7.28
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	0.00	0.20	0.02	8.60	0.71	9.54
2. Playground Redevelopment	1.32	2.34	1.83	2.51	7.54	15.53
3. Swimming Pools	0.03	0.05	0.04	0.03	0.01	0.16
E. System Replacements						
1. Roofs	29.47	27.58	29.71	38.49	55.87	181.12
2. Parapets	32.86	29.35	21.78	40.56	36.56	161.11
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	11.27	0.85	16.74	32.08	15.57	76.51
5. Exterior Masonry	64.16	37.60	88.33	69.08	101.37	360.54
6. Electrical Systems	2.70	0.18	1.82	0.52	5.00	10.22
7. Heating Plant Upgrade	3.39	6.74	4.74	8.97	3.88	27.71
8. Domestic Piping	13.55	0.52	1.64	3.71	0.68	20.09
9. Toilets - Students	0.03	5.74	1.39	3.23	7.43	17.83

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Bronx Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
E. System Replacements						
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.00	0.00	0.00	0.14	0.00	0.14
12. Paved Area - Blacktop	0.31	0.03	0.84	0.18	0.14	1.51
13. Paved Area - Concrete	1.64	1.28	4.83	4.42	7.26	19.44
14. Fencing	0.00	0.00	0.00	0.00	0.00	0.00
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	1.26	1.26
17. Auditorium Upgrade	2.46	0.36	0.23	1.85	0.06	4.95
18. Gymnasium Upgrade	3.56	0.43	0.33	2.22	1.70	8.25
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.09	0.03	0.04	0.32	3.21	3.69
<hr/>						
<i>I. State of Good Repair Yearly Totals:</i>	277.73	189.30	234.49	288.19	324.77	
					<b><i>I. State of Good Repair Total:</i></b>	<b>1,314.47</b>
<b>II. System Expansion</b>						
A. New Construction-Additional Capacity						
1. New Schools	0.43	0.10	0.16	5.62	97.92	104.22
2. Building Additions	1.26	59.44	146.29	70.10	8.60	285.70
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	0.07	0.04	0.04	0.00	0.01	0.16
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
9. 3-K Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	8.39	28.41	36.80
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.70	1.46	1.19	0.77	4.98	9.11

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Bronx Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>II. System Expansion</b>						
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	0.38	4.30	0.13	2.90	16.51	24.21
F. Replacements						
1. Replacements - New	0.00	0.00	0.00	0.00	0.00	0.00
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Lease	23.18	3.25	2.05	1.15	0.10	29.75
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<i>II. System Expansion Yearly Totals:</i>						
	26.03	68.60	149.86	88.93	156.54	
						<b>II. System Expansion Total: 489.95</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions / Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrade	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
<i>III. Educational Enhancements Yearly Totals:</i>						
	0.00	0.00	0.00	0.00	0.00	
						<b>III. Educational Enhancements Total: 0.00</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	1.14	0.00	1.11	0.04	0.01	2.30
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
<i>IV. Safety and Security Yearly Totals:</i>						
	1.14	0.00	1.11	0.04	0.01	
						<b>IV. Safety and Security Total: 2.30</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Borough of Bronx Plan Summary  
(in millions)**

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
<i>V. Ancillary Facilities Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>V. Ancillary Facilities Total: 0.00</b>
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	2.11	4.95	5.62	12.51	7.33	32.51
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>	2.11	4.95	5.62	12.51	7.33	
						<b>VI. Emergency, Unspecified and Misc. Total: 32.51</b>
<b>Yearly Totals for Bronx</b>	307.00	262.84	391.08	389.67	488.64	
						<b>Bronx Grand Total: \$1,839.23</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
Borough of Bronx  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	08	DSF0000798233	P.S. 14 ADDITION	344	Feb-15	Jul-16	Sep-18	66.16	0.18	63.92	2.06
*	10	DSF0000798175	P.S. 46 ADDITION	500	Feb-15	Dec-16	Jun-19	120.08	0.07	98.36	21.66
*	10	DSF0000798177	P.S. 33 ANNEX	388	Aug-17	Feb-19	Aug-21	61.99	0.02	49.15	12.82
*	10	DSF0000798176	P.S. 340 ANNEX	296	Aug-17	Mar-19	Sep-21	66.59	0.02	52.12	14.46
*	11	DSF0000798178	P.S. 97 ADDITION	548	Feb-17	Jun-18	Sep-21	82.12	0.11	64.26	17.75

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
Borough of Bronx  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	07	DSF0000800054 PRE-K CENTER @ 105 WILLIS AVENUE	90	Jun-14	Dec-14	Jul-15	7.95	0.00	7.95	0.00
* L	07	DSF0000800055 PRE-K CENTER @ 535 UNION AVENUE	180	Jun-14	Dec-14	Jul-15	11.83	0.00	11.83	0.00
* L	09	DSF0000801087 PRE-K CENTER @ 1434 OGDEN AVENUE	90	Oct-14	Mar-15	Aug-15	9.33	0.00	9.33	0.00
* L	10	DSF0000821711 PRE-K CENTER @ 3560 WEBSTER AVENUE	90	Dec-14	Sep-15	Sep-16	7.20	0.00	7.20	0.00
* L	10	DSF0000821828 PRE-K CENTER @ 5500 BROADWAY	54	Apr-15	Feb-16	Sep-16	5.55	0.00	5.55	0.00
* L	10	DSF0000821875 PRE-K CENTER @ 2490-2500 WEBSTER AVENUE	198	Apr-15	Feb-16	Sep-17	15.24	0.00	15.24	0.00
* L	10	DSF0000821874 PRE-K CENTER @ 3605 SEDGWICK AVENUE	36	Apr-15	Dec-15	Sep-16	4.84	0.00	4.84	0.00
* L	10	DSF0000822030 PRE-K CENTER @ 2510 MARION AVENUE	234	May-15	Jul-15	Sep-15	0.21	0.00	0.21	0.00
* L	10	DSF0000822032 PRE-K CENTER @ 2510 MARION AVENUE	36	May-15	Mar-16	Sep-16	13.44	0.00	13.44	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**3-K Initiative Projects**  
**Borough of Bronx**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	12	DSF0000891031 3K CENTER @ 1939 WEST FARMS ROAD	105	Nov-18	Jun-19	Aug-20	8.66	0.00	8.66	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Class Size Reduction Projects**  
**Borough of Bronx**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	11	DSF0000821591	P.S. 19 ADDITION	400	May-16	Jun-17	Jul-20	70.70	0.00	58.69	12.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Replacement Projects  
Borough of Bronx  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	10	DSF0000775874 JEROME PARK EDUCATIONAL BUILDING	Replacement	Sep-13	Mar-15	May-17	20.21	0.49	19.67	0.05
* L	78X	DSF0000800056 SOUTHERN BOULEVARD COMMUNITY CAMPUS	Replacement	Sep-14	Jul-15	Jul-16	10.01	0.00	10.01	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
07	Bronx	X001		<b>P.S. 1</b>				
					DSF0000799648	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	114,424
			X001		DSF0000793624	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
							<b>P.S. 1 Total:</b>	\$146,083
07	Bronx	X005		<b>P.S. 5</b>				
			X005		DSF0000793698	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	33,786
						<i>Other</i>		
			X005		DSF0000800167	New/Retrofit Telephone/Intercom Systems	2015	194,696
			X005		DSF0000822046	New/Retrofit Telephone/Intercom Systems	2015	194,696
							<b>P.S. 5 Total:</b>	\$423,178
07	Bronx	X018		<b>P.S. 18</b>				
					DSF0000912508	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	26,186
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
					DSF0000891034	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	925,347
					DSF0000817054	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	131,804

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							<b>P.S. 18 Total:</b>	\$1,083,337
07	Bronx	X025		<b>P.S. 25</b>				
					DSF0000794002	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	841,928
			X025		DSF0000775658	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	813,135
			X025		DSF0000817177	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2017	8,225,143
			X025		DSF0000891059	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			X025		DSF0000823600	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	952,104
			X025		DSF0000817176	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2017	1,282,368

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
					DSF0000817178	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	160,410
						FIXTURES:STUDENT:Toilet		
					DSF0000843682	<b>State of Good Repair - System Replacements - Windows</b>	2017	3,902,736
						<b>Other</b>		
			X025		DSF0000800206	Classroom Connectivity	2015	25,575
			X025		DSF0000822069	New/Retrofit Telephone/Intercom Systems	2015	216,684
							<b>P.S. 25 Total:</b>	<b>\$16,612,583</b>
07	Bronx	X027		<b>P.S. 277</b>				
					DSF0000883791	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	4,393,369
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000794046	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	896,226
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000883793	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,032,555

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
					DSF0000883792	<b>State of Good Repair - System Replacements - Roofs</b>	2019	2,846,079
						EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing		
		X277			DSF0000794052	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	107,792
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
		X277			DSF0000817223	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	278,678
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			X277		DSF0000800207	Classroom Connectivity	2015	38,725
							<b>P.S. 277 Total:</b>	<b>\$9,593,424</b>
07	Bronx	X029		<b>P.S. 29</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X029		DSF0000866287	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,461,111
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			X029		DSF0000861189	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	1,944,944
						EXTERIOR:EXTERIOR WALLS		
			X029		DSF0000861188	<b>State of Good Repair - System Replacements - Parapets</b>	2018	517,436
						EXTERIOR:COPING		
			X029		DSF0000839245	<b>State of Good Repair - System Replacements - Roofs</b>	2018	5,263,004
						<b>Other</b>		
			X029		DSF0000800177	New/Retrofit Telephone/Intercom Systems	2015	227,012
			X029		DSF0000800208	Classroom Connectivity	2015	16,230
			X029		DSF0000822047	New/Retrofit Telephone/Intercom Systems	2015	227,012
			X029		DSF0000889508	IP Surveillance Camera Installation	2019	39,175
						<b>P.S. 29 Total:</b>		\$9,695,924
07	Bronx	X030		<b>P.S. 30</b>				
			X030		DSF0000794103	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000799845	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	197,278
						<b>P.S. 30 Total:</b>		\$228,958
07	Bronx	X040		<b>P.S. 220</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X179		DSF0000800210	Classroom Connectivity	2015	417,700
							<b>P.S. 220 Total:</b>	<b>\$417,700</b>
07	Bronx	X043		<b>P.S. 43</b>				
			X043		DSF0000861379	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,419,650
			X043		DSF0000817455	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	3,016,235
					DSF0000794276	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,272,704
			X043		DSF0000861382	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS	2018	9,839,954
			X043		DSF0000861387	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2018	1,067,354



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Drinking Fountain FIXTURES:Student:Sink And Fountain Combo Unit DSF0000889571 <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	21,255
			X043		DSF0000861385	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	3,711,961
			X043		DSF0000839445	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	8,762,580
			X043		DSF0000891060	HEATING PLANT:Boiler System <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			X043		DSF0000866211	<b>Other</b> Classroom Connectivity	2017	40,040
							<b>P.S. 43 Total:</b>	<b>\$29,344,233</b>
07	Bronx	X049		<b>P.S. 49</b>	DSF0000890636	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,958

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000817585	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	162,759
			X049		DSF0000866212	<b>Other</b> Classroom Connectivity	2017	40,040
			X049		DSF0000889192	New/Retrofit Telephone/Intercom Systems	2018	257,699
							<b>P.S. 49 Total:</b>	<b>\$462,456</b>
07	Bronx	X065		<b>P.S. 65</b>				
			X065		DSF0000888901	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	80,873
					DSF0000798468	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	514,931
					DSF0000866981	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	4,005
			X065		DSF0000866140	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000907260	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	5,220,086
					DSF0000823658	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	127,663
						<b>Other</b>		
			X065		DSF0000800186	New/Retrofit Telephone/Intercom Systems	2015	188,079
			X065		DSF0000800220	Classroom Connectivity	2015	384,536
			X065		DSF0000822049	New/Retrofit Telephone/Intercom Systems	2015	188,079
							<b>P.S. 65 Total:</b>	<b>\$6,785,942</b>
07	Bronx	X139		<b>J.H.S. 222</b>				
					DSF0000796006	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,471,641
					DSF0000819196	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	308,282

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X224	DSF0000866074		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	429,587
						<b>Other</b>		
			X224	DSF0000800240		Classroom Connectivity	2015	427,685
			X224	DSF0000867091		New/Retrofit Telephone/Intercom Systems	2018	321,790
				DSF0000867073		IP Surveillance Camera Installation	2018	429,633
							<b>J.H.S. 222 Total:</b>	<b>\$3,388,618</b>
07	Bronx	X149		<b>J.H.S. 149</b>				
				DSF0000775797		<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2015	2,458,045
						CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE LAB:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE LAB SCIENCE PREP ROOM		
				DSF0000912326		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	52,763
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
				DSF0000798288		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,323,714
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000863244	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2019	1,994,981
			X221		DSF0000885886	INTERIOR:GYMNASIUM:Floor Finish <b>State of Good Repair - System Replacements - Roofs</b>	2019	2,601,767
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			X221		DSF0000865937	New/Retrofit Telephone/Intercom Systems	2017	246,874
							<b>J.H.S. 149 Total:</b>	<b>\$8,678,144</b>
07	Bronx	X151		<b>I.S. 151</b>				
			X151		DSF0000865721	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	3,013,971
			X151		DSF0000843885	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	97,794
						Technology		
			X031		DSF0000843920	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	97,794
						Technology		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X151	DSF0000845600		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	47,000
			X031	DSF0000865717		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	95,000
				DSF0000796234		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	2,453,465
				DSF0000889021		<b>State of Good Repair - System Replacements - Containerization</b>	2019	191,111
				DSF0000819442		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	110,605
						<b>Other</b>		
			X031	DSF0000800192		New/Retrofit Telephone/Intercom Systems	2015	294,416
			X031	DSF0000800244		Classroom Connectivity	2015	477,274
			X151	DSF0000822048		New/Retrofit Telephone/Intercom Systems	2015	295,132

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 151 Total:</b>	\$7,173,562
07	Bronx	X154		<b>P.S. 154</b>				
					DSF0000796295	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,281,504
			X154		DSF0000819504	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			X154		DSF0000800246	<b>Other</b> Classroom Connectivity	2015	420,089
							<b>P.S. 154 Total:</b>	\$1,846,379
07	Bronx	X156		<b>P.S. 156</b>				
			X359		DSF0000912484	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
					DSF0000796339	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,384,159

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000886019	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	6,040,576
					DSF0000886018	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING	2019	3,662,394
					DSF0000886017	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,450,683
			X359		DSF0000819545	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			X359		DSF0000866224	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	238,724
							<b>P.S. 156 Total:</b>	<b>\$16,126,536</b>
07	Bronx	X157		<b>P.S. 157</b>				
					DSF0000912222	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EXIT LIGHT	2019	49,258



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000796354	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,325,491
					DSF0000868308	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	466,925
			X157		DSF0000863394	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	5,911,027
			X157		DSF0000866075	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	107,397
					DSF0000888962	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	222,548
							<b>P.S. 157 Total:</b>	<b>\$8,082,646</b>
07	Bronx	X161		<b>P.S. 161</b>				
					DSF0000889383	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	15,566,420
					DSF0000796418	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,604,778

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000908908	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	4,964,288
						FIRE ALARM SYSTEM		
					DSF0000799856	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	217,023
			X161		DSF0000799873	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
							<b>P.S. 161 Total:</b>	\$22,384,168
07	Bronx	X162		<b>I.S. 162</b>				
			X162		DSF0000823627	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,902,274
			X500		DSF0000908922	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2019	152,000
						CONVEYING:Elevator INTERCOM SYSTEM:Elevator		
					DSF0000866309	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2018	181,166
						CAFETERIA:Lighting:Lighting Fixture - Fluorescent INTERIOR:CAFETERIA:Floor Finish INTERIOR:CAFETERIA:Sliding-folding Partition		
					DSF0000863476	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2018	157,222
						GYMNASIUM:Lighting:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:GYMNASIUM:Floor Finish INTERIOR:GYMNASIUM:Sliding-folding Partition		
			X162	DSF0000796441		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,630
						<b>Other</b>		
			X162	DSF0000800193		New/Retrofit Telephone/Intercom Systems	2015	313,446
			X162	DSF0000822040		New/Retrofit Telephone/Intercom Systems	2015	313,446
			X500	DSF0000889527		IP Surveillance Camera Installation	2019	39,779
							<b>I.S. 162 Total:</b>	<b>\$4,090,963</b>
07	Bronx	X183		<b>J.H.S. 203</b>				
			X551	DSF0000865855		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	95,000
			X551	DSF0000889298		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	60,000
			X168	DSF0000911878		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	105,000
				DSF0000886329		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,638,249

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
			X551	DSF0000889085		INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	842,163
					DSF0000886331	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,151,342
			X551	DSF0000886330		EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	5,172,729
			X168	DSF0000889067		EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
			X551	DSF0000889529		<b>Other</b> IP Surveillance Camera Installation	2019	39,693
							<b>J.H.S. 203 Total:</b>	<b>\$9,504,620</b>
07	Bronx	X184		<b>I.S. 184</b>				
					DSF0000800062	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	2,513,480
					DSF0000796696	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	2,246,722
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X296		DSF0000796702	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			X296		DSF0000886351	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2019	400,444
			X379		DSF0000889547	<b>Other</b> IP Surveillance Camera Installation	2019	40,163
							<b>I.S. 184 Total:</b>	<b>\$5,232,468</b>
07	Bronx	X478		<b>P.S. 65 GYM ANNEX</b>				
			X065		DSF0000889566	<b>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</b>	2019	10,871,735
							<b>P.S. 65 GYM ANNEX Total:</b>	<b>\$10,871,735</b>
07	Bronx	X855		<b>P.S. 30 ANNEX</b>				
			X309		DSF0000866251	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	82,419
							<b>P.S. 30 ANNEX Total:</b>	<b>\$82,419</b>
08	Bronx	X014		<b>P.S. 14</b>				
					DSF0000883580	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	2,262,496

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			X014		DSF0000883578	<b>State of Good Repair - System Replacements - Parapets</b>	2019	3,476,986
						EXTERIOR:PARAPETS		
			X014		DSF0000906449	<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,110,796
						EXTERIOR:ROOF:Roofing		
			X014		DSF0000883579	<b>State of Good Repair - System Replacements - Windows</b>	2019	3,974,015
						EXTERIOR:WINDOWS		
							<b>P.S. 14 Total:</b>	\$12,824,293
08	Bronx	X036		<b>P.S. 36</b>				
					DSF0000822097	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	8,845,786
					DSF0000799904	<b>Safety and Security - Safety and Security - Safety Systems</b>	2015	174,349
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
					DSF0000799905	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	2,212,314
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000906787	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	8,328
					DSF0000748526	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	10,491,472
						EXTERIOR:EXTERIOR WALLS		
					DSF0000794184	<b>State of Good Repair - System Replacements - Parapets</b>	2015	1,784,478
						EXTERIOR:PARAPETS		
					DSF0000794183	<b>State of Good Repair - System Replacements - Roofs</b>	2015	1,414,941
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
					DSF0000799903	<b>State of Good Repair - System Replacements - Windows</b>	2015	986,681
						EXTERIOR:WINDOWS		
<b>P.S. 36 Total:</b>								\$25,918,349
08	Bronx	X048		<b>P.S. 48</b>				
					DSF0000799893	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2016	11,428,891
					DSF0000771654	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	1,082,617
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000861477	<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,075,054

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<i>Other</i>		
			X048		DSF0000800213	Classroom Connectivity	2015	366,628
							<b>P.S. 48 Total:</b>	\$14,953,190
08	Bronx	X052		<b>I.S. 302</b>				
					DSF0000821878	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	52,993
			X302		DSF0000843869	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	59,982
			X302		DSF0000861535	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	3,252,928
					DSF0000799720	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	146,331
			X302		DSF0000800182	<i>Other</i> New/Retrofit Telephone/Intercom Systems	2015	277,311



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X302	DSF0000800214		Classroom Connectivity	2015	241,384
			X302	DSF0000822056		New/Retrofit Telephone/Intercom Systems	2015	277,311
			X302	DSF0000889511		IP Surveillance Camera Installation	2019	39,376
							<b>I.S. 302 Total:</b>	<b>\$4,347,616</b>
08	Bronx	X060		<b>P.S. 333</b>				
				DSF0000888779		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	209,779
			X333	DSF0000866139		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
						<b>Other</b>		
			X333	DSF0000800217		Classroom Connectivity	2015	31,856
			X333	DSF0000866245		New/Retrofit Telephone/Intercom Systems	2017	209,203
							<b>P.S. 333 Total:</b>	<b>\$528,528</b>
08	Bronx	X062		<b>P.S. 62</b>				
				DSF0000907203		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	96,280
			X062	DSF0000794625		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	8,985,864
			X062	DSF0000794627		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			X062	DSF0000821924		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	1,572,367

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000817814	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	156,318
			X062		DSF0000800185	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	176,206
			X062		DSF0000800218	Classroom Connectivity	2015	78,952
							<b>P.S. 62 Total:</b>	\$11,097,667
08	Bronx	X069		<b>P.S. 69</b>				
			X069		DSF0000866215	<b>Other</b> Classroom Connectivity	2017	22,121
							<b>P.S. 69 Total:</b>	\$22,121
08	Bronx	X071		<b>P.S. 71</b>				
			X071		DSF0000775950	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	703,370
					DSF0000799656	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	144,115

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X071	DSF0000754500		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	6,370,305
			X071	DSF0000772080		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	1,550,576
			X071	DSF0000772079		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	329,660
			X071	DSF0000866067		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 71 Total:</b>	<b>\$9,312,818</b>
08	Bronx	X072		<b>P.S. 72</b>				
				DSF0000912240		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	67,172
				DSF0000794813		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	699,923
				DSF0000868248		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	144,285
				DSF0000818005		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	102,760

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X072		DSF0000867093	New/Retrofit Telephone/Intercom Systems	2018	245,791
							<b>P.S. 72 Total:</b>	\$1,259,931
08	Bronx	X074		<b>I.S. 201</b>				
			X424		DSF0000889372	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	138,374
					DSF0000799658	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	166,252
					DSF0000861941	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	91,926
					DSF0000839997	<i>State of Good Repair - System Replacements - Paved Area - Concrete</i>	2017	633,104
			X424		DSF0000866065	SITE:RETAINING WALLS <i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>I.S. 201 Total:</b>	\$1,244,448
08	Bronx	X075		<b>P.S. 75</b>				
			X075		DSF0000821946	<i>State of Good Repair - Building Upgrade - Interior Spaces</i> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	282,054

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000794875	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,484,535
					DSF0000868249	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	185,446
			X075		DSF0000866270	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	228,972
							<b>P.S. 75 Total:</b>	\$2,181,007
08	Bronx	X093		<b>P.S. 93</b>				
					DSF0000798472	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	911,907
					DSF0000862312	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM SERVICE SWITCH SWITCHBOARD	2018	10,550
			X093		DSF0000889032	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	491,665

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			X093		DSF0000889033	<b>State of Good Repair - System Replacements - Parapets</b>	2018	926,834
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X093		DSF0000884976	<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,450,257
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
					DSF0000777222	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2016	1,774,351
						<b>Other</b>		
			X093		DSF0000800226	Classroom Connectivity	2015	37,041
							<b>P.S. 93 Total:</b>	<b>\$6,602,605</b>
08	Bronx	X100		<b>P.S. 100</b>				
					DSF0000772616	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,396,480
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:LOUVER		
					DSF0000912188	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
					DSF0000772615	<b>State of Good Repair - System Replacements - Parapets</b>	2015	2,725,616
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000772614	<b>State of Good Repair - System Replacements - Roofs</b>	2015	2,951,342
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			X100		DSF0000865925	Classroom Connectivity	2017	235,365
							<b>P.S. 100 Total:</b>	<b>\$8,387,738</b>
08	Bronx	X101		<b>I.S. 101</b>				
					DSF0000798384	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	6,196,386
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
					DSF0000795357	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,407,255
						CLIMATE CONTROL SYSTEM		
					DSF0000818533	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,725,719
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000772648	<b>State of Good Repair - System Replacements - Domestic Piping</b> Fire System Sprinklers SPRINKLERS, STANDPIPE, FIRE SYSTEM:FIRE BOOSTER PUMP ASSEMBLY SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING	2015	1,491,896
					DSF0000907906	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,791,035
			X101		DSF0000885074	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	6,274,571
			X101		DSF0000866069	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
			X101		DSF0000885078	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal	2019	138,158
			X101		DSF0000822070	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	405,879
							<b>I.S. 101 Total:</b>	<b>\$20,583,628</b>
08	Bronx	X107		<b>P.S. 107</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X107	DSF0000912175		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	69,990
				DSF0000799665		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	171,270
			X107	DSF0000866145		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			X107	DSF0000795476		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	92,554
			X107	DSF0000818658		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			X107	DSF0000800187		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	154,637
			X107	DSF0000843788		Classroom Connectivity	2016	320,401
							<b>P.S. 107 Total:</b>	<b>\$1,036,542</b>
08	Bronx	X119		<b>P.S. 119</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X119	DSF0000798497		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	6,477,760
			X119	DSF0000795691		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2019	1,929,581
			X119	DSF0000862747		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	706,647
				DSF0000795693		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	549,509
			X119	DSF0000912169		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	3,075,636
				DSF0000868324		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	262,127
			X119	DSF0000891061		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			X119	DSF0000885410		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	408,940
							<b>P.S. 119 Total:</b>	<b>\$13,602,700</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
08	Bronx	X120		<b>I.S. 301</b>				
					DSF0000821766	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	425,676
			X301		DSF0000821752	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	248,937
			X188		DSF0000843871	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	28,443
			X188		DSF0000843880	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	108,432
			X301		DSF0000844144	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	52,350
					DSF0000866993	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	3,650
					DSF0000908259	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY	2019	5,383,117

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
			X301	DSF0000795714		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	64,383
			X188	DSF0000908258		<b>State of Good Repair - System Replacements - Parapets</b>	2019	3,592,035
						EXTERIOR:PARAPETS		
			X188	DSF0000908257		<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,700,001
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
							<b>I.S. 301 Total:</b>	<b>\$13,607,024</b>
08	Bronx	X123		<b>I.S. 123</b>				
				DSF0000843910		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,481,616
				DSF0000868256		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	546,873
			X123	DSF0000795775		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
				DSF0000818959		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	308,282
						<b>Other</b>		
			X123	DSF0000800236		Classroom Connectivity	2015	394,991
			X123	DSF0000889518		IP Surveillance Camera Installation	2019	39,846
							<b>I.S. 123 Total:</b>	<b>\$3,803,288</b>
08	Bronx	X125		<b>I.S. 125</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X562		DSF0000890604	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	7,964,455
			X562		DSF0000885500	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	1,411,693
					DSF0000840918	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	2,918,241
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent		
					DSF0000912223	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	297,706
					DSF0000818977	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	115,096
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			X125		DSF0000889519	IP Surveillance Camera Installation	2019	45,245
							<b>I.S. 125 Total:</b>	<b>\$12,752,436</b>
08	Bronx	X130		<b>P.S. 130</b>				
					DSF0000819052	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	433,536
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000795870	INTERIOR:STRUCTURAL:VAULTS-BUNKERS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	942,386
					DSF0000819055	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	707,514
			X130		DSF0000795876	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,777
					DSF0000821697	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	307,617
			X130		DSF0000821687	<b>State of Good Repair - System Replacements - Roofs</b>	2016	3,618,360
						<b>Other</b>		
			X130		DSF0000866218	Classroom Connectivity	2017	22,121
			X130		DSF0000866244	New/Retrofit Telephone/Intercom Systems	2017	192,906
							<b>P.S. 130 Total:</b>	<b>\$6,275,217</b>
08	Bronx	X131		<b>I.S. 131</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X131	DSF0000843873		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	129,433
			X131	DSF0000845599		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	55,000
			X448	DSF0000845601		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Science Lab Upgrades	2017	374,662
			X131	DSF0000865780		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	183,095
			X448	DSF0000889318		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	253,436
				DSF0000795891		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	1,137,557
				DSF0000819072		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	195,561

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000795893	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2017	831,186
			X131		DSF0000799872	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	123,840
			X131		DSF0000819076	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	101,351
							<b>I.S. 131 Total:</b>	<b>\$3,385,121</b>
08	Bronx	X138		<b>P.S. 138</b>				
			X138		DSF0000885702	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:Theater Lighting System:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating	2019	2,331,703
			X138		DSF0000889523	<b>Other</b> IP Surveillance Camera Installation	2019	38,840
							<b>P.S. 138 Total:</b>	<b>\$2,370,543</b>



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
08	Bronx	X140		<b>P.S. 140</b>				
			X140		DSF0000796028	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
			X140		DSF0000888814	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	93,079
							<b>P.S. 140 Total:</b>	<b>\$124,738</b>
08	Bronx	X146		<b>P.S. 146</b>				
			X146		DSF0000821751	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2015	79,660
			X146		DSF0000843883	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2016	199,144
			X146		DSF0000865718	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2017	177,076
					DSF0000798354	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	971,772

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<i>Other</i>		
			X146		DSF0000865928	Classroom Connectivity	2017	167,569
							<b>P.S. 146 Total:</b>	<b>\$1,595,221</b>
08	Bronx	X152		<b>P.S. 152</b>				
			X152		DSF0000885943	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2019	400,444
			X152		DSF0000796259	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	4,958,461
			X152		DSF0000800245	<i>Other</i> Classroom Connectivity	2015	392,853
							<b>P.S. 152 Total:</b>	<b>\$5,751,758</b>
08	Bronx	X174		<b>I.S. 174</b>				
			X282		DSF0000823626	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	3,045,832
					DSF0000886222	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	96,138

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000841667	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,816,235
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent		
					DSF0000821617	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
					DSF0000886225	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	2,274,060
						EXTERIOR:EXTERIOR WALLS		
					DSF0000773838	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	56,465
					DSF0000886224	<b>State of Good Repair - System Replacements - Parapets</b>	2018	2,420,324
						EXTERIOR:PARAPETS		
					DSF0000819760	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2017	851,047
						SITE:PAVING - STUDENT NON-USE:Concrete SITE:PAVING - STUDENT USE:Concrete SITE:SIDEWALKS:DOT Sidewalk		
					DSF0000886223	<b>State of Good Repair - System Replacements - Roofs</b>	2018	4,720,745
						EXTERIOR:ROOF:Roofing		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X282	DSF0000796569		EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	93,571
			X282	DSF0000886228		FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
			X375	DSF0000799972		<b>Other</b> IP Surveillance Camera Installation	2015	340,146
							<b>I.S. 174 Total:</b>	<b>\$16,594,073</b>
08	Bronx	X182		<b>P.S. 182</b>				
				DSF0000799669		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,142,470
				DSF0000889317		<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2019	10,601,227
				DSF0000912363		<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	2,058,696

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000867004	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	6,000
					DSF0000886315	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	2,673,980
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
					DSF0000886314	<i>State of Good Repair - System Replacements - Roofs</i>	2019	813,753
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
							<b>P.S. 182 Total:</b>	\$17,296,126
08	Bronx	X192		<b>I.S. 192</b>				
					DSF0000868262	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	201,099
			X371		DSF0000886370	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	2,244,666
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			X371		DSF0000796723	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
					DSF0000819904	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	390,491
			X371		DSF0000866078	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X366	DSF0000800195		New/Retrofit Telephone/Intercom Systems	2015	236,532
			X371	DSF0000865938		Classroom Connectivity	2017	250,311
							<b>I.S. 192 Total:</b>	<b>\$3,507,508</b>
08	Bronx	X848		<b>P.S. 48 AX (HNTS PNT ECC1)</b>				
				DSF0000797422		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,105,254
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000867011		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	21,000
				DSF0000774687		<b>State of Good Repair - System Replacements - Parapets</b>	2015	742,785
						EXTERIOR:PARAPETS		
				DSF0000798241		<b>State of Good Repair - System Replacements - Roofs</b>	2015	413,376
						EXTERIOR:ROOFING:Roofing		
				DSF0000774688		<b>State of Good Repair - System Replacements - Windows</b>	2015	268,231
						EXTERIOR:WINDOWS		
							<b>P.S. 48 AX (HNTS PNT ECC1) Total:</b>	<b>\$2,550,646</b>
09	Bronx	X002		<b>MORRISANIA SEC ED COMPLEX</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X250		DSF0000793643	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,270,732
					DSF0000798315	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	5,553,304
					DSF0000798318	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	2,319,900
					SCA0000025434	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,085,746
			X250		DSF0000793644	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	55,332
			X250		DSF0000793641	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	1,605,741
			X250		DSF0000793640	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	2,032,665

**MORRISANIA SEC ED COMPLEX Total: \$14,923,420**

09 Bronx X004 P.S. 4

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000843981	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	168,918
					DSF0000793675	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,289,468
					DSF0000816881	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
						<b>Other</b>		
			X004		DSF0000866246	New/Retrofit Telephone/Intercom Systems	2017	227,223
			X004		DSF0000889505	IP Surveillance Camera Installation	2019	39,980
						<b>P.S. 4 Total:</b>		<b>\$1,795,312</b>
09	Bronx	X011		<b>P.S. 11</b>				
			X011		DSF0000838987	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:PAVING:DOT Sidewalk SITE:PAVING:Student Use:Concrete SITE:RETAINING WALLS SITE:STAIRS/RAMPS: EXTERIOR	2018	2,949,547
			X011		DSF0000866058	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 11 Total:</b>	<b>\$3,102,276</b>
09	Bronx	X022		<b>I.S. 22</b>				
					DSF0000821666	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	467,933
			X323		DSF0000821769	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	92,308
						Technology		
			X323		DSF0000845598	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	118,000
						Technology		
			X022		DSF0000866752	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	108,500
						Technology		
			X323		DSF0000888900	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2018	45,000
						Technology		
					DSF0000817119	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	1,070,139
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X022	DSF0000771219		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	2,231,229
				DSF0000817128		FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2015	142,633
			X022	DSF0000800175		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	275,333
				DSF0000867070		IP Surveillance Camera Installation	2018	403,075
							<b>I.S. 22 Total:</b>	<b>\$4,954,150</b>
09	Bronx	X028		<b>P.S. 28</b>				
				DSF0000912421		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT EXIT/EMERGENCY LIGHT	2019	63,423
				DSF0000748409		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	1,391,653

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X028		DSF0000800308	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	1,371,094
					DSF0000868245	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	403,903
					DSF0000817236	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	201,710
							<b>P.S. 28 Total:</b>	<b>\$3,431,783</b>
09	Bronx	X035		<b>P.S. 35</b>				
					DSF0000771439	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1,780,057
					DSF0000794162	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	620,033
					DSF0000771443	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY	2015	1,737,111

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X035		DSF0000794168	EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	114,299
					DSF0000817344	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	124,842
			X035		DSF0000800178	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	126,725
							<b>P.S. 35 Total:</b>	<b>\$4,503,067</b>
09	Bronx	X042		<b>P.S. 42</b>				
			X042		DSF0000884002	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2019	1,675,814
			X042		DSF0000884006	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	2,845,450

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X042		DSF0000884005	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2019	285,085
			X042		DSF0000884004	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,689,720
							<b>P.S. 42 Total:</b>	\$6,496,069
09	Bronx	X053		<b>P.S. 53</b>				
					DSF0000884191	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	4,109,789
			X053		DSF0000884190	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	4,891,456
							<b>P.S. 53 Total:</b>	\$9,001,245
09	Bronx	X055		<b>P.S. 55</b>				
			X055		DSF0000821770	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	92,308

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X055	DSF0000845607		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	177,582
				DSF0000794496		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,314,807
			X055	DSF0000884221		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly	2019	78,997
			X055	DSF0000839646		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2017	4,955,273
			X055	DSF0000866137		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X055	DSF0000911804		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	193,387
			X055	DSF0000839644		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	3,100,641
			X055	DSF0000839643		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	2,753,694
			X055	DSF0000817683		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	188,792
			X055	DSF0000889642		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			X055	DSF0000839645		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2017	9,552,076
			X055	DSF0000800215		<b>Other</b> Classroom Connectivity	2015	373,323
							<b>P.S. 55 Total:</b>	<b>\$23,073,362</b>
09	Bronx	X058		<b>P.S. 58</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799655	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	222,122
					DSF0000817736	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Toilet	2015	195,690
							<b>P.S. 58 Total:</b>	\$417,812
09	Bronx	X063		<b>P.S. 63</b>				
			X063		DSF0000861725	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2018	1,320,522
					DSF0000817833	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Toilet	2015	165,383
			X063		DSF0000866214	<i>Other</i> Classroom Connectivity	2017	40,040
							<b>P.S. 63 Total:</b>	\$1,525,945
09	Bronx	X064		<b>P.S. 64</b>				
					DSF0000794657	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,083,462



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<i>Other</i>		
			X064	DSF0000800219		Classroom Connectivity	2015	39,378
			X294	DSF0000867127		New/Retrofit Telephone/Intercom Systems	2018	270,841
							<b>P.S. 64 Total:</b>	\$1,393,681
09	Bronx	X070		<b>P.S. 70</b>				
			X070	DSF0000794783		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	6,562,639
			X070	DSF0000817970		<i>State of Good Repair - System Replacements - Parapets</i>	2017	1,418,607
			X070	DSF0000821923		<i>State of Good Repair - System Replacements - Roofs</i>	2017	640,586
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 70 Total:</b>	\$8,621,832
09	Bronx	X073		<b>P.S. 73</b>				
				DSF0000622598		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	1,900,604
						INTERIOR:Structural:Foundation Walls		
				DSF0000799657		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	225,037
				DSF0000884577		<i>State of Good Repair - System Replacements - Containerization</i>	2019	191,111
						SITE:CONTAINERIZATION		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000709411	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	5,159,509
					DSF0000727828	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	1,997,706
			X073		DSF0000794842	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	73,822
							<b>P.S. 73 Total:</b>	<b>\$9,547,789</b>
09	Bronx	X082		<b>I.S. 232</b>				
			X232		DSF0000818199	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	4,422,320
					DSF0000798432	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,213,687
			X232		DSF0000884741	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	209,616

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X232	SCA0000030993		<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2017	5,416,498
			X232	DSF0000821948		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	565,521
			X232	DSF0000884745		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	15,847,175
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
				DSF0000799851		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	103,825
			X232	DSF0000889084		<b>State of Good Repair - System Replacements - Parapets</b>	2019	970,265
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X232	DSF0000862088		<b>State of Good Repair - System Replacements - Roofs</b>	2019	2,529,481
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			X232	DSF0000795013		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	72,773
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X232	DSF0000821949		<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2017	611,881
			X232	DSF0000889545		<b>Other</b> IP Surveillance Camera Installation	2019	43,231
							<b>I.S. 232 Total:</b>	\$32,006,273
09	Bronx	X090		<b>P.S. 90</b>				
				DSF0000795167		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,082,568
				DSF0000818364		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	4,682,048
				DSF0000818363		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,514,382
			X443	DSF0000800225		<b>Other</b> Classroom Connectivity	2015	272,547
			X443	DSF0000867095		New/Retrofit Telephone/Intercom Systems	2018	269,560
							<b>P.S. 90 Total:</b>	\$7,821,105

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X104		<b>P.S. 199</b>				
			X199		DSF0000865726	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	2,733,374
					DSF0000885136	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	982,874
			X199		DSF0000800231	<i>Other</i> Classroom Connectivity	2015	18,221
							<b>P.S. 199 Total:</b>	<b>\$3,734,469</b>
09	Bronx	X109		<b>P.S. 109</b>				
					DSF0000728491	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	1,161,873
					DSF0000795501	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	26,129
					DSF0000795506	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:EXTERIOR WALLS	2017	3,282,707
			X109		DSF0000795508	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	38,488
					DSF0000799852	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	240,597

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000795505	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	160,028
					DSF0000795504	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	668,298
					DSF0000818691	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	138,796
			X109		DSF0000866070	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	305,460
			X109		DSF0000800189	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	148,281
							<b>P.S. 109 Total:</b>	<b>\$6,170,657</b>
09	Bronx	X110		<b>P.S. 110</b>				
					DSF0000866990	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	7,040
							<b>P.S. 110 Total:</b>	<b>\$7,040</b>
09	Bronx	X114		<b>P.S. 114</b>				
			X114		DSF0000798352	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	7,070,132

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X114		DSF0000795596	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	2,754,074
					DSF0000795598	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	717,193
			X114		DSF0000795601	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	38,086
					DSF0000818788	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2016	136,954
							<b>P.S. 114 Total:</b>	<b>\$10,716,439</b>
09	Bronx	X117		<b>I.S. 117</b>	DSF0000821888	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,632,687

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X568		DSF0000821890	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,052,708
					DSF0000818851	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Incandescent SCIENCE DEMO ROOM:POWER SUPPLY SCIENCE LAB SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Incandescent SCIENCE LAB:POWER SUPPLY SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2018	1,964,434
					DSF0000821908	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2018	980,368
			X117		DSF0000866316	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2018	519,444



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X117		DSF0000866071	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>I.S. 117 Total:</b>	\$6,302,370
09	Bronx	X126		<b>P.S. 126 (ECF)</b>				
					DSF0000795809	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,111,704
			X126		DSF0000795813	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			X126		DSF0000801046	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> HEATING PLANT:BOILER SYSTEM	2015	89,445
							<b>P.S. 126 (ECF) Total:</b>	\$1,232,829
09	Bronx	X132		<b>P.S. 132</b>				
			X132		DSF0000889373	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	226,331
					DSF0000795908	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,057,802

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X132	DSF0000819092		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			X132	DSF0000823621		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	53,166
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			X132	DSF0000866072		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			X132	DSF0000800237		Classroom Connectivity	2015	91,390
			X132	DSF0000889521		IP Surveillance Camera Installation	2019	39,577
							<b>P.S. 132 Total:</b>	<b>\$1,765,781</b>
09	Bronx	X145		<b>I.S. 145</b>				
			X145	DSF0000822085		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,402,297
			X145	DSF0000822686		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	3,059,409

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X325	DSF0000843881		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	97,794
			X145	DSF0000843882		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	197,200
			X328	DSF0000891083		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	102,313
			X328	DSF0000912246		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Interior Spaces	2019	177,973
			X594	DSF0000912247		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Interior Spaces	2019	249,067
				DSF0000843876		<b>Technology</b>	2017	401,647
				DSF0000843878		<b>Technology</b>	2017	467,086
				DSF0000912402		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL	2019	95,018

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EMERGENCY LIGHTING EXIT LIGHT		
					DSF0000796116	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,703,026
					DSF0000868260	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	958,729
			X145		DSF0000796122	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	72,271
			X145		DSF0000819319	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete SITE:PAVING - STUDENT USE:Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways	2017	1,165,768
							<b>I.S. 145 Total:</b>	\$11,149,598
09	Bronx	X147		<b>I.S. 339 (OLD 147)</b>				
					DSF0000844006	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,765,821
			X339		DSF0000844039	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING	2017	1,492,346

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXIT LIGHT		
					DSF0000796155	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,773,195
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000863201	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	117,009
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
					DSF0000773432	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	7,988,882
						EXTERIOR:EXTERIOR WALLS		
			X339		DSF0000798603	<b>State of Good Repair - System Replacements - Roofs</b>	2015	524,698
						EXTERIOR:ROOFING:Roofing		
			X313		DSF0000819357	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	166,780
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
					DSF0000776011	<b>State of Good Repair - System Replacements - Windows</b>	2015	2,708,680

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
EXTERIOR:WINDOWS								
<i>Other</i>								
			X339		DSF0000889526	IP Surveillance Camera Installation	2019	45,745
<b>I.S. 339 (OLD 147) Total:</b>								<b>\$17,583,156</b>
09	Bronx	X148		<b>I.S. 219 (OLD 148)</b>				
			X219		DSF0000823628	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,896,284
					DSF0000868307	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	319,837
					DSF0000796183	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	776,658
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
					DSF0000799855	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	184,639
<i>Other</i>								
					DSF0000868104	IP Surveillance Camera Installation	2019	388,438
<b>I.S. 219 (OLD 148) Total:</b>								<b>\$4,565,856</b>
09	Bronx	X163		<b>P.S. 163</b>				
					DSF0000798453	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	346,566

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<i>Other</i>		
			X163		DSF0000800247	Classroom Connectivity	2015	88,292
							<b>P.S. 163 Total:</b>	<b>\$434,858</b>
09	Bronx	X166		<b>I.S. 166</b>				
			X324		DSF0000776013	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	872,969
					DSF0000821579	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,936,878
					DSF0000773763	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2016	4,031,420
						INTERIOR:SCIENCE PREP ROOM:Fixed Equipment		
					DSF0000796472	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	2,157,172
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X324		DSF0000908946	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	166,980
						GAS SERVICE:Gas Meter Room Vent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Boiler System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube		
			X324	DSF0000865993		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	170,000
						<b>Other</b>		
			X324	DSF0000889528		IP Surveillance Camera Installation	2019	46,779
<b>I.S. 166 Total:</b>								\$10,382,198
09	Bronx	X170		<b>P.S. 170 (ECC)</b>				
				DSF0000889028		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	1,251,462
			X170	DSF0000863545		<b>State of Good Repair - System Replacements - Parapets</b>	2018	1,391,629
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X170	DSF0000863544		<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,418,560
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
			X170	DSF0000866219		Classroom Connectivity	2017	22,121
			X170	DSF0000867094		New/Retrofit Telephone/Intercom Systems	2018	158,611
<b>P.S. 170 (ECC) Total:</b>								\$4,242,383
09	Bronx	X171		<b>P.S. 4 ANNEX (P171 ECC)</b>				
			X004	DSF0000843691		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	182,145



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 4 ANNEX (P171 ECC) Total:</b>	\$182,145
09	Bronx	X172		<b>P.S. 11 ANNEX (P172 ECC)</b>				
				DSF0000773814		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	1,121,563
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						<b>Other</b>		
			X011	DSF0000867108		New/Retrofit Telephone/Intercom Systems	2018	166,786
							<b>P.S. 11 ANNEX (P172 ECC) Total:</b>	\$1,288,349
09	Bronx	X173		<b>P.S. 236</b>				
				DSF0000841659		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,919,238
						EXTERIOR:EXTERIOR SOFFITS		
						EXTERIOR:EXTERIOR WALLS		
			X236	DSF0000841657		<b>State of Good Repair - System Replacements - Parapets</b>	2017	336,648
						EXTERIOR:PARAPETS		
							<b>P.S. 236 Total:</b>	\$3,255,886
09	Bronx	X229		<b>P.S. 230/I.S. 229 (UDC)</b>				
			X229	DSF0000865776		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	3,490,362
				DSF0000799671		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	132,756

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000796822	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	2,204,666
					SCA0000027056	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System	2015	8,864,809
					SCA0000027593	<b>State of Good Repair - System Replacements - Domestic Piping</b> Fire System Sprinklers	2015	6,685,483
					DSF0000799351	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways	2015	704,976
						<b>Other</b>		
			X229		DSF0000865932	New/Retrofit Telephone/Intercom Systems	2017	391,504
			X274		DSF0000889530	IP Surveillance Camera Installation	2019	40,010
<b>P.S. 230/I.S. 229 (UDC) Total:</b>								\$22,514,566
09	Bronx	X235		<b>P.S./I.S. 218</b>				
					DSF0000844730	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	128,705
					DSF0000797776	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	54,359
			X218		DSF0000844167	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	49,655

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
					DSF0000823586	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,724
						<b>Other</b>		
			X218		DSF0000843787	Classroom Connectivity	2016	289,529
							<b>P.S./I.S. 218 Total:</b>	<b>\$591,972</b>
09	Bronx	X236		<b>P.S. 236 ANNEX (P173 ECC)</b>				
					DSF0000796839	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	199,615
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 236 ANNEX (P173 ECC) Total:</b>	<b>\$199,615</b>
09	Bronx	X338		<b>MORRIS HEIGHTS EDUCATIONAL COMPLEX</b>				
			X204		DSF0000889374	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	146,907
						<b>Other</b>		
			X204		DSF0000889532	IP Surveillance Camera Installation	2019	39,913
							<b>MORRIS HEIGHTS EDUCATIONAL COMPLEX Total:</b>	<b>\$186,820</b>
09	Bronx	X824		<b>P.S. 204</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000797370	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	233,475
			X695		DSF0000800264	<b>Other</b> Classroom Connectivity	2015	18,567
							<b>P.S. 204 Total:</b>	<b>\$252,042</b>
09	Bronx	X862		<b>P.S. 63 MINISCHOOL</b>				
			X177		DSF0000867019	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2018	149,336
							<b>P.S. 63 MINISCHOOL Total:</b>	<b>\$149,336</b>
09	Bronx	X980		<b>P.S. 204 ANNEX</b>				
					DSF0000867015	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,000
							<b>P.S. 204 ANNEX Total:</b>	<b>\$6,000</b>
10	Bronx	X003		<b>P.S. 3</b>				
					DSF0000911904	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	279,484
					DSF0000793656	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	4,976,667

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
					DSF0000816873	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2017	2,746,676
			X003		DSF0000866186	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK	2017	90,450
			X003		DSF0000793663	<b>State of Good Repair - System Replacements - Parapets</b>	2018	935,355
			X003		DSF0000816867	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2018	2,561,845
			X003		DSF0000816860	SITE:PAVING - STUDENT NON-USE:Concrete <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2018	777,218
							<b>P.S. 3 Total:</b>	\$12,367,695
10	Bronx	X007		<b>P.S. 7</b>				
					DSF0000799717	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	156,072
					DSF0000866973	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	6,461
			X007		DSF0000888929	<b>State of Good Repair - System Replacements - Roofs</b>	2018	81,327
							<b>P.S. 7 Total:</b>	\$243,860
10	Bronx	X008		<b>P.S. 8</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X008		DSF0000800204	<i>Other</i> Classroom Connectivity	2015	386,571
							<b>P.S. 8 Total:</b>	\$386,571
10	Bronx	X009		<b>P.S. 9 (OLD 115)</b>				
					DSF0000752356	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2016	8,333,075
					DSF0000752357	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2016	1,403,401
					DSF0000799649	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	147,987
					DSF0000912493	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	17,964,330
					DSF0000906407	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation	2019	576,367
					DSF0000906399	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	2,798,799
					DSF0000906398	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing	2019	1,754,184
							<b>P.S. 9 (OLD 115) Total:</b>	\$32,978,143
10	Bronx	X015		<b>P.S. 15</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000911903	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	228,690
					DSF0000843985	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	1,350,567
					DSF0000906462	INTERIOR:STRUCTURAL:FOUNDATION WALLS <i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2019	162,303
						<i>Other</i>		
			X015		DSF0000889194	New/Retrofit Telephone/Intercom Systems	2018	282,642
							<b>P.S. 15 Total:</b>	<b>\$2,024,202</b>
10	Bronx	X020		<b>P.S. 20</b>				
			X020		DSF0000843884	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	132,548
			X168		DSF0000911877	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2019	212,000
			X168		DSF0000912252	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2019	63,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799516	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Floor Finish	2015	225,060
					DSF0000771191	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Floor Finish	2015	877,693
					DSF0000861041	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2018	150,636
					DSF0000799515	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	523,451
						<b>Other</b>		
			X020		DSF0000800205	Classroom Connectivity	2015	519,884
							<b>P.S. 20 Total:</b>	<b>\$2,704,272</b>
10	Bronx	X023		<b>P.S. 23</b>				
			X023		DSF0000891058	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
							<b>P.S. 23 Total:</b>	<b>\$192,500</b>
10	Bronx	X024		<b>P.S. 24</b>				
					DSF0000843870	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	4,301,857



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X024		DSF0000843694	<b>Safety and Security - Safety and Security - Code Compliance</b>	2018	641,948
					DSF0000798382	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	5,867,203
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			X024		DSF0000799754	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	1,871,145
					DSF0000799651	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	189,916
			X024		DSF0000843978	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	799,915
						FIRE ALARM SYSTEM		
						<b>Other</b>		
			X024		DSF0000889195	New/Retrofit Telephone/Intercom Systems	2018	239,311
							<b>P.S. 24 Total:</b>	<b>\$13,911,295</b>
10	Bronx	X026		<b>P.S. 396</b>				
					DSF0000911897	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	261,783
						INTERIOR:CAFETERIA:Ceiling		
					DSF0000906646	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	82,113
						Fire System Sprinklers		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:Sprinkler Piping		
			X390	DSF0000794028		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			X390	DSF0000866059		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
						<i>Other</i>		
			X390	DSF0000889507		IP Surveillance Camera Installation	2019	43,840
							<b>P.S. 396 Total:</b>	<b>\$572,145</b>
10	Bronx	X032		<b>P.S. 32</b>				
				DSF0000844014		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	6,291,305
			X032	DSF0000799843		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
				DSF0000839282		<i>State of Good Repair - System Replacements - Parapets</i>	2017	1,474,480
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				DSF0000844015		<i>State of Good Repair - System Replacements - Windows</i>	2017	1,472,237
							<b>P.S. 32 Total:</b>	<b>\$9,269,681</b>
10	Bronx	X033		<b>P.S. 33</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799654	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	143,976
					DSF0000890607	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	2,291
						<i>Other</i>		
			X033		DSF0000800209	Classroom Connectivity	2015	43,303
			X033		DSF0000889509	IP Surveillance Camera Installation	2019	39,041
							<b>P.S. 33 Total:</b>	<b>\$228,611</b>
10	Bronx	X037		<b>P.S. 37</b>				
					DSF0000883946	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	1,010,965
			X037		DSF0000861317	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	89,701
						<i>Other</i>		
			X037		DSF0000867128	New/Retrofit Telephone/Intercom Systems	2018	218,026
							<b>P.S. 37 Total:</b>	<b>\$1,318,692</b>
10	Bronx	X045		<b>I.S. 45</b>				
			X045		DSF0000823641	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	1,438,487

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X045		DSF0000912483	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
					DSF0000794320	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,282,632
					DSF0000868247	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	669,745
			X045		DSF0000866061	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			X045		DSF0000800212	Classroom Connectivity	2015	30,425
			X045		DSF0000889510	IP Surveillance Camera Installation	2019	39,846
							<b>I.S. 45 Total:</b>	<b>\$3,875,927</b>
10	Bronx	X046		<b>P.S. 46</b>				
					DSF0000823583	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			X046		DSF0000794348	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	162,487

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
							<b>P.S. 46 Total:</b>	\$232,210
10	Bronx	X054		<b>P.S. 54</b>				
			X054	DSF0000865817		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	758,620
						<b>Other</b>		
			X054	DSF0000889196		New/Retrofit Telephone/Intercom Systems	2018	206,375
							<b>P.S. 54 Total:</b>	\$964,995
10	Bronx	X056		<b>P.S. 56</b>				
						<b>Other</b>		
			X056	DSF0000800216		Classroom Connectivity	2015	65,915
							<b>P.S. 56 Total:</b>	\$65,915
10	Bronx	X059		<b>P.S. 59</b>				
				DSF0000884299		<b>State of Good Repair - System Replacements - Containerization</b>	2019	191,111
						SITE:CONTAINERIZATION		
				DSF0000912186		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
			X059	DSF0000866064		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 59 Total:</b>	\$484,838

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
10	Bronx	X079		<b>P.S. 79</b>				
					DSF0000798466	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,041,624
					DSF0000821632	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	506,413
			X382		DSF0000862039	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:CORNICE	2018	6,516,123
					DSF0000799848	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	132,895
			X447		DSF0000866143	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000912187	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
			X382		DSF0000862038	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	8,616,178
			X382		DSF0000866082	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	2,010,106

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X386	DSF0000889053		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	200,221
			X382	DSF0000866083		<i>State of Good Repair - System Replacements - Windows</i>	2018	5,717,224
						<i>Other</i>		
			X382	DSF0000800222		Classroom Connectivity	2015	505,855
			X447	DSF0000889512		IP Surveillance Camera Installation	2019	41,169
							<b>P.S. 79 Total:</b>	<b>\$25,444,433</b>
10	Bronx	X080		<b>I.S. 80/P.S. 280</b>				
				DSF0000844731		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	250,662
				DSF0000821671		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,577,008
				DSF0000799659		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	127,129
			X080	DSF0000821800		<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2016	2,409,181
				DSF0000799849		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	232,537
						<i>Other</i>		
			X080	DSF0000800223		Classroom Connectivity	2015	503,349
			X280	DSF0000889513		IP Surveillance Camera Installation	2019	39,443

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 80/P.S. 280 Total:</b>	\$5,139,309
10	Bronx	X081		<b>P.S. 81</b>				
			X081	DSF0000823643		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,269,959
			X081	DSF0000818176		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP	2017	719,767
			X081	DSF0000889293		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	5,490,953
				DSF0000794983		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	832,617
			X081	DSF0000818181		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS	2017	2,036,397
				DSF0000799850		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	154,958



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X081		DSF0000818178	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,671,040
					DSF0000818184	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2016	180,228
			X081		DSF0000794989	<b>State of Good Repair - System Replacements - Windows</b>	2017	1,289,858
							<b>P.S. 81 Total:</b>	<b>\$14,645,777</b>
10	Bronx	X085		<b>P.S. 85</b>				
			X085		DSF0000821925	<b>Safety and Security - Safety and Security - Safety Systems</b>	2017	724,467
			X085		DSF0000801045	<b>State of Good Repair - Building Upgrade - Air Conditioning Retrofit</b>	2015	247,470
			X085		DSF0000795066	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,326,467
					DSF0000799660	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	153,009
					DSF0000907656	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2017	1,293,274

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CAFETERIA:Ceiling		
					DSF0000889019	<b>State of Good Repair - System Replacements - Containerization</b>	2019	191,111
						SITE:Containerization		
					DSF0000868252	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	301,034
			X085		DSF0000795070	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,849,015
						EXTERIOR:EXTERIOR WALLS		
					DSF0000795069	<b>State of Good Repair - System Replacements - Parapets</b>	2017	6,089,541
						EXTERIOR:PARAPETS		
			X085		DSF0000795068	<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,158,327
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			X085		DSF0000818268	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	248,144
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
					DSF0000866192	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	1,216,286
						<b>Other</b>		
			X085		DSF0000866216	Classroom Connectivity	2017	40,040

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 85 Total:</b>	\$16,838,185
10	Bronx	X086		<b>P.S. 86</b>				
					DSF0000795087	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	415,787
			X086		DSF0000843822	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	502,618
					DSF0000818289	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	163,017
							<b>P.S. 86 Total:</b>	\$1,081,422
10	Bronx	X091		<b>P.S. 91</b>				
					DSF0000799662	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	147,094
			X091		DSF0000884930	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2018	60,111
			X091		DSF0000845577	<b>State of Good Repair - System Replacements - Floors</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2017	135,227

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000818388	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal  <b>Other</b>	2016	122,580
			X091		DSF0000843789	Classroom Connectivity	2016	265,307
							<b>P.S. 91 Total:</b>	<b>\$730,319</b>
10	Bronx	X094		<b>P.S. 94</b>				
			X094		DSF0000884997	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	81,327
					DSF0000818448	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal  <b>Other</b>	2016	193,176
			X094		DSF0000800228	Classroom Connectivity	2015	217,235
							<b>P.S. 94 Total:</b>	<b>\$491,738</b>
10	Bronx	X095		<b>P.S. 95</b>				
					DSF0000795268	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,128,534

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
					DSF0000795267	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,355,804
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
						<b>Other</b>		
			X095		DSF0000889515	IP Surveillance Camera Installation	2019	40,449
							<b>P.S. 95 Total:</b>	<b>\$8,524,787</b>
10	Bronx	X115		<b>I.S. 399 (OLD X HS/115)</b>				
					DSF0000821893	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	1,157,066
					DSF0000799666	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	185,949
			X459		DSF0000795617	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2017	1,135,098
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
			X363		DSF0000799804	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			X459		DSF0000821891	<b>State of Good Repair - System Replacements - Roofs</b>	2017	293,407
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			X363		DSF0000867132	New/Retrofit Telephone/Intercom Systems	2018	295,182
							<b>I.S. 399 (OLD X HS/115) Total:</b>	<b>\$3,098,382</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
10	Bronx	X118		<b>I.S. 118</b>				
			X118		DSF0000908215	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	3,457,270
					DSF0000908219	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	12,274,566
			X118		DSF0000908218	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	4,534,117
					DSF0000908217	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	2,116,269
							<b>I.S. 118 Total:</b>	<b>\$22,382,222</b>
10	Bronx	X122		<b>P.S. 310</b>				
					DSF0000799667	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	114,722
			X310		DSF0000800190	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	199,905
							<b>P.S. 310 Total:</b>	<b>\$314,627</b>
10	Bronx	X137		<b>I.S. 391 (UDC)</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000865877	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	184,577
			X225		DSF0000823611	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,861,987
					DSF0000798464	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	545,543
					DSF0000889020	<b>State of Good Repair - System Replacements - Containerization</b> COMPACTOR SITE:CONTAINERIZATION	2019	191,111
					DSF0000867072	<b>Other</b> IP Surveillance Camera Installation	2018	509,137
							<b>I.S. 391 (UDC) Total:</b>	<b>\$4,292,355</b>
10	Bronx	X141		<b>M.S./H.S. 141</b>				
					DSF0000865878	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	266,738
					DSF0000890608	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	2,556
					DSF0000908573	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	545,269

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
					DSF0000885745	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,166,392
						EXTERIOR:COPING		
					DSF0000885744	<b>State of Good Repair - System Replacements - Roofs</b>	2019	7,703,883
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			X141		DSF0000800241	Classroom Connectivity	2015	192,350
					DSF0000868103	IP Surveillance Camera Installation	2019	568,853
							<b>M.S./H.S. 141 Total:</b>	<b>\$10,446,041</b>
10	Bronx	X143		<b>I.S. 143</b>				
					DSF0000798326	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	7,031,677
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000798327	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,843,834
						CLIMATE CONTROL SYSTEM		
					DSF0000819265	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	346,602
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799668	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	129,010
			X143		DSF0000821809	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	1,948,517
					DSF0000796075	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	863,676
					DSF0000819267	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOFING:Roofing	2016	3,186,419
					DSF0000819273	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	153,511
						<b>Other</b>		
			X237		DSF0000800242	Classroom Connectivity	2015	276,952
			X244		DSF0000889524	IP Surveillance Camera Installation	2019	40,919
							<b>I.S. 143 Total:</b>	<b>\$15,821,117</b>
10	Bronx	X177		<b>THE NORWOOD EAST CAMPUS</b>				
						<b>Other</b>		
			X177		DSF0000912229	IP Surveillance Camera Installation	2019	66,397
							<b>THE NORWOOD EAST CAMPUS Total:</b>	<b>\$66,397</b>
10	Bronx	X205		<b>P.S. 205A (ECF)</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000889022	<b>State of Good Repair - System Replacements - Containerization</b> COMPACTOR	2019	140,000
						<b>Other</b>		
			X205		DSF0000800252	Classroom Connectivity	2015	417,998
			X205		DSF0000867129	New/Retrofit Telephone/Intercom Systems	2018	185,969
							<b>P.S. 205A (ECF) Total:</b>	<b>\$743,967</b>
10	Bronx	X206		<b>I.S. 206B</b>				
			X206		DSF0000796800	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,777
			X206		DSF0000819982	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	150,000
			X206		DSF0000865930	<b>Other</b> Classroom Connectivity	2017	208,955
							<b>I.S. 206B Total:</b>	<b>\$409,732</b>
10	Bronx	X209		<b>P.S. 209</b>				
					DSF0000886458	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,504,570

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000886461	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	940,092
						EXTERIOR:CHIMNEY		
					DSF0000886460	<b>State of Good Repair - System Replacements - Parapets</b>	2019	141,010
						EXTERIOR:COPING		
					DSF0000886459	<b>State of Good Repair - System Replacements - Roofs</b>	2019	107,968
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			X209		DSF0000865931	Classroom Connectivity	2017	172,054
							<b>P.S. 209 Total:</b>	<b>\$2,865,694</b>
10	Bronx	X254		<b>I.S. 254</b>				
					DSF0000822210	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,858,240
					DSF0000821031	<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,520,098
						EXTERIOR:ROOFING:Roofing		
						<b>Other</b>		
			X254		DSF0000866221	Classroom Connectivity	2017	22,121
							<b>I.S. 254 Total:</b>	<b>\$5,400,459</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
10	Bronx	X279		<b>P.S. 279</b>				
			X279	DSF0000820035		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,953,531
				DSF0000909328		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2019	469,716
			X279	DSF0000866151		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	811,421
						<b>Other</b>		
			X279	DSF0000866222		Classroom Connectivity	2017	40,040
			X279	DSF0000867131		New/Retrofit Telephone/Intercom Systems	2018	235,962
			X279	DSF0000889531		IP Surveillance Camera Installation	2019	39,041
							<b>P.S. 279 Total:</b>	<b>\$3,549,711</b>
10	Bronx	X306		<b>P.S. 306</b>				
				DSF0000911901		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	594,034
						<b>Other</b>		
			X306	DSF0000889197		New/Retrofit Telephone/Intercom Systems	2018	631,935
							<b>P.S. 306 Total:</b>	<b>\$1,225,969</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
10	Bronx	X340		<b>P.S. 340</b>				
						<i>Other</i>		
			X340	DSF0000843790		Classroom Connectivity	2016	326,486
							<b>P.S. 340 Total:</b>	\$326,486
10	Bronx	X360		<b>P.S. 360</b>				
				DSF0000799535		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:HEATING AND VENTILATING UNIT	2015	2,385,864
				DSF0000775094		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,407,222
			X360	DSF0000800253		<i>Other</i> Classroom Connectivity	2015	332,733
							<b>P.S. 360 Total:</b>	\$4,125,819
10	Bronx	X361		<b>P.S. 94 ANNEX</b>				
						<i>Other</i>		
			X094	DSF0000889533		IP Surveillance Camera Installation	2019	38,705
							<b>P.S. 94 ANNEX Total:</b>	\$38,705
10	Bronx	X368		<b>M.S./H.S. 368</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X368		DSF0000799913	<i>State of Good Repair - System Replacements - Paved Area - Concrete</i>	2017	550,819
							<b>M.S./H.S. 368 Total:</b>	\$550,819
10	Bronx	X472		<b>P.S. 246 (POE CENTER)</b>				
			X246		DSF0000889038	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,844,200
							<b>P.S. 246 (POE CENTER) Total:</b>	\$10,844,200
10	Bronx	X481		<b>P.S. 205A (ECF)</b>				
			X205		DSF0000889568	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,922,084
							<b>P.S. 205A (ECF) Total:</b>	\$10,922,084
10	Bronx	X781		<b>P.S. 51</b>				
					DSF0000798134	<i>State of Good Repair - System Replacements - Gymnasium Upgrade</i> INTERIOR:GYMNASIUM:Floor Finish	2015	423,729
			X051		DSF0000800260	<i>Other</i> Classroom Connectivity	2015	545,671
							<b>P.S. 51 Total:</b>	\$969,400
10	Bronx	X819		<b>P.S. 207</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000888991	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	665,833
			X207		DSF0000800263	<b>Other</b> Classroom Connectivity	2015	503,443
							<b>P.S. 207 Total:</b>	\$1,169,276
10	Bronx	X826		<b>P.S. 226 MINISCHOOL</b>				
					DSF0000821732	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	270,697
			X226		DSF0000821731	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	1,493,998
					DSF0000821733	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	1,467,653
			X226		DSF0000866223	<b>Other</b> Classroom Connectivity	2017	22,121
			X226		DSF0000867130	New/Retrofit Telephone/Intercom Systems	2018	170,771
							<b>P.S. 226 MINISCHOOL Total:</b>	\$3,425,240
10	Bronx	X842		<b>P.S. 95 ANNEX</b>				
			X168		DSF0000912248	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	69,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 95 ANNEX Total:</b>	\$69,000
10	Bronx	X843		<b>P.S. 246 (POE CENTER)</b>				
					DSF0000751712	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2017	2,684,720
						CONVEYING:ELEVATORS		
			X246		DSF0000797406	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	2,167,036
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					SCA0000025015	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	4,338,631
			X246		DSF0000797408	<b>State of Good Repair - System Replacements - Parapets</b>	2017	4,523,704
						EXTERIOR:PARAPETS		
			X246		DSF0000797414	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2017	512,738
			X246		DSF0000797407	<b>State of Good Repair - System Replacements - Roofs</b>	2017	1,502,639
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			X246		DSF0000800265	Classroom Connectivity	2015	53,828
							<b>P.S. 246 (POE CENTER) Total:</b>	\$15,783,296
10	Bronx	X852		<b>BRONX DANCE ACADEMY</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X308	DSF0000800201		New/Retrofit Telephone/Intercom Systems	2015	110,599
			X308	DSF0000865934		Classroom Connectivity	2017	164,836
<b>BRONX DANCE ACADEMY Total:</b>								<b>\$275,435</b>
10	Bronx	X886		<b>P.S. 86 ANNEX</b>				
						<i>Other</i>		
			X307	DSF0000800202		New/Retrofit Telephone/Intercom Systems	2015	182,846
			X307	DSF0000822057		New/Retrofit Telephone/Intercom Systems	2015	182,846
<b>P.S. 86 ANNEX Total:</b>								<b>\$365,692</b>
10	Bronx	X896		<b>P.S. 279 ANNEX</b>				
						<i>Other</i>		
			X279	DSF0000800266		Classroom Connectivity	2015	7,332
<b>P.S. 279 ANNEX Total:</b>								<b>\$7,332</b>
11	Bronx	X016		<b>P.S. 16</b>				
				DSF0000748202		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	3,649,749
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000799650		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	46,402
				DSF0000860986		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	53,362

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X016		DSF0000911806	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	4,831,951
					DSF0000771141	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2015	1,551,832
					DSF0000817040	SITE:RETAINING WALLS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351
			X016		DSF0000822110	FIXTURES:STUDENT:Toilet <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	150,672
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			X016		DSF0000800173	New/Retrofit Telephone/Intercom Systems	2015	138,817
							<b>P.S. 16 Total:</b>	\$10,524,136
11	Bronx	X019		<b>P.S. 19</b>				
					DSF0000793888	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	482,651
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X019		DSF0000889506	IP Surveillance Camera Installation	2019	39,583
							<b>P.S. 19 Total:</b>	<b>\$522,234</b>
11	Bronx	X021		<b>P.S. 21</b>				
					DSF0000868244	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	358,897
			X021		DSF0000793930	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			X021		DSF0000861060	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:PAVING:Site Sidewalks & Walkways:Concrete SITE:PAVING:Student Non-Use:Concrete SITE:RETAINING WALLS	2019	4,762,649
							<b>P.S. 21 Total:</b>	<b>\$5,153,226</b>
11	Bronx	X041		<b>P.S. 41</b>				
			X041		DSF0000752360	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	5,510,343
			X041		DSF0000752361	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,436,167
					DSF0000883981	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	451,606

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799719	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	131,696
					DSF0000883986	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	7,233,260
						EXTERIOR:EXTERIOR WALLS		
			X041		DSF0000794242	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
					DSF0000883985	<i>State of Good Repair - System Replacements - Parapets</i>	2019	2,859,187
						EXTERIOR:PARAPETS		
					DSF0000883984	<i>State of Good Repair - System Replacements - Roofs</i>	2019	881,094
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
			X041		DSF0000866060	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	488,550
					DSF0000906844	<i>State of Good Repair - System Replacements - Windows</i>	2019	2,836,057
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			X041		DSF0000800211	Classroom Connectivity	2015	20,667
							<b>P.S. 41 Total:</b>	<b>\$21,880,286</b>
11	Bronx	X068		<b>P.S. 68</b>				
					DSF0000861830	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	2,423,807

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000749082	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent AUDITORIUM:LOCAL SOUND SYSTEM AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Sliding-folding Partition	2015	1,303,539
			X068		DSF0000799354	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	366,945
			X068		DSF0000844082	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	992,361
					DSF0000799847	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	182,616
			X068		DSF0000839883	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b> SITE:PAVING:Student Use:Asphalt	2017	1,222,933
			X068		DSF0000866066	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 68 Total:</b>	<b>\$6,706,993</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
11	Bronx	X076		<b>P.S. 76</b>				
					DSF0000884629	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,069,548
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000891026	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,502,392
						EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			X076		DSF0000866142	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000891025	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,297,459
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
			X076		DSF0000888834	<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,688,518
							<b>P.S. 76 Total:</b>	<b>\$5,635,607</b>
11	Bronx	X078		<b>P.S. 78</b>				
			X078		DSF0000840069	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	9,642,888
					DSF0000884673	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	2,956,936
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000888963	EXTERIOR:LOUVER <b>State of Good Repair - System Replacements - Parapets</b>	2019	908,524
					DSF0000818129	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	287,284
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
							<b>P.S. 78 Total:</b>	\$13,795,632
11	Bronx	X083		<b>P.S. 83</b>	DSF0000795028	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	988,713
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X083		DSF0000818226	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	116,301
					DSF0000822665	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	183,975
			X083		DSF0000889640	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X083	DSF0000911948		<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
						<b>Other</b>		
			X083	DSF0000866247		New/Retrofit Telephone/Intercom Systems	2017	337,477
			X083	DSF0000866248		New/Retrofit Telephone/Intercom Systems	2017	162,824
							<b>P.S. 83 Total:</b>	<b>\$2,345,352</b>
11	Bronx	X087		<b>P.S. 87</b>				
				DSF0000862191		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	919,565
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000795109		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	442,796
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000866986		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,443
				DSF0000862196		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	1,850,244
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DSF0000862194		<b>State of Good Repair - System Replacements - Parapets</b>	2018	901,714
						EXTERIOR:COPING		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
					DSF0000818311	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	450,000
						FIXTURES:STUDENT:Toilet		
					DSF0000862195	<b>State of Good Repair - System Replacements - Windows</b>	2018	689,855
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			X087		DSF0000867096	New/Retrofit Telephone/Intercom Systems	2018	173,481
							<b>P.S. 87 Total:</b>	<b>\$5,431,098</b>
11	Bronx	X089		<b>P.S. 89</b>				
					DSF0000884892	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,246,251
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799352	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2016	508,425
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799661	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	128,209
					DSF0000818346	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X089		DSF0000911949	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
						<b>Other</b>		
			X089		DSF0000800224	Classroom Connectivity	2015	439,816
			X089		DSF0000889199	New/Retrofit Telephone/Intercom Systems	2018	233,830
			X089		DSF0000889514	IP Surveillance Camera Installation	2019	43,731
						<b>P.S. 89 Total:</b>		\$3,011,255
11	Bronx	X096		<b>P.S. 96</b>				
					DSF0000866988	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	23,090
						<b>P.S. 96 Total:</b>		\$23,090
11	Bronx	X097		<b>P.S. 97</b>				
			X097		DSF0000845630	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,173,079
						<b>Other</b>		
			X097		DSF0000867097	New/Retrofit Telephone/Intercom Systems	2018	174,952
						<b>P.S. 97 Total:</b>		\$1,348,031
11	Bronx	X103		<b>P.S. 103</b>				
			X103		DSF0000885114	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2018	1,573,961

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799664	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	208,737
			X103		DSF0000885118	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	3,240,635
						EXTERIOR:AREAWAY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS		
					DSF0000885117	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,422,946
						EXTERIOR:COPING EXTERIOR:PARAPETS		
						<b>Other</b>		
			X103		DSF0000800229	Classroom Connectivity	2015	381,373
			X103		DSF0000889516	IP Surveillance Camera Installation	2019	37,565
							<b>P.S. 103 Total:</b>	<b>\$8,865,217</b>
11	Bronx	X105		<b>P.S. 105</b>				
			X105		DSF0000795434	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	4,085,865
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000798473	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	967,125
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000862482	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	26,183
					DSF0000888989	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	611,324
			X105		DSF0000818615	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,540,847
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000818620	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	358,000
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			X105		DSF0000800232	Classroom Connectivity	2015	427,295
							<b>P.S. 105 Total:</b>	<b>\$8,016,639</b>
11	Bronx	X106		<b>P.S. 106</b>				
					DSF0000912390	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	4,228
							<b>P.S. 106 Total:</b>	<b>\$4,228</b>
11	Bronx	X108		<b>P.S. 108</b>				
			X108		DSF0000865751	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X108	DSF0000865926		Classroom Connectivity	2017	225,202
			X108	DSF0000867107		New/Retrofit Telephone/Intercom Systems	2018	180,501
							<b>P.S. 108 Total:</b>	<b>\$721,576</b>
11	Bronx	X111		<b>P.S. 111</b>				
				DSF0000818720		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	974,246
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			X111	DSF0000795543		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
							<b>P.S. 111 Total:</b>	<b>\$1,005,905</b>
11	Bronx	X112		<b>P.S. 112</b>				
				DSF0000798321		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	5,871,653
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF0000795558		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,611,309
						CLIMATE CONTROL SYSTEM		
				DSF0000840692		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	813,253

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866991	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	8,823
			X112		DSF0000800233	<b>Other</b> Classroom Connectivity	2015	25,623
							<b>P.S. 112 Total:</b>	<b>\$8,330,661</b>
11	Bronx	X113		<b>I.S. 113</b>				
			X272		DSF0000822687	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	2,929,620
					DSF0000798439	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,556,698
			X287		DSF0000862622	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	1,256,410
					DSF0000821622	AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000818768	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	304,054
						FIXTURES:STUDENT:Toilet		
			X272		DSF0000885301	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	200,221
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Urinal		
						<b>Other</b>		
			X272		DSF0000800234	Classroom Connectivity	2015	481,584
			X272		DSF0000866249	New/Retrofit Telephone/Intercom Systems	2017	299,338
					DSF0000867071	IP Surveillance Camera Installation	2018	622,920
							<b>I.S. 113 Total:</b>	<b>\$8,129,911</b>
11	Bronx	X121		<b>P.S. 121</b>				
					DSF0000885448	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	678,756
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000822226	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	969,347
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000885451	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	2,306,558

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
			X121		DSF0000795736	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	44,634
					DSF0000885450	<b>State of Good Repair - System Replacements - Parapets</b>	2019	544,988
			X121		DSF0000908280	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	3,199,544
					DSF0000818925	EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	133,642
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
							<b>P.S. 121 Total:</b>	<b>\$7,877,469</b>
11	Bronx	X127		<b>I.S. 127</b>				
					DSF0000801085	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	2,228,556
					DSF0000822227	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	921,255
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866994	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	53,427
			X127		DSF0000862875	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	2,802,197
			X127		DSF0000862873	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	4,351,039
			X127		DSF0000862872	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,358,732
			X127		DSF0000862874	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	1,182,160
							<b>I.S. 127 Total:</b>	<b>\$15,897,366</b>
11	Bronx	X135		<b>I.S. 135</b>				
			X322		DSF0000822206	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2017	4,076,714
					DSF0000866996	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	19,386
			X322		DSF0000819133	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X322	DSF0000795950		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	138,769
			X556	DSF0000889522		<b>Other</b> IP Surveillance Camera Installation	2019	40,279
<b>I.S. 135 Total:</b>								<b>\$4,419,934</b>
11	Bronx	X142		<b>I.S. 142</b>				
			X529	DSF0000799481		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	334,868
				DSF0000912364		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	52,148
				DSF0000752369		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	3,647,884
				DSF0000868259		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	142,623
			X142	DSF0000796055		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	39,284

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000867074	IP Surveillance Camera Installation	2018	414,496
							<b>I.S. 142 Total:</b>	<b>\$4,631,303</b>
11	Bronx	X144		<b>I.S. 144</b>				
			X144	DSF0000752363		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2016	5,034,475
			X144	DSF0000752364		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2016	1,958,179
			X144	DSF0000796098		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			X144	DSF0000885798		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	200,221
						FIXTURES:Student:Lavatory/Sink		
						<i>Other</i>		
			X144	DSF0000889525		IP Surveillance Camera Installation	2019	39,443
							<b>I.S. 144 Total:</b>	<b>\$7,263,977</b>
11	Bronx	X153		<b>P.S. 153</b>				
				DSF0000885972		<b>Ventilation</b>	2019	2,448,231
						AIR CONDITIONING:Chilled Water System:Central Station Air Handler		
						MOTOR CONTROL CENTER		
						MOTOR STARTER/CONTACTOR		
						VENTILATION:Exhaust Fan		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						VENTILATION: Metal Ductwork		
					DSF0000890988	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	33,059
			X153		DSF0000885966	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
						FIXTURES: Student: Lavatory/Sink		
						<b>Other</b>		
			X153		DSF0000865929	Classroom Connectivity	2017	221,497
							<b>P.S. 153 Total:</b>	<b>\$3,103,231</b>
11	Bronx	X160		<b>P.S. 160</b>				
			X168		DSF0000912243	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	224,000
						Technology		
					DSF0000796397	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,623,964
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Incandescent		
					DSF0000868143	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	64,140
							<b>P.S. 160 Total:</b>	<b>\$1,912,104</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
11	Bronx	X169		<b>THE WILLIE ELLA PASCHAL BOWMAN CAMPUS</b>				
					DSF0000868145	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2018	16,518
							<b>THE WILLIE ELLA PASCHAL BOWMAN CAMPUS Total:</b>	\$16,518
11	Bronx	X175		<b>P.S. 175</b>				
					DSF0000798455	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	735,190
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X175		DSF0000796587	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
							<b>P.S. 175 Total:</b>	\$766,849
11	Bronx	X178		<b>P.S. 178</b>				
			X178		DSF0000863639	<i>State of Good Repair - System Replacements - Domestic Piping</i>	2018	178,038
					DSF0000890996	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	25,576
			X178		DSF0000886262	<i>State of Good Repair - System Replacements - Windows</i>	2018	4,183,127
						EXTERIOR:WINDOWS		
							<b>P.S. 178 Total:</b>	\$4,386,741

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
11	Bronx	X180		<b>I.S. 180</b>				
			X180	DSF0000886282		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
						FIXTURES:Student:Lavatory/Sink		
							<b>I.S. 180 Total:</b>	\$400,444
11	Bronx	X181		<b>I.S. 181</b>				
						<b>Other</b>		
			X181	DSF0000800250		Classroom Connectivity	2015	211,040
							<b>I.S. 181 Total:</b>	\$211,040
11	Bronx	X189		<b>P.S./I.S. 189 (@STEENWICK AVE)</b>				
						<b>Other</b>		
				DSF0000868106		IP Surveillance Camera Installation	2019	315,642
							<b>P.S./I.S. 189 (@STEENWICK AVE) Total:</b>	\$315,642
11	Bronx	X194		<b>P.S./I.S. 194</b>				
			X168	DSF0000912244		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	49,000
						Technology		
			X194	DSF0000821907		<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2015	227,586
						INTERIOR:GYMNASIUM:Floor Finish		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S./I.S. 194 Total:</b>	\$276,586
11	Bronx	X498		<b>THE LT. CURTIS MEYRAN AND JOHN BELLEW EDUCATION COMPLEX</b>				
					DSF0000865883	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	55,062
					DSF0000868144	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2018	15,236
						<i>Other</i>		
			X498		DSF0000800258	Classroom Connectivity	2015	310,463
			X498		DSF0000889551	IP Surveillance Camera Installation	2019	40,584
							<b>THE LT. CURTIS MEYRAN AND JOHN BELLEW EDUCATION COMPLEX Total:</b>	\$421,345
11	Bronx	XADY		<b>SAINT LUCY ELEMENTARY SCHOOL</b>				
			X000		DSF0000866304	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2017	40,000
							<b>SAINT LUCY ELEMENTARY SCHOOL Total:</b>	\$40,000
12	Bronx	X006		<b>P.S. 6</b>				
					DSF0000883480	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	375,144
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWITCHBOARD		
					DSF0000890635	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	7,308
							<b>P.S. 6 Total:</b>	\$382,452
12	Bronx	X044		<b>P.S. 44</b>				
					DSF0000794304	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	5,124,013
					DSF0000817479	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2017	4,198,033
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X044		DSF0000822073	<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,405,296
						EXTERIOR:ROOFING:Roofing		
						<b>Other</b>		
			X044		DSF0000800179	New/Retrofit Telephone/Intercom Systems	2015	215,880
			X044		DSF0000822050	New/Retrofit Telephone/Intercom Systems	2015	215,880
			X044		DSF0000822161	IP Surveillance Camera Installation	2016	852,018
							<b>P.S. 44 Total:</b>	\$13,011,120
12	Bronx	X047		<b>P.S. 47</b>				
					DSF0000771636	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	2,699,534
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821596	INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	542,237
					DSF0000771639	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	4,314,012
					DSF0000817543	EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000771638	<b>State of Good Repair - System Replacements - Parapets</b>	2015	3,385,383
					DSF0000771637	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2015	1,904,691
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 47 Total:</b>	\$12,915,580
12	Bronx	X050		<b>P.S. 50</b>				
			X050		DSF0000839573	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,917,373
			X050		DSF0000867175	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	75,073

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X314	DSF0000866062		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	199,314
			X050	DSF0000800180		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	165,218
							<b>P.S. 50 Total:</b>	<b>\$2,356,978</b>
12	Bronx	X057		<b>P.S. 57</b>				
			X057	DSF0000839662		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,397,995
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			X057	DSF0000839665		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	1,957,776
						EXTERIOR:AREAWAY		
						EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			X057	DSF0000866138		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			X057	DSF0000844740		<b>State of Good Repair - System Replacements - Parapets</b>	2018	760,962
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
			X057	DSF0000839664		<b>State of Good Repair - System Replacements - Roofs</b>	2018	359,983
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X057		DSF0000866063	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	76,365
						<b>Other</b>		
			X057		DSF0000800183	New/Retrofit Telephone/Intercom Systems	2015	214,220
			X057		DSF0000822058	New/Retrofit Telephone/Intercom Systems	2015	214,220
			X057		DSF0000866213	Classroom Connectivity	2017	40,040
						<b>P.S. 57 Total:</b>		\$5,099,251
12	Bronx	X061		<b>P.S. 61</b>				
					DSF0000884327	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	102,912
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000794603	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	870,018
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000884331	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,458,360
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000884330	<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,504,733
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000884329	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,878,280
			X061		DSF0000912228	<b>Other</b> IP Surveillance Camera Installation	2019	69,618
							<b>P.S. 61 Total:</b>	<b>\$8,883,921</b>
12	Bronx	X066		<b>P.S. 66</b>				
					DSF0000843909	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,451,205
			X066		DSF0000866141	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
							<b>P.S. 66 Total:</b>	<b>\$2,528,895</b>
12	Bronx	X067		<b>P.S. 67</b>				
			X372		DSF0000777273	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	873,008
			X067		DSF0000890620	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	3,277,316
					DSF0000884454	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	5,004,529
			X067		DSF0000911807	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,765,876

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000912512	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b> INTERIOR:CAFETERIA:Floor Finish	2019	272,269
					DSF0000884459	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS	2019	5,355,711
					DSF0000794722	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2016	3,010,433
			X067		DSF0000801053	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:UNIT VENTILATOR	2016	1,499,114
					DSF0000884457	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	2,786,224
			X067		DSF0000912446	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:PAVING:Student Use:Concrete	2019	205,676
					DSF0000884456	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	2,113,055

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000817911	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	341,568
					DSF0000884458	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	8,124,904
							<b>P.S. 67 Total:</b>	<b>\$34,629,683</b>
12	Bronx	X077		<b>P.S. 195</b>				
			X196		DSF0000840048	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	994,259
					DSF0000794912	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,078,990
			X196		DSF0000818106	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CORNICE	2017	5,775,920

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
					DSF0000840063	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	88,829
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System		
					DSF0000840051	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,838,846
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X196		DSF0000840050	<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,035,606
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			X195		DSF0000800221	Classroom Connectivity	2015	492,037
							<b>P.S. 195 Total:</b>	<b>\$12,304,487</b>
12	Bronx	X092		<b>P.S. 92</b>				
					DSF0000772483	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	760,185
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799721	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	138,643

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868254	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	283,581
					DSF0000772486	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	1,139,985
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
					DSF0000799466	<i>State of Good Repair - System Replacements - Parapets</i>	2015	1,493,792
						EXTERIOR:PARAPETS		
					DSF0000772485	<i>State of Good Repair - System Replacements - Roofs</i>	2015	2,441,589
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
			X092		DSF0000888930	<i>State of Good Repair - System Replacements - Roofs</i>	2018	81,327
			X092		DSF0000889641	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 92 Total:</b>	<b>\$6,553,894</b>
12	Bronx	X098		<b>I.S. 98</b>				
			X098		DSF0000845628	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	2,970,365
					DSF0000889301	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	8,233
					DSF0000822666	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	308,282
			X098		DSF0000866144	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000818505	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	171,003
			X098		DSF0000822113	FIXTURES:STUDENT:Toilet <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	247,348
			X098		DSF0000866068	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	107,397
							<b>I.S. 98 Total:</b>	<b>\$3,890,318</b>
12	Bronx	X102		<b>P.S. 102</b>				
					DSF0000865875	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	205,128
			X531		DSF0000799480	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	285,178
					DSF0000795381	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	3,225,150
					DSF0000799663	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	148,074

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000823585	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000844155	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	1,548,972
						<b>Other</b>		
			X102		DSF0000822071	New/Retrofit Telephone/Intercom Systems	2015	321,560
							<b>P.S. 102 Total:</b>	<b>\$5,803,785</b>
12	Bronx	X116		<b>I.S. 216</b>				
			X217		DSF0000865820	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	40,000
			X217		DSF0000888787	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	70,000
			X217		DSF0000888788	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	75,000
			X384		DSF0000889296	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	105,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			X384		DSF0000889297	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	40,000
						Technology		
					DSF0000795636	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,716,048
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			X217		DSF0000800235	Classroom Connectivity	2015	414,090
			X217		DSF0000889201	New/Retrofit Telephone/Intercom Systems	2018	387,929
			X384		DSF0000889517	IP Surveillance Camera Installation	2019	39,644
							<b>I.S. 216 Total:</b>	<b>\$2,887,711</b>
12	Bronx	X129				<b>I.S. 129 (PAIRED W P234)</b>		
					DSF0000865876	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2016	157,970
					DSF0000821626	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2017	304,054
			X129		DSF0000799854	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	33,846

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X129		DSF0000866217	Classroom Connectivity	2017	40,040
			X129		DSF0000889520	IP Surveillance Camera Installation	2019	39,376
							<b>I.S. 129 (PAIRED W P234) Total:</b>	<b>\$575,286</b>
12	Bronx	X134		<b>P.S. 134</b>				
			X134		DSF0000819122	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2019	368,651
					DSF0000889289	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	3,510,114
			X134		DSF0000800238	<i>Other</i> Classroom Connectivity	2015	417,834
							<b>P.S. 134 Total:</b>	<b>\$4,296,599</b>
12	Bronx	X150		<b>P.S. 150</b>				
			X150		DSF0000796218	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	28,083
					DSF0000912189	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X150		DSF0000800243	<i>Other</i> Classroom Connectivity	2015	40,596
							<b>P.S. 150 Total:</b>	<b>\$147,614</b>
12	Bronx	X158		<b>I.S. 158</b>				
					DSF0000865879	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	237,262
					DSF0000866281	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	466,500
			X245		DSF0000775850	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,183,705
					DSF0000796373	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	2,102,213
					DSF0000867003	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,968
					DSF0000823661	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	145,874

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X267		DSF0000866250	New/Retrofit Telephone/Intercom Systems	2017	289,382
					DSF0000868105	IP Surveillance Camera Installation	2019	347,594
							<b>I.S. 158 Total:</b>	<b>\$4,774,498</b>
12	Bronx	X167		<b>P.S. 214</b>				
			X214		DSF0000821737	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,044,636
					DSF0000799722	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	209,376
			X214		DSF0000863527	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	3,238,476
						EXTERIOR:EXTERIOR SOFFITS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
					DSF0000819688	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	173,939
						FIXTURES:STUDENT:Lavatory/Sink TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						<i>Other</i>		
			X214		DSF0000800249	Classroom Connectivity	2015	236,400
							<b>P.S. 214 Total:</b>	<b>\$4,902,827</b>
12	Bronx	X193		<b>P.S. 211</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000865880	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	103,472
					DSF0000866282	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	452,078
			X211		DSF0000821774	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	65,931
			X318		DSF0000821775	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	65,931
					DSF0000799670	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	184,214
							<b>P.S. 211 Total:</b>	<b>\$871,626</b>
12	Bronx	X198		<b>P.S. 198</b>				
					DSF0000844050	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	2,647,341
			X463		DSF0000911875	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2019	150,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X463	DSF0000911876		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	40,964
			X212	DSF0000912150		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	132,000
			X212	DSF0000912245		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Interior Spaces	2019	175,407
				DSF0000796759		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,491,774
				DSF0000891062		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
			X212	DSF0000800196		New/Retrofit Telephone/Intercom Systems	2015	258,442
			X212	DSF0000800251		Classroom Connectivity	2015	417,998
			X212	DSF0000822043		New/Retrofit Telephone/Intercom Systems	2015	258,442



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 198 Total:</b>	\$5,764,868
12	Bronx	X449		<b>P.S. 6 GYM ANNEX</b>				
			X006	DSF0000889044		<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2018	10,652,129
							<b>P.S. 6 GYM ANNEX Total:</b>	\$10,652,129
12	Bronx	X834		<b>P.S. 134 MINISCHOOL</b>				
				DSF0000912253		<i>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</i>	2019	1,847,711
							<b>P.S. 134 MINISCHOOL Total:</b>	\$1,847,711
33X	Bronx	X807		<b>DISTRICT OFFICE #7 (OLD 18)</b>				
				DSF0000797347		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	410,827
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			XADM	DSF0000820508		<i>State of Good Repair - Building Upgrade - Reinforcing Support Elements</i>	2017	139,728
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
							<b>DISTRICT OFFICE #7 (OLD 18) Total:</b>	\$550,555

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75X	Bronx	X012		<b>P.S. 12</b>				
			X012	DSF0000843972		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2018	2,897,091
			X012	DSF0000866177		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,265,915
			X012	DSF0000866166		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,981,916
			X012	DSF0000800172		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	229,108
							<b>P.S. 12 Total:</b>	<b>\$6,374,030</b>
75X	Bronx	X034		<b>P.S. 34</b>				
				DSF0000883893		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	624,674
				DSF0000883896		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,261,238

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS		
					DSF0000883895	<b>State of Good Repair - System Replacements - Parapets</b>	2019	517,953
						EXTERIOR:COPING		
					DSF0000883894	<b>State of Good Repair - System Replacements - Roofs</b>	2019	4,716,848
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
			X188		DSF0000867092	New/Retrofit Telephone/Intercom Systems	2018	271,256
							<b>P.S. 34 Total:</b>	<b>\$7,391,969</b>
75X	Bronx	X084		<b>P.S. 811 (OLD I84)</b>				
					DSF0000795047	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	2,084,123
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X811		DSF0000818244	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,827,603
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS		
			X811		DSF0000818243	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,598,137

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			X811	DSF0000818242		<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,833,646
			X811	DSF0000823639		EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Windows</b>	2017	915,272
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			X811	DSF0000865924		Classroom Connectivity	2017	337,396
			X811	DSF0000867106		New/Retrofit Telephone/Intercom Systems	2018	513,161
							<b>P.S. 811 (OLD I84) Total:</b>	<b>\$11,109,338</b>
75X	Bronx	X136		<b>P.S. 186 (OLD J136)</b>				
				DSF0000798387		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	6,860,837
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF0000795961		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	3,181,775
						CLIMATE CONTROL SYSTEM		
				DSF0000799880		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	597,980
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000865946	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	909,961
					DSF0000795963	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,463,245
					DSF0000799881	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	3,412,537
					SCA0000026417	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	7,048,767
					DSF0000795966	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	3,816,935
						<b>Other</b>		
			X186	DSF0000800239	Classroom Connectivity		2015	13,756
			X186	DSF0000865927	New/Retrofit Telephone/Intercom Systems		2017	278,051

**P.S. 186 (OLD J136) Total: \$27,583,844**

75X Bronx X155 **P.S. 754 (OLD IS155)**

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000796317	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,911,534
					DSF0000867001	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	15,000
					DSF0000819523	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			X754		DSF0000886002	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal	2019	200,221
			X754		DSF0000889546	<b>Other</b> IP Surveillance Camera Installation	2019	39,846
							<b>P.S. 754 (OLD IS155) Total:</b>	<b>\$2,311,387</b>
75X	Bronx	X701		<b>P.S. 723</b>				
			X723		DSF0000800259	<b>Other</b> Classroom Connectivity	2015	505,885
							<b>P.S. 723 Total:</b>	<b>\$505,885</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75X	Bronx	X722		<b>P.S. 721 (OTC)</b>				
					DSF0000798330	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,617,528
					DSF0000797329	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,335,873
					DSF0000775994	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	750,090
					DSF0000797331	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,194,060
					DSF0000775579	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	8,513,413
			X721		DSF0000891021	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2019	422,027
					DSF0000776000	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	842,536

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000775993	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	631,166
			X721		DSF0000886953	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2019	400,444
					DSF0000775995	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,678,162
			X721		DSF0000865933	<b>Other</b> Classroom Connectivity	2017	181,156
							<b>P.S. 721 (OTC) Total:</b>	<b>\$21,566,455</b>
75X	Bronx	X817		<b>P.S. 811 ANNEX</b>				
					DSF0000797359	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	308,450
							<b>P.S. 811 ANNEX Total:</b>	<b>\$308,450</b>
78X	Bronx	X039		<b>NEW SCH FOR ARTS AND SCIENCE</b>				



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
			X332	DSF0000864950		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	1,884,449	
				DSF0000866979		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,000	
			X332	DSF0000797758		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	43,893	
				DSF0000912191		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935	
				DSF0000820997		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	387,999	
				DSF0000868101		<b>Other</b> IP Surveillance Camera Installation	2019	355,463	
<b>NEW SCH FOR ARTS AND SCIENCE Total:</b>								<b>\$2,753,739</b>	
78X	Bronx	X099		<b>REV. J.A. POLITE AVE SCHOOL CAMPUS</b>					
				DSF0000911902		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	258,310	
			X248	DSF0000911192		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	285,525	

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Boiler System HEATING:Radiator/Convactor/Fin Tube		
<b>REV. J.A. POLITE AVE SCHOOL CAMPUS Total:</b>								\$543,835
78X	Bronx	X211		<b>P.U.L.S.E. HS</b>				
					DSF0000867006	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	67,682
						<b>Other</b>		
			X319		DSF0000866220	Classroom Connectivity	2017	22,121
			X319		DSF0000889198	New/Retrofit Telephone/Intercom Systems	2018	171,678
<b>P.U.L.S.E. HS Total:</b>								\$261,481
78X	Bronx	X362		<b>I.S./H.S. 362</b>				
					DSF0000844729	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	120,466
						<b>Other</b>		
			X270		DSF0000800254	Classroom Connectivity	2015	150,670
			X270		DSF0000889534	IP Surveillance Camera Installation	2019	42,578
<b>I.S./H.S. 362 Total:</b>								\$313,714
78X	Bronx	X392		<b>THE CASITA MARIA CENTER FOR ARTS AND EDUCATION</b>				
			X186		DSF0000844108	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	234,798
						<b>Other</b>		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X269		DSF0000889548	IP Surveillance Camera Installation	2019	36,716
<b>THE CASITA MARIA CENTER FOR ARTS AND EDUCATION Total:</b>								<b>\$271,514</b>
78X	Bronx	X400		<b>MORRIS HS</b>				
					DSF0000842000	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,545,412
					DSF0000844753	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2018	2,394,874
					DSF0000796884	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	174,314
					DSF0000799672	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	215,563
					DSF0000868309	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	174,108
					DSF0000800334	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	29,919,944
			X297		DSF0000886548	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	208,387

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000891063	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000844751	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	12,770,716
					DSF0000823662	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	159,319
					DSF0000844752	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,512,680
						<b>Other</b>		
			X297		DSF0000800255	Classroom Connectivity	2015	256,082
					DSF0000867075	IP Surveillance Camera Installation	2018	474,856
							<b>MORRIS HS Total:</b>	<b>\$49,998,755</b>
78X	Bronx	X401		<b>BRONX REGIONAL HS (OLD 133)</b>				
			X480		DSF0000820092	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	150,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
<b>BRONX REGIONAL HS (OLD 133) Total:</b>								\$150,000
78X	Bronx	X405		<b>HERBERT H. LEHMAN HS</b>				
			X349	DSF0000823642		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	1,247,833
				DSF0000843692		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	698,303
			X405	DSF0000865818		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	3,678,872
			X405	DSF0000775949		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	5,635,377
						Room Conversions / Partitioning		
				DSF0000796942		<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2015	16,551,878
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF0000796932		<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	3,839,965
						CLIMATE CONTROL SYSTEM		
				DSF0000796936		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	12,455,853
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799673	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	270,521
			X405		DSF0000863983	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2018	1,328,324
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
					DSF0000796955	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	671,208
						Waste System		
						DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP		
						DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP		
						DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
					DSF0000796941	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	2,866,642
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000842055	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System	2018	435,343
			X405		DSF0000886595	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation AIR CONDITIONING:Chilled Water System:Central Station Air Handler VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork	2019	1,748,586
			X405		DSF0000889570	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	120,168
					DSF0000799437	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b> SITE:Drainage System for Asphalt SITE:PAVING - STUDENT USE:Asphalt	2015	512,218
					DSF0000820117	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent	2017	405,405

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000867076	IP Surveillance Camera Installation	2018	737,294
<b>HERBERT H. LEHMAN HS Total:</b>								<b>\$53,203,790</b>
78X	Bronx	X410		<b>WILLIAM H. TAFT HS</b>				
					DSF0000889023	<b>State of Good Repair - System Replacements - Containerization</b> SITE:CONTAINERIZATION	2019	191,111
					DSF0000867007	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	28,445
			X413		DSF0000886606	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2018	8,865,215
			X412		DSF0000886604	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	12,782,809
					DSF0000864012	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:RETAINING WALLS	2018	1,666,578
			X412		DSF0000886603	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	5,156,176
					DSF0000820137	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink	2017	202,702



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
			X413	DSF0000886605		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	16,013,817	
			X227	DSF0000889193		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	1,062,702	
				DSF0000843855		IP Surveillance Camera Installation	2018	1,030,273	
<b>WILLIAM H. TAFT HS Total:</b>								<b>\$46,999,828</b>	
78X	Bronx	X415		<b>CHRISTOPHER COLUMBUS HS</b>					
			X415	DSF0000843699		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2018	1,924,957	
				DSF0000821601		<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2015	490,223	
				DSF0000867008		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	125,914	
				DSF0000796987		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2016	1,388,570	
			X417	DSF0000891064		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500	
				DSF0000755238		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	4,066,715	

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000796984	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,367,909	
					DSF0000820161	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2016	209,806	
			X415		DSF0000800197	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	815,542	
					DSF0000843856	IP Surveillance Camera Installation	2017	731,095	
<b>CHRISTOPHER COLUMBUS HS Total:</b>								<b>\$11,313,231</b>	
78X	Bronx	X420		<b>JAMES MONROE CAMPUS</b>					
					DSF0000822172	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	8,430,701	
					DSF0000820176	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,836,115	
					DSF0000822170	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP	2017	432,358	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000842105	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,672,516
					DSF0000799674	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	250,339
			X388		DSF0000820198	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b> CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent INTERIOR:CAFETERIA:Floor Finish	2019	595,789
					DSF0000868310	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	194,304
					DSF0000797012	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY	2018	11,234,965
					DSF0000909461	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube	2019	70,743
					DSF0000842108	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	2,291,630
					DSF0000844686	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	3,142,908

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000844687	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,013,174	
						<b>Other</b>			
					DSF0000867077	IP Surveillance Camera Installation	2018	650,266	
<b>JAMES MONROE CAMPUS Total:</b>								<b>\$32,815,808</b>	
78X	Bronx	X423		<b>JAMES MONROE HS CAMPUS ANNEX</b>					
					DSF0000911900	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	251,524	
						<b>Other</b>			
			X242		DSF0000800256	Classroom Connectivity	2015	453,710	
			X242		DSF0000889549	IP Surveillance Camera Installation	2019	39,712	
<b>JAMES MONROE HS CAMPUS ANNEX Total:</b>								<b>\$744,946</b>	
78X	Bronx	X425		<b>EVANDER CHILDS HS</b>					
					DSF0000865881	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	114,210	
			X265		DSF0000889329	<b>Interior Spaces</b>	2019	237,900	
					DSF0000799785	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	189,189	
					DSF0000868311	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	455,150	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000820208	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	233,904
					DSF0000820215	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2016	165,540
			X253		DSF0000799993	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	101,541
			X275		DSF0000866079	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			X253		DSF0000865752	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
			X253		DSF0000889200	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	940,220
					DSF0000843857	IP Surveillance Camera Installation	2017	607,303
<b>EVANDER CHILDS HS Total:</b>								<b>\$3,575,622</b>
78X	Bronx	X430		<b>WALTON HS</b>				
					DSF0000865882	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	120,697

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000912315	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHTING EXIT LIGHT EXIT/EMERGENCY LIGHT	2017	11,062
					DSF0000868263	<b>State of Good Repair - System Replacements - Electrical Systems</b>  <b>Other</b>	2019	15,623
					DSF0000843858	IP Surveillance Camera Installation	2017	584,659
							<b>WALTON HS Total:</b>	<b>\$732,041</b>
78X	Bronx	X435		<b>THEODORE ROOSEVELT EDUCATIONAL CAMPUS</b>				
					DSF0000821661	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,204,970
					DSF0000798443	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	867,057
					DSF0000889024	<b>State of Good Repair - System Replacements - Containerization</b>	2019	191,111
					DSF0000775991	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	27,953,888

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000891042	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	255,774
					DSF0000774340	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	14,219,478
					DSF0000886717	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete SITE:PAVING:Site Sidewalks & Walkways:Concrete SITE:PAVING:Student Non-Use:Concrete SITE:PAVING:Student Use:Concrete	2015	580,218
					DSF0000774339	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	7,974,143
			X437		DSF0000820249	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	168,761
					DSF0000774341	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	8,149,673
			X434		DSF0000843859	<b>Other</b> IP Surveillance Camera Installation	2017	641,977

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>THEODORE ROOSEVELT EDUCATIONAL CAMPUS Total:</b>								\$62,207,050
78X	Bronx	X440		<b>DEWITT CLINTON HS</b>				
			X440	DSF0000799362		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,793,625
			X440	DSF0000774374		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Gymnasium Upgrade GYMNASIUM:LIGHTING:Lighting Fixture - Fluorescent GYMNASIUM:SCOREBOARD INTERIOR:GYMNASIUM:Floor Finish INTERIOR:GYMNASIUM:Seating INTERIOR:LOCKER ROOM	2019	5,999,658
			X440	DSF0000777278		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Electrical Systems PANEL BOARD	2016	4,046,297
			X440	DSF0000777280		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Low-Voltage Electrical System PUBLIC ADDRESS SYSTEM	2016	2,388,230



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X440		DSF0000777281	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,167,438
					DSF0000867029	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:Elevator	2018	1,141,774
					DSF0000797100	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	2,104,037
					DSF0000821605	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
					DSF0000912527	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,074
					DSF0000754569	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	12,718,228
					DSF0000909543	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	260,000
					DSF0000798647	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	13,449,359

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X440	DSF0000821913		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	4,105,172
				DSF0000820271		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink	2016	212,822
			X440	DSF0000866080		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			X351	DSF0000800198		New/Retrofit Telephone/Intercom Systems	2015	714,146
			X351	DSF0000800257		Classroom Connectivity	2015	556,133
				DSF0000867078		IP Surveillance Camera Installation	2018	699,104
<b>DEWITT CLINTON HS Total:</b>								<b>\$52,050,955</b>
78X	Bronx	X445		<b>BRONX HS OF SCIENCE</b>				
				DSF0000911899		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	403,107
			X445	DSF0000799896		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	5,374,372
			X445	DSF0000844088		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,947,647
				DSF0000797127		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	244,892

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799723	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	498,438
			X445		DSF0000864171	<i>State of Good Repair - System Replacements - Gymnasium Upgrade</i>	2018	2,450,625
						INTERIOR:GYMNASIUM:Ceiling		
						INTERIOR:GYMNASIUM:Walls		
			X445		DSF0000820296	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
					DSF0000912190	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	78,935
			X445		DSF0000822171	<i>State of Good Repair - System Replacements - Parapets</i>	2017	2,966,324
						EXTERIOR:PARAPETS		
			X445		DSF0000820291	<i>State of Good Repair - System Replacements - Roofs</i>	2017	7,453,983
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						<i>Other</i>		
					DSF0000868107	IP Surveillance Camera Installation	2019	631,752
<b>BRONX HS OF SCIENCE Total:</b>								<b>\$22,194,861</b>
78X	Bronx	X450		<b>ADLAI E. STEVENSON EDUCATIONAL CAMPUS</b>				
					DSF0000799901	<i>Safety and Security - Safety and Security - Safety Systems</i>	2015	1,425,828
					DSF0000889345	<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2019	116,660

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
					DSF0000799676	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	311,693
					DSF0000797153	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2015	582,557
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
				X312	DSF0000866285	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2018	2,973,950
					DSF0000868312	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	672,428
				X295	DSF0000797155	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	1,161,822
						EXTERIOR:EXTERIOR WALLS		
					DSF0000774426	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2015	3,737,663
						INTERIOR:GYMNASIUM:Ceiling		
						INTERIOR:GYMNASIUM:Door(s)		
						INTERIOR:GYMNASIUM:Floor Finish		
						INTERIOR:GYMNASIUM:Seating		
						INTERIOR:GYMNASIUM:Walls		
				X312	DSF0000886777	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	211,637

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000774413	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	9,996,848
					DSF0000820322	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2017	233,629
						<b>Other</b>		
					DSF0000843860	IP Surveillance Camera Installation	2018	764,130
					DSF0000774423	Ansul Systems	2015	582,351
<b>ADLAI E. STEVENSON EDUCATIONAL CAMPUS Total:</b>								<b>\$22,771,196</b>
78X	Bronx	X451		<b>STEVENSON HS AF</b>				
			X321		DSF0000842251	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2017	213,392
<b>STEVENSON HS AF Total:</b>								<b>\$213,392</b>
78X	Bronx	X455		<b>HARRY S. TRUMAN HS</b>				
					DSF0000777424	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2015	479,516
					DSF0000820334	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,863,261

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X455		DSF0000888827	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	282,665
					DSF0000844139	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	4,657,920
					DSF0000842273	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System	2018	891,469
					DSF0000842259	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	172,401
					DSF0000820343	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink	2016	218,826
						<b>Other</b>		
					DSF0000867079	IP Surveillance Camera Installation	2018	973,463
							<b>HARRY S. TRUMAN HS Total:</b>	<b>\$9,539,521</b>
78X	Bronx	X460		<b>HS OF LAW, GOV'T &amp; JUSTICE</b>				
					DSF0000844732	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	193,359
					DSF0000912204	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	751,147
							<b>HS OF LAW, GOV'T &amp; JUSTICE Total:</b>	<b>\$944,506</b>
78X	Bronx	X465		<b>EAGLE ACADEMY FOR YOUNG MEN</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X231		DSF0000889550	IP Surveillance Camera Installation	2019	39,443
							<b>EAGLE ACADEMY FOR YOUNG MEN Total:</b>	<b>\$39,443</b>
78X	Bronx	X470		<b>SOUTH BRONX EDUCATIONAL CAMPUS (OLD 38)</b>				
					DSF0000799677	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	203,840
					DSF0000867010	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	12,000
			X473		DSF0000801047	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	39,918
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT GAS SERVICE:GAS PRESSURE BOOSTER HEATING		
					DSF0000820364	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	127,632
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						<i>Other</i>		
					DSF0000867080	IP Surveillance Camera Installation	2018	373,784
							<b>SOUTH BRONX EDUCATIONAL CAMPUS (OLD 38) Total:</b>	<b>\$757,174</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78X	Bronx	X471		<b>SOUTH BRONX HS AF</b>	DSF0000820378	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2018	9,537,354
						ATHLETIC FIELD:EXTERIOR LIGHTING		
						ATHLETIC FIELD:LOCAL SOUND SYSTEM		
						ATHLETIC FIELD:SCOREBOARD		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						EXTERIOR:DOORS:DOORS AND FRAMES		
						EXTERIOR:PARAPETS		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
						GROUNDING SYSTEM		
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
						SECURITY:INTRUSION ALARM		
						SITE:PAVING - STUDENT USE:Asphalt		
						SITE:RETAINING WALLS		
						<b>SOUTH BRONX HS AF Total:</b>		<b>\$9,537,354</b>
78X	Bronx	X475		<b>JOHN F. KENNEDY HS</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X213	DSF0000821771		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	78,520
			X213	DSF0000821772		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	78,520
			X546	DSF0000821773		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	39,977
			X213	DSF0000843886		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	252,340
			X284	DSF0000843887		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	17,044
			X397	DSF0000843888		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	220,091

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X546		DSF0000843889	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	22,620
			X284		DSF0000843921	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	216,864
			X477		DSF0000843922	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	195,996
			X546		DSF0000843924	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	195,996
			X475		DSF0000823597	<b>Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	4,285,869
					DSF0000823598	<b>Science Lab Upgrades</b>	2016	3,685,453

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X477	DSF0000823599		SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent <b>Interior Spaces</b>	2016	7,396,230
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
			X475	DSF0000820383		INTERIOR:STAIRS/RAMPS: INTERIOR <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,302,011
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
				DSF0000797223		INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	263,700
				DSF0000820380		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,496,002
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			X475	DSF0000799534		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,543,113

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000774499	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging	2016	2,380,425
			X475		DSF0000797229	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2017	9,910,547
					DSF0000799859	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	197,283
					DSF0000820386	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	967,327
			X475		DSF0000820385	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,651,839
			X475		DSF0000820391	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	150,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X546		DSF0000866081	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
					DSF0000777221	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2017	1,132,198
						<i>Other</i>		
					DSF0000800298	IP Surveillance Camera Installation	2015	1,134,816
<b>JOHN F. KENNEDY HS Total:</b>								<b>\$38,967,510</b>
78X	Bronx	X476		<b>KENNEDY HS AF</b>				
			X475		DSF0000843758	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</i>	2016	775,290
<b>KENNEDY HS AF Total:</b>								<b>\$775,290</b>
78X	Bronx	X600		<b>ALFRED E. SMITH HS</b>				
			X600		DSF0000775834	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Room Conversions / Partitioning	2019	7,694,760
					DSF0000799356	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Room Conversions / Partitioning	2019	4,245,052
					DSF0000821609	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	479,066

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868264	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	21,475
			X381		DSF0000797255	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	58,794
					DSF0000799860	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	292,599
					DSF0000820412	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351
							<b>ALFRED E. SMITH HS Total:</b>	<b>\$12,893,097</b>
78X	Bronx	X650		<b>JANE ADDAMS HS</b>				
					DSF0000911898	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	273,688
					DSF0000797270	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	457,612
					DSF0000820436	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains	2016	49,935

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000864303	<b>State of Good Repair - System Replacements - Electrical Systems</b> EMERGENCY GENERATOR SET GROUNDING SYSTEM PANEL BOARD	2018	277,535
			X559		DSF0000866146	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000891065	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
			X650		DSF0000800199	New/Retrofit Telephone/Intercom Systems	2015	287,649
							<b>JANE ADDAMS HS Total:</b>	<b>\$1,616,609</b>
78X	Bronx	X655		<b>SAMUEL GOMPERS VOC HS</b>				
			X259		DSF0000890619	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	3,302,753
			X557		DSF0000843925	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	108,432
			X259		DSF0000865794	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	50,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Bronx  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X655		DSF0000820446	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	2,798,307
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000798448	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,266,154
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X557		DSF0000886914	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
			X655		DSF0000844007	<b>State of Good Repair - System Replacements - Windows</b>	2018	2,005,520
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			X208		DSF0000800200	New/Retrofit Telephone/Intercom Systems	2015	478,772
			X557		DSF0000822041	New/Retrofit Telephone/Intercom Systems	2015	478,772
							<b>SAMUEL GOMPERS VOC HS Total:</b>	<b>\$10,889,154</b>
78X	Bronx	X660		<b>GRACE H. DODGE VOC HS</b>				
			X660		DSF0000754499	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	3,111,972



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
					DSF0000799678	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	179,762	
					DSF0000886936	<i>State of Good Repair - System Replacements - Containerization</i>	2019	191,111	
						SITE:CONTAINERIZATION			
					DSF0000868314	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	4,729	
						<i>Other</i>			
					DSF0000868108	IP Surveillance Camera Installation	2019	465,989	
<b>GRACE H. DODGE VOC HS Total:</b>								<b>\$3,953,563</b>	
78X	Bronx	X790		<b>MOTT HAVEN EDUCATIONAL CAMPUS</b>					
			X188		DSF0000821767	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	48,201	
			X548		DSF0000821768	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	39,618	
			X188		DSF0000865753	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	45,000	

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X547	DSF0000865754		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	45,000
			X548	DSF0000865755		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	45,000
				DSF0000889025		<i>State of Good Repair - System Replacements - Containerization</i> COMPACTOR	2019	191,111
			X527	DSF0000800261		<i>Other</i> Classroom Connectivity	2015	208,145
				DSF0000800102		IP Surveillance Camera Installation	2015	342,437
<b>MOTT HAVEN EDUCATIONAL CAMPUS Total:</b>								<b>\$964,512</b>
78X	Bronx	X839		<b>BRONX HS FOR THE VISUAL ARTS</b>				
				DSF0000799486		<i>Low-Voltage Electrical System</i> FIRE ALARM SYSTEM	2018	2,302,512
				DSF0000731467		<i>State of Good Repair - Building Upgrade - Flood Elimination</i> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	4,008,190
<b>BRONX HS FOR THE VISUAL ARTS Total:</b>								<b>\$6,310,702</b>
78X	Bronx	X876		<b>BRONX LEADERSHIP ACADEMY</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			X525		DSF0000843791	Classroom Connectivity	2016	243,341
							<b>BRONX LEADERSHIP ACADEMY Total:</b>	\$243,341
78X	Bronx	X884		<b>HEALTH OPPORTUNITIES HS</b>				
						<i>Other</i>		
			X670		DSF0000889552	IP Surveillance Camera Installation	2019	42,240
							<b>HEALTH OPPORTUNITIES HS Total:</b>	\$42,240
78X	Bronx	X905		<b>HS OF AMERICAN STUDIES</b>				
						<i>Other</i>		
			X696		DSF0000865935	New/Retrofit Telephone/Intercom Systems	2017	119,215
							<b>HS OF AMERICAN STUDIES Total:</b>	\$119,215
78X	Bronx	X972		<b>SOUNDVIEW EDUCATIONAL CAMPUS</b>				
						<i>Other</i>		
			X519		DSF0000800203	New/Retrofit Telephone/Intercom Systems	2015	268,989
			X519		DSF0000822042	New/Retrofit Telephone/Intercom Systems	2015	268,989
			X519		DSF0000889553	IP Surveillance Camera Installation	2019	38,594
							<b>SOUNDVIEW EDUCATIONAL CAMPUS Total:</b>	\$576,572
78X	Bronx	X973		<b>M.S./H.S. 270</b>				
						<i>Other</i>		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Bronx**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000888958	IP Surveillance Camera Installation	2019	284,908
							<b>M.S./H.S. 270 Total:</b>	<b>\$284,908</b>
78X	Bronx	X988		<b>LAFAYETTE ACADEMIES</b>				
						<i>Other</i>		
			X966		DSF0000865936	Classroom Connectivity	2017	153,248
							<b>LAFAYETTE ACADEMIES Total:</b>	<b>\$153,248</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Brooklyn Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.00	0.00	0.00	0.00	0.00	0.01
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	37.85	29.20	43.33	40.63	62.98	214.00
3. Climate Control	10.27	7.20	12.67	13.38	18.44	61.96
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	25.60	14.67	9.80	15.47	9.17	74.71
7. Lighting Fixtures	48.68	51.91	4.17	1.14	1.20	107.10
8. Elevators and Escalators	2.20	0.13	0.14	4.08	0.60	7.14
9. Reinforcing Cinder Concrete Slabs	5.92	0.12	0.39	0.26	0.10	6.80
10. Flood Elimination	46.40	14.42	35.21	34.40	40.78	171.21
11. Air Conditioning Retrofit	1.66	0.20	0.03	0.07	0.01	1.98
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	1.45	5.28	4.09	1.09	0.79	12.70
14. Interior Spaces	11.06	5.07	2.30	8.67	1.16	28.26
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	12.80	14.39	2.21	8.78	2.31	40.48
2. Playground Redevelopment	3.37	8.74	9.95	6.22	5.37	33.65
3. Swimming Pools	0.07	0.03	12.71	0.67	0.85	14.33
E. System Replacements						
1. Roofs	40.28	38.52	32.06	103.76	87.81	302.44
2. Parapets	37.99	27.29	24.66	71.98	57.98	219.89
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	28.81	11.39	24.23	46.40	34.38	145.21
5. Exterior Masonry	72.79	61.57	79.98	209.11	135.90	559.34
6. Electrical Systems	12.49	3.49	1.43	6.77	13.04	37.23
7. Heating Plant Upgrade	40.35	9.39	14.99	21.80	20.01	106.54
8. Domestic Piping	2.45	6.51	1.12	15.14	2.68	27.91
9. Toilets - Students	0.28	11.04	2.61	4.01	14.37	32.32

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Brooklyn Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
E. System Replacements						
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.96	0.30	0.51	0.46	0.24	2.47
12. Paved Area - Blacktop	1.82	1.49	0.42	0.50	0.11	4.35
13. Paved Area - Concrete	3.83	0.00	0.16	0.88	0.70	5.58
14. Fencing	0.03	0.00	0.01	0.23	0.00	0.27
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.03	0.00	0.00	0.00	0.28	0.32
17. Auditorium Upgrade	1.05	0.26	1.41	3.14	0.92	6.78
18. Gymnasium Upgrade	0.14	0.18	0.72	0.64	0.24	1.91
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.17	0.16	0.02	0.91	4.69	5.95
<i>I. State of Good Repair Yearly Totals:</i>	450.81	322.95	321.32	620.60	517.15	
						<b><i>I. State of Good Repair Total: 2,232.82</i></b>
<b>II. System Expansion</b>						
A. New Construction-Additional Capacity						
1. New Schools	30.34	5.08	194.30	175.50	164.61	569.84
2. Building Additions	0.52	4.59	147.12	120.51	57.94	330.68
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	9.80	3.80	17.45	15.95	3.51	50.51
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
9. 3-K Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	8.19	61.94	70.13
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.00	0.00	1.58	1.24	9.33	12.15

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Brooklyn Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>II. System Expansion</b>						
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	9.07	0.31	24.82	86.29	51.26	171.76
F. Replacements						
1. Replacements - New	0.09	0.03	0.02	0.05	0.41	0.60
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Lease	0.11	0.09	0.03	0.00	0.00	0.23
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>II. System Expansion Yearly Totals:</i>	49.94	13.91	385.33	407.74	348.98	
						<b>II. System Expansion Total: 1,205.90</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions / Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrade	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>III. Educational Enhancements Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>III. Educational Enhancements Total: 0.00</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	1.36	0.00	0.31	0.25	0.00	1.92
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>IV. Safety and Security Yearly Totals:</i>	1.36	0.00	0.31	0.25	0.00	
						<b>IV. Safety and Security Total: 1.92</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Brooklyn Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
<i>V. Ancillary Facilities Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>V. Ancillary Facilities Total: 0.00</b>
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	3.98	6.93	22.40	34.30	32.16	99.76
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>	3.98	6.93	22.40	34.30	32.16	
						<b>VI. Emergency, Unspecified and Misc. Total: 99.76</b>
<b>Yearly Totals for Brooklyn</b>	506.08	343.79	729.36	1,062.88	898.29	
						<b>Brooklyn Grand Total: \$3,540.40</b>



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
Borough of Brooklyn  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	13	DSF0000687093 THE DOCK STREET EDUCATIONAL COMPLEX	333	May-12	May-15	Jul-16	38.20	3.57	34.63	0.00
*	15	DSF0000798185 P.S. 32 ADDITION	436	Mar-15	Jun-17	Jul-20	102.67	0.09	83.74	18.85
*L	15	DSF0000798184 EDUCATIONAL CAMPUS @ 500 19TH STREET	378	Mar-16	Jul-17	Sep-17	27.53	0.00	22.24	5.29
		§ Total Estimated Cost								
*L	15	DSF0000799396 P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL	113	Jan-14	Jul-14	Jul-16	11.54	0.12	11.42	0.00
*	15	DSF0000798182 P.S. @ 4302 4TH AVENUE	332	Jun-17	Jun-19	Jun-22	99.22	0.00	79.74	19.48
*	15	DSF0000843828 P.S. @ 836-841 5TH AVENUE	404	Aug-17	Apr-19	Apr-21	95.01	0.00	75.53	19.49
*L	15	DSF0000866093 P.S. @ 736 48TH STREET	224	Oct-17	Jun-18	Sep-18	15.16	0.00	14.23	0.93
*	15	DSF0000798183 P.S. @ 4513 8TH AVENUE	328	Aug-17	Apr-19	Sep-21	95.31	0.04	80.87	14.40
*	19	DSF0000822081 P.S./I.S. @ 3269 ATLANTIC AVENUE	1,000	Jul-16	Jun-18	Sep-20	133.16	0.00	105.64	27.52
*	20	DSF0000798189 P.S. 127 ADDITION	364	Feb-17	Jul-18	Aug-21	79.67	0.00	64.05	15.61
*	20	DSF0000798186 P.S. @ 270 59TH STREET	976	Apr-15	Jun-17	Mar-20	143.45	0.10	121.31	22.04
*	21	DSF0000798193 P.S. 97 ADDITION	468	Mar-17	Jun-18	Jun-21	71.39	0.00	54.86	16.53
*	21	DSF0000798192 P.S. 101 ADDITION	456	May-15	Nov-16	Jun-19	87.08	0.00	78.82	8.25
*	22	DSF0000798194 P.S. 254 ADDITION	416	Aug-17	Apr-19	Jun-21	69.23	0.00	49.48	19.75

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Pre-Kindergarten Initiative Projects**  
**Borough of Brooklyn**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	13	DSF0000821675 THE DOCK STREET EDUCATIONAL COMPLEX	72	Dec-14	May-15	Jul-16	5.84	0.00	5.84	0.00
* L	15	DSF0000821918 EDUCATIONAL CAMPUS @ 500 19TH STREET	288	Feb-15	Mar-15	Aug-15	5.30	0.00	5.30	0.00
		§ Total Estimated Cost								
* L	15	DSF0000822214 PRE-K CENTER @ 219 25TH STREET	72	Jul-15	Apr-16	Sep-17	10.74	0.00	10.74	0.00
* L	15	DSF0000821832 PRE-K CENTER @ 305-307 THIRD AVENUE	54	Mar-15	Nov-15	Aug-16	9.69	0.00	9.69	0.00
* L	15	DSF0000821928 PRE-K CENTER @ 173 25TH STREET	108	Mar-15	May-15	Aug-15	8.24	0.00	8.24	0.00
		§ Total Estimated Cost								
* L	15	DSF0000822084 PRE-K CENTER @ 131 UNION STREET	36	Jun-15	Feb-16	Sep-16	7.28	0.00	7.28	0.00
*	20	DSF0000821654 PRE-K CENTER @ 8501 5TH AVENUE	18	Oct-14	Apr-15	Sep-15	5.53	0.00	5.53	0.00
* L	20	DSF0000821713 PRE-K CENTER @ 2165 71ST STREET	90	Dec-14	May-15	Aug-16	17.21	0.00	17.42	-0.21
* L	20	DSF0000800304 PRE-K CENTER @ 550 59TH STREET	162	Jul-14	Dec-15	Aug-16	9.16	0.00	9.16	0.00
*	20	DSF0000821813 PRE-K CENTER @ 369 93RD STREET	252	Feb-15	Jun-16	Mar-18	38.94	0.00	38.94	0.00
*	20	DSF0000821967 PRE-K CENTER @ 140A 58TH STREET	126	Apr-15	Jun-15	Sep-15	14.57	0.00	14.57	0.00
* L	20	DSF0000821958 PRE-K CENTER @ 1423 62ND STREET	324	Apr-15	May-16	Aug-17	32.86	0.00	32.86	0.00
* L	20	DSF0000800123 PRE-K CENTER @ 1258 65TH STREET	126	Jun-14	Dec-14	Jul-15	12.31	0.00	12.31	0.00
* L	20	DSF0000822082 PK/3K CENTER @ 21 BAY 11TH STREET	54	Apr-15	Jan-16	Sep-16	11.09	0.00	11.09	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Pre-Kindergarten Initiative Projects**  
**Borough of Brooklyn**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	20	DSF0000822014 PK/3K CENTER @ 21 BAY 11TH STREET	234	Jan-15	Aug-15	Sep-15	0.57	0.00	0.57	0.00
* L	20	DSF0000800057 PRE-K CENTER @ 1355 84TH STREET	90	Jun-14	Jan-15	Sep-15	12.13	0.00	12.13	0.00
* L	20	DSF0000822162 PRE-K CENTER @ 1355 84TH STREET	72	May-15	Aug-15	Sep-16	0.40	0.00	0.40	0.00
* L	20	DSF0000800047 PRE-K CENTER @ 1668 46TH STREET	180	Jun-14	Nov-14	Jul-15	6.77	0.02	6.74	0.00
* L	20	DSF0000822086 PRE-K CENTER @ 7401 FORT HAMILTON PARKWAY	270	May-15	Jul-15	Sep-15	13.11	0.00	12.45	0.65
		§ Total Estimated Cost								
* L	21	DSF0000800230 PRE-K CENTER @ 2202 60TH STREET	108	Jun-14	Jan-15	Jul-15	5.16	0.00	5.16	0.00
* L	21	DSF0000822037 PRE-K CENTER @ 385 AVENUE W	126	Apr-15	May-15	Sep-15	3.98	0.00	3.98	0.00
		§ Total Estimated Cost								
* L	21	DSF0000821960 PRE-K CENTER @ 1223 CONEY ISLAND AVENUE	72	Apr-15	Jan-16	Jul-17	10.13	0.00	10.12	0.01
* L	21	DSF0000821873 PRE-K CENTER @ 10 BOUCK COURT	180	Mar-15	Jan-16	Aug-16	15.62	0.00	15.62	0.00
* L	21	DSF0000800303 PRE-K CENTER @ 1215 AVENUE X	108	Jul-14	Dec-14	Aug-15	5.42	0.00	5.42	0.00
* L	22	DSF0000822024 PRE-K CENTER @ 3610 GLENWOOD ROAD	144	Mar-15	May-15	Sep-15	13.08	0.00	13.08	0.00
		§ Total Estimated Cost								
* L	22	DSF0000822027 PRE-K CENTER @ 1340 EAST 29TH STREET	252	Mar-15	May-15	Sep-15	14.07	0.00	14.07	0.00
		§ Total Estimated Cost								
* L	22	DSF0000800113 PRE-K CENTER @ 1139 CONEY ISLAND AVENUE	144	Jun-14	Dec-14	Jul-15	12.18	0.00	12.18	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**3-K Initiative Projects**  
**Borough of Brooklyn**  
 (in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	20	DSF0000889666 PK/3K CENTER @ 21 BAY 11TH STREET	45	Oct-18	Jun-19	Apr-20	10.11	0.00	10.11	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
 L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Class Size Reduction Projects**  
**Borough of Brooklyn**  
 (in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	78K	DSF0000844038	EAST NY FAMILY ACADEMY	602	Apr-17	Aug-18	Sep-21	99.60	0.00	79.53	20.07

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
 L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
13	Brooklyn	K003		<b>P.S. 3</b>				
					DSF0000798244	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	5,382,730
					DSF0000798245	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2016	1,626,889
					DSF0000755394	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,013,161
					DSF0000755393	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	2,163,744
					DSF0000868177	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	247,380
					DSF0000801203	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2015	150,000
			K003		DSF0000865952	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 3 Total:</b>	\$10,798,696
13	Brooklyn	K008		<b>P.S. 8</b>				
					DSF0000777455	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	64,193
					DSF0000798390	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	442,539
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 8 Total:</b>	\$506,732
13	Brooklyn	K009		<b>P.S. 9</b>				
			K009		DSF0000889353	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	144,781
			K009		DSF0000777935	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			K009		DSF0000865730	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
						<b>Other</b>		
			K009		DSF0000889202	New/Retrofit Telephone/Intercom Systems	2018	204,741
							<b>P.S. 9 Total:</b>	\$697,075
13	Brooklyn	K011		<b>P.S. 11</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868551	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	508,515
					DSF0000799680	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	178,531
					DSF0000868555	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	1,647,354
					DSF0000868554	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	2,885,571
					DSF0000868553	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,417,351
							<b>P.S. 11 Total:</b>	<b>\$9,637,322</b>
13	Brooklyn	K020		<b>P.S. 20</b>				
			K020		DSF0000846039	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2017	130,917



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K020		DSF0000868140	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2018	258,908
						INTERIOR:GYMNASIUM:Floor Finish		
			K020		DSF0000824038	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	56,611
						GAS SERVICE:Gas Distribution Piping		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						HEATING:Heating Coil In Ductwork		
						HEATING:Radiator/Convactor/Fin Tube		
						HEATING:Steam Heating		
						HEATING:Unit Heater/Cabinet Heater		
			K020		DSF0000822131	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	154,311
						<b>Other</b>		
			K020		DSF0000889203	New/Retrofit Telephone/Intercom Systems	2018	194,189
							<b>P.S. 20 Total:</b>	<b>\$794,936</b>
13	Brooklyn	K044		<b>P.S. 44</b>				
					DSF0000710245	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	5,215,060
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000710254	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,717,269
					DSF0000756027	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	998,654
			K044		DSF0000801839	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY	2017	623,265
					DSF0000866770	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,603
			K044		DSF0000889582	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 44 Total:</b>	<b>\$8,775,643</b>
13	Brooklyn	K046		<b>P.S. 46</b>				
			K046		DSF0000821818	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Auditorium Upgrade INTERIOR:AUDITORIUM:Stage:Stage	2017	940,457

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K046		DSF0000869074	INTERIOR:AUDITORIUM:Stage:Stage Curtains <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	348,007
			K046		DSF0000889583	GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 46 Total:</b>	\$1,503,256
13	Brooklyn	K054		<b>P.S. 54</b>				
			K054		DSF0000824489	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	68,766
			K054		DSF0000867121	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	194,851
							<b>P.S. 54 Total:</b>	\$263,617
13	Brooklyn	K056		<b>P.S. 56</b>				
					DSF0000799685	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	280,106

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K056		DSF0000869208	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR WALLS	2019	5,222,910
			K056		DSF0000889350	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	3,100,799
			K056		DSF0000869207	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	8,587,492
			K056		DSF0000867110	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	2,932,024
							<b>P.S. 56 Total:</b>	\$20,123,331
13	Brooklyn	K067		<b>P.S. 67</b>				
					DSF0000799686	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	316,793
			K067		DSF0000778830	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			K067		DSF0000869312	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
					DSF0000802160	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	325,478

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
							<b>P.S. 67 Total:</b>	\$866,451
13	Brooklyn	K093		<b>P.S. 93</b>				
					DSF0000799687	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	150,399
			K093		DSF0000779133	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
							<b>P.S. 93 Total:</b>	\$182,058
13	Brooklyn	K113		<b>I.S. 113</b>				
					DSF0000821885	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	106,183
						CLIMATE CONTROL SYSTEM		
			K113		DSF0000779463	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	126,965
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K113		DSF0000865963	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>I.S. 113 Total:</b>	\$447,940
13	Brooklyn	K117		<b>I.S. 117</b>				
			K412		DSF0000777712	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,175,915
					DSF0000802874	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i> CAFETERIA:LOCAL SOUND SYSTEM INTERIOR:CAFETERIA:Floor Finish	2019	479,066
					DSF0000757040	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:EXTERIOR WALLS	2016	6,182,794
					DSF0000779533	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,274,728
					DSF0000779532	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOFING:Roofing	2016	4,845,390
						<b>Other</b>		
			K412		DSF0000889403	IP Surveillance Camera Installation	2019	40,480
							<b>I.S. 117 Total:</b>	\$14,998,373
13	Brooklyn	K258		<b>I.S. 258</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K140		DSF0000843992	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	238,503
			K140		DSF0000827557	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> PUBLIC ADDRESS SYSTEM	2017	1,247,766
					DSF0000781910	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation VENTILATION:EXHAUST FAN	2015	297,763
						<i>Other</i>		
			K517		DSF0000889416	IP Surveillance Camera Installation	2019	40,181
							<b>I.S. 258 Total:</b>	<b>\$1,824,213</b>
13	Brooklyn	K265		<b>I.S. 265</b>				
			K265		DSF0000775954	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	876,806
			K265		DSF0000775955	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	766,424
			K265		DSF0000799495	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	888,411
			K265		DSF0000888768	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,550,357

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K265		DSF0000843906	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2016	85,775
					DSF0000798255	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,081,826
					DSF0000782007	<i>State of Good Repair - Building Upgrade - Climate Control</i> CLIMATE CONTROL SYSTEM	2017	1,929,275
			K265		DSF0000782017	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			K265		DSF0000889418	<i>Other</i> IP Surveillance Camera Installation	2019	47,078
							<b>I.S. 265 Total:</b>	<b>\$11,257,632</b>
13	Brooklyn	K270		<b>P.S. 270</b>				
					DSF0000799556	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	133,993
					DSF0000799750	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	41,237
			K270		DSF0000782086	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K270		DSF0000872345	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
							<b>P.S. 270 Total:</b>	\$399,389
13	Brooklyn	K282		<b>P.S. 282</b>				
					DSF0000912239	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	55,465
					DSF0000868200	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	106,433
			K282		DSF0000872509	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING:Heating Coil In Ductwork HEATING:Radiator/Convector/Fin Tube HEATING:Steam Heating	2019	329,825
					DSF0000805576	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	150,000
							<b>P.S. 282 Total:</b>	\$641,723
13	Brooklyn	K287		<b>P.S. 287</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K287		DSF0000843994	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	108,144
					DSF0000805651	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	886,254
					DSF0000872579	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	4,732,729
					DSF0000872578	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	4,280,800
					DSF0000872577	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,963,344
							<b>P.S. 287 Total:</b>	\$11,971,271
13	Brooklyn	K305		<b>P.S. 305</b>				
					DSF0000866832	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,000
					DSF0000805916	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	198,937

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 305 Total:</b>	\$204,937
13	Brooklyn	K307		<b>P.S. 307</b>				
					DSF0000866833	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	19,533
					DSF0000777710	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	3,278,018
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			K307		DSF0000782661	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	56,043
					DSF0000782658	<b>State of Good Repair - System Replacements - Parapets</b>	2016	3,257,285
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000782657	<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,351,398
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
					DSF0000805961	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	159,427
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 307 Total:</b>	\$9,121,704
14	Brooklyn	K016		<b>P.S. 16</b>				
			K016	DSF0000843891		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	61,811
			K016	DSF0000868645		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	1,889,735
			K016	DSF0000868649		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	623,313
			K016	DSF0000868648		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	628,534
			K016	DSF0000868647		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	2,557,098
			K016	DSF0000865954		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 16 Total:</b>	\$5,913,220
14	Brooklyn	K017		<b>P.S. 17</b>				
			K017		DSF0000845625	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	1,068,292
					DSF0000777457	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	85,183
					DSF0000799536	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	101,525
					DSF0000799741	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	27,636
			K017		DSF0000778097	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	990,642
						GROUNDING SYSTEM SERVICE SWITCH SWITCHBOARD TRANSFORMER		
					DSF0000755637	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	6,590,075
						Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
			K017		DSF0000866101	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K017		DSF0000778098	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	121,140
							<b>P.S. 17 Total:</b>	\$9,062,183
14	Brooklyn	K018		<b>P.S. 18</b>				
			K018		DSF0000801464	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	129,966
						<b>Other</b>		
			K018		DSF0000867120	New/Retrofit Telephone/Intercom Systems	2018	134,816
							<b>P.S. 18 Total:</b>	\$264,782
14	Brooklyn	K019		<b>P.S. 19</b>				
					DSF0000821883	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	114,396
							<b>P.S. 19 Total:</b>	\$114,396
14	Brooklyn	K023		<b>P.S. 23</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000865887	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	73,911
			K023		DSF0000778207	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			K023		DSF0000866076	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	429,587
							<b>P.S. 23 Total:</b>	<b>\$535,178</b>
14	Brooklyn	K031		<b>P.S. 31 (OLD 126)</b>				
					DSF0000777458	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	78,277
					DSF0000798403	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	686,420
					DSF0000866767	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	39,410
			K031		DSF0000778318	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2017	3,748,336
			K031		DSF0000821872	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,541,114

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K031		DSF0000801662	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	173,031
							<b>P.S. 31 (OLD 126) Total:</b>	\$6,266,588
14	Brooklyn	K033		<b>I.S. 33</b>				
			K368		DSF0000844696	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,224,923
			K368		DSF0000821753	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	35,576
			K330		DSF0000821776	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	33,343
			K330		DSF0000843894	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	233,857
			K368		DSF0000843895	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	359,160



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			K330		DSF0000843926	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	325,800
						Technology		
			K368		DSF0000843927	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	108,432
						Technology		
			K368		DSF0000888770	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	46,200
						Technology		
			K368		DSF0000888772	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	35,549
						Science Lab Upgrades		
			K367		DSF0000890591	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	7,179,907
						HEATING PLANT:Boiler Auxiliaries		
						HEATING:Steam Heating		
			K367		DSF0000868912	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	4,326,959
						CLIMATE CONTROL SYSTEM		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000778354	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2016	233,188
			K330		DSF0000777709	<b>State of Good Repair - System Replacements - Kitchen Areas</b> INTERIOR:KITCHEN/WARMING PANTRY:Floor Finish	2016	2,173,833
			K322		DSF0000822133	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2015	125,055
			K367		DSF0000889397	<b>Other</b> IP Surveillance Camera Installation	2019	40,230
			K330		DSF0000821682	Ansul Systems	2016	416,583
							<b>I.S. 33 Total:</b>	<b>\$16,898,595</b>
14	Brooklyn	K034		<b>P.S. 34</b>				
					DSF0000798250	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	4,586,977
					DSF0000798252	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,096,349
			K034		DSF0000801712	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	983,361

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000755905	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	818,380
					DSF0000801718	EXTERIOR:STAIRS/RAMPS: EXTERIOR <b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	165,212
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			K034		DSF0000889204	New/Retrofit Telephone/Intercom Systems	2018	146,561
							<b>P.S. 34 Total:</b>	\$7,796,840
14	Brooklyn	K049		<b>I.S. 49</b>				
					DSF0000890567	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	8,865
			K586		DSF0000865956	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
					DSF0000800059	IP Surveillance Camera Installation	2015	349,471
							<b>I.S. 49 Total:</b>	\$573,128
14	Brooklyn	K050		<b>J.H.S. 50</b>				
			K050		DSF0000844694	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,835,629

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K050		DSF0000866753	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2017	190,154
			K050		DSF0000888859	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2018	36,000
					DSF0000866772	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	2,580
							<b>J.H.S. 50 Total:</b>	<b>\$2,064,363</b>
14	Brooklyn	K059		<b>P.S. 59</b>				
			K059		DSF0000911884	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	531,136
			K059		DSF0000843896	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2016	73,964
			K059		DSF0000843928	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology</i>	2016	98,340
			K059		DSF0000845602	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	116,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			K059		DSF0000821897	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	164,847
						CLIMATE CONTROL SYSTEM		
							<b>P.S. 59 Total:</b>	<b>\$984,287</b>
14	Brooklyn	K071		<b>I.S. 71</b>				
			K071		DSF0000823625	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	3,212,710
			K071		DSF0000844125	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,439,010
					DSF0000798383	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,985,084
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K071		DSF0000888903	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	126,418
						Waste System		
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
			K071		DSF0000846659	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	149,546
						GAS SERVICE:Gas Distribution Piping		
						HEATING PLANT:Fuel System		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000802198	HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	143,499
			K071		DSF0000889400	<b>Other</b> IP Surveillance Camera Installation	2019	40,114
							<b>I.S. 71 Total:</b>	\$7,096,381
14	Brooklyn	K084		<b>P.S. 84</b>	DSF0000778990	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,318,994
							<b>P.S. 84 Total:</b>	\$1,318,994
14	Brooklyn	K110		<b>P.S. 110</b>	DSF0000798408	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	541,187

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 110 Total:</b>	\$541,187
14	Brooklyn	K120		<b>P.S. 120</b>				
			K368	DSF0000868069		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	117,000
			K120	DSF0000865965		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 120 Total:</b>	\$331,792
14	Brooklyn	K126		<b>J.H.S. 126</b>				
				DSF0000866793		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	8,197
			K126	DSF0000825410		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Unit Heater/Cabinet Heater	2018	109,250
			K126	DSF0000889586		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>J.H.S. 126 Total:</b>	\$332,239
14	Brooklyn	K132		<b>P.S. 132</b>				
					DSF0000779724	<b>State of Good Repair - System Replacements - Floors</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2016	283,697
							<b>P.S. 132 Total:</b>	\$283,697
14	Brooklyn	K147		<b>P.S. 147</b>				
			K147		DSF0000779877	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	3,133,037
					DSF0000757389	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:SIDEWALKS:DOT Sidewalk	2016	844,382
					DSF0000870289	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	9,502,278
			K147		DSF0000822137	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	159,963
							<b>P.S. 147 Total:</b>	\$13,639,660



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
14	Brooklyn	K157		<b>P.S. 157</b>				
			K157		DSF0000780044	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	165,957
							<b>P.S. 157 Total:</b>	\$165,957
14	Brooklyn	K196		<b>P.S. 196</b>				
			K196		DSF0000871071	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	2,054,030
					DSF0000798388	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	943,732
					DSF0000893860	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	1,280,295

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K196		DSF0000848383	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	130,855
						GAS SERVICE:Gas Distribution Piping		
					DSF0000889001	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
			K196		DSF0000893858	<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,024,143
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
					DSF0000804039	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	119,297
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			K196		DSF0000776043	IP Surveillance Camera Installation	2015	555,676
							<b>P.S. 196 Total:</b>	<b>\$8,197,012</b>
14	Brooklyn	K250		<b>P.S. 250</b>				
			K250		DSF0000865978	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 250 Total:</b>	<b>\$214,792</b>
14	Brooklyn	K257		<b>P.S. 257</b>				
					DSF0000821724	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	106,804
						FIXTURES:STUDENT:Toilet		
							<b>P.S. 257 Total:</b>	<b>\$106,804</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
14	Brooklyn	K297		<b>P.S. 297</b>				
			K297	DSF0000888767		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,003,690
				DSF0000866830		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	11,900
				DSF0000799802		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	62,246
				DSF0000805806		<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	146,678
							<b>P.S. 297 Total:</b>	<b>\$1,224,514</b>
14	Brooklyn	K315		<b>P.S. 17 GYM ANNEX</b>				
			K017	DSF0000889554		<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	12,060,364
							<b>P.S. 17 GYM ANNEX Total:</b>	<b>\$12,060,364</b>
14	Brooklyn	K318		<b>I.S. 318</b>				
				DSF0000844027		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,905,290

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866835	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	5,470
			K318		DSF0000782769	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	37,661
					DSF0000801068	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	106,900
						HEATING		
							<b>I.S. 318 Total:</b>	\$2,055,321
14	Brooklyn	K319		<b>P.S. 319</b>				
					DSF0000806083	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	203,708
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 319 Total:</b>	\$203,708
14	Brooklyn	K380		<b>P.S. 380</b>				
					DSF0000806385	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	179,261
						HEATING		
						<b>Other</b>		
			K380		DSF0000889205	New/Retrofit Telephone/Intercom Systems	2018	261,863
							<b>P.S. 380 Total:</b>	\$441,124

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
14	Brooklyn	K673		<b>P.S. 18 GYM ANNEX</b>				
					DSF0000866744	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2018	9,432,713
							<b>P.S. 18 GYM ANNEX Total:</b>	\$9,432,713
14	Brooklyn	K745		<b>P.S. 132 GYM ANNEX</b>				
			K132		DSF0000889556	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,088,469
							<b>P.S. 132 GYM ANNEX Total:</b>	\$10,088,469
15	Brooklyn	K001		<b>P.S. 1</b>				
			K001		DSF0000868414	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2019	946,409
						AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM		
			K001		DSF0000889581	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 1 Total:</b>	\$1,161,201
15	Brooklyn	K010		<b>P.S. 10</b>				
					DSF0000799679	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	294,720
							<b>P.S. 10 Total:</b>	\$294,720

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
15	Brooklyn	K015		<b>P.S. 15</b>				
					DSF0000755590	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	2,431,134
					DSF0000755592	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	4,971,044
					DSF0000777696	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	1,466,221
					DSF0000799892	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	1,249,601
					DSF0000755595	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,567,486
			K015		DSF0000777695	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	6,434,116

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000778072	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2015	1,556,923
			K015		DSF0000801409	VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	117,477
							<b>P.S. 15 Total:</b>	\$19,794,002
15	Brooklyn	K024		<b>P.S. 24</b>	DSF0000844722	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	115,464
					DSF0000912200	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	834,918
					DSF0000823569	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	69,723

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 24 Total:</b>	\$1,020,105
15	Brooklyn	K027		<b>P.S. 27</b>				
					DSF0000798393	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	974,880
					DSF0000866764	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	105,233
					DSF0000755806	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2015	4,749,850
					DSF0000755805	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	4,622,099
			K676		DSF0000801622	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	296,589



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 27 Total:</b>	\$10,748,651
15	Brooklyn	K029		<b>P.S. 29</b>				
					DSF0000801644	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS	2015	128,125
			K029		DSF0000889206	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	177,595
							<b>P.S. 29 Total:</b>	\$305,720
15	Brooklyn	K032		<b>P.S. 32</b>				
			K032		DSF0000822132	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	156,717
							<b>P.S. 32 Total:</b>	\$156,717
15	Brooklyn	K038		<b>P.S. 38</b>				
					DSF0000799682	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	134,594
					DSF0000868969	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	984,210
			K038		DSF0000891709	<b>State of Good Repair - System Replacements - Parapets</b>	2019	405,377

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868968	EXTERIOR:PARAPETS <i>State of Good Repair - System Replacements - Roofs</i>	2019	6,437,067
			K038		DSF0000822134	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	150,000
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 38 Total:</b>	\$8,111,248
15	Brooklyn	K039		<b>P.S. 39</b>	DSF0000798405	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	226,353
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 39 Total:</b>	\$226,353
15	Brooklyn	K051		<b>I.S. 51</b>	DSF0000821884	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	105,534
						CLIMATE CONTROL SYSTEM		
			K051		DSF0000888776	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	593,988
			K051		DSF0000891887	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	3,829,366

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
					DSF0000891886	<b>State of Good Repair - System Replacements - Parapets</b>	2019	2,305,401
			K051		DSF0000891885	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	4,525,545
			K051		DSF0000865957	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>I.S. 51 Total:</b>	\$11,574,626
15	Brooklyn	K058		<b>P.S. 58</b>				
			K058		DSF0000798389	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	5,674,287
			K058		DSF0000798396	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,041,630
							<b>P.S. 58 Total:</b>	\$7,715,917
15	Brooklyn	K088		<b>I.S. 88</b>				
			K088		DSF0000889355	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	172,887

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K088		DSF0000912475	<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2019	200,000
					DSF0000775609	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2017	5,989,338
			K088		DSF0000775610	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2017	2,663,300
			K088		DSF0000869484	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2019	192,804
						AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000868182	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	396,008
					DSF0000802365	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	144,794
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
			K088		DSF0000822135	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	150,052
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>I.S. 88 Total:</b>	<b>\$9,909,183</b>
15	Brooklyn	K094		<b>P.S. 94</b>				
					DSF0000846897	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2018	780,536

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000779148	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,131,733
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000756679	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	588,713
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			K094		DSF0000821882	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	6,003,032
					DSF0000824937	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	89,992
			K094		DSF0000888999	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
					DSF0000846900	<b>State of Good Repair - System Replacements - Windows</b>	2018	4,789,316
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			K094		DSF0000889207	New/Retrofit Telephone/Intercom Systems	2018	212,903

**P.S. 94 Total: \$13,685,209**

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
15	Brooklyn	K107		<b>P.S. 107</b>				
					DSF0000866788	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	26,191
					DSF0000869785	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	2,617,615
						EXTERIOR:EXTERIOR WALLS		
					DSF0000869784	<i>State of Good Repair - System Replacements - Parapets</i>	2018	932,590
						EXTERIOR:PARAPETS		
					DSF0000869783	<i>State of Good Repair - System Replacements - Roofs</i>	2018	2,211,506
						EXTERIOR:ROOF:Roofing		
			K107		DSF0000865962	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>P.S. 107 Total:</b>	<b>\$5,940,631</b>
15	Brooklyn	K124		<b>P.S. 124</b>				
			K124		DSF0000825396	<i>Domestic Piping</i>	2017	266,765
						DOMESTIC WATER SYSTEM		
						FIXTURES:Student:Drinking Fountain		
						FIXTURES:Student:Sink And Fountain Combo Unit		
			K124		DSF0000802950	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	1,152,101
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			K124		DSF0000825394	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	2,159,464
						EXTERIOR:AREAWAY		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			K124		DSF0000843697	<b>State of Good Repair - System Replacements - Parapets</b>	2017	997,992
						EXTERIOR:PARAPETS		
			K124		DSF0000825393	<b>State of Good Repair - System Replacements - Roofs</b>	2017	1,310,052
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			K124		DSF0000779630	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	221,484
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000825397	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	129,728
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 124 Total:</b>	\$6,237,586
15	Brooklyn	K130		<b>P.S. 130</b>				
					DSF0000866794	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	93,918

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000779686	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2017	12,399,131
			K130		DSF0000866084	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	89,632
					DSF0000803013	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	2,173,968
					DSF0000803012	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,505,997
			K130		DSF0000865966	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
			K130		DSF0000822051	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	153,565
							<b>P.S. 130 Total:</b>	<b>\$16,568,940</b>
15	Brooklyn	K131		<b>P.S. 131</b>				
					DSF0000777464	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	152,507
					DSF0000803027	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	1,086,611



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000803025	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	868,236
					DSF0000779700	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	8,622,143
					DSF0000803030	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	4,837,719
					DSF0000803029	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	2,339,969
							<b>P.S. 131 Total:</b>	<b>\$17,907,185</b>
15	Brooklyn	K136		<b>I.S. 136</b>				
					DSF0000912282	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	66,340
			K136		DSF0000889027	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	3,131,783

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000757249	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	1,943,261
					DSF0000775639	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2016	846,561
			K136		DSF0000779760	<b>State of Good Repair - System Replacements - Electrical Systems</b> PANEL BOARD SERVICE SWITCH SWITCHBOARD	2019	2,600,785
					DSF0000868315	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	24,805
			K136		DSF0000870171	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2019	9,185,656
			K136		DSF0000870169	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	2,064,314
			K136		DSF0000847483	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	4,780,834
						<b>Other</b>		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000752460	IP Surveillance Camera Installation	2015	583,434
							<b>I.S. 136 Total:</b>	\$25,227,773
15	Brooklyn	K142		<b>J.H.S. 142</b>				
					DSF0000866757	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,014,094
							<b>J.H.S. 142 Total:</b>	\$5,014,094
15	Brooklyn	K154		<b>P.S. 154</b>				
					DSF0000800302	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling	2015	97,226
					DSF0000798410	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	545,516
					DSF0000866798	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	2,929
					DSF0000803335	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	178,447
							<b>Other</b>	

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K154		DSF0000889208	New/Retrofit Telephone/Intercom Systems	2018	160,365
							<b>P.S. 154 Total:</b>	<b>\$984,483</b>
15	Brooklyn	K169		<b>P.S. 169</b>				
					DSF0000780241	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,109,976
					DSF0000844138	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS FIRED FURNACE	2018	68,765
			K169		DSF0000866108	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
							<b>P.S. 169 Total:</b>	<b>\$1,256,431</b>
15	Brooklyn	K172		<b>P.S. 172</b>				
					DSF0000780299	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	676,390
			K172		DSF0000826042	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	40,661

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Unit Heater/Cabinet Heater		
							<b>P.S. 172 Total:</b>	\$717,051
15	Brooklyn	K230		<b>P.S. 230</b>				
					DSF0000781392	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	859,060
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000849017	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,076,423
						GROUNDING SYSTEM PANEL BOARD		
							<b>P.S. 230 Total:</b>	\$1,935,483
15	Brooklyn	K280		<b>EDUCATIONAL CAMPUS @ 500 19TH STREET</b>				
					DSF0000889658	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	782,094

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
<b>EDUCATIONAL CAMPUS @ 500 19TH STREET Total:</b>								\$782,094	
15	Brooklyn	K293		<b>J.H.S. 293</b>					
					DSF0000821577	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	598,637	
					DSF0000821655	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	1,363,626	
						Library Upgrade			
			K368		DSF0000821777	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	33,343	
						Technology			
					K497	DSF0000843911	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	528,208
						Technology			
			K368		DSF0000843912	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	125,216	
						Technology			
			K368		DSF0000843995	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	108,432	
						Technology			

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K429		DSF0000888897	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	77,000
					DSF0000912376	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	10,001
					DSF0000759888	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	6,287,095
					DSF0000782463	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,860,162
					DSF0000805764	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	5,166,425
			K129		DSF0000822139	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2015	164,131
			K429		DSF0000822052	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	301,379
			K429		DSF0000889424	IP Surveillance Camera Installation	2019	40,584

**J.H.S. 293 Total: \$17,664,239**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000800269	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	6,558,423
					DSF0000806121	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,064,654
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K321		DSF0000806120	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	928,375
						FIRE ALARM SYSTEM		
					DSF0000821725	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	131,369
						FIXTURES:STUDENT:Toilet		
			K321		DSF0000865739	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
						<b>Other</b>		
			K321		DSF0000889209	New/Retrofit Telephone/Intercom Systems	2018	214,549
			K321		DSF0000776049	IP Surveillance Camera Installation	2015	514,636
							<b>P.S. 321 Total:</b>	<b>\$9,727,879</b>
15	Brooklyn	K442		<b>I.S. 442</b>				
			K442		DSF0000889597	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>I.S. 442 Total:</b>	<b>\$214,792</b>
15	Brooklyn	K477		<b>P.S. 172 GYM ANNEX</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K172	DSF0000889559		<b>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</b>	2019	10,806,321
<b>P.S. 172 GYM ANNEX Total:</b>								\$10,806,321
15	Brooklyn	K749		<b>PRE-K CENTER @ 173 25TH STREET</b>				
				DSF0000888716		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2019	322,500
<b>PRE-K CENTER @ 173 25TH STREET Total:</b>								\$322,500
15	Brooklyn	K763		<b>P.S. 118 MAURICE SENDAK COMMUNITY SCHOOL</b>				
				DSF0000799768		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	14,572
<b>P.S. 118 MAURICE SENDAK COMMUNITY SCHOOL Total:</b>								\$14,572
15	Brooklyn	K845		<b>P.S. 295</b>				
				DSF0000784298		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	6,405,074
				DSF0000784296		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	650,173

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000761629	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2017	1,939,779
					DSF0000807597	INTERIOR:STRUCTURAL:ROOF STRUCTURE <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	1,112,195
			K443		DSF0000784302	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Floors</b>	2017	728,283
					DSF0000775989	INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish <b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2017	830,973
					DSF0000807596	INTERIOR:Gymnasium:Flooring <b>State of Good Repair - System Replacements - Parapets</b>	2017	588,737
					DSF0000807595	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2017	388,460
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
							<b>P.S. 295 Total:</b>	<b>\$12,643,674</b>
15	Brooklyn	K908		<b>P.S. 230 ANNEX</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799763	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	18,592
							<b>P.S. 230 ANNEX Total:</b>	\$18,592
16	Brooklyn	K005		<b>P.S. 5</b>				
			K005		DSF0000865953	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
			K005		DSF0000865729	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2018	315,873
							<b>P.S. 5 Total:</b>	\$468,602
16	Brooklyn	K021		<b>P.S. 21</b>				
			K021		DSF0000801513	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY	2018	1,255,384
			K140		DSF0000846047	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork	2017	114,678

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K021	DSF0000801519		HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351
			K021	DSF0000776035		FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS  <b>Other</b> IP Surveillance Camera Installation	2015	527,530
<b>P.S. 21 Total:</b>								<b>\$1,998,943</b>
16	Brooklyn	K025		<b>P.S. 25</b>				
			K025	DSF0000844693		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	974,805
			K025	DSF0000912256		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	175,000
			K025	DSF0000798635		<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT	2015	754,862

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798391	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	977,588
					DSF0000866763	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,189
					DSF0000755763	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2015	3,919,026
			K025		DSF0000889351	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Meter Room Vent	2019	117,171
					DSF0000755762	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2015	1,981,162
					DSF0000755761	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,881,840
			K025		DSF0000889395	<b>Other</b> IP Surveillance Camera Installation	2019	40,047
							<b>P.S. 25 Total:</b>	<b>\$10,824,690</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
16	Brooklyn	K026		<b>P.S. 26</b>				
					DSF0000801089	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	6,553,176
			K026		DSF0000801599	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2017	2,264,006
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000868834	<i>State of Good Repair - System Replacements - Containerization</i>	2019	185,523
						SITE:CONTAINERIZATION		
					DSF0000868178	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	196,954
						<i>Other</i>		
			K026		DSF0000889396	IP Surveillance Camera Installation	2019	40,346
<b>P.S. 26 Total:</b>								<b>\$9,240,005</b>
16	Brooklyn	K035		<b>I.S. 35</b>				
					DSF0000822095	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	10,851,969
			K035		DSF0000889387	<i>Interior Spaces</i>	2019	152,709
					DSF0000799537	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	282,586
					DSF0000912424	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	9,075

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K035		DSF0000868950	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
			K035		DSF0000889210	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	268,006
			K035		DSF0000889433	IP Surveillance Camera Installation	2019	46,978
							<b>I.S. 35 Total:</b>	\$11,803,823
16	Brooklyn	K040		<b>P.S. 40</b>				
					DSF0000799683	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	51,248
					DSF0000866768	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	5,922
							<b>P.S. 40 Total:</b>	\$57,170
16	Brooklyn	K057		<b>J.H.S. 57</b>				
					DSF0000778722	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	64,668
					DSF0000799538	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	201,821
					DSF0000802044	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2017	779,795

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000912419	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	3,729
						<b>Other</b>		
			K057		DSF0000867122	New/Retrofit Telephone/Intercom Systems	2018	262,997
			K057		DSF0000889398	IP Surveillance Camera Installation	2019	40,431
							<b>J.H.S. 57 Total:</b>	<b>\$1,353,441</b>
16	Brooklyn	K081		<b>P.S. 81</b>				
					DSF0000802291	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	782,090
						PUBLIC ADDRESS SYSTEM		
					DSF0000802298	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	134,229
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						<b>Other</b>		
			K081		DSF0000776037	IP Surveillance Camera Installation	2015	528,527
							<b>P.S. 81 Total:</b>	<b>\$1,444,846</b>
16	Brooklyn	K243		<b>P.S. 243</b>				
			K243		DSF0000868139	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	41,980
						Technology		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000759073	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,077,003
					DSF0000866818	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	18,340
			K243		DSF0000804935	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
							<b>P.S. 243 Total:</b>	\$1,282,109
16	Brooklyn	K262		<b>P.S. 262</b>				
			K262		DSF0000865979	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 262 Total:</b>	\$214,792
16	Brooklyn	K304		<b>P.S. 304</b>				
					DSF0000805894	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	2,501,967
					DSF0000782597	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	2,872,371
					DSF0000805897	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	138,465

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
FIXTURES:STUDENT:Toilet								
							<b>P.S. 304 Total:</b>	\$5,512,803
16	Brooklyn	K308		<b>P.S. 308</b>				
			K308	DSF0000850180		<i>State of Good Repair - Building Upgrade - Climate Control</i>	2018	94,150
				DSF0000895701		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	110,000
			K308	DSF0000865984		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
						<i>Other</i>		
			K308	DSF0000822053		New/Retrofit Telephone/Intercom Systems	2015	222,133
			K308	DSF0000889425		IP Surveillance Camera Installation	2019	39,980
							<b>P.S. 308 Total:</b>	\$618,992
16	Brooklyn	K309		<b>P.S. 309</b>				
				DSF0000799559		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	406,034
				DSF0000799751		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	109,477
			K309	DSF0000889594		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
			K309	DSF0000865738		<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2018	315,873

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 309 Total:</b>	\$1,046,176
16	Brooklyn	K324		<b>I.S. 324</b>				
			K267	DSF0000889357		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	133,597
			K267	DSF0000843913		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	66,293
						Technology		
			K267	DSF0000843932		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	108,634
						Technology		
			K267	DSF0000866158		<i>State of Good Repair - Building Upgrade - Climate Control</i>	2018	64,130
						DSF0000895854		
						<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2019	192,424
						DSF0000866836		
						<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	39,189
			K267	DSF0000865985		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
			K267	DSF0000873016		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	200,221
						FIXTURES:Student:Lavatory/Sink		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
						<i>Other</i>		
			K267		DSF0000889428	IP Surveillance Camera Installation	2019	40,516
							<b>I.S. 324 Total:</b>	<b>\$1,059,796</b>
16	Brooklyn	K335		<b>P.S. 335</b>				
			K335		DSF0000845614	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	814,593
						<i>Other</i>		
			K335		DSF0000867147	New/Retrofit Telephone/Intercom Systems	2018	257,403
							<b>P.S. 335 Total:</b>	<b>\$1,071,996</b>
16	Brooklyn	KBBY		<b>BROOKLYN CHILDREN CENTER</b>				
			K368		DSF0000868068	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	84,500
							<b>BROOKLYN CHILDREN CENTER Total:</b>	<b>\$84,500</b>
17	Brooklyn	K002		<b>I.S. 2</b>				
					DSF0000865884	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	176,706

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K002	DSF0000843996		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	135,513
			K141	DSF0000865779		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	96,349
			K141	DSF0000911798		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	289,000
			K002	DSF0000823764		<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS INTERIOR:INTERIOR GUARDS	2015	88,884
			K002	DSF0000845732		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	468,082
				DSF0000801188		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	69,722
			K002	DSF0000866182		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System	2017	213,797

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K002		DSF0000868435	AIR CONDITIONING:DX Split System <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2018	200,221
			K002		DSF0000889392	<b>Other</b> IP Surveillance Camera Installation	2019	39,913
							<b>I.S. 2 Total:</b>	<b>\$1,778,187</b>
17	Brooklyn	K006		<b>P.S. 6</b>				
					DSF0000865885	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	114,800
			K006		DSF0000889352	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	79,599
			K006		DSF0000801233	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	108,766
					DSF0000801239	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	69,722
							<b>P.S. 6 Total:</b>	<b>\$372,887</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
17	Brooklyn	K012		<b>P.S. 12</b>				
					DSF0000865886	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	71,891
							<b>P.S. 12 Total:</b>	\$71,891
17	Brooklyn	K022		<b>P.S. 22</b>				
			K705		DSF0000889354	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	107,530
					DSF0000732914	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	2,446,532
						CLIMATE CONTROL SYSTEM		
					DSF0000755717	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	215,264
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			K705		DSF0000868772	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	3,304,639
						Ventilation		
						<b>Other</b>		
			K705		DSF0000889212	New/Retrofit Telephone/Intercom Systems	2018	217,285
			K705		DSF0000889394	IP Surveillance Camera Installation	2019	39,309
							<b>P.S. 22 Total:</b>	\$6,330,559
17	Brooklyn	K061		<b>I.S. 61</b>				
					DSF0000802105	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	115,340

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K061		DSF0000865958	FIXTURES:STUDENT:Toilet <i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>I.S. 61 Total:</b>	\$330,132
17	Brooklyn	K091		<b>P.S. 91</b>				
			K091		DSF0000824866	<i>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</i>	2017	334,369
			K091		DSF0000892289	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	189,575
							<b>P.S. 91 Total:</b>	\$523,944
17	Brooklyn	K092		<b>P.S. 92</b>				
			K092		DSF0000888782	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	649,318
					DSF0000912281	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	57,816
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
			K092		DSF0000846851	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2018	58,080
					DSF0000799539	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	304,823



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000756631	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	1,670,592
					DSF0000869540	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	5,597,105
					DSF0000892310	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	5,496,779
					DSF0000892309	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	3,184,956
			K092		DSF0000869542	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2018	200,221
							<b>P.S. 92 Total:</b>	\$17,219,690
17	Brooklyn	K138		<b>P.S. 138</b>				
			K138		DSF0000888898	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	35,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K138		DSF0000888899	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	80,000
					DSF0000777465	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	185,653
					DSF0000847527	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	125,814
			K138		DSF0000847528	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> HEATING PLANT:Boiler Auxiliaries	2017	273,710
					DSF0000912194	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	78,935
			K138		DSF0000822146	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	170,659
						<i>Other</i>		
			K138		DSF0000889405	IP Surveillance Camera Installation	2019	47,344
							<b>P.S. 138 Total:</b>	<b>\$997,115</b>
17	Brooklyn	K161		<b>P.S. 161</b>				
			K161		DSF0000821778	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	65,931

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K161		DSF0000888771	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	209,500
					DSF0000777467	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	214,688
			K161		DSF0000803429	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	3,239,883
			K161		DSF0000870512	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	93,545
			K161		DSF0000889406	<b>Other</b> IP Surveillance Camera Installation	2019	39,779
							<b>P.S. 161 Total:</b>	<b>\$3,863,326</b>
17	Brooklyn	K167		<b>P.S. 167</b>				
			K167		DSF0000799948	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	191,165
			K532		DSF0000799949	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	133,132
					DSF0000780235	<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES	2015	96,035

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K167		DSF0000780227	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	8,527,853
			K167		DSF0000803545	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	2,739,014
			K167		DSF0000803544	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	1,735,295
							<b>P.S. 167 Total:</b>	\$13,422,494
17	Brooklyn	K181		<b>P.S. 181</b>				
						<b>Other</b>		
			K181		DSF0000867135	New/Retrofit Telephone/Intercom Systems	2018	262,452
							<b>P.S. 181 Total:</b>	\$262,452
17	Brooklyn	K189		<b>P.S. 189</b>				
			K189		DSF0000912476	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
			K189		DSF0000867105	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	61,923
			K189		DSF0000803898	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2017	198,690

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
FIXTURES:STUDENT:Urinal								
							<b>P.S. 189 Total:</b>	\$460,613
17	Brooklyn	K191		<b>P.S. 191</b>				
			K191	DSF0000866147		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	90,416
			K191	DSF0000866148		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	150,050
				DSF0000822221		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	790,756
			K191	DSF0000803935		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2017	3,308,577
			K191	DSF0000826342		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	542,528
			K191	DSF0000844012		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2017	1,023,048

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K191		DSF0000803939	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	176,400
			K191		DSF0000889270	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
							<b>P.S. 191 Total:</b>	<b>\$6,423,045</b>
17	Brooklyn	K210		<b>I.S. 394</b>				
					DSF0000844089	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,068,700
					K394	DSF0000889299 <b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	150,000
					DSF0000798593	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,312,080
					DSF0000799547	INTERIOR:STRUCTURAL:VAULTS-BUNKERS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	310,758

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K394		DSF0000865972	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>I.S. 394 Total:</b>	\$2,994,267
17	Brooklyn	K221		<b>P.S. 221</b>				
			K221		DSF0000911882	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	477,578
			K221		DSF0000844134	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	129,466
					Technology			
			K221		DSF0000735778	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2015	961,203
					FIRE ALARM SYSTEM			
					DSF0000912620	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	5,050
					PANEL BOARD			
			K221		DSF0000781221	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,986
			K221		DSF0000844745	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	39,660
					Air Conditioning Split System			
			K221		DSF0000889004	<i>State of Good Repair - System Replacements - Roofs</i>	2019	88,984
							<b>P.S. 221 Total:</b>	\$1,733,927

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
17	Brooklyn	K241		<b>P.S. 241</b>				
					DSF0000781591	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	47,798
					DSF0000799554	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	137,708
					DSF0000804894	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	150,000
						FIXTURES:STUDENT:Toilet		
							<b>P.S. 241 Total:</b>	<b>\$335,506</b>
17	Brooklyn	K246		<b>I.S. 246</b>				
					DSF0000911930	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	722,584
			K246		DSF0000888916	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	380,000
			K246		DSF0000866754	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	447,134
						Technology		
			K246		DSF0000866755	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2018	552,800
						Science Lab Upgrades		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K246		DSF0000867016	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	96,000
			K246		DSF0000867018	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	41,500
					DSF0000781675	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,497,508
			K246		DSF0000822149	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			K246		DSF0000889414	<b>Other</b> IP Surveillance Camera Installation	2019	41,120
							<b>I.S. 246 Total:</b>	<b>\$3,928,646</b>
17	Brooklyn	K249		<b>P.S. 249</b>				
					DSF0000911929	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	799,786

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K249		DSF0000798267	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	6,932,642
			K249		DSF0000781711	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	2,022,123
			K249		DSF0000827389	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2018	2,703,157
					DSF0000805018	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	61,325
					DSF0000912192	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
			K249		DSF0000889590	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 249 Total:</b>	<b>\$12,812,760</b>
17	Brooklyn	K289		<b>P.S. 289</b>				
					DSF0000844717	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	128,901
					DSF0000799557	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	283,502
					DSF0000799733	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	55,296

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K289		DSF0000849928	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2017	123,042
			K289		DSF0000872616	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube	2018	42,686
					DSF0000912193	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
			K289		DSF0000872617	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2018	138,158
						<b>Other</b>		
			K289		DSF0000866232	New/Retrofit Telephone/Intercom Systems	2017	195,185
							<b>P.S. 289 Total:</b>	<b>\$1,045,705</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
17	Brooklyn	K316		<b>P.S. 316</b>				
					DSF0000782760	<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS	2015	78,469
					DSF0000872925	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	3,668,600
						<b>Other</b>		
			K316		DSF0000889427	IP Surveillance Camera Installation	2019	39,577
							<b>P.S. 316 Total:</b>	<b>\$3,786,646</b>
17	Brooklyn	K320		<b>P.S. 375</b>				
			K352		DSF0000843993	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	216,816
			K375		DSF0000844685	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	47,430
			K352		DSF0000888892	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	35,000

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K352	DSF0000888893		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	100,000
			K375	DSF0000891040		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	162,053
				DSF0000798261		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	6,872,897
				DSF0000798262		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,464,159
			K352	DSF0000782802		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
							<b>P.S. 375 Total:</b>	<b>\$8,930,035</b>
17	Brooklyn	K390		<b>I.S. 390</b>				
				DSF0000888856		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	369,899
				DSF0000843656		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Library Upgrade	2017	1,414,527

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:LIBRARY:Built-in Furnishing INTERIOR:LIBRARY:Floor Finish INTERIOR:LIBRARY:Walls		
			K334		DSF0000798298	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	5,288,897
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K334		DSF0000783145	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	2,565,044
						CLIMATE CONTROL SYSTEM		
					DSF0000783146	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	154,686
					DSF0000896148	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2019	277,110
			K334		DSF0000783151	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000799805	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	249,368
			K354		DSF0000888953	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
						<b>Other</b>		
			K354		DSF0000868114	IP Surveillance Camera Installation	2019	428,880
							<b>I.S. 390 Total:</b>	<b>\$10,780,091</b>
17	Brooklyn	K391		<b>I.S. 391</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000911926	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	195,866
					DSF0000777482	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	49,219
					DSF0000799735	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	77,789
					DSF0000912432	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,430
			K356		DSF0000783170	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000806466	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	117,297
							<b>I.S. 391 Total:</b>	<b>\$473,281</b>
17	Brooklyn	K397		<b>P.S. 397</b>	DSF0000783184	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	567,379

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K397		DSF0000889595	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 397 Total:</b>	<b>\$782,171</b>
17	Brooklyn	K398		<b>P.S. 398 (UDC)</b>				
					DSF0000799560	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	227,442
					DSF0000912511	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2019	253,090
			K398		DSF0000845576	<i>State of Good Repair - System Replacements - Domestic Piping Waste System</i>	2017	109,207
			K398		DSF0000799786	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	34,774
					DSF0000912195	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	78,935
			K398		DSF0000865988	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 398 (UDC) Total:</b>	<b>\$918,240</b>
17	Brooklyn	K399		<b>P.S. 399</b>				
					DSF0000912178	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2019	5,565,336
			K399		DSF0000783207	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 399 Total:</b>	\$5,596,995
17	Brooklyn	K707		<b>P.S. 189 GYM ANNEX</b>				
			K189	DSF0000889331		<b>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</b>	2019	10,763,794
							<b>P.S. 189 GYM ANNEX Total:</b>	\$10,763,794
17	Brooklyn	K874		<b>I.S. 340 (OLD 249 AX)</b>				
			K340	DSF0000829872		<b>Domestic Piping</b> DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain	2019	243,462
			K340	DSF0000807762		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	846,422
				DSF0000784452		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	374,032
			K340	DSF0000761807		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY	2017	1,777,798

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
			K340	DSF0000889577		<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2019	837,136
							<b>I.S. 340 (OLD 249 AX) Total:</b>	\$4,078,850
17	Brooklyn	K892		<b>P.S. 221 MINISCHOOL</b>				
				DSF0000798589		<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2015	234,516
							<b>P.S. 221 MINISCHOOL Total:</b>	\$234,516
18	Brooklyn	K066		<b>P.S. 66</b>				
			K066	DSF0000866181		<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2018	1,380,019
							<b>P.S. 66 Total:</b>	\$1,594,811
						FIRE ALARM SYSTEM		
			K066	DSF0000889584		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
18	Brooklyn	K068		<b>I.S. 68</b>				
			K068	DSF0000912425		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2019	549,144
							<b>I.S. 68 Total:</b>	\$63,155
						Interior Spaces		
				DSF0000912280		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	63,155

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
					DSF0000868181	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	398,037
			K068		DSF0000778852	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	284,352
					DSF0000799797	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	132,895
			K068		DSF0000865848	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	100,749
						Air Conditioning Split System		
			K068		DSF0000889585	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
					DSF0000867030	IP Surveillance Camera Installation	2018	529,551
							<b>I.S. 68 Total:</b>	<b>\$2,272,675</b>
18	Brooklyn	K114		<b>P.S. 114</b>				
					DSF0000911873	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	5,945
			K114		DSF0000844103	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	184,477
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System		
			K114		DSF0000822145	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	150,000
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
					DSF0000867031	IP Surveillance Camera Installation	2018	465,284
							<b>P.S. 114 Total:</b>	<b>\$805,706</b>
18	Brooklyn	K115		<b>P.S. 115</b>				
			K115		DSF0000865964	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			K115		DSF0000888942	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
							<b>P.S. 115 Total:</b>	<b>\$214,792</b>
18	Brooklyn	K135		<b>P.S. 135</b>				
			K135		DSF0000847464	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	4,513,835
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000892915	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	7,704,137
			K135		DSF0000870150	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	2,923,308
			K135		DSF0000890997	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	1,292,669
					DSF0000803073	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2015	180,482
							<b>P.S. 135 Total:</b>	\$16,614,431
18	Brooklyn	K208		<b>P.S. 208</b>				
					DSF0000780969	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	507,987
					DSF0000798411	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	881,023
					DSF0000780973	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY	2016	1,637,727

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
			K208		DSF0000826670	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,095,242
						EXTERIOR:ROOF:Roofing		
			K208		DSF0000780975	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	160,183
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
					DSF0000799939	<b>State of Good Repair - System Replacements - Windows</b>	2016	1,223,467
						EXTERIOR:WINDOWS		
							<b>P.S. 208 Total:</b>	<b>\$5,505,629</b>
18	Brooklyn	K211		<b>I.S. 211</b>				
			K211		DSF0000843903	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	195,007
						Technology		
			K211		DSF0000843929	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	385,630
						Technology		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K211		DSF0000912172	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	185,000
					DSF0000781022	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	1,707,321
					DSF0000799436	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	2,785,612
					DSF0000781046	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	1,238,557
					DSF0000781023	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,389,527
					DSF0000781029	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,387,483

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
					DSF0000781030	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	8,752,303
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
					DSF0000804335	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	108,413
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			K211		DSF0000776044	IP Surveillance Camera Installation	2015	627,813
							<b>I.S. 211 Total:</b>	<b>\$18,762,666</b>
18	Brooklyn	K219		<b>P.S. 219</b>				
					DSF0000804479	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	2,150,005
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			K219		DSF0000799935	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	1,933,072



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000844118	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	14,125,425
						EXTERIOR:EXTERIOR WALLS		
					DSF0000844117	<b>State of Good Repair - System Replacements - Parapets</b>	2018	4,526,980
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000826871	<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,882,409
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
			K219		DSF0000867136	New/Retrofit Telephone/Intercom Systems	2018	219,845
							<b>P.S. 219 Total:</b>	<b>\$25,837,736</b>
18	Brooklyn	K232		<b>I.S. 232</b>				
			K581		DSF0000888781	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	741,027
			K598		DSF0000888915	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	198,232
			K598		DSF0000888792	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	130,000
						Technology		
			K598		DSF0000888793	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	140,000
						Technology		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000871757	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	4,484,311
					DSF0000871756	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	3,675,691
			K581		DSF0000889081	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	557,899
			K581		DSF0000804724	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	272,808
					DSF0000888939	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>  <b>Other</b>	2019	332,010
			K598		DSF0000866235	New/Retrofit Telephone/Intercom Systems	2017	240,231
			K598		DSF0000889413	IP Surveillance Camera Installation	2019	40,565
							<b>I.S. 232 Total:</b>	<b>\$10,812,774</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
18	Brooklyn	K233		<b>P.S. 233</b>				
			K233	DSF0000845624		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	988,917
				DSF0000781448		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	804,256
				DSF0000799731		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	35,173
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K233	DSF0000804745		<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2018	338,162
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
			K233	DSF0000843650		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	4,687,035
						EXTERIOR:CHIMNEY		
						EXTERIOR:CORNICE		
						EXTERIOR:LOUVER		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			K233	DSF0000843651		<b>State of Good Repair - System Replacements - Parapets</b>	2018	588,065
			K233	DSF0000827141		<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,733,359
						EXTERIOR:ROOF:Roofing		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K233		DSF0000822148	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	110,388
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 233 Total:</b>	\$9,285,355
18	Brooklyn	K235		<b>P.S. 235</b>				
					DSF0000777476	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	89,050
			K235		DSF0000799530	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2016	2,909,769
			K235		DSF0000889006	<i>State of Good Repair - System Replacements - Roofs</i>	2019	88,984
			K235		DSF0000804784	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	161,010
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							<b>P.S. 235 Total:</b>	\$3,248,813
18	Brooklyn	K242		<b>P.S. 235 ANNEX</b>				
			K235		DSF0000804911	<i>State of Good Repair - Building Upgrade - Reinforcing Support Elements</i>	2017	1,243,178

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K235	DSF0000804914		INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	150,000
<b>P.S. 235 ANNEX Total:</b>								\$1,393,178
18	Brooklyn	K244		<b>P.S. 244</b>				
				DSF0000781655		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	266,324
				DSF0000799690		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	228,789
				DSF0000868194		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	210,736
				DSF0000759098		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY	2016	5,289,108

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
					DSF0000781658	<b>State of Good Repair - System Replacements - Parapets</b>	2016	1,184,146
						EXTERIOR:PARAPETS		
					DSF0000781657	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,631,400
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
					DSF0000799878	<b>State of Good Repair - System Replacements - Windows</b>	2016	4,690,314
						EXTERIOR:WINDOWS		
							<b>P.S. 244 Total:</b>	<b>\$13,500,817</b>
18	Brooklyn	K252		<b>I.S. 252</b>				
					DSF0000844098	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2017	36,000
						Technology		
					DSF0000777477	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	81,296
					DSF0000798253	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	14,050,173
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
					DSF0000781767	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,864,001
						CLIMATE CONTROL SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000781769	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	828,340
					DSF0000866820	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	4,670
					DSF0000849373	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	8,011,932
					DSF0000849371	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	4,691,300
					DSF0000872074	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	2,156,244
			K588		DSF0000805080	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink	2017	124,986
			K588		DSF0000889415	<b>Other</b> IP Surveillance Camera Installation	2019	39,712
							<b>I.S. 252 Total:</b>	<b>\$31,888,654</b>
18	Brooklyn	K268		<b>P.S. 268</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000912284	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	30,216
					DSF0000759470	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	941,700
					DSF0000799732	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	45,924
			K268		DSF0000799531	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2015	1,726,304
					DSF0000868196	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	293,913
			K268		DSF0000889593	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 268 Total:</b>	<b>\$3,252,849</b>
18	Brooklyn	K272		<b>P.S. 272</b>				
					DSF0000912383	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING	2019	17,612



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXIT LIGHT		
					DSF0000759549	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	151,833
					DSF0000799692	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	219,145
			K272		DSF0000799526	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	1,846,625
					DSF0000868197	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	354,242
					DSF0000759552	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,175,153
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
			K272		DSF0000805414	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	88,245
					DSF0000822654	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	183,975
					DSF0000759551	<b>State of Good Repair - System Replacements - Parapets</b>	2015	2,319,085
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000759550	<b>State of Good Repair - System Replacements - Roofs</b>	2015	3,662,132
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K272		DSF0000865980	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			K272		DSF0000867146	New/Retrofit Telephone/Intercom Systems	2018	197,813
							<b>P.S. 272 Total:</b>	<b>\$11,430,652</b>
18	Brooklyn	K276		<b>P.S. 276</b>				
					DSF0000805475	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	904,440
						<b>Other</b>		
			K276		DSF0000889421	IP Surveillance Camera Installation	2019	39,175
							<b>P.S. 276 Total:</b>	<b>\$943,615</b>
18	Brooklyn	K279		<b>P.S. 279</b>				
					DSF0000777692	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	2,290,070
					DSF0000799882	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:ELEVATORS	2015	526,352
					DSF0000777688	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	9,312,544

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K279	DSF0000777691		<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	1,178,824
				DSF0000805533		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	927,200
				DSF0000782243		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	1,650,473
				DSF0000799884		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b> SITE:Drainage System for Asphalt SITE:Drainage System for Concrete SITE:PAVING - STUDENT USE:Concrete SITE:PLAYGROUNDS:Play Equipment SITE:PLAYGROUNDS:Safety Surfacing SITE:SEATING:Benches	2015	786,588
				DSF0000799883		<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	984,322

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K279		DSF0000888831	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	837,853
			K279		DSF0000777689	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,939,838
			K279		DSF0000759677	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	6,745,144
					DSF0000782256	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:HEATING AND VENTILATING UNIT	2015	2,373,683
			K279		DSF0000865982	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 279 Total:</b>	<b>\$29,705,620</b>
18	Brooklyn	K285		<b>I.S. 285</b>				
					DSF0000912312	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING	2019	56,886

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000782314	EXIT LIGHT <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,499,533
			K285		DSF0000736829	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	2,405,353
					DSF0000868269	FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	378,998
			K285		DSF0000889422	<b>Other</b> IP Surveillance Camera Installation	2019	39,644
							<b>I.S. 285 Total:</b>	<b>\$4,380,414</b>
18	Brooklyn	K855		<b>P.S. 135/P.S. 235 ANNEX</b>				
			K135		DSF0000912276	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping	2019	393,329
							<b>P.S. 135/P.S. 235 ANNEX Total:</b>	<b>\$393,329</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
18	Brooklyn	K860		<b>P.S. 219 ANNEX</b>				
					DSF0000761724	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	3,849,384
							<b>P.S. 219 ANNEX Total:</b>	<b>\$3,849,384</b>
19	Brooklyn	K007		<b>P.S. 7</b>				
					DSF0000844727	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	116,543
					DSF0000777901	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	93,594
			K007		DSF0000866152	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2017	91,547
					DSF0000823568	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	69,723
			K007		DSF0000888935	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	260,558
							<b>P.S. 7 Total:</b>	<b>\$631,965</b>
19	Brooklyn	K013		<b>P.S. 13</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K013		DSF0000843893	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	79,303
					DSF0000799681	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	123,549
					DSF0000799770	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	111,698
			K013		DSF0000845902	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2018	1,185,222
					DSF0000801363	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			K013		DSF0000823910	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2017	134,858
			K013		DSF0000911947	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
							<b>P.S. 13 Total:</b>	<b>\$2,120,686</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
19	Brooklyn	K072		<b>P.S. 72</b>				
					DSF0000912510	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2019	281,291
			K677		DSF0000778896	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			K677		DSF0000824703	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	117,789
			K677		DSF0000865960	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 72 Total:</b>	<b>\$645,552</b>
19	Brooklyn	K108		<b>P.S. 108</b>				
			K108		DSF0000802709	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2016	798,509
			K108		DSF0000844744	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	84,896
			K108		DSF0000865835	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2019	398,563
							<b>P.S. 108 Total:</b>	<b>\$1,281,968</b>
19	Brooklyn	K149		<b>P.S. 149</b>				
			K149		DSF0000866106	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 149 Total:</b>	\$77,690
19	Brooklyn	K158		<b>P.S. 158</b>				
					DSF0000777466	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	110,070
					DSF0000870464	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	4,603,925
					DSF0000799746	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	85,741
					DSF0000757554	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	2,147,494
					DSF0000825820	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE	2016	794,809
			K158		DSF0000865785	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2017	680,931
					DSF0000868184	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	563,458

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K158		DSF0000803389	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	244,884
					DSF0000912438	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2019	2,036,657
			K158		DSF0000870476	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Floor Finish	2019	203,957
					DSF0000780067	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2016	991,011
					DSF0000821660	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2016	829,675
			K158		DSF0000757565	<b>State of Good Repair - System Replacements - Kitchen Areas</b> INTERIOR:KITCHEN/WARMING PANTRY:Floor Finish	2016	4,429,582

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000870467	INTERIOR:KITCHEN/WARMING PANTRY:Walls <b>State of Good Repair - System Replacements - Parapets</b>	2019	4,681,514
					DSF0000893246	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	556,696
			K158		DSF0000803387	SITE:PAVING:DOT Sidewalk SITE:PAVING:Student Use:Concrete SITE:STAIRS/RAMPS: EXTERIOR <b>State of Good Repair - System Replacements - Roofs</b>	2016	280,067
					DSF0000912437	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Roofs</b>	2019	2,625,530
			K158		DSF0000865968	EXTERIOR:ROOF:Roofing <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
					DSF0000870468	<b>State of Good Repair - System Replacements - Windows</b>	2019	7,266,393
			K158		DSF0000865787	EXTERIOR:WINDOWS <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	478,791
							<b>P.S. 158 Total:</b>	<b>\$33,825,977</b>
19	Brooklyn	K159		<b>P.S. 159</b>				
			K159		DSF0000888875	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	376,963

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K159		DSF0000822138	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	187,236
							<b>P.S. 159 Total:</b>	\$564,199
19	Brooklyn	K166		<b>I.S. 166</b>				
			K654		DSF0000844135	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	70,785
					DSF0000777470	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	216,852
					DSF0000803530	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	153,459
			K359		DSF0000868111	<i>Other</i> IP Surveillance Camera Installation	2019	399,631
							<b>I.S. 166 Total:</b>	\$840,727
19	Brooklyn	K171		<b>I.S. 171</b>				
					DSF0000777471	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	140,699

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K171	DSF0000780281		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	3,784,370
			K171	DSF0000826018		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2017	1,791,123
				DSF0000868187		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	337,486
			K171	DSF0000826031		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Metal Ductwork VENTILATION:Supply Fan	2017	2,827,866
			K171	DSF0000826023		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	1,857,785
				DSF0000803608		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	123,944

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
					DSF0000803605	<b>State of Good Repair - System Replacements - Windows</b>	2017	7,075,140
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			K171		DSF0000776042	IP Surveillance Camera Installation	2015	617,459
							<b>I.S. 171 Total:</b>	<b>\$18,555,872</b>
19	Brooklyn	K174		<b>P.S. 174</b>				
					DSF0000912283	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	42,809
						EMERGENCY LIGHT/EXIT LIGHT PANEL		
						EMERGENCY LIGHTING		
						EXIT LIGHT		
					DSF0000780317	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	349,429
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000799747	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	51,547
					DSF0000868188	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	297,288
			K174		DSF0000844104	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	47,025

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:Gas Distribution Piping		
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						GAS SERVICE:Gas Meter Room Vent		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
					DSF0000889000	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
					DSF0000803645	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	192,106
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						<b>Other</b>		
			K174		DSF0000889213	New/Retrofit Telephone/Intercom Systems	2018	198,595
						<b>P.S. 174 Total:</b>		\$1,267,783
19	Brooklyn	K190		<b>P.S. 190</b>				
					DSF0000780589	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	111,620
						<b>Other</b>		
			K190		DSF0000866236	New/Retrofit Telephone/Intercom Systems	2017	222,820
						<b>P.S. 190 Total:</b>		\$334,440

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
19	Brooklyn	K202		<b>P.S. 202</b>				
			K202		DSF0000799933	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	442,989
			K202		DSF0000888917	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	402,794
			K202		DSF0000821756	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	169,381
			K202		DSF0000843901	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	79,571
			K202		DSF0000865770	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	122,610
					DSF0000799748	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	161,809
			K680		DSF0000888883	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2019	5,945,096
			K202		DSF0000823660	<i>State of Good Repair - System Replacements - Toilets - Students</i> INTERIOR:TOILET ROOMS - STUDENTS	2017	320,000



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 202 Total:</b>	\$7,644,250
19	Brooklyn	K213	<b>P.S. 213</b>					
			K213	DSF0000889349		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	7,309,909
			K213	DSF0000871392		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	2,386,790
						CLIMATE CONTROL SYSTEM		
			K213	DSF0000843864		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	118,680
						Air Conditioning Split System		
			K213	DSF0000871400		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	414,833
						GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube		
			K213	DSF0000888951		<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
						<b>Other</b>		
			K213	DSF0000867141		New/Retrofit Telephone/Intercom Systems	2018	160,553
							<b>P.S. 213 Total:</b>	\$10,390,765
19	Brooklyn	K214	<b>P.S. 214</b>					

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799548	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	121,204
					DSF0000894204	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2019	159,710
			K214		DSF0000822269	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2017	3,694,364
			K214		DSF0000865836	<i>State of Good Repair - System Replacements - Gymnasium Upgrade</i>	2017	275,824
			K214		DSF0000866110	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			K214		DSF0000889002	<i>State of Good Repair - System Replacements - Roofs</i>	2019	88,984
							<b>P.S. 214 Total:</b>	<b>\$4,417,776</b>
19	Brooklyn	K218		<b>I.S. 218</b>				
					DSF0000826850	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	1,951,356
					DSF0000804473	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	479,066
					DSF0000826853	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:CHIMNEY	2018	1,809,749

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K218	DSF0000822130		EXTERIOR:EXTERIOR WALLS <i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	150,000
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
			K218	DSF0000889409		<i>Other</i> IP Surveillance Camera Installation	2019	39,644
							<b>I.S. 218 Total:</b>	<b>\$4,429,815</b>
19	Brooklyn	K224		<b>P.S. 224</b>				
					DSF0000781282	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	95,509
					DSF0000799550	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	285,624
					DSF0000804578	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	69,723
						HEATING PLANT:BOILER SYSTEM		
							<b>P.S. 224 Total:</b>	<b>\$450,856</b>
19	Brooklyn	K260		<b>P.S. 260</b>				
					DSF0000759360	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	785,517
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868195	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	958,729
							<b>P.S. 260 Total:</b>	\$1,744,246
19	Brooklyn	K273		<b>P.S. 273</b>				
			K273		DSF0000821886	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	111,303
					DSF0000799693	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	188,001
			K273		DSF0000782141	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	32,844
							<b>P.S. 273 Total:</b>	\$332,148
19	Brooklyn	K290		<b>P.S. 290</b>				
					DSF0000782399	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	1,335,542
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K290		DSF0000821978	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2017	1,354,960
			K290		DSF0000782405	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000805706	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	744,482
			K290		DSF0000782401	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	2,483,731
					DSF0000822187	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,093,155
						<b>Other</b>		
			K290		DSF0000776048	IP Surveillance Camera Installation	2015	500,423
							<b>P.S. 290 Total:</b>	<b>\$7,543,952</b>
19	Brooklyn	K292		<b>I.S. 292</b>				
					DSF0000799558	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	415,762
					DSF0000799749	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	186,287
					DSF0000866828	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	13,724
			K292		DSF0000782446	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	36,552
			K292		DSF0000805747	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K292		DSF0000889423	IP Surveillance Camera Installation	2019	43,731
							<b>I.S. 292 Total:</b>	<b>\$840,842</b>
19	Brooklyn	K302		<b>I.S. 302</b>				
					DSF0000821663	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	2,568,573
			K302		DSF0000865799	<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2017	763,302
			K302		DSF0000843816	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2017	1,495,541
			K662		DSF0000865798	<i>State of Good Repair - System Replacements - Auditorium Upgrade</i>	2018	864,219
						<i>Other</i>		
			K661		DSF0000868112	IP Surveillance Camera Installation	2019	419,885
							<b>I.S. 302 Total:</b>	<b>\$6,111,520</b>
19	Brooklyn	K306		<b>P.S. 306</b>				
					DSF0000912313	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	47,423

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799696	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	372,457
					DSF0000868272	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,133,842
			K306		DSF0000782639	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,630
					DSF0000828244	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	56,221
			K306		DSF0000782640	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	111,567
			K306		DSF0000866237	<i>Other</i> New/Retrofit Telephone/Intercom Systems	2017	187,899
							<b>P.S. 306 Total:</b>	<b>\$1,941,039</b>
19	Brooklyn	K328		<b>P.S. 328</b>				
					DSF0000868201	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	10,000
					DSF0000873060	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	1,071,765

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
					DSF0000806186	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	168,837
						HEATING		
					DSF0000873059	<b>State of Good Repair - System Replacements - Parapets</b>	2019	965,482
						EXTERIOR:PARAPETS		
					DSF0000873058	<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,005,596
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			K328		DSF0000865740	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
<b>P.S. 328 Total:</b>								<b>\$5,537,553</b>
19	Brooklyn	K345		<b>P.S. 345</b>				
			K345		DSF0000798295	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	6,111,230
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K345		DSF0000798296	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	2,927,531
						CLIMATE CONTROL SYSTEM		
			K345		DSF0000865839	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2017	31,746



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K345		DSF0000865986	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
					DSF0000844016	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2017	1,385,281
							<b>P.S. 345 Total:</b>	<b>\$10,670,580</b>
19	Brooklyn	K346		<b>P.S. 346</b>				
					DSF0000845615	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	749,622
					DSF0000866313	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	427,072
					DSF0000799769	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	32,661
			K346		DSF0000782973	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			K346		DSF0000873134	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	400,444
			K452		DSF0000912635	FIXTURES:Student:Lavatory/Sink <i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2019	170,000
							<b>P.S. 346 Total:</b>	<b>\$1,811,479</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
19	Brooklyn	K368		<b>P.S. 159 GYM ANNEX</b>				
			K159		DSF0000889557	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,239,099
<b>P.S. 159 GYM ANNEX Total:</b>								\$10,239,099
19	Brooklyn	K478		<b>P.S. 190 GYM ANNEX</b>				
			K190		DSF0000889560	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,564,494
<b>P.S. 190 GYM ANNEX Total:</b>								\$10,564,494
19	Brooklyn	K798		<b>CESIAH TORO MULLANE SCHOOL</b>				
					DSF0000865782	<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2017	288,801
					DSF0000799761	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	125,280
			K065		DSF0000889434	<i>Other</i> IP Surveillance Camera Installation	2019	39,041
<b>CESIAH TORO MULLANE SCHOOL Total:</b>								\$453,122
19	Brooklyn	K814		<b>CYPRESS HILLS COMMUNITY SCHOOL</b>				
					DSF0000799771	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	21,104

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K089		DSF0000889437	IP Surveillance Camera Installation	2019	37,119
<b>CYPRESS HILLS COMMUNITY SCHOOL Total:</b>								<b>\$58,223</b>
19	Brooklyn	K848		<b>P.S. 149 ANNEX</b>				
					DSF0000807608	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	210,088
			K149		DSF0000897226	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	944,064
					DSF0000874362	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	504,315
					DSF0000874361	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	2,034,182
<b>P.S. 149 ANNEX Total:</b>								<b>\$3,692,649</b>
20	Brooklyn	K048		<b>P.S. 48</b>				
					DSF0000756089	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,486,144
					DSF0000778562	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	778,436

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866771	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,551
			K048		DSF0000778566	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	9,408,869
			K048		DSF0000778569	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	167,438
			K048		DSF0000778565	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Windows</b>	2018	2,974,458
						EXTERIOR:WINDOWS		
							<b>P.S. 48 Total:</b>	\$14,816,896
20	Brooklyn	K062		<b>I.S. 62</b>	DSF0000888784	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	6,195,085
			K062			HEATING PLANT:Boiler Auxiliaries		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K062		DSF0000869288	HEATING PLANT:Boiler System <i>State of Good Repair - Building Upgrade - Climate Control</i>	2019	3,244,002
					DSF0000866775	CLIMATE CONTROL SYSTEM <i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	4,019
					DSF0000868180	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	161,085
			K062		DSF0000799861	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
					DSF0000802129	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
						<i>Other</i>		
			K062		DSF0000866253	New/Retrofit Telephone/Intercom Systems	2017	320,228
			K062		DSF0000889399	IP Surveillance Camera Installation	2019	39,913
							<b>I.S. 62 Total:</b>	<b>\$10,140,777</b>
20	Brooklyn	K069		<b>P.S. 69</b>				
					DSF0000887369	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	4,190,333
					DSF0000889079	EXTERIOR:AWNINGS AND CANOPIES <i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	54,068
			K069		DSF0000889043	<i>State of Good Repair - System Replacements - Kitchen Areas</i>	2018	131,280

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000887368	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing	2019	2,654,502
							<b>P.S. 69 Total:</b>	\$7,030,183
20	Brooklyn	K102		<b>P.S. 102</b>				
			K102		DSF0000802608	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	7,618,256
					DSF0000866785	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	2,823
			K102		DSF0000825075	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2017	3,654,901
			K102		DSF0000825073	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing	2017	2,127,407
			K102		DSF0000865961	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 102 Total:</b>	\$13,618,179
20	Brooklyn	K104		<b>P.S. 104</b>				
			K104		DSF0000802628	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	962,313

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000798406	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	762,177
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866786	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,747
			K104		DSF0000712695	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	5,129,452
						EXTERIOR:EXTERIOR WALLS		
			K104		DSF0000802631	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,643,504
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			K104		DSF0000802630	<b>State of Good Repair - System Replacements - Roofs</b>	2017	7,276,794
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			K104		DSF0000776039	IP Surveillance Camera Installation	2015	479,361
							<b>P.S. 104 Total:</b>	<b>\$16,257,348</b>
20	Brooklyn	K105		<b>P.S. 105</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K105		DSF0000779335	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	1,130,061
					DSF0000779333	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,187,474
			K105		DSF0000869757	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b> INTERIOR:CAFETERIA:Floor Finish	2019	200,355
			K105		DSF0000779340	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	6,386,926
					DSF0000867023	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2018	184,953
			K105		DSF0000779337	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	513,429

**P.S. 105 Total: \$9,603,198**



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000779438	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	491,733
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K112		DSF0000844158	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	2,181,003
						<b>Other</b>		
			K112		DSF0000889402	IP Surveillance Camera Installation	2019	37,833
							<b>P.S. 112 Total:</b>	<b>\$2,710,569</b>
20	Brooklyn	K127		<b>P.S. 127</b>				
			K127		DSF0000802993	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	47,327
						GAS SERVICE:GAS DISTRIBUTION PIPING		
						HEATING		
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT:FUEL SYSTEMS		
							<b>P.S. 127 Total:</b>	<b>\$47,327</b>
20	Brooklyn	K160		<b>P.S. 160</b>				
					DSF0000780092	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	466,072

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000868185	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	402,256
					DSF0000710359	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	5,793,040
						EXTERIOR:Exterior Walls		
					DSF0000799784	<b>State of Good Repair - System Replacements - Parapets</b>	2016	1,144,937
						EXTERIOR:PARAPETS		
							<b>P.S. 160 Total:</b>	<b>\$7,806,305</b>
20	Brooklyn	K163		<b>P.S. 163</b>				
					DSF0000777469	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	83,690
					DSF0000870552	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	35,165
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						HEATING:Radiator/Convactor/Fin Tube		
						HEATING:Steam Heating		
						HEATING:Unit Heater/Cabinet Heater		
			K748		DSF0000803477	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	280,576
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
							<b>P.S. 163 Total:</b>	\$399,431
20	Brooklyn	K164		<b>P.S. 164</b>				
					DSF0000825915	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	1,066,307
						CLIMATE CONTROL SYSTEM		
					DSF0000798394	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,061,634
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000780173	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	7,020,319
						EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR SOFFITS		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
					DSF0000844157	<b>State of Good Repair - System Replacements - Parapets</b>	2018	337,179
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000825919	<b>State of Good Repair - System Replacements - Roofs</b>	2018	599,751
						EXTERIOR:ROOF:Roofing		
							<b>P.S. 164 Total:</b>	\$10,085,190

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
20	Brooklyn	K170		<b>P.S. 170</b>				
					DSF0000780265	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	3,710,627
						EXTERIOR:EXTERIOR WALLS		
					DSF0000799800	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	132,895
			K170		DSF0000845579	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	45,843
						Air Conditioning Split System		
			K170		DSF0000845580	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	127,402
							<b>P.S. 170 Total:</b>	<b>\$4,016,767</b>
20	Brooklyn	K176		<b>P.S. 176</b>				
					DSF0000799727	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	104,018
			K176		DSF0000865778	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	32,864
							<b>P.S. 176 Total:</b>	<b>\$136,882</b>
20	Brooklyn	K179		<b>P.S. 179</b>				
			K179		DSF0000803746	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	133,719
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 185 Total:</b>	\$79,369
20	Brooklyn	K186		<b>P.S. 186</b>				
					DSF0000777473	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	127,483
					DSF0000758018	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,818,637
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000868266	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	65,249
					DSF0000780537	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	142,819
						Ventilation VENTILATION:EXHAUST FAN VENTILATION:SUPPLY FAN		
						<b>Other</b>		
			K186		DSF0000865906	New/Retrofit Telephone/Intercom Systems	2017	170,389
			K186		DSF0000889408	IP Surveillance Camera Installation	2019	39,175
							<b>P.S. 186 Total:</b>	\$2,363,752
20	Brooklyn	K192		<b>P.S. 192</b>				
			K192		DSF0000848300	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	68,970

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000780632	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	732,987
					DSF0000798397	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	913,937
					DSF0000780635	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2016	3,876,797
					DSF0000780634	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,832,455
					DSF0000800109	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	963,498
			K192		DSF0000780636	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	343,384

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 192 Total:</b>	\$9,732,028
20	Brooklyn	K200		<b>P.S. 200</b>				
					DSF0000780804	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	960,354
			K200		DSF0000871169	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2019	148,924
			K200		DSF0000868163	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2018	3,780,766
			K200		DSF0000848464	<b>State of Good Repair - System Replacements - Parapets</b>	2018	4,326,097
			K200		DSF0000848463	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	2,158,517



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 200 Total:</b>	\$11,374,658
20	Brooklyn	K201		<b>I.S. 201</b>				
					DSF0000780828	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,030,656
							<b>I.S. 201 Total:</b>	\$1,030,656
20	Brooklyn	K204		<b>P.S. 204</b>				
					DSF0000799545	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	284,411
					DSF0000799729	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	63,731
			K204		DSF0000871233	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2018	112,241
					DSF0000799801	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	101,705
							<b>P.S. 204 Total:</b>	\$562,088
20	Brooklyn	K205		<b>P.S. 205</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K205		DSF0000871241	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	2,404,809
					DSF0000799546	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	210,704
			K205		DSF0000865859	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2017	254,592
			K205		DSF0000889030	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	753,369
			K205		DSF0000848555	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING:Steam Heating	2017	410,679
			K205		DSF0000871243	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	2,531,381
			K205		DSF0000889029	<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,551,180
							<b>P.S. 205 Total:</b>	<b>\$8,116,714</b>
20	Brooklyn	K220		<b>I.S. 220</b>				
					DSF0000781208	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2016	4,068,365

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment		
						INTERIOR:SCIENCE PREP ROOM:Fixed Equipment		
						SCIENCE DEMO ROOM		
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent		
						SCIENCE PREP ROOM		
						SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000868192	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	15,878
			K220		DSF0000848820	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	99,473
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						HEATING:Heating Coil In Ductwork		
						HEATING:Radiator/Convactor/Fin Tube		
						HEATING:Unit Heater/Cabinet Heater		
						<b>Other</b>		
			K220		DSF0000889410	IP Surveillance Camera Installation	2019	39,644
						<b>I.S. 220 Total:</b>		<b>\$4,223,360</b>
20	Brooklyn	K223		<b>I.S. 223</b>				
					DSF0000865889	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	176,152

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000758723	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2018	2,022,841
					DSF0000871592	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	214,036
			K223		DSF0000821911	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2016	262,267
			K223		DSF0000848892	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2017	107,973
					DSF0000912378	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	7,119

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000871596	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	5,105,976
			K223		DSF0000866112	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000871595	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	671,715
					DSF0000871594	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	2,790,357
						<b>Other</b>		
			K223		DSF0000912227	IP Surveillance Camera Installation	2019	69,114
							<b>I.S. 223 Total:</b>	<b>\$11,505,240</b>
20	Brooklyn	K227		<b>I.S. 227</b>				
					DSF0000911927	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	384,351
			K227		DSF0000848965	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,606,661

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000781344	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,452,403
			K227		DSF0000848971	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2018	2,816,383
					DSF0000894473	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	47,619
			K227		DSF0000848969	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,016,556
			K227		DSF0000848968	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	3,038,841
						<b>Other</b>		
			K227		DSF0000776045	IP Surveillance Camera Installation	2015	519,722
							<b>I.S. 227 Total:</b>	<b>\$10,882,536</b>
20	Brooklyn	K229		<b>P.S. 229</b>				
					DSF0000871715	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2019	4,994,950

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799552	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	114,343
					DSF0000799730	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	137,169
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000800137	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	5,327,552
					DSF0000866816	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,985
					DSF0000871719	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	6,831,708
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
					DSF0000871718	<b>State of Good Repair - System Replacements - Parapets</b>	2019	3,174,096
						EXTERIOR:PARAPETS		
					DSF0000894506	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b>	2019	990,975
						SITE:PLAYGROUNDS:Pavement		
					DSF0000871717	<b>State of Good Repair - System Replacements - Roofs</b>	2019	2,204,012
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K229		DSF0000889412	IP Surveillance Camera Installation	2019	39,510
							<b>P.S. 229 Total:</b>	<b>\$23,821,300</b>
20	Brooklyn	K237		<b>LUCRETIA MARCIGLIANO CAMPUS</b>				
			K370		DSF0000866266	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	177,433
							<b>LUCRETIA MARCIGLIANO CAMPUS Total:</b>	<b>\$177,433</b>
20	Brooklyn	K247		<b>P.S. 247</b>				
			K247		DSF0000894803	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	4,596,280
					DSF0000781696	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	833,281
			K247		DSF0000894807	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	1,184,426
					DSF0000894806	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	2,075,089



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K247		DSF0000894805	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,502,894
			K247		DSF0000865977	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 247 Total:</b>	\$10,406,762
20	Brooklyn	K259		<b>I.S. 259</b>				
					DSF0000865890	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	49,676
			K259		DSF0000798278	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	6,958,518
			K259		DSF0000798281	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,887,398
					DSF0000798415	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	795,600
					DSF0000781917	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY	2016	8,061,687

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
					DSF0000805209	<b>State of Good Repair - System Replacements - Parapets</b>	2016	3,000,391
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000821683	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,679,871
						EXTERIOR:ROOFING:Roofing		
					DSF0000821729	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	114,632
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			K259		DSF0000889417	IP Surveillance Camera Installation	2019	40,449
							<b>I.S. 259 Total:</b>	<b>\$22,588,222</b>
20	Brooklyn	K314		<b>P.S. 314</b>				
					DSF0000844724	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	103,692
					DSF0000798566	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	5,730,843
						EXTERIOR:EXTERIOR WALLS		
					DSF0000799803	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	132,895
					DSF0000806033	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
						HEATING PLANT:BOILER SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000828341	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit	2017	221,175
			K503		DSF0000844105	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler System	2016	62,463
					DSF0000801066	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	467,558
					DSF0000782731	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2017	729,570
			K503		DSF0000806034	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink	2016	243,405
			K503		DSF0000866254	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	347,835
							<b>P.S. 314 Total:</b>	<b>\$8,109,159</b>
20	Brooklyn	K331		<b>P.S./I.S. 30 MARY WHITE OVINGTON</b>				
					DSF0000844721	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	138,920

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S./I.S. 30 MARY WHITE OVINGTON Total:</b>	\$138,920
20	Brooklyn	K486		<b>I.S. 187</b>				
					DSF0000783643	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,056,673
					DSF0000866843	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	10,185
			K187		DSF0000851083	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Meter Room Exhaust Fan HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2019	203,235
			K187		DSF0000888995	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	25,086
			K187		DSF0000822150	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	213,108

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K187		DSF0000776050	IP Surveillance Camera Installation	2015	529,182
							<b>I.S. 187 Total:</b>	<b>\$2,037,469</b>
20	Brooklyn	K693		<b>P.S. 112 GYM ANNEX</b>				
			K112		DSF0000889330	<b>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</b>	2019	10,739,980
							<b>P.S. 112 GYM ANNEX Total:</b>	<b>\$10,739,980</b>
20	Brooklyn	K767		<b>PRE-K CENTER @ 1668 46TH STREET</b>				
			K768		DSF0000888833	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	628,400
							<b>PRE-K CENTER @ 1668 46TH STREET Total:</b>	<b>\$628,400</b>
20	Brooklyn	K807		<b>P.S./ I.S. 163</b>				
					DSF0000800140	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	6,295,698
			K163		DSF0000888851	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2018	279,984
			K163		DSF0000888911	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2019	263,002

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:GYMNASIUM:Floor Finish		
						<i>Other</i>		
			K163		DSF0000889436	IP Surveillance Camera Installation	2019	39,980
							<b>P.S./ I.S. 163 Total:</b>	\$6,878,664
20	Brooklyn	K940		<b>I.S. 30</b>				
					DSF0000798402	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	301,714
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K030		DSF0000799841	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,777
							<b>I.S. 30 Total:</b>	\$352,491
20	Brooklyn	K971		<b>P.S. 971</b>				
					DSF0000799739	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	52,149
						<i>Other</i>		
			K971		DSF0000889439	IP Surveillance Camera Installation	2019	38,236
							<b>P.S. 971 Total:</b>	\$90,385
21	Brooklyn	K043		<b>I.S. 98</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K098		DSF0000778489	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2015	11,146,254
					DSF0000799432	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,925,682
					DSF0000778487	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,901,695
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799431	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	3,449,798
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000778485	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,831,434
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000799906	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	2,249,496

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM		
					DSF0000799458	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2015	961,625
						INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Stage:Stage		
					DSF0000821587	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2015	46,200
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging		
			K098		DSF0000799874	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			K098		DSF0000822141	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	150,000
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>I.S. 98 Total:</b>	\$26,693,843
21	Brooklyn	K090		<b>P.S. 90</b>				
					DSF0000756589	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,212,457
						CLIMATE CONTROL SYSTEM		
					DSF0000777684	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	5,691,627
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000777685	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,631,068
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
					DSF0000756596	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,584,987
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
			K090		DSF0000756597	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	5,480,959
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000779077	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	399,444
						Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR		
			K090		DSF0000799875	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
					DSF0000779064	<b>State of Good Repair - System Replacements - Roofs</b>	2015	2,324,205
						EXTERIOR:ROOFING:Roofing		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
EXTERIOR:ROOFING:Specialties								
							<b>P.S. 90 Total:</b>	\$18,356,406
21	Brooklyn	K095		<b>P.S. 95</b>				
					DSF0000779172	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2015	4,429,467
					SCA0000026515	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	2,624,267
					DSF0000779171	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	1,084,897
					DSF0000802497	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2015	150,000
			K095		DSF0000822143	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	159,757
			K095		DSF0000776038	<b>Other</b> IP Surveillance Camera Installation	2015	568,643
							<b>P.S. 95 Total:</b>	\$9,017,031

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
21	Brooklyn	K096		<b>I.S. 96</b>				
			K096		DSF0000844695	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	500,696
			K096		DSF0000821754	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	424,102
					DSF0000889077	<i>State of Good Repair - System Replacements - Floors</i>	2018	80,634
					DSF0000799798	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	257,257
						<b>Other</b>		
			K096		DSF0000889215	New/Retrofit Telephone/Intercom Systems	2018	264,566
			K096		DSF0000889401	IP Surveillance Camera Installation	2019	39,846
							<b>I.S. 96 Total:</b>	<b>\$1,567,101</b>
21	Brooklyn	K097		<b>P.S. 97</b>				
					DSF0000777461	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	89,206
					DSF0000799799	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	239,898
			K097		DSF0000802533	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	307,620

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 97 Total:</b>	\$636,724
21	Brooklyn	K099		<b>P.S. 99</b>				
			K099	DSF0000889388		<i>Interior Spaces</i>	2019	21,270
				DSF0000779245		<i>Safety and Security - Safety and Security - Safety Systems</i>	2015	361,153
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
				DSF0000756759		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	2,265,266
						EXTERIOR:EXTERIOR WALLS		
				DSF0000779234		<i>State of Good Repair - System Replacements - Parapets</i>	2015	3,861,425
						EXTERIOR:PARAPETS		
			K099	DSF0000822144		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	197,645
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 99 Total:</b>	\$6,706,759
21	Brooklyn	K100		<b>P.S. 100</b>				
				DSF0000799688		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	76,388

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000802577	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Toilet	2015	159,459
							<b>P.S. 100 Total:</b>	\$235,847
21	Brooklyn	K101		<b>P.S. 101</b>				
					DSF0000732197	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	6,480,248
					DSF0000799540	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	107,119
					DSF0000866784	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	7,407
			K101		DSF0000777444	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	7,559,639
			K101		DSF0000866102	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			K101		DSF0000777442	<i>State of Good Repair - System Replacements - Parapets</i>	2015	237,977
			K101		DSF0000777443	<i>State of Good Repair - System Replacements - Roofs</i>	2015	1,197,000
							<b>P.S. 101 Total:</b>	\$15,667,080
21	Brooklyn	K121		<b>P.S. 121</b>				
					DSF0000799725	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	14,572

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866791	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	2,372
			K121		DSF0000847313	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2018	2,666,106
			K121		DSF0000866261	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:PARAPETS	2018	3,089,616
			K121		DSF0000847312	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	1,074,855
							<b>P.S. 121 Total:</b>	<b>\$6,847,521</b>
21	Brooklyn	K128		<b>P.S. 128 (TANDEM BROOKLYN STUDIO)</b>				
					DSF0000800301	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2016	1,121,859
					DSF0000911872	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	4,858
			K128		DSF0000822174	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	862,523
			K128		DSF0000822175	<i>State of Good Repair - System Replacements - Windows</i>	2017	1,543,969

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K128		DSF0000889216	New/Retrofit Telephone/Intercom Systems	2018	289,526
			K128		DSF0000889404	IP Surveillance Camera Installation	2019	39,644
<b>P.S. 128 (TANDEM BROOKLYN STUDIO) Total:</b>								<b>\$3,862,379</b>
21	Brooklyn	K153		<b>P.S. 153</b>				
			K153		DSF0000822147	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	158,352
						<i>Other</i>		
			K153		DSF0000867133	New/Retrofit Telephone/Intercom Systems	2018	179,698
<b>P.S. 153 Total:</b>								<b>\$338,050</b>
21	Brooklyn	K177		<b>P.S. 177</b>				
					DSF0000757861	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	5,094,461
						EXTERIOR:EXTERIOR WALLS		
<b>P.S. 177 Total:</b>								<b>\$5,094,461</b>
21	Brooklyn	K188		<b>P.S. 188</b>				
			K188		DSF0000870923	<b>Auditorium Upgrade</b>	2019	393,750
						INTERIOR:AUDITORIUM:Floor Finish		
			K188		DSF0000780542	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	978,245
						CLIMATE CONTROL SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K188		DSF0000780545	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	6,276,853
			K188		DSF0000780563	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	2,464,137
					DSF0000780543	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	1,856,456
			K188		DSF0000780550	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,003,150
					DSF0000870915	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	252,579



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000780560	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2015	1,690,196
			K188		DSF0000798612	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	4,710,201
							<b>P.S. 188 Total:</b>	\$20,625,567
21	Brooklyn	K199		<b>P.S. 199</b>				
					DSF0000780783	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	708,291
							<b>P.S. 199 Total:</b>	\$708,291
21	Brooklyn	K209		<b>P.S. 209</b>				
					DSF0000848624	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Meter Room Exhaust Fan HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating	2018	274,596

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K209	DSF0000865971		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>P.S. 209 Total:</b>	<b>\$427,325</b>
21	Brooklyn	K212		<b>P.S. 212</b>				
			K212	DSF0000826760		<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2017	500,431
						INTERIOR:STAIRS/RAMPS: INTERIOR		
			K212	DSF0000804352		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	6,054,464
						EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR WALLS		
			K212	DSF0000804351		<i>State of Good Repair - System Replacements - Parapets</i>	2018	1,683,745
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
			K212	DSF0000804350		<i>State of Good Repair - System Replacements - Roofs</i>	2018	2,136,936
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			K212	DSF0000822685		<i>State of Good Repair - System Replacements - Windows</i>	2018	6,298,830
						EXTERIOR:WINDOWS		
							<b>P.S. 212 Total:</b>	<b>\$16,674,406</b>
21	Brooklyn	K215		<b>P.S. 215</b>				
				DSF0000798398		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	808,453

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000871434	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	2,320,398
					DSF0000871433	EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER <b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,549,787
							<b>P.S. 215 Total:</b>	<b>\$4,678,638</b>
21	Brooklyn	K216		<b>P.S. 216</b>				
					DSF0000781136	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING	2016	349,463
					DSF0000781122	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2016	1,405,353

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
			K216		DSF0000865973	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 216 Total:</b>	\$1,969,608
21	Brooklyn	K225		<b>P.S. 225</b>				
			K225		DSF0000735855	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	2,652,789
					DSF0000799551	INTERIOR:STRUCTURAL:FOUNDATION WALLS <i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	399,903
					DSF0000866815	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	5,335
			K225		DSF0000758755	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	3,128,446
			K225		DSF0000758754	EXTERIOR:EXTERIOR WALLS <i>State of Good Repair - System Replacements - Parapets</i>	2017	3,872,018
			K225		DSF0000775945	EXTERIOR:PARAPETS <i>State of Good Repair - System Replacements - Roofs</i>	2017	1,841,025
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K225		DSF0000865976	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
			K225		DSF0000889411	<i>Other</i> IP Surveillance Camera Installation	2019	39,577
							<b>P.S. 225 Total:</b>	\$12,153,885
21	Brooklyn	K226		<b>P.S. 226</b>				
			K226		DSF0000889356	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	50,000
					DSF0000777475	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	75,364
							<b>P.S. 226 Total:</b>	\$125,364
21	Brooklyn	K228		<b>I.S. 228</b>				
					DSF0000821597	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2015	585,559
					DSF0000844008	<i>State of Good Repair - System Replacements - Domestic Piping</i>	2015	147,546
			K228		DSF0000804663	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	184,413

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<i>Other</i>		
			K228		DSF0000889536	IP Surveillance Camera Installation	2019	39,846
							<b>I.S. 228 Total:</b>	<b>\$957,364</b>
21	Brooklyn	K238		<b>P.S. 238</b>				
					DSF0000866817	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	7,986
					DSF0000799876	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	7,685,183
					DSF0000804821	<i>State of Good Repair - System Replacements - Parapets</i>	2017	1,213,580
						EXTERIOR:PARAPETS		
			K238		DSF0000804826	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	195,438
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 238 Total:</b>	<b>\$9,102,187</b>
21	Brooklyn	K239		<b>I.S. 239</b>				
			K239		DSF0000781545	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	4,674,186

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000798613	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	3,042,529
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
			K239		DSF0000798614	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	557,696
			K239		DSF0000781544	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2015	6,172,326
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
			K239		DSF0000781551	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	2,690,527
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
			K239		DSF0000798615	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	6,941,131

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000804851	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	465,787
						FIXTURES:STUDENT:Toilet		
							<b>I.S. 239 Total:</b>	\$24,544,182
21	Brooklyn	K253		<b>P.S. 253</b>				
			K253		DSF0000781795	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	1,796,651
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
			K253		DSF0000889015	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	552,671
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000889312	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	45,721
			K253		DSF0000849395	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	4,190,631
						EXTERIOR:EXTERIOR WALLS		
			K253		DSF0000798623	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	4,632,451
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K253		DSF0000872098	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,087,197



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000781804	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Paved Area - Blacktop</b>	2015	2,519,489
			K253		DSF0000872097	SITE:Drainage System for Asphalt SITE:PAVING - STUDENT NON-USE:Asphalt SITE:PAVING - STUDENT USE:Asphalt <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	2,084,172
							<b>P.S. 253 Total:</b>	<b>\$18,908,983</b>
21	Brooklyn	K281		<b>I.S. 281</b>	DSF0000821589	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	607,546
			K281		DSF0000865852	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,183,398
					DSF0000799408	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2015	1,063,463
					DSF0000805551	CONVEYING:ASH HOIST CONVEYING:SIDEWALK ELEVATOR <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	342,773
					DSF0000799694	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	169,836

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000805550	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,760,538
						AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY		
			K281		DSF0000821625	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2017	423,797
			K281		DSF0000912395	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	62,953
						DOMESTIC WATER SYSTEM		
			K281		DSF0000866073	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
					DSF0000868172	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	368,240
						<b>Other</b>		
			K281		DSF0000776047	IP Surveillance Camera Installation	2015	672,524
							<b>I.S. 281 Total:</b>	<b>\$6,869,860</b>
21	Brooklyn	K288		<b>P.S. 288</b>				
			K288		DSF0000782372	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2015	9,463,436
					DSF0000782368	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	889,696
						CLIMATE CONTROL SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799415	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	2,465,276
					DSF0000799413	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	2,487,589
					DSF0000799414	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD	2015	1,063,695
					DSF0000868270	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	229,199
			K288		DSF0000799834	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			K288		DSF0000843652	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	4,435,192
			K288		DSF0000805675	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	141,537

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 288 Total:</b>	\$21,207,279
21	Brooklyn	K303		<b>I.S. 303</b>				
			K303	DSF0000822168		<b>Educational Enhancements - Educational Enhancements - Library Upgrade</b>	2015	416,419
						INTERIOR:LIBRARY:Ceiling INTERIOR:LIBRARY:Walls		
				DSF0000759997		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,719,906
						CLIMATE CONTROL SYSTEM		
				DSF0000777693		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	3,323,925
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000777694		<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,905,518
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799695	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	229,760
					DSF0000760001	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,307,140
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
					DSF0000866831	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	2,637
			K303		DSF0000911833	<b>State of Good Repair - System Replacements - Floors</b>	2019	142,061
					DSF0000760002	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	9,603,704
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000782591	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	673,974
						Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR		
			K303		DSF0000799862	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K303		DSF0000865983	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>I.S. 303 Total:</b>	\$19,509,432
21	Brooklyn	K329		<b>P.S. 329</b>				
					DSF0000799460	<i>State of Good Repair - Building Upgrade - Air Conditioning Retrofit</i>	2015	1,717,484
					DSF0000799430	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	861,515
					DSF0000799456	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2015	316,397
						CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR		
					DSF0000799429	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	9,836,877
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799425	<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2015	2,534,320
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000806200	INTERIOR:STAIRS/RAMPS: INTERIOR <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,100,380
					DSF0000799923	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b> SITE:PLAYGROUNDS:Fence SITE:PLAYGROUNDS:Play Equipment SITE:PLAYGROUNDS:Safety Surfacing SITE:SEATING:Benches	2015	630,738
					DSF0000782913	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING	2015	1,698,090
					DSF0000782900	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD	2015	1,892,621

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SERVICE SWITCH SWITCHBOARD		
					DSF0000782901	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	7,080,825
					DSF0000782912	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	737,873
						Ventilation AIR CONDITIONING:CHILLED WATER SYSTEM:Central Station Air Handler AIR CONDITIONING:CHILLED WATER SYSTEM:Fan Coil Unit MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:UNIT VENTILATOR		
			K329		DSF0000799840	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			K329		DSF0000806207	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	150,000
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K329	DSF0000873073		TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	200,221
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							<b>P.S. 329 Total:</b>	\$28,789,000
22	Brooklyn	K014		<b>I.S. 14</b>				
				DSF0000821955		<b>Room Conversions / Partitioning</b>	2016	2,807,501
			K014	DSF0000798243		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	7,251,773
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS		
				DSF0000778032		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	3,617,653
			K014	DSF0000801384		CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	950,073
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSF0000799790		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	52,272

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K014		DSF0000801393	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent AUDITORIUM:THEATER LIGHTING SYSTEM:Dimming System AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Ceiling INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains INTERIOR:AUDITORIUM:Walls INTERIOR:AUDITORIUM:Window Curtains/Shades/Blinds	2018	72,127
					DSF0000821945	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2016	57,771
			K014		DSF0000823943	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2016	136,147

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
					DSF0000801388	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	101,351
						FIXTURES:STUDENT:Toilet		
						<b>Other</b>		
			K014		DSF0000889217	New/Retrofit Telephone/Intercom Systems	2018	299,890
			K014		DSF0000889393	IP Surveillance Camera Installation	2019	40,181
							<b>I.S. 14 Total:</b>	<b>\$15,386,739</b>
22	Brooklyn	K052		<b>P.S. 52</b>				
			K052		DSF0000891914	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	50,569
						Waste System		
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
					DSF0000866773	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	36,789
					DSF0000756171	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,028,146
						EXTERIOR:EXTERIOR WALLS		
					SCA0000025073	<b>State of Good Repair - System Replacements - Parapets</b>	2015	4,617,540
					DSF0000756169	<b>State of Good Repair - System Replacements - Roofs</b>	2015	1,033,334
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000801977	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2015	101,351
						<b>Other</b>		
			K052		DSF0000776036	IP Surveillance Camera Installation	2015	560,050
							<b>P.S. 52 Total:</b>	<b>\$8,427,779</b>
22	Brooklyn	K078		<b>I.S. 78</b>				
			K078		DSF0000888761	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	614,049
			K078		DSF0000845583	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	126,000
			K078		DSF0000821898	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging	2018	66,744
			K078		DSF0000892197	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2019	140,952
					DSF0000866777	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,404

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K078		DSF0000869425	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube	2018	178,271
			K078		DSF0000888816	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	1,141,914
			K078		DSF0000822142	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	204,424
						<b>Other</b>		
			K078		DSF0000889218	New/Retrofit Telephone/Intercom Systems	2018	226,771
			K078		DSF0000868109	IP Surveillance Camera Installation	2018	500,949
							<b>I.S. 78 Total:</b>	<b>\$3,206,478</b>
22	Brooklyn	K119		<b>P.S. 119</b>				
			K119		DSF0000798251	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	6,150,083
					DSF0000779550	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	1,011,080

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000757056	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	971,733
					DSF0000757060	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	633,441
			K119		DSF0000802881	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	280,576
							<b>P.S. 119 Total:</b>	<b>\$9,046,913</b>
22	Brooklyn	K139		<b>P.S. 139</b>				
					DSF0000779810	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	993,409
			K139		DSF0000803155	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	123,882

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
INTERIOR:TOILET ROOMS - STUDENTS								
							<b>P.S. 139 Total:</b>	\$1,117,291
22	Brooklyn	K152		<b>P.S. 152</b>				
			K315	DSF0000865939		<b>Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Floor Finish	2018	891,686
				DSF0000799726		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	119,002
				DSF0000803297		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY	2018	1,814,095
			K315	DSF0000822188		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,645,659
				DSF0000888979		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	180,000
			K152	DSF0000847702		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller AIR CONDITIONING:DX Split System	2018	1,171,948

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 152 Total:</b>	\$5,822,390
22	Brooklyn	K193		<b>P.S. 193</b>		AIR CONDITIONING:Refrigerant Piping AIR CONDITIONING:Return Fan		
			K193	DSF0000821910		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	1,746,968
			K193	DSF0000893807		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	142,758
						HEATING:Steam Heating		
			K193	DSF0000803976		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	176,328
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 193 Total:</b>	\$2,066,054
22	Brooklyn	K194		<b>P.S. 194</b>				
			K194	DSF0000799529		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2015	1,144,105
				SCA0000026654		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	1,663,268
				DSF0000780676		<b>State of Good Repair - System Replacements - Parapets</b>	2016	1,389,958
						EXTERIOR:PARAPETS		
				DSF0000799794		<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,062,016



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799793	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2016	667,844
							<b>P.S. 194 Total:</b>	\$6,927,191
22	Brooklyn	K195		<b>P.S. 195</b>	DSF0000780694	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	937,722
					DSF0000799411	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP	2015	4,402,791
					DSF0000799410	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	397,007

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000780696	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	669,956
					DSF0000780701	<b>State of Good Repair - System Replacements - Electrical Systems</b> LIGHTNING PROTECTION PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,546,007
					DSF0000800314	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2015	684,846
					DSF0000800325	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING	2015	4,089,166
			K195		DSF0000889588	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 195 Total:</b>	<b>\$12,942,287</b>
22	Brooklyn	K197		<b>P.S. 197</b>				
					DSF0000848400	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,603,368

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799544	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	177,687
					DSF0000888808	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	787,817
					DSF0000848403	DOMESTIC WATER SYSTEM <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	7,158,314
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
			K197		DSF0000866109	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000848402	<b>State of Good Repair - System Replacements - Parapets</b>	2018	2,158,791
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000866190	<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,511,527
						EXTERIOR:ROOF:Roofing		
			K197		DSF0000865969	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,823
					DSF0000866191	<b>State of Good Repair - System Replacements - Windows</b>	2018	1,835,301
						EXTERIOR:WINDOWS		
							<b>P.S. 197 Total:</b>	<b>\$16,463,318</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
22	Brooklyn	K198		<b>P.S. 198</b>				
					DSF0000735361	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:ELEVATORS	2015	1,328,971
			K198		DSF0000799532	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,642,720
					DSF0000758236	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2015	2,622,105
					DSF0000848425	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2018	113,206
					DSF0000780761	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	694,041
					DSF0000780760	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	1,559,086

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
					DSF0000758235	<b>State of Good Repair - System Replacements - Windows</b>	2015	2,270,456
						EXTERIOR:WINDOWS		
							<b>P.S. 198 Total:</b>	\$10,230,585
22	Brooklyn	K203		<b>P.S. 203</b>				
					DSF0000799728	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	116,404
					DSF0000868190	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	261,846
						<b>Other</b>		
			K203		DSF0000867137	New/Retrofit Telephone/Intercom Systems	2018	207,054
							<b>P.S. 203 Total:</b>	\$585,304
22	Brooklyn	K206		<b>P.S. 206</b>				
			K206		DSF0000735507	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,310,653
						FIRE ALARM SYSTEM		
							<b>P.S. 206 Total:</b>	\$1,310,653
22	Brooklyn	K207		<b>P.S. 207</b>				
					DSF0000777474	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	101,858

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K207	DSF0000804258		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	101,351
							<b>P.S. 207 Total:</b>	\$203,209
22	Brooklyn	K217		<b>P.S. 217</b>				
			K217	DSF0000804446		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	831,876
				DSF0000799549		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	126,384
			K217	DSF0000758598		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	2,693,749
			K217	DSF0000866111		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			K217	DSF0000801043		<b>State of Good Repair - System Replacements - Kitchen Areas</b> INTERIOR:KITCHEN/WARMING PANTRY:Ceiling	2015	85,848
			K217	DSF0000781142		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	3,534,349
				DSF0000871479		<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	60,545

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SITE:PAVING:Site Sidewalks & Walkways:Concrete		
			K217		DSF0000865974	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			K217		DSF0000781143	<b>State of Good Repair - System Replacements - Windows</b>	2018	7,220,827
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			K217		DSF0000867138	New/Retrofit Telephone/Intercom Systems	2018	232,090
							<b>P.S. 217 Total:</b>	<b>\$15,078,150</b>
22	Brooklyn	K222		<b>P.S. 222</b>				
			K222		DSF0000865975	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			K222		DSF0000867145	New/Retrofit Telephone/Intercom Systems	2018	225,075
							<b>P.S. 222 Total:</b>	<b>\$439,867</b>
22	Brooklyn	K234		<b>I.S. 234</b>				
					DSF0000912311	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	63,289
						EMERGENCY LIGHT/EXIT LIGHT PANEL		
						EMERGENCY LIGHTING		
						EXIT LIGHT		
						EXIT/EMERGENCY LIGHT		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868268	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	575,630
					DSF0000822243	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	73,207
						<i>Other</i>		
			K234		DSF0000776046	IP Surveillance Camera Installation	2015	628,355
							<b>I.S. 234 Total:</b>	<b>\$1,340,481</b>
22	Brooklyn	K236		<b>P.S. 236</b>				
					DSF0000804795	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	860,987
			K236		DSF0000844159	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2018	5,804,264
					DSF0000775684	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:EXTERIOR WALLS	2018	7,169,377
			K236		DSF0000849125	<i>State of Good Repair - System Replacements - Fencing</i> SITE:FENCES	2018	310,338
					DSF0000781500	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	4,471,483
					DSF0000781499	<i>State of Good Repair - System Replacements - Roofs</i>	2018	3,027,672



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						<i>Other</i>		
			K236		DSF0000866225	New/Retrofit Telephone/Intercom Systems	2017	185,141
							<b>P.S. 236 Total:</b>	<b>\$21,829,262</b>
22	Brooklyn	K240		<b>I.S. 240</b>				
					DSF0000871887	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	2,856,022
					DSF0000781566	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,201,603
			K240		DSF0000804879	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains	2018	112,136
					DSF0000871891	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,149,810

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
					DSF0000871888	<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,984,685
						EXTERIOR:ROOF:Roofing		
			K240		DSF0000889589	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000871890	<b>State of Good Repair - System Replacements - Windows</b>	2019	1,905,816
						EXTERIOR:WINDOWS		
							<b>I.S. 240 Total:</b>	<b>\$9,424,864</b>
22	Brooklyn	K251		<b>P.S. 251</b>				
					DSF0000781763	<b>Safety and Security - Safety and Security - Safety Systems</b>	2015	239,302
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
			K251		DSF0000888998	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	6,195,030
			K251		DSF0000781746	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	1,064,602
						CLIMATE CONTROL SYSTEM		
					DSF0000805048	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,032,114
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000759195	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,281,591
					DSF0000759194	EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2015	2,073,448
					DSF0000759193	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2015	3,181,541
			K251		DSF0000889591	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000798646	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	439,357
							<b>P.S. 251 Total:</b>	<b>\$16,721,777</b>
22	Brooklyn	K254		<b>P.S. 254</b>				
			K254		DSF0000781813	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	551,531
			K254		DSF0000781814	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP	2015	2,039,232

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			K254		DSF0000798618	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	194,036
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
					DSF0000781824	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	1,462,615
						Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR		
			K254		DSF0000798617	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	4,132,325
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000781815	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,654,344
						EXTERIOR:ROOFING:Roofing		
					DSF0000801067	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,194,131
						EXTERIOR:ROOFING:Specialties		
							<b>P.S. 254 Total:</b>	<b>\$11,228,214</b>
22	Brooklyn	K255		<b>P.S. 255</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799691	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	114,581
					DSF0000872134	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	4,173,194
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
					DSF0000872132	<b>State of Good Repair - System Replacements - Parapets</b>	2019	2,136,989
						EXTERIOR:PARAPETS		
					DSF0000872131	<b>State of Good Repair - System Replacements - Roofs</b>	2019	2,787,246
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			K255		DSF0000889592	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000872133	<b>State of Good Repair - System Replacements - Windows</b>	2019	7,554,406
						EXTERIOR:WINDOWS		
							<b>P.S. 255 Total:</b>	<b>\$16,981,208</b>
22	Brooklyn	K269		<b>P.S. 269</b>				
					DSF0000799555	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	800,980
					DSF0000736572	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	3,359,471
						EXTERIOR:CHIMNEY		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
					DSF0000782062	<b>State of Good Repair - System Replacements - Parapets</b>	2015	1,988,953
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000782061	<b>State of Good Repair - System Replacements - Roofs</b>	2015	2,098,093
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 269 Total:</b>	<b>\$8,247,497</b>
22	Brooklyn	K277		<b>P.S. 277</b>				
					DSF0000777478	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	103,889
					DSF0000798258	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	5,433,829
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
					DSF0000798259	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	1,926,055
						CLIMATE CONTROL SYSTEM		
					DSF0000912389	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,698
			K277		DSF0000782213	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			K277		DSF0000849756	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	109,461
						<b>Other</b>		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K277	DSF0000889219		New/Retrofit Telephone/Intercom Systems	2018	157,847
							<b>P.S. 277 Total:</b>	<b>\$7,764,438</b>
22	Brooklyn	K278		<b>I.S. 278</b>				
			K278	DSF0000821903		<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2018	81,679
			K278	DSF0000827876		<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2017	111,237
							<b>I.S. 278 Total:</b>	<b>\$192,916</b>
22	Brooklyn	K312		<b>P.S. 312</b>				
			K312	DSF0000828317		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	1,298,040
				DSF0000866834		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	849
				DSF0000782718		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING	2015	1,641,828

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K312		DSF0000799863	HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS <i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	298,455
							<b>P.S. 312 Total:</b>	\$3,239,172
22	Brooklyn	K395		<b>P.S./I.S. 395</b>				
					DSF0000799736	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	155,620
			K109		DSF0000797530	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	1,978,497
			K109		DSF0000842620	EXTERIOR:EXTERIOR WALLS <i>State of Good Repair - System Replacements - Gymnasium Upgrade</i>	2016	245,332
			K109		DSF0000912160	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	133,396
			K109		DSF0000801050	GAS SERVICE:Gas Distribution Piping HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater <i>State of Good Repair - System Replacements - Parapets</i>	2018	1,197,057
			K109		DSF0000801049	EXTERIOR:PARAPETS <i>State of Good Repair - System Replacements - Roofs</i>	2018	1,560,080
							<b>P.S./I.S. 395 Total:</b>	\$5,269,982



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
22	Brooklyn	K729		<b>P.S. 207 ANNEX</b>				
					DSF0000911874	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	2,259
						<i>Other</i>		
			K207		DSF0000867152	New/Retrofit Telephone/Intercom Systems	2018	147,768
							<b>P.S. 207 ANNEX Total:</b>	<b>\$150,027</b>
22	Brooklyn	K735		<b>P.S. 245</b>				
					DSF0000912314	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	33,636
						EMERGENCY LIGHTING		
						EXIT LIGHT		
							<b>P.S. 245 Total:</b>	<b>\$33,636</b>
22	Brooklyn	K776		<b>PS 152 ANNEX</b>				
					DSF0000797971	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	889,262
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>PS 152 ANNEX Total:</b>	<b>\$889,262</b>
22	Brooklyn	K839		<b>P.S. 134 MINISCHOOL</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K134		DSF0000889601	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 134 MINISCHOOL Total:</b>	\$214,792
22	Brooklyn	K849		<b>P.S. 134</b>				
					DSF0000799576	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	520,961
					DSF0000807626	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	375,860
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR WALLS		
					DSF0000807625	<i>State of Good Repair - System Replacements - Parapets</i>	2015	251,756
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000784330	<i>State of Good Repair - System Replacements - Roofs</i>	2015	1,112,001
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
					DSF0000821635	<i>State of Good Repair - System Replacements - Roofs</i>	2015	216,427
						EXTERIOR:ROOFING:Roofing		
			K134		DSF0000865992	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
						<i>Other</i>		
			K134		DSF0000822060	New/Retrofit Telephone/Intercom Systems	2015	135,928

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 134 Total:</b>	\$2,765,662
22	Brooklyn	K864		<b>P.S. 361 (OLD 89)</b>				
			K361	DSF0000888993		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b> Gymnasium Upgrade	2018	317,460
			K361	DSF0000822151		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	101,351
							<b>P.S. 361 (OLD 89) Total:</b>	\$418,811
23	Brooklyn	K041		<b>P.S. 41</b>				
			K041	DSF0000890602		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2019	6,697,135
			K041	DSF0000884667		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	3,185,765
				DSF0000868179		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	243,320
				DSF0000801809		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	183,975

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000822660	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
					DSF0000801810	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Toilet	2015	133,620
							<b>P.S. 41 Total:</b>	\$10,588,601
23	Brooklyn	K055		<b>I.S. 55</b>				
			K493		DSF0000844720	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	350,117
			K493		DSF0000846491	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2018	1,054,468
			K493		DSF0000869196	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> PUBLIC ADDRESS SYSTEM GAS SERVICE:Gas Meter Room Exhaust Fan HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2019	778,317
							<b>I.S. 55 Total:</b>	\$2,182,902
23	Brooklyn	K073		<b>P.S. 73</b>				
			K599		DSF0000865827	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	348,589

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K073	DSF0000821912		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	943,935
			K073	SCA0000028933		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	9,412,032
				DSF0000823570		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
						HEATING PLANT:BOILER SYSTEM		
			K073	DSF0000802236		<b>State of Good Repair - System Replacements - Parapets</b>	2016	595,287
						EXTERIOR:PARAPETS		
			K073	DSF0000802235		<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,420,900
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			K073	DSF0000778918		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	217,851
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
			K073	DSF0000865959		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729

**P.S. 73 Total: \$14,161,046**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000779774	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	566,102
					DSF0000866796	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	38,560
					DSF0000821942	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	5,450,717
			K137		DSF0000888922	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	199,386
					DSF0000843959	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	268,919
					DSF0000803113	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	138,098
							<b>P.S. 137 Total:</b>	<b>\$6,661,782</b>
23	Brooklyn	K150		<b>P.S. 150</b>				
			K150		DSF0000843900	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	63,923

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K150		DSF0000825695	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	868,199
					DSF0000866797	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	5,166
			K150		DSF0000821710	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	2,054,377
					DSF0000822242	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2016	52,124
					DSF0000822652	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	308,282
			K150		DSF0000844013	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	2,995,843
					DSF0000803265	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	307,526
			K150		DSF0000822129	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2015	284,241
							<b>P.S. 150 Total:</b>	<b>\$6,939,681</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
23	Brooklyn	K155		<b>P.S. 155</b>				
			K155		DSF0000865830	<i>Educational Enhancements - Educational Enhancements - Library Upgrade</i>	2017	432,995
			K155		DSF0000866107	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			K155		DSF0000888904	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	416,555
			K155		DSF0000780027	GAS SERVICE:Gas Distribution Piping <i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	118,398
							<b>P.S. 155 Total:</b>	<b>\$1,045,638</b>
23	Brooklyn	K165		<b>P.S. 165</b>				
			K165		DSF0000825934	<i>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</i>	2018	241,376
					DSF0000912418	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	18,402



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000803510	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	205,521
					DSF0000803511	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	203,007
						FIXTURES:STUDENT:Toilet		
			K165		DSF0000823663	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	226,203
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
			K165		DSF0000865732	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
							<b>P.S. 165 Total:</b>	\$1,210,382
23	Brooklyn	K178		<b>P.S. 178</b>				
					DSF0000844145	<b>Domestic Piping</b>	2017	108,286
						DOMESTIC WATER SYSTEM		
						FIXTURES:Student:Drinking Fountain		
						FIXTURES:Student:Sink And Fountain Combo Unit		
			K077		DSF0000826122	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	512,126
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000780383	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,152,204

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866801	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	46,811
			K077		DSF0000826128	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2017	2,139,527
					DSF0000803719	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2017	171,528
			K077		DSF0000826126	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	308,650
			K077		DSF0000757881	<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,374,122

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
			K178	DSF0000889599		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			K077	DSF0000826127		<b>State of Good Repair - System Replacements - Windows</b>	2017	3,742,662
			K178	DSF0000865733		EXTERIOR:WINDOWS <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
							<b>P.S. 178 Total:</b>	<b>\$11,086,581</b>
23	Brooklyn	K183		<b>P.S. 183</b>				
				DSF0000757961		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	9,454,293
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
				DSF0000780472		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	74,389
						HEATING		
				DSF0000822653		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	205,521
				DSF0000823584		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	52,218
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K446	DSF0000865734		HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
							<b>P.S. 183 Total:</b>	\$10,102,294
23	Brooklyn	K184		<b>P.S. 184</b>				
				DSF0000777472		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	221,127
				DSF0000870862		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	4,686,585
				DSF0000844133		EXTERIOR:CHIMNEY <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	84,838
				DSF0000870861		<b>State of Good Repair - System Replacements - Parapets</b>	2019	1,085,529
				DSF0000870860		EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	3,543,229
				DSF0000867026		EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	2,717,836
							<b>P.S. 184 Total:</b>	\$12,339,144
23	Brooklyn	K263		<b>P.S./I.S. 323</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821624	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2017	331,221
					DSF0000888980	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	621,543
			K140		DSF0000822114	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR SOFFITS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	361,916
			K323		DSF0000805288	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2018	144,786
			K323		DSF0000865736	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2018	315,873
							<b>P.S./I.S. 323 Total:</b>	<b>\$1,775,339</b>
23	Brooklyn	K271		<b>I.S. 271</b>				
			K522		DSF0000843916	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2016	310,139

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			K644		DSF0000843930	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2016	165,634
						Technology		
			K522		DSF0000798283	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	6,904,109
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System		
			K522		DSF0000798285	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,940,707
						CLIMATE CONTROL SYSTEM		
					DSF0000866823	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	22,761
			K522		DSF0000782104	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	37,426
						<b>Other</b>		
			K644		DSF0000889419	IP Surveillance Camera Installation	2019	40,382
							<b>I.S. 271 Total:</b>	<b>\$10,421,158</b>
23	Brooklyn	K275		<b>I.S. 275</b>				
			K647		DSF0000843917	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	101,725

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866825	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	6,683
			K518		DSF0000782173	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	302,173
			K518		DSF0000865981	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
						<i>Other</i>		
			K518		DSF0000889420	IP Surveillance Camera Installation	2019	40,297
							<b>I.S. 275 Total:</b>	<b>\$665,670</b>
23	Brooklyn	K284		<b>P.S. 284</b>				
			K284		DSF0000827934	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2018	1,917,529
			K284		DSF0000827950	<i>State of Good Repair - Building Upgrade - Interior Spaces</i> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	445,346
					DSF0000798400	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> INTERIOR:STAIRS/RAMPS: INTERIOR	2015	427,538
			K284		DSF0000822117	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2018	1,038,959

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			K284		DSF0000866113	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
							<b>P.S. 284 Total:</b>	<b>\$3,907,062</b>
23	Brooklyn	K298		<b>P.S. 298</b>				
					DSF0000912238	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	54,965
					DSF0000828143	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2017	632,985
						AUDITORIUM:Local Sound System AUDITORIUM:Theater Lighting System:Dimming System AUDITORIUM:Theater Lighting System:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtains		
					DSF0000868271	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	306,469
			K298		DSF0000828138	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	45,708
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K298		DSF0000850039	HEATING PLANT:Boiler System HEATING PLANT:Fuel System <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	394,602
			K298		DSF0000865825	GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2017	593,609
							<b>P.S. 298 Total:</b>	<b>\$2,028,338</b>
23	Brooklyn	K327		<b>P.S. 327 (TANDEM K396-D75)</b>				
					DSF0000865891	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	261,175
			K327		DSF0000889358	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	151,072
					DSF0000866837	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	6,000
			K327		DSF0000782865	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	37,727

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K396		DSF0000828470	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Backflow Preventer AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller AIR CONDITIONING:Packaged / Rooftop Unit	2016	232,420
					DSF0000806167	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	152,831
<b>P.S. 327 (TANDEM K396-D75) Total:</b>								\$841,225
23	Brooklyn	K332		<b>P.S. 332</b>				
			K401		DSF0000843914	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	88,587
			K401		DSF0000843934	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	216,864

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K332		DSF0000782921	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	31,680
					DSF0000806225	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	308,282
						<b>Other</b>		
			K332		DSF0000866226	New/Retrofit Telephone/Intercom Systems	2017	180,112
							<b>P.S. 332 Total:</b>	<b>\$825,525</b>
23	Brooklyn	K356		<b>P.S. 156</b>				
			K156		DSF0000864553	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	65,340
			K156		DSF0000866184	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING:Steam Heating	2018	266,211
			K156		DSF0000866027	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	170,000
			K156		DSF0000888949	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	196
							<b>P.S. 156 Total:</b>	<b>\$501,747</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
23	Brooklyn	K854		<b>P.S. 178 AX (BED STUY ECC 1)</b>				
			K178		DSF0000865743	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
<b>P.S. 178 AX (BED STUY ECC 1) Total:</b>								<b>\$315,873</b>
32	Brooklyn	K045		<b>P.S. 45</b>				
					DSF0000798385	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	667,560
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000799742	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	106,303
					DSF0000801865	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			K045		DSF0000888815	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	771,617
			K045		DSF0000778533	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	96,740
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			K045		DSF0000865955	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 45 Total:</b>	\$2,001,798
32	Brooklyn	K075		<b>P.S. 75</b>				
					DSF0000869404	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	1,274,758
					DSF0000778935	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	763,078
					DSF0000869407	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	3,692,816
					DSF0000778943	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2015	88,318
					DSF0000912549	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	1,998,868
						<b>Other</b>		
			K075		DSF0000866238	New/Retrofit Telephone/Intercom Systems	2017	167,369
							<b>P.S. 75 Total:</b>	\$7,985,207

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
32	Brooklyn	K086		<b>P.S. 86</b>				
					DSF0000867172	<i>Domestic Piping</i>	2018	1,510,000
					DSF0000866779	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	41,814
			K086		DSF0000779033	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	399,846
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
<b>P.S. 86 Total:</b>								\$1,951,660
32	Brooklyn	K106		<b>P.S. 106</b>				
			K106		DSF0000866103	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			K106		DSF0000822136	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	373,752
						INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			K106		DSF0000889260	New/Retrofit Telephone/Intercom Systems	2018	190,499
<b>P.S. 106 Total:</b>								\$641,941
32	Brooklyn	K111		<b>I.S. 111</b>				
			K347		DSF0000821837	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	1,242,411

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K347		DSF0000843897	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	29,011
			K349		DSF0000843898	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	329,776
			K347		DSF0000843933	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2016	196,195
			K347		DSF0000844736	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	302,078
			K349		DSF0000888790	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	190,000
			K349		DSF0000912254	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2019	35,000
					DSF0000802752	<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2017	2,137,649

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:EMERGENCY GAS SHUT-OFF VALVE SCIENCE DEMO ROOM:EMERGENCY SHUT-OFF POWER		
					DSF0000821904	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2017	839,303
					DSF0000777462	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	118,340
					DSF0000799689	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	283,885
					DSF0000821628	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
					DSF0000847155	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2018	992,935
							<b>I.S. 111 Total:</b>	<b>\$7,175,649</b>
32	Brooklyn	K116		<b>P.S. 116</b>				



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799541	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	83,518
					DSF0000799743	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	15,577
							<b>P.S. 116 Total:</b>	<b>\$99,095</b>
32	Brooklyn	K123		<b>P.S. 123</b>				
					DSF0000757105	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	271,406
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799744	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	52,485
					DSF0000757104	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2015	1,344,403
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000847330	<i>State of Good Repair - System Replacements - Domestic Piping</i>	2018	123,899
						DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain FIXTURES:Student:Sink And Fountain Combo Unit		
					DSF0000757108	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2015	3,879,647
						EXTERIOR:EXTERIOR WALLS		
					DSF0000757112	<i>State of Good Repair - System Replacements - Floors</i>	2015	1,240,055

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish		
			K123		DSF0000866104	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000779611	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2015	1,143,154
					DSF0000753103	SITE:SIDEWALKS:Site Sidewalk and Walkways <b>State of Good Repair - System Replacements - Roofs</b>	2015	5,138,347
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			K123		DSF0000776040	IP Surveillance Camera Installation	2015	566,163
							<b>P.S. 123 Total:</b>	<b>\$13,837,249</b>
32	Brooklyn	K145		<b>P.S. 145</b>				
					DSF0000844723	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	125,566
					DSF0000779855	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	114,262
					DSF0000890570	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	2,174
					DSF0000779864	<b>State of Good Repair - System Replacements - Floors</b>	2016	281,957
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K145		DSF0000866105	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			K145		DSF0000822127	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	105,412
						INTERIOR:TOILET ROOMS - STUDENTS		
			K145		DSF0000865967	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
			K145		DSF0000888948	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2019	TBD
						<i>Other</i>		
			K145		DSF0000867123	New/Retrofit Telephone/Intercom Systems	2018	249,547
							<b>P.S. 145 Total:</b>	<b>\$1,171,400</b>
32	Brooklyn	K151		<b>P.S. 151</b>				
			K151		DSF0000893130	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	309,727
						HEATING:Steam Heating		
					DSF0000803286	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	244,978
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868066	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	141,082
							<b>P.S. 151 Total:</b>	<b>\$695,787</b>
32	Brooklyn	K162		<b>I.S. 162</b>				
			K162		DSF0000847841	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	856,145
			K162		DSF0000866310	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	822,618
			K162		DSF0000803472	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:STAIRS/RAMPS: INTERIOR	2018	6,940,024
					DSF0000780130	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	899,638
			K162		DSF0000847838	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2018	1,332,215
			K162		DSF0000847844	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	7,870,418

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
			K162		DSF0000847843	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,829,321
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			K162		DSF0000847842	<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,993,405
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			K162		DSF0000867139	New/Retrofit Telephone/Intercom Systems	2018	198,722
			K162		DSF0000889535	IP Surveillance Camera Installation	2019	39,242
							<b>I.S. 162 Total:</b>	<b>\$25,781,748</b>
32	Brooklyn	K291		<b>I.S. 291</b>				
			K291		DSF0000844680	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,628,378
					DSF0000777479	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	241,619
					DSF0000798386	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	491,825
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000805726	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent  <b>Other</b>	2017	172,554
					DSF0000867033	IP Surveillance Camera Installation	2018	603,960
							<b>I.S. 291 Total:</b>	\$4,138,336
32	Brooklyn	K296		<b>I.S. 296</b>				
			K296		DSF0000843931	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2016	108,432
			K053		DSF0000888860	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	36,000
					DSF0000867034	<b>Other</b> IP Surveillance Camera Installation	2018	438,940
							<b>I.S. 296 Total:</b>	\$583,372
32	Brooklyn	K376		<b>P.S. 376A</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000865892	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	115,116
					DSF0000896059	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2019	226,164
			K376		DSF0000873206	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	314,724
					DSF0000823571	EXTERIOR:CHIMNEY <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
						HEATING PLANT:BOILER SYSTEM		
						<b>Other</b>		
			K376		DSF0000889261	New/Retrofit Telephone/Intercom Systems	2018	160,657
							<b>P.S. 376A Total:</b>	<b>\$886,384</b>
32	Brooklyn	K377		<b>P.S. 377</b>				
			K377		DSF0000888786	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2018	140,000
						Technology		
			K377		DSF0000912255	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	500,000
						Technology		
					DSF0000799759	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	63,731

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000873229	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:Local Sound System AUDITORIUM:Theater Lighting System:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtains	2019	1,354,091
					DSF0000821709	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2016	164,188
					DSF0000783062	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	1,097,077
					DSF0000806361	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	2,109,931
					DSF0000783063	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2016	2,379,481
			K377		DSF0000888954	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	TBD
							<b>P.S. 377 Total:</b>	<b>\$7,808,499</b>
32	Brooklyn	K383		I.S. 383				
					DSF0000844725	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	134,133



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000873263	<b>State of Good Repair - System Replacements - Containerization</b> SITE:CONTAINERIZATION	2019	178,469
							<b>I.S. 383 Total:</b>	\$312,602
32	Brooklyn	K384		<b>P.S. 384</b>				
					DSF0000777481	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	203,997
					DSF0000912528	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	36,663
					DSF0000783126	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,264,286
					DSF0000867025	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	187,170
					DSF0000888981	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	130,987
						<b>Other</b>		
			K384		DSF0000889429	IP Surveillance Camera Installation	2019	39,510

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 384 Total:</b>	\$1,862,613
32	Brooklyn	K842		<b>P.S. 45 AX (OLD BS RDGWD ECC1)</b>				
			K045	DSF0000851654		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2017	322,042
							<b>P.S. 45 AX (OLD BS RDGWD ECC1) Total:</b>	\$322,042
33K	Brooklyn	K801		<b>CENT HEADQTRS (65 COURT)</b>				
			K990	DSF0000888829		<b>Domestic Piping</b>	2018	688,511
			K990	DSF0000874197		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	114,741
				DSF0000851530		<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:Elevator INTERCOM SYSTEM:Elevator	2018	4,368,104
				DSF0000784115		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	457,591
				DSF0000851535		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	9,707,582
				DSF0000867176		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	5,097,234

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>CENT HEADQTRS (65 COURT) Total:</b>								\$20,433,763
33K	Brooklyn	K802				<b>CENT HEADQTRS (131 LIV)</b>		
					DSF0000798423	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	944,304
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
<b>CENT HEADQTRS (131 LIV) Total:</b>								\$944,304
33K	Brooklyn	K905				<b>DISTRICT 22 ECOLOGY CENTER</b>		
			KADM		DSF0000822093	<b>State of Good Repair - System Replacements - Windows</b>	2015	330,118
						EXTERIOR:WINDOWS		
<b>DISTRICT 22 ECOLOGY CENTER Total:</b>								\$330,118
33K	Brooklyn	K986				<b>DIV. OF INSTR. &amp; INFO. TECH.</b>		
					DSF0000799766	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	74,978
<b>DIV. OF INSTR. &amp; INFO. TECH. Total:</b>								\$74,978
33K	Brooklyn	K995				<b>LEARNING SUPPORT CENTER</b>		
					DSF0000799740	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	25,626

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K602		DSF0000799842	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659
<b>LEARNING SUPPORT CENTER Total:</b>								\$57,285
75K	Brooklyn	K085		<b>P.S. 753 (OLD P85/STERLING HS)</b>				
					DSF0000798249	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,202,178
					DSF0000779005	<i>State of Good Repair - Building Upgrade - Climate Control</i> CLIMATE CONTROL SYSTEM	2017	1,395,113
					DSF0000779007	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	892,990
					DSF0000733730	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	1,032,236
					DSF0000912420	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	2,533
			K753		DSF0000779013	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,659

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000779019	<b>State of Good Repair - System Replacements - Kitchen Areas</b> KITCHEN	2015	373,202
						<b>Other</b>		
			K753		DSF0000868110	IP Surveillance Camera Installation	2019	301,184
<b>P.S. 753 (OLD P85/STERLING HS) Total:</b>								<b>\$9,231,095</b>
75K	Brooklyn	K148		<b>P.S. 373 (OLD P148)</b>				
					DSF0000757397	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1,015,962
					DSF0000799542	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	113,255
					DSF0000799745	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	95,945
					DSF0000713258	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS	2015	2,426,810
					DSF0000912158	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	9,132
					DSF0000757401	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2015	3,870,888
					DSF0000757400	<b>State of Good Repair - System Replacements - Parapets</b>	2015	3,610,939

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K373		DSF0000803236	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	215,163
					DSF0000822128	INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	191,646
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						<b>Other</b>		
			K373		DSF0000776041	IP Surveillance Camera Installation	2015	594,207
							<b>P.S. 373 (OLD P148) Total:</b>	<b>\$12,143,947</b>
75K	Brooklyn	K286		<b>P.S. 811 (OLD P286)</b>				
			K811		DSF0000849869	<b>Safety and Security - Safety and Security - Code Compliance</b> Electrical Systems EMERGENCY GENERATOR SET GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2019	280,432
					DSF0000827972	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:Elevator	2017	221,404

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERCOM SYSTEM:Elevator		
			K811		DSF0000827979	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	50,515
			K811		DSF0000849878	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	432,596
						Air Conditioning Split System		
						AIR CONDITIONING:Chilled Water System:Air Cooled Chiller		
						AIR CONDITIONING:Chilled Water System:Air Cooled Condenser		
						AIR CONDITIONING:Chilled Water System:Backflow Preventer		
						AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller		
			K811		DSF0000872570	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	1,512,675
						Ventilation		
						AIR CONDITIONING:Chilled Water System:Fan Coil Unit		
			K811		DSF0000889051	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	200,221
							<b>P.S. 811 (OLD P286) Total:</b>	<b>\$2,697,843</b>
75K	Brooklyn	K369	<b>P.S. 369 (COY COX SCHOOL)</b>					
					DSF0000850482	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	738,747

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798412	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	551,703
					DSF0000799767	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	14,069
					DSF0000828583	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	2,486,769
					DSF0000850485	EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2018	1,768,208
					DSF0000850484	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2018	1,216,724
						EXTERIOR:ROOF:Roofing		
<b>P.S. 369 (COY COX SCHOOL) Total:</b>								<b>\$6,776,220</b>
75K	Brooklyn	K370		<b>P.S. 370</b>				
					DSF0000799697	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	143,443
					DSF0000867035	<b>Other</b> IP Surveillance Camera Installation	2018	401,206



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 370 Total:</b>	\$544,649
75K	Brooklyn	K371		<b>P.S. 371 (OLD 615)</b>				
					DSF0000777480	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2016	106,067
					DSF0000783026	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,145,296
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K371		DSF0000806334	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b>	2016	1,741,983
						SITE:Drainage System for Asphalt		
			K371		DSF0000865987	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			K371		DSF0000868113	IP Surveillance Camera Installation	2019	376,883
							<b>P.S. 371 (OLD 615) Total:</b>	\$3,585,021
75K	Brooklyn	K396		<b>P.S. 396 (TANDEM K327-D23)</b>				
			K396		DSF0000867183	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2019	2,352,044
						CONVEYING:ELEVATORS		
							<b>P.S. 396 (TANDEM K327-D23) Total:</b>	\$2,352,044

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75K	Brooklyn	K722		<b>P.S. 721 OTC</b>				
			K721	DSF0000807390		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER):Dual Temperature Distribution: Piping, Pumps and Auxiliaries	2015	67,380
			K721	DSF0000865990		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 721 OTC Total:</b>	<b>\$282,172</b>
75K	Brooklyn	K834		<b>P.S. 372 (OUR LADY OF PEACE)</b>				
			K418	DSF0000821881		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2018	905,416
			K372	DSF0000844164		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2018	870,804
			K418	DSF0000784250		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2015	143,971

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K372		DSF0000867153	New/Retrofit Telephone/Intercom Systems	2018	185,928
							<b>P.S. 372 (OUR LADY OF PEACE) Total:</b>	\$2,106,119
75K	Brooklyn	K843		<b>P.S. 4 (ECC)</b>				
					DSF0000784282	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	344,366
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 4 (ECC) Total:</b>	\$344,366
75K	Brooklyn	K857		<b>P.S. 36 ANNEX</b>				
						<i>Other</i>		
			K036		DSF0000889262	New/Retrofit Telephone/Intercom Systems	2018	172,947
							<b>P.S. 36 ANNEX Total:</b>	\$172,947
75K	Brooklyn	K877		<b>P.S. 369 AX-(OL 396X/FLTB TN HL)</b>				
					DSF0000777494	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	38,124
					DSF0000784472	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	238,641
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 369 AX-(OL 396X/FLTB TN HL) Total:</b>	\$276,765

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75K	Brooklyn	K902		<b>P.S. 77 ANNEX</b>				
					DSF0000738916	<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOOR HARDWARE EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS	2016	240,086
					DSF0000799577	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	493,881
					DSF0000761845	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2016	1,266,394
					DSF0000717681	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2016	25,757,822
					DSF0000738917	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	3,936,946
					DSF0000761860	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:CHILLED WATER SYSTEM:Packaged Air Cooled Chiller	2016	6,494,017
					DSF0000738909	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2016	4,430,013

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000738911	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete	2016	1,633,540
					DSF0000738908	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	5,972,236
			K077		DSF0000865991	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			K266		DSF0000889602	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000775578	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2016	4,405,366
							<b>P.S. 77 ANNEX Total:</b>	<b>\$55,059,885</b>
78K	Brooklyn	K175			<b>TEACHERS PREP HS(OL REDIRECTION)</b>			
					DSF0000865888	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	91,090
					DSF0000911928	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	242,845
					DSF0000780331	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID	2016	866,897

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777264	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	3,179,405
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			K697		DSF0000889587	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			K697		DSF0000889407	IP Surveillance Camera Installation	2019	39,510
<b>TEACHERS PREP HS(OL REDIRECTION) Total:</b>								<b>\$4,634,539</b>
78K	Brooklyn	K313				<b>ADAMS STREET EDUCATIONAL CAMPUS</b>		
					DSF0000844726	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	109,676
						<b>Other</b>		
			K527		DSF0000889426	IP Surveillance Camera Installation	2019	46,026
<b>ADAMS STREET EDUCATIONAL CAMPUS Total:</b>								<b>\$155,702</b>
78K	Brooklyn	K400				<b>LAFAYETTE EDUCATIONAL CAMPUS</b>		
					DSF0000798621	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	4,592,367
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			K337		DSF0000821920	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	1,496,260

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					DSF0000798619	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2016	3,743,354
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000798418	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,751,815
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000800061	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	1,621,967
						DOMESTIC WATER SYSTEM		
					DSF0000821919	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	1,094,525
						DOMESTIC WATER SYSTEM		
					DSF0000888982	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,214,055

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798620	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	7,485,121
<b>LAFAYETTE EDUCATIONAL CAMPUS Total:</b>								\$22,999,464
78K	Brooklyn	K401		<b>LAFAYETTE HS AF</b>				
			K337		DSF0000873375	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELDS:FIXED EQUIPMENT	2019	48,987
<b>LAFAYETTE HS AF Total:</b>								\$48,987
78K	Brooklyn	K405		<b>MIDWOOD HS</b>				
					DSF0000799561	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	413,475
			K405		DSF0000760638	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	3,046,175
					DSF0000777218	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:THEATER LIGHTING SYSTEM:Dimming System	2015	400,747
			K405		DSF0000888933	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	450,000



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000783257	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2015	421,804
			K405		DSF0000868115	<b>Other</b> IP Surveillance Camera Installation	2019	476,816
							<b>MIDWOOD HS Total:</b>	\$5,209,017
78K	Brooklyn	K406		<b>MIDWOOD HS AF (MAIN)</b>				
					DSF0000755235	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS	2017	10,679,111
			K405		DSF0000783260	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELD:EXTERIOR LIGHTING ATHLETIC FIELD:LOCAL SOUND SYSTEM ATHLETIC FIELD:SCOREBOARD ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING	2017	19,199,397
							<b>MIDWOOD HS AF (MAIN) Total:</b>	\$29,878,508

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78K	Brooklyn	K410		<b>ABRAHAM LINCOLN HS</b>				
			K410		DSF0000798652	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	2,691,340
					DSF0000737753	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	2,466,660
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799403	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	3,470,636
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799402	<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2015	1,152,423
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799562	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	328,720
			K410		DSF0000737750	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2015	2,374,609
						FIRE ALARM SYSTEM		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						PUBLIC ADDRESS SYSTEM		
					DSF0000783265	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2015	237,754
					DSF0000783273	INTERIOR:STRUCTURAL:FLOOR STRUCTURE <b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,429,988
					DSF0000783272	GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	821,258
					DSF0000783284	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	1,168,787
						Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR		
			K410		DSF0000866114	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000783270	<b>State of Good Repair - System Replacements - Parapets</b>	2015	1,083,827
					DSF0000783269	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2015	9,766,203

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000737755	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	21,578,739
					DSF0000843844	<b>Other</b> IP Surveillance Camera Installation	2018	670,461
<b>ABRAHAM LINCOLN HS Total:</b>								<b>\$49,319,095</b>
78K	Brooklyn	K411		<b>LINCOLN HS AF</b>	DSF0000799406	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	1,043,578
					DSF0000799404	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	255,178
			K410		DSF0000800327	INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2015	465,783

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000783287	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELD:EXTERIOR LIGHTING ATHLETIC FIELD:SCOREBOARD ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING	2015	3,312,680
					DSF0000799405	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD	2015	187,870
							<b>LINCOLN HS AF Total:</b>	<b>\$5,265,089</b>
78K	Brooklyn	K415			<b>SAMUEL J. TILDEN EDUCATIONAL CAMPUS</b>			
					DSF0000912370	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHTING EXIT LIGHT	2019	105,402
					DSF0000873417	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	745,931
					DSF0000798414	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	565,225

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866839	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,461,831
					DSF0000873422	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	4,836,026
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
					DSF0000873421	<i>State of Good Repair - System Replacements - Parapets</i>	2019	14,243,659
						EXTERIOR:COPING		
					DSF0000873420	<i>State of Good Repair - System Replacements - Roofs</i>	2019	20,092,874
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<i>Other</i>		
					DSF0000843845	IP Surveillance Camera Installation	2017	600,644
<b>SAMUEL J. TILDEN EDUCATIONAL CAMPUS Total:</b>								<b>\$42,651,592</b>
78K	Brooklyn	K422		<b>SPRING CREEK EDUCATIONAL CAMPUS</b>				
					DSF0000799760	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	36,681
			K422		DSF0000868065	<i>State of Good Repair - System Replacements - Floors</i>	2019	775,765
<b>SPRING CREEK EDUCATIONAL CAMPUS Total:</b>								<b>\$812,446</b>
78K	Brooklyn	K425		<b>JAMES MADISON HS</b>				
					DSF0000799564	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	370,228

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799898	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> PUBLIC ADDRESS SYSTEM	2015	1,033,874
					DSF0000753104	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools</b> INTERIOR:POOLS	2017	7,669,721
					DSF0000806647	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtains	2018	85,330
			K425		DSF0000891046	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	53,811
					DSF0000752896	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	590,589
					DSF0000868273	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	305,854
			K425		DSF0000806643	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER SYSTEM	2015	125,412

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:FUEL SYSTEMS		
			K425	DSF0000889596		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			K425	DSF0000868116		IP Surveillance Camera Installation	2019	387,331
<b>JAMES MADISON HS Total:</b>								<b>\$10,836,942</b>
78K	Brooklyn	K430		<b>BROOKLYN TECH HS</b>				
				DSF0000844718		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	300,362
			K430	DSF0000873499		<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	2,235,798
						INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment		
						INTERIOR:SCIENCE LAB:Fixed Equipment		
						INTERIOR:SCIENCE PREP ROOM:Fixed Equipment		
						SCIENCE DEMO ROOM:Emergency Gas Shut-Off Valve		
						SCIENCE DEMO ROOM:Emergency Shut-Off Power		
						SCIENCE DEMO ROOM:Power Supply		
						SCIENCE LAB:Emergency Gas Shut-Off Valve		
						SCIENCE LAB:Emergency Shut-Off Power		
						SCIENCE LAB:Lighting:Lighting Fixture - Incandescent		
						SCIENCE LAB:Power Supply		
						SCIENCE PREP ROOM		
						SCIENCE PREP ROOM:Emergency Gas Shut-Off Valve		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SCIENCE PREP ROOM:Power Supply:Instructor Unit		
					DSF0000777483	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	639,601
			K430		DSF0000888926	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	30,214,167
			K430		DSF0000896356	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	4,574,037
						CLIMATE CONTROL SYSTEM		
			K430		DSF0000896377	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2019	186,554
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799698	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,284,689
					DSF0000760755	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	5,865,460
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		
			K430		DSF0000889322	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	6,966,405
						PUBLIC ADDRESS SYSTEM		
					DSF0000806678	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	1,178,462
						INTERIOR:CAFETERIA:Floor Finish		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868203	INTERIOR:CAFETERIA:Sliding-folding Partition INTERIOR:MULTI-PURPOSE ROOM:Floor Finish <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	2,073,920
			K430		DSF0000828949	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,935,282
					DSF0000806665	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	233,904
					DSF0000806675	HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2016	664,877
			K430		DSF0000823609	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	202,816
					DSF0000828951	GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT GAS SERVICE:GAS PRESSURE BOOSTER HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	81,108

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System		
			K430	DSF0000912445		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	315,204
			K430	DSF0000850828		<b>State of Good Repair - System Replacements - Parapets</b>	2018	7,905,438
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			K430	DSF0000850833		<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2018	1,140,815
						SITE:PAVING:Student Non-Use:Concrete SITE:STAIRS/RAMPS: EXTERIOR		
			K430	DSF0000866288		<b>State of Good Repair - System Replacements - Roofs</b>	2018	12,869,065
						EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
			K430	DSF0000822140		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	167,550
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
			K430	DSF0000866289		<b>State of Good Repair - System Replacements - Windows</b>	2018	2,567,324
						EXTERIOR:WINDOWS		
						<b>Other</b>		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K430		DSF0000868117	IP Surveillance Camera Installation	2019	1,124,489
					DSF0000777292	Ansul Systems	2015	1,674,134
<b>BROOKLYN TECH HS Total:</b>								<b>\$90,401,461</b>
78K	Brooklyn	K435		<b>THOMAS JEFFERSON HS</b>				
					DSF0000783396	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	3,504,205
					DSF0000821604	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	700,813
					DSF0000868274	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	529,832
					DSF0000806688	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	69,723
			K502		DSF0000823618	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS	2016	89,932

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K504	DSF0000865741		<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
						<b>Other</b>		
				DSF0000843846		IP Surveillance Camera Installation	2018	722,327
<b>THOMAS JEFFERSON HS Total:</b>								<b>\$5,932,705</b>
78K	Brooklyn	K440		<b>PROSPECT HEIGHTS HS</b>				
				DSF0000777484		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	203,297
			K524	DSF0000850865		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	94,380
			K524	DSF0000828988		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,917,943
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000798419		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	817,405
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000873531		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	317,460
						FIRE ALARM SYSTEM		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K547	DSF0000873548		<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2018	442,546
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging		
				DSF0000866840		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,770
				DSF0000889390		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	618,804
			K524	DSF0000828992		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	9,419,470
						EXTERIOR:CHIMNEY		
						EXTERIOR:LOUVER		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DSF0000873541		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	255,775
			K524	DSF0000896405		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	95,873
			K524	DSF0000843949		<b>State of Good Repair - System Replacements - Parapets</b>	2017	5,285,202
			K524	DSF0000828990		<b>State of Good Repair - System Replacements - Roofs</b>	2017	4,682,600
						EXTERIOR:ROOF:Specialties		
			K524	DSF0000828991		<b>State of Good Repair - System Replacements - Windows</b>	2017	4,056,595
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			K524	DSF0000866233		New/Retrofit Telephone/Intercom Systems	2017	467,521

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>PROSPECT HEIGHTS HS Total:</b>								<b>\$28,676,641</b>
78K	Brooklyn	K445		<b>NEW UTRECHT HS</b>				
			K445	DSF0000775948		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	3,116,639
			K445	DSF0000889323		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	2,768,584
				DSF0000799565		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	600,080
				DSF0000783448		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools</b> FIXTURES:STUDENT:Locker Room Shower INTERIOR:POOLS INTERIOR:SHOWER ROOM LOCKER ROOM:LIGHTING:Lighting Fixture - Fluorescent LOCKER ROOM:LIGHTING:Lighting Fixture - Incandescent SWIMMING POOL SWIMMING POOL:LIGHTING:Lighting Fixture - Fluorescent	2017	8,218,849
			K445	DSF0000829026		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	162,822

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
			K445		DSF0000873575	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2019	100,666
					DSF0000866841	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	2,337
					DSF0000822655	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	233,035
			K445		DSF0000866115	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
						<b>Other</b>		
			K445		DSF0000868118	IP Surveillance Camera Installation	2019	408,098
							<b>NEW UTRECHT HS Total:</b>	<b>\$15,688,800</b>
78K	Brooklyn	K446		<b>NEW UTRECHT HS AF</b>				
			K445		DSF0000783461	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELDS:PLAYING SURFACE	2017	6,458,755



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>NEW UTRECHT HS AF Total:</b>	<b>\$6,458,755</b>
78K	Brooklyn	K450		<b>GRAND STREET CAMPUS (OLD E.D.HS)</b>				
					DSF0000775794	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	973,079
			K478		DSF0000799897	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	620,387
					DSF0000777485	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	371,661
					DSF0000783464	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	198,273
					DSF0000806775	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	811,767
					DSF0000873586	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	32,552,798
						EXTERIOR:EXTERIOR WALLS		
			K474		DSF0000783472	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	41,262
					DSF0000799806	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	132,895
					DSF0000888961	<i>State of Good Repair - System Replacements - Parapets</i>	2018	3,189,534
						EXTERIOR:PARAPETS		
					DSF0000873584	<i>State of Good Repair - System Replacements - Roofs</i>	2018	27,345,192
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000873585	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	11,871,620
			K474		DSF0000865742	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
			K474		DSF0000889430	<b>Other</b> IP Surveillance Camera Installation	2019	42,041
<b>GRAND STREET CAMPUS (OLD E.D.HS) Total:</b>								<b>\$78,466,382</b>
78K	Brooklyn	K455		<b>BOYS &amp; GIRLS HS</b>				
					DSF0000911925	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	273,135
			K455		DSF0000865819	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,815,872
			K455		DSF0000888994	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Absorption Chiller AIR CONDITIONING:Cooling Tower	2018	131,304
					DSF0000844051	<b>Technology</b>	2016	1,045,624
					DSF0000844052	<b>Science Lab Upgrades</b>	2018	819,453
					DSF0000777486	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	421,553

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821598	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2018	818,271
			K455		DSF0000873611	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	134,404
						EMERGENCY GENERATOR SET GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
			K455		DSF0000829074	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	3,444,844
						Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Absorption Chiller AIR CONDITIONING:Cooling Tower		
							<b>BOYS &amp; GIRLS HS Total:</b>	\$8,904,460
78K	Brooklyn	K457		<b>BOYS HS AF (OLD)</b>				
			K553		DSF0000866085	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	116,688
							<b>BOYS HS AF (OLD) Total:</b>	\$116,688
78K	Brooklyn	K458		<b>BOYS HS (OLD)</b>				
			K553		DSF0000889328	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	882,026

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K553		DSF0000889650	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	315,000
					DSF0000799787	<b>Miscellaneous</b>	2015	654,063
			K373		DSF0000775845	<b>Safety and Security - Safety and Security - Code Compliance</b>	2018	12,149,970
					DSF0000799566	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	167,337
			K373		DSF0000873635	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	12,433,291
					DSF0000896493	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	196,686
					DSF0000873634	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING	2019	1,843,356
			K575		DSF0000873633	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing	2019	1,932,282
						<b>Other</b>		
			K517		DSF0000868119	IP Surveillance Camera Installation	2019	665,930

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>BOYS HS (OLD) Total:</b>	<b>\$31,239,941</b>
78K	Brooklyn	K460		<b>JOHN JAY EDUCATIONAL CAMPUS</b>				
					DSF0000911924	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	283,824
			K462		DSF0000800274	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,146,676
			K462		DSF0000800275	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	991,883
			K464		DSF0000822220	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	1,269,791
			K462		DSF0000798587	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	2,110,630
						Low-Voltage Electrical System		
						PUBLIC ADDRESS SYSTEM		
					DSF0000777487	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	278,568
					DSF0000799567	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	255,093
			K462		DSF0000783558	<i>State of Good Repair - System Replacements - Domestic Piping</i>	2018	10,302,684
						Waste System		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868275	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,025,631
					DSF0000891041	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	255,775
			K462		DSF0000799999	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	61,448
			K462		DSF0000822035	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	781,853
<b>JOHN JAY EDUCATIONAL CAMPUS Total:</b>								<b>\$18,763,856</b>
78K	Brooklyn	K465		<b>ERASMUS HALL CAMPUS</b>				
			K539		DSF0000829121	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	6,604,241
					DSF0000783561	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,558,329
					DSF0000806872	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
			K382		DSF0000851021	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	185,309

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump		
					DSF0000806855	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	70,702
					DSF0000896532	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	265,000
			K467		DSF0000865989	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			K382		DSF0000889211	New/Retrofit Telephone/Intercom Systems	2018	1,020,513
					DSF0000843847	IP Surveillance Camera Installation	2018	947,581
<b>ERASMUS HALL CAMPUS Total:</b>								<b>\$11,283,470</b>
78K	Brooklyn	K466		<b>ERASMUS HALL HS AF</b>				
			K543		DSF0000865862	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	114,736
<b>ERASMUS HALL HS AF Total:</b>								<b>\$114,736</b>
78K	Brooklyn	K470		<b>GEORGE W. WINGATE HS</b>				
					DSF0000911923	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	456,013
					DSF0000777488	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	257,907

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821588	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains	2019	163,625
					DSF0000868276	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	672,608
			K544		DSF0000806875	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2015	48,373
					DSF0000806877	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	103,225
			K544		DSF0000873695	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal	2018	200,221
			K544		DSF0000866234	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	449,432
					DSF0000867036	IP Surveillance Camera Installation	2018	757,819
							<b>GEORGE W. WINGATE HS Total:</b>	<b>\$3,109,223</b>
78K	Brooklyn	K480		<b>BUSHWICK EDUCATIONAL CAMPUS</b>				
					DSF0000865893	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	136,411



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K549		DSF0000822683	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,937,017
			K168		DSF0000752880	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	3,000,131
					DSF0000800336	PUBLIC ADDRESS SYSTEM <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools</b>	2015	231,370
					DSF0000868277	SWIMMING POOL <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	526,736
			K549		DSF0000829162	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	6,831,780
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
			K549		DSF0000829165	<b>State of Good Repair - System Replacements - Floors</b>	2018	764,490
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish		
			K549		DSF0000844037	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	103,498
			K549		DSF0000851041	<b>State of Good Repair - System Replacements - Parapets</b>	2018	8,925,341
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			K549		DSF0000866263	<b>State of Good Repair - System Replacements - Roofs</b>	2018	9,930,646

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOF:Roofing		
						<i>Other</i>		
					DSF0000867037	IP Surveillance Camera Installation	2018	705,901
<b>BUSHWICK EDUCATIONAL CAMPUS Total:</b>								<b>\$33,093,321</b>
78K	Brooklyn	K485				<b>TELECOM. ARTS &amp; TECH.</b>		
			K485		DSF0000665737	<i>Safety and Security - Safety and Security - Code Compliance</i>	2018	11,383,144
					DSF0000783627	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	133,891
					DSF0000799699	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	423,397
					DSF0000868278	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	606,407
					DSF0000896594	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	144,075
					DSF0000896601	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	181,532
						Ventilation		
			K485		DSF0000889598	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
						<i>Other</i>		
			K485		DSF0000889214	New/Retrofit Telephone/Intercom Systems	2018	311,652
			K485		DSF0000868120	IP Surveillance Camera Installation	2019	438,822

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>TELECOM. ARTS &amp; TECH. Total:</b>	<b>\$13,837,712</b>
78K	Brooklyn	K490		<b>FORT HAMILTON HS</b>				
					DSF0000829210	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	918,975
					DSF0000798422	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	638,138
					DSF0000866844	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	16,496
					DSF0000783669	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	23,826,129
			K490		DSF0000799401	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	6,619,393
					DSF0000829214	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	2,277,495
					DSF0000829213	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	4,545,895

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000806960	<b>State of Good Repair - System Replacements - Toilets - Students</b>  FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	151,071
			K490		DSF0000868121	<b>Other</b> IP Surveillance Camera Installation	2019	663,750
<b>FORT HAMILTON HS Total:</b>								\$39,657,342
78K	Brooklyn	K495		<b>FRANK J. MACCHIAROLA EDUCATIONAL COMPLEX</b>				
			K495		DSF0000822176	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,228,103
					DSF0000799568	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	244,806
			K495		DSF0000806979	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			K495		DSF0000867148	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	389,318
					DSF0000843848	IP Surveillance Camera Installation	2018	760,832
<b>FRANK J. MACCHIAROLA EDUCATIONAL COMPLEX Total:</b>								\$3,767,845
78K	Brooklyn	K496		<b>SHEEPSHEAD BAY HS AF</b>				
			K611		DSF0000851136	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2017	474,579

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>SHEEPSHEAD BAY HS AF Total:</b>	\$474,579
78K	Brooklyn	K500		<b>CANARSIE HS</b>				
					DSF0000777489	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	270,531
					DSF0000761082	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i>	2018	7,144,610
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000806993	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2018	1,617,311
						CLIMATE CONTROL SYSTEM		
					DSF0000829257	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2018	2,313,893
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799569	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	276,226
			K617		DSF0000821603	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	680,495
						<i>Other</i>		
					DSF0000843849	IP Surveillance Camera Installation	2018	654,553
							<b>CANARSIE HS Total:</b>	\$12,957,619
78K	Brooklyn	K505		<b>FRANKLIN D. ROOSEVELT HS</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000783734	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	309,291
					DSF0000799570	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	292,971
			K505		DSF0000783739	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	38,077
					DSF0000807028	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	150,494
FIXTURES:STUDENT:Toilet								
<b>FRANKLIN D. ROOSEVELT HS Total:</b>								<b>\$790,833</b>
78K	Brooklyn	K515		<b>SOUTH SHORE EDUCATIONAL COMPLEX</b>				
					DSF0000799895	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	697,636
					DSF0000821664	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	707,081
			K578		DSF0000822684	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	3,228,944
			K566		DSF0000865945	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	1,906,600
					DSF0000888769	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	3,468,842
			K578		DSF0000888857	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	2,082,983

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K578		DSF0000821755	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	75,470
			K567		DSF0000821779	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	85,414
			K637		DSF0000821780	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2015	33,343
			K637		DSF0000844127	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	38,000
			K637		DSF0000844128	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2017	82,709
			K567		DSF0000845635	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i> Technology	2018	94,585

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K576	DSF0000845637		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	80,351
			K637	DSF0000845638		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	175,502
			K578	DSF0000866256		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	128,966
			K578	DSF0000866257		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	62,834
			K578	DSF0000866258		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	97,810
			K567	DSF0000866259		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	167,670



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K566	DSF0000866260		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2017	161,936
			K567	DSF0000891020		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	100,000
			K637	DSF0000912415		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2019	35,000
				DSF0000799571		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	514,823
				DSF0000821599		<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
			K566	DSF0000867114		<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2018	706,115
				DSF0000868279		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	442,551
			K517	DSF0000873859		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink INTERIOR:TOILET ROOMS - STUDENTS	2018	138,158

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
			K566	DSF0000889052		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
			K578	DSF0000829300		<b>State of Good Repair - System Replacements - Windows</b>	2018	11,963,851
						EXTERIOR:WINDOWS		
						<b>Other</b>		
				DSF0000843850		IP Surveillance Camera Installation	2018	719,234
<b>SOUTH SHORE EDUCATIONAL COMPLEX Total:</b>								<b>\$28,875,918</b>
78K	Brooklyn	K516		<b>SOUTH SHORE HS AF</b>				
				DSF0000807062		<b>Athletic Fields</b>	2017	2,209,744
						ATHLETIC FIELD:SCOREBOARD		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						DOMESTIC WATER SYSTEM		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE / WASTE PIPING		
						EMERGENCY LIGHTING		
						EXTERIOR:DOORS:DOORS AND FRAMES		
						EXTERIOR:DOORS:LINTELS		
						EXTERIOR:EXTERIOR WALLS		
						FIRE ALARM SYSTEM		
						GAS FIRED FURNACE		
						GROUNDING SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE LIGHTING - SECURITY LIGHTS LOCKER ROOM:LIGHTING:Lighting Fixture - Fluorescent MOTOR STARTER/CONTACTOR PANEL BOARD SECURITY:INTRUSION ALARM SERVICE SWITCH SITE:FENCES SITE:PAVING - STUDENT USE:Asphalt SITE:SITE WALLS (NOT RETAINING WALLS) TELEPHONE TOILET ROOM - STAFF:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
			K566		DSF0000844106	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2017	86,231
							<b>SOUTH SHORE HS AF Total:</b>	<b>\$2,295,975</b>
78K	Brooklyn	K520		<b>PACIFIC ALT HS</b>				
					DSF0000775823	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	275,414
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K423		DSF0000851197	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> PUBLIC ADDRESS SYSTEM	2018	496,692
							<b>PACIFIC ALT HS Total:</b>	\$772,106
78K	Brooklyn	K525		<b>EDWARD R. MURROW HS</b>				
					DSF0000799572	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	471,067
					DSF0000821627	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2017	483,673
					DSF0000888983	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	98,683
			K525		DSF0000783788	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
					DSF0000807073	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2017	297,107
			K525		DSF0000807084	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Air Conditioning Split System	2015	66,914
						AIR CONDITIONING:CONDENSER WATER PUMP		
			K525		DSF0000822661	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
			K525		DSF0000829347	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Air Conditioning Split System	2016	829,978

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K525	DSF0000851223		AIR CONDITIONING:Cooling Tower <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	965,503
						Air Conditioning Split System		
			K525	DSF0000865719		AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Condenser Water Pump <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	160,950
						Air Conditioning Split System		
			K525	DSF0000912396		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	288,014
			K525	DSF0000873891		GAS SERVICE:Gas Distribution Piping <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	400,444
						FIXTURES:Student:Lavatory/Sink TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
						<b>Other</b>		
			K525	DSF0000868122		IP Surveillance Camera Installation	2019	481,082
							<b>EDWARD R. MURROW HS Total:</b>	<b>\$4,719,881</b>
78K	Brooklyn	K540		<b>JOHN DEWEY HS</b>				
				DSF0000799407		<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	253,526

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799573	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	400,517
					DSF0000783809	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	3,252,461
						EMERGENCY GENERATOR SET		
						GROUNDING SYSTEM		
						PANEL BOARD		
						<b>Other</b>		
					DSF0000843851	IP Surveillance Camera Installation	2018	713,832
							<b>JOHN DEWEY HS Total:</b>	<b>\$4,620,336</b>
78K	Brooklyn	K564		<b>SUNSET PARK HS</b>				
						<b>Other</b>		
			K667		DSF0000889431	IP Surveillance Camera Installation	2019	50,443
							<b>SUNSET PARK HS Total:</b>	<b>\$50,443</b>
78K	Brooklyn	K580		<b>GEORGE WESTINGHOUSE VOC HS</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000911922	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	264,980
			K605		DSF0000798585	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,078,306
					DSF0000783843	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Library Upgrade INTERIOR:LIBRARY:Door(s) INTERIOR:LIBRARY:Floor Finish LIBRARY:LIGHTING:Lighting Fixture - Fluorescent	2016	1,607,294
					DSF0000798586	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2016	1,651,799
					DSF0000912285	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	115,460
			K605		DSF0000807133	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	956,392
					DSF0000868280	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	633,010
			K605		DSF0000807137	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	1,048,587
					DSF0000821922	<b>State of Good Repair - System Replacements - Parapets</b>	2016	6,885,888

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K605	DSF0000807135		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,667,157
						<b>Other</b>		
			K008	DSF0000822044		New/Retrofit Telephone/Intercom Systems	2015	448,371
			K605	DSF0000889432		IP Surveillance Camera Installation	2019	42,193
<b>GEORGE WESTINGHOUSE VOC HS Total:</b>								<b>\$17,399,437</b>
78K	Brooklyn	K590		<b>MIDDLE COLLEGE HS</b>				
				DSF0000844719		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	273,558
			K590	DSF0000888918		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	1,029,356
			K590	DSF0000866267		<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2018	414,797
<b>MIDDLE COLLEGE HS Total:</b>								<b>\$1,717,711</b>
78K	Brooklyn	K600		<b>CLARA BARTON HS</b>				
				DSF0000911921		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	275,224
				DSF0000783849		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	2,078,649



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866847	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	23,625
		K600			DSF0000807157	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	6,184,986
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS		
		K600			DSF0000783858	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	255,807
		K600			DSF0000807155	<b>State of Good Repair - System Replacements - Roofs</b>	2017	3,101,339
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
		K600			DSF0000867150	New/Retrofit Telephone/Intercom Systems	2018	461,068
		K600			DSF0000889537	IP Surveillance Camera Installation	2019	40,651
							<b>CLARA BARTON HS Total:</b>	<b>\$12,421,349</b>
78K	Brooklyn	K610			<b>AUTOMOTIVE TRADES VOC HS</b>			
					DSF0000873970	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	4,614,063
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000783877	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,432,127
					DSF0000868205	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,301,468
					DSF0000873975	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	8,237,418
					DSF0000873973	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	5,851,010
					DSF0000873972	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	4,499,906
					DSF0000873974	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	11,416,913
						<b>Other</b>		
			K610		DSF0000868124	IP Surveillance Camera Installation	2019	454,384

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>AUTOMOTIVE TRADES VOC HS Total:</b>	<b>\$37,807,289</b>
78K	Brooklyn	K615		<b>E NY VOC HS OF TRANSIT TECH.</b>				
			K615	DSF0000865841		<b>Educational Enhancements - Educational Enhancements - Library Upgrade</b>	2017	785,714
				DSF0000783901		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,484,443
				DSF0000829459		<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:House Lighting:Lighting Fixture - Incandescent INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Stage:Stage Curtains	2018	718,031
				DSF0000868281		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	30,787
				DSF0000807212		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	143,333

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
			K615	DSF0000911946		<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
						<b>Other</b>		
			K615	DSF0000867151		New/Retrofit Telephone/Intercom Systems	2018	343,720
			K615	DSF0000868079		IP Surveillance Camera Installation	2019	413,681
<b>E NY VOC HS OF TRANSIT TECH. Total:</b>								<b>\$4,260,979</b>
78K	Brooklyn	K620		<b>WILLIAM E. GRADY VOC HS</b>				
				DSF0000777492		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	190,435
				DSF0000783923		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	2,422,964
						CLIMATE CONTROL SYSTEM		
				DSF0000799434		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,833,136
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000783925		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,969,831
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799947	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2015	9,837,193
					DSF0000799459	SITE:Drainage System for Asphalt SITE:Drainage System for Soil SITE:PAVING - STUDENT NON-USE:Asphalt <b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	459,286
					DSF0000783933	DOMESTIC WATER SYSTEM FIXTURES:STUDENT:Drinking Fountain FIXTURES:STUDENT:Sink And Fountain Combo Unit <b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	2,085,083
					DSF0000888984	GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	494,519
					DSF0000783934	HEATING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	7,487,815

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
						<i>Other</i>		
					DSF0000867038	IP Surveillance Camera Installation	2018	568,263
<b>WILLIAM E. GRADY VOC HS Total:</b>								<b>\$30,348,525</b>
78K	Brooklyn	K625				<b>ROBESON HS COMP&amp;BUS TC (A HML)</b>		
					DSF0000851375	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	834,618
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000783952	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	54,770
					DSF0000799574	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	197,760
					DSF0000866849	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	13,500
					DSF0000889391	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	409,504
				K122	DSF0000807257	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	9,793,117
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
					DSF0000896900	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	313,144

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Ventilation		
					DSF0000851378	<b>State of Good Repair - System Replacements - Parapets</b>	2018	181,042
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000851377	<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,585,003
						EXTERIOR:ROOF:Roofing		
					DSF0000851379	<b>State of Good Repair - System Replacements - Windows</b>	2018	4,061,309
						EXTERIOR:WINDOWS		
<b>ROBESON HS COMP&amp;BUS TC (A HML) Total:</b>								<b>\$17,443,767</b>
78K	Brooklyn	K650		<b>HARRY VANARSDALE VOC HS(WHITNEY)</b>				
					DSF0000822222	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,446,252
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000783976	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	6,009,297
						EXTERIOR:EXTERIOR WALLS		
					DSF0000807294	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	200,069
						Ventilation		
					DSF0000783974	<b>State of Good Repair - System Replacements - Parapets</b>	2016	781,695
						EXTERIOR:PARAPETS		
					DSF0000761351	<b>State of Good Repair - System Replacements - Roofs</b>	2016	3,885,934

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
			K561		DSF0000889600	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	429,587
					DSF0000783975	<b>State of Good Repair - System Replacements - Windows</b>	2016	3,068,764
						EXTERIOR:WINDOWS		
						<b>Other</b>		
					DSF0000868080	IP Surveillance Camera Installation	2019	579,562
<b>HARRY VANARSDALE VOC HS(WHITNEY) Total:</b>								<b>\$16,401,160</b>
78K	Brooklyn	K655		<b>BKLYN HS OF THE ARTS (OL S J HL)</b>				
					DSF0000822691	<b>Auditorium Upgrade</b>	2016	1,036,426
					DSF0000777490	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	198,298
					DSF0000799700	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	212,525
			K656		DSF0000752882	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	1,774,442
						FIRE ALARM SYSTEM		
					DSF0000866850	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	8,205
					DSF0000761374	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	6,617,969
						EXTERIOR:EXTERIOR WALLS		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K656	DSF0000784010		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2016	138,998
			K656	DSF0000823619		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2016	67,468
			K656	DSF0000799355		<b>State of Good Repair - System Replacements - Kitchen Areas</b>	2016	189,880
				DSF0000807302		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,681,804

**BKLYN HS OF THE ARTS (OL S J HL) Total: \$11,926,015**

78K Brooklyn K656 **BKLYN HS OF THE ARTS AX (S J HL)**

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798263	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	6,818,029
					DSF0000784013	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,511,432
					DSF0000784015	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	894,687
			K656		DSF0000784014	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2016	1,369,621
					DSF0000784033	<b>State of Good Repair - System Replacements - Domestic Piping</b> Fire System Sprinklers SPRINKLERS, STANDPIPE, FIRE SYSTEM:DELUGE VALVE SPRINKLERS, STANDPIPE, FIRE SYSTEM:ROOF TANK SPRINKLERS, STANDPIPE, FIRE SYSTEM:SIAMESE CONNECTION SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER HEAD	2016	3,986,514

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000829540	SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING SPRINKLERS, STANDPIPE, FIRE SYSTEM:STANDPIPE SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	142,318
<b>BKLYN HS OF THE ARTS AX (S J HL) Total:</b>								<b>\$14,722,601</b>
78K	Brooklyn	K660		<b>WILLIAM MAXWELL CTE HS</b>				
					DSF0000865781	<b>Educational Enhancements - Educational Enhancements - Library Upgrade</b>	2018	867,160
			K660		DSF0000866149	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,650,365
			K660		DSF0000888765	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	922,202
					DSF0000784036	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	155,783
					DSF0000799575	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	139,337
					DSF0000889572	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	22,561
					DSF0000874126	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES	2019	5,322,952

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K660	DSF0000874124		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	1,307,455
			K660	DSF0000912444		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	2,509,865
				DSF0000874125		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	7,095,093
						<b>Other</b>		
			K660	DSF0000868081		IP Surveillance Camera Installation	2019	415,005
<b>WILLIAM MAXWELL CTE HS Total:</b>								<b>\$21,407,778</b>
78K	Brooklyn	K721				<b>BROOKLYN STUDIO (TANDEM K128)</b>		
				DSF0000911871		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	6,308
			K771	DSF0000784059		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	1,864,247
			K690	DSF0000822173		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	947,637
				DSF0000807364		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2017	3,309,302

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>BROOKLYN STUDIO (TANDEM K128) Total:</b>								\$6,127,494
78K	Brooklyn	K728		<b>LIBERATION DIPLOMA PLUS H.S.</b>				
			K728	DSF0000821869		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	2,041,512
<b>LIBERATION DIPLOMA PLUS H.S. Total:</b>								\$2,041,512
78K	Brooklyn	K743		<b>ADULT LRNG CTR (OLD GRLS HS)</b>				
				DSF0000851507		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2019	274,077
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000851506		<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2019	1,369,994
						FIRE ALARM SYSTEM		
				DSF0000843680		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	4,011,881
						EXTERIOR:AREAWAY		
						EXTERIOR:EXTERIOR SOFFITS		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
				DSF0000851523		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	4,323,504
						Ventilation		
						VENTILATION:Exhaust Fan		
						VENTILATION:Supply Fan		
				DSF0000866095		<i>State of Good Repair - System Replacements - Parapets</i>	2019	202,725

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000851509	<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,678,248
						EXTERIOR:ROOF:Roofing		
					DSF0000851510	<b>State of Good Repair - System Replacements - Windows</b>	2019	1,388,493
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			K755		DSF0000889265	New/Retrofit Telephone/Intercom Systems	2018	342,566
<b>ADULT LRNG CTR (OLD GRLS HS) Total:</b>								<b>\$13,591,488</b>
78K	Brooklyn	K778		<b>EL PUENTE HS</b>				
			K685		DSF0000822118	<b>Exterior Masonry</b>	2017	2,830,215
					DSF0000797940	<b>State of Good Repair - System Replacements - Parapets</b>	2017	911,927
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			K685		DSF0000797939	<b>State of Good Repair - System Replacements - Roofs</b>	2017	764,032
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
					DSF0000797941	<b>State of Good Repair - System Replacements - Windows</b>	2017	1,438,187
						EXTERIOR:WINDOWS		
<b>EL PUENTE HS Total:</b>								<b>\$5,944,361</b>
78K	Brooklyn	K779		<b>ALL CITY LEADERSHIP SCHOOL</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			K554		DSF0000912226	IP Surveillance Camera Installation	2019	68,814
<b>ALL CITY LEADERSHIP SCHOOL Total:</b>								\$68,814
78K	Brooklyn	K781		<b>WEST BROOKLYN COMMUNITY HS</b>				
					DSF0000797988	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	74,978
						<i>Other</i>		
			K529		DSF0000867134	New/Retrofit Telephone/Intercom Systems	2018	169,216
<b>WEST BROOKLYN COMMUNITY HS Total:</b>								\$244,194
78K	Brooklyn	K799		<b>BROOKLYN EAST ALTERNATIVE LEARNING CENTER</b>				
					DSF0000822169	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	4,991,017
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
					DSF0000843222	<b>State of Good Repair - System Replacements - Parapets</b>	2018	666,430
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000843221	<b>State of Good Repair - System Replacements - Roofs</b>	2018	882,423
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000843223	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,481,758
<b>BROOKLYN EAST ALTERNATIVE LEARNING CENTER Total:</b>								\$8,021,628
78K	Brooklyn	K804		<b>COBBLE HILL SCL OF AMR STD (OL6)</b>				
			K519	DSF0000897085		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING:Steam Heating	2019	236,691
			K519	DSF0000784168		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	166,098
<b>COBBLE HILL SCL OF AMR STD (OL6) Total:</b>								\$402,789
78K	Brooklyn	K805		<b>WATERS EDGE EDUCATIONAL COMPLEX</b>				
				DSF0000911920		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	306,862
						<b>Other</b>		
			K439	DSF0000866231		New/Retrofit Telephone/Intercom Systems	2017	370,550
<b>WATERS EDGE EDUCATIONAL COMPLEX Total:</b>								\$677,412
78K	Brooklyn	K806		<b>METROPOLITAN CORPORATE ACAD.</b>				
			K592	DSF0000874259		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	380,784



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:Gas Distribution Piping HEATING PLANT:Fuel System HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
			K530		DSF0000843639	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	111,470
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			K592		DSF0000889435	IP Surveillance Camera Installation	2019	39,779
<b>METROPOLITAN CORPORATE ACAD. Total:</b>								<b>\$532,033</b>
78K	Brooklyn	K813				<b>DIST. OFFICE #13 (OLD 9 AX)</b>		
					DSF0000784200	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	263,877
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866856	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,000
<b>DIST. OFFICE #13 (OLD 9 AX) Total:</b>								<b>\$266,877</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Brooklyn**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78K	Brooklyn	K824		<b>W.E.B. DUBOIS HS</b>				
					DSF0000784233	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	670,422
							<b>W.E.B. DUBOIS HS Total:</b>	<b>\$670,422</b>
78K	Brooklyn	K865		<b>SECOND OPPORTUNITY SCHOOL</b>				
					DSF0000784416	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	768,047
					DSF0000889344	<b>State of Good Repair - System Replacements - Electrical Systems</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2018	3,564
					DSF0000807731	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT GAS SERVICE:GAS PRESSURE BOOSTER HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2016	82,417

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
<b>SECOND OPPORTUNITY SCHOOL Total:</b>								\$854,028
78K	Brooklyn	K907		<b>BROWNSVILLE DIPLOMA PLUS HS</b>				
					DSF0000784507	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	49,672
						<i>Other</i>		
			K568		DSF0000889438	IP Surveillance Camera Installation	2019	37,320
<b>BROWNSVILLE DIPLOMA PLUS HS Total:</b>								\$86,992
78K	Brooklyn	K909		<b>ACORN COMMUNITY HS</b>				
						<i>Other</i>		
					DSF0000888959	IP Surveillance Camera Installation	2019	408,912
<b>ACORN COMMUNITY HS Total:</b>								\$408,912
78K	Brooklyn	K914		<b>BENJAMIN BANNEKER ACADEMY</b>				
					DSF0000799764	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	127,083
<b>BENJAMIN BANNEKER ACADEMY Total:</b>								\$127,083
78K	Brooklyn	K917		<b>BKLYN COLL ACAD (BRIDGES TO K)</b>				
					DSF0000784545	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	589,665

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Brooklyn  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799738	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	16,079
<b>BKLYN COLL ACAD (BRIDGES TO K) Total:</b>								\$605,744
78K	Brooklyn	K932		<b>HIGH SCHOOL SUSPENSION CENTER</b>				
			X695	DSF0000843640		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	179,913
<b>HIGH SCHOOL SUSPENSION CENTER Total:</b>								\$179,913
78K	Brooklyn	K934		<b>FORT HAMILTON HS MODULAR UNIT</b>				
				DSF0000829999		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	3,704,882
<b>FORT HAMILTON HS MODULAR UNIT Total:</b>								\$3,704,882
78K	Brooklyn	K994		<b>BEDFORD ACADEMY</b>				
					DSF0000799914	<b>Other</b> IP Surveillance Camera Installation	2015	509,422
<b>BEDFORD ACADEMY Total:</b>								\$509,422

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Queens Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.01	0.00	-0.09	0.00	-0.01	-0.09
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	11.89	11.07	51.15	50.01	45.82	169.94
3. Climate Control	20.78	3.23	14.75	28.51	15.01	82.28
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	17.12	4.42	3.53	6.57	12.65	44.30
7. Lighting Fixtures	50.63	36.73	3.73	0.88	0.48	92.44
8. Elevators and Escalators	0.20	0.05	0.14	12.83	10.69	23.90
9. Reinforcing Cinder Concrete Slabs	1.85	0.79	0.33	2.68	0.34	5.98
10. Flood Elimination	46.39	10.13	21.84	17.23	31.98	127.57
11. Air Conditioning Retrofit	0.00	0.00	0.00	0.16	0.00	0.17
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.18	0.16	1.57	1.30	0.05	3.25
14. Interior Spaces	12.82	2.44	3.77	2.37	1.44	22.84
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	21.93	18.32	11.65	0.53	0.93	53.35
2. Playground Redevelopment	8.44	5.13	19.54	11.44	10.69	55.24
3. Swimming Pools	0.05	0.04	0.01	0.01	0.00	0.11
E. System Replacements						
1. Roofs	32.28	26.01	40.80	70.30	52.70	222.09
2. Parapets	24.01	26.87	42.65	47.75	54.82	196.09
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	2.97	1.59	2.98	9.31	32.14	48.99
5. Exterior Masonry	21.12	23.86	53.80	93.14	103.45	295.36
6. Electrical Systems	13.85	1.11	1.89	3.29	21.67	41.81
7. Heating Plant Upgrade	39.77	7.31	7.44	5.41	9.00	68.93
8. Domestic Piping	3.84	3.13	0.97	3.16	0.92	12.03
9. Toilets - Students	0.20	5.96	1.19	3.87	10.91	22.13

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Queens Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
E. System Replacements						
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.00	0.00	0.02	0.51	0.06	0.60
12. Paved Area - Blacktop	3.05	2.89	0.23	0.13	0.39	6.68
13. Paved Area - Concrete	0.48	1.60	1.78	0.36	-0.03	4.20
14. Fencing	0.01	0.01	0.00	0.00	0.57	0.60
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	0.65	1.04	0.39	1.52	0.25	3.85
18. Gymnasium Upgrade	0.17	1.35	0.07	0.22	0.22	2.04
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.02	0.00	0.00	0.85	2.12	2.99
<hr/>						
<i>I. State of Good Repair Yearly Totals:</i>	334.71	195.23	286.12	374.34	419.25	
				<b><i>I. State of Good Repair Total:</i></b>		<b>1,609.66</b>
<b>II. System Expansion</b>						
A. New Construction-Additional Capacity						
1. New Schools	85.01	81.82	159.68	217.86	88.78	633.15
2. Building Additions	12.37	295.66	319.49	94.71	158.50	880.73
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	0.58	20.97	9.29	3.47	17.44	51.76
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
9. 3-K Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	7.24	9.57	16.81
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.53	1.92	0.22	1.61	5.48	9.75

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Queens Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>II. System Expansion</b>						
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	21.57	-6.71	30.42	-0.21	38.41	83.47
F. Replacements						
1. Replacements - New	0.40	10.17	3.91	33.99	2.37	50.84
2. Replacements - Addition	0.11	6.84	0.49	0.67	32.35	40.46
3. Replacements - Lease	0.11	0.00	0.00	0.00	0.00	0.12
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>II. System Expansion Yearly Totals:</i>	120.68	410.68	523.50	359.33	352.91	
						<b>II. System Expansion Total: 1,767.10</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions / Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrade	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>III. Educational Enhancements Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>III. Educational Enhancements Total: 0.00</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	0.42	0.11	0.03	3.42	0.30	4.29
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>IV. Safety and Security Yearly Totals:</i>	0.42	0.11	0.03	3.42	0.30	
						<b>IV. Safety and Security Total: 4.29</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Borough of Queens Plan Summary  
(in millions)**

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
<i>V. Ancillary Facilities Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>V. Ancillary Facilities Total: 0.00</b>
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	0.29	5.58	6.62	13.12	14.81	40.42
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>	0.29	5.58	6.62	13.12	14.81	
						<b>VI. Emergency, Unspecified and Misc. Total: 40.42</b>
<b>Yearly Totals for Queens</b>	456.10	611.60	816.28	750.21	787.27	
						<b>Queens Grand Total: \$3,421.47</b>



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	24	DSF0000798568	P.S. 19 ADDITION	640	Mar-15	Jul-16	Sep-18	100.58	0.01	97.57	2.99
*	24	DSF0000798200	P.S. 49 ADDITION	333	Mar-14	Dec-15	Sep-17	40.80	0.13	40.67	0.00
*	24	DSF0000798199	I.S. 125 ADDITION	728	Feb-14	Dec-15	Sep-17	101.71	0.30	97.59	3.81
*	24	DSF0000798195	P.S. 143 ADDITION	980	Jan-16	Jul-17	Sep-20	121.85	0.07	102.21	19.57
*	24	DSF0000821576	P.S. 128 ADDITION	440	Mar-16	Jun-17	Jun-20	43.21	0.00	37.21	6.00
*	24	DSF0000798196	I.S. 419	646	Sep-16	May-18	Jun-21	117.70	0.14	95.91	21.65
*L	24	DSF0000798197	P.S. 143 ANNEX	211	Dec-15	Jul-17	Sep-18	8.42	0.00	7.62	0.80
*	25	DSF0000798203	P.S. 24 ADDITION	600	Dec-14	Jul-16	Sep-18	103.69	0.05	98.11	5.52
*	25	DSF0000843833	P.S. 129 ADDITION	548	Sep-16	Apr-18	Sep-20	63.09	0.00	52.97	10.12
*	26	DSF0000798205	BAYSIDE HILLS SCHOOL OF EXCELLENCE	468	Feb-14	Aug-15	Sep-17	90.93	6.85	84.08	0.00
*L	26	DSF0000889304	P.S. @ 56-10 214 STREET	292	Aug-18	Jun-19	Sep-20	19.84	0.00	16.37	3.47
*	27	DSF0000801039	P.S. 66 ADDITION	124	Aug-15	Jun-17	Sep-19	43.17	0.00	38.69	4.48
*	27	DSF0000417420	CENTREVILLE EDUCATIONAL BUILDING	516	Sep-13	Jul-15	Sep-17	104.79	6.25	90.54	8.00
*	28	DSF0000798208	P.S. 303 ADDITION	484	Feb-15	Jan-17	Sep-19	97.67	0.00	84.23	13.45
*	28	DSF0000798209	P.S. 144 ADDITION	590	Dec-15	Jul-17	Sep-19	71.51	0.00	61.72	9.80
*	28	DSF0000843834	P.S. 196 ADDITION	250	Jun-18	Jun-19	Jun-21	50.94	0.00	38.78	12.16
*	28	DSF0000888762	P.S. 206 ADDITION	392	Mar-18	Jun-19	Jun-22	55.58	0.00	42.29	13.29
*	30	DSF0000843984	P.S. @ PARCEL F	612	Apr-16	Jul-17	Jun-21	92.53	0.00	75.45	17.07
*	30	DSF0000798210	P.S. 398	476	Jun-15	Mar-17	Jun-19	92.50	0.00	80.24	12.26

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Capacity Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	30	DSF0000843825	I.S. @ 47-10 BARNETT AVENUE	725	Jan-18	Jun-19	Jun-22	109.85	0.00	89.15	20.70
*L	78Q	DSF0000798226	THE COLLEGE POINT COLLABORATIVE EDUCATIONAL BUILDING	507	Oct-13	Jul-16	Sep-18	28.20	0.45	26.95	0.80
*	78Q	DSF0000821799	FRANCIS LEWIS HS ANNEX	555	Apr-17	Jul-18	Jul-21	63.07	0.00	51.58	11.48
*	78Q	DSF0000888760	CARDOZO HIGH SCHOOL ANNEX	795	Jun-18	Jun-19	Jun-22	63.30	0.00	49.35	13.95
*	78Q	DSF0000798215	ACADEMY OF AMERICAN STUDIES	969	Jul-16	May-18	Jun-21	111.70	0.02	91.99	19.69

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	24	DSF0000822186 PRE-K CENTER @ 70-24 47TH AVENUE	90	Jun-15	Apr-16	Sep-17	4.11	0.00	4.11	0.00
* L	24	DSF0000822111 PRE-K CENTER @ 56-01 61ST STREET	162	May-15	Jul-15	Sep-15	6.65	0.00	6.65	0.00
		§ Total Estimated Cost								
* L	24	DSF0000844691 PRE-K CENTER @ 54-25 101ST STREET	54	Sep-16	Jan-18	Jul-18	4.38	0.00	4.38	0.00
* L	24	DSF0000844698 PRE-K CENTER @ 104-14 ROOSEVELT AVENUE	72	Aug-16	May-17	Sep-17	11.31	0.00	10.93	0.38
*	24	DSF0000866312 PRE-K CENTER @ 104-04 CORONA AVENUE	18	Jun-17	Mar-18	Sep-18	5.02	0.00	4.77	0.25
* L	24	DSF0000800114 PRE-K CENTER @ 46-16 76TH STREET	108	Jun-14	Dec-14	Aug-15	13.62	0.00	13.62	0.00
* L	24	DSF0000800248 PRE-K CENTER @ 44-15 JUDGE STREET	144	Jun-14	Dec-14	Jun-15	6.05	0.00	6.05	0.00
* L	24	DSF0000800282 PRE-K CENTER @ 68-20 MYRTLE AVENUE	180	Jul-14	Dec-14	Jul-15	6.90	0.00	6.90	0.00
* L	24	DSF0000822099 PRE-K CENTER @ 107-17 NORTHERN BOULEVARD	77	Jun-15	Jan-16	Jul-16	5.41	0.00	5.41	0.00
* L	24	DSF0000822098 PRE-K CENTER @ 106-02 NORTHERN BOULEVARD	36	Jun-15	Feb-16	Aug-16	3.85	0.00	3.85	0.00
* L	24	DSF0000845581 PRE-K CENTER @ 108-18 ROOSEVELT AVENUE	54	Oct-16	Mar-18	Sep-18	6.34	0.00	6.34	0.00
* L	24	DSF0000844747 PRE-K CENTER @ 57-06 99TH STREET	36	Sep-16	Jun-17	Sep-17	5.89	0.00	5.89	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
* L	24	DSF0000865849	PRE-K CENTER @ 98-22 55 AVENUE	54	Jan-17	Apr-17	Sep-17	1.90	0.00	1.90	0.00
* L	25	DSF0000821980	PRE-K CENTER @ 14-45 143RD STREET	108	Apr-15	Jan-16	Jul-16	3.74	0.00	3.74	0.00
* L	25	DSF0000821868	PRE-K CENTER @ 123-07 22ND AVENUE	144	Feb-15	Dec-15	Sep-17	6.63	0.00	6.63	0.00
* L	28	DSF0000800117	PRE-K CENTER @ 89-14 PARSONS BOULEVARD	72	Jun-14	Dec-14	Jun-15	7.40	0.00	7.40	0.00
* L	28	DSF0000800124	PRE-K CENTER @ 132-10 JAMAICA AVENUE	90	Jun-14	Dec-14	Jun-15	10.94	0.00	10.94	0.00
* L	28	DSF0000801086	PRE-K CENTER @ 83-30 KEW GARDENS ROAD	72	Sep-14	Mar-15	Aug-15	7.35	0.00	7.35	0.00
* L	29	DSF0000800116	PRE-K CENTER @ 168-42 JAMAICA AVENUE	126	Jun-14	Dec-14	Jun-15	15.40	0.00	15.40	0.00
* L	29	DSF0000801025	PRE-K CENTER @ 100-01 SPRINGFIELD BOULEVARD	162	Aug-14	Dec-14	Jul-15	8.06	0.00	8.06	0.00
* L	30	DSF0000800058	PRE-K CENTER @ 96-10 23RD AVENUE	108	Jun-14	Dec-14	Jun-15	10.64	0.01	10.63	0.00
* L	30	DSF0000822015	PRE-K CENTER @ 32-52 37TH STREET	270	Apr-15	Aug-15	Sep-15	0.65	0.00	0.65	0.00
* L	30	DSF0000821858	PRE-K CENTER @ 32-52 37TH STREET	126	Apr-15	Jul-16	Jul-17	9.75	0.00	9.75	0.00
* L	30	DSF0000843935	PRE-K CENTER @ 27-35 JACKSON AVENUE	180	Jan-16	Dec-16	Sep-17	10.08	0.00	9.77	0.31

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

§ Total estimated cost includes cost of additional work after initial occupancy.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
3-K Initiative Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	27	DSF0000889652 DISTRICT 27 PRE-K CENTER @ 101-49 WOODHAVEN BOULEVARD	165	Aug-18	Feb-19	Jul-19	16.07	0.00	16.07	0.00
* L	27	DSF0000889334 DISTRICT 27 PRE-K CENTER @ 100-02 ROCKAWAY BOULEVARD	165	Jul-18	Jan-19	Jul-19	15.40	0.00	15.40	0.00
* L	27	DSF0000889347 3K CENTER @ 104-06 101 AVENUE	120	Jun-18	Jul-18	Aug-18	9.95	0.00	9.95	0.00
* L	27	DSF0000889573 DISTRICT 27 PRE-K CENTER @ 87-40 88 STREET	120	Jun-18	Jan-19	Jul-19	10.09	0.00	10.09	0.00
* L	27	DSF0000891039 DISTRICT 27 PRE-K CENTER @ 160-06 CROSS BAY BOULEVARD	45	Oct-18	May-19	Aug-19	7.85	0.00	7.85	0.00
* L	29	DSF0000890627 3K CENTER @ 92-80 220TH STREET	420	Jun-18	Jun-19	Sep-20	15.74	0.00	15.74	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Class Size Reduction Projects**  
**Borough of Queens**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	29	DSF0000843904	P.S. 131 ADDITION	384	Mar-17	Jun-18	Jul-21	68.32	0.00	53.86	14.47

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Replacement Projects  
Borough of Queens  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	24	DSF0000798568	P.S. 19 MINISCHOOL	Replacement	Mar-15	Jul-16	Sep-18	12.56	0.00	12.19	0.37
*	25	DSF0000798203	P.S. 24 ADDITION	Replacement	Dec-14	Jul-16	Sep-18	8.47	0.00	8.01	0.45
*	30	DSF0000888778	P.S. 2 MINISCHOOL	Replacement	Feb-18	May-19	Sep-21	43.69	0.00	32.58	11.11
*	75Q	DSF0000843866	P.S. 256 ANNEX	Replacement	Apr-16	Jul-18	Sep-20	52.35	0.00	37.41	14.94

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
24	Queens	Q005		<b>I.S. 5</b>				
					DSF0000800040	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	2,386,206
						PUBLIC ADDRESS SYSTEM		
					DSF0000800039	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	4,167,969
						Ventilation		
						VENTILATION:METAL DUCTWORK		
			Q005		DSF0000877655	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	117,085
						GAS SERVICE:Gas Distribution Piping		
						HEATING PLANT:Boiler Auxiliaries		
							<b>I.S. 5 Total:</b>	<b>\$6,671,260</b>
24	Queens	Q007		<b>P.S. 7</b>				
			Q007		DSF0000843863	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	8,303,303
						CLIMATE CONTROL SYSTEM		
			Q007		DSF0000855070	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	4,823,928
						AUXILIARY SIGNAL/BELL SYSTEM		
						FIRE ALARM SYSTEM		
			Q007		DSF0000855086	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	46,701
						Waste System		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump		
					DSF0000811071	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,722
			Q007		DSF0000877673	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	66,655
						<b>Other</b>		
					DSF0000867051	IP Surveillance Camera Installation	2019	379,780
							<b>P.S. 7 Total:</b>	<b>\$13,690,089</b>
24	Queens	Q012		<b>P.S. 12</b>				
					DSF0000798344	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2016	4,980,236
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000787816	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2016	1,633,479
						CLIMATE CONTROL SYSTEM		
					DSF0000799783	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2016	792,001
						SERVICE SWITCH SWITCHBOARD		
					DSF0000868213	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2016	727,653

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q012	DSF0000799865		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			Q012	DSF0000843641		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	101,351
			Q012	DSF0000865744		<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
			Q012	DSF0000843797		<b>Other</b> Classroom Connectivity	2016	41,085
							<b>P.S. 12 Total:</b>	<b>\$8,623,337</b>
24	Queens	Q013		<b>P.S. 13</b>				
				DSF0000775628		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	891,328
				DSF0000868214		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	262,188
			Q013	DSF0000889474		<b>Other</b> IP Surveillance Camera Installation	2019	40,114

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 13 Total:</b>	\$1,193,630
24	Queens	Q014		<b>P.S. 14</b>				
					DSF0000868215	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	516,880
					DSF0000765246	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	909,580
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000765245	<b>State of Good Repair - System Replacements - Parapets</b>	2016	8,675,679
						EXTERIOR:PARAPETS		
					DSF0000765244	<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,811,096
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
					DSF0000811184	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
			Q014		DSF0000843642	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	101,351
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			Q014		DSF0000776062	IP Surveillance Camera Installation	2015	654,743
							<b>P.S. 14 Total:</b>	\$13,770,680
24	Queens	Q019		<b>P.S. 19</b>				
			Q019		DSF0000888774	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	187,324
			Q019		DSF0000891080	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
							<b>P.S. 19 Total:</b>	\$379,824
24	Queens	Q049		<b>P.S. 49</b>				
					DSF0000799779	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	98,487
			Q049		DSF0000866021	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<i>Other</i>		
			Q049		DSF0000843796	Classroom Connectivity	2016	307,542
							<b>P.S. 49 Total:</b>	\$620,821
24	Queens	Q058		<b>P.S. 58</b>				
					DSF0000844716	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	98,642

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q058	DSF0000887550		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan	2019	908,917
			Q058	DSF0000866022		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			Q058	DSF0000776065		<b>Other</b> IP Surveillance Camera Installation	2015	379,034
							<b>P.S. 58 Total:</b>	<b>\$1,601,385</b>
24	Queens	Q061		<b>I.S. 61</b>				
			Q061	DSF0000833966		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2018	1,048,751
			Q061	DSF0000844152		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,268,808
			Q061	DSF0000833964		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	4,460,468
			Q061	DSF0000889476		<b>Other</b> IP Surveillance Camera Installation	2019	39,779

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 61 Total:</b>	\$6,817,806
24	Queens	Q068		<b>P.S. 68</b>				
					DSF0000788656	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	536,765
					DSF0000743071	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent AUDITORIUM:LOCAL SOUND SYSTEM AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating	2018	1,287,894
					DSF0000868219	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	332,431
						<b>Other</b>		
			Q068		DSF0000776066	IP Surveillance Camera Installation	2015	672,517
							<b>P.S. 68 Total:</b>	\$2,829,607
24	Queens	Q071		<b>P.S. 71</b>				
					DSF0000822249	<b>Accessibility</b>	2016	1,001,165
					DSF0000766069	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,375,353

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
					DSF0000766068	<b>State of Good Repair - System Replacements - Parapets</b>	2018	2,766,770
						EXTERIOR:PARAPETS		
					DSF0000878637	<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,738,517
						EXTERIOR:ROOF:Roofing		
					DSF0000812031	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	152,027
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						<b>Other</b>		
			Q071		DSF0000866228	New/Retrofit Telephone/Intercom Systems	2017	229,743
							<b>P.S. 71 Total:</b>	<b>\$11,263,575</b>
24	Queens	Q073		<b>I.S. 73</b>				
					DSF0000912380	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	158,088
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
			Q073		DSF0000890603	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	7,645,713
						HEATING PLANT:Boiler Auxiliaries		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000885445	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2019	4,926,670
					DSF0000799610	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	200,938
					DSF0000856093	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2018	7,500
					DSF0000912095	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	815,565
					DSF0000812069	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	186,777
						<b>Other</b>		
			Q073		DSF0000889542	IP Surveillance Camera Installation	2019	39,644
							<b>I.S. 73 Total:</b>	<b>\$13,980,895</b>
24	Queens	Q081		<b>P.S. 81</b>				
			Q081		DSF0000844057	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2018	2,354,741



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q081		DSF0000867169	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	127,090
			Q081		DSF0000878785	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	43,547
						GAS SERVICE:Gas Distribution Piping HEATING:Radiator/Convector/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
			Q081		DSF0000891070	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000812197	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	149,390
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							<b>P.S. 81 Total:</b>	<b>\$2,867,268</b>
24	Queens	Q087		<b>P.S. 87</b>				
					DSF0000865903	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	136,490
					DSF0000788975	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	895,299

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866169	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	232,136
			Q087		DSF0000843644	<b>State of Good Repair - System Replacements - Toilets - Students</b>  FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	256,352
			Q087		DSF0000889478	<b>Other</b> IP Surveillance Camera Installation	2019	40,651
							<b>P.S. 87 Total:</b>	<b>\$1,560,928</b>
24	Queens	Q088		<b>P.S. 88</b>				
			Q088		DSF0000878883	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>  AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly	2019	1,480,296
			Q088		DSF0000867103	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	129,795

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
			Q088	DSF0000866128		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			Q088	DSF0000878897		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	1,022,119
			Q088	DSF0000891072		Ventilation <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
							<b>P.S. 88 Total:</b>	\$2,902,400
24	Queens	Q089		<b>P.S. 89</b>				
				DSF0000868221		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	552,206
			Q089	DSF0000901784		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	365,402
						Ventilation AIR CONDITIONING:Chilled Water System:Central Station Air Handler MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan		
			Q089	DSF0000812320		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	68,147
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			Q089		DSF0000775700	IP Surveillance Camera Installation	2015	552,001
							<b>P.S. 89 Total:</b>	<b>\$1,537,756</b>
24	Queens	Q091		<b>P.S. 91</b>				
			Q091		DSF0000912479	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
					DSF0000798294	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	836,407
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000868222	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	514,000
			Q091		DSF0000843645	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	173,036
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
			Q091		DSF0000865745	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	315,873
						<i>Other</i>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q091		DSF0000866206	Classroom Connectivity	2017	232,205
			Q091		DSF0000868097	IP Surveillance Camera Installation	2019	462,475
							<b>P.S. 91 Total:</b>	<b>\$2,733,996</b>
24	Queens	Q093		<b>I.S. 93</b>				
					DSF0000800329	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2018	16,158,149
			Q093		DSF0000821618	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
			Q093		DSF0000789066	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY	2018	1,336,416
			Q093		DSF0000812370	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,302,448
			Q093		DSF0000789064	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	4,895,416
			Q093		DSF0000812371	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2018	1,597,050
						<b>Other</b>		
			Q093		DSF0000889221	New/Retrofit Telephone/Intercom Systems	2018	319,998
					DSF0000775701	IP Surveillance Camera Installation	2015	601,956

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 93 Total:</b>	\$26,690,499
24	Queens	Q102		<b>P.S./I.S. 102</b>				
			Q102	DSF0000730986		<b>Accessibility</b>	2017	3,849,382
				DSF0000879111		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,639,012
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000879115		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	5,023,370
						EXTERIOR:CHIMNEY		
				DSF0000879114		<b>State of Good Repair - System Replacements - Parapets</b>	2019	6,500,613
						EXTERIOR:COPING		
			Q102	DSF0000912469		<b>State of Good Repair - System Replacements - Roofs</b>	2019	1,516,911
						EXTERIOR:ROOF:Roofing		
			Q102	DSF0000889622		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			Q102	DSF0000912468		<b>State of Good Repair - System Replacements - Windows</b>	2019	3,921,161
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			Q102	DSF0000889222		New/Retrofit Telephone/Intercom Systems	2018	311,265
							<b>P.S./I.S. 102 Total:</b>	\$22,976,506

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
24	Queens	Q113		<b>P.S./I.S. 113</b>				
						<i>Other</i>		
			Q113		DSF0000889481	IP Surveillance Camera Installation	2019	39,443
							<b>P.S./I.S. 113 Total:</b>	<b>\$39,443</b>
24	Queens	Q119		<b>I.S. 119</b>				
			Q119		DSF0000844123	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	637,402
					DSF0000789466	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,027,989
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866923	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	12,338
			Q119		DSF0000866029	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>I.S. 119 Total:</b>	<b>\$1,830,458</b>
24	Queens	Q125		<b>I.S. 125</b>				
					DSF0000777509	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	142,916
					DSF0000799888	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	551,802

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868320	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	387,325
			Q125		DSF0000866129	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	79,389
					DSF0000879488	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	192,500
							<b>I.S. 125 Total:</b>	<b>\$1,353,932</b>
24	Queens	Q143		<b>P.S. 143</b>				
					DSF0000789897	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,012,909
					DSF0000889277	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	364,316
					DSF0000799826	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	129,754
			Q143		DSF0000866036	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 143 Total:</b>	<b>\$1,721,771</b>
24	Queens	Q153		<b>P.S. 153</b>				
					DSF0000799618	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	165,945



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866090	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	3,052,542
					DSF0000866089	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:PARAPETS	2018	268,409
					DSF0000857427	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing	2018	1,532,977
			Q153		DSF0000889626	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
			Q153		DSF0000866320	<i>State of Good Repair - System Replacements - Windows</i> EXTERIOR:WINDOWS	2018	301,955
			Q153		DSF0000776069	<i>Other</i> IP Surveillance Camera Installation	2015	605,179
							<b>P.S. 153 Total:</b>	<b>\$6,141,799</b>
24	Queens	Q199		<b>P.S. 199</b>				
			Q199		DSF0000798372	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	5,782,937
					DSF0000790833	<i>State of Good Repair - Building Upgrade - Climate Control</i> CLIMATE CONTROL SYSTEM	2018	1,521,188
			Q199		DSF0000814110	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	2,210,612

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
					DSF0000843865	<b>State of Good Repair - System Replacements - Parapets</b>	2018	821,558
						EXTERIOR:PARAPETS		
			Q199		DSF0000843655	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	3,125,030
						<b>Other</b>		
			Q199		DSF0000776072	IP Surveillance Camera Installation	2015	566,354
							<b>P.S. 199 Total:</b>	<b>\$14,027,679</b>
24	Queens	Q229		<b>P.S. 229</b>				
					DSF0000912427	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	78,061
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
					DSF0000791281	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,430,420
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q229	DSF0000881069		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2019	1,457,490
				DSF0000868233		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	843,980
				DSF0000791284		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	857,251
			Q229	DSF0000866047		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
			Q229	DSF0000888956		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	6,868,478
			Q229	DSF0000776074		<b>Other</b> IP Surveillance Camera Installation	2015	641,142
							<b>P.S. 229 Total:</b>	<b>\$12,329,551</b>
24	Queens	Q239		<b>P.S. 239</b>				
				DSF0000844712		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	74,805

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q239		DSF0000891052	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	192,500
						<i>Other</i>		
					DSF0000868130	IP Surveillance Camera Installation	2018	290,002
							<b>P.S. 239 Total:</b>	<b>\$557,307</b>
24	Queens	Q245		<b>P.S. 245 ECC (@ SENECA AVE)</b>				
						<i>Other</i>		
			Q305		DSF0000889485	IP Surveillance Camera Installation	2019	40,531
							<b>P.S. 245 ECC (@ SENECA AVE) Total:</b>	<b>\$40,531</b>
24	Queens	Q247		<b>P.S. 128</b>				
					DSF0000865865	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	139,775
							<b>P.S. 128 Total:</b>	<b>\$139,775</b>
24	Queens	Q260		<b>P.S. 307</b>				
					DSF0000865866	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	180,366
						<i>Other</i>		
			Q307		DSF0000889487	IP Surveillance Camera Installation	2019	39,577
							<b>P.S. 307 Total:</b>	<b>\$219,943</b>
24	Queens	Q269		<b>P.S./I.S. 269</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q016		DSF0000881784	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	203,646
			Q016		DSF0000881792	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	915,049
						Ventilation AIR CONDITIONING:Chilled Water System:Central Station Air Handler MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Metal Ductwork		
					DSF0000823652	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	160,634
						INTERIOR:TOILET ROOMS - STUDENTS		
<b>P.S. 16 (OLD Q721 SPED) Total:</b>								\$3,643,414
24	Queens	Q848		<b>P.S. 81 ANNEX (OLD 75)</b>				
			Q081		DSF0000815382	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
<b>P.S. 81 ANNEX (OLD 75) Total:</b>								\$101,351
24	Queens	Q849		<b>I.S. 77</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798430	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	733,063
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000868302	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	200,570
						<b>Other</b>		
			Q077		DSF0000889497	IP Surveillance Camera Installation	2019	40,047
							<b>I.S. 77 Total:</b>	<b>\$973,680</b>
24	Queens	Q877		<b>51ST AVENUE ACADEMY</b>				
					DSF0000792212	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	304,475
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						<b>Other</b>		
			Q877		DSF0000865921	Classroom Connectivity	2017	192,966
					DSF0000799915	IP Surveillance Camera Installation	2015	450,875
							<b>51ST AVENUE ACADEMY Total:</b>	<b>\$948,316</b>
24	Queens	Q878		<b>P.S. 128 ANNEX</b>				
						<b>Other</b>		
			Q128		DSF0000867140	New/Retrofit Telephone/Intercom Systems	2018	121,758

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 128 ANNEX Total:</b>	\$121,758
25	Queens	Q020		<b>P.S. 20</b>				
					DSF0000865899	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	94,613
			Q020		DSF0000866315	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	463,756
			Q020		DSF0000867109	<i>Safety and Security - Safety and Security - Code Compliance</i>	2019	2,096,231
			Q020		DSF0000877872	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2019	341,705
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000765327	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i>	2019	3,640,388
						FIRE ALARM SYSTEM		
			Q020		DSF0000877874	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2019	1,457,504
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY		
					DSF0000787947	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	5,513,545
						Ventilation AIR CONDITIONING:CHILLED WATER SYSTEM:Central Station Air Handler		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
			Q020	DSF0000877873		<b>State of Good Repair - System Replacements - Parapets</b>	2019	605,852
			Q020	DSF0000889087		EXTERIOR:COPING <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	5,903,578
							<b>P.S. 20 Total:</b>	\$20,117,172
25	Queens	Q021		<b>P.S. 21</b>				
			Q021	DSF0000823566		<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling	2017	441,027
			Q021	DSF0000776063		<b>Other</b> IP Surveillance Camera Installation	2015	663,069
							<b>P.S. 21 Total:</b>	\$1,104,096
25	Queens	Q022		<b>P.S. 22</b>				
				DSF0000866911		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	121,921
			Q022	DSF0000787973		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	40,812

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q022		DSF0000866016	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			Q022		DSF0000843793	Classroom Connectivity	2016	263,344
							<b>P.S. 22 Total:</b>	<b>\$640,869</b>
25	Queens	Q024		<b>P.S. 24</b>				
					DSF0000799607	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	138,914
						<b>Other</b>		
			Q024		DSF0000776064	IP Surveillance Camera Installation	2015	598,486
							<b>P.S. 24 Total:</b>	<b>\$737,400</b>
25	Queens	Q025		<b>J.H.S. 25</b>				
					DSF00008665900	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	101,361
			Q025		DSF0000866275	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	466,500
					DSF0000788018	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,971,490
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866914	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	47,627
			Q025		DSF0000877946	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping HEATING:Steam Heating	2019	192,500
			Q025		DSF0000889034	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Air Cooled Chiller	2019	1,378,405
					DSF0000811344	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2015	101,351
			Q025		DSF0000866017	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			Q025		DSF0000889475	<b>Other</b> IP Surveillance Camera Installation	2019	40,315
							<b>J.H.S. 25 Total:</b>	<b>\$4,514,341</b>
25	Queens	Q029		<b>P.S. 29</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798481	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	307,799
					DSF0000866915	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	37,146
							<b>P.S. 29 Total:</b>	<b>\$344,945</b>
25	Queens	Q032		<b>P.S. 32</b>				
					DSF0000799704	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	111,975
					DSF0000888986	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	398,539
					DSF0000811427	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	101,351
			Q032		DSF0000889224	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	313,789
							<b>P.S. 32 Total:</b>	<b>\$925,654</b>
25	Queens	Q079		<b>P.S. 79</b>				
			Q079		DSF0000823601	<b>Safety and Security - Safety and Security - Code Compliance</b>	2019	11,593,543

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000788834	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,319,308
					DSF0000856162	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2019	3,746,023
			Q079		DSF0000866283	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	2,678,766
					DSF0000743236	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2016	631,075
					DSF0000856168	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	6,918,317
			Q079		DSF0000788841	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	57,549
			Q079		DSF0000888906	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	206,505
			Q079		DSF0000888905	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2019	4,637,029
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q079	DSF0000889225		New/Retrofit Telephone/Intercom Systems	2018	238,770
							<b>P.S. 79 Total:</b>	\$32,026,885
25	Queens	Q107		<b>P.S. 107</b>				
			Q107	DSF0000843809		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	732,093
				DSF0000789285		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,058,731
			Q107	DSF0000834682		<b>State of Good Repair - System Replacements - Floors</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2017	692,402
			Q107	DSF0000789291		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	81,899

**Other**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q107	DSF0000865915		Classroom Connectivity	2017	276,196
							<b>P.S. 107 Total:</b>	<b>\$2,841,321</b>
25	Queens	Q120		<b>P.S. 120</b>				
				DSF0000799612		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	271,535
						<b>Other</b>		
			Q120	DSF0000776067		IP Surveillance Camera Installation	2015	569,714
							<b>P.S. 120 Total:</b>	<b>\$841,249</b>
25	Queens	Q129		<b>P.S. 129</b>				
				DSF0000798491		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	585,676
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000866924		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,375
				DSF0000823644		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	110,190
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000775702	IP Surveillance Camera Installation	2015	533,416
							<b>P.S. 129 Total:</b>	\$1,232,657
25	Queens	Q130		<b>P.S. 130</b>				
					DSF0000766962	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	757,238
					DSF0000798493	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	830,951
					DSF0000766966	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS	2015	2,295,960
					DSF0000799824	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	184,207
					DSF0000766965	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2015	1,471,235
					DSF0000766964	<b>State of Good Repair - System Replacements - Roofs</b>	2015	2,006,074



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing		
						<i>Other</i>		
			Q130		DSF0000865916	Classroom Connectivity	2017	206,660
					DSF0000867067	IP Surveillance Camera Installation	2018	226,851
							<b>P.S. 130 Total:</b>	<b>\$7,979,176</b>
25	Queens	Q154		<b>P.S. 154</b>				
					DSF0000799619	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	258,005
			Q154		DSF0000889627	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 154 Total:</b>	<b>\$472,797</b>
25	Queens	Q163		<b>P.S. 163</b>				
					DSF0000912321	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	40,770
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
					DSF0000889063	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	299,970
							<b>P.S. 163 Total:</b>	<b>\$340,740</b>
25	Queens	Q164		<b>P.S. 164</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000790290	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	986,775
			Q164		DSF0000822212	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM FIXTURES:STUDENT:Drinking Fountain FIXTURES:STUDENT:Sink And Fountain Combo Unit	2016	74,264
					DSF0000813581	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	114,170
			Q164		DSF0000889226	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	184,946
							<b>P.S. 164 Total:</b>	<b>\$1,360,155</b>
25	Queens	Q165		<b>P.S. 165</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866929	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	7,432
							<b>P.S. 165 Total:</b>	\$7,432
25	Queens	Q168		<b>J.H.S. 168</b>				
			Q252		DSF0000857661	<i>State of Good Repair - System Replacements - Domestic Piping</i> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2017	104,478
					DSF0000889292	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	11,064
					DSF0000880233	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	400,572
					DSF0000912490	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:PARAPETS	2019	2,951,870
					DSF0000880232	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	473,248
							<b>J.H.S. 168 Total:</b>	\$3,941,232
25	Queens	Q169		<b>P.S. 169</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q169		DSF0000790351	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	833,638
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000911870	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	267,278
			Q169		DSF0000866040	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
			Q169		DSF0000889227	New/Retrofit Telephone/Intercom Systems	2018	286,850
							<b>P.S. 169 Total:</b>	<b>\$1,540,495</b>
25	Queens	Q184		<b>P.S. 184</b>				
					DSF0000798371	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	5,618,208
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
					DSF0000790584	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,190,164
						CLIMATE CONTROL SYSTEM		
					DSF0000790586	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	707,058
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000790598	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Floor Finish	2016	1,450,984
						<b>Other</b>		
			Q184		DSF0000889228	New/Retrofit Telephone/Intercom Systems	2018	163,345
							<b>P.S. 184 Total:</b>	<b>\$9,129,759</b>
25	Queens	Q185		<b>J.H.S. 185</b>				
					DSF0000844709	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	142,928
					DSF0000868229	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	310,689
					DSF0000880467	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000911810	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	105,465
			Q185		DSF0000813893	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	101,351
					DSF0000822107	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2016	1,567,834

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			Q185		DSF0000889229	New/Retrofit Telephone/Intercom Systems	2018	391,275
			Q185		DSF0000867045	IP Surveillance Camera Installation	2018	536,085
							<b>J.H.S. 185 Total:</b>	\$3,348,127
25	Queens	Q189		<b>J.H.S. 189</b>				
					DSF0000799827	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	294,020
			Q189		DSF0000889630	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<i>Other</i>		
			Q263		DSF0000776071	IP Surveillance Camera Installation	2015	643,744
							<b>J.H.S. 189 Total:</b>	\$1,152,556
25	Queens	Q193		<b>P.S. 193</b>				
			Q193		DSF0000888785	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2019	6,302,642
			Q193		DSF0000880580	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2019	2,240,329
					DSF0000790733	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,037,305

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000790732	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	825,968
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
		Q193			DSF0000843951	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	3,716,553
					DSF0000888988	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	996,486
					DSF0000880588	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
		Q193			DSF0000889230	New/Retrofit Telephone/Intercom Systems	2018	171,982
					DSF0000775707	IP Surveillance Camera Installation	2015	544,747
							<b>P.S. 193 Total:</b>	<b>\$16,028,512</b>
25	Queens	Q194		<b>J.H.S. 194</b>				
					DSF0000798297	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	6,798,923
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000790753	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	2,090,867
						CLIMATE CONTROL SYSTEM		
			Q194		DSF0000790759	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000799828	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	170,272
						<b>Other</b>		
			Q194		DSF0000889231	New/Retrofit Telephone/Intercom Systems	2018	270,477
							<b>J.H.S. 194 Total:</b>	<b>\$9,362,219</b>
25	Queens	Q200		<b>P.S. 200</b>				
					DSF0000866935	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	19,610
							<b>P.S. 200 Total:</b>	<b>\$19,610</b>
25	Queens	Q201		<b>P.S. 201</b>				
					DSF0000912323	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	60,889
						EMERGENCY LIGHT/EXIT LIGHT PANEL		
						EMERGENCY LIGHTING		
						EXIT LIGHT		
			Q201		DSF0000798431	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	5,165,106
						HEATING PLANT:BOILER AUXILIARIES		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q201	DSF0000790872		HEATING PLANT:BOILER SYSTEM <i>State of Good Repair - Building Upgrade - Climate Control</i>	2019	2,739,775
				DSF0000790873		CLIMATE CONTROL SYSTEM <i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	908,835
				DSF0000890984		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,382,681
							<b>P.S. 201 Total:</b>	\$10,257,286
25	Queens	Q209		<b>P.S. 209</b>				
				DSF0000890986		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	7,325
						<i>Other</i>		
			Q209	DSF0000867163		New/Retrofit Telephone/Intercom Systems	2018	218,183
							<b>P.S. 209 Total:</b>	\$225,508
25	Queens	Q214		<b>P.S. 214</b>				
			Q214	DSF0000812865		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	945,450

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			Q214	DSF0000814328		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	3,717,954
			Q214	DSF0000745395		<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,433,678
						EXTERIOR:PARAPETS		
			Q214	DSF0000814327		<b>State of Good Repair - System Replacements - Roofs</b>	2017	2,279,940
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						<b>Other</b>		
			Q214	DSF0000822055		New/Retrofit Telephone/Intercom Systems	2015	160,427
							<b>P.S. 214 Total:</b>	<b>\$8,537,449</b>
25	Queens	Q219		<b>P.S. 219</b>				
					DSF0000814406	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,362,278
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			Q219	DSF0000745480		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	1,990,155
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000814419	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING	2016	79,109
					DSF0000858398	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	985,945
			Q219		DSF0000791153	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
					DSF0000799467	<b>State of Good Repair - System Replacements - Kitchen Areas</b>	2018	571,549
					DSF0000880952	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	6,342,670
			Q219		DSF0000822039	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2015	203,052
							<b>P.S. 219 Total:</b>	<b>\$11,566,417</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
25	Queens	Q237		J.H.S. 237				
					DSF0000881116	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:Elevator INTERCOM SYSTEM:Elevator	2019	13,093,164
					DSF0000799830	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	161,966
			Q237		DSF0000814588	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	101,351
<b>J.H.S. 237 Total:</b>								<b>\$13,356,481</b>
25	Queens	Q242		P.S. 242 - (ECC)				
					DSF0000799392	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	1,433,747
					DSF0000797681	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2016	157,031
			Q242		DSF0000889575	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	993,813

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000868133	IP Surveillance Camera Installation	2018	260,148
							<b>P.S. 242 - (ECC) Total:</b>	<b>\$2,844,739</b>
25	Queens	Q244		<b>P.S. 244 ECC (@ FRANKLIN AVE)</b>				
						<i>Other</i>		
			Q244		DSF0000889484	IP Surveillance Camera Installation	2019	38,907
							<b>P.S. 244 ECC (@ FRANKLIN AVE) Total:</b>	<b>\$38,907</b>
25	Queens	Q499		<b>P.S./I.S. 499</b>				
					DSF0000865868	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	263,485
						<i>Other</i>		
			Q499		DSF0000776077	IP Surveillance Camera Installation	2015	573,713
							<b>P.S./I.S. 499 Total:</b>	<b>\$837,198</b>
26	Queens	Q018		<b>P.S. 18</b>				
			Q018		DSF0000889618	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 18 Total:</b>	<b>\$214,792</b>
26	Queens	Q026		<b>P.S. 26</b>				
			Q026		DSF0000798312	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	6,257,006

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q026		DSF0000798314	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	3,157,496
					DSF0000788039	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,203,698
			Q026		DSF0000889619	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 26 Total:</b>	\$10,832,992
26	Queens	Q031		<b>P.S. 31</b>				
			Q031		DSF0000833500	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System	2017	5,464,022
			Q031		DSF0000843954	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	830,226
			Q031		DSF0000833494	<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b>	2017	336,460

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
			Q031		DSF0000800273	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	3,434,773
			Q031		DSF0000843955	EXTERIOR:CHIMNEY <i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	1,458,655
			Q031		DSF0000833496	EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR <i>State of Good Repair - System Replacements - Parapets</i>	2017	4,056,564
			Q031		DSF0000833495	EXTERIOR:PARAPETS <i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing	2017	2,861,871
							<b>P.S. 31 Total:</b>	<b>\$18,442,571</b>
26	Queens	Q041		<b>P.S. 41</b>				
					DSF0000798483	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	565,949

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000811593	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	115,799
			Q041		DSF0000867161	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	152,369
							<b>P.S. 41 Total:</b>	<b>\$834,117</b>
26	Queens	Q046		<b>P.S. 46</b>				
					DSF0000798319	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	617,089
			Q046		DSF0000889009	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
			Q046		DSF0000866020	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 46 Total:</b>	<b>\$858,802</b>
26	Queens	Q067		<b>J.H.S. 67</b>				
					DSF0000788635	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,186,271



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866917	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	28,457
					DSF0000811959	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	308,282
			Q067		DSF0000834056	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convector/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2016	53,905
			Q067		DSF0000866024	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	152,729
			Q067		DSF0000889232	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	316,550
							<b>J.H.S. 67 Total:</b>	<b>\$3,046,194</b>
26	Queens	Q074		<b>I.S. 74</b>	DSF0000865902	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	225,195

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q074		DSF0000866274	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	447,000
					DSF0000788769	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,156,945
					DSF0000812090	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2017	158,527
							<b>I.S. 74 Total:</b>	<b>\$1,987,667</b>
26	Queens	Q094		<b>P.S. 94</b>				
					DSF0000789084	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	638,472
			Q094		DSF0000812391	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	158,894

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
			Q094	DSF0000843646		FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	240,705	
			Q094	DSF0000867165		FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS  <b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	202,113	
								<b>P.S. 94 Total:</b>	\$1,240,184
26	Queens	Q098		<b>P.S. 98</b>					
				DSF0000901929		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	4,577,218	
			Q098	DSF0000799461		<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:RETAINING WALLS SITE:STAIRS/RAMPS: EXTERIOR	2016	827,904	
			Q098	DSF0000866026		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792	
								<b>P.S. 98 Total:</b>	\$5,619,914

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
26	Queens	Q115		<b>THE JAMES J. AMBROSE SCHOOL</b>				
					DSF0000798279	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,371,435
					DSF0000798280	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,796,876
			Q115		DSF0000834790	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2017	1,808,431
			Q115		DSF0000834789	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	4,440,871
					DSF0000812703	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	143,042
<b>THE JAMES J. AMBROSE SCHOOL Total:</b>								<b>\$13,560,655</b>
26	Queens	Q133		<b>P.S. 133</b>				
					DSF0000789714	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	727,503

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q133		DSF0000813021	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	181,485
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 133 Total:</b>	<b>\$908,988</b>
26	Queens	Q158		<b>J.H.S. 158</b>				
					DSF0000912319	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	73,588
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT		
			Q158		DSF0000880102	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2019	1,889,293
						FIRE ALARM SYSTEM		
			Q158		DSF0000868321	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	714,707
			Q158		DSF0000866039	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>J.H.S. 158 Total:</b>	\$2,892,380
26	Queens	Q159		<b>P.S. 159</b>				
					DSF0000880124	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	1,684,667
					DSF0000790203	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	905,431
			Q159		DSF0000790210	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	241,990
			Q159		DSF0000889233	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	207,252
							<b>P.S. 159 Total:</b>	\$3,039,340
26	Queens	Q162		<b>P.S. 162</b>				
					DSF0000798369	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	6,046,973

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798370	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	1,855,782
					DSF0000790250	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	2,249,343
					DSF0000790253	INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	5,852,817
					DSF0000790252	EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR <b>State of Good Repair - System Replacements - Parapets</b>	2016	2,335,532
					DSF0000800283	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,269,573
						<b>Other</b>		
			Q162	DSF0000889234		New/Retrofit Telephone/Intercom Systems	2018	236,272
							<b>P.S. 162 Total:</b>	<b>\$19,846,292</b>
26	Queens	Q172		J.H.S. 172				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000813679	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	229,035
							<b>J.H.S. 172 Total:</b>	\$229,035
26	Queens	Q173		<b>P.S. 173</b>				
					DSF0000790406	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	976,452
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000890990	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	10,855
			Q173		DSF0000866041	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 173 Total:</b>	\$1,202,099
26	Queens	Q178		<b>P.S. 178</b>				
						<i>Other</i>		
			Q178		DSF0000889235	New/Retrofit Telephone/Intercom Systems	2018	277,110
							<b>P.S. 178 Total:</b>	\$277,110
26	Queens	Q186		<b>P.S. 186</b>				
					DSF0000800305	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	362,226



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000813911	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	76,345
							<b>P.S. 186 Total:</b>	\$438,571
26	Queens	Q188		<b>P.S. 188</b>				
					DSF0000798329	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	700,249
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q188		DSF0000889629	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			Q188		DSF0000867155	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	175,097
							<b>P.S. 188 Total:</b>	\$1,090,138
26	Queens	Q191		<b>P.S. 191</b>				
					DSF0000880545	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	267,984
					DSF0000813971	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	718,106

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000880548	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	3,322,904
					DSF0000880547	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	206,663
					DSF0000880546	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	3,872,587
							<b>P.S. 191 Total:</b>	<b>\$8,388,244</b>
26	Queens	Q203		<b>P.S. 203</b>				
					DSF0000890606	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,018
					DSF0000880739	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	4,945,600
						<b>Other</b>		
			Q203		DSF0000867142	New/Retrofit Telephone/Intercom Systems	2018	269,892
							<b>P.S. 203 Total:</b>	<b>\$5,216,510</b>
26	Queens	Q205		<b>P.S. 205</b>				
					DSF0000798368	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES	2017	8,634,192

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
					DSF0000789227	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	2,361,258
			Q205		DSF0000836272	CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	890,084
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
					DSF0000814216	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	957,191
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000880778	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2018	150,552
			Q205		DSF0000836276	AUDITORIUM:Local Sound System INTERIOR:AUDITORIUM:Ceiling <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,285,285
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
					DSF0000814224	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	152,690
			Q205		DSF0000822663	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000836274	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	2,036,517
					DSF0000836273	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	4,242,426
						<b>Other</b>		
			Q205		DSF0000867159	New/Retrofit Telephone/Intercom Systems	2018	220,168
							<b>P.S. 205 Total:</b>	<b>\$22,075,149</b>
26	Queens	Q213		<b>P.S. 213</b>				
			Q213		DSF0000814311	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			Q213		DSF0000889631	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			Q213		DSF0000889236	New/Retrofit Telephone/Intercom Systems	2018	219,860
							<b>P.S. 213 Total:</b>	<b>\$579,438</b>
26	Queens	Q216		<b>J.H.S. 216</b>				
					DSF0000912324	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	64,504

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXIT/EMERGENCY LIGHT		
					DSF0000798301	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2017	6,503,624
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000791100	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,585,253
						CLIMATE CONTROL SYSTEM		
					DSF0000799623	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	186,578
			Q216		DSF0000814383	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	457,059
						CAFETERIA:LOCAL SOUND SYSTEM INTERIOR:CAFETERIA:Floor Finish INTERIOR:CAFETERIA:Walls		
					DSF0000889661	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	183,351
					DSF0000880912	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	5,201,456
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			Q216		DSF0000791108	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000880911	<b>State of Good Repair - System Replacements - Parapets</b>	2019	3,209,181

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000880910	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	9,714,790
			Q216		DSF0000814370	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	150,000
					DSF0000903778	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Windows</b>	2019	5,756,590
			Q216		DSF0000889237	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	239,125
							<b>J.H.S. 216 Total:</b>	<b>\$33,283,191</b>
26	Queens	Q221		<b>P.S. 221</b>	DSF0000903856	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	55,000
			Q221		DSF0000889632	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 221 Total:</b>	<b>\$269,792</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
26	Queens	Q266		P.S./I.S. 266				
						<i>Other</i>		
			Q266	DSF0000889489		IP Surveillance Camera Installation	2019	47,641
							<b>P.S./I.S. 266 Total:</b>	<b>\$47,641</b>
26	Queens	Q858		P.S. 188 ANNEX				
				DSF0000866945		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	34,862
							<b>P.S. 188 ANNEX Total:</b>	<b>\$34,862</b>
27	Queens	Q042		P.S. 42				
				DSF0000799428		<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	1,533,793
						CLIMATE CONTROL SYSTEM		
				DSF0000788293		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	5,814,733
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000788302		<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2015	2,659,001
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799608	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	440,530
					DSF0000799439	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING	2015	785,440
					DSF0000799919	<b>State of Good Repair - System Replacements - Electrical Systems</b> PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,432,941
					DSF0000868216	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	148,180
			Q042		DSF0000788296	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler Auxiliaries	2015	7,183,102



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799438	HEATING PLANT:Boiler System HEATING PLANT:Fuel System <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2015	2,153,813
			Q042		DSF0000912233	<b>Other</b> IP Surveillance Camera Installation	2019	74,413
								<b>P.S. 42 Total: \$23,225,946</b>
27	Queens	Q043		<b>P.S. 43</b>	DSF0000788303	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	1,627,265
					DSF0000799416	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:ELEVATORS	2015	517,085
			Q043		DSF0000844151	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2016	44,906
					DSF0000798639	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	3,790,667

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					DSF0000798637	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	2,468,417
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
					DSF0000798638	INTERIOR:STAIRS/RAMPS: INTERIOR <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	6,434,765
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
			Q043		DSF0000866126	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000788306	<b>State of Good Repair - System Replacements - Roofs</b>	2015	4,017,393
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 43 Total:</b>	\$18,978,188
27	Queens	Q045		<b>P.S. 45</b>				
					DSF0000878240	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	2,477,062
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000878244	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	3,708,804
					DSF0000878243	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	6,738,881
					DSF0000878242	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	2,288,126
			Q045		DSF0000866019	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
<b>P.S. 45 Total:</b>								\$15,427,665
27	Queens	Q047		<b>P.S. 47</b>				
					DSF0000788356	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	858,126
					DSF0000799398	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,862,472
					DSF0000788371	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	372,226

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000788362	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	296,515
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
					DSF0000911942	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2019	55,139
					DSF0000788370	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	727,650
						Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK		
			Q047		DSF0000866264	<b>State of Good Repair - System Replacements - Roofs</b>	2019	4,508,761
						EXTERIOR:ROOF:Roofing		
							<b>P.S. 47 Total:</b>	<b>\$10,680,889</b>
27	Queens	Q053		<b>I.S. 53</b>				
					DSF0000866087	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	716,957

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Safety Systems		
					DSF0000866088	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	480,773
						Toilets - Students		
			Q053		DSF0000844124	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	1,674,434
			Q053		DSF0000865822	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	368,065
						Technology		
			Q319		DSF0000865823	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2017	369,865
						Technology		
			Q053		DSF0000866086	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2018	261,125
						Floors		
			Q319		DSF0000889659	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2019	90,000
						Technology		
			Q319		DSF0000890564	<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2019	70,000

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			Q053		DSF0000890565	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	203,853
						Technology		
			Q319		DSF0000867383	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	4,860,446
			Q053		DSF0000843772	<b>Code Compliance</b>	2018	2,704,305
					DSF0000777506	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	124,161
			Q053		DSF0000890601	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	11,326,304
			Q053		DSF0000878359	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2019	7,598,319
						CLIMATE CONTROL SYSTEM		
			Q053		DSF0000822674	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,440,891
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000788432	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	2,011,778
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q053	DSF0000855786		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,097,537
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
			Q053	DSF0000822673		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	4,812,892
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			Q053	DSF0000822675		<b>State of Good Repair - System Replacements - Parapets</b>	2018	5,485,981
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			Q053	DSF0000811759		<b>State of Good Repair - System Replacements - Roofs</b>	2018	3,379,007
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
			Q053	DSF0000822676		<b>State of Good Repair - System Replacements - Windows</b>	2018	4,590,185
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			Q053	DSF0000867144		New/Retrofit Telephone/Intercom Systems	2018	356,891

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q053		DSF0000889541	IP Surveillance Camera Installation	2019	41,456
							<b>I.S. 53 Total:</b>	<b>\$54,065,225</b>
27	Queens	Q056		<b>P.S. 56 (OLD R HILL AX)</b>				
					DSF0000765864	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	1,080,849
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			Q056		DSF0000912167	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,588,034
					DSF0000799468	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	1,480,097
						EXTERIOR:EXTERIOR WALLS		
					DSF0000765865	<b>State of Good Repair - System Replacements - Parapets</b>	2015	961,836
						EXTERIOR:PARAPETS		
					DSF0000788490	<b>State of Good Repair - System Replacements - Roofs</b>	2015	208,786
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			Q056		DSF0000788493	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	97,352
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						<b>Other</b>		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q056	DSF0000865914		Classroom Connectivity	2017	320,028
			Q056	DSF0000866243		New/Retrofit Telephone/Intercom Systems	2017	146,683
<b>P.S. 56 (OLD R HILL AX) Total:</b>								<b>\$5,883,665</b>
27	Queens	Q060		<b>P.S. 60</b>				
				DSF0000777507		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	121,197
				DSF0000811856		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	140,792
<b>P.S. 60 Total:</b>								<b>\$261,989</b>
27	Queens	Q062		<b>P.S. 62</b>				
			Q062	DSF0000891067		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q062	DSF0000889620		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
<b>P.S. 62 Total:</b>								<b>\$407,292</b>
27	Queens	Q063		<b>P.S. 63</b>				
			Q063	DSF0000788585		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	2,562,718

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000811913	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2016	186,791
			Q063		DSF0000811907	INTERIOR:AUDITORIUM:Fixed Seating <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	2,358,311
					DSF0000811906	EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2017	263,030
			Q063		DSF0000811905	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2017	773,189
					DSF0000823656	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	94,708
			Q063		DSF0000866023	INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q063		DSF0000889238	New/Retrofit Telephone/Intercom Systems	2018	257,033
			Q063		DSF0000775699	IP Surveillance Camera Installation	2015	586,612
							<b>P.S. 63 Total:</b>	\$7,235,121
27	Queens	Q064		<b>P.S. 64</b>				
			Q064		DSF0000844688	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	5,482,932
			Q064		DSF0000855949	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,115,927
						CLIMATE CONTROL SYSTEM		
			Q064		DSF0000855950	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	1,102,679
						FIRE ALARM SYSTEM		
			Q064		DSF0000834021	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	1,762,095
						HEATING PLANT:Boiler System		
			Q064		DSF0000891068	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						HEATING:Steam Heating		
					DSF0000811925	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	111,141
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 64 Total:</b>	\$10,767,274
27	Queens	Q066		<b>P.S. 66</b>				
					DSF0000866916	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	4,085
			Q066		DSF0000788621	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	156,904
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						<b>Other</b>		
			Q066		DSF0000866229	New/Retrofit Telephone/Intercom Systems	2017	133,853
							<b>P.S. 66 Total:</b>	\$294,842
27	Queens	Q090		<b>P.S. 90</b>				
					DSF0000743438	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2019	1,434,377
						AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent AUDITORIUM:PROJECTION SYSTEM AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Door(s)		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q090	DSF0000867180		INTERIOR:AUDITORIUM:Fixed Seating <b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2018	152,564
				DSF0000912097		INTERIOR:CAFETERIA:Floor Finish <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	180,594
			Q090	DSF0000812341		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	131,191
							<b>P.S. 90 Total:</b>	\$1,898,726
27	Queens	Q097		<b>P.S. 97</b>				
				DSF0000789138		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	906,613
			Q097	DSF0000891073		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING:Steam Heating	2019	192,500
							<b>P.S. 97 Total:</b>	\$1,099,113

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
27	Queens	Q100		<b>P.S. 100</b>				
					DSF0000865904	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	105,676
			Q100		DSF0000866277	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2018	447,000
			Q100		DSF0000732406	<i>Code Compliance</i>	2017	1,547,532
					DSF0000844084	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2017	429,029
						CONVEYING:Elevator INTERCOM SYSTEM:Elevator		
			Q100		DSF0000865863	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	124,564
						HEATING:Steam Heating		
			Q100		DSF0000812496	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2016	195,724
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
					DSF0000823657	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	218,067
							<b>P.S. 100 Total:</b>	<b>\$3,067,592</b>
27	Queens	Q104		<b>P.S. 104</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q104	DSF0000856554		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System	2018	6,849,274
			Q104	DSF0000812532		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,477,558
			Q104	DSF0000821892		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2018	404,442
							<b>P.S. 104 Total:</b>	<b>\$8,731,274</b>
27	Queens	Q105		<b>P.S. 105</b>				
				DSF0000789244		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	1,475,708
				DSF0000799426		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	6,663,779
			Q105	DSF0000822165		<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,471,537

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000789257	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2015	148,657
						INTERIOR:AUDITORIUM:Floor Finish		
					DSF0000799444	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	1,324,191
						FIXTURES:STUDENT:Drinking Fountain		
						FIXTURES:STUDENT:Sink And Fountain Combo Unit		
					DSF0000789250	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,891,218
						GROUNDING SYSTEM		
						PANEL BOARD		
			Q105		DSF0000789251	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	7,422,618
			Q105		DSF0000822167	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	1,550,043
						Ventilation		
						MOTOR STARTER/CONTACTOR		
			Q105		DSF0000822164	<b>State of Good Repair - System Replacements - Paved Area - Blacktop</b>	2015	2,993,681



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000812555	SITE:Drainage System for Asphalt SITE:Playgrounds:Pavement <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	161,979
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			Q105		DSF0000866207	Classroom Connectivity	2017	283,412
			Q105		DSF0000889479	IP Surveillance Camera Installation	2019	39,644
						<b>P.S. 105 Total:</b>		\$25,426,467
27	Queens	Q106		<b>P.S. 106</b>				
					DSF0000789267	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	2,166,097
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000789283	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	4,198,096
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
		Q106			DSF0000912397	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	122,624
					DSF0000798643	DOMESTIC WATER SYSTEM <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	1,320,459
					DSF0000812571	HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	195,629
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 106 Total:</b>	<b>\$8,002,905</b>
27	Queens	Q108		<b>P.S. 108</b>				
					DSF0000879196	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	11,149,540
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000879199	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	3,558,531
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR SOFFITS		
					DSF0000902076	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	38,017
			Q108		DSF0000902075	<b>State of Good Repair - System Replacements - Parapets</b>	2019	5,975,971
						EXTERIOR:PARAPETS		
					DSF0000879198	<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,519,263
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
					DSF0000812606	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	139,332
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
			Q108		DSF0000912414	<b>State of Good Repair - System Replacements - Windows</b>	2019	5,428,021
						EXTERIOR:WINDOWS		
							<b>P.S. 108 Total:</b>	<b>\$29,808,675</b>
27	Queens	Q114		<b>P.S. 114</b>				
			Q114		DSF0000798628	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,219,769

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q114	DSF0000798627		CLIMATE CONTROL SYSTEM <b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	5,220,228
			Q114	DSF0000798625		DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,270,633
				DSF0000798634		INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR <b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2015	407,756
				DSF0000799929		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	463,984
			Q114	DSF0000789386		DOMESTIC WATER SYSTEM <b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	3,289,107

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000789394	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2015	1,322,021
			Q114		DSF0000798626	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2015	5,865,334
			Q114		DSF0000889239	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	169,144
							<b>P.S. 114 Total:</b>	<b>\$19,227,976</b>
27	Queens	Q123		<b>P.S. 123</b>				
					DSF0000798490	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	233,133
			Q123		DSF0000821930	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,815,862
			Q123		DSF0000866030	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	182,908

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 123 Total:</b>	\$2,231,903
27	Queens	Q124		<b>P.S. 124</b>				
			Q124	DSF0000798317		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,887,918
			Q124	DSF0000789560		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	2,189,282
				DSF0000789561		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	807,024
			Q124	DSF0000799994		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	78,283
				DSF0000821720		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink	2016	114,482

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							<b>P.S. 124 Total:</b>	\$8,076,989
27	Queens	Q137		<b>M.S. 137</b>				
					DSF0000823577	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000891048	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
			Q137		DSF0000868100	IP Surveillance Camera Installation	2018	534,991
							<b>M.S. 137 Total:</b>	\$797,214
27	Queens	Q146		<b>P.S. 146</b>				
			Q146		DSF0000912514	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	61,578
					DSF0000799395	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,887,203
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000789978	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,127,587

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000799615	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	369,010
			Q146		DSF0000889667	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,478,941
					DSF0000789964	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	539,035
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
					DSF0000789974	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	2,075,446
						Ventilation		
						VENTILATION:EXHAUST FAN		
						VENTILATION:HEATING AND VENTILATING UNIT		
						VENTILATION:METAL DUCTWORK		
					DSF0000813260	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	197,233
						FIXTURES:STUDENT:Lavatory/Sink		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799397	FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent <b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2015	370,968
							<b>P.S. 146 Total:</b>	\$11,107,001
27	Queens	Q155		<b>P.S. 155</b>	DSF0000799620	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	169,438
			Q155		DSF0000844160	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,988,909
					DSF0000813418	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	268,283
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent <b>Other</b>		
					DSF0000775704	IP Surveillance Camera Installation	2015	528,794
							<b>P.S. 155 Total:</b>	\$2,955,424
27	Queens	Q180		<b>I.S. 323 (OLD IS 180)</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799995	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling	2015	511,256
					DSF0000798286	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,254,837
			Q323		DSF0000865949	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:DX Split System	2019	797,300
					DSF0000813825	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	258,070
			Q323		DSF0000866043	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	180,050

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q323		DSF0000880407	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2019	200,221
<b>I.S. 323 (OLD IS 180) Total:</b>								\$3,201,734
27	Queens	Q183		<b>P.S. 183</b>				
					DSF0000799433	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,339,372
					DSF0000799424	<b>State of Good Repair - Building Upgrade - Interior Spaces</b> INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	701,695
					DSF0000790575	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD	2015	486,893
			Q183		DSF0000790576	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	661,679

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System		
			Q183	DSF0000799867		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			Q183	DSF0000866044		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			Q183	DSF0000867042		IP Surveillance Camera Installation	2018	369,406
							<b>P.S. 183 Total:</b>	<b>\$5,805,496</b>
27	Queens	Q197		<b>P.S. 197</b>				
				DSF0000868230		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	309,643
			Q197	DSF0000880645		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	3,082,014
						EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
				DSF0000880647		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q197	DSF0000880643		<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,782,377
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000814075	<b>State of Good Repair - System Replacements - Toilets - Students</b>  FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	101,351
			Q197		DSF0000843798	<b>Other</b> Classroom Connectivity	2016	337,645
							<b>P.S. 197 Total:</b>	<b>\$7,805,530</b>
27	Queens	Q198		<b>I.S. 198</b>				
					DSF0000799423	<b>State of Good Repair - Building Upgrade - Climate Control</b>  CLIMATE CONTROL SYSTEM	2015	1,989,587
					DSF0000799422	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>  DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,885,050
					DSF0000799622	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	204,177
					DSF0000799419	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>  INTERIOR:STRUCTURAL:FLOOR STRUCTURE	2015	2,171,961

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799421	<b>State of Good Repair - System Replacements - Electrical Systems</b> GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD TRANSFORMER	2015	1,686,896
					DSF0000866934	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	3,808
					DSF0000790816	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	7,452,279
							<b>I.S. 198 Total:</b>	<b>\$17,393,758</b>
27	Queens	Q202		<b>I.S. 202</b>				
					DSF0000777515	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	77,546
					DSF0000814178	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING	2016	46,526
					DSF0000889332	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,880

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q202		DSF0000790901	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	32,796
							<b>I.S. 202 Total:</b>	\$158,748
27	Queens	Q207		<b>P.S. 207</b>				
			Q207		DSF0000845639	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	123,806
			Q207		DSF0000880807	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2018	400,444
							<b>P.S. 207 Total:</b>	\$524,250
27	Queens	Q210		<b>I.S. 210</b>				
					DSF0000798476	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	986,719
					DSF0000791033	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	2,112,076

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q210	DSF0000814295		<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	109,403
			Q210	DSF0000889240		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	384,518
				DSF0000868128		IP Surveillance Camera Installation	2018	518,827
							<b>I.S. 210 Total:</b>	<b>\$4,111,543</b>
27	Queens	Q215		<b>P.S. 215</b>				
				DSF0000791085		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	958,541
			Q215	DSF0000745409		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	1,697,159
				DSF0000821739		<b>State of Good Repair - System Replacements - Roofs</b>	2018	2,593,682
				DSF0000814351		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2015	103,202



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
FIXTURES:STUDENT:Urinal								
							<b>P.S. 215 Total:</b>	\$5,352,584
27	Queens	Q223		<b>P.S. 223</b>				
			Q223	DSF0000791211		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			Q223	DSF0000881015		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation AIR CONDITIONING:Chilled Water System:Central Station Air Handler AIR CONDITIONING:Chilled Water System:Fan Coil Unit MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork VENTILATION:Unit Ventilator	2018	679,185
			Q223	DSF0000889633		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 223 Total:</b>	\$925,657
27	Queens	Q225		<b>P.S. 225</b>				
				DSF0000791225		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	802,825

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
					DSF0000791229	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,142,195
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000800307	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	827,258
					DSF0000814477	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,173,086
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000791231	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,686,035
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
					DSF0000791232	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	3,541,270
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		

**P.S. 225 Total: \$12,172,669**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000881036	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	3,025,685
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000821696	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	1,221,523
						PUBLIC ADDRESS SYSTEM		
			Q226		DSF0000800309	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	4,807,711
					DSF0000881038	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	11,364,555
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
					DSF0000881040	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000881037	<b>State of Good Repair - System Replacements - Parapets</b>	2019	2,791,179
						EXTERIOR:COPING		
			Q226		DSF0000889634	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			Q226		DSF0000889483	IP Surveillance Camera Installation	2019	40,449
							<b>I.S. 226 Total:</b>	<b>\$23,658,394</b>
27	Queens	Q232		<b>P.S. 232</b>				
			Q232		DSF0000888970	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2019	10,324,367

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q232	DSF0000881100		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2019	2,567,651
			Q232	DSF0000881103		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2019	5,454,172
				DSF0000799626		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	126,179
			Q232	DSF0000881101		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> AUXILIARY SIGNAL/BELL SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly	2019	1,853,787
			Q232	DSF0000891023		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	1,155,441
			Q232	DSF0000791320		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	98,683
			Q232	DSF0000889241		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	169,820

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 232 Total:</b>	\$21,750,100
27	Queens	Q253		<b>P.S. 253</b>				
						<i>Other</i>		
			Q253	DSF0000866255		New/Retrofit Telephone/Intercom Systems	2017	203,072
							<b>P.S. 253 Total:</b>	\$203,072
27	Queens	Q254		<b>P.S. 254</b>				
						DSF0000911910		
						<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	286,649
			Q254	DSF0000820911		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	2,322,173
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
			Q254	DSF0000891053		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	192,500
			Q254	DSF0000820910		<i>State of Good Repair - System Replacements - Parapets</i>	2017	3,141,350
						EXTERIOR:PARAPETS		
			Q254	DSF0000820913		<i>State of Good Repair - System Replacements - Paved Area - Concrete</i>	2017	1,302,837
						SITE:RETAINING WALLS		
			Q254	DSF0000797689		<i>State of Good Repair - System Replacements - Roofs</i>	2017	2,881,654
						EXTERIOR:ROOFING:Roofing		
						<i>Other</i>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q254	DSF0000822068		New/Retrofit Telephone/Intercom Systems	2015	206,252
							<b>P.S. 254 Total:</b>	\$10,333,415
27	Queens	Q262		<b>P.S. 262</b>				
						<i>Other</i>		
			Q306	DSF0000889488		IP Surveillance Camera Installation	2019	37,632
							<b>P.S. 262 Total:</b>	\$37,632
27	Queens	Q273		<b>P.S. 273</b>				
						<i>Other</i>		
			Q273	DSF0000889490		IP Surveillance Camera Installation	2019	38,705
							<b>P.S. 273 Total:</b>	\$38,705
27	Queens	Q806		<b>P.S. 106 MINISCHOOL</b>				
				DSF0000798645		<i>State of Good Repair - System Replacements - Paved Area - Blacktop</i>	2017	3,646,467
							<b>P.S. 106 MINISCHOOL Total:</b>	\$3,646,467
27	Queens	Q907		<b>P.S. 43 ANNEX</b>				
				DSF0000800332		<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	4,154,869
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000800331		<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2015	1,015,856

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						<i>Other</i>		
			Q043		DSF0000867143	New/Retrofit Telephone/Intercom Systems	2018	103,170
							<b>P.S. 43 ANNEX Total:</b>	<b>\$5,273,895</b>
28	Queens	Q003		<b>P.S. 303</b>				
					DSF0000799606	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	116,660
						<i>Other</i>		
			Q303		DSF0000889472	IP Surveillance Camera Installation	2019	37,766
							<b>P.S. 303 Total:</b>	<b>\$154,426</b>
28	Queens	Q008		<b>J.H.S. 8</b>				
					DSF0000787765	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2015	224,354
						INTERIOR:GYMNASIUM:Walls		
			Q008		DSF0000855092	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	149,346
						HEATING:Hydronic Heating:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
						<i>Other</i>		
			Q008		DSF0000889473	IP Surveillance Camera Installation	2019	43,140
							<b>J.H.S. 8 Total:</b>	<b>\$416,840</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
28	Queens	Q030		<b>P.S. 30</b>				
			Q030		DSF0000788068	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,362,872
					DSF0000799703	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	143,132
			Q030		DSF0000800310	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,457,676
			Q030		DSF0000821679	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	1,198,164
			Q030		DSF0000811388	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
					DSF0000799997	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	3,119,321
			Q030		DSF0000811385	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	3,260,612
					DSF0000811390	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	133,020
							<b>P.S. 30 Total:</b>	<b>\$11,819,583</b>
28	Queens	Q040		<b>P.S. 40</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000833666	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump	2017	925,208
			Q040		DSF0000800317	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	2,214,108
					DSF0000788263	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	9,732,974
			Q040		DSF0000811574	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	122,164
<b>P.S. 40 Total:</b>								\$12,994,454
28	Queens	Q048		<b>P.S. 48</b>				
					DSF0000408987	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	3,566,485
					DSF0000788373	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	732,456

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q075	DSF0000801073		<b>State of Good Repair - Building Upgrade - Reinforcing Support Elements</b> INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS	2018	113,884
			Q075	DSF0000878295		<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain FIXTURES:Student:Sink And Fountain Combo Unit	2018	42,876
			Q075	DSF0000855709		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2018	4,273,418
			Q075	DSF0000855707		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2018	2,004,232
							<b>P.S. 48 Total:</b>	\$10,733,351
28	Queens	Q054		<b>P.S. 54</b>				
				DSF0000811776		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	168,158
						<b>Other</b>		
			Q054	DSF0000889243		New/Retrofit Telephone/Intercom Systems	2018	181,995
							<b>P.S. 54 Total:</b>	\$350,153

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
28	Queens	Q055		<b>P.S. 55</b>				
					DSF0000798475	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	6,263,716
					DSF0000788465	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2019	1,781,919
					DSF0000788467	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	581,249
			Q055		DSF0000754451	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2015	1,880,991
			Q055		DSF0000891066	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
			Q055		DSF0000865913	Classroom Connectivity	2017	344,155
			Q055		DSF0000867156	New/Retrofit Telephone/Intercom Systems	2018	189,741
							<b>P.S. 55 Total:</b>	<b>\$11,234,271</b>
28	Queens	Q072		<b>J.H.S. 72</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821665	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	455,580
					DSF0000812057	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE LAB:EMERGENCY SHUT-OFF POWER SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2018	3,175,388
					DSF0000777508	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	213,963
					DSF0000868220	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	324,290
			Q072		DSF0000889621	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
			Q072		DSF0000889477	<b>Other</b> IP Surveillance Camera Installation	2019	45,644

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>J.H.S. 72 Total:</b>	\$4,429,657
28	Queens	Q080		<b>P.S. 80</b>				
					DSF0000788856	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,120,855
			Q080		DSF0000788862	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			Q080		DSF0000891069	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000812178	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	104,000
							<b>P.S. 80 Total:</b>	\$1,449,035
28	Queens	Q082		<b>P.S. 82</b>				
					DSF0000788896	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	374,065

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000844036	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	1,574,035
			Q082		DSF0000891071	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q082		DSF0000866097	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,104,431
						EXTERIOR:PARAPETS		
			Q082		DSF0000856222	<b>State of Good Repair - System Replacements - Roofs</b>	2018	521,382
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
			Q082		DSF0000866205	Classroom Connectivity	2017	22,121
							<b>P.S. 82 Total:</b>	<b>\$5,788,534</b>
28	Queens	Q099		<b>P.S. 99</b>				
			Q099		DSF0000834567	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	2,795,753
			Q099		DSF0000789174	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,810
			Q099		DSF0000834578	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	92,223
						Air Conditioning Split System		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Water Cooled Chiller AIR CONDITIONING:Condenser Water Piping AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Cooling Tower AIR CONDITIONING:Return Fan		
			Q099	DSF0000866298		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2018	1,779,850
						<b>Other</b>		
			Q099	DSF0000867160		New/Retrofit Telephone/Intercom Systems	2018	144,754
							<b>P.S. 99 Total:</b>	<b>\$4,863,390</b>
28	Queens	Q101		<b>P.S. 101</b>				
					DSF0000789202	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	720,042
					DSF0000912159	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	3,248
							<b>P.S. 101 Total:</b>	<b>\$723,290</b>
28	Queens	Q117		<b>P.S. 117</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798488	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	687,780
			Q117		DSF0000879329	<b>State of Good Repair - System Replacements - Electrical Systems</b> SERVICE SWITCH	2019	101,587
			Q117		DSF0000879330	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS FIRED FURNACE GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Pressure Booster HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating	2019	129,069
			Q117		DSF0000891076	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q117		DSF0000867157	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	258,236
			Q117		DSF0000868098	IP Surveillance Camera Installation	2019	429,642



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 117 Total:</b>	<b>\$1,798,814</b>
28	Queens	Q121		<b>P.S. 121</b>				
					DSF0000902289	<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT	2019	197,439
			Q121		DSF0000912452	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	805,933
			Q121		DSF0000822677	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2018	174,943
			Q121		DSF0000821931	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	1,527,972
					DSF0000879403	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2019	6,127,871
			Q121		DSF0000902285	<b>State of Good Repair - System Replacements - Fencing</b> SITE:FENCES	2019	817,514
					DSF0000879401	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	381,884
					DSF0000879400	<b>State of Good Repair - System Replacements - Roofs</b>	2019	2,311,562

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOF:Roofing		
			Q121	DSF0000889623		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
				DSF0000879402		<b>State of Good Repair - System Replacements - Windows</b>	2019	10,244,230
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			Q121	DSF0000843794		Classroom Connectivity	2016	266,427
							<b>P.S. 121 Total:</b>	<b>\$23,070,567</b>
28	Queens	Q139		<b>P.S. 139</b>				
			Q139	DSF0000789815		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,166,466
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			Q139	DSF0000879729		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	124,775
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						HEATING:Radiator/Convactor/Fin Tube		
						HEATING:Steam Heating		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:Unit Heater/Cabinet Heater		
					DSF0000891049	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q139		DSF0000821927	<b>State of Good Repair - System Replacements - Roofs</b>	2017	1,371,010
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			Q139		DSF0000889625	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
					DSF0000867027	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2018	105,148
			Q139		DSF0000889268	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	341,270
							<b>P.S. 139 Total:</b>	<b>\$3,515,961</b>
28	Queens	Q140		<b>P.S. 140</b>				
					DSF0000789829	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,054,736
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q140		DSF0000813129	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:TOILET ROOMS - STUDENTS		
			Q140	DSF0000866035		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 140 Total:</b>	\$1,370,879
28	Queens	Q144		<b>P.S. 144</b>				
			Q144	DSF0000888775		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	185,446
			Q144	DSF0000866130		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
			Q144	DSF0000866037		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	429,587
						<i>Other</i>		
			Q144	DSF0000866230		New/Retrofit Telephone/Intercom Systems	2017	144,689
							<b>P.S. 144 Total:</b>	\$837,412
28	Queens	Q157		<b>J.H.S. 157</b>				
			Q157	DSF0000813455		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	141,178
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							<b>J.H.S. 157 Total:</b>	\$141,178

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
28	Queens	Q160		<b>P.S. 160</b>				
					DSF0000813516	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,413,298
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000790225	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	732,455
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000801051	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	6,340,796
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000880147	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000822251	<b>State of Good Repair - System Replacements - Parapets</b>	2017	3,432,912
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000822250	<b>State of Good Repair - System Replacements - Roofs</b>	2017	1,453,106
						EXTERIOR:ROOFING:Roofing		
						<b>Other</b>		
			Q160		DSF0000867166	New/Retrofit Telephone/Intercom Systems	2018	175,568
							<b>P.S. 160 Total:</b>	<b>\$13,740,635</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
28	Queens	Q161		<b>P.S. 161</b>				
			Q161	DSF0000912480		<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2019	200,000
							<b>P.S. 161 Total:</b>	\$200,000
28	Queens	Q174		<b>P.S. 174</b>				
				DSF0000799621		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	247,313
			Q174	DSF0000790435		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	45,137
						<i>Other</i>		
			Q174	DSF0000889244		New/Retrofit Telephone/Intercom Systems	2018	168,812
							<b>P.S. 174 Total:</b>	\$461,262
28	Queens	Q175		<b>P.S. 175</b>				
				DSF0000912518		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	71,382
						EMERGENCY LIGHT/EXIT LIGHT PANEL		
						EMERGENCY LIGHTING		
						EXIT LIGHT		
						EXIT/EMERGENCY LIGHT		
				DSF0000790447		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	766,949
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000891032	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,443,962
					DSF0000880334	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000767727	<b>State of Good Repair - System Replacements - Parapets</b>	2015	3,731,279
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000767726	<b>State of Good Repair - System Replacements - Roofs</b>	2015	2,505,907
						EXTERIOR:ROOFING:Roofing		
					DSF0000767728	<b>State of Good Repair - System Replacements - Windows</b>	2015	3,001,904
						EXTERIOR:WINDOWS		
							<b>P.S. 175 Total:</b>	<b>\$11,713,883</b>
28	Queens	Q190		<b>J.H.S. 190</b>				
			Q190		DSF0000844711	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	863,049
					DSF0000777514	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	133,503
					DSF0000880533	<b>State of Good Repair - System Replacements - Roofs</b>	2019	3,370,038
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
			Q190		DSF0000868102	IP Surveillance Camera Installation	2018	397,645

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>J.H.S. 190 Total:</b>	\$4,764,235
28	Queens	Q196		<b>P.S. 196</b>				
					DSF0000798336	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	573,570
					DSF0000745120	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2015	2,229,732
			Q196		DSF0000799792	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000745119	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2015	1,833,559
					DSF0000745118	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,248,141
							<b>P.S. 196 Total:</b>	\$6,916,682
28	Queens	Q206		<b>P.S. 206</b>				
					DSF0000790975	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	551,762



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000814242	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
							<b>P.S. 206 Total:</b>	\$696,548
28	Queens	Q217		<b>I.S. 217</b>				
					DSF0000911911	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	288,484
			Q217		DSF0000798373	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	5,951,398
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000791125	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,788,642
						CLIMATE CONTROL SYSTEM		
					DSF0000814392	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			Q217		DSF0000865918	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	296,575

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q217	DSF0000912231		IP Surveillance Camera Installation	2019	69,702
							<b>I.S. 217 Total:</b>	\$9,496,152
28	Queens	Q220		<b>P.S. 220</b>				
			Q220	DSF0000866046		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 220 Total:</b>	\$214,792
28	Queens	Q276		<b>THE WILLIAM WORDSWORTH EDUCATIONAL COMPLEX</b>				
						<i>Other</i>		
			Q048	DSF0000889491		IP Surveillance Camera Installation	2019	40,315
							<b>THE WILLIAM WORDSWORTH EDUCATIONAL COMPLEX Total:</b>	\$40,315
28	Queens	Q277		<b>PS 182 SAMANTHA SMITH</b>				
				DSF0000911909		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	230,234
						<i>Other</i>		
			Q182	DSF0000912232		IP Surveillance Camera Installation	2019	69,914
							<b>PS 182 SAMANTHA SMITH Total:</b>	\$300,148
28	Queens	Q278		<b>PS 182 ANNEX</b>				
						<i>Other</i>		
			Q182	DSF0000867167		New/Retrofit Telephone/Intercom Systems	2018	98,425
							<b>PS 182 ANNEX Total:</b>	\$98,425

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
29	Queens	Q015		<b>P.S. 15</b>				
					DSF0000787871	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,058,323
			Q015		DSF0000855223	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Floor Finish	2018	10,345
			Q015		DSF0000889008	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
			Q015		DSF0000843792	<b>Other</b> Classroom Connectivity	2016	247,027
							<b>P.S. 15 Total:</b>	<b>\$1,404,679</b>
29	Queens	Q033		<b>P.S. 33</b>				
					DSF0000788132	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	920,286

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q033		DSF0000843952	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2018	1,787,826
					DSF0000811451	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	5,295,118
						EXTERIOR:EXTERIOR WALLS		
					DSF0000788138	<b>State of Good Repair - System Replacements - Parapets</b>	2017	605,278
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000788137	<b>State of Good Repair - System Replacements - Roofs</b>	2017	4,658,483
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 33 Total:</b>	\$13,266,991
29	Queens	Q034		<b>P.S. 34</b>				
					DSF0000788154	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	724,352
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000900927	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	7,690,133
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
			Q034		DSF0000911865	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	247,307

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Air Conditioning Split System AIR CONDITIONING:Window Type A/C		
					DSF0000900925	<b>State of Good Repair - System Replacements - Roofs</b>	2019	801,087
			Q034		DSF0000866018	EXTERIOR:ROOF:Roofing <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
					DSF0000912552	<b>State of Good Repair - System Replacements - Windows</b>	2019	385,368
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			Q034		DSF0000843800	Classroom Connectivity	2016	307,493
							<b>P.S. 34 Total:</b>	\$10,308,469
29	Queens	Q035		<b>P.S. 35</b>				
			Q035		DSF0000833597	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	396,519
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
					DSF0000912275	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	7,378
							<b>P.S. 35 Total:</b>	\$403,897
29	Queens	Q036		<b>P.S. 36</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q233	DSF0000798270		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	5,595,543
			Q036	DSF0000788193		<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	1,229,614
				DSF0000788195		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	714,516
				DSF0000811514		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	194,856

**P.S. 36 Total: \$7,734,529**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798349	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	6,071,238
					DSF0000788217	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2018	6,014,302
					DSF0000811529	<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b> CONVEYING:ASH HOIST CONVEYING:ELEVATORS	2017	277,424
					DSF0000777242	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	6,798,515
					DSF0000833629	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	649,086
					DSF0000788218	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	1,315,178
					DSF0000844042	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	7,543,335
			Q037		DSF0000811536	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
					DSF0000833628	<b>State of Good Repair - System Replacements - Parapets</b>	2017	3,109,253

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:COPING EXTERIOR:PARAPETS		
							<b>P.S. 37 Total:</b>	\$31,923,117
29	Queens	Q038		<b>P.S. 38</b>				
			Q038	DSF0000800311		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2016	2,183,589
						<b>Other</b>		
			Q038	DSF0000867168		New/Retrofit Telephone/Intercom Systems	2018	147,766
							<b>P.S. 38 Total:</b>	\$2,331,355
29	Queens	Q052		<b>P.S. 52</b>				
			Q052	DSF0000788418		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	1,828,636
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000788417		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	766,105
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q052	DSF0000821932		<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,390,531
			Q052	DSF0000865816		<b>State of Good Repair - System Replacements - Parapets</b>	2017	543,277
						EXTERIOR:PARAPETS		



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000811745	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2018	234,201
							<b>P.S. 52 Total:</b>	\$4,762,750
29	Queens	Q059		<b>I.S. 59</b>				
					DSF0000801064	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	550,897
			Q059		DSF0000868063	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	545,946
			Q059		DSF0000888960	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	629,325
			Q176		DSF0000821781	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2015	33,343
			Q059		DSF0000845587	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Technology	2018	355,000
					DSF0000798357	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	701,290

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000868217	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	57,190
			Q059		DSF0000866127	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
						<b>Other</b>		
					DSF0000867053	IP Surveillance Camera Installation	2018	568,168
							<b>I.S. 59 Total:</b>	<b>\$3,518,849</b>
29	Queens	Q095		<b>P.S. 95</b>				
					DSF0000799705	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	143,274
					DSF0000891051	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,057,184
					DSF0000812410	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	258,126
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 95 Total:</b>	<b>\$1,458,584</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
29	Queens	Q109		<b>I.S. 109</b>				
					DSF0000799611	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	222,613
						<b>Other</b>		
			Q109		DSF0000889480	IP Surveillance Camera Installation	2019	39,644
							<b>I.S. 109 Total:</b>	<b>\$262,257</b>
29	Queens	Q116		<b>P.S. 116</b>				
					DSF0000789417	<b>State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs</b>	2016	3,788,490
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
					DSF0000766746	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	5,875,827
						EXTERIOR:EXTERIOR WALLS		
			Q116		DSF0000891075	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						HEATING:Steam Heating		
					DSF0000800108	<b>State of Good Repair - System Replacements - Parapets</b>	2016	3,067,425
						EXTERIOR:PARAPETS		
					DSF0000789420	<b>State of Good Repair - System Replacements - Roofs</b>	2016	1,317,238
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			Q116		DSF0000789425	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	191,875

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 116 Total:</b>	\$14,433,355
29	Queens	Q118		<b>P.S. 118</b>				
					DSF0000789451	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	949,172
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000799822	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	221,280
					DSF0000812756	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	126,621
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 118 Total:</b>	\$1,297,073

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
29	Queens	Q131		<b>P.S. 131</b>				
					DSF0000812978	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	2,880,998
					DSF0000812977	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	728,514
					DSF0000812976	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2017	3,031,224
			Q131		DSF0000866032	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 131 Total:</b>	<b>\$6,793,465</b>
29	Queens	Q132		<b>P.S. 132</b>				
			Q132		DSF0000857028	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	800,291
					DSF0000789691	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	724,942

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866925	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	4,287
			Q132		DSF0000835085	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	2,911,693
			Q132		DSF0000857031	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2018	1,042,631
			Q132		DSF0000857030	EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2018	1,787,998
			Q132		DSF0000889624	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>P.S. 132 Total:</b>	<b>\$7,486,634</b>
29	Queens	Q134		<b>P.S. 134</b>				
					DSF0000789732	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	919,200
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 134 Total:</b>	<b>\$919,200</b>
29	Queens	Q136		<b>P.S. 136</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000789771	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,125,122
			Q136		DSF0000866033	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 136 Total:</b>	\$1,277,851
29	Queens	Q138		<b>P.S. 138</b>				
					DSF0000912403	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	27,310
					DSF0000868224	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	683,827
			Q138		DSF0000866034	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			Q138		DSF0000867158	New/Retrofit Telephone/Intercom Systems	2018	263,746
							<b>P.S. 138 Total:</b>	\$1,189,675
29	Queens	Q147		<b>P.S. 147</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000789981	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,352,483
					DSF0000879899	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q147		DSF0000866038	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 147 Total:</b>	<b>\$1,697,712</b>
29	Queens	Q156		<b>P.S. 156</b>				
			Q289		DSF0000911828	<b>Educational Enhancements - Educational Enhancements - Library Upgrade</b>	2019	500,000
					DSF0000790141	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	946,112
			Q156		DSF0000843953	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	4,386,351
			Q156		DSF0000889628	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 156 Total:</b>	\$6,047,255
29	Queens	Q176		<b>P.S. 176</b>				
					DSF0000912322	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	30,314
						EMERGENCY LIGHTING		
						EXIT LIGHT		
					DSF0000868228	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	119,230
						<b>Other</b>		
			Q176		DSF0000866209	Classroom Connectivity	2017	196,939
							<b>P.S. 176 Total:</b>	\$346,483
29	Queens	Q181		<b>P.S. 181</b>				
					DSF0000844112	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	295,854
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000821590	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2017	3,606,729
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
					DSF0000798325	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	661,864
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000866932	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	7,373
					DSF0000835911	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	1,279,301
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY		
					DSF0000844111	<b>State of Good Repair - System Replacements - Parapets</b>	2017	1,171,487
						EXTERIOR:PARAPETS		
					DSF0000835909	<b>State of Good Repair - System Replacements - Roofs</b>	2017	559,447
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
							<b>P.S. 181 Total:</b>	\$7,582,055
29	Queens	Q192		<b>I.S. 192</b>				
					DSF0000821676	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	1,595,424
					DSF0000798358	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	840,308
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>I.S. 192 Total:</b>	\$2,435,732

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
29	Queens	Q195		<b>P.S. 195</b>				
					DSF0000798332	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	718,956
					DSF0000814054	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	277,267
							<b>P.S. 195 Total:</b>	\$996,223
29	Queens	Q208		<b>P.S./I.S. 208</b>				
			Q208		DSF0000864728	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	68,970
			Q208		DSF0000912507	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	74,424
			Q208		DSF0000889482	<b>Other</b> IP Surveillance Camera Installation	2019	40,047
							<b>P.S./I.S. 208 Total:</b>	\$183,441
29	Queens	Q231		<b>I.S. 231 (TANDEM Q251)</b>				
					DSF0000799625	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	204,545

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 231 (TANDEM Q251) Total:</b>	<b>\$204,545</b>
29	Queens	Q238		<b>I.S. 238</b>				
					DSF0000865864	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	180,506
					DSF0000777516	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	131,559
					DSF0000814600	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,667,247
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			Q238		DSF0000814621	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
						CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent INTERIOR:CAFETERIA:Ceiling INTERIOR:CAFETERIA:Floor Finish		
					DSF0000868234	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	664,489
			Q238		DSF0000791361	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	118,318
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							<b>I.S. 238 Total:</b>	\$3,241,185
29	Queens	Q251		<b>P.S. 251 (TANDEM Q231)</b>				
						<i>Other</i>		
			Q251	DSF0000889486		IP Surveillance Camera Installation	2019	40,785
							<b>P.S. 251 (TANDEM Q231) Total:</b>	\$40,785
29	Queens	Q263		<b>P.S. /I.S 295</b>				
						<i>Other</i>		
			Q295	DSF0000889245		New/Retrofit Telephone/Intercom Systems	2018	298,963
				DSF0000868134		IP Surveillance Camera Installation	2019	333,459
							<b>P.S. /I.S 295 Total:</b>	\$632,422
29	Queens	Q268		<b>P.S. 268</b>				
				DSF0000844715		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	75,541
							<b>P.S. 268 Total:</b>	\$75,541
29	Queens	Q270		<b>P.S. 270</b>				
			Q270	DSF0000797701		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	836,517
						EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
			Q270	DSF0000800111		<i>State of Good Repair - System Replacements - Parapets</i>	2017	3,724,146
			Q270	DSF0000820925		<i>State of Good Repair - System Replacements - Roofs</i>	2017	2,286,943
						EXTERIOR:ROOFING:Roofing		
			Q270	DSF0000889636		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
							<b>P.S. 270 Total:</b>	<b>\$7,062,398</b>
29	Queens	Q357		<b>P.S. 36 GYM ANNEX</b>				
			Q036	DSF0000889562		<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,838,585
							<b>P.S. 36 GYM ANNEX Total:</b>	<b>\$10,838,585</b>
29	Queens	Q836		<b>P.S. 36 MINISCHOOL</b>				
			Q036	DSF0000822094		<i>State of Good Repair - System Replacements - Roofs</i>	2016	254,817
						EXTERIOR:ROOFING:Roofing		
							<b>P.S. 36 MINISCHOOL Total:</b>	<b>\$254,817</b>
29	Queens	Q892		<b>P.S. 892</b>				
			Q360	DSF0000844010		<i>Playground Redevelopment</i>	2016	450,210
							<b>P.S. 892 Total:</b>	<b>\$450,210</b>
30	Queens	Q002		<b>P.S. 2</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000787698	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	752,349
					DSF0000889300	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	693,323
			Q002		DSF0000811038	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	152,827
							<b>P.S. 2 Total:</b>	<b>\$1,598,499</b>
30	Queens	Q010		<b>I.S. 10</b>				
			Q010		DSF0000912478	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
					DSF0000777505	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	108,908
					DSF0000787795	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	842,316

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q010		DSF0000742213	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,812,391
					DSF0000868212	FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM <b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	344,268
					DSF0000889007	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
						<b>Other</b>		
					DSF0000867052	IP Surveillance Camera Installation	2018	342,233
							<b>I.S. 10 Total:</b>	<b>\$3,739,100</b>
30	Queens	Q011		<b>P.S. 11</b>				
					DSF0000799821	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	165,233
							<b>P.S. 11 Total:</b>	<b>\$165,233</b>
30	Queens	Q069		<b>P.S. 69</b>				
			Q069		DSF0000856028	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	283,666



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799609	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	110,496
			Q069		DSF0000834091	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	2,357,296
			Q069		DSF0000865951	EXTERIOR:CHIMNEY <i>State of Good Repair - System Replacements - Floors</i>	2018	654,775
			Q069		DSF0000865950	INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish <i>State of Good Repair - System Replacements - Roofs</i>	2018	675,836
						EXTERIOR:ROOF:Roofing		
							<b>P.S. 69 Total:</b>	\$4,082,069
30	Queens	Q070		<b>P.S. 70</b>				
					DSF0000788685	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	1,029,178
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							<b>P.S. 70 Total:</b>	\$1,029,178
30	Queens	Q076		<b>P.S. 76</b>				
			Q076		DSF0000866025	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 76 Total:</b>	\$214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
30	Queens	Q084		<b>P.S. 84</b>				
					DSF0000812234	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	101,454
			Q084		DSF0000843643	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	190,306
			Q084		DSF0000889246	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	165,116
					DSF0000867054	IP Surveillance Camera Installation	2018	409,458
							<b>P.S. 84 Total:</b>	<b>\$866,334</b>
30	Queens	Q085		<b>P.S. 85</b>				
					DSF0000788936	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	665,485

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q085		DSF0000752879	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	815,872
					DSF0000775650	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	657,575
					DSF0000800060	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,393,857
					DSF0000834339	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2017	164,908
			Q085		DSF0000866252	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	185,233
					DSF0000867064	IP Surveillance Camera Installation	2018	350,169
							<b>P.S. 85 Total:</b>	<b>\$4,233,099</b>
30	Queens	Q111		<b>P.S. 111</b>				
			Q111		DSF0000821782	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2015	33,343

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
					DSF0000856663	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	2,166,358
						GROUNDING SYSTEM LIGHTNING PROTECTION PANEL BOARD SERVICE SWITCH SWITCHBOARD		
			Q111		DSF0000843648	<b>State of Good Repair - System Replacements - Kitchen Areas</b>	2017	7,149,323
					DSF0000812649	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	153,694
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							<b>P.S. 111 Total:</b>	<b>\$9,502,718</b>
30	Queens	Q112		<b>P.S. 112</b>				
					DSF0000789357	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	786,662
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000868223	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	44,477

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q112	DSF0000879255		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	1,366,039
			Q112	DSF0000891074		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING:Steam Heating	2019	192,500
				DSF0000879254		<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	3,422,293
			Q112	DSF0000879253		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	3,487,871
			Q112	DSF0000866028		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
							<b>P.S. 112 Total:</b>	<b>\$9,452,571</b>
30	Queens	Q122		<b>P.S. 122</b>				
				DSF0000789518		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,286,924
			Q122	DSF0000891077		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000867065	IP Surveillance Camera Installation	2018	337,076
							<b>P.S. 122 Total:</b>	\$1,816,500
30	Queens	Q126		<b>I.S. 126</b>				
					DSF0000799613	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	251,865
					DSF0000799823	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	203,595
			Q126		DSF0000812900	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	150,000
			Q126		DSF0000843801	<b>Other</b> Classroom Connectivity	2016	398,364
					DSF0000867066	IP Surveillance Camera Installation	2018	468,295
							<b>I.S. 126 Total:</b>	\$1,472,119
30	Queens	Q127		<b>P.S. 127</b>				
					DSF0000798478	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	992,128

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q127	DSF0000722711		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	7,919,844
				DSF0000753074		EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Parapets</b>	2015	2,774,298
			Q127	DSF0000866031		EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 127 Total:</b>	\$11,901,062
30	Queens	Q141		<b>I.S. 141</b>				
				DSF0000799614		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	242,836
				DSF0000879767		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
			Q141	DSF0000889010		<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
			Q141	DSF0000789856		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	147,528
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							<b>I.S. 141 Total:</b>	\$671,848
30	Queens	Q145		<b>I.S. 145</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000911912	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	315,017
					DSF0000777511	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2016	165,784
					DSF0000798276	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	7,301,414
					DSF0000789941	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2017	3,567,654
						<b>Other</b>		
			Q145		DSF0000889543	IP Surveillance Camera Installation	2019	39,443
							<b>I.S. 145 Total:</b>	<b>\$11,389,312</b>
30	Queens	Q148		<b>P.S. 148</b>				
					DSF0000879919	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	1,496,428
			Q148		DSF0000866131	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000879918	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	3,421,320



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000813299	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	150,000
							<b>P.S. 148 Total:</b>	\$5,145,438
30	Queens	Q149		<b>P.S. 149</b>				
					DSF0000844710	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	129,931
					DSF0000777512	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	126,607
					DSF0000799616	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	219,070
					DSF0000866927	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	9,110
							<b>P.S. 149 Total:</b>	\$484,718
30	Queens	Q150		<b>P.S. 150</b>				
					DSF0000868226	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	416,650
					DSF0000813332	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2017	169,895

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 150 Total:</b>	<b>\$586,545</b>
30	Queens	Q151		<b>P.S. 151</b>				
			Q151		DSF0000866742	<i>Playground Redevelopment</i>	2018	1,019,277
					DSF0000790055	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2017	1,579,560
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799617	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	126,270
			Q151		DSF0000866094	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2018	6,136,494
					DSF0000813349	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	1,274,770
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
					DSF0000813348	<i>State of Good Repair - System Replacements - Parapets</i>	2017	1,308,782
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000813347	<i>State of Good Repair - System Replacements - Roofs</i>	2017	2,088,114
						EXTERIOR:ROOFING:Roofing		
			Q151		DSF0000822119	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	173,873
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			Q151		DSF0000866208	Classroom Connectivity	2017	40,040
					DSF0000867068	IP Surveillance Camera Installation	2019	294,864
							<b>P.S. 151 Total:</b>	<b>\$14,042,044</b>
30	Queens	Q152		<b>P.S. 152</b>				
			Q152		DSF0000790080	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	140,439
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
							<b>P.S. 152 Total:</b>	<b>\$140,439</b>
30	Queens	Q166		<b>P.S. 166</b>				
					DSF0000798494	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	831,103
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000889309	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	4,672

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 166 Total:</b>	<b>\$835,775</b>
30	Queens	Q171		<b>P.S. 171</b>				
					DSF0000798323	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	926,373
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000880268	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		
			Q171		DSF0000889248	New/Retrofit Telephone/Intercom Systems	2018	213,233
			Q171		DSF0000867039	IP Surveillance Camera Installation	2018	335,139
							<b>P.S. 171 Total:</b>	<b>\$1,667,245</b>
30	Queens	Q204		<b>I.S. 204</b>				
			Q204		DSF0000912481	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	200,000
					DSF0000868290	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	147,719
			Q204		DSF0000889662	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2019	143,472
						INTERIOR:GYMNASIUM:Ceiling		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799829	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	265,759
			Q204		DSF0000866045	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
						<i>Other</i>		
			Q204		DSF0000865917	New/Retrofit Telephone/Intercom Systems	2017	335,736
			Q204		DSF0000867048	IP Surveillance Camera Installation	2018	598,741
							<b>I.S. 204 Total:</b>	<b>\$1,844,156</b>
30	Queens	Q222		<b>P.S. 222 (ECC)</b>				
			Q222		DSF0000889324	<i>State of Good Repair - System Replacements - Domestic Piping</i>	2018	66,273
			Q222		DSF0000889574	<i>System Expansion - New Physical Education Facilities - Playgrounds</i>	2019	4,707,735
							<b>P.S. 222 (ECC) Total:</b>	<b>\$4,774,008</b>
30	Queens	Q227		<b>I.S. 227</b>				
					DSF0000801062	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,269,541
					DSF0000801065	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,722,611
					DSF0000799624	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	184,378
			Q227		DSF0000889635	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>I.S. 227 Total:</b>	<b>\$3,391,322</b>
30	Queens	Q230		<b>I.S. 230</b>				
			Q230	DSF0000821607		<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2017	364,518
				DSF0000823578		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	69,723
							<b>I.S. 230 Total:</b>	<b>\$434,241</b>
30	Queens	Q234		<b>P.S. 234</b>				
				DSF0000865905		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	254,525
				DSF0000823579		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	69,723
			Q234	DSF0000891047		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	192,500
						<b>Other</b>		
			Q234	DSF0000865919		Classroom Connectivity	2017	276,909
			Q234	DSF0000867049		IP Surveillance Camera Installation	2018	456,615
							<b>P.S. 234 Total:</b>	<b>\$1,250,272</b>
30	Queens	Q280		<b>P.S. 280</b>				
			Q280	DSF0000889576		<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2019	1,177,088

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 280 Total:</b>	\$1,177,088
30	Queens	Q292		<b>P.S. 92</b>				
			Q092	DSF0000866321		<i>Interior Spaces</i>	2019	1,500,000
				DSF0000791379		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	107,197
				DSF0000745712		<i>State of Good Repair - System Replacements - Windows</i>	2015	4,670,821
EXTERIOR:WINDOWS								
							<b>P.S. 92 Total:</b>	\$6,278,018
30	Queens	Q397		<b>PRE-K CENTER @ 32-52 37TH STREET</b>				
				DSF0000889279		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	400,000
						Air Conditioning Split System		
			Q389	DSF0000889637		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2019	214,792
<b>PRE-K CENTER @ 32-52 37TH STREET Total:</b>								\$614,792
30	Queens	Q797		<b>PS 150 ANNEX</b>				
						<i>Other</i>		
			Q150	DSF0000889247		New/Retrofit Telephone/Intercom Systems	2018	102,363
							<b>PS 150 ANNEX Total:</b>	\$102,363
33Q	Queens	Q800		<b>DOE ADMINISTRATIVE / STUDENT SERVICES</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777531	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	155,273
					DSF0000792074	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,846,181
<b>DOE ADMINISTRATIVE / STUDENT SERVICES Total:</b>								\$2,001,454
33Q	Queens	Q801		<b>OSSS / DSF</b>				
			QSFS		DSF0000801052	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	91,439
			Q974		DSF0000799869	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
<b>OSSS / DSF Total:</b>								\$123,098
33Q	Queens	Q998		<b>NYC SCHOOL CONSTR. AUTHORITY</b>				
			Q998		SCA0000055706	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2019	10,524
					DSF0000844041	<b>Domestic Piping</b>	2017	13,448,571
					DSF0000844121	<b>Domestic Piping</b>	2017	2,384,089
<b>NYC SCHOOL CONSTR. AUTHORITY Total:</b>								\$15,843,184
75Q	Queens	Q009		<b>P.S. 9 (W REED SCHOOL)</b>				



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799910	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	1,954,897
					DSF0000720930	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,343,349
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000787775	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	583,551
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			Q009		DSF0000811101	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2018	802,227
						AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
					DSF0000720934	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	6,766,993
						EXTERIOR:EXTERIOR WALLS		
			Q009		DSF0000900575	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	117,414
						GAS SERVICE:Gas Meter Room Exhaust Fan HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
					DSF0000720933	<b>State of Good Repair - System Replacements - Parapets</b>	2018	3,405,640
						EXTERIOR:PARAPETS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000877706	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	738,815
<b>P.S. 9 (W REED SCHOOL) Total:</b>								\$15,712,886
75Q	Queens	Q075		<b>P.S. 75 (R PEARY SCHOOL)</b>				
					DSF0000798274	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	4,417,288
					DSF0000788791	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2016	1,103,365
					DSF0000788792	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,178,068
			Q075		DSF0000788798	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
					DSF0000843715	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2016	1,575,274
<b>P.S. 75 (R PEARY SCHOOL) Total:</b>								\$8,305,654
75Q	Queens	Q142		<b>P.S. 752 (OLD J142)</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777510	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	138,758
					DSF0000789870	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,092,682
					DSF0000866926	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	9,000
					DSF0000799825	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	280,625
						<b>Other</b>		
			Q752		DSF0000843803	Classroom Connectivity	2016	455,622
							<b>P.S. 752 (OLD J142) Total:</b>	<b>\$1,976,687</b>
75Q	Queens	Q177		<b>P.S. 177</b>				
			Q177		DSF0000867084	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	2,394,577
					DSF0000798293	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	8,302,938
					DSF0000790486	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2017	1,556,226

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
					DSF0000880356	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	567,416
					DSF0000790487	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,341,203
					DSF0000880359	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	970,903
					DSF0000790493	EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000880358	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	5,470,445
					DSF0000880357	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	5,313,763
			Q177		DSF0000866042	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q177	DSF0000912509		<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	3,662,021
			Q177	DSF0000843802		<b>Other</b> Classroom Connectivity	2016	356,146
							<b>P.S. 177 Total:</b>	\$30,120,047
75Q	Queens	Q667		<b>SKILLMAN HIGH SCHOOL</b>				
						<b>Other</b> IP Surveillance Camera Installation	2019	207,598
							<b>SKILLMAN HIGH SCHOOL Total:</b>	\$207,598
75Q	Queens	Q722		<b>JOHN F. KENNEDY JR. SCHOOL</b>				
			Q721	DSF0000815284		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2018	3,433,389
				DSF0000823580		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
				DSF0000792064		<b>State of Good Repair - System Replacements - Roofs</b>	2016	37,531

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q721	DSF0000815282		EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Roofs</b>	2018	1,572,511
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
<b>JOHN F. KENNEDY JR. SCHOOL Total:</b>								\$5,113,154
75Q	Queens	Q811		<b>P.S. 811 (OLD 187)</b>				
				DSF0000777532		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	119,349
				DSF0000798374		<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	5,505,270
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF0000792110		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	2,438,612
						CLIMATE CONTROL SYSTEM		
				DSF0000792112		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,129,986
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q811	DSF0000881858		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	200,221
						FIXTURES:Student:Lavatory/Sink		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							<b>P.S. 811 (OLD 187) Total:</b>	<b>\$9,393,438</b>
78Q	Queens	K420		<b>FRANKLIN K. LANE HS</b>				
					DSF0000844728	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	707,601
					DSF0000821839	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	1,411,799
					DSF0000888763	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2018	5,540,372
			K764		DSF0000912173	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	367,000
						Technology		
			K618		DSF0000912174	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2019	380,500
						Technology		
					DSF0000912318	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	176,920
						EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT EXIT/EMERGENCY LIGHT		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K583		DSF0000873442	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,423,223
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799563	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	420,622
			K618		DSF0000865804	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2019	1,663,699
					DSF0000868202	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	741,663
			K583		DSF0000873446	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	26,933,598
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR SOFFITS		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
			K618		DSF0000783323	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	1,699,752
						GAS SERVICE:GAS DISTRIBUTION PIPING		
						HEATING		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT:FUEL SYSTEMS		
			K583		DSF0000799866	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821798	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	233,904
					DSF0000821905	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	210,061
					DSF0000873445	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	13,661,913
			K583		DSF0000873444	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	7,590,521
					DSF0000806620	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	154,039
						<b>Other</b>		
					DSF0000843861	IP Surveillance Camera Installation	2018	700,388
<b>FRANKLIN K. LANE HS Total:</b>								<b>\$64,049,234</b>
78Q	Queens	Q023		<b>QUEENS ACADEMY HS</b>				
					DSF0000787986	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	2,033,028
					DSF0000787985	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	489,481

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q540		DSF0000855333	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System	2017	73,859
					DSF0000800271	<b>State of Good Repair - System Replacements - Exterior Masonry</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2016	379,321
					DSF0000800270	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:EXTERIOR WALLS EXTERIOR:ROOFING:Roofing	2016	388,923
<b>QUEENS ACADEMY HS Total:</b>								<b>\$3,364,612</b>
78Q	Queens	Q400		<b>AUGUST MARTIN HS</b>				
			Q400		DSF0000799365	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	605,433
			Q400		DSF0000799367	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	364,354
					DSF0000843890	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	2,400,215
					DSF0000843675	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b>	2017	2,639,702

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Library Upgrade		
					DSF0000777517	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	222,609
			Q400		DSF0000798303	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b>	2018	8,506,821
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
					DSF0000798305	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	3,813,183
						CLIMATE CONTROL SYSTEM		
					DSF0000868236	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	588,857
			Q400		DSF0000799996	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	131,241
						FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS		
			Q400		DSF0000867056	<b>Other</b> IP Surveillance Camera Installation	2018	695,594
<b>AUGUST MARTIN HS Total:</b>								\$19,968,009
78Q	Queens	Q405		<b>BAYSIDE HS</b>				
					DSF0000912242	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2019	154,643
			Q495		DSF0000821803	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	1,057,748

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868237	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	840,723
			Q495		DSF0000791438	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	50,777
						<i>Other</i>		
					DSF0000868138	IP Surveillance Camera Installation	2019	496,336
							<b>BAYSIDE HS Total:</b>	<b>\$2,600,227</b>
78Q	Queens	Q410			<b>BEACH CHANNEL EDUCATIONAL CAMPUS</b>			
			Q351		DSF0000868062	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	2,531,063
					DSF0000777518	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	254,314
					DSF0000791453	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2015	2,306,668
						CLIMATE CONTROL SYSTEM		
					DSF0000799435	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	7,331,564
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799931	<i>State of Good Repair - Building Upgrade - Interior Spaces</i>	2015	644,996
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799628	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	701,185
					DSF0000791459	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	1,346,424
						DOMESTIC WATER SYSTEM		
					DSF0000791457	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	2,343,837
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
					DSF0000799946	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	488,404
						EMERGENCY GENERATOR SET		
					DSF0000868291	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,508,878
			Q262		DSF0000904097	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	109,401
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
					DSF0000791458	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	11,084,685
						GAS SERVICE:GAS DISTRIBUTION PIPING		
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT:FUEL SYSTEMS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000814698	<b>State of Good Repair - System Replacements - Toilets - Students</b>  FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	135,616
					DSF0000843862	<b>Other</b> IP Surveillance Camera Installation	2017	780,876
<b>BEACH CHANNEL EDUCATIONAL CAMPUS Total:</b>								<b>\$31,567,911</b>
78Q	Queens	Q411		<b>BEACH CHANNEL HS AF</b>				
			Q410		DSF0000843700	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>  ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING SITE:Drainage System for Asphalt SITE:Drainage System for Soil SITE:DRINKING FOUNTAINS SITE:FENCES SITE:IRRIGATION SYSTEM SITE:PAVING - STUDENT NON-USE:Asphalt SITE:RETAINING WALLS SITE:SIDEWALKS:DOT Sidewalk SITE:SITE WALLS (NOT RETAINING WALLS)	2017	9,619,315

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>BEACH CHANNEL HS AF Total:</b>	<b>\$9,619,315</b>
78Q	Queens	Q415		<b>BENJAMIN N. CARDOZO HS</b>				
					DSF0000845618	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	859,662
					DSF0000777519	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	57,743
					DSF0000791475	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2016	539,710
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799706	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	224,030
			Q415		DSF0000822228	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2017	3,327,638
					DSF0000799831	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	161,489
			Q415		DSF0000814720	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	144,786
			Q415		DSF0000881249	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Water Cooled Chiller	2019	200,790

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						AIR CONDITIONING:Condenser Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Cooling Tower AIR CONDITIONING:DX Split System AIR CONDITIONING:Refrigerant Piping AIR CONDITIONING:Return Fan		
						<i>Other</i>		
					DSF0000867116	IP Surveillance Camera Installation	2018	628,222
							<b>BENJAMIN N. CARDOZO HS Total:</b>	<b>\$6,144,070</b>
78Q	Queens	Q416		<b>CARDOZO HS AF</b>				
					DSF0000814735	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELD:SCOREBOARD ATHLETIC FIELDS:FIXED EQUIPMENT SITE:FENCES SITE:PAVING - STUDENT USE:Asphalt	2017	6,389,260
							<b>CARDOZO HS AF Total:</b>	<b>\$6,389,260</b>
78Q	Queens	Q420		<b>SPRINGFIELD GARDENS HS</b>				
			Q265		DSF0000911816	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b>	2019	100,000
					DSF0000777520	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	155,733
					DSF0000799629	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	238,723



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q265	DSF0000814742		<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2017	9,868,274
				DSF0000814748		<b>State of Good Repair - System Replacements - Paved Area - Concrete</b> SITE:Drainage System for Concrete SITE:PAVING - STUDENT NON-USE:Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways SITE:SITE WALLS (NOT RETAINING WALLS)	2017	498,159
			Q265	DSF0000822213		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	296,945
			Q248	DSF0000881262		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2019	400,444
						<b>Other</b>		
			Q272	DSF0000867057		IP Surveillance Camera Installation	2018	532,314

**SPRINGFIELD GARDENS HS Total: \$12,090,592**

78Q    Queens    Q421    **SPRINGFIELD GDNS HS AF**

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000791517	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b> ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING SITE:Drainage System for Asphalt SITE:Drainage System for Soil SITE:PAVING - STUDENT USE:Asphalt SITE:PAVING - STUDENT USE:Concrete SITE:SIDEWALKS:DOT Sidewalk SITE:SITE WALLS (NOT RETAINING WALLS) SITE:STAIRS/RAMPS: EXTERIOR	2016	10,021,374
			Q283		DSF0000844738	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2016	313,694
<b>SPRINGFIELD GDNS HS AF Total:</b>								<b>\$10,335,068</b>
78Q	Queens	Q425		<b>JOHN BOWNE HS</b>				
					DSF0000799630	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	199,327
					DSF0000799780	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	212,788
			Q425		DSF0000881278	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2018	6,815,789

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q425		DSF0000791523	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
					DSF0000814775	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	273,386
						Ventilation		
			Q425		DSF0000881277	<b>State of Good Repair - System Replacements - Roofs</b>	2018	1,629,904
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			Q425		DSF0000867058	IP Surveillance Camera Installation	2018	431,494
							<b>JOHN BOWNE HS Total:</b>	<b>\$9,594,368</b>
78Q	Queens	Q430		<b>FRANCIS LEWIS HS</b>				
					DSF0000799991	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2017	2,096,322
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799631	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	215,162
					DSF0000791538	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	1,424,670
						PUBLIC ADDRESS SYSTEM		
			Q430		DSF0000891054	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
						<b>Other</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000867117	IP Surveillance Camera Installation	2018	548,184
							<b>FRANCIS LEWIS HS Total:</b>	\$4,476,838
78Q	Queens	Q435		<b>MARTIN VAN BUREN HS</b>				
					DSF0000911908	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	254,262
					DSF0000843892	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	2,432,008
					DSF0000777521	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	188,929
			Q435		DSF0000858778	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	13,003
					DSF0000799707	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	602,190
					DSF0000745890	<i>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</i> FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	3,383,571
					DSF0000868293	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	1,627,874
<i>Other</i>								

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q435		DSF0000867059	IP Surveillance Camera Installation	2018	622,557
<b>MARTIN VAN BUREN HS Total:</b>								\$9,124,394
78Q	Queens	Q440		<b>FOREST HILLS HS</b>				
			Q440	DSF0000844713		<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	773,761
				DSF0000777522		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	68,144
				DSF0000791601		<i>Safety and Security - Safety and Security - Safety Systems</i>	2018	4,332,922
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
				DSF0000799781		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	154,643
				DSF0000791598		<i>State of Good Repair - System Replacements - Auditorium Upgrade</i>	2016	105,786
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
				DSF0000868238		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,110,309
				DSF0000912202		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	817,061
				SCA0000021454		<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	10,505,139

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q440		DSF0000791591	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	32,510
					DSF0000814835	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	290,110
						<b>Other</b>		
					DSF0000868137	IP Surveillance Camera Installation	2019	625,251
<b>FOREST HILLS HS Total:</b>								<b>\$18,815,636</b>
78Q	Queens	Q445		<b>WILLIAM C. BRYANT HS</b>				
					DSF0000912325	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT EXIT/EMERGENCY LIGHT	2019	154,081
					DSF0000791625	<b>Safety and Security - Safety and Security - Safety Systems</b> EXTERIOR:DOORS:DOORS AND FRAMES INTERIOR:INTERIOR GUARDS	2015	266,626
					DSF0000799708	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	204,287

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q445		DSF0000821933	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2017	3,171,350
					DSF0000791621	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2019	212,659
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
					DSF0000868322	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,378,538
					DSF0000889294	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	5,452
					DSF0000836991	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2016	73,282
						INTERIOR:GYMNASIUM:Seating		
			Q445		DSF0000891055	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000814859	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	147,734
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
					DSF0000823651	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	261,702
			Q445		DSF0000866048	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000868136	IP Surveillance Camera Installation	2019	476,167
						<b>WILLIAM C. BRYANT HS Total:</b>		\$6,697,107
78Q	Queens	Q450		<b>NEWCOMERS HIGH SCHOOL (OLD LIC)</b>				
					DSF0000791632	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	1,356,426
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q555		DSF0000845578	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2017	653,438
						DOMESTIC WATER SYSTEM		
						FIXTURES:Student:Drinking Fountain		
					DSF0000799832	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	242,649
					DSF0000889011	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,984
						<b>NEWCOMERS HIGH SCHOOL (OLD LIC) Total:</b>		\$2,341,497
78Q	Queens	Q451		<b>ACADEMY OF AMERICAN STUD HS AX</b>				
					DSF0000889348	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,750
						Air Conditioning Split System		
						<b>ACADEMY OF AMERICAN STUD HS AX Total:</b>		\$78,750



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78Q	Queens	Q452		<b>LONG ISLAND CITY HS (NEW)</b>				
					DSF0000822192	<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Kitchen Areas	2018	2,832,101
					DSF0000768897	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	13,667,770
			Q450		DSF0000814902	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	4,354,739
					DSF0000745990	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2015	9,987,463
			Q450		DSF0000814906	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	2,655,281
					DSF0000799462	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	38,664
					DSF0000814908	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			Q450		DSF0000791664	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	11,302,315
			Q450		DSF0000814904	<b>State of Good Repair - System Replacements - Roofs</b>	2019	7,510,560

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						<i>Other</i>		
					DSF0000868135	IP Surveillance Camera Installation	2019	459,676
<b>LONG ISLAND CITY HS (NEW) Total:</b>								<b>\$52,878,292</b>
78Q	Queens	Q455		<b>NEWTOWN HS</b>				
			Q455	DSF0000799498		<b>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</b> Room Conversions / Partitioning	2015	2,724,990
				DSF0000912221		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EXIT LIGHT	2019	186,199
				DSF0000791680		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	276,614
				DSF0000799632		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	219,378
				DSF0000868294		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,612,385
			Q455	DSF0000866132		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
			Q455	DSF0000791687		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	115,464

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
			Q455		DSF0000866049	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
						<b>Other</b>		
					DSF0000868132	IP Surveillance Camera Installation	2019	517,997
<b>NEWTOWN HS Total:</b>								<b>\$5,883,446</b>
78Q	Queens	Q456		<b>HS FOR ARTS AND BUS. (OL NUTN X)</b>				
						<b>Other</b>		
			Q550		DSF0000867162	New/Retrofit Telephone/Intercom Systems	2018	266,847
<b>HS FOR ARTS AND BUS. (OL NUTN X) Total:</b>								<b>\$266,847</b>
78Q	Queens	Q460		<b>FLUSHING HS</b>				
					DSF0000777523	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	130,908
					DSF0000799709	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	198,866
					DSF0000868295	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	976,151
			Q460		DSF0000881483	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	2,820,121

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
			Q460		DSF0000791726	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,810
					DSF0000799833	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	270,350
			Q460		DSF0000881482	<b>State of Good Repair - System Replacements - Parapets</b>	2019	2,390,328
						EXTERIOR:COPING EXTERIOR:PARAPETS		
			Q460		DSF0000881481	<b>State of Good Repair - System Replacements - Roofs</b>	2019	6,455,805
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
					DSF0000814966	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	139,885
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
					DSF0000868131	IP Surveillance Camera Installation	2019	715,472

**FLUSHING HS Total: \$14,148,696**

78Q Queens Q465 FAR ROCKAWAY HS

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000821672	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	2,040,235
					DSF0000821673	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,019,202
					DSF0000777524	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	251,083
					DSF0000799633	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	491,973
					DSF0000791745	<i>State of Good Repair - Building Upgrade - Reinforcing Support Elements</i>	2017	1,923,023
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
		Q260			DSF0000821629	<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2019	743,196
					DSF0000868239	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	1,236,396
		Q260			SCA0000026014	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	5,724,286
		Q282			DSF0000866133	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
					DSF0000881509	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	152,733
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						HEATING:Heating Coil In Ductwork		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
					DSF0000791747	<b>State of Good Repair - System Replacements - Parapets</b>	2017	9,921,573
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000791746	<b>State of Good Repair - System Replacements - Roofs</b>	2017	6,764,607
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
			Q260		DSF0000791751	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	129,482
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
					DSF0000791748	<b>State of Good Repair - System Replacements - Windows</b>	2017	3,192,455
						EXTERIOR:WINDOWS		
						<b>Other</b>		
					DSF0000843853	IP Surveillance Camera Installation	2017	516,392
<b>FAR ROCKAWAY HS Total:</b>								<b>\$34,184,326</b>
78Q	Queens	Q470		<b>JAMAICA HS</b>				
					DSF0000777525	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	181,506

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798427	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	483,215
			Q310		DSF0000889657	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2019	733,471
			Q470		DSF0000821614	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2015	428,849
					DSF0000888825	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2018	151,548
					DSF0000868296	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	679,094
			Q470		DSF0000845574	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	3,840,774
			Q350		DSF0000889648	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Seating	2019	221,910
					DSF0000815011	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	235,040

**Other**

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000868129	IP Surveillance Camera Installation	2019	427,475
							<b>JAMAICA HS Total:</b>	<b>\$7,382,882</b>
78Q	Queens	Q475		<b>RICHMOND HILL HS</b>				
			Q475	DSF0000799973		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,896,704
			Q475	DSF0000799974		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	455,746
				DSF0000843980		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	168,918
			Q475	DSF0000799975		<i>Educational Enhancements - Educational Enhancements - School Improvement and Restructuring</i>	2015	119,190
						Technology		
			Q475	DSF0000844147		<i>Safety and Security - Safety and Security - Code Compliance</i>	2017	131,562
				DSF0000777526		<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	198,395
				DSF0000799634		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	608,273
				DSF0000799900		<i>State of Good Repair - Building Upgrade - Reinforcing Support Elements</i>	2018	1,342,668
			Q475	DSF0000800122		<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2015	5,526,190



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q475		DSF0000821610	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	523,605
					DSF0000868297	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	598,562
			Q475		DSF0000791801	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,810
					DSF0000881553	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	255,774
						GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube		
					DSF0000815038	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	726,936
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						<b>Other</b>		
					DSF0000868127	IP Surveillance Camera Installation	2019	548,974
							<b>RICHMOND HILL HS Total:</b>	<b>\$13,152,307</b>
78Q	Queens	Q480		<b>JOHN ADAMS HS</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q480		DSF0000799368	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	682,717
					DSF0000777527	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	187,858
					DSF0000904447	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,933,919
					DSF0000799635	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	227,206
			Q480		DSF0000845623	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,140,413
			Q480		DSF0000823638	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	568,914
					DSF0000868298	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,291,721
			Q480		DSF0000791828	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	8,077,817
					DSF0000791830	EXTERIOR:EXTERIOR WALLS <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			Q480		DSF0000891056	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	192,500
					DSF0000904451	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	10,864,565

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000904450	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	6,932,279
					DSF0000904452	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	817,574
					DSF0000843854	<b>Other</b> IP Surveillance Camera Installation	2017	557,515
							<b>JOHN ADAMS HS Total:</b>	<b>\$33,506,678</b>
78Q	Queens	Q485		<b>GROVER CLEVELAND HS</b>				
					DSF0000865867	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	161,626
			Q485		DSF0000889364	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	167,236
			Q485		DSF0000791848	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	1,120,533
					DSF0000799636	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	181,590
					DSF0000868240	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,303,594

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000815083	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2018	233,904
					DSF0000822658	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	290,110
			Q485		DSF0000881601	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	224,793
			Q485		DSF0000881602	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2019	400,444
						<b>Other</b>		
					DSF0000868126	IP Surveillance Camera Installation	2019	434,058
<b>GROVER CLEVELAND HS Total:</b>								<b>\$4,517,888</b>
78Q	Queens	Q488		<b>CLEVELAND HS AF NO. 2</b>				
					DSF0000769098	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2016	10,178,296
<b>CLEVELAND HS AF NO. 2 Total:</b>								<b>\$10,178,296</b>
78Q	Queens	Q490		<b>CAMPUS MAGNET HS (JACKSON)</b>				
					DSF0000843982	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	1,501,488

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777528	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	90,310
					DSF0000868299	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	840,144
			Q492		DSF0000866134	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2018	77,690
						<i>Other</i>		
			Q243		DSF0000867060	IP Surveillance Camera Installation	2018	578,797
<b>CAMPUS MAGNET HS (JACKSON) Total:</b>								<b>\$3,088,429</b>
78Q	Queens	Q505		<b>HILLCREST HS</b>				
					DSF0000865869	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	91,384
			Q505		DSF0000843728	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2017	1,178,102
					DSF0000777529	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	249,305
					DSF0000791893	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	3,810,410
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent			
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID			
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent			

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q505	DSF0000821631		<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2015	608,371
				DSF0000868300		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	911,777
			Q505	DSF0000791900		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	50,810
						<b>Other</b>		
				DSF0000868125		IP Surveillance Camera Installation	2019	653,255
							<b>HILLCREST HS Total:</b>	<b>\$7,553,414</b>
78Q	Queens	Q515		<b>TOWNSEND HARRIS HS</b>				
				DSF0000844714		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	194,095
				DSF0000859130		<b>State of Good Repair - Building Upgrade - Climate Control</b>	2018	638,969
						CLIMATE CONTROL SYSTEM		
			Q525	DSF0000891043		<b>State of Good Repair - System Replacements - Domestic Piping</b>	2019	148,895
						DOMESTIC WATER SYSTEM		
			Q525	DSF0000904545		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	654,983
						DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER):Dual Temperature Terminal Fan Coil Unit GAS SERVICE:Gas Meter Room Exhaust Fan		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q525	DSF0000904556		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:Heating And Ventilating Unit	2019	644,932
			Q525	DSF0000867154		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	328,506
<b>TOWNSEND HARRIS HS Total:</b>								\$2,610,380
78Q	Queens	Q520		<b>MIDDLE COLLEGE CAMPUS</b>				
						<b>Other</b> IP Surveillance Camera Installation	2019	66,197
<b>MIDDLE COLLEGE CAMPUS Total:</b>								\$66,197
78Q	Queens	Q566		<b>QNS HS OF TEACH., LIB. ARTS&amp;SCI</b>				
				DSF0000844708		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2016	101,976
			Q566	DSF0000889319		<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b> INTERIOR:GYMNASIUM:Fixed Equipment	2018	116,318
			Q566	DSF0000866242		<b>Other</b> New/Retrofit Telephone/Intercom Systems	2017	352,171
<b>QNS HS OF TEACH., LIB. ARTS&amp;SCI Total:</b>								\$570,465
78Q	Queens	Q567		<b>GLEN OAKS CAMPUS FACILITY</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000754249	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</i>	2015	21,929,523
<b>GLEN OAKS CAMPUS FACILITY Total:</b>								\$21,929,523
78Q	Queens	Q570		<b>FRANK SINATRA HIGH SCHOOL</b>				
					DSF0000865870	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	175,389
			Q501		DSF0000891057	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	192,500
						<i>Other</i>		
			Q501		DSF0000843799	Classroom Connectivity	2016	107,662
<b>FRANK SINATRA HIGH SCHOOL Total:</b>								\$475,551
78Q	Queens	Q585		<b>MASPETH HIGH SCHOOL</b>				
			Q585		DSF0000889365	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	75,609
<b>MASPETH HIGH SCHOOL Total:</b>								\$75,609
78Q	Queens	Q595		<b>AUX. SERV. - JAMAICA LEARN CT</b>				
					DSF0000912456	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2019	55,311
						EMERGENCY LIGHT/EXIT LIGHT PANEL		
						EMERGENCY LIGHTING		
						EXIT LIGHT		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000791938	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	426,142
					DSF0000868241	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	126,419
			Q950		DSF0000844149	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2018	539,016
					DSF0000815168	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	101,351
<b>AUX. SERV. - JAMAICA LEARN CT Total:</b>								<b>\$1,248,239</b>
78Q	Queens	Q600		<b>QUEENS VOC HS</b>				
			Q600		DSF0000801044	<b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP	2015	28,794
			Q600		DSF0000889012	<b>State of Good Repair - System Replacements - Roofs</b>	2019	88,981

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>QUEENS VOC HS Total:</b>	<b>\$117,775</b>
78Q	Queens	Q610		<b>AVIATION HS</b>				
					DSF0000799902	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2016	1,755,208
			Q610		DSF0000889366	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	180,535
			Q610		DSF0000866269	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2018	222,691
					DSF0000769187	CONVEYING:Escalator <i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2016	673,796
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000791966	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	977,035
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000769206	<i>State of Good Repair - System Replacements - Domestic Piping</i> Fire System Sprinklers	2016	3,224,695

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:DELUGE VALVE		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER HEAD		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:STANDPIPE SYSTEM		
					DSF0000868301	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	612,451
					DSF0000769191	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	3,944,520
						EXTERIOR:AREAWAY		
						EXTERIOR:AWNINGS AND CANOPIES		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR SOFFITS		
					DSF0000769202	<b>State of Good Repair - System Replacements - Gymnasium Upgrade</b>	2016	1,711,925
						FIXTURES:STUDENT:Locker Room Shower		
						GYMNASIUM:LIGHTING:Lighting Fixture - HID		
						GYMNASIUM:LIGHTING:Lighting Fixture - Incandescent		
						GYMNASIUM:LOCAL SOUND SYSTEM		
						GYMNASIUM:SCOREBOARD		
						INTERIOR:GYMNASIUM:Floor Finish		
					DSF0000769190	<b>State of Good Repair - System Replacements - Parapets</b>	2016	6,037,532

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000769189	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2016	6,241,855
					DSF0000791972	EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties <b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2016	1,265,485
							<b>AVIATION HS Total:</b>	\$26,847,728
78Q	Queens	Q620		<b>THOMAS A. EDISON VOC HS</b>				
					DSF0000800338	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	1,093,194
					DSF0000777530	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	204,708
					DSF0000799637	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	301,755
					DSF0000769212	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	6,805,900
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			Q620		DSF0000799868	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	63,729
					DSF0000769211	<b>State of Good Repair - System Replacements - Parapets</b>	2015	5,255,569

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000791991	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,606,521
					DSF0000868123	<b>Other</b> IP Surveillance Camera Installation	2019	415,790
<b>THOMAS A. EDISON VOC HS Total:</b>								\$16,747,166
78Q	Queens	Q650		<b>HS FOR CONST.TRADES,ENGG.,&amp; ARCH</b>				
			Q650		DSF0000889367	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	174,576
						<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	385,715
<b>HS FOR CONST.TRADES,ENGG.,&amp; ARCH Total:</b>								\$560,291
78Q	Queens	Q680		<b>YOUNG WOMENS' LEADERSHIP SCHOOL</b>				
					DSF0000866939	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	1,629
					DSF0000837276	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2017	452,924
					DSF0000822241	EXTERIOR:CHIMNEY <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:BOILER SYSTEM	2016	44,207

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q896	DSF0000815239		<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:PLAZA DECK EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,708,225
<b>YOUNG WOMENS' LEADERSHIP SCHOOL Total:</b>								\$2,206,985
78Q	Queens	Q686		<b>METROPOLITAN AVENUE CAMPUS</b>				
				DSF0000865871		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	98,108
						<b>Other</b>		
			Q686	DSF0000889492		IP Surveillance Camera Installation	2019	59,214
<b>METROPOLITAN AVENUE CAMPUS Total:</b>								\$157,322
78Q	Queens	Q690		<b>HS FOR LAW ENFORCEMENT</b>				
				DSF0000800326		<b>State of Good Repair - System Replacements - Domestic Piping</b> Fire System Sprinklers	2015	124,984
						<b>Other</b>		
			Q690	DSF0000889493		IP Surveillance Camera Installation	2019	40,986
<b>HS FOR LAW ENFORCEMENT Total:</b>								\$165,970
78Q	Queens	Q695		<b>QUEENS GATEWAY TO HEALTH SCIENCES SECONDARY SCHOOL</b>				
				DSF0000865872		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	143,807

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000866276	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	466,500
						<b>Other</b>		
			Q680		DSF0000889494	IP Surveillance Camera Installation	2019	41,724
<b>QUEENS GATEWAY TO HEALTH SCIENCES SECONDARY SCHOOL Total:</b>								\$652,031
78Q	Queens	Q707		<b>R. F. KENNEDY COMM. MIDDLE/HS</b>				
					DSF0000792029	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	464,596
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<b>Other</b>		
			Q670		DSF0000866241	New/Retrofit Telephone/Intercom Systems	2017	179,554
<b>R. F. KENNEDY COMM. MIDDLE/HS Total:</b>								\$644,150
78Q	Queens	Q725		<b>HS FOR INFORMATION TECH</b>				
					DSF0000799782	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	76,852
			Q502		DSF0000867181	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	1,074,516
						Air Conditioning Split System		
						AIR CONDITIONING:Cooling Tower		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Queens  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			Q502	DSF0000889495		IP Surveillance Camera Installation	2019	37,186
<b>HS FOR INFORMATION TECH Total:</b>								\$1,188,554
78Q	Queens	Q739		<b>YOUNG WOMEN'S LEADERSHIP ACADEMY</b>				
				DSF0000889660		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2019	3,262,973
<b>YOUNG WOMEN'S LEADERSHIP ACADEMY Total:</b>								\$3,262,973
78Q	Queens	Q744		<b>ELMHURST EDUCATIONAL CAMPUS</b>				
			Q296	DSF0000799518		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	337,035
			Q744	DSF0000823567		<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2016	2,770,252
			Q744	DSF0000889496		<i>Other</i> IP Surveillance Camera Installation	2019	39,917
<b>ELMHURST EDUCATIONAL CAMPUS Total:</b>								\$3,147,204
78Q	Queens	Q792		<b>NORTH QUEENS COMMUNITY HS</b>				
			Q792	DSF0000867164		<i>Other</i> New/Retrofit Telephone/Intercom Systems	2018	165,843
<b>NORTH QUEENS COMMUNITY HS Total:</b>								\$165,843
78Q	Queens	Q798		<b>BACCALAUREATE SCL FOR GLOBAL ED</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q580	DSF0000843905		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Condenser Water Piping AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Cooling Tower AIR CONDITIONING:Packaged / Rooftop Unit AIR CONDITIONING:Return Fan	2016	267,043
			Q580	DSF0000865920		<b>Other</b> Classroom Connectivity	2017	168,743
							<b>BACCALAUREATE SCL FOR GLOBAL ED Total:</b>	\$435,786
78Q	Queens	Q799				<b>CAMBRIA HEIGHTS ACADEMY</b>		
			Q326	DSF0000888830		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING:Unit Heater/Cabinet Heater	2018	58,274
			Q326	DSF0000866210		<b>Other</b> Classroom Connectivity	2017	60,193
							<b>CAMBRIA HEIGHTS ACADEMY Total:</b>	\$118,467
78Q	Queens	Q859				<b>REGION 3 / ROC C</b>		
				DSF0000799710		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	178,191
				DSF0000844132		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	198,764

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Queens**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Air Conditioning Split System AIR CONDITIONING:COOLING TOWER		
			Q985		DSF0000888852	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	62,244
						HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
			Q985		DSF0000912278	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	180,664
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
<b>REGION 3 / ROC C Total:</b>								\$619,863
78Q	Queens	Q891		<b>R. F. WAGNER SEC SCL ARTS &amp; TECH</b>				
					DSF0000821790	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	693,310
<b>R. F. WAGNER SEC SCL ARTS &amp; TECH Total:</b>								\$693,310

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Staten Island Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.01	0.00	0.00	0.00	0.00	0.01
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	6.15	3.66	0.83	0.71	6.44	17.79
3. Climate Control	3.85	1.24	0.34	0.14	3.05	8.61
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversion	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical System	0.32	1.22	1.72	0.45	0.48	4.18
7. Lighting Fixtures	9.59	6.61	0.79	0.10	-0.02	17.07
8. Elevators and Escalators	0.09	0.04	0.03	0.01	0.27	0.44
9. Reinforcing Cinder Concrete Slabs	0.00	0.00	0.00	0.00	0.00	0.00
10. Flood Elimination	11.65	0.00	0.89	4.84	8.72	26.09
11. Air Conditioning Retrofit	0.06	0.31	0.21	0.17	0.01	0.76
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.00	0.00	0.00	0.00	0.00	0.00
14. Interior Spaces	2.00	0.03	0.03	0.29	0.01	2.36
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	1.07	0.65	8.08	0.71	13.60	24.12
2. Playground Redevelopment	0.42	0.06	0.12	0.54	1.23	2.37
3. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. System Replacements						
1. Roofs	7.07	5.43	13.99	13.66	15.40	55.54
2. Parapets	4.68	4.39	7.39	12.64	11.18	40.28
3. Painting and Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	4.55	1.31	3.57	0.13	12.85	22.42
5. Exterior Masonry	4.60	13.60	29.26	28.55	22.41	98.42
6. Electrical Systems	0.85	1.61	2.34	1.16	3.36	9.32
7. Heating Plant Upgrade	15.81	1.22	2.23	6.02	2.02	27.29
8. Domestic Piping	1.01	0.09	0.39	0.86	0.01	2.35
9. Toilets - Students	0.08	1.22	0.27	3.52	1.99	7.08

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Staten Island Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>I. State of Good Repair</b>						
E. System Replacements						
10. Toilets - Staff	0.00	0.00	0.00	0.00	0.00	0.00
11. Floors	0.00	0.00	0.00	0.00	0.00	0.00
12. Paved Area - Blacktop	0.00	0.00	0.00	0.00	0.00	0.00
13. Paved Area - Concrete	0.15	0.21	0.66	0.36	0.12	1.50
14. Fencing	0.00	0.00	0.00	0.00	0.00	0.00
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	0.69	0.14	0.23	0.02	0.97	2.05
18. Gymnasium Upgrade	0.05	0.03	0.01	0.47	0.00	0.56
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.00	0.02	0.10	2.75	0.93	3.79
<i>I. State of Good Repair Yearly Totals:</i>	74.72	43.08	73.48	78.11	105.03	
						<b>I. State of Good Repair Total: 374.43</b>
<b>II. System Expansion</b>						
A. New Construction-Additional Capacity						
1. New Schools	0.61	0.24	8.57	6.40	79.44	95.27
2. Building Additions	25.57	76.65	8.91	4.21	1.98	117.32
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	20.22	0.57	0.44	0.07	0.27	21.58
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
9. 3-K Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.18	44.40	44.58
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.00	0.00	0.00	0.00	1.74	1.74

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Staten Island Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>II. System Expansion</b>						
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	0.02	0.01	3.79	20.48	0.34	24.64
F. Replacements						
1. Replacements - New	0.09	0.09	1.99	42.68	84.46	129.32
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Lease	0.00	0.00	0.00	0.00	0.00	0.00
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>II. System Expansion Yearly Totals:</i>	46.51	77.57	23.70	74.03	212.64	
						<b>II. System Expansion Total: 434.44</b>
<b>III. Educational Enhancements</b>						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions / Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrade	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>III. Educational Enhancements Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>III. Educational Enhancements Total: 0.00</b>
<b>IV. Safety and Security</b>						
A. Safety and Security						
1. Safety Systems	0.03	0.06	1.23	0.05	0.02	1.39
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>IV. Safety and Security Yearly Totals:</i>	0.03	0.06	1.23	0.05	0.02	
						<b>IV. Safety and Security Total: 1.39</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Borough of Staten Island Plan Summary**  
(in millions)

Category	FY15	FY16	FY17	FY18	FY19	Total
<b>V. Ancillary Facilities</b>						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>V. Ancillary Facilities Yearly Totals:</i>	0.00	0.00	0.00	0.00	0.00	
						<b>V. Ancillary Facilities Total: 0.00</b>
<b>VI. Emergency, Unspecified and Misc.</b>						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	8.38	3.45	11.27	11.89	17.57	52.57
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
<hr/>						
<i>VI. Emergency, Unspecified and Misc. Yearly Totals:</i>	8.38	3.45	11.27	11.89	17.57	
						<b>VI. Emergency, Unspecified and Misc. Total: 52.57</b>
<hr/>						
<b>Yearly Totals for Staten Island</b>	129.64	124.16	109.68	164.08	335.27	
						<b>Staten Island Grand Total: \$862.83</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Capacity Projects**  
**Borough of Staten Island**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	31	DSF0000821684 FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	224	Jun-14	Dec-14	Sep-16	23.20	0.00	21.20	2.00
*	31	DSF0000843832 P.S. @ 357 TARGEE STREET	773	Jun-17	Jan-19	Mar-22	134.66	0.00	108.53	26.13
*L	31	DSF0000798214 I.S. 82	309	Nov-15	Nov-16	Jun-17	15.19	0.01	14.85	0.32
*	78R	DSF0000798232 CURTIS HIGH SCHOOL ANNEX	345	Apr-14	Sep-15	Jul-17	94.88	0.14	93.42	1.32

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility.

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
Pre-Kindergarten Initiative Projects  
Borough of Staten Island  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	31	DSF0000800050 FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	90	Jun-14	Dec-14	Sep-15	20.20	0.01	20.19	0.00
* L	31	DSF0000800328 THE RICHMOND PRE-K CENTER @ 1 TELEPORT DRIVE	144	Aug-14	Dec-14	Sep-15	13.43	0.00	13.43	0.00
* L	31	DSF0000800267 PRE-K CENTER @ 120 STUYVESANT PLACE	108	Jul-14	Jan-15	Aug-15	16.73	0.00	16.73	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
Fiscal Years 2015 - 2019  
3-K Initiative Projects  
Borough of Staten Island  
(in millions)**

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
* L	31	DSF0000889335 THE RICHMOND PRE-K CENTER @ 1535 RICHMOND AVENUE	225	Jul-18	Jan-19	Sep-19	16.06	0.00	16.06	0.00
* L	31	DSF0000889336 THE RICHMOND PRE-K CENTER @ 20 EBBITTS STREET	105	Jul-18	Feb-19	Sep-19	12.29	0.00	12.29	0.00
* L	31	DSF0000889338 THE RICHMOND PRE-K CENTER @ 2530 VICTORY BOULEVARD	75	Jun-18	Mar-19	Jun-19	9.79	0.00	9.79	0.00
* L	31	DSF0000889339 THE RICHMOND PRE-K CENTER @ 104 HOUSMAN AVENUE	75	Jul-18	Jan-19	Sep-19	11.46	0.00	11.46	0.00
* L	31	DSF0000889340 3K CENTER @ 1 TELEPORT DRIVE	60	Jul-18	Mar-19	Aug-19	4.70	0.00	4.70	0.00

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**Fiscal Years 2015 - 2019**  
**Replacement Projects**  
**Borough of Staten Island**  
(in millions)

District	Project #	School	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete	
*	75R	DSF0000844161	I.S./H.S. @ 715 OCEAN TERRACE	Replacement	Sep-17	May-19	Sep-21	106.15	0.00	83.75	22.39
*	75R	DSF0000821871	D75 REPLACEMENT @ 15 FAIRFIELD STREET	Replacement	Sep-16	Mar-18	Sep-20	60.42	0.00	51.95	8.47

\* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.  
L Proposed Leased Facility

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
31	Staten Island	R001		<b>P.S. 1</b>				
					DSF0000792253	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	691,661
					DSF0000889066	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	756,269
					DSF0000792257	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2017	8,453,219
					DSF0000859513	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2017	222,677
			R001		DSF0000912292	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Meter Room Vent	2019	51,917
					DSF0000792256	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2017	1,852,728
					DSF0000815507	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2017	1,258,369

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
					DSF0000821810	<b>State of Good Repair - System Replacements - Windows</b>	2017	3,061,443
						EXTERIOR:WINDOWS		
						<b>Other</b>		
			R001		DSF0000889249	New/Retrofit Telephone/Intercom Systems	2018	179,291
							<b>P.S. 1 Total:</b>	\$16,527,574
31	Staten Island	R002		<b>I.S. 2</b>				
					DSF0000799449	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,052,750
						CLIMATE CONTROL SYSTEM		
					DSF0000799448	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	3,409,783
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799445	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	554,793
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799639	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	505,539
					DSF0000799753	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	102,303
					DSF0000799447	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2015	782,986
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
					DSF0000799446	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	5,822,227
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
					DSF0000815530	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2015	150,000
						FIXTURES:STUDENT:Toilet		
							<b>I.S. 2 Total:</b>	<b>\$12,380,381</b>
31	Staten Island	R003		<b>P.S. 3</b>				
					DSF0000888889	<i>Safety and Security - Safety and Security - Code Compliance</i>	2019	1,348,891

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R003		DSF0000882106	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork HEATING:Radiator/Convactor/Fin Tube HEATING:Unit Heater/Cabinet Heater	2018	172,777
							<b>P.S. 3 Total:</b>	\$1,521,668
31	Staten Island	R004		<b>P.S. 4</b>				
			R004		DSF0000837585	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b> FIRE ALARM SYSTEM	2017	1,173,605
			R004		DSF0000792298	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
							<b>P.S. 4 Total:</b>	\$1,205,285
31	Staten Island	R005		<b>P.S. 5</b>				
					DSF0000837609	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,799,783
			R005		DSF0000889250	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	127,411

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 5 Total:</b>	\$2,927,194
31	Staten Island	R006		<b>P.S. 6</b>				
					DSF0000797735	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	80,259
			R006		DSF0000843899	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	55,677
						DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER):Dual Temperature Distribution: Piping, Pumps and Auxiliaries GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Hydronic Heating:Backflow Preventer HEATING:Hydronic Heating:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
						<b>Other</b>		
					DSF0000868078	IP Surveillance Camera Installation	2019	393,894
							<b>P.S. 6 Total:</b>	\$529,830
31	Staten Island	R007		<b>I.S. 7</b>				
					DSF0000799640	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	205,684
					DSF0000815617	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2017	585,770

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000882160	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	3,538,587
			R007		DSF0000889498	<b>Other</b> IP Surveillance Camera Installation	2019	41,321
							<b>I.S. 7 Total:</b>	<b>\$4,371,362</b>
31	Staten Island	R008		<b>P.S. 8</b>				
					DSF0000799711	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	126,414
					DSF0000775655	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2015	927,527
					DSF0000912236	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	21,980
			R008		DSF0000815624	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	124,675



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			R008		DSF0000889251	New/Retrofit Telephone/Intercom Systems	2018	177,189
							<b>P.S. 8 Total:</b>	\$1,377,785
31	Staten Island	R011		<b>P.S. 11</b>				
			R011		DSF0000815645	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS	2019	2,816,251
						<i>Other</i>		
			R011		DSF0000889252	New/Retrofit Telephone/Intercom Systems	2018	138,448
							<b>P.S. 11 Total:</b>	\$2,954,699
31	Staten Island	R013		<b>P.S. 13</b>				
					DSF0000882219	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,154,773
							<b>P.S. 13 Total:</b>	\$1,154,773
31	Staten Island	R014		<b>P.S. 14</b>				
					DSF0000888890	<b>Safety and Security - Safety and Security - Code Compliance</b>	2019	468,587
			R078		DSF0000866050	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<i>Other</i>								
					DSF0000868083	IP Surveillance Camera Installation	2019	419,100
							<b>P.S. 14 Total:</b>	\$1,102,479
31	Staten Island	R016		<b>P.S. 16</b>				
			R016		DSF0000777539	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2015	1,560,982
					DSF0000859681	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	1,463,905
						GROUNDING SYSTEM SERVICE SWITCH SWITCHBOARD		
			R016		DSF0000866051	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
							<b>P.S. 16 Total:</b>	\$3,239,679
31	Staten Island	R018		<b>P.S. 18</b>				
					DSF0000866947	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	9,000
					DSF0000815705	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2017	138,205
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 18 Total:</b>	\$147,205
31	Staten Island	R019		<b>P.S. 19</b>				
			R019		DSF0000912482	<i>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</i>	2019	200,000
					DSF0000746802	<i>State of Good Repair - Building Upgrade - Flood Elimination</i> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	2,311,240
					DSF0000799641	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	119,656
					DSF0000792471	<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:EXTERIOR WALLS	2016	4,577,716
					DSF0000746804	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:PARAPETS	2016	4,400,491
			R019		DSF0000859712	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2016	1,841,978
					DSF0000769753	<i>State of Good Repair - System Replacements - Windows</i> EXTERIOR:WINDOWS	2016	874,975
							<b>P.S. 19 Total:</b>	\$14,326,056
31	Staten Island	R020		<b>P.S. 20</b>				

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000792489	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	682,050
							<b>P.S. 20 Total:</b>	\$682,050
31	Staten Island	R021		<b>P.S. 21</b>				
					DSF0000792507	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	347,526
			R021		DSF0000837807	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Packaged / Rooftop Unit	2016	119,751
			R021		DSF0000843976	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2016	44,609

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Fuel System		
					DSF0000815763	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2015	157,924
						FIXTURES:STUDENT:Toilet		
							<b>P.S. 21 Total:</b>	\$669,810
31	Staten Island	R022		<b>P.S. 22</b>				
					DSF0000868242	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	486,470
			R022		DSF0000866052	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
						<b>Other</b>		
			R022		DSF0000889499	IP Surveillance Camera Installation	2019	39,712
							<b>P.S. 22 Total:</b>	\$740,974
31	Staten Island	R023		<b>P.S. 23</b>				
					DSF0000799791	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	41,121
						<b>Other</b>		
			R023		DSF0000867111	New/Retrofit Telephone/Intercom Systems	2018	156,728
							<b>P.S. 23 Total:</b>	\$197,849
31	Staten Island	R024		<b>I.S. 24</b>				
					DSF0000859812	<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2018	95,099

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CAFETERIA:Floor Finish		
					DSF0000799835	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	372,319
					DSF0000837849	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	50,683
						HEATING PLANT:Boiler System		
					DSF0000912198	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
							<b>I.S. 24 Total:</b>	\$597,036
31	Staten Island	R026		<b>P.S. 26</b>				
					DSF0000905281	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	80,000
					DSF0000815840	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	154,511
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			R026		DSF0000889253	New/Retrofit Telephone/Intercom Systems	2018	132,896
							<b>P.S. 26 Total:</b>	\$367,407
31	Staten Island	R027		<b>I.S. 27</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R027		DSF0000792611	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	49,559
			R027		DSF0000822152	<b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2015	150,000
							<b>I.S. 27 Total:</b>	<b>\$199,559</b>
31	Staten Island	R029		<b>P.S. 29</b>				
					DSF0000769913	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	1,732,439
					DSF0000799712	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	105,076
			R029		DSF0000822179	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2017	3,425,211
			R029		DSF0000843919	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	789,803
			R029		DSF0000843918	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing	2017	1,200,783

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
EXTERIOR:ROOF:Specialties								
							<b>P.S. 29 Total:</b>	\$7,253,312
31	Staten Island	R030		<b>P.S. 30</b>				
					DSF0000792650	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	952,314
					DSF0000882465	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER	2018	4,615,556
			R030		DSF0000882464	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2018	4,808,166
			R030		DSF0000882463	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	4,179,511
			R030		DSF0000889254	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	200,940



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 30 Total:</b>	\$14,756,487
31	Staten Island	R031		<b>P.S. 31</b>				
					DSF0000815908	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,028,386
					DSF0000912440	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	340,362
							<b>P.S. 31 Total:</b>	\$1,368,748
31	Staten Island	R032		<b>P.S. 32</b>				
			R032		DSF0000792692	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	674,595
			R032		DSF0000912279	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	46,683
			R032		DSF0000815933	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2017	1,333,298
					DSF0000912196	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935
			R032		DSF0000837971	<b>State of Good Repair - System Replacements - Roofs</b>	2017	587,860

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000815936	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	124,572
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			R032		DSF0000889255	<b>Other</b> New/Retrofit Telephone/Intercom Systems	2018	201,834
					DSF0000868086	IP Surveillance Camera Installation	2019	277,094
							<b>P.S. 32 Total:</b>	<b>\$3,324,871</b>
31	Staten Island	R034		<b>I.S. 34 (OLD TOTTEVILLE)</b>				
					DSF0000776033	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2016	15,643,246
			R034		DSF0000775996	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	695,800
					DSF0000792723	<b>Educational Enhancements - Educational Enhancements - Science Lab Upgrades</b> INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment	2019	1,864,012

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:SCIENCE LAB:Fixed Equipment SCIENCE DEMO ROOM SCIENCE LAB SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Incandescent		
					DSF0000799755	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	64,668
					DSF0000792708	<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2016	1,756,713
			R034		DSF0000838002	FIRE ALARM SYSTEM <b>State of Good Repair - System Replacements - Domestic Piping</b> Waste System	2017	162,921
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
					DSF0000912526	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2019	3,506,251
					DSF0000859939	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	464,258
					DSF0000890989	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:COPING EXTERIOR:PARAPETS	2019	8,341,067

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000882522	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	6,885,502
					DSF0000889305	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2019	9,128,947
<b>I.S. 34 (OLD TOTTEVILLE) Total:</b>								<b>\$48,513,385</b>
31	Staten Island	R035		<b>P.S. 35</b>				
					DSF0000792734	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	5,028,359
					DSF0000815965	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2016	815,622
					DSF0000798338	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	386,581
			R035		DSF0000815971	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	129,050

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
			R035		DSF0000865922	New/Retrofit Telephone/Intercom Systems	2017	147,284
							<b>P.S. 35 Total:</b>	\$6,506,896
31	Staten Island	R036		<b>P.S. 36</b>				
					DSF0000770042	<b>State of Good Repair - Building Upgrade - Boiler Conversion</b> HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	6,900,232
					DSF0000792744	<b>State of Good Repair - Building Upgrade - Climate Control</b> CLIMATE CONTROL SYSTEM	2015	1,109,102
					DSF0000770036	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	470,578
					DSF0000799713	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	313,948
					DSF0000770040	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:CHIMNEY	2015	1,424,276

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
					DSF0000792760	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation	2015	2,948,669
					DSF0000843714	VENTILATION:HEATING AND VENTILATING UNIT <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	71,897
					DSF0000867028	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	118,922
					DSF0000770037	<b>State of Good Repair - System Replacements - Roofs</b> EXTERIOR:ROOFING:Roofing	2015	4,562,490
					DSF0000770039	<b>State of Good Repair - System Replacements - Windows</b> EXTERIOR:WINDOWS	2015	4,123,939
						<b>Other</b>		
			R036		DSF0000867112	New/Retrofit Telephone/Intercom Systems	2018	214,536
					DSF0000775856	IP Surveillance Camera Installation	2015	614,399
<b>P.S. 36 Total:</b>								<b>\$22,872,988</b>
31	Staten Island	R038		<b>P.S. 38</b>				
			R038		DSF0000882569	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS FIRED FURNACE	2019	107,794

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING:Radiator/Convactor/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
							<b>P.S. 38 Total:</b>	\$107,794
31	Staten Island	R039		<b>P.S. 39</b>				
			R039	DSF0000823620		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	40,710
						<b>Other</b>		
			R039	DSF0000865923		Classroom Connectivity	2017	152,165
							<b>P.S. 39 Total:</b>	\$192,875
31	Staten Island	R041		<b>P.S. 41</b>				
				DSF0000799714		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	135,449
			R041	DSF0000843971		<b>State of Good Repair - Building Upgrade - Low-Voltage Electrical System</b>	2017	694,732
						AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			R041	DSF0000816045		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2017	1,522,355
						GROUNDING SYSTEM		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R041		DSF0000792820	LIGHTNING PROTECTION PANEL BOARD SERVICE SWITCH SWITCHBOARD <b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	126,169
							<b>P.S. 41 Total:</b>	\$2,478,705
31	Staten Island	R042		<b>P.S. 42</b>				
					DSF0000792840	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	80,207
			R042		DSF0000816066	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2018	144,786
					DSF0000912197	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	78,935



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
			R042		DSF0000889256	New/Retrofit Telephone/Intercom Systems	2018	258,612
							<b>P.S. 42 Total:</b>	\$562,540
31	Staten Island	R044		<b>P.S. 44</b>				
					DSF0000888891	<b>Safety and Security - Safety and Security - Code Compliance</b>	2019	507,066
					DSF0000905516	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	1,097,925
					DSF0000816080	INTERIOR:STRUCTURAL:FOUNDATION WALLS <b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	837,606
					DSF0000704503	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent <b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	8,175,728
					DSF0000816083	EXTERIOR:Exterior Walls <b>State of Good Repair - System Replacements - Parapets</b>	2016	351,702
					DSF0000821741	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2016	1,629,899
					DSF0000821742	EXTERIOR:ROOFING:Roofing <b>State of Good Repair - System Replacements - Windows</b>	2016	965,389
						EXTERIOR:WINDOWS		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000888836	<b>System Expansion - New Physical Education Facilities - Playgrounds</b>	2019	2,077,197
						<b>Other</b>		
			R044		DSF0000843807	Classroom Connectivity	2016	333,921
							<b>P.S. 44 Total:</b>	<b>\$15,976,433</b>
31	Staten Island	R045		<b>P.S. 45</b>				
					DSF0000792874	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2016	1,543,759
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799642	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	131,769
					DSF0000792877	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2016	5,920,169
						EXTERIOR:EXTERIOR WALLS		
			R045		DSF0000843946	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2016	145,357
			R045		DSF0000866135	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000770166	<b>State of Good Repair - System Replacements - Parapets</b>	2016	4,500,310
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
					DSF0000770165	<b>State of Good Repair - System Replacements - Roofs</b>	2016	2,551,669
						EXTERIOR:ROOFING:Roofing		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000888928	<b>State of Good Repair - System Replacements - Roofs</b>	2018	81,327
						<b>Other</b>		
					DSF0000775711	IP Surveillance Camera Installation	2015	491,328
							<b>P.S. 45 Total:</b>	\$15,443,378
31	Staten Island	R046		<b>P.S. 46</b>				
					DSF0000866953	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	40,255
					DSF0000822659	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	183,975
					DSF0000816116	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	196,700
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			R046		DSF0000889257	New/Retrofit Telephone/Intercom Systems	2018	211,963
							<b>P.S. 46 Total:</b>	\$632,893
31	Staten Island	R048		<b>P.S. 48</b>				
					DSF0000681389	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2017	1,338,176
						SITE:Retaining Walls		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 48 Total:</b>	\$1,338,176
31	Staten Island	R049		<b>I.S. 49</b>				
			R049	DSF0000882722		<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	3,856,100
				DSF0000821615		<b>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</b>	2019	479,066
				DSF0000816149		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Toilet	2016	137,882
						<b>Other</b>		
			R049	DSF0000867061		IP Surveillance Camera Installation	2018	421,628
							<b>I.S. 49 Total:</b>	\$4,894,676
31	Staten Island	R050		<b>P.S. 50</b>				
				DSF0000866954		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	18,408
						<b>Other</b>		
			R050	DSF0000867062		IP Surveillance Camera Installation	2018	422,018
							<b>P.S. 50 Total:</b>	\$440,426
31	Staten Island	R051		<b>I.S. 51</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R051		DSF0000889368	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2018	197,352
					DSF0000775659	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	851,792
					DOMESTIC WATER SYSTEM			
			R051		DSF0000838238	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2015	333,972
					Waste System			
					DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping			
					<b>Other</b>			
					DSF0000868087	IP Surveillance Camera Installation	2019	360,963
							<b>I.S. 51 Total:</b>	<b>\$1,744,079</b>
31	Staten Island	R052		<b>P.S. 52</b>				
					DSF0000799454	<b>State of Good Repair - Building Upgrade - Climate Control</b>	2015	1,262,132
					CLIMATE CONTROL SYSTEM			
			R052		DSF0000747329	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	1,037,369
					DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP			
					INTERIOR:STRUCTURAL:FOUNDATION WALLS			
					DSF0000799453	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	4,298,005

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
					DSF0000799451	<b>State of Good Repair - Building Upgrade - Interior Spaces</b>	2015	1,756,040
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
					DSF0000822225	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	765,457
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
					DSF0000799455	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2015	509,264
						SITE:PLAYGROUNDS:Safety Surfacing		
					DSF0000799452	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2015	1,876,500
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
					DSF0000792985	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	8,836,356

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
					DSF0000792994	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Ventilation VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2015	1,157,377
			R052		DSF0000912230	<b>Other</b> IP Surveillance Camera Installation	2019	69,214
							<b>P.S. 52 Total:</b>	\$21,567,714
31	Staten Island	R053		<b>P.S. 53</b>				
			R053		DSF0000888996	<b>State of Good Repair - System Replacements - Domestic Piping</b> DOMESTIC WATER SYSTEM	2019	67,864
			R053		DSF0000793004	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	39,392
					DSF0000799837	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	220,875

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R053		DSF0000816209	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2018	144,786
					DSF0000775712	<b>Other</b> IP Surveillance Camera Installation	2015	417,773
							<b>P.S. 53 Total:</b>	<b>\$890,690</b>
31	Staten Island	R054		<b>P.S. 54</b>				
					DSF0000912422	<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b> EMERGENCY LIGHT/EXIT LIGHT PANEL EMERGENCY LIGHTING EXIT LIGHT	2019	40,512
					DSF0000793018	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	893,790
			R054		DSF0000793020	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R054		DSF0000816224	<i>State of Good Repair - System Replacements - Toilets - Students</i> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	101,993
							<b>P.S. 54 Total:</b>	\$1,067,975
31	Staten Island	R055		<b>P.S. 55</b>				
					DSF0000799715	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	200,092
			R055		DSF0000793042	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
					DSF0000799838	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	138,509
							<b>P.S. 55 Total:</b>	\$370,281
31	Staten Island	R056		<b>P.S. 56</b>				
					DSF0000865874	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2017	256,929
					DSF0000860240	<i>State of Good Repair - Building Upgrade - Climate Control</i> CLIMATE CONTROL SYSTEM	2018	638,969
							<b>P.S. 56 Total:</b>	\$895,898
31	Staten Island	R057		<b>P.S. 57</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000799877	<b>Safety and Security - Safety and Security - Code Compliance</b>	2017	1,315,706
					DSF0000912392	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,682
			R057		DSF0000882859	<b>State of Good Repair - System Replacements - Paved Area - Concrete</b>	2019	73,641
			R057		DSF0000822153	SITE:STAIRS/RAMPS: EXTERIOR <b>State of Good Repair - System Replacements - Toilets - Students</b> INTERIOR:TOILET ROOMS - STUDENTS	2016	101,351
			R057		DSF0000843808	<b>Other</b> Classroom Connectivity	2016	332,755
							<b>P.S. 57 Total:</b>	<b>\$1,825,135</b>
31	Staten Island	R058		<b>P.S. 58</b>				
					DSF0000844733	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	66,663
					DSF0000799756	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	100,732
					DSF0000823581	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			R058		DSF0000867063	<b>Other</b> IP Surveillance Camera Installation	2019	381,302

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>P.S. 58 Total:</b>	\$618,420
31	Staten Island	R059		<b>THE HARBOR VIEW SCHOOL</b>				
			R059	DSF0000866054		<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	152,729
							<b>THE HARBOR VIEW SCHOOL Total:</b>	\$152,729
31	Staten Island	R060		<b>P.S. 60</b>				
			R060	DSF0000793094		<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:PARAPETS	2015	1,534,619
							<b>P.S. 60 Total:</b>	\$1,534,619
31	Staten Island	R061		<b>I.S. 61</b>				
				DSF0000799643		<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	155,977
				DSF0000821620		<i>State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade</i>	2015	482,149
			R061	DSF0000867171		<i>State of Good Repair - System Replacements - Electrical Systems</i>	2018	41,118
				DSF0000882896		<i>State of Good Repair - System Replacements - Exterior Masonry</i> EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	1,982,944
				DSF0000912199		<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	78,934
				DSF0000882894		<i>State of Good Repair - System Replacements - Parapets</i>	2019	2,001,597

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000882893	EXTERIOR:COPING EXTERIOR:PARAPETS <b>State of Good Repair - System Replacements - Roofs</b>	2019	9,070,807
			R061		DSF0000816314	EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties <b>State of Good Repair - System Replacements - Toilets - Students</b>	2016	134,266
					DSF0000882895	FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS <b>State of Good Repair - System Replacements - Windows</b>	2019	4,972,587
						EXTERIOR:WINDOWS <b>Other</b>		
			R061		DSF0000889544	IP Surveillance Camera Installation	2019	46,480
							<b>I.S. 61 Total:</b>	<b>\$18,966,859</b>
31	Staten Island	R069		<b>P.S. 69</b>	DSF0000799644	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	141,923
						<b>Other</b>		
			R069		DSF0000889258	New/Retrofit Telephone/Intercom Systems	2018	283,984
							<b>P.S. 69 Total:</b>	<b>\$425,907</b>

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
31	Staten Island	R071		<b>P.S./I.S. 48</b>				
			R048		DSF0000889369	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	146,529
			R048		DSF0000912183	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2019	101,523
							<b>P.S./I.S. 48 Total:</b>	<b>\$248,052</b>
31	Staten Island	R072		<b>I.S. 72</b>				
					DSF0000912443	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i> EMERGENCY LIGHT/EXIT LIGHT PANEL EXIT LIGHT EXIT/EMERGENCY LIGHT	2019	99,215
			R072		DSF0000890598	<i>State of Good Repair - Building Upgrade - Boiler Conversion</i> HEATING PLANT:Boiler Auxiliaries	2019	8,557,800
			R072		DSF0000877738	<i>State of Good Repair - Building Upgrade - Climate Control</i>	2019	3,250,004
					DSF0000799757	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	127,080
			R072		DSF0000816367	<i>State of Good Repair - System Replacements - Domestic Piping</i> Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP	2016	94,828

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP		
						DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
					DSF0000868323	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	465,960
			R072		DSF0000799871	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,659
			R072		DSF0000816353	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	144,786
			R072		DSF0000816355	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	168,998
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						<b>Other</b>		
			R072		DSF0000889500	IP Surveillance Camera Installation	2019	50,044
							<b>I.S. 72 Total:</b>	<b>\$12,990,374</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R075		DSF0000799934	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2015	319,769
					DSF0000860369	<b>State of Good Repair - System Replacements - Electrical Systems</b> EMERGENCY GENERATOR SET GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2018	927,554
					DSF0000816378	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
			R075		DSF0000838444	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Air Cooled Chiller AIR CONDITIONING:Chilled Water System:Air Cooled Condenser AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries	2018	2,164,320
						<b>Other</b>		
					DSF0000868091	IP Surveillance Camera Installation	2019	456,004
							<b>I.S. 75 Total:</b>	<b>\$3,937,370</b>

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R020		DSF0000889564	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	12,583,688
							<b>P.S. 20 GYM ANNEX Total:</b>	\$12,583,688
31	Staten Island	R099		<b>P.S. 39 GYM ANNEX</b>				
			R039		DSF0000889565	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,887,323
							<b>P.S. 39 GYM ANNEX Total:</b>	\$10,887,323
31	Staten Island	R700		<b>P.S. 74 GYM ANNEX</b>				
			R074		DSF0000889035	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	10,898,910
							<b>P.S. 74 GYM ANNEX Total:</b>	\$10,898,910
31	Staten Island	R701		<b>P.S. 1 GYM ANNEX</b>				
			R001		DSF0000889036	<i>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</i>	2019	9,877,265
							<b>P.S. 1 GYM ANNEX Total:</b>	\$9,877,265
31	Staten Island	R702		<b>P.S. 54 GYM ANNEX</b>				



**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R054		DSF0000889287	<b>System Expansion - New Construction-Common-Facilities-Additions - Gymnasiums</b>	2019	10,038,937
							<b>P.S. 54 GYM ANNEX Total:</b>	\$10,038,937
31	Staten Island	R802		<b>P.S. 1 ANNEX</b>				
					DSF0000866960	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	15,003
			R001		DSF0000860575	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	4,802,352
							<b>P.S. 1 ANNEX Total:</b>	\$4,817,355
31	Staten Island	R826		<b>P.S. 3 ANNEX</b>				
					DSF0000798340	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	417,041
			R003		DSF0000838676	<b>State of Good Repair - System Replacements - Electrical Systems</b> SERVICE SWITCH	2017	932,164
					DSF0000866962	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	9,534
							<b>P.S. 3 ANNEX Total:</b>	\$1,358,739

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
31	Staten Island	R829		<b>ARTHUR D. PHILLIPS SCHOOL</b>				
			R065	DSF0000843902		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Pressure Booster	2016	61,787
						<b>Other</b>		
			R065	DSF0000889502		IP Surveillance Camera Installation	2019	39,041
							<b>ARTHUR D. PHILLIPS SCHOOL Total:</b>	<b>\$100,828</b>
31	Staten Island	R831		<b>P.S. 74</b>				
				DSF0000866963		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	30,815
				DSF0000821889		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:CONDENSER WATER PUMP	2015	33,154
			R074	DSF0000906109		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> GAS SERVICE:Gas Distribution Piping	2019	51,770
						<b>Other</b>		
			R074	DSF0000843806		Classroom Connectivity	2016	364,069
							<b>P.S. 74 Total:</b>	<b>\$479,808</b>
31	Staten Island	R844		<b>P.S. 36 ANNEX</b>				

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000798347	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	152,251
					DSF0000866965	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	50,942
							<b>P.S. 36 ANNEX Total:</b>	<b>\$203,193</b>
31	Staten Island	R848		<b>P.S. 42 ANNEX</b>				
			R042		DSF0000882638	<b>State of Good Repair - Building Upgrade - Flood Elimination</b> DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	2,006,882
			R042		DSF0000906153	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:EXTERIOR WALLS	2019	1,028,470
			R042		DSF0000912209	<b>State of Good Repair - System Replacements - Roofs</b>	2019	893,968
			R042		DSF0000793508	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	237,932

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							<b>P.S. 42 ANNEX Total:</b>	\$4,167,252
31	Staten Island	R861		<b>ELIZABETH A. CONNELLY CAMPUS</b>				
						<i>Other</i>		
			R861		DSF0000843805	Classroom Connectivity	2016	236,923
			R861		DSF0000889259	New/Retrofit Telephone/Intercom Systems	2018	344,238
			R861		DSF0000889503	IP Surveillance Camera Installation	2019	40,919
							<b>ELIZABETH A. CONNELLY CAMPUS Total:</b>	\$622,080
31	Staten Island	R880		<b>P.S. 80 (PETR COMPL-BLDG B)</b>				
			R080		DSF0000889371	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	102,666
					DSF0000843727	<b>Safety and Security - Safety and Security - Code Compliance</b>	2015	99,644
					DSF0000770810	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2015	898,865
					DSF0000866967	<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	13,463
					DSF0000793531	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	349,339
						Air Conditioning Split System		
						AIR CONDITIONING:PACKAGED TERMINAL A/C		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R080	DSF0000838758		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Absorption Chiller AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller AIR CONDITIONING:Condenser Water Piping AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Cooling Tower AIR CONDITIONING:Packaged Terminal A/C AIR CONDITIONING:Return Fan	2016	501,790
			R080	DSF0000860685		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b> Air Conditioning Split System	2017	575,960
			R080	DSF0000866057		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	152,729
			R080	DSF0000889504		<b>Other</b> IP Surveillance Camera Installation	2019	53,006
<b>P.S. 80 (PETR COMPL-BLDG B) Total:</b>								<b>\$2,747,462</b>
33R	Staten Island	R080		<b>REGION 7/ ROC F</b>				
				DSF0000912203		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2019	1,173,716

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							<b>REGION 7/ ROC F Total:</b>	<b>\$1,173,716</b>
75R	Staten Island	R025		<b>P.S. 25 ANNEX (OLD 4)</b>				
					DSF0000792581	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2016	234,121
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R025		DSF0000912168	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</b>	2019	1,679,559
					DSF0000866183	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	85,251
			R025		DSF0000866053	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
							<b>P.S. 25 ANNEX (OLD 4) Total:</b>	<b>\$2,213,723</b>
75R	Staten Island	R040		<b>P.S. 373 (OLD P40)</b>				
					DSF0000770084	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2015	199,475
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000754447	<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2015	2,359,407
						EXTERIOR:EXTERIOR WALLS		
			R373		DSF0000816029	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2017	154,677

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						<i>Other</i>		
					DSF0000775710	IP Surveillance Camera Installation	2015	418,452
							<b>P.S. 373 (OLD P40) Total:</b>	<b>\$3,132,011</b>
75R	Staten Island	R722				<b>P.S. 722 (OTC)</b>		
			R721		DSF0000844119	<b>Heating Plant Upgrade</b>	2019	4,044,905
						HEATING PLANT:Boiler System		
					DSF0000770703	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	1,849,271
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R721		DSF0000843947	<b>State of Good Repair - System Replacements - Domestic Piping</b>	2016	212,264
					DSF0000866179	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	755,000
							<b>P.S. 722 (OTC) Total:</b>	<b>\$6,861,440</b>
75R	Staten Island	R818				<b>P.S. 37 TRANSPORTABLE</b>		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000800333	<b>System Expansion - New Construction-Additional Capacity - Transportables</b> Interior Spaces	2015	91,487
<b>P.S. 37 TRANSPORTABLE Total:</b>								\$91,487
75R	Staten Island	R825		<b>P.S. 25 (MOUNT LORETTO)</b>				
					DSF0000799758	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	17,230
<b>P.S. 25 (MOUNT LORETTO) Total:</b>								\$17,230
75R	Staten Island	R840		<b>P.S. 37 ( OLD I24X)</b>				
					DSF0000793472	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	780,030
			R037		DSF0000793476	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			R037		DSF0000889638	<b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
						<b>Other</b>		
			R037		DSF0000867113	New/Retrofit Telephone/Intercom Systems	2018	280,955
<b>P.S. 37 ( OLD I24X) Total:</b>								\$1,307,457



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75R	Staten Island	R843		<b>P.S. 37 MINISCHOOL (OLD P32)</b>				
					DSF0000798345	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	242,420
<b>P.S. 37 MINISCHOOL (OLD P32) Total:</b>								\$242,420
78R	Staten Island	R043		<b>JEROME PARKER CAMPUS</b>				
					DSF0000865873	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	198,625
					DSF0000801048	<b>Playground Redevelopment</b> SITE:Drainage System for Asphalt SITE:Drainage System for Concrete	2017	3,668,310
			R047		DSF0000799795	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			R047		DSF0000843804	<b>Other</b> Classroom Connectivity	2016	330,901
<b>JEROME PARKER CAMPUS Total:</b>								\$4,229,516
78R	Staten Island	R435		<b>NEW DORP HS (NEW)</b>				
					DSF0000843658	<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2017	743,046
			R440		DSF0000844153	<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	997,611

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000777534	<i>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</i>	2015	331,542
			R440		DSF0000816406	<i>State of Good Repair - Building Upgrade - Climate Control</i> CLIMATE CONTROL SYSTEM	2016	294,748
					DSF0000793212	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	417,717
					DSF0000838464	<i>State of Good Repair - System Replacements - Gymnasium Upgrade</i> INTERIOR:GYMNASIUM:Floor Finish	2016	470,464
			R440		DSF0000793217	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	31,680
			R440		DSF0000866055	<i>State of Good Repair - System Replacements - Toilets - Students</i>	2018	214,792
						<i>Other</i>		
					DSF0000868093	IP Surveillance Camera Installation	2019	606,795
							<b>NEW DORP HS (NEW) Total:</b>	<b>\$4,108,395</b>
78R	Staten Island	R436			<b>NEW DORP HS AF (NEW)</b>			
					DSF0000801024	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</i> ATHLETIC FIELDS:PLAYING SURFACE	2017	10,220,009
							<b>NEW DORP HS AF (NEW) Total:</b>	<b>\$10,220,009</b>
78R	Staten Island	R440			<b>STATEN ISLAND TECHNICAL HS</b>			

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R605		DSF0000821877	<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2019	2,133,773
					DSF0000798351	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,421,206
					DSF0000793248	<b>State of Good Repair - System Replacements - Auditorium Upgrade</b> INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging	2015	295,920
					DSF0000883015	<b>State of Good Repair - System Replacements - Exterior Masonry</b> EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2019	1,604,864
			R605		DSF0000866136	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	77,690
					DSF0000889671	<b>State of Good Repair - System Replacements - Parapets</b> EXTERIOR:PARAPETS	2019	732,545
			R605		DSF0000816436	<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	186,565

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
<b>STATEN ISLAND TECHNICAL HS Total:</b>								\$6,452,563
78R	Staten Island	R445		<b>PORT RICHMOND HS</b>				
					DSF0000800120	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2015	537,174
			R445		DSF0000775992	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	1,523,648
			R445		DSF0000798577	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2015	439,974
					DSF0000860430	<i>State of Good Repair - Building Upgrade - Flood Elimination</i>	2018	359,223
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
					DSF0000799645	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	163,974
			R445		DSF0000821801	<i>State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment</i>	2018	726,682
			R445		DSF0000822178	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2018	20,267,260
						EXTERIOR:AWNINGS AND CANOPIES		
						EXTERIOR:EXTERIOR SOFFITS		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			R445		DSF0000838507	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	376,013

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Air Conditioning Split System		
					DSF0000860431	<b>State of Good Repair - System Replacements - Parapets</b>	2018	839,008
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
			R445		DSF0000866098	<b>State of Good Repair - System Replacements - Roofs</b>	2018	5,621,182
						EXTERIOR:ROOF:Roofing		
						<b>Other</b>		
					DSF0000868094	IP Surveillance Camera Installation	2019	509,146
							<b>PORT RICHMOND HS Total:</b>	<b>\$31,363,284</b>
78R	Staten Island	R446		<b>PORT RICHMOND HS AF</b>				
					DSF0000843757	<b>State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields</b>	2019	19,919,978
						ATHLETIC FIELD:Scoreboard		
						ATHLETIC FIELDS:FIXED EQUIPMENT		
						ATHLETIC FIELDS:PLAYING SURFACE		
						ATHLETIC FIELDS:SEATING		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:Lighting:Lighting Fixture - Fluorescent		
						CLIMATE CONTROL SYSTEM		
						DOMESTIC WATER SYSTEM		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:Sewage/Waste/Vent Piping		
						EMERGENCY LIGHTING		
						EXIT LIGHT		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:COPING		
						EXTERIOR:DOORS:DOORS AND FRAMES		
						EXTERIOR:DOORS:LINTELS		
						EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
						EXTERIOR:EXTERIOR WALLS		
						EXTERIOR:LOUVER		
						EXTERIOR:PARAPETS		
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
						EXTERIOR:WINDOWS		
						FIXTURES:Staff And Other		
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						GROUNDING SYSTEM		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						HEATING:Radiator/Convactor/Fin Tube		
						HEATING:Steam Heating		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARING WALLS		
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
						INTERIOR:TOILET ROOMS - STUDENTS		
						MOTOR STARTER/CONTACTOR		
						PANEL BOARD		
						SECURITY:Lighting - Security		
						SITE:Drainage System for Asphalt		
						SITE:Drainage System for Concrete		
						SITE:Drainage System for Soil		
						SITE:FENCES		
						SITE:IRRIGATION SYSTEM		
						SITE:PAVING:Site Sidewalks & Walkways:Concrete		
						SITE:PAVING:Student Use:Asphalt		
						SITE:PAVING:Student Use:Pavers		
						SITE:RETAINING WALLS		
						SITE:STAIRS/RAMPS: EXTERIOR		
						TELEPHONE SYSTEM		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R445	DSF0000889649		TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent TRANSFORMER VENTILATION:Exhaust Fan VENTILATION:Metal Ductwork <b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2019	94,127
<b>PORT RICHMOND HS AF Total:</b>								\$20,014,105
78R	Staten Island	R450		<b>CURTIS HS</b>				
				DSF0000777535		<b>Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits</b>	2015	151,742
				DSF0000793283		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	149,956
				DSF0000816488		<b>State of Good Repair - System Replacements - Auditorium Upgrade</b>	2015	33,628
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
				DSF0000866958		<b>State of Good Repair - System Replacements - Electrical Systems</b>	2018	9,009
				DSF0000816478		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2017	157,456
			R450	DSF0000860454		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	254,754
						HEATING PLANT:Boiler System		



**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R450	DSF0000866056		<b>State of Good Repair - System Replacements - Toilets - Students</b>	2018	214,792
			R450	DSF0000883063		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Urinal	2019	400,444
							<b>CURTIS HS Total:</b>	<b>\$1,371,781</b>
78R	Staten Island	R455		<b>TOTTENVILLE HS</b>				
				DSF0000821950		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2016	633,842
				DSF0000793314		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b> CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	3,619,160
			R455	DSF0000793321		<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2015	31,680
			R455	DSF0000823655		<b>State of Good Repair - System Replacements - Toilets - Students</b> FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	101,351

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						<i>Other</i>		
					DSF0000868096	IP Surveillance Camera Installation	2019	668,661
							<b>TOTTENVILLE HS Total:</b>	\$5,054,694
78R	Staten Island	R460		<b>SUSAN E. WAGNER HS</b>				
					DSF0000911905	<i>Educational Enhancements - Educational Enhancements - Accessibility</i>	2019	397,544
			R460		DSF0000845613	<i>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</i>	2018	2,865,075
					DSF0000747719	<i>Safety and Security - Safety and Security - Safety Systems</i>	2017	1,766,932
						EXTERIOR:DOORS:DOOR HARDWARE EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS		
			R460		DSF0000816523	<i>State of Good Repair - Building Upgrade - Elevators and Escalators</i>	2016	267,673
						CONVEYING:ASH HOIST CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR		
					DSF0000793341	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	411,105
					DSF0000799716	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2015	191,815
					DSF0000868304	<i>State of Good Repair - System Replacements - Electrical Systems</i>	2019	953,878

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					SCA0000025813	<i>State of Good Repair - System Replacements - Exterior Masonry</i>	2017	17,650,905
			R460		DSF0000793350	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2015	36,751
					DSF0000799839	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i>	2016	290,655
					DSF0000905995	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation	2019	526,446
					DSF0000793346	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	5,961,772
					DSF0000793345	<i>State of Good Repair - System Replacements - Roofs</i> EXTERIOR:ROOFING:Roofing	2017	11,446,954
					DSF0000793347	<i>State of Good Repair - System Replacements - Windows</i> EXTERIOR:WINDOWS	2017	981,429
						<b>Other</b>		
					DSF0000868099	IP Surveillance Camera Installation	2019	622,198
<b>SUSAN E. WAGNER HS Total:</b>								<b>\$44,371,132</b>
78R	Staten Island	R470		<b>CONCORD HS (OLD 12)</b>				
					DSF0000793368	<i>State of Good Repair - Building Upgrade - Lighting Fixtures</i>	2016	468,734

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R470	DSF0000889639		CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent <b>State of Good Repair - System Replacements - Toilets - Students</b>	2019	214,792
							<b>CONCORD HS (OLD 12) Total:</b>	<b>\$683,526</b>
78R	Staten Island	R600		<b>RALPH MCKEE VOC HS</b>				
			R600	DSF0000889370		<b>Educational Enhancements - Educational Enhancements - Accessibility</b>	2019	176,760
			R600	DSF0000845617		<b>Educational Enhancements - Educational Enhancements - Room Conversions / Partitioning</b>	2017	800,039
			R600	DSF0000906016		<b>State of Good Repair - Building Upgrade - Elevators and Escalators</b>	2019	1,139,025
						CONVEYING:Elevator INTERCOM SYSTEM:Elevator		
				DSF0000883139		<b>State of Good Repair - Building Upgrade - Flood Elimination</b>	2018	1,589,968
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF0000799647		<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	118,149
				DSF0000888902		<b>State of Good Repair - System Replacements - Exterior Masonry</b>	2018	5,487,787

**New York City School Construction Authority  
New York City Department of Education  
Final Five-Year Capital Plan Report  
School Based Report  
Borough of Staten Island  
Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DSF0000823582	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	69,723
					DSF0000838607	<b>State of Good Repair - System Replacements - Heating Plant Upgrade</b>	2018	151,500
						Ventilation VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork VENTILATION:Supply Fan VENTILATION:Unit Ventilator		
					DSF0000883142	<b>State of Good Repair - System Replacements - Parapets</b>	2018	6,223,310
						EXTERIOR:COPING EXTERIOR:PARAPETS		
					DSF0000883141	<b>State of Good Repair - System Replacements - Roofs</b>	2018	5,429,007
						EXTERIOR:PLAZA DECK EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
						<b>Other</b>		
			R600		DSF0000889501	IP Surveillance Camera Installation	2019	43,334
							<b>RALPH MCKEE VOC HS Total:</b>	<b>\$21,228,602</b>
78R	Staten Island	R801			<b>AUX. SERV - ST. GEORGE SCHOOL</b>			
					DSF0000793425	<b>State of Good Repair - Building Upgrade - Lighting Fixtures</b>	2015	234,555

**New York City School Construction Authority**  
**New York City Department of Education**  
**Final Five-Year Capital Plan Report**  
**School Based Report**  
**Borough of Staten Island**  
**Fiscal Years 2015 - 2019**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
<b>AUX. SERV - ST. GEORGE SCHOOL Total:</b>								\$234,555