FY 2015 - 2019

PROPOSED FIVE YEAR CAPITAL PLAN AMENDMENT



Bill de Blasio Mayor Lorraine Grillo President & CEO

November 2016

Table of Contents

EXECUTIVE SUMMARY	5
Introduction	7
Mayoral Initiatives	10
FY2010 – 2014 Capital Plan: New Capacity Projects in Construction	10
Structure of the FY 2015 – 2019 Capital Plan	
Capacity	
Capital Investment	
Mandated Programs	12 13
CAPACITY	
Capacity	
New Capacity Program Pre-Kindergarten for All Initiative	
Class Size Reduction Program	
Facility Replacement Program	
CAPITAL INVESTMENT	29
Capital Investment	31
Capital Improvement Program	
Exteriors	
Interiors	33
Transportable Classroom Unit Removal/ Playground Redevelopment	34
Athletic Field Upgrades	37
School Enhancement Projects	
Facility Enhancements	
Facility Restructuring	38
Safety and Security	39
Middle School Science Lab Upgrades	
Accessibility	40
Physical Fitness Upgrades	40 41
Library UpgradesAuditorium Upgrades	41 41
Bathroom Upgrades	
	45
MANDATED Mandated	
Lighting Replacements	
Boiler Conversions	10 49
Asbestos Abatement	49
Lead Abatement	50
Emergency Lighting	50
Code Compliance with NYC Building Code and other City Agency Regulations	51
Building Condition Surveys	51
Wrap-Up Insurance	51
Prior Plan Completion Cost	52
Emergency, Unspecified & Miscellaneous	
FINANCING STRATEGY	53
Capital Plan Funding	
PROPOSED FIVE-YEAR PLAN PREPARATION	
New Capacity	
Current Utilization	59
	0/

Enrollment Projections	59
New Capacity Needs Assessment	60
Existing Facilities	_ 60
Background	60
Methodology	61
KEY STEPS AND DATES FOR APPROVAL OF THE PROPOSED AMENDMENT _	62
APPENDICES TABLE OF CONTENTS	_63

EXECUTIVE SUMMARY

Introduction

In June 2016, the School Construction Authority (SCA) adopted a \$14.86 billion Capital Plan which represented an increase of \$1.4 billion from the Spring 2015 Amendment. The November 2016 Amendment proposes \$15.44 billion in funding, which is approximately \$580 million more than the last adopted Amendment, and which provides allocations for additional Mayoral, City Council, and Borough President initiatives. In this November 2016 Amendment, the SCA invests in New York City's future and continue creating the school buildings and facilities that the City's children need and deserve. This Plan sustains the growth of the last Plan by taking significant steps to address pre-kindergarten need and by creating more than 44,000 seats in areas of current overcrowding and projected enrollment growth. The SCA will continue making investments in our infrastructure, thereby providing the framework for enhanced educational services and better facilities for the City's more than one million school children and the teachers and staff who serve them.

As the demand for capital investment always exceeds available funding, needs must be prioritized to ensure the most critical issues are addressed first and that the SCA leverages all possible funding sources. New York State's Executive Budget recommended a \$2 billion general obligation bond act, known as the Smart Schools Bond, which was brought before voters and passed in 2014. New York City is anticipated to receive approximately \$783 million from this bond. Bond proceeds may fund enhanced technology, expansion of pre-kindergarten classroom capacity, and the removal of Transportable Classroom Units (TCUs), including capacity required to enable their removal. The SCA has engaged with parents and communities for their suggestions regarding the most strategic use of this funding. Based on the community input the SCA has received, a plan has been developed and submitted to the New York State Smart Schools Review Board for review and approval.

The SCA is faced with both a growing student population in pockets of some districts and an aging infrastructure. Annually, the SCA undertakes a comprehensive assessment of alternatives to balance the City's economic conditions with the projected demand for public school education. The construction of new facilities is designed to address the most critical existing and anticipated capacity needs and to address pre-kindergarten need and class size reduction. Priority is given to areas where there is existing overcrowding at the neighborhood or district level. The SCA also undertakes an annual assessment of the condition of our existing buildings. The annual assessment allows for the prioritization of projects for our current inventory in order to provide safe and comfortable learning environments.

KEY CHANGES: In this Proposed Amendment, key changes include the identification of approximately 14 projects that will create over 8,600 seats, and the addition of pre-kindergarten

projects to create almost 8,200 pre-kindergarten seats. This Proposed Amendment also displays additional TCU removal projects completed and identified, as well as the identification of one additional year of Capital Investment projects.

The FY2015 – 2019 Capital Plan Amendment features the following proposed investments:

- **\$5.8 billion for Capacity**. The Capacity Program includes four elements:
 - **\$4.5 billion for New Capacity** funds more than 44,300 new seats in an estimated 81 projects. New Capacity funding will help us alleviate existing over-crowding, respond to ongoing pockets of growth in some neighborhoods, and support our goal to remove all TCUs. In addition, the SCA has secured the opportunity to include new public school facilities across the City within several major, predominantly residential development projects undertaken by private developers in areas of existing or projected overcrowding.
 - **\$800 million for Pre-Kindergarten for All** funds a robust and comprehensive approach to increase our pre-kindergarten seat capacity by almost 8,200. This is achieved by expanding the projected capacity within new build projects and by identifying additional new locations.
 - **\$490 million for Class Size Reduction -** targets additional resources to areas with seat need, and funds approximately 4,900 new seats. Class Size Reduction funding allows us to make a significant investment and commitment to reduce class sizes system-wide.
 - \$62 million for Facility Replacement Program funds the development of seats for schools that must be relocated during this Plan. In some instances, a landlord may refuse to renew a lease. In other instances, the DOE may choose to relocate students from a site that is no longer appropriate for those students. Funds in this category cover the costs to construct a new building or to build a new leased location.
- **\$6.0 billion for Capital Investment**. The Capital Investment portion of this Plan includes two main categories:
 - **\$3.8 billion for the Capital Improvement Program (CIP)** includes exterior and interior building upgrades and other necessary capital repairs to our buildings.
 - **\$1.5 billion for School Enhancement Projects** enhances the educational opportunities for our children. This category includes funding to support technology enhancements, realignment of existing facilities and the addition of pre-kindergarten capacity. Also included in this category are bathroom upgrades, physical fitness projects, science labs, accessibility and other necessary improvements.

- In addition, funding in the amount of approximately \$700 million has been provided from the City Council, Borough Presidents, and Mayor/Council sources.
- **\$3.7 billion for Mandated Programs.** This program provides funding to meet requirements by local law, City agency mandates and other required elements such as remediation and building code compliance projects, insurance, and emergencies. Under this program, all remaining light fixtures containing polychlorinated biphenyls (PCBs) in school buildings will be replaced. In addition, funding is allocated to continue boiler conversions as required by the NYC Department of Environmental Protection's (DEP) regulation to phase out the use of Number 4 oil by 2030.

PUBLIC REVIEW: The Proposed FY2015 – 2019 Capital Plan will continue the public input process implemented under the FY2005 – 2009 Plan and FY2010 – 2014 Plans. During this process, a draft plan or Amendment is released and during the public review period, the SCA meets with Community Education Councils (CECs), Community Boards, New York City Council Borough Delegations and other elected officials. An update incorporating the results of the meetings is released in the Spring. The Panel for Education Policy reviews the Spring Amendment and following PEP approval, the plan is forwarded to the Mayor and the City Council for review and approval as part of the City's annual budget adoption process. This process allows for increased transparency and results in an expanded review and dialogue for stakeholders.

Mayoral Initiatives

Access to pre-kindergarten and class size reduction are key priorities for the current Administration, and the introduction of targeted funds in the Capital Plan for the reduction of class sizes and Pre-Kindergarten for All collectively support these efforts.

The SCA also continues working with the Administration on two other Mayoral initiatives which may lead to capacity needs. "Housing New York: A Five-Borough, 10-Year Plan" to build or preserve 200,000 affordable housing units throughout New York City and the investment in Community Schools may result in adjustments to enrollment projections or capacity needs. The SCA will continue to work with the New York City Department of City Planning (DCP) as well as other partners in the Administration on any land use proposal or other actions as part of the Housing New York plan and on the investment to Community Schools to assess the potential impacts on school enrollment and utilization.

As part of the current Administration's "One City, Built to Last" green building plan, the City has committed to installing 100 Megawatts of solar photovoltaic capacity on City-owned buildings by 2025. This initiative will be implemented by the Department of Citywide Administrative Services in partnership with the Department of Education and other City agencies. Schools will continue to be targeted as key buildings for solar installations, with 35 projects completed to date and approximately 70 additional projects in the pipeline.

FY2010 – 2014 Capital Plan: New Capacity Projects in Construction

New Capacity Status:

- Between September 2010 and September 2016, 24,540 seats funded by the FY2010 2014 Plan became available in schools across all five boroughs.
- In the next year, more than 2,600 additional seats will open.
 - o September 2017: 2,675

A table providing geographic detail of seats coming online in the next year is provided in the appendices.

Structure of the FY 2015 – 2019 Capital Plan

The FY2015 – 2019 Capital Plan enhances the structure of the FY2010 – 2014 Capital Plan by combining all code, mandate and regulation related programs under a new top level category: Mandated Programs. Therefore, there are now three major categories: Capacity, Capital Investment and Mandated Programs. **Capacity** includes all initiatives that create new school facilities, **Capital Investment** includes all programs undertaken to improve and upgrade existing facilities and **Mandated** includes all initiatives to comply with new mandates and existing, local laws and codes as well as prior plan completion costs, wrap up insurance and emergencies.

As in the FY2010 – 2014 Plan, the proposed new Capacity projects are identified for all five years. In previous Amendments, Capital Investment projects that renovate existing buildings were identified for the first four years of the plan (FY2015, FY2016, FY2017, and FY2018) with funding allocations for the remaining one year. The November 2016 Proposed Amendment now identifies projects for the last year of this Plan.

The annual Amendment process allows the SCA to reassess priorities and to take into account shifts in enrollments, variations in housing growth, changes in building conditions, new educational initiatives, adjustments in the construction marketplace, and incorporate any impact from financial changes implemented by the City or State. An annual review has proven to be the most effective way to make the Capital Plan a living, working document that, within budgetary constraints, keeps pace with the needs of the educational system.

Each section has a summary table showing the proposed funding for each category of the Plan.

Capacity

The **Capacity** category (**\$5.8 billion**) includes all programmatic elements related to creating, expanding or replacing school buildings, or capacity in our school system. Four key elements of the Capacity category in this Plan include: accommodating existing overcrowding and projected enrollment growth at the neighborhood level within districts with identified need, creating a far reaching expansion in pre-kindergarten capacity, investing in new capacity to reduce class size, and replacing seats.

The analysis for this Plan includes a multi-dimensional review and analysis of localized capacity and enrollment patterns within each district. The result is a set of recommendations for each district that take into account the needs within each area of the district within funding limitations. Recommendations will be reviewed annually based on updated enrollment projections, capacity changes and housing information. This *New Capacity Program* proposes a \$4.5 billion investment for an estimated 81 projects adding over 44,300 seats Citywide. The program includes:

- 44 projects for small primary school buildings, grades pre-kindergarten 5;
- 29 projects for larger buildings which can be flexibly programmed for PK-5, middle schools, or support two organizations, one serving PK-5 and the other 6-8;
- Four projects for middle/high school buildings to serve secondary or high schools;
- Four buildings with 2,601 seats will be funded for design in this plan and construction in the next plan.

New capacity, coupled with strategies to align current facilities with enrollment needs, will assist the SCA in:

- Reducing localized overcrowding within districts;
- Enabling removal of all TCUs.

Continuing the practice initiated under the FY2005 – 2009 Plan, the design of the larger facilities to be built will provide the flexibility to program spaces to serve PK-5, middle school, or support two organizations, one serving PK-5 and the other serving 6-8. In order to meet the growing demand, and consistent with the goal of serving students with disabilities in the least restrictive, appropriate setting, new PS and larger PS/IS facilities will continue to include facilities designed to serve students with disabilities.

The *New Capacity Program* also includes a \$490 million investment in class size reduction, which will generate an additional 4,900 seats.

The Capacity category also includes the *Pre-Kindergarten for All Initiative* (\$800 million). These funds will enable the creation of almost 8,200 new pre-kindergarten seats.

The final element of our Capacity category, the *Facility Replacement Program* (62 million) continues the initiative begun under the FY2005 – 2009 Plan to provide replacement sites for schools or administrative facilities that must vacate their current locations.

Capital Investment

The **Capital Investment** category (**\$6.0 billion**) includes the *Capital Improvement Program* (CIP) (\$3.8 billion) and *School Enhancement Projects* (\$1.5 billion). CIP projects cover infrastructure work in our existing buildings. Our current inventory of facilities is mainly comprised of older assets and includes nearly 200 buildings that are at least 100 years old. The needs identified under this Plan are based on several factors, including the annual Building Condition Assessment Survey (BCAS), which provides an evaluation of the condition of our

building systems. The SCA uses the evaluation in conjunction with recommendations from facility personnel, school administration and the community in developing the projects to be included in this Capital Plan. While the SCA will continue to maintain focus on ensuring that buildings are watertight and safe, the SCA will also allocate funding to facilitate the removal of all remaining TCUs.

School Enhancement Projects (\$1.5 billion) continue the work from the FY2010 - 2014 Plan to upgrade instructional spaces in existing buildings. The two main programs in this category are Facility Enhancements and Technology.

Facility Enhancements support key initiatives such as restructuring under-used spaces to increase capacity for programmatic needs. Such needs may include middle school science lab upgrades, expanded accessibility, and safety and security needs. In addition, this category includes upgraded physical fitness spaces, libraries, auditoriums, cafeteria serving lines and bathroom upgrades.

The SCA will continue developing and expanding its technology infrastructure in school buildings to provide its students and educators with the necessary tools for academic achievements and professional success in today's environment. This Capital Plan will allow the SCA to build on the success and investments of prior Capital Plans and ensure that schools meet new technological challenges in the coming years.

Mandated Programs

The **Mandated Programs** category (**\$3.7 billion**) includes funding for non-discretionary elements such as remediation/code compliance work, prior plan completion costs, emergency work, building condition assessments, and contractor insurance. This category also includes funding for projects required by local law or City agency mandates.

In April 2011, the City finalized a Department of Environmental Protection (DEP) rule that phases out the use of two highly polluting forms of heating oil – Number 6 oil and Number 4 oil. The phase out of Number 6 oil was completed in 2015. The phase out of Number 4 oil is mandated by 2030. In this Proposed Amendment, the SCA allocates \$750 million to convert boilers at approximately 120 of 380 buildings currently using Number 4 oil. Eliminating the use of heavy oils and transitioning to the cleanest fuels will comply with this mandate. This level of spending paces boiler conversions evenly across the Capital Plans between now and the 2030 mandate.

The SCA is on track to fulfill its agreement with the City to replace all polychlorinated biphenyl (PCB) containing light fixtures by the end of December 2016 rather than the originally

envisioned year of 2021. \$480 million is allocated to complete the replacement and removal of all remaining PCB containing lighting fixtures. The anticipated total cost of this program, since its inception, is approximately \$1 billion.



Capacity

Introduction

SUMMARY
Proposed Amendment
\$5,831.4 mm
2016 Adopted
Amendment
\$5,683.1 mm

The **Capacity Category** encompasses all aspects of creating new seats necessary to provide for the expansion of our system and the replacement of seats no longer available. New capacity provides the infrastructure necessary to continue advancing our goals of growth, sustainability, equity and resilience. By building new capacity, the City will meet local enrollment demands, strategically grow facilities to meet future demand, and eliminate our reliance on temporary facilities.

Although public school enrollment is projected to only slightly increase Citywide, localized growth may be higher in some areas. This growth, combined with existing overcrowded areas and methodology changes to the Blue Book, requires new construction to meet capacity needs in certain areas of the City. As a result, through the new Capacity Program, over 44,300 new seats will be created in areas within districts that have or are projected to experience overcrowding in the next five years in the absence of the additional capacity.

Recently, methodology changes were incorporated into the SCA's Enrollment, Capacity, and Utilization report, more commonly known as the Blue Book. More information about the methodology changes is found in the introductory pages of the recently released 2015-16 Blue Book. As a result of the methodology changes and updated enrollment projections, the January 2016 Amendment identified a seat need of approximately 83,000 seats, an increase of over 33,000 seats from the last Amendment that was adopted in June 2015. As a result of additional funding that was made available by the City, the SCA is able to fund the design and construction of 11,800 additional seats.

The SCA is also working with the Administration on two Mayoral initiatives which may lead to capacity needs: "Housing New York: A Five-Borough, 10-Year Plan" to build or preserve 200,000 affordable housing units throughout New York City, and the investment in Community Schools which may result in adjustments to enrollment projections or capacity needs. The SCA will continue to work with the

New York City Department of City Planning (DCP) as well as other partners in the Administration on any land use proposal or other actions as part of the Housing New York plan and will assess the impacts of the investment to Community Schools on school enrollment and utilization.

During the prior two Capital Plans, the SCA secured the opportunity to include new public school facilities across the City within several major, predominantly residential, development projects undertaken by private developers in areas of existing or projected overcrowding. The partnerships with these developers allow the SCA to provide new school facilities in areas of need with contributions of land or space by those developers. Continuing this practice, over 5,000 seats within developments projected to begin during this Five-Year Plan are funded for design or design and construction, including:

- Hudson Square Rezoning, Trinity Place Holdings, and Hudson Yards in Manhattan;
- Crotona Park East/West Farms Rezoning in the Bronx;
- Atlantic Yards, Greenpoint Landing and Domino Redevelopment in Brooklyn;
- Halletts Point Rezoning in Queens.

Finally, the SCA will continue to monitor conditions at the NYU Core development, as well as in the vicinity of the City's Seward Park Mixed-Use Redevelopment Project (both in Manhattan), where City-owned land has been reserved for future school construction should it be determined necessary. The inclusion and schedule of each of these developer projects in the Plan is contingent upon the advancement of each of the developments.

The schools and programs to inhabit these facilities will be determined on the basis of extensive discussions with community stakeholders. Details regarding new schools and the ability to provide input can be found at: http://schools.nyc.gov/community/planning/default.htm

In addition to new construction, the SCA will continue to employ, wherever possible, two strategies undertaken in the prior two Capital Plans to create new capacity. The strategies were designed to maximize our resources and included revitalization of the Education Construction Fund (ECF) and expansion of leasing as a means to build seats in districts and neighborhoods where finding new construction sites has proven to be difficult. The SCA will also work closely with other City agencies to ensure that major residential developments provide appropriate resources to assist in mitigating the impact created by these projects.

As part of the Capacity Program, the SCA has allocated \$800 million specifically for the support and development of pre-kindergarten seats. The Pre-Kindergarten for All Initiative supports capital investment for the creation of new pre-kindergarten seats in all five boroughs and invests in closing the access gap to pre-kindergarten in neighborhoods throughout the City.

Funding in the amount of \$490 million has been allocated towards Class Size Reduction. The SCA proposes a significant investment in reducing class sizes system-wide by creating an additional 4,900 new seats. To date, three projects have been identified and are located in districts 11, 19, and 29.

Funding under the Facility Replacement Program of the Capacity category allows us to provide for the development of seats for schools that must be relocated. Current projects under the Facility Replacement program are found in the appendices. Additional sites will be included in the Plan as they are identified.

New Capacity Program

SUMMARY
Proposed Amendment
\$4,479.4 mm
2016 Adopted
Amendment
\$4,461.1 mm

The creation of additional capacity is directly connected with the goals of supporting student enrollment growth, sustainability, equity and resilience. In the service of these goals, the SCA has identified prospective investments by gathering the best information about capacity needs in local communities and the available resources in the system to meet those needs.

This process starts with understanding challenges that can be solved through structural and systems solutions. Such challenges might include school quality, current learning conditions such as overcrowding, patterns of student enrollment, and unmet demand for particular types of schools or programs within schools. The City will seek solutions to these challenges first through the resources that already exist within the SCA. Thus, where the SCA proposes future investment in this Plan, it does so having assessed its ability to change structures, and having concluded that capital investment is the optimal – perhaps only – means by which to address current or future needs.

There are areas where growth is projected to continue or where overenrollment persists. These are local conditions, requiring truly local analysis. In creating this Plan, the SCA analyzed current capacity figures, capacity scheduled to become available over the next several years, and long-term enrollment and housing projections. The SCA further assessed spaces below maximum utilization – building by building – to determine the viability of plans to change the instructional usage or enrollment constraints for those spaces. Such analysis yields understanding of both problems – such as over-enrollment or lack of student choice – and solutions, which include a capital investment or the repurposing of current resources. This type of local analysis and planning is ongoing and responds to local enrollment and facilities conditions while developing the Capital Plan.

The chart below identifies the new capacity currently funded in the Plan and the additional need by district for elementary and middle schools and by borough for high schools. The chart also includes the status of the seats already in process.

District	Sub-District	January 2016 Identified Need	November 2016 Funded Need	Additional Need (Unfunded)	Number of Seats in Scope / Design
	Tribeca / Village	1,970	1,928	42	1,492
2	Chelsea/ Midtown West *	1,262	1,222	40	766
3	Upper West Side	692	692	0	692
7	Concourse	456	456	0	
,	Melrose	572	0	572	
8	Soundview	572	0	572	
0	Throgs Neck	456	456	0	344
9	Highbridge South	572	0	572	
	Spuyten Duyvil / Riverdale / Fieldston / North Riverdale	456	456	0	
10	Kingsbridge / Norwood / Bedford Park	3,384	2,104	1,280	500
10	Fordham / Belmont	572	0	572	
	University Heights	1,280	456	824	
11	Van Nest / Pelham Parkway	1,920	640	1,280	554
11	Woodlawn / Williamsbridge	572	0	572	
12	Tremont / West Farms *	1,484	912	572	456
13	Park Slope / Prospect Heights	640	640	0	640
	DUMBO/ Navy Yard / Fort Greene	2,777	1,953	824	333
14	Williamsburg / Greenpoint *	1,563	991	572	
	Sunset Park	2,610	1,096	1,514	445
15	Park Slope	2,744	1,464	1,280	
	Carroll Gardens / Gowanus / Red Hook	2,192	1,280	912	436
19	Cypress Hills / East New York	1,000	1,000	0	1,000
	Owls Head Park / Bay Ridge	3,337	2,037	1,300	976
20	Dyker Heights	4,647	1,920	2,727	332
	Borough Park / Kensington, Bensonhurst	2,338	912	1,426	
	Coney Island	476	0	476	
21	Gravesend	1,504	912	592	912
	Gravesend/Ocean Parkway	456	0	456	
22	Flatlands / Midwood	476	0	476	
22	Mill Basin	824	456	368	
	North Corona / South Corona / Lefrak City / Elmhurst	5,288	3,200	2,088	2,477
24	Maspeth / South of Woodside	1,853	912	941	728
24	Middle Village	1,786	773	1,013	773
	Glendale, Ridgewood	476	0	476	
25	Beechhurst / College Point / Whitestone	3,066	1,464	1,602	548
23	Flushing / Murray Hill / Willets Point	2,057	757	1,300	600
26	Oakland Gardens / Fresh Meadows	1,464	456	1,008	
20	Bayside / Auburndale	1,040	468	572	468
27	Howard Beach / Lindenwood	640	516	124	516
21	Ozone Park / South Ozone Park / Richmond Hill / Woodhaven	1,096	456	640	124
28	South Jamaica / Rochdale / Kew Gardens	476	0	476	
20	Rego Park / Forest Hills / Kew Gardens / Jamaica	3,162	1,920	1,242	1,074
	East Elmhurst / Jackson Heights	1,397	912	485	476
30	Woodside / Sunnyside	1,550	824	726	824
30	Long Island City / Ravenswood	2,028	1,800	228	1,184
	Astoria / Steinway *	1,000	1,000	0	
	West Shore	456	456	0	
31	New Dorp	476	0	476	
	North Shore	2,416	1,280	1,136	1,280
ueens High)	School	6,880	2,802	4,078	1,476
taten Island	High School	400	345	55	345
Total		82,811	44,324	38,487	22,771

*Area includes the project funded for design only.

Note: 2,601 seats identified above are funded for design in this plan and construction in the next plan.

The new school buildings funded for construction in the Proposed Amendment are:

- 46 projects for small primary school buildings, grades prekindergarten-5
- 31 projects for larger buildings which can be flexibly programmed for primary, middle or planned two separate schools to be co-located
- Four projects for middle/high school buildings to serve secondary or high schools

The Plan provides for the creation of seats in every borough. This includes five projects for PS or PS/IS school buildings in Manhattan, 11 in the Bronx, 26 in Brooklyn, 27 in Queens, and four in Staten Island. Of the four projects for IS/HS school buildings proposed, one will be located in Staten Island and three in Queens. In addition, 2,601 seats (in four buildings) are funded for design in this plan and construction in the next plan.

New Capacity Summary by Borough

		S MALL PS			PS/IS			IS/HS			TOTAL	
DISTRICT	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST
MANHATTAN												
1	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
2*	3	1,368	\$108.06	2	1,782	\$141.91	0	0	\$0.00	5	3,150	\$249.97
3	0	0	\$0.00	1	692	\$106.57	0	0	\$0.00	1	692	\$106.57
4	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
5	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
6	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
MANHATTAN TOTAL	3	1,368	\$108.06	3	2,474	\$248.48	0	0	\$0.00	6	3,842	\$356.54
BRONX												
7	1	456	\$36.80	0	0	\$0.00	0	0	\$0.00	1	456	\$36.80
8	2	456	\$79.57	0	0	\$0.00	0	0	\$0.00	2	456	\$79.57
9	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
10	3	1,412	\$155.89	2	1,604	\$129.23	0	0	\$0.00	5	3,016	\$285.12
11	0	0	\$0.00	2	640	\$59.48	0	0	\$0.00	2	640	\$59.48
12*	2	912	\$26.15	0	0	\$0.00	0	0	\$0.00	2	912	\$26.15
HS	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
BRONX TOTAL	8	3,236	\$298.41	4	2,244	\$188.71	0	0	\$0.00	12	5,480	\$487.12
BROOKLYN												
13	1	476	\$38.13	4	2,117	\$234.01	0	0	\$0.00	5	2,593	\$272.14
14*	1	379	\$3.55	1	612	\$30.07	0	0	\$0.00	2	991	\$33.62
15	3	881	\$100.86	4	2,959	\$231.82	0	0	\$0.00	7	3,840	\$332.68
16	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
17	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
18	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
19	0	0	\$0.00	1	1,000	\$76.52	0	0	\$0.00	1	1,000	\$76.52
20	6	2,984	\$231.19	3	1,885	\$131.80	0	0	\$0.00	9	4,869	\$362.99
21	2	912	\$105.97	0	0	\$0.00	0	0	\$0.00	2	912	\$105.97
22	1	456	\$22.42	0	0	\$0.00	0	0	\$0.00	1	456	\$22.42
23	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
32	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
HS	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
BROOKLYN TOTAL	14	6,088	\$502.12	13	8,573	\$704.22	0	0	\$0.00	27	14,661	\$1,206.34

New Capacity Summary by Borough (cont.)

		S MALL PS			PS/IS			IS/HS			TOTAL	
DISTRICT	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST	# BLDGS	# SEATS	COST
QUEENS												
24	4	2,015	\$228.10	5	2,870	\$321.73	0	0	\$0.00	9	4,885	\$549.83
25	3	1,305	\$175.88	1	916	\$37.12	0	0	\$0.00	4	2,221	\$213.00
26	2	924	\$115.77	0	0	\$0.00	0	0	\$0.00	2	924	\$115.77
27	3	972	\$156.73	0	0	\$0.00	0	0	\$0.00	3	972	\$156.73
28	2	1,074	\$130.56	1	846	\$41.56	0	0	\$0.00	3	1,920	\$172.12
29	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00	0	0	\$0.00
30*	4	2,096	\$200.10	3	2,440	\$124.40	0	0	\$0.00	7	4,536	\$324.50
HS	0	0	\$0.00	0	0	\$0.00	3	2,802	\$237.41	3	2,802	\$237.41
QUEENS TOTAL	18	8,386	\$1,007.14	10	7,072	\$524.81	3	2,802	\$237.41	31	18,260	\$1,769.36
STATEN ISLAND												
31	3	1,427	\$110.51	1	309	\$12.77	0	0	\$0.00	4	1,736	\$123.28
HS	0	0	\$0.00	0	0	\$0.00	1	345	\$97.14	1	345	\$97.14
STATEN ISLAND TOTAL	3	1,427	\$110.51	1	309	\$12.77	1	345	\$97.14	5	2,081	\$220.42
CITYWIDE TOTAL	46	20,505	\$ 2,026.24	31	20,672	\$1,678.99	4	3,147 \$	334.55	81	44,324	\$4,039.78
CITYWIDE SITE ACQUISITION COSTS											S	5 341.99
GRAND TOTAL INCLUDING SITE ACQUISITION												\$4,381.77

*District which includes seats that are funded for design in this Plan and construction in the next Plan.

Notes: Number of projects may vary depending upon availability and configuration of sites and appropriate leased spaces. All dollar amounts are represented in millions. Excludes \$97.63 mm for potential site specific/environmental/code costs.

In recent years, our population of students with disabilities has increased. This is true of students served by District 75 and those included in districtbased programs located in schools that serve both general education and students with disabilities. The FY2005–2009 and FY 2010–2014 Capital Plans provided approximately 6,800 seats in newly constructed buildings for District 75 use with additional classrooms provided for district-based programs. In this plan, the SCA continues to respond to the enrollment growth of students with disabilities by providing approximately 3,000 seats in our capacity projects.

Pre-Kindergarten for All Initiative

SUMMARY
Proposed Amendment
\$800.0 mm
2016 Adopted
Amendment
\$670.0 mm

The Capital Plan recognizes the commitment and desire to implement a truly universal full day pre-kindergarten program. The SCA has identified the major expansion and enhancement to the existing prekindergarten program as a critical objective. In order to support this goal, the Pre-Kindergarten for All Initiative will address the capital investments needed Citywide to increase the number of seats for full day prekindergarten.

Funding in this category allows for the expansion of the number of prekindergarten classrooms in new buildings that are being constructed for elementary use, as well as leasing space for pre-kindergarten centers. In seeking opportunities to lease non-traditional space, the SCA opens a new avenue of possibilities that previously went untapped. Investments in our future will ensure a greater availability and distribution of prekindergarten seats than currently available.

The Pre-Kindergarten for All Initiative provides for the creation of seats in every borough, opening high quality opportunities, and closing the access gap for neighborhoods throughout the City. The list of pre-kindergarten centers that are in design or construction can be found in the appendices.

Class Size Reduction Program

SUMMARY
Proposed Amendment
\$490.0 mm
2016 Adopted
Amendment
\$490.0 mm

The Class Size Reduction Program recognizes the need for targeted investments to build additions or new buildings near school buildings that would significantly benefit from additional capacity. The \$490 million program signals a significant investment and commitment to reducing class sizes system wide by creating approximately an additional 4,900 seats.

A multi-disciplinary group comprised of representatives from the Office of Space Planning, the Office of Student Enrollment, the Division of Operations, and the School Construction Authority meet on a regular basis to discuss and evaluate which school buildings may benefit most from the funding in this category and to establish the criteria to be used when choosing school buildings. Some of the criteria to be considered include:

- 1. High rate of overutilization per enrollment and capacity figures established by the latest Enrollment, Capacity, and Utilization Report;
- 2. Unfunded seat need in the sub-district where school building is located;
- 3. Use of Transportable Classroom Units;
- 4. Geographic isolation.

With this Amendment, the SCA identifies the first Class Size Reduction projects:

Borough	District	Building Name	Address
Bronx	11	P.S.19	4318 Katonah Avenue
Brooklyn	19	East New York Family Academy	2057 Linden Boulevard
Queens	29	P.S. 131	170-45 84th Avenue

Facility Replacement Program

SUMMARY
Proposed Amendment
\$62.0 mm
2016 Adopted
Amendment
\$62.0 mm

The Facility Replacement Program allocates \$62 million to provide for the development of seats for schools that must be relocated. The seats will be provided through new construction or alternative leasing opportunities, similar to new capacity. Current projects under the Facility Replacement program are found in the appendices and additional sites will be included in the Plan as they are identified.

CAPITAL INVESTMENT

Capital Investment

Introduction

SUMMARY
Proposed Amendment
\$5,972.9 mm
2016 Adopted
Amendment
\$5,514.7 mm

The **Capital Investment** category includes two elements: the Capital Improvement Program and School Enhancement Projects. The capital improvements for existing facilities included in the FY2015–2019 Proposed Amendment continue the SCA's effort to provide a safe and comfortable learning environment. The Capital Improvement Program (CIP) consists of a wide range of construction projects, including building repairs and system replacements. Our efforts to improve the quality of our school buildings have been effective, but the size and age of our building inventory drives the continuing need to invest. School Enhancement Projects provide enhancements to existing facilities to support modern instructional models.

Capital Improvement Program

SUMMARY	
Proposed Amendment	
\$3,803.5 mm	
2016 Adopted	
Amendment	
\$3,616.8 mm	

The emphasis of the FY2010-2014 Five-Year Plan was on exteriors in order to safeguard existing buildings from water infiltration and interior improvements. Because of the size and age of our inventory, the efforts to safeguard existing buildings from water infiltration will continue and, to the extent our funding allows, additional resources are proposed to fund interior improvements.

The Capital Improvement Program for existing buildings totals \$3.8 billion. This funding allows the SCA to address only the most critical building elements: those rated a "5" (poor) by the Building Condition Assessment Survey (BCAS). In addition, a small number of building elements that were rated "3" (fair) or "4" (fair to poor), but have deficiencies that may adversely impact life safety or the structure of the

building will also be included. In some cases, exterior components rated "3" or "4" at buildings that are slated for extensive exterior work may be included as well.

Capital Improvement Program Overview		
Program	Proposed Amendment	2016 Adopted Amendment
Exterior	\$2,321.3 mm	\$2,146.5 mm
Interior	\$871.9 mm	\$830.0 mm
Other	\$80.3 mm	\$65.3 mm
TCU Removal and Playground Redevelopment	\$405.0 mm	\$450.0 mm
Athletic Field Upgrades	\$125.0 mm	\$125.0 mm
TOTAL	\$3,803.5 mm	\$3,616.8 mm

SUPER STORM SANDY UPDATE

Many of our school buildings sustained varying degrees of damage as a result of this storm. The Division of School Facilities (DSF) personnel undertook efforts in several buildings to address the storm damage. In more severely damaged buildings, emergency work was performed by the SCA. These efforts enabled the SCA to reopen these buildings in the fastest time frame possible to our school children, many of whom were displaced from their homes.

While this work allowed us to ensure the buildings were safe for occupancy, many buildings required more extensive work, and the SCA is well on its way to repairing the damage incurred. The SCA continues working with the Federal Emergency Management Agency (FEMA) to obtain assistance for the restoration and resiliency of the infrastructure in the Sandy affected buildings, remain committed to ensuring that all our Sandy impacted buildings are restored and strengthened and will work with our partners at the Federal, State and City level to secure this. Our commitment extends to all Sandy work, from the removal of the temporary heating systems to finishes in our school buildings. In the appendices, a separate list of the proposed projects is included in this Proposed Amendment.

Exteriors

SUMMARY	
Proposed Amendment	
\$2,321.3 mm	
2016 Adopted	
Amendment	
\$2,146.5 mm	

Water infiltration is the single greatest cause of accelerated deterioration of existing facilities. The costs stemming from water infiltration include measures needed to correct damage to interior walls, floors and ceilings, and also include related asbestos and lead abatement. For that reason, the last Five-Year Plan focused on making schools watertight. This Plan continues that important effort.

The major components of a building's exterior are roofs, parapets, windows, and masonry. If the BCAS ratings for any building indicated that any of these four major components were in "poor" condition, then most of the other major exterior components rated "3" or worse may be included in the project.

The proposed funding for exterior components is summarized below:

Exteriors Overview Program	Proposed Amendment	2016 Adopted Amendment
Flood Elimination	\$336.3 mm	\$325.5 mm
Reinforcing Support Elements	\$21.2 mm	\$15.0 mm
Reinforcing Cinder Concrete Slabs	\$19.2 mm	\$17.8 mm
Roofs	\$402.0 mm	\$345.6 mm
Parapets	\$357.4 mm	\$340.3 mm
Exterior Masonry	\$1,004.3 mm	\$929.1 mm
Windows	\$180.9 mm	\$173.2 mm
TOTAL	\$2,321.3 mm	\$2,146.5 mm

Interiors

The Five-Year Plan for interiors includes capital work identified by the BCAS and work required to support educational needs.

Components of the interior program include electrical upgrades, plumbing, low-voltage electrical systems, and mechanical systems that may be replaced rather than repaired based on age, condition and future ability to maintain.

Interior work in occupied buildings continues to be one of our most challenging undertakings. The SCA has developed extensive protocols to perform the most intrusive work over the summer months, schedule work after normal school hours during the year and work closely with the school communities to schedule work during holidays. This is not always the most cost effective means of performing the required work, but it assures the safety of our students and teachers and minimizes the disruption to the instructional program.

Interiors Overview		
Program	Proposed Amendment	2016 Adopted Amendment
Low-Voltage Electrical System	\$141.1 mm	\$147.9 mm
Interior Spaces	\$62.7 mm	\$54.8 mm
Cafeteria/Multipurpose Room		
(excludes SchoolFood's		
Initiative)	\$2.4 mm	\$0.8 mm
Climate Control (excludes		
Mandated Program)	\$71.5 mm	\$67.4 mm
Air Conditioning Retrofit	\$11.3 mm	\$11.1 mm
Boiler Conversions (excludes		
Mandated Program)	\$43.1 mm	\$39.5 mm
Elevators & Escalators	\$8.8 mm	\$8.8 mm
Floors	\$3.6 mm	\$3.4 mm
Electrical Systems (excludes		
projects under Facility		
Restructuring)	\$29.0 mm	\$40.2 mm
Toilets – Staff	\$0.1 mm	\$0.1 mm
Heating Plant Upgrade	\$422.2 mm	\$406.5 mm
Domestic Piping (non-		
mandated projects)	\$70.0 mm	\$42.8 mm
Safety Systems	\$6.1 mm	\$6.7 mm
TOTAL	\$871.9 mm	\$830.0 mm

The major interior system needs being addressed are summarized below:

Transportable Classroom Unit Removal/ Playground Redevelopment

SUMMARY	
Proposed Amendment	
\$405.0 mm	
2016 Adopted	
Amendment	
\$450.0 mm	

The SCA continues its commitment to remove TCUs across the City. The November 2016 Proposed Amendment supports this effort by allocating funding for the removal of all units. The schedule of removal of each unit is contingent upon capacity constraints within the area and the desires of local school communities. Several new capacity projects in the form of additions have been created in sites that currently contain TCUs. As a result of these additions, approximately 50 TCUs will be removed and the costs of the TCU removal will be included with the addition projects, which allows us to shift funding from the TCU category to the New Capacity category.

To date, 94 TCUs have been removed, and 104 out of the approximately 260 remaining TCUs are identified for removal.

DISTRICT	BUILDING NAME	NO OF TCUS
6	P.S. 5 TRANSPORTABLE - M	2
9	P.S. 28 TRANSPORTABLE - X	1
9	I.S. 117 TRANSPORTABLE - X	1
10	I.S. 80/P.S. 280 TRANSPORTABLE - X	4
11	P.S. 96 TRANSPORTABLE - X	11
11	P.S. 106 TRANSPORTABLE - X	5
18	P.S. 276 TRANSPORTABLE - K	8
18	P.S. 135 TRANSPORTABLE - K	2
18	P.S. 208 TRANSPORTABLE - K	4
18	P.S. 219 TRANSPORTABLE - K	1
18	P.S. 235 TRANSPORTABLE - K	4
18	P.S. 268 TRANSPORTABLE - K	1
18	P.S. 272 TRANSPORTABLE - K	3
20	P.S. 170 TRANSPORTABLE - K	2
22	P.S. 193 TRANSPORTABLE - K	2
22	P.S. 194 TRANSPORTABLE - K	1
24	P.S. 19 TRANSPORTABLE - Q	5
25	P.S. 24 TRANSPORTABLE - Q	2
27	RICHMOND HILL HS TRANSPORTABLE - Q	11
28	P.S. 55 TRANSPORTABLE - Q	3
28	P.S. 121 TRANSPORTABLE - Q	1
28	P.S. 140 TRANSPORTABLE - Q	4
29	P.S. 35 TRANSPORTABLE - Q	2
29	P.S. 38 TRANSPORTABLE - Q	3
29	P.S. 52 TRANSPORTABLE - Q	1
29	P.S. 176 TRANSPORTABLE - Q	2
29	P.S. 132 TRANSPORTABLE - Q	2
30	P.S. 70 TRANSPORTABLE - Q	2
30	P.S. 92 TRANSPORTABLE - Q	2
31	CURTIS HS TRANSPORTABLE - R	2
TOTAL # OF UNITS REMOVED		94

TCUs Removed To Date

TCUs with Removal Plan Identified

DISTRICT	BUILDING NAME	NO OF TCUS
3	P.S. 163 TRANSPORTABLE - M	2
6	P.S. 48 TRANSPORTABLE - M	2
7	CROTONA ACADEMY - X	8
8	P.S. 14 TRANSPORTABLE - X	2
10	J.F. KENNEDY HS TRANSPORTABLE- X	2
11	P.S. 97 TRANSPORTABLE - X	4
15	P.S. 32 TRANSPORTABLE - K	7
19	P.S. 214 TRANSPORTABLE - K	7
19	P.S. 290 TRANSPORTABLE - K	1
19	I.S. 302 TRANSPORTABLE - K	3
19	EAST NY FAMILY ACADEMY TRANS - K	6
20	P.S. 112 TRANSPORTABLE - K	1
21	P.S. 97 TRANSPORTABLE - K	2
22	P.S. 152 TRANSPORTABLE - K	2
22	P.S. 198 TRANSPORTABLE - K	2
22	P.S. 236 TRANSPORTABLE - K	2
24	P.S. 81 TRANSPORTABLE - Q	3
24	I.S. 125 TRANSPORTABLE - Q	4
24	P.S. 143 TRANSPORTABLE - Q	3
25	P.S. 129 TRANSPORTABLE - Q	2
25	P.S. 163 TRANSPORTABLE - Q	2
25	P.S. 193 TRANSPORTABLE - Q	1
26	BAYSIDE HS TRANSPORTABLE - Q	2
26	B. N. CARDOZO HS TRANSPORTABLE - Q	2
27	P.S. 66 TRANSPORTABLE - Q	1
27	I.S. 226 TRANSPORTABLE - Q	1
27	P.S. 155 TRANSPORTABLE - Q	2
28	P.S. 30 TRANSPORTABLE - Q	2
28	P.S. 40 TRANSPORTABLE - Q	3
28	P.S. 144 TRANSPORTABLE - Q	1
29	P.S. 33 TRANSPORTABLE - Q	1
29	P.S. 131 TRANSPORTABLE - Q	3
29	P.S. 156 TRANSPORTABLE - Q	2
30	P.S. 11 TRANSPORTABLE - Q	4
30	WILLIAM BRYANT HS TRANSPORTABLE-Q	3
31	PORT RICHMOND HS TRANS R	2
31	JOHN ADAMS HS	5
31	P.S. 37 TRANSPORTABLE - R	2
TOTAL # OF UNITS IN PROCESS OF BEING REMOVED		104
TOTAL # OF UNITS REMOVED AND IN PROCESS		198

Athletic Field Upgrades

SUMMARY
Proposed Amendment
\$125.0 mm
2016 Adopted
Amendment
\$125.0 mm

The SCA is expanding the physical fitness opportunities for our school children by undertaking a new initiative to upgrade existing athletic fields. The SCA has evaluated the condition of all existing athletic fields and will leverage limited resources to maximize the reach of this program.

School Enhancement Projects

SUMMARY
Proposed Amendment
\$1,505.8 mm
2016 Adopted
Amendment
\$1,410.1 mm

The projects in this category continue the work from the FY2010 - 2014 Plan to upgrade instructional spaces in existing buildings. The two main programs in this category are Facility Enhancements and Technology.

S Program	chool Enhancement Overv Proposed Amendment	riew 2016 Adopted Amendment
Facility Enhancements	\$855.8 mm	\$760.1 mm
Technology	\$650.0 mm	\$650.0 mm
TOTAL	\$1,505.8 mm	\$1,410.1 mm

Facility Enhancements

SUMMARY	
Proposed Amendment	
\$855.8 mm	
2016 Adopted	
Amendment	
\$760.1 mm	

The Facilities Enhancement Program funds facility adjustments that enable changes to instructional offerings in many buildings. This program complements new capacity investment by ensuring that space already in service is aligned with the goals of meeting demand, improving learning conditions, using resources efficiently, and improving student achievement. The Facilities Enhancement Program provides funding to enhance our safety and security systems, expand the functional accessibility of our facilities, and upgrade science, library, auditorium, bathroom and physical fitness facilities.

Facility Enhancements Overview		
Program	Proposed Amendment	2016 Adopted Amendment
Facility Restructuring	\$438.9 mm	\$365.4 mm
Safety & Security	\$100.0 mm	\$100.0 mm
Middle School Science Lab Upgrades	\$50.0 mm	\$50.0 mm
Accessibility	\$127.6 mm	\$100.0 mm
Physical Fitness Upgrades	\$27.2 mm	\$29.8 mm
Library Upgrades	\$1.3 mm	\$0.9 mm
Auditorium Upgrades	\$10.8 mm	\$14.0 mm
Bathroom Upgrades	\$100.0 mm	\$100.0 mm
TOTAL	\$855.8 mm	\$760.1 mm

Facility Restructuring

SUMMARY	
Proposed Amendment	
\$438.9 mm	
2016 Adopted	
Amendment	
\$365.4 mm	

The Facilities Enhancement Program funds facility adjustments that enable changes to instructional offerings in particular buildings. This program complements new capacity investment by ensuring that space already in service is aligned with the goals of meeting demand, improving learning conditions, using resources efficiently, and improving student achievement.

In the Proposed FY2015-2019 Capital Plan, the restructuring of existing buildings will include:

- Conversion of unused shops/extra-large classrooms to create more capacity;
- Construction of School Based Health Centers in Renewal Schools, and schools with Students in Temporary Housing;
- Electrical upgrades to buildings experiencing large increases in utilization rates that tax their electrical systems;

- A program to renovate cafeterias to support School Food's mission to promote healthy and attractive food choices to students while serving students more quickly and efficiently;
- Creation of community school features in existing schools in support of the Mayoral initiative.

Safety and Security

SUMMARY
Proposed Amendment
\$100.0 mm
2016 Adopted
Amendment
\$100.0 mm

The Safety Enhancements Program provides schools with state-of-the-art security technology as a key component of the SCA's comprehensive strategy to promote and sustain a climate of safety in all New York City public schools. Enhancements have been implemented through the prior two Capital Plans in the areas of network-based video surveillance, ID-card access control, radio communications, and metal detection. Innovation in these areas will continue throughout the Proposed Capital Plan.

During the FY 2015-2019 Plan, the SCA plans to continue the implementation of Internet Protocol Digital Video Surveillance (IPDVS). As of October 5, 2016, this application has been successfully implemented in 654 buildings serving 1,050 schools, with a total of 27,578 cameras online. The IPDVS application allows authorized school officials to view live and archived camera images directly on their computer stations and provides remote viewing capability to authorized personnel from borough and central offices. Updated IPDVS standards were issued in July 2015 to provide megapixel cameras with far superior image quality compared to cameras deployed in earlier years.

Middle School Science Lab Upgrades

SUMMARY
Proposed Amendment
\$50.0 mm
2016 Adopted
Amendment
\$50.0 mm

One of the SCA's priorities is to provide quality instruction in the sciences. The FY2010–2014 Capital Plan completed its goal of providing science facilities in all buildings housing high school students, where appropriate. The FY2015–2019 Proposed Amendment will continue the effort by providing middle school students with grade appropriate science facilities within their buildings.

Accessibility

SUMMARY
Proposed Amendment
\$127.6 mm
2016 Adopted
Amendment
\$100.0 mm

The SCA strives to offer access to a range of programs for students with mobility impairments and other physical disabilities. In keeping with prior Plans, the SCA will continue the program to provide additional accessible facilities throughout the City. A cross-functional committee including the Space Management Group, School Construction Authority, Division of School Facilities, Office of Student Enrollment, Division of Specialized Instruction, and the Office of the General Counsel's legal office works to identify specific projects and ensure equity across districts in providing access for students with physical disabilities. An additional \$27.6 million has been allocated in this Proposed Amendment to create projects in school buildings that are identified as emergency shelters.

Physical Fitness Upgrades

SUMMARY
Proposed Amendment
\$27.2 mm
2016 Adopted
Amendment
\$29.8 mm

The SCA understands the importance of incorporating physical fitness into the daily routine of school children. As such, the SCA is allocating funding to swimming pools and gymnasium upgrades as specified below. Other physical fitness upgrades include TCU Removals/Playground Redevelopment and Athletic Field Upgrades under Capital Improvements.

Physical Education Upgrades Overview		
Program	Proposed Amendment	2016 Adopted Amendment
Swimming Pools	\$15.3 mm	\$15.9 mm
Gymnasium Upgrades	\$11.9 mm	\$13.9 mm
TOTAL	\$27.2 mm	\$29.8 mm

Library Upgrades

SUMMARY
Proposed Amendment
\$1.3 mm
2016 Adopted
Amendment
\$0.9 mm

Library upgrades include work related to refurbishing existing library facilities within our schools. School libraries provide resources to support curriculum, instruction, and specialized efforts geared to improving student literacy.

Auditorium Upgrades

SUMMARY
Proposed Amendment
\$10.8 mm
2016 Adopted
Amendment
\$14.0 mm

Auditorium upgrade projects may include stage and auditorium lighting, sound system upgrades, replacement of seating, stage curtains and rigging, and renovation of the stage. These spaces serve an important function as central gathering places for the school population and often serve as a vital community resource for the surrounding neighborhood as well. As such, the resources identified in this category will be applied strategically to ensure the maximum benefit possible.

Bathroom Upgrades

SUMMARY
Proposed Amendment
\$100.0 mm
2016 Adopted
Amendment
\$100.0 mm

As our large inventory of buildings age, the need to upgrade certain facilities within our buildings becomes more pressing. Bathroom upgrades are frequently requested. Although bathrooms are functional, some may be outdated. Under this Proposed Amendment, the SCA continues the new program to upgrade student bathrooms. A list of the identified buildings receiving bathroom upgrades is included in the appendices.

Technology Enhancements

SUMMARY
Proposed Amendment
\$650.0 mm
2016 Adopted
Amendment
\$650.0 mm

Funding in the FY2015-2019 Plan, besides increasing bandwidth connectivity in schools, will increase the capacity of each classroom to support ever-more widespread and intensive use of web-enabled devices to access a range of digital learning tools. This investment in bandwidth is critically important to the implementation of a range of DOE instructional priorities – including Computer Science for All, the City's commitment to ensuring that all students have the opportunity to receive computer science instruction, and associated programs including the Software Engineering Program and Advanced Placement Computer Science courses.

The integration of technology into instruction is increasingly prevalent not only in computer science, but across subject areas. Digital tools support teaching and learning in subjects ranging from reading, to social studies, to algebra, and beyond. Accordingly, the number of web-enabled devices present in schools is expected to continue to increase substantially over the period of this plan. New devices funded by tech-focused grants from New York State and other entities, coupled with the City's recent lift of the ban on student cell phones in schools, will place unprecedented demand upon the SCA's internet infrastructure. Additionally, this investment in infrastructure supports growing use of web-based tools to engage a parent around their students' academic work, and in the life of their schools more generally.

The New York State Education Department (NYSED) has also communicated to districts its intent to transition to computer-based testing (CBT). Starting in 2016, the New York State Alternate Assessment (NYSAA) will be administered using a computer-adaptive assessment, and there will be field testing of computer-adaptive assessments in English Language Arts (ELA) and Mathematics in grades 3 through 8. Beginning in 2017, NYSED intends to offer the option of completing ELA and Math assessments online, and in the years that follow to transition fully to CBT. Large portions of a school's student population will be accessing online assessment portals simultaneously, and schools must have the bandwidth capacity to ensure that students do not become disconnected or experience performance issues during assessments.

The DOE will mitigate the risks of any problems occurring as well as strengthen our digital network through investing in the necessary upgrades to provide increased broadband capacity to our schools. 61 percent of the current proposed technology funding in this Plan has been targeted to support the expansion of the existing building infrastructure. This investment will provide for the upgrades to our Wireless/Wide and Local Area Network (W/LAN) to accommodate higher connection speeds with intensive concurrent users in the schools. The existing hardware in schools will need to be upgraded or replaced to allow it to accept new high-speed digital links. Network cabling and Internet links must also be upgraded to handle more capacity. The modern classroom is quickly becoming an "always connected learning atmosphere" and these upgrades will complement and support any upcoming technology challenges and initiatives for schools in addition to supporting the rollout of the online assessment initiative.

A portion of the 61 percent of current proposed technology funding will be allocated to support the complete overhaul of the Wide Area Network (WAN). The current WAN infrastructure was completed in 2005, before the rise to popularity of digital instructional tools. The bandwidth needs and standards were different at the time and the best solution available was chosen. But that was over a decade ago, and the newly generally accepted standard from the NYSED and Federal Communications Commission in E-Rate Modernization Order is 100 Mbps per 1,000 students. То accommodate for this standard, NYCDOE will upgrade the decade old WAN and focus efforts to modernize the school building's backbone infrastructure. New York City's SSBA allocation of \$383 million will help support the cost to modernize the public school building backbone infrastructure. About \$88 million will be used for classroom technology which includes laptops, tablets, and desktops to be disbursed throughout the five boroughs. This will afford students more access to educational applications aimed at differentiated instruction and blended learning programs such as iLearn to make the classroom more students centered.

Supporting digital learning and teaching initiatives require that our school buildings have the ability to accommodate the ancillary devices and components that allow students and educators to connect to the Internet or servers where digital resources reside. Many of DOE's buildings will require modernized electrical systems that can provide the electrical capacity necessary for a digital learning environment. Likewise, the copious amounts of data used by digital learners travel through cables that were installed when schools used considerably less data and had fewer connected devices. Cabling and electrical upgrades are vital aspects of enabling schools to utilize the latest educational technologies. The proposed technology funding allocates approximately 17 percent to upgrade these critical building elements.

This Capital Plan will also invest 22 percent of the technological enhancement budget to upgrade basic education business initiatives that help administrators support the goals and efforts of students and educators throughout the schools. These initiatives will upgrade and improve DOE's existing student information systems, provide greater network security, and allow for greater mobility for its users within the system. These initiatives will also improve data management systems that will help the DOE better support and meet critical business and programmatic mandates while improving organizational efficiency.

Technological Enhancements Summary			
Enhancement	Proposed Amendment	2016 Adopted Amendment	
Next Generation Voice and Data Upgrade	\$246.9mm	\$246.9mm	
Next Generation Access Points Upgrade	\$101.8mm	\$101.8mm	
Next Generation School Data Wiring Upgrades	\$46.8mm	\$46.8mm	
School Electrification Upgrades	\$64.6mm	\$64.6mm	
Ancillary Technology Facilities Upgrade	\$44.5mm	\$44.5mm	
Non-Infrastructure Projects	\$145.4mm	\$145.4mm	
TOTAL	\$650.0mm	\$650.0mm	



Mandated

Introduction

SUMMARY
Proposed Amendment
\$3,676.6 mm
2016 Adopted
Amendment
\$3,659.3 mm

This new category collects a number of items that were previously included in the Capital Investment category such as lighting replacements, boiler conversions, asbestos remediation, lead paint abatement, funding for projects mandated by local law or City agency mandates, performing building condition surveys, emergency lighting, code compliance, and insurance.

Mandated Programs Overview		
Program	Proposed Amendment	2016 Adopted Amendment
Lighting Replacements	\$480.0 mm	\$480.0 mm
Boiler Conversions and associated Climate Control	\$750.0 mm	\$750.0 mm
Asbestos Remediation	\$181.5 mm	\$179.8 mm
Lead Paint Removal	\$11.3 mm	\$11.2 mm
Emergency Lighting	\$38.4 mm	\$38.9 mm
Code Compliance	\$124.4 mm	\$124.0 mm
Building Condition Surveys	\$81.1 mm	\$86.4 mm
Wrap Up Insurance	\$881.8 mm	\$831.7 mm
Prior Plan Completion	\$660.2 mm	\$661.6 mm
Emergency, Unspecified & Miscellaneous	\$467.9 mm	\$495.7 mm
TOTAL	\$ 3,676.6 mm	\$ 3,659.3 mm

Lighting Replacements

SUMMARY
Proposed Amendment
\$480.0 mm
2016 Adopted
Amendment
\$480.0 mm

The Five Year Capital Plan is allocating \$480 million to remove all PCBcontaining light fixtures from New York City public school buildings. While removing all PCB-containing light fixtures is mandated, the SCA will continue seeking ways to further support and enhance our sustainability measures by ensuring the current light fixtures are replaced with energy efficient units. On May 21, 2013, the City entered into an agreement to accelerate the original 10-year plan that started in 2011 to complete the lighting replacements by December 31, 2016. The total cost of this program is anticipated to be approximately \$1 billion.

By the end of the FY2010–2014 Capital Plan, the City had started or completed lighting replacements at 412 buildings with T-12 fixtures likely to have PCB-containing ballasts. Between the 2010-14 and 2015-19 Capital Plans, 927 lighting projects have been completed, and 13 are under construction and will be complete by December 2016. Additionally, the Amendment includes funding to ensure replacement of older High Intensity Discharge (HID) lighting within our buildings.

The SCA continues to undertake periodic visual inspections of all lighting fixtures suspected of containing older ballasts that may have deteriorated and have visible leaks. When leaking fixtures are identified they are replaced immediately and the building is prioritized for scheduling building-wide lighting replacements. As additional leaks are identified, the SCA will continue to inform school communities, update our records, and take appropriate action. The complete list of buildings with confirmed visual leaks can be found at:

DOE Buildings with Confirmed Visual Leaks

The list of buildings that have had comprehensive lighting replacement projects completed can be found at: DOE Buildings with Completed Lighting Replacement Projects

Boiler Conversions

SUMMARY
Proposed Amendment
\$750.0 mm
2016 Adopted
Amendment
\$750.0 mm

The SCA will continue to phase out use of Number 4 oil which is mandated to be eliminated by 2030. The SCA has allocated \$750 million to convert boilers at approximately 125 of 380 buildings currently using Number 4 oil. Eliminating the use of heavy oils and transitioning to the cleanest fuels will comply with this mandate. The SCA will continue seeking ways to enhance our sustainability measures by ensuring more energy efficient units are replacing the current boilers. This level of spending paces boiler conversions evenly across the Capital Plans between now and the 2030 mandate.

Asbestos Abatement

SUMMARY
Proposed Amendment
\$181.5 mm
2016 Adopted
Amendment
\$179.8 mm

The SCA's Asbestos Abatement program is federally mandated by the Asbestos Hazard Emergency Response Act (AHERA) of 1986. The Act requires that every public and private school building be inspected once every three years. The location of any asbestos must be documented and a plan must be developed for the continuous management of the asbestos in the building.

Asbestos abatement removes the potential health hazard presented by airborne asbestos fibers. In schools, asbestos is found most commonly in pipe and boiler insulation, plaster, floor tiles, and spray-on insulation. Only asbestos in a loosely bound or "friable" condition is dangerous and must be removed. Asbestos must be removed from construction areas prior to being disturbed during construction or maintenance activities.

The cost of asbestos abatement is included in the individual project costs for building modernizations and individual interior and exterior upgrades where asbestos is present. This funding category provides for abatement of disturbed asbestos in buildings where no related major capital projects are planned.

Lead Abatement

SUMMARY
Proposed Amendment
\$11.3 mm
2016 Adopted
Amendment
\$11.2 mm

Lead paint abatement is mandated by US Environmental Protection Agency and New York City Department of Health and Mental Hygiene (DOHMH) regulations. The targeted population includes prekindergarten, kindergarten, day care in schools, special education, and first grade students. The SCA continues to remediate areas identified by lead inspections and DOHMH referrals.

Lead abatement is included as an integral part of individual capital projects that affect surfaces that may contain lead paint, *e.g.*, window replacement and the removal of paint from exterior walls prior to repointing. This proposed funding provides for lead paint abatement in buildings where no related major capital projects are planned.

In addition, the DOE continues to test schools for the presence of lead in drinking water and perform remediation when necessary. The water in every NYC public school was tested for lead in 2016. The vast majority are confirmed negative, and for those buildings that had even one outlet with results above recommended levels, the DOE has been implementing a protocol, approved by DOHMH and based on EPA guidance, involving a combination of flushing, equipment replacement, and re-testing to ensure the safety of students and faculty.

Emergency Lighting

SUMMARY
Proposed Amendment
\$38.4 mm
2016 Adopted
Amendment
\$38.9 mm

This category funds the SCA's continuing program to bring all school buildings into compliance with the emergency lighting requirements of Local Law 41/78 (Fire Safety in Places of Public Assembly), Local Law 16/84 (Fire Safety in Buildings), Local Law 26/04 (Power Source for Exit Signs). These laws establish minimum standards for emergency lighting, exit lighting, emergency power and elevator safety. These local laws apply retroactively to most school buildings. All school buildings are assessed for compliance with these requirements and necessary upgrades are proposed. Documentation showing compliance is filed at the Department of Buildings when the assessments are completed.

Code Compliance with NYC Building Code and other City Agency Regulations

SUMMARY
Proposed Amendment
\$124.4 mm
2016 Adopted
Amendment
\$124.0 mm

Similar to emergency lighting, this category is an ongoing program to bring all school buildings into conformance with safety-related regulations. Although many DOE schools are old enough to pre-date the New York City Building Code, code requirements relating to life and fire safety systems apply retroactively so that buildings that are not in compliance must be retrofitted accordingly. Local Law 10 (Owners' Inspection of Building Facades) and its successor legislation, Local Law 11, require that the exterior masonry for buildings over a certain height be inspected every five years. If hazardous conditions are discovered during an inspection, a sidewalk shed must be installed immediately and plans to make the necessary repairs must be developed. Local Law 5 (Fire Safety in High Rise Buildings) mandates the installation of fire alarm systems in buildings over a certain size so that the Fire Department can override the elevators' operations in the event of an emergency.

Building Condition Surveys

SUMMARY
Proposed Amendment
\$81.1 mm
2016 Adopted
Amendment
\$86.4 mm

Keeping the baseline data of building conditions in school facilities up-to date is essential to the SCA's ability to program capital improvement projects. The SCA conducts annual BCAS reports in preparation for the Five-Year Plan and its Amendments.

Wrap-Up Insurance

SUMMARY						
Proposed Amendment						
\$881.8 mm						
2016 Adopted						
Amendment						
\$831.7 mm						

Since 1990, the SCA has maintained an Owner Controlled Insurance Program (OCIP) that provides insurance coverage for the SCA, contractors and subcontractors working on SCA projects. Rather than the traditional approach of having each contractor and subcontractor procure its own insurance, the SCA negotiates and purchases coverage for Worker's Compensation and Employer's Liability, General Liability, Excess Liability, and Builder's Risk. The cost of this program is uncertain, and the annual cost will depend upon the ultimate loss experienced.

Prior Plan Completion Cost

SUMMARY
Proposed Amendment
\$660.2 mm
2016 Adopted
Amendment
\$661.6 mm

Many projects funded in the FY 2010–2014 Plan will still be in progress during this Five-Year Capital Plan period. Although construction contracts are obligated in the FY 2010–2014 Capital Plan, other costs, such as furniture and equipment purchases, as well as construction change orders, may occur during the FY 2015–2019 Capital Plan period. This category provides the funding to complete these projects after the end of FY2014.

Emergency, Unspecified & Miscellaneous

SUMMARY
Proposed Amendment
\$467.9 mm
2016 Adopted
Amendment
\$495.7 mm

Any building condition found to be potentially dangerous will be immediately referred to the SCA for further evaluation. If necessary, sidewalk bridging will be installed immediately as a safeguard for the entire school community. If any condition is found to need immediate attention, capital funding from the Plan's Emergency, Unspecified & Miscellaneous allocation will be used to remedy the condition without delay.

This lump sum funding allows the SCA to respond to emergencies and unforeseeable needs without having to divert funds from other projects. By law, this amount cannot exceed five percent of the total estimated cost of the Five-Year Plan.

FINANCING STRATEGY

Capital Plan Funding

The Five Year Capital Plan has historically been funded almost equally between the City and State, with potential additional funding for specific projects from federal programs, the NYC Education Construction Fund (ECF), and privately raised funds.

This Capital Plan is funded differently than past plans, with \$15.4 billion for fiscal years 2015 - 2019 from Federal, City and State tax levy, inclusive of \$783 million from the Smart Schools Bond Act.

Note: \$ in billions										
Total	\$ 2.755	\$ 2.621	\$	4.056	\$	3.108	\$	2.900		
Federal/Other	\$ 0.314	\$ 0.135	\$	0.003						
State	\$ 1.017	\$ 0.257	\$	0.398	\$	0.672	\$	0.195		
City	\$ 1.424	\$ 2.229	\$	3.655	\$	2.436	\$	2.705		
Funding Source	FY 15	FY 16 FY 17		FY 17 FY 18		FY 17 FY 18		F	FY 19	

The proposed funding will support the SCA's goals of improving educational performance and sustaining the diverse portfolio of existing facilities in good repair.

38 percent of total funding is for the creation of over 57,400 new seats, which include 44,324 seats in 81 new projects, almost 8,200 prekindergarten seats, and 4,900 seats specifically targeted towards Class Size Reduction. In addition, over 700 seats will be created to replace sites that must vacate their current locations.

38 percent of the total funding is targeted toward capital investment in basic facility needs and enhancing school facilities, both system-wide and specifically to support instructional programs. These improvements include improved technology, safety enhancements and other general improvements to the learning environments.

The remaining 24 percent of the total funding is dedicated to mandated programs.

To complement the Plan funding, both City and State elected officials generally allocate additional capital funds for specific projects at individual schools. These funds are targeted towards the specific schools' needs in areas such as technology, science laboratories, sports/athletic fields,

playgrounds, bathrooms other quality-of-life facility and upgrades/enhancements. The City's elected officials allocated, on average, \$70 million to \$100 million annually during the FY 2010-2014 Plan period. Some State elected officials have also sponsored capital projects in individual schools through various Grant Programs administered by the NYS Dormitory Authority, such as the Community Capital Assistance Program (CCAP), New York State Technology and Development Program (NYS TAD), New York State Economic Development Assistance Program (NYS EDAP), and the State and Municipal Facilities Program (SAM). The SCA greatly appreciates the support of these contributions which are an additional source for enhancements in buildings throughout the City.

The SCA will continue to work with ECF and its private partners to investigate appropriate financing options to supplement and/or leverage the City and State funding over the five-year Plan period. The SCA will also continue to be diligent in its effort to pursue new federal programs pertaining to financing and funding technology infrastructure.

PROPOSED FIVE-YEAR PLAN PREPARATION

New Capacity

The New Capacity portion of the plan is based upon an enormous volume of data that the SCA collects and analyzes each year in order to accurately forecast when and where additional seats will be needed. These data include the capacity of existing schools, as well as demographic projections of future student enrollment, including increased demand resulting from projected new housing. Ultimately, if the demand is greater than the supply, the school is deemed overcrowded.

Current Utilization

The first step in identifying new capacity needs is to assess existing school facilities. The SCA maintains an inventory of the amount of space and utilization of every DOE facility. This allows the SCA to ensure that space is being used efficiently before proposing to spend capital funds on the creation of additional seats.

Each year the SCA conducts a Principal Annual Space Survey (PASS) to update its information regarding the size, function, and use of each room in every school building. School principals complete the surveys, which are then analyzed to determine capacity. Building capacity is defined as the target number of students who can be accommodated reasonably in a facility without adversely affecting educational services and programs. The utilization rate for each school building is then determined by comparing capacity with actual enrollment figures.

The detailed results of this analysis on a school-by-school basis can be found on the NYC School Construction Authority website, <u>www.nycsca.org</u>, in the report entitled "Enrollment, Capacity, Utilization Report for School Year 2015–2016," known as the "Blue Book."

Enrollment Projections

The next task in developing the capacity program is to project the future demand for seats. The enrollment projection process entails 128 separate demographic projections, taking into account the unique migration, birth and enrollment trends in each Community School District. These projections are used to develop total enrollment projections by District, Borough and the City as a whole. Projections are prepared for five years and ten years into the future in order to ensure that capital funds are not expended to meet only short-term anomalies in enrollment.

These detailed projections can be found on the NYC School Construction Authority website, <u>www.nycsca.org</u> in the report entitled "Enrollment Projections 2015 to 2024 New York City Public Schools."

New Capacity Needs Assessment

The enrollment projections for year 2019 were used to determine future utilization for this Capital Plan. This is, in effect, a supply and demand analysis. The future enrollment projections are compared to the existing capacity of seats in school buildings. When demand exceeds supply, additional seats must be provided or overcrowding will result. This analysis was performed below the district level. Areas within each district were analyzed to determine need and recommendations were developed accordingly.

In order to project future utilization accurately, it is necessary to fine-tune the analysis. The cohort survival projection methodology used by the SCA's demographers takes into account, either explicitly or implicitly, most of the factors that affect enrollment. These include migration within the City, in-migration to the City from outside, movement out of the City, births, transfers, long-term absences and dropouts. However, policy changes and international economic and political events can undo even the best projections. For example, dramatic economic trends or changes in federal immigration policy may result in unforeseeable increases or decreases in enrollment. In addition, new housing development projects can stress the local schools by introducing an influx of new students. The SCA carefully tracks new housing starts and builds the expected increase in school-age population into projections.

Existing Facilities

Background

Preparation of the Capital Improvement Program (CIP) begins with a baseline survey of the SCA's approximately 130,000,000 square feet of space, including school buildings, administrative buildings, leased facilities, annexes, mini-schools, temporary buildings, and field houses.

Methodology

Each year, a detailed visual inspection of each school facility is conducted by a four-person team consisting of two architects, an electrical engineer and a mechanical engineer. Each team member carries a hand-held computer programmed with over 2,000 possible deficient conditions. Averaging one school per day, the inspectors visually assesses each facility's physical condition. The teams rate each building's main systems and underlying components, identifying and quantifying any deficiencies.

The condition of each building system is assessed in various ways beginning with interviewing building personnel, including the principal(s) and custodian, quantifying the existing deficiencies through a visual inspection, reviewing violation information and assessing the remaining useful life. This assessment is performed at a component level and then the information is combined to present an evaluation of the overall system condition.

After the building deficiencies are identified, a software program is used to assign order of magnitude costs to repair each deficiency. This data is then grouped into capital projects falling into one of 60 capital planning categories. Once the projects are created, an analysis is conducted to ensure that the project costs reflect the approximate budget necessary to accomplish the needed repair.

The 2015-2016 BCAS reports for every DOE school building can be found on the DOE website, <u>http://schools.nyc.gov</u>. These reports are located under the reports section of each school's website.

KEY STEPS AND DATES FOR APPROVAL OF THE PROPOSED AMENDMENT

November 2016	Proposed Amendment released
November 2016- January 2017	Meet with Community Education Councils and other community representatives
February 2017	Issue a revised Amendment to the Panel for Educational Policy
Spring 2017	Vote on Proposed Amendment by the Panel for Educational Policy Submit Panel-approved Proposed Amendment to Mayor and City Council
June 2017	Adoption by City Council

APPENDICES TABLE OF CONTENTS

Plan Summary	C-1
Borough of Bronx Summary	X-1
Borough of Brooklyn Summary	K-1
Borough of Manhattan Summary	M-1
Borough of Queens Summary	Q-1
Borough of Staten Island Summary	R-1
Capacity Listing by Borough	CR -1
FY 2015 – FY 2019 Capacity Program Site Locations	CR-5
FY 2010 – FY 2014 Capacity Projects in Process Site Locations	CR-7
Pre-Kindergarten Projects	CR-8
Pre-Kindergarten Site Locations	CR-12
Facility Replacement Program	CR-14
Project Listing by Borough	
Bronx	X -1
Brooklyn	K -1
Manhattan	M -1
Queens	Q-1
Staten Island	R -1

FY15 0.00 0.00 0.02	FY16 0.00 0.01	FY17	FY18 0.00	FY19	Total
0.00		0.00	0.00	0.00	
0.00		0.00	0.00	0.00	
0.00		0.00	0.00	0.00	
	0.01			0.00	0.00
	0.01				
0.02	0.01	0.00	0.00	0.00	0.01
	0.01	0.00	0.00	0.00	0.03
0.08	0.09	0.00	0.00	0.00	0.17
39.77	36.70	35.00	35.00	35.00	181.47
32.26	70.81	146.20	223.83	142.77	615.88
39.82	21.81	56.06	72.95	58.12	248.77
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
61.64	28.11	27.66	14.35	9.37	141.14
207.96	152.72	106.78	12.54	0.01	480.00
2.63	2.25	2.27	1.44	0.24	8.83
8.22	1.06	8.02	0.82	1.05	19.16
138.71	42.90	65.34	56.05	33.32	336.33
1.65	0.36	7.39	1.85	0.00	11.25
1.10	1.19	3.00	3.00	3.00	11.29
2.29	6.71	8.98	3.11	0.07	21.16
27.61	9.90	15.76	4.36	5.04	62.67
32.80	33.30	25.14	22.83	10.93	125.00
16.28	16.45	92.23	161.74	118.31	405.00
0.46	0.30	0.44	12.95	1.15	15.30
97.59	86.25	100.75	50.64	66.74	401.97
100.91	83.92	68.12	58.54	45.95	357.44
0.00	0.00	0.00	0.00	0.00	0.00
53.87	19.39	45.54	31.23	30.94	180.96
217.22	159.51	214.08	197.95	215.52	1,004.27
32.36	6.90	24.93	11.26	3.57	79.01
137.84	44.17	183.03	44.09	13.11	422.24
22.07	12.02	23.54	4.71	7.62	69.97
	0.08 39.77 32.26 39.82 0.00 0.00 61.64 207.96 2.63 8.22 138.71 1.65 1.10 2.29 27.61 32.80 16.28 0.46 97.59 100.91 0.00 53.87 217.22 32.36 137.84	0.080.0939.7736.7032.2670.8139.8221.810.000.000.000.0061.6428.11207.96152.722.632.258.221.06138.7142.901.650.361.101.192.296.7127.619.9032.8033.3016.2816.450.460.3097.5986.25100.9183.920.000.0053.8719.39217.22159.5132.366.90137.8444.17	0.08 0.09 0.00 39.77 36.70 35.00 32.26 70.81 146.20 39.82 21.81 56.06 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 61.64 28.11 27.66 207.96 152.72 106.78 2.63 2.25 2.27 8.22 1.06 8.02 138.71 42.90 65.34 1.65 0.36 7.39 1.10 1.19 3.00 2.29 6.71 8.98 27.61 9.90 15.76 32.80 33.30 25.14 16.28 16.45 92.23 0.46 0.30 0.44 97.59 86.25 100.75 100.91 83.92 68.12 0.00 0.00 0.00 53.87 19.39 45.54 217.22 159.51 214.08 32.36 6.90 24.93 137.84 44.17 183.03	0.08 0.09 0.00 0.00 39.77 36.70 35.00 35.00 32.26 70.81 146.20 223.83 39.82 21.81 56.06 72.95 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 61.64 28.11 27.66 14.35 207.96 152.72 106.78 12.54 2.63 2.25 2.27 1.44 8.22 1.06 8.02 0.82 138.71 42.90 65.34 56.05 1.65 0.36 7.39 1.85 1.10 1.19 3.00 3.00 2.29 6.71 8.98 3.11 27.61 9.90 15.76 4.36 32.80 33.30 25.14 22.83 36.25 100.75 50.64 100.91 83.92 68.12 97.59 86.25 100.75 50.64 100.91 83.92 68.12 58.54 0.00 0.00 0.00 0.00 53.87 19.39 45.54 31.23 217.22 159.51 214.08 197.95 32.36 6.90 24.93 11.26 137.84 44.17 183.03 44.09	0.08 0.09 0.00 0.00 0.00 39.77 36.70 35.00 35.00 35.00 32.26 70.81 146.20 223.83 142.77 39.82 21.81 56.06 72.95 58.12 0.00 0.10 152.72 106.78 12.54 0.12 1.06 8.02 0.82 1.05 138.71 42.90 65.34 56.05 33.32 1.65 0.36 7.39 1.85 0.00 1.10 1.19 3.00 3.00 3.00 2.29 6.71 8.98 3.11 0.07 27.61 9.90 15.76 4.36 5.04 32.80 33.30 25.14 22.83 10.93 16.28 16.45 92.23 161.74 118.31 0.46 0.30 0.44 12.95 1.15 97.59 86.25 100.75 50.64 66.74 10.00 0.00 <t< td=""></t<>

Category	FY15	FY16	FY17	FY18	FY19	Total
9. Toilets-Students	4.95	29.20	41.42	4.48	19.95	100.00
10. Toilets-Staff	0.00	0.00	0.00	0.00	0.05	0.05
11. Floors	0.95	0.31	0.22	0.88	1.21	3.56
12. Paved Area-Blacktop	5.50	4.54	1.13	3.32	0.18	14.67
13. Paved Area-Concrete	6.22	3.31	9.68	0.76	1.76	21.73
14. Fencing	0.05	0.13	1.97	0.17	0.00	2.32
15. Kitchen Areas	3.07	4.70	3.33	1.78	2.00	14.88
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	5.24	3.15	1.64	0.37	0.44	10.84
18. Gymnasium Upgrade	5.14	2.03	1.91	2.65	0.17	11.91
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.37	0.49	0.06	4.01	22.42	27.35
. State of Good Repair Yearly Totals:	1,306.66	884.70	1,321.59	1,043.67	850.00	
		<i>I.</i> S	State of Goo	od Repair 1	Total:	5,406.63
I. System Expansion						
A. New Construction-Additional Capacity						
1. New Schools	250.83	182.83	367.10	915.88	1,071.55	2,788.19
2. Building Additions	48.31	459.72	604.27	118.98	71.30	1,302.56
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	35.25	24.53	32.27	188.54	255.95	536.54
4. Transportables	0.01	0.00	0.09	0.00	0.00	0.10
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	261.81	275.39	213.93	38.07	10.79	800.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00

	(
Category	FY15	FY16	FY17	FY18	FY19	Total		
D. New Const-Common Facil-Bldg Add/Mod								
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00		
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00		
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00		
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00		
E. Site Acquisition								
1. Site Acquisition	39.02	(1.87)	121.84	183.00	0.00	341.99		
F. Replacements								
1. Replacements - New	3.60	13.68	2.23	0.87	0.67	21.05		
2. Replacements - Addition	0.13	6.98	1.26	0.52	0.40	9.30		
3. Replacements - Leases	27.50	3.43	0.62	0.00	0.10	31.65		
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00		
I. System Expansion Yearly Totals:	668.21	968.70	1,346.40	1,455.20	1,415.28			
	II. System Expansion Total:							
II. Educational Enhancements								
A. Educational Enhancements								
1. Technology	62.20	11.70	191.96	192.06	192.08	650.00		
2. Room Conversions/Partitioning	25.26	71.06	87.77	50.71	41.00	275.79		
3. Accessibility	3.14	24.19	37.62	27.25	35.36	127.56		
4. School Improvement and Restructuring	19.98	28.71	15.54	13.71	10.14	88.08		
5. Science Lab Upgrades	4.94	15.51	8.80	10.74	10.01	50.00		
6. Library Upgrades	0.13	0.76	0.16	0.23	0.00	1.28		
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00		
II. Educational Enhancements Yearly Totals:	115.65	151.94	341.85	294.70	288.59			
	III. Educational Enhancements Total:							
V. Safety and Security								
A. Safety and Security								
1. Safety Systems	2.91	0.16	1.79	1.20	0.07	6.14		
1a. School Safety	10.15	4.16	27.69	28.00	30.00	100.00		
2. Emergency Lighting and Fire Safety Retrofits	7.13	1.29	10.00	10.00	10.00	38.41		
3. Code Compliance	1.06	0.95	22.50	22.50	22.50	69.52		
V. Safety and Security Yearly Totals:	21.26	6.56	61.98	61.70	62.57			

IV. Safety and Security Total:

214.07

	(III IIIIIIOIIS)					
Category	FY15	FY16	FY17	FY18	FY19	Total
V. Ancillary Facilities						
A. Administrative Support						
1. Administrative Support	0.06	0.06	8.00	6.00	5.00	19.12
V. Ancillary Facilities Yearly Totals:	0.06	0.06	8.00	6.00	5.00	
		١	/. Ancillary	Facilities 7	Total:	19.12
VI. Emergency, Unspecified and Misc.						
A. Research and Development						
1. Building Condition Surveys	12.01	15.10	18.00	18.00	18.00	81.11
C. DOE Administration						
1. DOE Administration	0.00	9.60	7.00	7.00	7.00	30.60
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	223.32	218.48	180.00	130.00	130.00	881.80
E. Emergency Unspecified						
1. Emergency Unspecified	32.69	46.27	106.99	81.02	113.93	380.90
2. Emergency Stabilization	10.19	16.21	10.00	10.00	10.00	56.40
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	259.40	190.30	210.56	0.00	0.00	660.26
G. Resolution A						
1. City Council	87.46	86.10	318.81	0.00	0.00	492.37
2. Borough President	17.58	26.09	124.36	0.68	0.00	168.72
H. Mayor/Council Program						
1. Mayor/Council Program	0.97	1.26	0.21	0.08	0.00	2.52
VI. Emergency, Unspecified and Misc. Yearly Totals:	643.62	609.43	975.93	246.78	278.93	
	VI. Em	ergency, U	nspecified	and Misc. 1	Total:	2,754.69
Yearly Totals:	2,755.45	2,621.39	4,055.76	3,108.05	2,900.38	
				Grand	Total:	\$15,441.03

	(11111110113)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.02	0.01	0.00	0.00	0.00	0.03
3. Exterior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	1.58	15.08	21.75	39.95	28.52	106.88
3. Climate Control	4.35	5.62	6.66	16.02	8.35	41.01
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversions	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical Systems	4.79	1.85	0.34	0.23	0.20	7.42
7. Lighting Fixtures	56.27	31.04	23.28	3.17	0.00	113.75
8. Elevators and Escalators	0.15	2.01	0.18	0.06	0.12	2.52
9. Reinforcing Cinder Concrete Slabs	0.37	0.12	5.21	0.13	1.03	6.86
10. Flood Elimination	25.94	8.10	11.08	8.45	8.60	62.17
11. Air Conditioning Retrofit	0.00	0.00	0.10	0.00	0.00	0.10
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.55	0.05	0.96	0.13	0.00	1.70
14. Interior Spaces	0.17	2.89	1.57	0.24	3.15	8.02
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	0.00	0.20	0.99	0.18	9.67	11.05
2. Playground Redevelopment	1.45	2.33	17.94	39.15	28.72	89.60
3. Swimming Pools	0.03	0.05	0.00	0.00	0.00	0.08
E. System Replacements						
1. Roofs	28.60	26.10	23.14	6.54	12.38	96.77
2. Parapets	29.53	25.91	12.68	13.69	11.23	93.03
3. Painting & Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	11.26	0.76	11.40	6.11	8.84	38.37
5. Exterior Masonry	65.56	37.02	52.29	42.25	42.42	239.55
6. Electrical Systems	2.70	0.18	0.18	0.20	1.58	4.84
7. Heating Plant Upgrade	17.86	13.39	7.83	6.64	0.91	46.64
8. Domestic Piping	13.53	0.52	2.43	1.10	0.03	17.60
0. Tailata Otudanta						
9. Toilets-Students	0.03	5.75	8.49	0.15	4.19	18.61

	(11111110113)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
E. System Replacements						
11. Floors	0.00	0.00	0.01	0.17	0.01	0.19
12. Paved Area-Blacktop	0.31	0.02	0.03	0.01	0.00	0.37
13. Paved Area-Concrete	1.60	0.96	7.84	0.44	0.29	11.13
14. Fencing	0.00	0.00	0.00	0.00	0.00	0.00
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	2.45	0.36	0.35	0.08	0.00	3.24
18. Gymnasium Upgrade	3.45	0.37	0.77	0.52	0.00	5.10
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.09	0.03	0.00	1.00	4.51	5.63
I. State of Good Repair Yearly Totals:	272.64	180.73	217.54	186.60	174.80	
		<i>I.</i> Si	otal:	1,032.31		
II. System Expansion						
A. New Construction-Additional Capacity						
1. New Schools	1.98	1.51	39.94	85.43	237.78	366.64
2. Building Additions	4.51	62.59	148.37	6.52	15.31	237.31
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	1.26	0.32	2.30	44.28	21.46	69.62
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.70	1.46	1.27	1.86	0.10	5.39
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00

	(11111110115)					
Category	FY15	FY16	FY17	FY18	FY19	Total
II. System Expansion						
D. New Const-Common Facil-Bldg Add/Mod						
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	0.38	4.30	20.03	30.00	0.00	54.71
F. Replacements						
1. Replacements - New	0.00	0.00	0.00	0.00	0.00	0.00
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Leases	23.33	3.25	0.61	0.00	0.00	27.19
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
II. System Expansion Yearly Totals:	32.17	73.42	212.53	168.10	274.64	
	II. System Expansion Total:					760.86
III. Educational Enhancements						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions/Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
III. Educational Enhancements Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
	III. Educational Enhancements Total:					
IV. Safety and Security						
A. Safety and Security						
1. Safety Systems	1.14	0.14	0.52	0.89	0.06	2.74
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
IV. Safety and Security Yearly Totals:	1.14	0.14	0.52	0.89	0.06	
	IV. Safety and Security Total:					2.74
V. Ancillary Facilities						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
V. Ancillary Facilities Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
		V	Ancillary H		otal [.]	0 00

V. Ancillary Facilities Total:

0.00

	(
Category	FY15	FY16	FY17	FY18	FY19	Total	
VI. Emergency, Unspecified and Misc.							
A. Research and Development							
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00	
C. DOE Administration							
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00	
D. Wrap-Up Insurance							
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00	
E. Emergency Unspecified							
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00	
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00	
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00	
F. Prior Plan Completion Cost							
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00	
G. Resolution A							
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00	
2. Borough President	2.11	4.95	15.93	0.00	0.00	22.98	
H. Mayor/Council Program							
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00	
VI. Emergency, Unspecified and Misc. Yearly Totals:	2.11	4.95	15.93	0.00	0.00		
	VI. Emergency, Uns	rgency, Unspecified and Misc. Total:				22.98	
Yearly Totals for Bronx	308.06	259.24	446.51	355.59	449.50		
		Bronx Grand Total:					

	(11111110113)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	18.21	27.38	57.73	99.13	32.57	235.01
3. Climate Control	10.11	7.04	19.02	27.85	21.15	85.17
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversions	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical Systems	25.70	14.62	9.86	7.82	3.76	61.76
7. Lighting Fixtures	51.19	53.87	31.76	4.17	0.00	140.99
8. Elevators and Escalators	2.17	0.12	0.35	0.42	0.02	3.07
9. Reinforcing Cinder Concrete Slabs	5.92	0.12	1.12	0.53	0.00	7.69
10. Flood Elimination	47.43	13.48	18.06	20.48	8.44	107.90
11. Air Conditioning Retrofit	1.56	0.02	0.12	0.14	0.00	1.85
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	1.44	5.28	4.58	1.68	0.01	12.98
14. Interior Spaces	11.83	4.87	1.78	1.85	0.02	20.36
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	12.61	14.20	2.95	10.65	0.53	40.94
2. Playground Redevelopment	3.62	8.71	24.76	36.68	29.75	103.52
3. Swimming Pools	0.07	0.03	0.44	12.95	1.15	14.64
E. System Replacements						
1. Roofs	35.43	35.54	33.46	13.52	24.65	142.61
2. Parapets	35.71	24.96	21.86	10.47	10.03	103.03
3. Painting & Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	28.81	11.37	17.55	17.63	8.46	83.82
5. Exterior Masonry	75.43	60.63	77.17	53.03	63.78	330.04
6. Electrical Systems	13.17	3.26	4.17	1.73	0.96	23.28
7. Heating Plant Upgrade	53.28	9.43	120.46	23.14	6.60	212.92
8. Domestic Piping	2.42	6.49	2.59	1.55	6.04	19.09
9. Toilets-Students	0.29	10.25	13.67	0.28	5.85	30.34
10. Toilets-Staff	0.00	0.00	0.00	0.00	0.00	0.00

	(in minorio)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
E. System Replacements						
11. Floors	0.93	0.30	0.15	0.71	0.05	2.15
12. Paved Area-Blacktop	2.12	1.46	0.23	0.19	0.00	4.00
13. Paved Area-Concrete	3.83	-0.50	0.36	0.15	0.00	3.84
14. Fencing	0.03	0.01	0.00	0.00	0.00	0.04
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	1.08	0.19	0.54	0.07	0.24	2.12
18. Gymnasium Upgrade	0.23	0.04	0.06	1.17	0.09	1.58
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.17	0.16	0.00	1.00	7.52	8.85
I. State of Good Repair Yearly Totals:	444.78	313.35	464.79	349.01	231.65	
		<i>I.</i> S	tate of Goo	d Repair To	otal:	1,803.59
II. System Expansion						
A. New Construction-Additional Capacity						
1. New Schools	33.94	7.85	128.05	334.80	417.00	921.64
2. Building Additions	1.93	6.16	130.94	76.70	34.33	250.05
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	9.98	2.21	3.65	86.47	92.73	195.04
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.00	0.00	0.47	4.33	0.85	5.64
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00

	(III IIIIIIOIIS)					
Category	FY15	FY16	FY17	FY18	FY19	Total
II. System Expansion						
D. New Const-Common Facil-Bldg Add/Mod						
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	9.07	0.31	28.30	70.00	0.00	107.68
F. Replacements						
1. Replacements - New	0.09	0.03	0.00	0.00	0.00	0.12
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Leases	0.11	0.09	0.00	0.00	0.00	0.20
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
II. System Expansion Yearly Totals:	55.11	16.64	291.40	572.29	544.90	
		Ш.	System Ex	pansion T	otal:	1,480.35
III. Educational Enhancements						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions/Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
III. Educational Enhancements Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
	11	II. Educatio	onal Enhan	cements T	otal:	0.00
IV. Safety and Security						
A. Safety and Security						
1. Safety Systems	1.31	-0.15	0.38	0.12	0.00	1.65
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
IV. Safety and Security Yearly Totals:	1.31	-0.15	0.38	0.12	0.00	
		<i>IV.</i> 3	Safety and	Security T	otal:	1.65
V. Ancillary Facilities						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
V. Ancillary Facilities Yearly Totals:	0.00	0.00	0.00	0.00	0.00	_
		V	Ancillary I	Facilities To	ntal:	0 00

V. Ancillary Facilities Total:

0.00

,					
FY15	FY16	FY17	FY18	FY19	Total
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00	0.00	0.00
3.98	6.93	40.84	0.00	0.00	51.75
0.00	0.00	0.00	0.00	0.00	0.00
3.98	6.93	40.84	0.00	0.00	
VI. Eme	VI. Emergency, Unspecified and Misc. Total:				51.75
505.18	336.77	797.42	921.42	776.55	
		Brookl	yn Grand 1	otal:	\$3,337.35
	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 3.98 6.93 VI. Emergency, United States	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 3.98 6.93 40.84 0.00 0.00 0.00 3.98 6.93 40.84 VI. Emergency, Unspecified at 505.18 336.77	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 3.98 6.93 40.84 0.00 3.98 6.93 40.84 0.00 3.98 6.93 40.84 0.00 505.18 336.77 797.42 921.42	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

	(III IIIIIIOIIS)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.01	0.00	0.00	0.00	0.01
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.06	0.09	0.00	0.00	0.00	0.15
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	1.36	19.16	14.62	24.39	14.42	73.95
3. Climate Control	0.83	4.72	5.23	6.70	4.05	21.52
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversions	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical Systems	14.06	6.22	13.91	4.54	3.84	42.58
7. Lighting Fixtures	39.62	21.55	13.53	1.23	0.01	75.92
8. Elevators and Escalators	0.09	0.03	0.31	0.00	0.00	0.42
9. Reinforcing Cinder Concrete Slabs	0.07	0.03	0.95	0.02	0.02	1.10
10. Flood Elimination	7.94	11.49	4.68	5.61	2.73	32.45
11. Air Conditioning Retrofit	0.03	0.04	0.00	0.00	0.00	0.07
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.13	1.23	1.39	0.17	0.00	2.93
14. Interior Spaces	0.98	0.09	1.20	0.25	1.81	4.34
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playground Redevelopment	1.67	0.22	5.85	6.90	3.13	17.78
3. Swimming Pools	0.30	0.19	0.00	0.00	0.00	0.48
E. System Replacements						
1. Roofs	15.65	7.35	12.71	1.78	13.11	50.59
2. Parapets	14.26	10.08	14.12	3.34	11.79	53.59
3. Painting & Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	5.98	4.37	12.17	1.93	9.05	33.49
5. Exterior Masonry	50.55	25.25	36.95	23.44	44.68	180.87
6. Electrical Systems	1.99	0.92	1.07	7.22	0.64	11.83
7. Heating Plant Upgrade	5.44	9.72	9.15	3.59	1.45	29.34
8. Domestic Piping	1.29	1.79	0.58	0.72	1.23	5.61
9. Toilets-Students	4.35	6.02	7.42	0.15	3.00	20.95
10. Toilets-Staff	0.00	0.00	0.00	0.00	0.00	0.00

FY17	FY18	FY19	Total
0.00	0.00	0.00	0.02
0.10	2.61	0.18	3.13
0.25	0.06	0.00	1.48
1.97	0.17	0.00	2.26
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.07	0.10	0.00	2.00
0.60	0.35	0.04	2.49
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.06	0.51	4.42	5.37
158.90	95.79	119.59	
te of Goo	d Repair To	otal:	676.75
63.45	121.03	34.80	407.98
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	1.89	20.49	22.41
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
0.25	0.55	0.00	1.95
0.00	0.00	0.00	0.00
0.00	0.00	0.00	0.00
	0.00 0.10 0.25 1.97 0.00 0.07 0.60 0.00 0.00 0.00 158.90 te of Goo 63.45 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0	0.00 0.00 0.10 2.61 0.25 0.06 1.97 0.17 0.00 0.00 0.00 <td>0.00 0.00 0.00 0.10 2.61 0.18 0.25 0.06 0.00 1.97 0.17 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.60 0.35 0.04 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00</td>	0.00 0.00 0.00 0.10 2.61 0.18 0.25 0.06 0.00 1.97 0.17 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.60 0.35 0.04 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

	(III IIIIIIOIIS)					
Category	FY15	FY16	FY17	FY18	FY19	Total
II. System Expansion						
D. New Const-Common Facil-Bldg Add/Mod						
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	8.12	0.22	20.07	0.00	0.00	28.41
F. Replacements						
1. Replacements - New	3.01	1.76	0.00	0.00	0.00	4.78
2. Replacements - Addition	0.00	0.00	0.00	0.00	0.00	0.00
3. Replacements - Leases	3.95	0.09	0.01	0.00	0.00	4.05
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
II. System Expansion Yearly Totals:	126.29	80.74	83.78	123.48	55.29	
		П.	System Ex	pansion To	otal:	469.58
III. Educational Enhancements						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions/Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
III. Educational Enhancements Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
	I	II. Educatio	nal Enhan	cements To	otal:	0.00
IV. Safety and Security						
A. Safety and Security						
1. Safety Systems	0.01	0.00	0.01	0.13	0.01	0.16
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
IV. Safety and Security Yearly Totals:	0.01	0.00	0.01	0.13	0.01	
		IV. S	Safety and	Security To	otal:	0.16
V. Ancillary Facilities						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
V. Ancillary Facilities Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
		v	Ancillary I	Facilities To	tal	0 00

V. Ancillary Facilities Total:

0.00

·						
Category	FY15	FY16	FY17	FY18	FY19	Total
VI. Emergency, Unspecified and Misc.						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	2.83	5.19	28.95	0.00	0.00	36.96
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
VI. Emergency, Unspecified and Misc. Yearly Totals:	2.83	5.19	28.95	0.00	0.00	
	VI. Eme	rgency, Un	specified a	nd Misc. To	otal:	36.96
Yearly Totals for Manhattan	297.72	219.80	271.64	219.41	174.89	
			Manhatt	an Grand T	otal:	\$1,183.45

	(
Category	FY15	FY16	FY17	FY18	FY19	Total
State of Good Repair						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.01	0.00	0.00	0.00	0.00	0.01
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	11.12	9.20	52.10	55.47	50.08	177.96
3. Climate Control	20.69	3.20	24.05	20.66	19.72	88.32
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversions	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical Systems	16.77	4.20	2.78	1.65	1.57	26.96
7. Lighting Fixtures	51.37	38.68	30.00	3.07	0.00	123.12
8. Elevators and Escalators	0.15	0.04	1.41	0.67	0.08	2.35
9. Reinforcing Cinder Concrete Slabs	1.85	0.79	0.73	0.14	0.00	3.51
10. Flood Elimination	45.77	9.99	30.19	19.47	12.47	117.88
11. Air Conditioning Retrofit	0.00	0.00	0.00	0.00	0.00	0.00
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.17	0.15	2.05	1.13	0.06	3.56
14. Interior Spaces	12.63	2.01	10.95	1.85	0.07	27.51
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	19.13	18.27	13.19	3.17	0.00	53.75
2. Playground Redevelopment	9.08	5.13	39.56	72.50	50.28	176.55
3. Swimming Pools	0.05	0.04	0.00	0.00	0.00	0.09
E. System Replacements						
1. Roofs	13.70	13.50	29.69	16.35	15.51	88.74
2. Parapets	16.85	18.64	16.78	23.29	12.30	87.86
3. Painting & Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	3.26	1.60	1.41	2.54	4.39	13.19
5. Exterior Masonry	21.01	23.15	43.12	35.21	54.25	176.74
6. Electrical Systems	13.65	0.93	17.82	1.87	0.39	34.65
7. Heating Plant Upgrade	39.41	6.81	38.08	6.96	4.00	95.25
8. Domestic Piping						
er zemeetter ipnig	3.83	3.13	13.53	0.83	0.31	21.64
9. Toilets-Students	3.83 0.20	3.13 5.96	13.53 9.66	0.83 2.58	0.31 5.59	21.64 24.00

	(III IIIIIIOIIS)						
Category	FY15	FY16	FY17	FY18	FY19	Total	
I. State of Good Repair							
E. System Replacements							
11. Floors	0.00	0.00	0.05	0.00	1.15	1.20	
12. Paved Area-Blacktop	3.02	2.88	0.76	0.51	0.00	7.17	
13. Paved Area-Concrete	0.48	1.60	0.51	0.06	1.47	4.12	
14. Fencing	0.01	0.01	0.00	0.00	0.00	0.02	
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00	
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00	
17. Auditorium Upgrade	0.65	1.02	0.51	0.12	0.20	2.50	
18. Gymnasium Upgrade	0.17	1.35	0.46	0.21	0.01	2.20	
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00	
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00	
21. Cafeteria / Multipurpose Room Upgrade	0.02	0.00	0.00	1.00	4.47	5.49	
I. State of Good Repair Yearly Totals:	305.04	172.27	379.37	271.30	238.37		
		<i>I.</i> St	I. State of Good Repair Total:				
II. System Expansion							
A. New Construction-Additional Capacity							
1. New Schools	101.04	93.75	134.48	363.85	309.32	1,002.44	
2. Building Additions	16.34	314.31	312.13	27.94	21.66	692.37	
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00	
3. Leased Facility Improvements	3.46	21.35	7.80	32.58	120.82	186.01	
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00	
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00	
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00	
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00	
B. New Construction-Common-Facilities-Additions							
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00	
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00	
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00	
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00	
C. New Physical Education Facilities							
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00	
2. Playgrounds	0.53	1.92	0.80	2.60	3.58	9.43	
D. New Const-Common Facil-Bldg Add/Mod							
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00	
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00	
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00	
,							

	(11111110115)					
Category	FY15	FY16	FY17	FY18	FY19	Total
II. System Expansion						
D. New Const-Common Facil-Bldg Add/Mod						
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	21.44	-6.71	49.89	73.00	0.00	137.61
F. Replacements						
1. Replacements - New	0.41	11.63	2.15	0.87	0.67	15.73
2. Replacements - Addition	0.12	6.97	1.25	0.52	0.40	9.25
3. Replacements - Leases	0.11	0.00	0.00	0.00	0.10	0.21
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
II. System Expansion Yearly Totals:	143.43	443.21	508.50	501.36	456.55	
		П.	System Ex	pansion T	otal:	2,053.05
III. Educational Enhancements						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions/Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
III. Educational Enhancements Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
		III. Educatio	onal Enhan	cements To	otal:	0.00
IV. Safety and Security						
A. Safety and Security						
1. Safety Systems	0.42	0.11	0.00	0.00	0.00	0.53
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
IV. Safety and Security Yearly Totals:	0.42	0.11	0.00	0.00	0.00	
		IV.	Safety and	Security To	otal:	0.53
V. Ancillary Facilities						
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
V. Ancillary Facilities Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
		V	Ancillary I	Facilities Tr	otal·	0 00

V. Ancillary Facilities Total:

0.00

	(
Category	FY15	FY16	FY17	FY18	FY19	Total
VI. Emergency, Unspecified and Misc.						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	0.29	5.58	15.65	0.68	0.00	22.19
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
VI. Emergency, Unspecified and Misc. Yearly Totals:	0.29	5.58	15.65	0.68	0.00	
	VI. Eme	rgency, Un	specified a	nd Misc. To	otal:	22.19
Yearly Totals for Queens	449.18	621.17	903.52	773.33	694.92	
			Quee	ns Grand T	otal:	\$3,442.12

	(11111110113)					
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
A. New Construction						
1. Building Replacement	0.00	0.00	0.00	0.00	0.00	0.00
B. Major Modernizations and Rehabilitations						
1. Full Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
2. Interior Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Exterior Modernizations	0.01	0.00	0.00	0.00	0.00	0.01
C. Building Upgrade						
1. Asbestos	0.00	0.00	0.00	0.00	0.00	0.00
2. Boiler Conversion	0.00	0.00	0.00	4.89	17.19	22.07
3. Climate Control	3.85	1.24	1.10	1.71	4.86	12.75
4. Indoor Air Pollution Abatement	0.00	0.00	0.00	0.00	0.00	0.00
5. Kitchen Conversions	0.00	0.00	0.00	0.00	0.00	0.00
6. Low-Voltage Electrical Systems	0.32	1.22	0.78	0.12	0.00	2.43
7. Lighting Fixtures	9.51	7.58	8.21	0.91	0.00	26.21
8. Elevators and Escalators	0.09	0.04	0.02	0.29	0.02	0.47
9. Reinforcing Cinder Concrete Slabs	0.00	0.00	0.00	0.00	0.00	0.00
10. Flood Elimination	11.63	-0.16	1.33	2.04	1.09	15.93
11. Air Conditioning Retrofit	0.06	0.29	7.16	1.71	0.00	9.23
12. Lead Paint Abatement	0.00	0.00	0.00	0.00	0.00	0.00
13. Reinforcing Support Elements	0.00	0.00	0.00	0.00	0.00	0.00
14. Interior Spaces	2.00	0.03	0.25	0.16	0.00	2.44
D. Rehabilitation of Physical Education Facilities						
1. Athletic Fields	1.06	0.63	8.01	8.82	0.73	19.25
2. Playground Redevelopment	0.45	0.06	4.12	6.50	6.43	17.56
3. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. System Replacements						
1. Roofs	4.22	3.76	1.74	12.45	1.08	23.25
2. Parapets	4.56	4.32	2.69	7.75	0.60	19.93
3. Painting & Plastering	0.00	0.00	0.00	0.00	0.00	0.00
4. Windows	4.55	1.30	3.01	3.02	0.20	12.08
5. Exterior Masonry	4.67	13.46	4.54	44.02	10.39	77.07
6. Electrical Systems	0.85	1.61	1.70	0.24	0.00	4.40
7. Heating Plant Upgrade	21.85	4.82	7.51	3.76	0.15	38.09
8. Domestic Piping	1.00	0.09	4.40	0.51	0.01	6.02
9. Toilets-Students	0.08	1.22	2.18	1.32	1.31	6.11
10. Toilets-Staff	0.00	0.00	0.00	0.00	0.00	0.00

	(
Category	FY15	FY16	FY17	FY18	FY19	Total
I. State of Good Repair						
E. System Replacements						
11. Floors	0.00	0.00	0.00	0.00	0.00	0.00
12. Paved Area-Blacktop	0.00	0.00	0.00	0.00	0.00	0.00
13. Paved Area-Concrete	0.15	0.23	0.73	0.04	0.00	1.15
14. Fencing	0.00	0.00	0.00	0.00	0.00	0.00
15. Kitchen Areas	0.00	0.00	0.00	0.00	0.00	0.00
16. Containerization	0.00	0.00	0.00	0.00	0.00	0.00
17. Auditorium Upgrade	0.69	0.13	0.16	0.00	0.00	0.98
18. Gymnasium Upgrade	0.05	0.03	0.03	0.40	0.03	0.54
19. Asset Management Program	0.00	0.00	0.00	0.00	0.00	0.00
20. CIP Response	0.00	0.00	0.00	0.00	0.00	0.00
21. Cafeteria / Multipurpose Room Upgrade	0.00	0.00	0.00	0.50	1.50	2.00
I. State of Good Repair Yearly Totals:	71.66	41.89	59.67	101.19	45.59	
		I. St	ate of Goo	d Repair To	otal:	319.99
II. System Expansion						
A. New Construction-Additional Capacity						
1. New Schools	3.19	1.72	1.19	10.75	72.66	89.51
2. Building Additions	25.53	76.66	12.82	7.83	0.00	122.84
2a. Building Additions/Modernizations	0.00	0.00	0.00	0.00	0.00	0.00
3. Leased Facility Improvements	20.54	0.63	18.51	23.32	0.45	63.46
4. Transportables	0.00	0.00	0.00	0.00	0.00	0.00
5. Modular Classrooms	0.00	0.00	0.00	0.00	0.00	0.00
7. Capacity - Interior Modernization	0.00	0.00	0.00	0.00	0.00	0.00
8. Pre-Kindergarten Initiative	0.00	0.00	0.00	0.00	0.00	0.00
B. New Construction-Common-Facilities-Additions						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
C. New Physical Education Facilities						
1. Athletic Fields	0.00	0.00	0.00	0.00	0.00	0.00
2. Playgrounds	0.00	0.00	0.00	0.00	0.00	0.00
D. New Const-Common Facil-Bldg Add/Mod						
1. Lunchrooms	0.00	0.00	0.00	0.00	0.00	0.00
2. Auditoriums	0.00	0.00	0.00	0.00	0.00	0.00
3. Gymnasiums	0.00	0.00	0.00	0.00	0.00	0.00
•						

	(in minoris)					
Category	FY15	FY16	FY17	FY18	FY19	Total
II. System Expansion						
D. New Const-Common Facil-Bldg Add/Mod						
4. Swimming Pools	0.00	0.00	0.00	0.00	0.00	0.00
E. Site Acquisition						
1. Site Acquisition	0.02	0.01	3.55	10.00	0.00	13.58
F. Replacements						
1. Replacements - New	0.09	0.26	0.08	0.00	0.00	0.43
2. Replacements - Addition	0.02	0.02	0.01	0.00	0.00	0.05
3. Replacements - Leases	0.00	0.00	0.00	0.00	0.00	0.00
4. Replacements - Capacity - Interior Mod	0.00	0.00	0.00	0.00	0.00	0.00
II. System Expansion Yearly Totals:	49.39	79.29	36.17	51.89	73.11	
		<i>II.</i>	System Ex	pansion To	otal:	289.86
III. Educational Enhancements						
A. Educational Enhancements						
1. Technology	0.00	0.00	0.00	0.00	0.00	0.00
2. Room Conversions/Partitioning	0.00	0.00	0.00	0.00	0.00	0.00
3. Accessibility	0.00	0.00	0.00	0.00	0.00	0.00
4. School Improvement and Restructuring	0.00	0.00	0.00	0.00	0.00	0.00
5. Science Lab Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
6. Library Upgrades	0.00	0.00	0.00	0.00	0.00	0.00
7. Charter/Innovative Schools	0.00	0.00	0.00	0.00	0.00	0.00
III. Educational Enhancements Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
	1	II. Educatio	nal Enhand	ements To	otal:	0.00
IV. Safety and Security						
A. Safety and Security						
1. Safety Systems	0.03	0.06	0.89	0.07	0.00	1.04
1a. School Safety	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Lighting and Fire Safety Retrofits	0.00	0.00	0.00	0.00	0.00	0.00
3. Code Compliance	0.00	0.00	0.00	0.00	0.00	0.00
IV. Safety and Security Yearly Totals:	0.03	0.06	0.89	0.07	0.00	
		IV. S	Safety and S	Security To	otal:	1.04
V. Ancillary Facilities			-	-		
A. Administrative Support						
1. Administrative Support	0.00	0.00	0.00	0.00	0.00	0.00
V. Ancillary Facilities Yearly Totals:	0.00	0.00	0.00	0.00	0.00	
		V	Ancillary F	acilitios To	tal·	0 00

V. Ancillary Facilities Total:

0.00

	(
Category	FY15	FY16	FY17	FY18	FY19	Total
VI. Emergency, Unspecified and Misc.						
A. Research and Development						
1. Building Condition Surveys	0.00	0.00	0.00	0.00	0.00	0.00
C. DOE Administration						
1. DOE Administration	0.00	0.00	0.00	0.00	0.00	0.00
D. Wrap-Up Insurance						
1. Wrap-Up Insurance	0.00	0.00	0.00	0.00	0.00	0.00
E. Emergency Unspecified						
1. Emergency Unspecified	0.00	0.00	0.00	0.00	0.00	0.00
2. Emergency Stabilization	0.00	0.00	0.00	0.00	0.00	0.00
3. Emergency Response	0.00	0.00	0.00	0.00	0.00	0.00
F. Prior Plan Completion Cost						
1. Prior Plan Completion Cost	0.00	0.00	0.00	0.00	0.00	0.00
G. Resolution A						
1. City Council	0.00	0.00	0.00	0.00	0.00	0.00
2. Borough President	8.38	3.45	23.00	0.00	0.00	34.83
H. Mayor/Council Program						
1. Mayor/Council Program	0.00	0.00	0.00	0.00	0.00	0.00
VI. Emergency, Unspecified and Misc. Yearly Totals:	8.38	3.45	23.00	0.00	0.00	
	VI. Eme	rgency, Un	specified a	nd Misc. To	otal:	34.83
Yearly Totals for Staten Island	129.47	124.69	119.72	153.14	118.70	
			Staten Islai	nd Grand T	otal:	\$645.73

								Actual /			Funding	
Dist	trict	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Est. Compl	Total Est. Cost	Previous Appropriations	Req'd FY 15-19	Needed to Complete
0	2	DSF0000798235	I.S. 323	М	1,016	Aug-13	Feb-15	Jun-18	176.93	44.10	132.83	0.00
0	2	DSF0000424314	P.S./I.S. @ WESTERN RAILYARDS	М	766	Dec-16	Jul-19	Sep-22	106.29	0.33	9.08	96.87
0	2	DSF0000798170	P.S. 464	М	476	May-15	Aug-17	Jun-20	53.87	0.00	49.41	4.46
L 0	2	DSF0000798172	PROJECT #1	М	456	Sep-17	Oct-18	Mar-21	25.07	0.00	22.39	2.68
0	2	DSF0000798236	PROJECT #3	М	436	Apr-17	May-18	Jul-21	39.69	0.00	36.26	3.43
0	3	DSF0000730952	P.S. 342 (RIVERSIDE CENTER)	М	692	Apr-11	Jun-16	Sep-17	110.18	3.61	106.57	0.00
0	7	DSF0000798173	PROJECT #1	х	456	May-17	Jul-18	Sep-20	41.08	0.00	36.80	4.28
0	8	DSF0000798233	P.S. 14 ADDITION	х	344	Feb-15	Jul-16	Sep-18	70.21	0.18	70.03	0.00
0	8	DSF0000823631	PROJECT #1	х	112	Sep-17	Oct-18	Jan-21	10.56	0.00	9.54	1.02
1	0	DSF0000798175	P.S. 46 ADDITION	х	500	Feb-15	Nov-16	May-19	110.62	0.07	110.56	0.00
1	0	DSF0000843830	PROJECT #1	х	824	Jun-17	Dec-18	Jun-22	74.23	0.00	66.41	7.81
L 1	0	DSF0000798174	PROJECT #2	х	456	Sep-17	Oct-18	Apr-21	25.08	0.07	22.44	2.57
1	0	DSF0000798176	PROJECT #3	х	780	Nov-17	Dec-18	Sep-21	70.22	0.02	62.82	7.38
L 1	0	DSF0000798177	PROJECT #4	х	456	Mar-17	May-18	Jul-20	25.04	0.02	22.89	2.13
1	1	DSF0000798178	P.S. 97 ADDITION	х	554	Feb-17	May-18	May-21	57.59	0.11	52.54	4.95
1	1	DSF0000845621	PROJECT #1	х	86	Aug-17	Feb-19	May-21	7.65	0.00	6.94	0.71
1	2	DSF0000798179	P.S. @ TREMONT/WEST FARMS	х	456	May-17	Jul-19	Jul-22	41.19	0.03	3.25	37.91
L 1	2	DSF0000798238	PROJECT #2	х	456	Aug-17	Jun-18	Aug-20	25.11	0.00	22.90	2.20
1	3	DSF0000843824	PROJECT #1	к	572	Apr-17	Aug-18	Sep-21	51.48	0.00	46.21	5.28
1	3	DSF0000843660	PROJECT #2	к	572	Oct-17	Apr-19	Jul-22	51.05	0.00	45.71	5.34
1	3	DSF0000843661	PROJECT #3	к	476	Jun-17	Apr-19	Jun-21	42.57	0.00	38.13	4.44

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	13	DSF0000687093	THE DOCK STREET EDUCATIONAL COMPLEX	К	333	May-12	May-15	Jul-16	41.41	3.57	37.84	0.00
*	13	DSF0000798239	I.S. 653	К	640	May-15	Jul-17	Aug-20	114.29	0.00	104.25	10.04
L	14	DSF0000687094	PROJECT #1	К	612	Jan-18	Feb-19	Sep-22	33.66	0.06	30.07	3.53
	14	DSF0000798240	PROJECT #2	К	379	May-18	Jul-19	Aug-21	34.03	0.00	3.55	30.48
*	15	DSF0000798185	P.S. 32 ADDITION	К	436	Mar-15	Jun-17	Aug-20	66.04	0.09	60.19	5.77
	15	DSF0000798184	PROJECT #1	К	640	Nov-17	Jan-19	Sep-21	57.86	0.00	51.84	6.02
	15	DSF0000843828	PROJECT #6	К	824	Apr-17	Jun-18	Mar-21	74.12	0.00	67.63	6.48
L	15	DSF0000798183	PROJECT #4	К	651	May-17	Jun-18	Jun-20	48.87	0.05	45.42	3.40
	15	DSF0000843826	PROJECT #5	К	844	Sep-17	Jul-18	Sep-21	74.77	0.00	66.93	7.84
*L	15	DSF0000799396	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL	К	113	Jan-14	Jul-14	Jul-16	10.84	0.12	10.73	0.00
*	15	DSF0000798182	P.S. @ 4302 4TH AVENUE	К	332	Aug-16	Jan-18	Aug-20	32.73	0.00	29.94	2.79
*	19	DSF0000822081	P.S./I.S. @ 3269 ATLANTIC AVENUE	К	1,000	Jul-16	Dec-17	Sep-20	83.74	0.00	76.52	7.22
*	20	DSF0000798189	P.S. 127 ADDITION	К	332	Feb-17	Apr-18	Sep-21	38.44	0.00	34.67	3.77
	20	DSF0000798187	PROJECT #1	К	640	Jul-17	Jan-19	Sep-21	57.62	0.00	51.60	6.02
L	20	DSF0000798188	PROJECT #2	К	640	Aug-17	Sep-18	Sep-21	35.21	0.00	31.45	3.76
	20	DSF0000843829	PROJECT #4	К	605	Jun-17	Sep-18	Sep-21	54.45	0.00	48.75	5.70
L	20	DSF0000798191	PROJECT #6	К	456	Mar-17	May-18	Jan-21	25.08	0.05	22.82	2.21
	20	DSF0000798190	PROJECT #7	К	456	May-17	Aug-18	Sep-21	40.95	0.00	36.69	4.26
*	20	DSF0000798186	P.S. 746	К	976	Apr-15	Feb-17	Aug-20	108.11	0.10	98.62	9.39

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable. L Proposed Leased Facility

					Forecast	Design	Constr	Actual / Est.	Total Est.	Previous	Funding Req'd	Needed to
	District	Project #	School	Boro	Capacity	Start	Start	Compl	Cost	Appropriations	FY 15-19	Complete
L	20	DSF0000845622	PROJECT #3	к	308	Aug-17	Sep-18	Sep-19	16.94	0.00	15.78	1.16
L	20	DSF0000798567	PROJECT #5	К	456	May-17	Jun-18	Aug-21	25.08	0.00	22.61	2.47
*	21	DSF0000798193	P.S. 97 ADDITION	К	456	Feb-17	Jul-18	Sep-21	31.03	0.00	27.72	3.31
*	21	DSF0000798192	P.S. 101 ADDITION	к	456	May-15	Nov-16	Jun-19	78.25	0.00	78.25	0.00
L	22	DSF0000798194	PROJECT #1	к	456	Jul-17	Aug-18	Aug-20	25.08	0.00	22.42	2.66
*	24	DSF0000798568	P.S. 19 ADDITION	Q	640	Mar-15	Jul-16	Sep-18	126.92	0.01	126.91	0.00
*	24	DSF0000798200	P.S. 49 ADDITION	Q	333	Mar-14	Dec-15	Sep-17	44.14	0.13	44.02	0.00
*	24	DSF0000798199	I.S. 125 ADDITION	Q	728	Feb-14	Dec-15	Sep-17	116.89	0.30	116.58	0.00
*	24	DSF0000798195	P.S. 143 ADDITION	Q	980	Jan-16	Jun-17	Sep-20	95.53	0.07	87.03	8.43
*	24	DSF0000821576	P.S. 128 ADDITION	Q	440	Mar-16	May-17	Jun-20	31.95	0.00	29.82	2.13
	24	DSF0000843831	PROJECT #1	Q	723	Apr-17	Jul-18	Sep-21	65.07	0.00	58.23	6.84
L	24	DSF0000798198	PROJECT #5	Q	184	Jul-17	Aug-18	Aug-20	8.31	0.00	7.42	0.89
*	24	DSF0000798196	I.S. 419	Q	646	Oct-16	Dec-17	Sep-21	79.13	0.14	73.08	5.90
*L	24	DSF0000798197	P.S. 143 ANNEX	Q	211	Dec-15	Aug-17	Sep-18	6.74	0.00	6.74	0.00
*	25	DSF0000798203	P.S. 24 ADDITION	Q	600	Dec-14	Jul-16	Sep-18	111.17	0.05	111.12	0.00
*	25	DSF0000843833	P.S. 129 ADDITION	Q	548	Sep-16	Dec-17	Sep-20	57.00	0.00	52.03	4.97
L	25	DSF0000798201	PROJECT #1	Q	916	Nov-17	Jan-19	Sep-21	41.50	0.00	37.12	4.38
	25	DSF0000821765	PROJECT #3	Q	157	May-17	Feb-19	Sep-21	14.13	0.00	12.73	1.40
*	26	DSF0000798205	P.S. 332	Q	468	Feb-14	Aug-15	Jul-17	100.22	6.85	93.37	0.00
L	26	DSF0000798204	PROJECT #2	Q	456	Jul-17	Aug-18	Aug-20	25.08	0.00	22.40	2.68
*	27	DSF0000801039	P.S. 66 ADDITION	Q	124	Sep-15	Jan-17	Sep-19	39.76	0.00	38.73	1.04

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	27	DSF0000417420	P.S. 335	Q	516	Sep-13	Jul-15	Sep-17	107.53	6.25	101.28	0.00
L	27	DSF0000798206	PROJECT #2	Q	332	Jan-17	Feb-18	May-20	18.26	0.00	16.72	1.55
*	28	DSF0000798208	P.S. 303 ADDITION	Q	484	Feb-15	Dec-16	Sep-19	69.04	0.00	67.26	1.79
*	28	DSF0000798209	P.S. 144 ADDITION	Q	590	Oct-15	Feb-17	Sep-19	65.16	0.00	63.30	1.86
L	28	DSF0000843834	PROJECT #1	Q	846	Sep-17	Aug-18	Sep-21	46.53	0.00	41.56	4.97
	30	DSF0000843827	PROJECT #4	Q	616	Mar-17	Jul-18	Aug-21	55.44	0.00	49.64	5.80
L	30	DSF0000798211	PROJECT #2	Q	436	Mar-17	Jul-18	Aug-20	23.98	0.00	21.42	2.56
*	30	DSF0000843659	P.S. @ PARCEL C	Q	572	Dec-16	Jan-18	Apr-21	51.48	0.00	47.02	4.46
*	30	DSF0000843984	P.S. @ PARCEL F	Q	612	Apr-16	Dec-17	Jun-21	65.52	0.00	59.86	5.66
*	30	DSF0000798210	P.S. 398	Q	476	Jun-15	Dec-16	Jul-19	71.80	0.00	71.80	0.00
*	30	DSF0000843825	I.S. @ 38-04 48TH STREET	Q	824	Mar-17	Jul-18	Sep-21	74.16	0.00	67.83	6.33
	30	DSF0000798212	PROJECT #3	Q	1,000	May-18	Aug-19	Sep-22	90.00	0.01	6.93	83.06
*L	31	DSF0000821684	FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	R	224	Jun-14	Dec-14	Sep-16	27.49	0.00	27.49	0.00
*	31	DSF0000843832	P.S. @ 357 TARGEE STREET	R	747	May-17	Jul-18	May-21	67.23	0.00	60.17	7.05
*L	31	DSF0000798214	I.S. 82	R	309	Mar-16	Dec-16	Sep-17	12.79	0.01	12.77	0.00
L	31	DSF0000798213	PROJECT #2	R	456	Mar-17	May-18	Jul-21	25.08	0.00	22.85	2.23
*L	78Q	DSF0000798226	IS/HS 336	Q	507	Oct-13	Jun-16	Sep-18	27.57	0.45	27.12	0.00
*	78Q	DSF0000798215	ACADEMY OF AMERICAN STUDIES	Q	969	Jul-16	Sep-17	Sep-21	113.30	0.02	102.98	10.29
	78Q	DSF0000821799	PROJECT #2	Q	1,326	May-17	Jul-18	Jul-22	119.88	0.00	107.31	12.56
*	78R	DSF0000798232	CURTIS HIGH SCHOOL ANNEX	R	345	May-14	Sep-15	Sep-17	97.27	0.14	97.14	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable. L Proposed Leased Facility

New York City School Construction Authority New York City Department of Education FY 2015 - FY 2019 Capacity Program Site Location

DISTRICT	SCHOOL	BOROUGH	LOCATION
2	I.S. 323	М	75 MORTON STREET
2	P.S. / I.S. @ WESTERN RAILYARDS	М	WEST 30TH STREET AND 11TH AVENUE
2	P.S. 464	М	28-42 TRINITY PLACE
3	P.S. 342 (RIVERSIDE CENTER)	М	21 WEST END AVENUE
8	P.S. 14 ADDITION	Х	3041 BRUCKNER BOULEVARD
10	P.S. 46 ADDITION	Х	279 EAST 196TH STREET
11	P.S. 97 ADDITION	Х	1375 MACE AVENUE
12	P.S. @ TREMONT / WEST FARMS	Х	BOONE AVENUE AND EAST 172ND STREET
13	THE DOCK STREET EDUCATIONAL COMPLEX	К	19 DOCK STREET
13	I.S. 653	К	491 DEAN STREET
15	P.S. 32 ADDITION	К	317 HOYT STREET
15	P.S. 516 SUNSET PARK AVENUES ELEMENTARY SCHOOL	К	4222 4TH AVENUE
15	P.S. @ 4302 4TH AVENUE	К	4302 4TH AVENUE
19	P.S./I.S. @ 3269 ATLANTIC AVENUE	К	3269 ATLANTIC AVENUE
20	P.S. 127 ADDITION	K	7805 7TH AVENUE
20	P.S. 746	K	256 59TH STREET
21	P.S. 97 ADDITION	К	1855 STILLWELL AVENUE
21	P.S. 101 ADDITION	K	2360 BENSON AVENUE
24	P.S 19 ADDITION	Q	98-02 ROOSEVELT AVENUE
24	I.S. 125 ADDITION	Q	46-02 47TH AVENUE
24	P.S. 49 ADDITION	Q	63-60 80TH STREET
24	P.S. 143 ADDITION	Q	34-74 113TH STREET
24	P.S. 128 ADDITION	Q	69-10 65TH DRIVE
24	I.S. 419	Q	111-10 ASTORIA BOULEVARD
24	P.S. 143 ANNEX	Q	98-07 38TH AVENUE
25	P.S. 24 ADDITION	Q	141-11 HOLLY AVENUE
25	P.S. 129 ADDITION	Q	128-02 7TH AVENUE
26	P.S. 332	Q	210-07 48TH AVENUE

New York City School Construction Authority New York City Department of Education FY 2015 - FY 2019 Capacity Program Site Location

DISTRICT	SCHOOL	BOROUGH	LOCATION
27	P.S. 66 ADDITION	Q	85-11 102ND STREET
27	P.S. 335	Q	150-15 RALEIGH STREET
28	P.S. 303 ADDITION	Q	108-55 69TH AVENUE
28	P.S. 144 ADDITION	Q	93-02 69TH AVENUE
30	P.S. @ PARCEL C	Q	1-50 54TH AVENUE
30	P.S. @ PARCEL F	Q	2ND STREET BETWEEN 56TH AVENUE AND 57TH AVENUE
30	P.S. 398	Q	69-01 34TH AVENUE
30	I.S. @ 38-04 48TH STREET	Q	38-04 48TH STREET
31	FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	R	1625 FOREST AVENUE
31	P.S. @ 357 TARGEE STREET	R	357 TARGEE STREET
31	I.S. 82	R	104 GORDON STREET
78Q	IS/HS 336	Q	124-06 14TH AVENUE
78Q	ACADEMY OF AMERICAN STUDIES	Q	28-01 41ST AVENUE
78R	CURTIS HS ANNEX	R	105 HAMILTON AVENUE

New York City School Construction Authority New York City Department of Education FY 2010 - FY 2014 Five Year Capital Plan Capacity in Process

District		BOROUGH	ADDRESS	NUMBER OF SEATS
8	PS 317		1024-1036 WHITE PLAINS ROAD	468
22	PS/IS 338	K	510 CONEY ISLAND AVE	757
24	P.S./ I.S. 298	Q	50-51 98TH STREET	796
30	P.S. 11 ADDITION	Q	54-25 SKILLMAN AVENUE	654
	TOTAL SEATS OPENING SEPTEMBER 2017			2,675

					Forecast	Design	Constr	Actual / Est.	Total Est.	Previous	Funding Reg'd	Needed to
	District	Project #	School	Boro		Start	Start	Compl	Cost	Appropriations	FY 15-19	Complete
*L	02	DSF0000800052	PRE-K CENTER@ 2-26 WASHINGTON ST	М	108	Jun-14	Jan-15	Sep-15	13.33	0.01	13.32	0.00
*	02	DSF0000821653	PRE-K CENTER @ 2 LAFAYETTE STREET	М	36	Oct-14	Jul-15	Sep-16	8.43	0.00	8.43	0.00
*L	07	DSF0000800054	PRE-K CENTER @ 105 WILLIS AVENUE	Х	90	Jun-14	Dec-14	Jul-15	8.61	0.00	8.61	0.00
*L	07	DSF0000800055	PRE-K CENTER@ 535 UNION AVENUE	Х	180	Jun-14	Dec-14	Jul-15	13.15	0.00	13.15	0.00
*L	09	DSF0000801087	PRE-K CENTER @1434 OGDEN AVENUE	Х	90	Oct-14	Mar-15	Aug-15	10.57	0.00	10.57	0.00
*L	10	DSF0000821711	PRE-K CENTER @ 3560 WEBSTER AVENUE	Х	90	Dec-14	Sep-15	Sep-16	8.04	0.00	8.04	0.00
*L	10	DSF0000821828	PRE-K CENTER @ 5500 BROADWAY	Х	54	Apr-15	Feb-16	Sep-16	5.74	0.00	5.74	0.00
*L	10	DSF0000821875	PRE-K CENTER 2 @ 2490-2500 WEBSTER AVENUE	Х	198	Apr-15	Feb-16	Sep-17	16.02	0.00	16.02	0.00
*L	10	DSF0000821874	PRE-K CENTER @ 3605 SEDGWICK AVENUE	Х	36	Apr-15	Dec-15	Sep-16	5.20	0.00	5.20	0.00
* L	10	DSF0000822032	PRE-K CENTER @ 2510 MARION AVENUE	х	36	May-15	Mar-16	Sep-16	12.77	0.00	12.77	0.00
* L	10	DSF0000822030	PRE-K CENTER @ 2510 MARION AVENUE	х	234	May-15	Jul-15	Sep-15	0.21	0.00	0.21	0.00
*L	13	DSF0000821675	THE DOCK STREET EDUCATIONAL COMPLEX	К	72	Dec-14	May-15	Jul-16	5.75	0.00	5.75	0.00
*L	15	DSF0000821918 § Total Estimated C	PRE-K CENTER @ 500 19TH STREET ost	К	288	Feb-15	Mar-15	Sep-15	41.83	0.00	41.83	0.00
* L	15	DSF0000822214	PRE-K CENTER @ 219 25TH STREET	К	72	Jul-15	Apr-16	Sep-17	11.65	0.00	11.65	0.00
L	15	DSF0000845586	PRE-K CENTER @ 4TH AVENUE	К	144	Sep-16	Jan-17	Sep-17	20.00	0.00	20.00	0.00
* L	15	DSF0000821832	PRE-K CENTER @ 305-307 THIRD AVENUE	к	54	Mar-15	Nov-15	Sep-16	10.01	0.00	10.01	0.00
*L	15	DSF0000821928 § Total Estimated C	PRE-K CENTER @ 173 25TH STREET ost	К	108	Mar-15	May-15	Aug-15	8.22	0.00	8.22	0.00
* L	15	DSF0000822084	PRE-K CENTER @ 131 UNION STREET	к	36	Jun-15	Jan-16	Sep-16	7.78	0.00	7.78	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*	20	DSF0000821654	PRE-K CENTER@ 8501 5TH AVENUE	к	18	Oct-14	Apr-15	Sep-15	6.03	0.00	6.03	0.00
*L	20	DSF0000821713	PRE-K CENTER @ 2165 71ST STREET	К	90	Dec-14	May-15	Aug-16	21.10	0.00	21.10	0.00
*L	20	DSF0000800304	PRE-K CENTER @ 550 59TH STREET	К	162	Jul-14	Dec-15	Aug-16	10.02	0.00	10.02	0.00
*	20	DSF0000821813	PRE-K CENTER @ 369 93RD STREET	К	252	Feb-15	Jun-16	Sep-18	43.54	0.00	43.54	0.00
*	20	DSF0000821967	PRE-K CENTER @ 140A 58TH STREET	К	126	Apr-15	Jun-15	Sep-15	19.02	0.00	19.02	0.00
*L	20	DSF0000821958	PRE-K CENTER @ 1423 62ND STREET	К	324	Apr-15	May-16	Jul-17	34.41	0.00	34.41	0.00
*L	20	DSF0000800123	PRE-K CENTER @ 1258 65TH STREET	К	126	Jun-14	Dec-14	Jul-15	13.10	0.00	13.10	0.00
*L	20	DSF0000822082	PRE-K CENTER @ 21 BAY 11TH STREET	К	54	Apr-15	Jan-16	Sep-16	11.38	0.00	11.38	0.00
*L	20	DSF0000822014	PRE-K CENTER @ 21 BAY 11TH STREET	К	234	Jan-15	Sep-15	Sep-15	0.23	0.00	0.23	0.00
*L	20	DSF0000800057	PRE-K CENTER @ 1355 84TH STREET	К	90	Jun-14	Jan-15	Sep-15	12.18	0.00	12.18	0.00
*L	20	DSF0000822162	PRE-K CENTER @ 1355 84TH STREET	К	72	May-15	Aug-15	Sep-16	0.39	0.00	0.39	0.00
*L	20	DSF0000800047	PRE-K CENTER @ 1668 46TH STREET	К	180	Jun-14	Nov-14	Jul-15	7.11	0.02	7.08	0.00
*L	20	DSF0000822086	PRE-K CENTER @ 7401 FORT HAMILTON	К	270	May-15	Jul-15	Sep-15	15.65	0.00	15.65	0.00
		§ Total Estimated Co	PARKWAY ost									
*L	21	DSF0000800230	PRE-K CENTER @ 2202 60TH STREET	к	108	Jun-14	Jan-15	Jul-15	5.06	0.00	5.06	0.00
*L	21	DSF0000822037 § Total Estimated Co	PRE-K CENTER @ 385 AVENUE W ost	К	126	May-15	May-15	Sep-15	3.75	0.00	3.75	0.00
*L	21	DSF0000821960	PRE-K CENTER @ 1223 CONEY ISLAND AVENUE	К	72	Apr-15	Jan-16	Jul-17	10.02	0.00	10.02	0.00
*L	21	DSF0000821873	PRE-K CENTER @ 10 BOUCK COURT	К	180	Mar-15	Jan-16	Aug-16	17.94	0.00	17.94	0.00
*L	21	DSF0000800303	PRE-K CENTER @ 1215 AVENUE X	К	108	Jul-14	Dec-14	Sep-15	5.30	0.00	5.30	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

						_ .	•	Actual /			Funding	N I. I.
	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Est. Compl	Total Est. Cost	Previous Appropriations	Req'd FY 15-19	Needed to Complete
*L	22	DSF0000822024 § Total Estimated C	PRE-K CENTER @ 3610 GLENWOOD ROAD ost	К	144	Apr-15	May-15	Sep-15	14.88	0.00	14.88	0.00
*L	22	DSF0000822027 § Total Estimated C	PRE-K CENTER @ 1340 EAST 29TH STREET ost	К	252	Apr-15	May-15	Sep-15	15.54	0.00	15.54	0.00
*L	22	DSF0000800113	PRE-K CENTER @ 1139 CONEY ISLAND AVENUE	К	144	Jun-14	Dec-14	Sep-15	13.03	0.00	13.03	0.00
* L	24	DSF0000822186	PRE-K CENTER @ 70-24 47TH AVENUE	Q	90	Jun-15	Apr-16	Sep-17	5.03	0.00	5.03	0.00
*L	24	DSF0000822111 § Total Estimated C	PRE-K CENTER @ 56-01 61ST STREET ost	Q	162	May-15	Aug-15	Sep-15	7.04	0.00	7.04	0.00
L	24	DSF0000844691	PRE-K CENTER @ 101ST STREET	Q	54	Sep-16	Apr-17	Sep-18	10.00	0.00	10.00	0.00
L	24	DSF0000844699	PRE-K CENTER @ 111TH STREET	Q	306	Aug-16	Dec-16	Aug-19	50.00	0.00	48.56	1.44
L	24	DSF0000844698	PRE-K CENTER 1 @ ROOSEVELT AVENUE	Q	72	Aug-16	May-17	Sep-17	15.01	0.00	15.01	0.00
* L	24	DSF0000800114	PRE-K CENTER @ 46-16 76TH STREET	Q	108	Jun-14	Dec-14	Sep-15	15.80	0.00	15.80	0.00
* L	24	DSF0000800248	PRE-K CENTER @ 44-15 JUDGE STREET	Q	144	Jun-14	Dec-14	Jun-15	6.16	0.00	6.16	0.00
* L	24	DSF0000800282	PRE-K CENTER @ 68-20 MYRTLE AVENUE	Q	180	Jul-14	Dec-14	Jul-15	7.86	0.00	7.86	0.00
*L	24	DSF0000822099	PRE-K CENTER @ 107-17 NORTHERN BOULEVARD	Q	77	Jun-15	Jan-16	Jul-16	5.60	0.00	5.60	0.00
*L	24	DSF0000822098	PRE-K CENTER @ 106-02 NORTHERN BOULEVARD	Q	36	Jun-15	Jan-16	Sep-16	4.08	0.00	4.08	0.00
L	24	DSF0000845581	PRE-K CENTER 2 @ ROOSEVELT AVENUE	Q	54	Sep-16	Jan-17	Sep-17	8.00	0.00	8.00	0.00
L	24	DSF0000844747	PRE-K CENTER @ 99 STREET	Q	36	Sep-16	Apr-17	Sep-17	8.00	0.00	8.00	0.00
* L	25	DSF0000821980 PRE-K CENTER @ 14-45 143RD STREET		Q	108	Apr-15	Jan-16	Sep-16	3.59	0.00	3.59	0.00
* L	25	DSF0000821868	PRE-K CENTER @ 123-07 22ND AVENUE	Q	144	Feb-15	Dec-15	Sep-17	6.29	0.00	6.29	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

					Forecast	Design	Constr	Actual / Est.	Total Est.	Previous	Funding Req'd	Needed to
	District	Project #	School	Boro	Capacity	Start	Start	Compl	Cost	Appropriations	FY 15-19	Complete
*L	28	DSF0000800117	PRE-K CENTER @ 89-14 PARSONS BOULEVARD	Q	72	Jun-14	Dec-14	Jun-15	8.33	0.00	8.33	0.00
*L	28	DSF0000800124	PRE-K CENTER @ 132-10 JAMAICA AVENUE	Q	90	Jun-14	Dec-14	Sep-15	11.98	0.00	11.98	0.00
*L	28	DSF0000801086	PRE-K CENTER @ 83-30 KEW GARDENS ROAD	Q	72	Sep-14	Mar-15	Sep-15	8.34	0.00	8.34	0.00
*L	29	DSF0000800116	PRE-K CENTER @ 168-42 JAMAICA AVENUE	Q	126	Jun-14	Dec-14	Aug-15	18.22	0.00	18.22	0.00
*L	29	DSF0000801025	PRE-K CENTER @ 100-01 SPRINGFIELD BOULEVARD	Q	162	Aug-14	Dec-14	Jul-15	8.72	0.00	8.72	0.00
*L	30	DSF0000800058	PRE-K CENTER @ 96-10 23RD AVENUE	Q	108	Jun-14	Dec-14	Jun-15	11.20	0.01	11.19	0.00
*L	30	DSF0000821858	PRE-K CENTER @ 32-52 37TH STREET	Q	126	Apr-15	Jul-16	Sep-17	9.72	0.00	9.72	0.00
* L	30	DSF0000822015	PRE-K CENTER @ 32-52 37TH STREET	Q	270	Apr-15	Aug-15	Sep-15	0.05	0.00	0.05	0.00
*L	30	DSF0000843935	PRE-K CENTER @ 27-35 JACKSON AVENUE	Q	180	Jan-16	Apr-16	Sep-17	15.85	0.00	15.85	0.00
*L	31	DSF0000800050	FOREST AVENUE COMMUNITY EDUCATIONAL COMPLEX	R	90	Jun-14	Dec-14	Sep-15	19.62	0.01	19.61	0.00
* L	31	DSF0000800328	PRE-K CENTER @ 1 TELEPORT DRIVE	R	144	Aug-14	Dec-14	Sep-15	15.22	0.00	15.22	0.00
*L	31	DSF0000800267	PRE-K CENTER @120 STUYVESANT PLACE	R	108	Jul-14	Jan-15	Aug-15	19.26	0.00	19.26	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable.

L Proposed Leased Facility

New York City School Construction Authority New York City Department of Education FY 2015 - FY 2019 Pre-Kindergarten Initiative Projects Site Location

DISTRICT	SCHOOL	BOROUGH	LOCATION
2	PRE-K CENTER @ 2-26 WASHINGTON	M	2-26 WASHINGTON STREET
2	PRE-K CENTER @ 2 LAFAYETTE STREET	М	2 LAFAYETTE STREET
7	PRE-K CENTER @ 105 WILLIS AVENUE	Х	105 WILLIS AVENUE
7	PRE-K CENTER @ 535 UNION AVENUE	Х	535 UNION AVENUE
9	PRE-K CENTER @ 1434 OGDEN AVENUE	Х	1434 OGDEN AVENUE
10	PRE-K CENTER @ 3605 SEDGWICK AVENUE	Х	3605 SEDGWICK AVENUE
10	PRE-K CENTER @ 3560 WEBSTER AVENUE	Х	3560 WEBSTER AVENUE
10	PRE-K CENTER @ 2510 MARION AVENUE	Х	2510 MARION AVENUE
10	PRE-K CENTER @ 5500 BROADWAY	Х	5500 BROADWAY
10	PRE-K CENTER @ 2490-2500 WEBSTER AVENUE	Х	2490-2500 WEBSTER AVENUE
13	THE DOCK STREET EDUCAITONAL COMPLEX	К	19 DOCK STREET
15	PRE-K CENTER @ 500 19TH STREET	К	500 19TH STREET
15	PRE-K CENTER @ 173 25TH STREET	K	173 25TH STREET
15	PRE-K CENTER @ 219 25TH STREET	К	219 25TH STREET
15	PRE-K CENTER @ 305-307 3RD AVENUE	К	305-307 3RD AVENUE
15	PRE-K CENTER @ 131 UNION STREET	К	131 UNION STREET
20	PRE-K CENTER @ 550 59TH STREET	К	550 59TH STREET
20	PRE-K CENTER @ 1258 65TH STREET	К	1258 65TH STREET
20	PRE-K CENTER @ 140A 58TH STREET	К	140A 58TH STREET
20	PRE-K CENTER @ 8501 5TH AVENUE	К	8501 5TH AVENUE
20	PRE-K CENTER @ 369 93RD STREET	К	369 93RD STREET
20	PRE-K CENTER @ 21 BAY 11TH STREET	К	21 BAY 11TH STREET
20	PRE-K CENTER @ 1355 84TH STREET	К	1355 84TH STREET
20	PRE-K CENTER @ 7401 FORT HAMILTON PARKWAY	К	7401 FORT HAMILTON PARKWAY
20	PRE-K CENTER @ 2165 71ST STREET	К	2165 71ST STREET
20	PRE-K CENTER @ 1423 62ND STREET	К	1423 62ND STREET
20	PRE-K CENTER @ 1668 46TH STREET	К	1668 46TH STREET
21	PRE-K CENTER @ 2202 60TH STREET	К	2202 60TH STREET

New York City School Construction Authority New York City Department of Education FY 2015 - FY 2019 Pre-Kindergarten Initiative Projects Site Location

DISTRICT	SCHOOL	BOROUGH	LOCATION
21	PRE-K CENTER @ 1223 CONEY ISLAND AVENUE	К	1223 CONEY ISLAND AVENUE
21	PRE-K CENTER @ 385 AVENUE W	К	385 AVENUE W
21	PRE-K CENTER @ 10 BOUCK COURT	К	10 BOUCK COURT
21	PRE-K CENTER @ 1215 AVENUE X	К	1215 AVENUE X
22	PRE-K CENTER @ 3610 GLENWOOD ROAD	K	3610 GLENWOOD ROAD
22	PRE-K CENTER @ 1340 EAST 29TH STREET	K	1340 EAST 29TH STREET
22	PRE-K CENTER @ 1139 CONEY ISLAND AVENUE	K	1139 CONEY ISLAND AVENUE
24	PRE-K CENTER @ 70-24 47TH AVENUE	Q	70-24 47TH AVENUE
24	PRE-K CENTER @ 106-02 NORTHERN BOULEVARD	Q	106-02 NORTHERN BOULEVARD
24	PRE-K CENTER @ 107-17 NORTHERN BOULEVARD	Q	107-17 NORTHERN BOULEVARD
24	PRE-K CENTER @ 46-16 76TH STREET	Q	46-16 76TH STREET
24	PRE-K CENTER @ 44-15 JUDGE STREET	Q	44-15 JUDGE STREET
24	PRE-K CENTER @ 56-01 61ST STREET	Q	56-01 61ST STREET
24	PRE-K CENTER @ 68-20 MYRTLE AVENUE	Q	68-20 MYRTLE AVENUE
25	PRE-K CENTER @ 14-45 143RD STREET	Q	14-45 143RD STREET
25	PRE-K CENTER @ 123-07 22ND AVENUE	Q	123-07 22ND AVENUE
28	PRE-K CENTER @ 89-14 PARSONS BOULEVARD	Q	89-14 PARSONS BOULEVARD
28	PRE-K CENTER @ 83-30 KEW GARDENS	Q	83-30 KEW GARDEN ROAD
28	PRE-K CENTER @132-10 JAMAICA AVENUE	Q	132-10 JAMAICA AVENUE
29	PRE-K CENTER @ 168-42 JAMAICA AVENUE	Q	168-42 JAMAICA AVENUE
29	PRE-K CENTER @ 100-01 SPRINGFIELD BOULEVARD	Q	100-01 SPRINGFIELD BOULEVARD
30	PRE-K CENTER @ 96-10 23RD AVENUE	Q	96-10 23RD AVENUE
30	PRE-K CENTER @ 32-52 37TH STREET	Q	32-52 37TH STREET
30	PRE-K CENTER @ 27-35 JACKSON AVENUE	Q	27-35 JACKSON AVENUE
31	ECC @ 1625 FOREST AVENUE	R	1625 FOREST AVENUE
31	PRE-K CENTER @ 120 STUYVESANT PLACE	R	120 STUYVESANT PLACE
31	PRE-K CENTER @ 1 TELEPORT DRIVE	R	1 TELEPORT DRIVE

	District	Project #	School	Boro	Forecast Capacity	Design Start	Constr Start	Actual / Est. Compl	Total Est. Cost	Previous Appropriations	Funding Req'd FY 15-19	Needed to Complete
*L	10	DSF0000775874	P.S. 315	Х	Replacement	Sep-13	Mar-15	May-17	17.45	0.49	16.96	0.00
*L	12	DSF0000800056	SOUTHERN BOULEVARD COMMUNITY CAMPUS	х	Replacement	Sep-14	Jul-15	Jul-16	9.98	0.00	9.98	0.00
*	24	DSF0000798568	P.S. 19 MINISCHOOL	Q	Replacement	Mar-15	Jul-16	Sep-18	15.87	0.00	15.86	0.00
*	25	DSF0000798203	P.S. 24 ADDITION	Q	Replacement	Dec-14	Jul-16	Sep-18	9.26	0.00	9.26	0.00

* School with existing site identified. Total Estimated Cost includes site acquisition costs when applicable. L Proposed Leased Facility

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
07	Bronx	X001		P.S. 1				
				DS	F0000799648	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	116,869
			X001	DS	F0000793624	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 1 Total:	\$152,108
07	Bronx	X005		P.S. 5				
			X005	DS	F0000845607	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	68,000
			X005	DS	F0000793698	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			X005	DS	F0000800167	New/Retrofit Telephone/Intercom Systems	2015	194,696
			X005	DS	F0000822046	New/Retrofit Telephone/Intercom Systems	2015	194,696
							P.S. 5 Total:	\$492,655
07	Bronx	X018		P.S. 18				
				DS	F0000817054	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 18 Total:	\$101,351
07	Bronx	X025		P.S. 25				
				DSF	60000794002	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	821,464
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X025	DSF	0000775658	State of Good Repair - System Replacements - Domestic Piping	2015	769,263
			X025		0000817177	DOMESTIC WATER SYSTEM State of Good Repair - System Replacements - Exterior	2017	12,139,150
			7025	031	0000817177	Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2017	12,139,130
			X025	DSF	0000823600	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2017	1,372,518
			X025	DSF	0000817176	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,559,803
				DSF	0000817178	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	254,512

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000843682	State of Good Repair - System Replacements - Windows	2017	6,326,572
						Other		
			X025	DSI	F0000800206	Classroom Connectivity	2015	25,575
			X025	DSI	F0000822069	New/Retrofit Telephone/Intercom Systems	2015	216,684
							P.S. 25 Total:	\$23,485,541
07	Bronx	X027		P.S. 277				
				DSI	F0000794046	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	878,747
			X277	DSI	F0000794052	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	172,336
			X277	DSI	F0000817223	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	352,474

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			- 5			FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
						Other		
			X277	DSF	0000800207	Classroom Connectivity	2015	38,725
							P.S. 277 Total:	\$1,442,282
07	Bronx	X029		P.S. 29				
						Other		
			X029	DSF	0000800177	New/Retrofit Telephone/Intercom Systems	2015	227,012
			X029	DSF	0000800208	Classroom Connectivity	2015	16,230
			X029	DSF	0000822047	New/Retrofit Telephone/Intercom Systems	2015	227,012
							P.S. 29 Total:	\$470,254
07	Bronx	X030		P.S. 30				
			X030	DSF	0000794103	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	0000799845	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	37,146
							P.S. 30 Total:	\$72,409
07	Bronx	X040		P.S. 220				

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X179	DSF	-0000800210	Classroom Connectivity	2015	417,700
							P.S. 220 Total:	\$417,700
07	Bronx	X043		P.S. 43				
				DSF	-0000794276	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,272,167
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 43 Total:	\$1,272,167
07	Bronx	X049		P.S. 49				
				DSF	-0000817585	State of Good Repair - System Replacements - Toilets-Students	2016	101,399
						FIXTURES:Student:Lavatory/Sink		
_						FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							P.S. 49 Total:	\$101,399
07	Bronx	X065		P.S. 65				
				DSF	-0000798468	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	517,398

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000823658	State of Good Repair - System Replacements -	2016	101,351
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			X065	-	F0000800186	New/Retrofit Telephone/Intercom Systems	2015	188,079
			X065	DS	F0000800220	Classroom Connectivity	2015	384,536
			X065	DS	F0000822049	New/Retrofit Telephone/Intercom Systems	2015	188,079
							P.S. 65 Total:	\$1,379,443
07	Bronx	X139		J.H.S. 22	2			
				DS	F0000796006	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,477,231
				DS	F0000819196	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Heating	2018	245,771
						Plant Upgrade		
						Other		
			X224	DS	F0000800240	Classroom Connectivity	2015	427,685

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							J.H.S. 222 Total:	\$2,150,687
07	Bronx	X149		J.H.S. 149				
				DSF	0000775797	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2015	2,441,679
						CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE LAB:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE LAB SCIENCE PREP ROOM		
				DSF	0000798288	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,330,369
				DSF	0000821600	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
							J.H.S. 149 Total:	\$4,305,284
07	Bronx	X151		I.S. 151				
			X151	DSF	0000865721	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2019	2,300,000
			X151	DSF	0000843885	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2016	97,794

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			X031	DS	F0000843920	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	97,794
			X151	DS	F0000845600	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	47,000
			X031	DS	F0000865717	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	95,000
				DS	F0000796234	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	2,472,881
				DS	F0000819442	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X031	DSI	F0000800192	New/Retrofit Telephone/Intercom Systems	2015	294,416
			X031	DSI	F0000800244	Classroom Connectivity	2015	477,274
			X151	DSI	F0000822048	New/Retrofit Telephone/Intercom Systems	2015	294,416
							I.S. 151 Total:	\$6,277,926
07	Bronx	X154		P.S. 154				
				DS	F0000796295	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,288,700
			X154	DS	F0000819504	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
						Other		
			X154	DSI	F0000800246	Classroom Connectivity	2015	420,089
							P.S. 154 Total:	\$1,864,155
07	Bronx	X156		P.S. 156				
				DSI	F0000796339	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,393,864

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X359	DS	F0000819545	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 156 Total:	\$1,645,215
07	Bronx	X157		P.S. 157				
				DS	F0000796354	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,332,566
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 157 Total:	\$1,332,566
07	Bronx	X161		P.S. 161				
				DS	F0000796418	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,618,231
				DS	F0000799856	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	37,146

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X161	DS	F0000799873	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 161 Total:	\$1,690,616
07	Bronx	X162		I.S. 162				
			X162	DS	F0000823627	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,971,405
			X162	DS	F0000796441	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			X162	DS	F0000800193	New/Retrofit Telephone/Intercom Systems	2015	313,446
			X162	DS	F0000822040	New/Retrofit Telephone/Intercom Systems	2015	313,446
							I.S. 162 Total:	\$3,633,560
07	Bronx	X184		I.S. 184				
				DS	F0000800062	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	2,433,513
				DS	F0000796696	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	2,263,968
			X296	DS	F0000796702	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 184 Total:	\$4,732,720
07	Bronx	X807		DISTRICT	OFFICE #7 (OI	LD 18)		
				DSF	-0000797347	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	393,117
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			XADM	DSF	0000820508	State of Good Repair - Building Upgrade - Reinforcing	2017	232,682
						Support Elements INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		
						DISTRICT OFFICE #	7 (OLD 18) Total:	\$625,799
08	Bronx	X036		P.S. 36				
				DSF	-0000822097	Educational Enhancements - Educational Enhancements - Accessibility	2019	8,746,263
				DSF	-0000799904	Safety and Security - Safety and Security - Safety Systems	2016	316,468
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
				DSF	-0000799905	State of Good Repair - Building Upgrade - Flood Elimination	2016	2,436,127

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSI	F0000748526	State of Good Repair - System Replacements - Exterior	2016	9,774,184
						Masonry EXTERIOR:EXTERIOR WALLS		
				DSI	F0000794184	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	1,825,213
				DSI	F0000794183	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	1,459,672
				DSI	F0000799903	EXTERIOR:ROOFING:Specialties State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	1,148,156
						Other		
			X036	DSI	F0000776080	IP Surveillance Camera Installation	2015	670,990
							P.S. 36 Total:	\$26,377,073
08	Bronx	X048		P.S. 48				
				DSI	F0000799893	Educational Enhancements - Educational Enhancements - Accessibility	2016	11,875,853
				DSI	F0000771654	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,090,221

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
						Other		
			X048	DSF	-0000800213	Classroom Connectivity	2015	366,628
							P.S. 48 Total:	\$13,332,702
08	Bronx	X052		I.S. 302				
			X302	DSF	-0000865723	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
				DSF	-0000821878	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	45,982
			X302	DSF	-0000843869	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	79,500
				DSF	-0000799720	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	145,412
						Other		
			X302	DSF	-0000800182	New/Retrofit Telephone/Intercom Systems	2015	277,311
			X302	DSF	0000800214	Classroom Connectivity	2015	241,384

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X302	DSI	F0000822056	New/Retrofit Telephone/Intercom Systems	2015	277,311
							I.S. 302 Total:	\$3,366,900
08	Bronx	X060		P.S. 333				
						Other		
			X333	DS	F0000800217	Classroom Connectivity	2015	31,856
							P.S. 333 Total:	\$31,856
08	Bronx	X062		P.S. 62				
				DSI	F0000798495	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,500,000
				DSI	F0000794621	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,277,027
			X062	DS	F0000794625	State of Good Repair - System Replacements - Exterior Masonry	2018	7,415,141
			X062	DS	F0000794627	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			X062	DSI	F0000821924	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2018	1,349,323
				DSI	F0000817814	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						Other		
			X062	DSF	0000800185	New/Retrofit Telephone/Intercom Systems	2015	176,206
			X062	DSF	0000800218	Classroom Connectivity	2015	78,952
							P.S. 62 Total:	\$14,991,540
08	Bronx	X069		P.S. 69				
						Other		
			X069	DSF	0000776081	IP Surveillance Camera Installation	2015	613,959
							P.S. 69 Total:	\$613,959
08	Bronx	X071		P.S. 71				
			X071	DSF	0000775950	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP	2015	817,056
						PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSF	0000799656	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	143,831
			X071	DSF	0000754500	State of Good Repair - System Replacements - Exterior Masonry	2015	5,625,822
						EXTERIOR:EXTERIOR WALLS	0015	
			X071	DSF	0000772080	State of Good Repair - System Replacements - Parapets	2015	1,552,101

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
			X071	DS	SF0000772079	State of Good Repair - System Replacements - Roofs	2015	623,390
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
							P.S. 71 Total:	\$8,762,200
08	Bronx	X072		P.S. 72				
				DS	F0000794813	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	699,576
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000818005	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	81,924
						Other		
			X072	DS	F0000776082	IP Surveillance Camera Installation	2015	680,566
							P.S. 72 Total:	\$1,462,066
08	Bronx	X074		I.S. 201				
				DS	F0000799658	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	178,200
				DS	F0000839997	State of Good Repair - System Replacements - Paved Area-Concrete	2017	751,662
						SITE:RETAINING WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 201 Total:	\$929,862
08	Bronx	X075		P.S. 75				
			X075	DSI	F0000821946	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	152,560
				DSI	F0000794875	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,608,073
				DSI	F0000844137	System Expansion - New Physical Education Facilities - Playgrounds	2017	211,702
							P.S. 75 Total:	\$1,972,335
08	Bronx	X093		P.S. 93				
				DSI	F0000798472	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	906,561

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000777222	System Expansion - New Physical Education Facilities - Playgrounds	2016	1,694,484
						Other		
			X093	DSF	-0000800226	Classroom Connectivity	2015	37,041
							P.S. 93 Total:	\$2,638,086
08	Bronx	X100		P.S. 100				
				DSF	-0000772616	State of Good Repair - System Replacements - Exterior Masonry	2015	2,255,016
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
				DSF	-0000772615	EXTERIOR:LOUVER State of Good Repair - System Replacements - Parapets	2015	2,713,857
				201	0000112010	EXTERIOR:COPING	2010	2,710,007
						EXTERIOR:PARAPETS		
				DSF	-0000772614	State of Good Repair - System Replacements - Roofs	2015	2,899,574
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		* 7 000 447
							P.S. 100 Total:	\$7,868,447
08	Bronx	X101		I.S. 101				
				DSF	-0000798384	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,513,010

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000795357	State of Good Repair - Building Upgrade - Climate Control	2017	1,280,719
						CLIMATE CONTROL SYSTEM		
				DS	F0000818533	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,669,392
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000772648	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers	2015	1,370,886
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:FIRE BOOSTER PUMP ASSEMBLY SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING		
						Other		
			X101	DS	F0000822070	New/Retrofit Telephone/Intercom Systems	2015	405,879
						· · ·	I.S. 101 Total:	\$9,239,886
08	Bronx	X107		P.S. 107				
				DS	F0000799665	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	173,130

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X107	DSI	F0000795476	State of Good Repair - System Replacements -	2015	138,431
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			X107	DSI	F0000818658	State of Good Repair - System Replacements -	2016	251,351
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						INTERIOR. TOILET ROOMS - STUDENTS		
						Other		
			X107	DSI	F0000800187	New/Retrofit Telephone/Intercom Systems	2015	154,637
			X107	DSI	F0000843788	Classroom Connectivity	2016	320,401
							P.S. 107 Total:	\$1,037,950
08	Bronx	X119		P.S. 119				
				DSI	F0000798497	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000795691	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000795693	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	625,186
							P.S. 119 Total:	\$6,402,213
08	Bronx	X120		I.S. 301				
				DSI	F0000821766	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	425,404
			X301	DSI	F0000821752	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	113,100
			X188	DSI	F0000843871	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	51,000
			X188	DSI	F0000843880	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
			X301	DSI	F0000844144	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2017	121,215

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			X301	DS	F0000795714	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,475
							I.S. 301 Total:	\$854,626
08	Bronx	X123		I.S. 123				
				DS	F0000843910	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,477,444
			X123	DS	F0000795775	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000818959	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
						Other		
			X123	DS	F0000800236	Classroom Connectivity	2015	394,991
							I.S. 123 Total:	\$3,153,469
08	Bronx	X125		I.S. 125				
			X125	DS	F0000818971	State of Good Repair - Building Upgrade - Flood Elimination	2017	1,299,038
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000840918	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	2,904,218

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent		
				DSF	0000818977	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	214,639
						TATOREO.OTODENT.TOIRC	I.S. 125 Total:	\$4,417,895
08	Bronx	X130		P.S. 130				
				DSF	F0000819052	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP	2016	379,663
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSF	-0000795870	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	950,451
				DSF	50000819055	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2016	654,659

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X130	DS	F0000795876	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	50,777
				DS	F0000821697	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	272,076
			X130	DS	F0000821687	State of Good Repair - System Replacements - Roofs	2016	3,580,141
							P.S. 130 Total:	\$5,887,767
08	Bronx	X131		I.S. 131				
			X131	DS	F0000843873	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	127,000
			X131	DS	F0000845599	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	55,000
			X448	DS	F0000845601	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	155,000
				DS	F0000795891	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,173,391
				DS	F0000819072	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - System Replacements - Exterior Masonry	2016	201,509

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DS	F0000795893	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	811,402
						GAS SERVICE: GAS DISTRIBUTION PIPING HEATING		
						HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			X131	DS	F0000799872	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	55,822
			X131	DS	F0000819076	State of Good Repair - System Replacements - Toilets-Students	2015	187,779
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 131 Total:	\$2,766,903
08	Bronx	X140		P.S. 140				
			X140	DS	F0000796028	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 140 Total:	\$35,239
08	Bronx	X146		P.S. 146				
			X146	DS	F0000821751	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2015	75,660

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			X146	DS	F0000843883	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	199,144
			X146	DS	F0000865718	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	177,000
				DS	F0000798354	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	990,202
						of AGE.EIGHTING.Eighting Fixture - incandescent	P.S. 146 Total:	\$1,442,006
08	Bronx	X152		P.S. 152				
			X152	DS	F0000845627	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
						Other		
			X152	DS	F0000800245	Classroom Connectivity	2015	392,853
							P.S. 152 Total:	\$2,692,853
08	Bronx	X174		I.S. 174				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X282	D	SF0000823626	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,246,924
				D	SF0000841667	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	2,156,289
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent		
				D	SF0000821617	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				D	SF0000819760	State of Good Repair - System Replacements - Paved Area-Concrete SITE:PAVING - STUDENT NON-USE:Concrete SITE:PAVING - STUDENT USE:Concrete SITE:SIDEWALKS:DOT Sidewalk	2017	782,948
			X282	D	SF0000796569	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	149,527
			X375	'n	SF0000799972	<i>Other</i> IP Surveillance Camera Installation	2015	340.008
			7010		G1 00001 9991 Z		I.S. 174 Total:	\$7,208,932

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
08	Bronx	X182		P.S. 182				
				DSI	F0000799669	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,149,451
							P.S. 182 Total:	\$1,149,451
08	Bronx	X192		I.S. 192				
			X371	DSI	F0000796723	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSI	F0000819904	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310
						Other		
			X366	DSI	F0000800195	New/Retrofit Telephone/Intercom Systems	2015	236,532
							I.S. 192 Total:	\$583,105
08	Bronx	X848		P.S. 48 A)	K (HNTS PNT E	CC1)		
				DSI	F0000797422	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,104,772
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000774687	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	742,584
				DSI	F0000798241	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	413,053

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000774688	State of Good Repair - System Replacements - Windows	2015	281,448
						EXTERIOR:WINDOWS		<u> </u>
						P.S. 48 AX (HNT	S PNT ECC1) Total:	\$2,541,857
09	Bronx	X002		MORRISA	NIA SEC ED C	OMPLEX		
			X250	-	F0000793643	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,289,890
				DSI	F0000798315	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,513,010
				DSI	F0000798318	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,227,863
				SC	A0000025434	State of Good Repair - System Replacements - Exterior Masonry	2015	1,991,692
			X250	DS	F0000793644	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	52,241
			X250	DSI	F0000793641	State of Good Repair - System Replacements - Parapets	2015	1,487,215

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
			X250	DS	F0000793640	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	2,250,723
						MORRISANIA SEC EL	OCOMPLEX Total:	\$12,812,634
09	Bronx	X004		P.S. 4				
				DS	F0000843981	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	266,047
				DS	F0000793675	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,379,031
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000816881	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							P.S. 4 Total:	\$1,719,884
09	Bronx	X011		P.S. 11				
						Other		
			X011	DS	F0000776078	IP Surveillance Camera Installation	2015	518,247
							P.S. 11 Total:	\$518,247
09	Bronx	X022		I.S. 22				
				DS	F0000821666	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	288,374

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X323	DS	F0000821769	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	92,308
			X323	DS	F0000845598	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	118,000
				DS	F0000817119	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,281,620
			X022	DS	F0000771219	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	2,220,936
				DS	F0000817128	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2016	243,984
						Other		
			X022	DS	F0000800175	New/Retrofit Telephone/Intercom Systems	2015	275,333
							I.S. 22 Total:	\$4,520,555

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X028		P.S. 28				
				DSF	-0000748409	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2016	1,427,512
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			X028	DSF	-0000800308	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,927,444
				DSF	-0000799844	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
				DSF	-0000817236	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal	P.S. 28 Total:	\$3,535,613
09	Bronx	X035		P.S. 35				<i>40,000,0</i>
				DSF	-0000771439	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,862,132
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	-0000794162	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	624,418

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000771443	State of Good Repair - System Replacements - Exterior Masonry	2015	1,573,124
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS		
				DS	F0000771442	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	7,341
			X035	DS	F0000794168	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	182,677
				DS	F0000817344	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2017	159,628
						Other		
			X035	DS	F0000800178	New/Retrofit Telephone/Intercom Systems	2015	126,725
							P.S. 35 Total:	\$4 536 045

P.S. 35 Total: \$4,536,045

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X053		P.S. 53 DSF	-0000799846	State of Good Repair - System Replacements - Heating	2015	61,958
						Plant Upgrade	P.S. 53 Total:	\$61,958
09	Bronx	X055	X055	P.S. 55 DSF	F0000821770	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	92,308
				DSF	F0000794496	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,486,537
			X055	DSF	50000817683	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351
			X055	DSF	-0000800215	<i>Other</i> Classroom Connectivity	2015	373,323

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 55 Total:	\$2,203,519
09	Bronx	X058		P.S. 58				
				DSF	0000799655	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	230,375
				DSF	0000817736	State of Good Repair - System Replacements - Toilets-Students	2015	295,623
						FIXTURES:STUDENT:Toilet		
							P.S. 58 Total:	\$525,998
09	Bronx	X063		P.S. 63				
				DSF	0000817833	State of Good Repair - System Replacements - Toilets-Students	2015	265,850
						FIXTURES:STUDENT:Toilet		
							P.S. 63 Total:	\$265,850
09	Bronx	X064		P.S. 64				
				DSF	0000794657	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,091,090
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			X064	DSF	0000800219	Classroom Connectivity	2015	39,378

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 64 Total:	\$1,130,468
09	Bronx	X070		P.S. 70				
			X070	DSF	-0000794783	State of Good Repair - System Replacements - Exterior Masonry	2017	6,944,092
			X070	DSF	0000817970	State of Good Repair - System Replacements - Parapets	2017	768,490
			X070	DSF	-0000821923	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2017	737,980
							P.S. 70 Total:	\$8,450,562
09	Bronx	X073		P.S. 73				
				DSF	-0000622598	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,551,510
						INTERIOR:Structural:Foundation Walls		
				DSF	-0000799657	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	237,235
				DSF	-0000709411	State of Good Repair - System Replacements - Exterior Masonry	2015	5,002,077
				DSF	-0000727828	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	2,026,791
			X073	DSF	-0000794842	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	117,401

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 73 Total:	\$8,935,014
09	Bronx	X082		I.S. 232				
			X232	DSF	-0000818199	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	4,785,441
				DSF	50000798432	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,213,687
			X232	SCA	40000030993	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2017	5,869,988
			X232	DSF	0000821948	State of Good Repair - System Replacements - Domestic Piping	2017	564,338
				DSF	-0000799851	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
			X232	DSF	50000795013	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	72,660

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			X232	DSF	-0000821949	State of Good Repair - System Replacements - Toilets-Students	2017	622,354
						INTERIOR: TOILET ROOMS - STUDENTS		
							I.S. 232 Total:	\$13,190,426
09 E	Bronx	X090		P.S. 90				
				DSF	-0000795167	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,196,223
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000818364	State of Good Repair - System Replacements - Exterior Masonry	2019	10,939,645
						EXTERIOR: EXTERIOR WALLS		
				DSF	-0000818363	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2019	1,596,611
						EXTERIOR:ROOFING:Specialties		
						Other		
			X443	DSF	-0000800225	Classroom Connectivity	2015	272,547
							P.S. 90 Total:	\$14,005,026

X - 39 of 123

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X104		P.S. 199				
			X199	DSI	F0000865726	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
						Other		
			X199	DSI	F0000800231	Classroom Connectivity	2015	18,221
							P.S. 199 Total:	\$2,318,221
09	Bronx	X109		P.S. 109				
	U9 DIOIIX			DSI	F0000798496	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,500,000
				DSI	F0000795500	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSI	F0000728491	State of Good Repair - Building Upgrade - Flood Elimination	2018	917,555
				DSI	F0000795501	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - Building Upgrade - Lighting Fixtures	2015	29,083
				DSI	F0000795506	State of Good Repair - System Replacements - Exterior Masonry	2018	2,719,422
			X109	DSI	F0000795508	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799852	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
				DS	F0000795505	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	155,629
				DS	F0000795504	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	636,357
				DS	F0000818691	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351
						Other		
			X109	DS	F0000800189	New/Retrofit Telephone/Intercom Systems	2015	148,281
							P.S. 109 Total:	\$10,581,926
09	Bronx	X114		P.S. 114				
			X114	DS	F0000798352	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2018	4,664,685
			X114	DS	F0000795596	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	SF0000795598	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	777,927
			X114	DS	F0000795601	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	\$F0000818788	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2016	101,351
							P.S. 114 Total:	\$6,902,988
09	Bronx	X117		I.S. 117 DS	F0000821888	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,059,666
			X568	DS	F0000821890	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	686,929
				DS	SF0000818851	Educational Enhancements - Educational Enhancements - Science Lab Upgrades INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM	2018	1,922,036

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture -		
						Fluorescent		
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture -		
						Incandescent		
						SCIENCE DEMO ROOM:POWER SUPPLY		
						SCIENCE LAB		
						SCIENCE LAB: EMERGENCY GAS SHUT-OFF VALVE		
						SCIENCE LAB:LIGHTING:Lighting Fixture -		
						Fluorescent		
						SCIENCE LAB:LIGHTING:Lighting Fixture -		
						SCIENCE LAB:POWER SUPPLY		
						SCIENCE PREP ROOM		
						SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent		
				DSFC	000821908	Educational Enhancements - Educational	2018	1,019,525
						Enhancements - Science Lab Upgrades		,,
							I.S. 117 Total:	\$4,688,156
09	Bronx	X126		P.S. 126 (E	CF)			
				DSFC	0000795809	State of Good Repair - Building Upgrade - Lighting	2015	1,120,839
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X126	DS	F0000795813	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			X126	DS	F0000801046	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2015	37,582
							P.S. 126 (ECF) Total:	\$1,193,684
09	Bronx	X132		P.S. 132				
				DS	F0000795908	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,070,762
			X132	DS	F0000819092	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
			X132	DS	F0000823621	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2019	84,146

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X132	DSF	0000800237	Classroom Connectivity	2015	91,390
							P.S. 132 Total:	\$1,401,664
09	Bronx	X145		I.S. 145				
			X145	DSF	-0000822085	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,413,605
			X145	DSF	-0000822686	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,959,540
			X325	DSF	F0000843881	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	97,794
			X145	DSF	-0000843882	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	173,960
				DSF	0000843876	Technology	2016	401,531
				DSF	-0000843878	Technology	2016	467,085
				DSF	-0000796116	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,717,193
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

I.S. 145 Total: \$8,230,708

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X147		I.S. 339 (O	LD 147)			
				DSF	0000844006	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,668,947
				DSF	0000796155	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,780,817
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000773432	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	8,033,900
			X339	DSF	0000798603	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	634,431
			X313	DSF	0000819357	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	251,351
					-000770044	INTERIOR: TOILET ROOMS - STUDENTS	0045	0.057.000
				DSF	0000776011	State of Good Repair - System Replacements - Windows	2015	2,657,203
						EXTERIOR:WINDOWS		

I.S. 339 (OLD 147) Total: \$16,026,649

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X148		I.S. 219 (C	OLD 148)			
			X219	DS	F0000823628	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,123,880
				DS	F0000796183	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	776,658
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
				DS	F0000799855	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	62,246
						1.5	6. 219 (OLD 148) Total:	\$3,962,784
09	Bronx	X163		P.S. 163				
			X163	DS	F0000798355	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685
			X163	DS	F0000798353	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DS	F0000798453	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	346,523
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			X163	DSF	0000800247	Classroom Connectivity	2015	88,292
							P.S. 163 Total:	\$6,423,262
09	Bronx	X166		I.S. 166				
			X324	DSF	0000776013	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	823,752
				DSF	0000821579	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,599,897
				DSF	0000773763	Educational Enhancements - Educational Enhancements - Science Lab Upgrades INTERIOR:SCIENCE PREP ROOM:Fixed Equipment	2016	3,737,081
				DSF	0000796472	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	2,358,489
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 166 Total:	\$9,519,219
09	Bronx	X171		P.S. 4 ANN	IEX (P171 ECC	;)		
			X004		0000843691	, State of Good Repair - System Replacements - Heating Plant Upgrade	2016	28,722

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						P.S. 4 ANNEX	(P171 ECC) Total:	\$28,722
09	Bronx	X172		P.S. 11 AM	NNEX (P172 EC	C)		
				DSF	-0000773814	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,108,026
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						P.S. 11 ANNEX	(P172 ECC) Total:	\$1,108,026
09	Bronx	X173		P.S. 236				
				DSF	-0000841659	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR SOFFITS	2017	3,141,510
						EXTERIOR:EXTERIOR WALLS		
			X236	DSF	-0000841657	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	165,826
							P.S. 236 Total:	\$3,307,336
09	Bronx	X229		P.S. 230/I.	.S. 229 (UDC)			
				DSF	-0000799671	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	130,317
				DSF	-0000796822	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	2,349,805
				SCA	40000027056	State of Good Repair - System Replacements - Domestic Piping Waste System	2015	9,371,790

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				SC/	40000027593	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers	2015	6,225,783
				DSI	F0000799351	State of Good Repair - System Replacements - Paved Area-Concrete	2015	861,778
						SITE:Drainage System for Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways		
						P.S. 230	/I.S. 229 (UDC) Total:	\$18,939,473
09	Bronx	X235		P.S./I.S. 2	18			
				DSI	F0000844730	Educational Enhancements - Educational Enhancements - Accessibility	2018	81,913
				DSI	F0000797776	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	32,439
			X218	DSI	F0000844166	State of Good Repair - System Replacements - Domestic Piping	2015	TBD
			X218	DSI	F0000844167	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2018	45,432
				DSI	F0000823586	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,807
						Other		
			X218	DSI	F0000843787	Classroom Connectivity	2016	289,529
							P.S./I.S. 218 Total:	\$524,120

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
09	Bronx	X236		P.S. 236 A	ANNEX (P173 E	CC)		
				DSI	F0000796839	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	207,885
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						P.S. 236 ANNEX	(P173 ECC) Total:	\$207,885
09	Bronx	X824		P.S. 204				
				DS	F0000797370	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	234,837
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						Other		
			X695	DS	F0000800264	Classroom Connectivity	2015	18,567
							P.S. 204 Total:	\$253,404
10	Bronx	X003		P.S. 3				
				DSI	F0000793656	State of Good Repair - Building Upgrade - Climate	2018	5,403,566
						Control CLIMATE CONTROL SYSTEM		
				DSI	F0000816873	State of Good Repair - System Replacements - Heating	2018	2,068,601
						Plant Upgrade Ventilation		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK		
			X003	C	SF0000793663	State of Good Repair - System Replacements - Parapets	2015	852,206
			X003	C	SF0000816867	State of Good Repair - System Replacements - Paved Area-Concrete	2016	2,018,525
						SITE: PAVING - STUDENT NON-USE: Concrete		
			X003	C	SF0000816860	State of Good Repair - System Replacements - Roofs	2016	1,142,893
						EXTERIOR:ROOFING:Roofing		
							P.S. 3 Total:	\$11,485,791
10	Bronx	X007		P.S. 7				
				C	SF0000799717	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	162,832
							P.S. 7 Total:	\$162,832
10	Bronx	X008		P.S. 8				
						Other		
			X008	C	SF0000800204	Classroom Connectivity	2015	386,571
							P.S. 8 Total:	\$386,571
10	Bronx	X009		P.S. 9 (OLD 115)			
			X009	٢	SF0000865724	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
				C	SF0000752356	State of Good Repair - Building Upgrade - Boiler Conversion	2016	7,319,028

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000752357	State of Good Repair - Building Upgrade - Climate Control	2016	1,369,417
				DS	F0000799649	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	153,603
							P.S. 9 (OLD 115) Total:	\$11,142,048
10	Bronx	X015		P.S. 15				
				DS	F0000843985	State of Good Repair - Building Upgrade - Flood Elimination	2017	564,378
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
							P.S. 15 Total:	\$564,378
10	Bronx	X020		P.S. 20				
			X020	DS	F0000843884	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	136,500
				DS	F0000799516	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Floor Finish	2015	229,135
				DS	F0000771191	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Floor Finish	2015	879,633
				DS	F0000799515	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	536,288

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			X020	DS	F0000800205	Classroom Connectivity	2015	519,884
							P.S. 20 Total:	\$2,301,440
10	Bronx	X024		P.S. 24				
				DS	F0000843870	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	4,270,754
				DS	F0000798382	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,513,010
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			X024	DS	F0000799754	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
				DS	F0000799651	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	194,481
							P.S. 24 Total:	\$10,206,108
10	Bronx	X026		P.S. 396				
			X390	DS	F0000794028	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 396 Total:	\$35,263
10	Bronx	X032		P.S. 32				
				DS	F0000844014	State of Good Repair - System Replacements - Exterior Masonry	2018	7,421,330

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X032	DSI	F0000799843	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DSI	F0000839282	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	85,380
				DSI	F0000844015	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2018	1,796,010
							P.S. 32 Total:	\$9,337,959
10	Bronx	X033		P.S. 33				
				DSI	F0000799654	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	139,385
						Other		
			X033	DSI	F0000800209	Classroom Connectivity	2015	43,303
							P.S. 33 Total:	\$182,688
10	Bronx	X045		I.S. 45				
			X045	DS	F0000823641	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	877,137
				DS	F0000794320	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,310,119
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			X045	DSF	-0000800212	Classroom Connectivity	2015	30,425
							I.S. 45 Total:	\$2,217,681
10	Bronx	X046		P.S. 46				
				DSF	-0000823583	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
			X046	DSF	-0000794348	State of Good Repair - System Replacements - Toilets-Students	2015	257,239
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 46 Total:	\$332,045
10	Bronx	X056		P.S. 56				
						Other		
			X056	DSF	-0000800216	Classroom Connectivity	2015	65,915
							P.S. 56 Total:	\$65,915
10	Bronx	X079		P.S. 79				
				DSF	-0000798466	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,031,544

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000821632	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DSF	0000799848	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
						Other		
			X382	DSF	0000800222	Classroom Connectivity	2015	505,855
							P.S. 79 Total:	\$2,149,941
10	Bronx	X080		I.S. 80/P.S.	. 280			
				DSF	0000844731	Educational Enhancements - Educational Enhancements - Accessibility	2018	112,263
				DSF	0000821671	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	972,078
				DSF	0000799659	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	125,316
			X080	DSF	0000821800	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	2,681,406
				DSF	0000799849	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	103,825

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X080	DSF	-0000800223	Classroom Connectivity	2015	503,251
							I.S. 80/P.S. 280 Total:	\$4,498,139
10	Bronx	X081		P.S. 81				
			X081	DSF	F0000823643	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	1,173,475
			X081	DSF	-0000818176	State of Good Repair - Building Upgrade - Flood Elimination	2017	715,142
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMI PUMP	2	
				DSF	-0000794983	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	872,631
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X081	DSF	-0000818181	State of Good Repair - System Replacements - Exterior	· 2017	1,616,354
						Masonry		
						EXTERIOR:CHIMNEY EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR WALLS		
				DSF	-0000799850	State of Good Repair - System Replacements - Heating	2016	132,895
						Plant Upgrade		
			X081	DSF	F0000818178	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2017	982,859

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
				DS	F0000818184	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
			Vood	DO	50000704000	Fluorescent	0017	4 0 4 0 0 0 5
			X081	DS	F0000794989	State of Good Repair - System Replacements - Windows	2017	1,349,235
							P.S. 81 Total:	\$6,943,942
10	Bronx	X085		P.S. 85				
			X085	DS	F0000821925	Safety and Security - Safety and Security - Safety Systems	2018	969,548
			X085	DS	F0000801045	State of Good Repair - Building Upgrade - Air Conditioning Retrofit	2015	97,162
			X085	DS	F0000795066	State of Good Repair - Building Upgrade - Flood Elimination	2018	1,800,943
				DS	F0000799660	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	150,427
			X085	DS	F0000795070	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2018	3,134,861
				DS	F0000795069	State of Good Repair - System Replacements - Parapets	2018	7,995,161

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
			X085	DS	F0000795068	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	2,343,557
			X085	DS	F0000818268	State of Good Repair - System Replacements - Toilets-Students	2015	399,882
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 85 Total:	\$16,891,541
10	Bronx	X086		P.S. 86				
					F0000795087	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	441,866
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000818289	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	262,687
							P.S. 86 Total:	\$704,553
40	D	V/004		D O O O				

10 Bronx X091 **P.S. 91**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799662	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	153,431
			X091	DS	F0000845577	State of Good Repair - System Replacements - Floors INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2018	195,042
				DS	F0000818388	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351
						Other		
			X091	DS	F0000843789	Classroom Connectivity	2016	265,307
							P.S. 91 Total:	\$715,131
10	Bronx	X094		P.S. 94				
				DS	F0000818448	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						Other		
			X094	DS	F0000800228	Classroom Connectivity	2015	217,235
							P.S. 94 Total:	\$318,586
10	Bronx	X095		P.S. 95				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000795268	State of Good Repair - System Replacements - Exterior Masonry	2015	3,934,165
_				DS	F0000795267	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,622,776
							P.S. 95 Total:	\$6,556,941
10	Bronx	X115		I.S. 399 (OLD X HS/115)			
				DS	F0000821893	Educational Enhancements - Educational Enhancements - Accessibility	2019	999,739
				DS	F0000799666	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	196,575
			X459	DS	F0000795617	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs INTERIOR:STRUCTURAL:FLOOR STRUCTURE	2019	939,716
			X363	DS	F0000799804	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			X459	DS	F0000821891	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2019	137,791
						I.S. 399 (OL	D X HS/115) Total:	\$2,309,084
10	Bronx	X118		I.S. 118				
			X118	DS	F0000845629	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 118 Total:	\$2,300,000
10	Bronx	X122		P.S. 310				
				DSF	0000799667	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	124,814
						Other		
			X310	DSF	0000800190	New/Retrofit Telephone/Intercom Systems	2015	199,905
			X310	DSF	0000776086	IP Surveillance Camera Installation	2015	601,159
							P.S. 310 Total:	\$925,878
10	Bronx	X137		I.S. 391 (U	DC)			
			X225	DSF	0000823611	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,877,202
				DSF	0000798464	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	545,288
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 391 (UDC) Total:	\$3,422,490
10	Bronx	X141		M.S./H.S. 1	141			
						Other		
			X141	DSF	0000800241	Classroom Connectivity	2015	192,350

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							M.S./H.S. 141 Total:	\$192,350
10	Bronx	X143		I.S. 143				
				DS	F0000798326	State of Good Repair - Building Upgrade - Boiler Conversion	2017	8,300,361
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000798327	State of Good Repair - Building Upgrade - Climate Control	2017	2,166,677
						CLIMATE CONTROL SYSTEM		
				DS	F0000819265	State of Good Repair - Building Upgrade - Flood Elimination	2016	141,747
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	F0000799668	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	140,716
			X143	DS	F0000821809	State of Good Repair - System Replacements - Exterior Masonry	2016	1,988,589
				DSI	F0000796075	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	844,890
				DSI	F0000819267	State of Good Repair - System Replacements - Roofs EXTERIOR:PLAZA DECK EXTERIOR:ROOFING:Roofing	2016	3,259,915

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000819273	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Toilet		
						Other		
			X237	DS	F0000800242	Classroom Connectivity	2015	276,952
							I.S. 143 Total:	\$17,371,198
10	Bronx	X205		P.S. 205A	(ECF)			
			X205	DSI	F0000798399	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,667,715
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			X205	DS	F0000796778	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
						Other		
			X205	DSI	F0000800252	Classroom Connectivity	2015	417,998
							P.S. 205A (ECF) Total:	\$6,410,335
10	Bronx	X206		I.S. 206B				
				DS	F0000798498	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798499	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
			X206	DS	F0000796800	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	50,777
			X206	DS	F0000819982	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
							I.S. 206B Total:	\$6,079,155
10	Bronx	X254		I.S. 254				
				DS	F0000822210	State of Good Repair - System Replacements - Exterior Masonry	2017	2,441,805
				DS	F0000821031	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2017	2,199,423
							I.S. 254 Total:	\$4,641,228
10	Bronx	X306		P.S. 306				
				DS	F0000799857	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
							P.S. 306 Total:	\$61,958
10	Bronx	X340		P.S. 340				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			X340	DS	F0000843790	Classroom Connectivity	2016	326,486
						<u>.</u>	P.S. 340 Total:	\$326,486
10	Bronx	X360		P.S. 360				
				DS	F0000799535	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	2,522,747
						VENTILATION: HEATING AND VENTILATING UNIT		
				DS	F0000775094	State of Good Repair - System Replacements - Roofs	2015	1,447,990
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						Other		
			X360	DS	F0000800253	Classroom Connectivity	2015	332,733
							P.S. 360 Total:	\$4,303,470
10	Bronx	X368		M.S./H.S.	368			
			X368	DS	F0000799913	State of Good Repair - System Replacements - Paved Area-Concrete	2015	712,618
						Other		
			X368	DS	F0000776088	IP Surveillance Camera Installation	2015	517,491
							M.S./H.S. 368 Total:	\$1,230,109
10	Bronx	X781		P.S. 51				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798134	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Floor Finish	2015	804,066
						Other		
			X051	DS	F0000800260	Classroom Connectivity	2015	545,671
							P.S. 51 Total:	\$1,349,737
10	Bronx	X819		P.S. 207				
						Other		
			X207	DS	F0000800263	Classroom Connectivity	2015	503,443
							P.S. 207 Total:	\$503,443
10	Bronx	X826		P.S. 226 M	MINISCHOOL			
				DS	F0000821732	State of Good Repair - Building Upgrade - Flood Elimination	2016	338,091
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			X226	DS	F0000821731	State of Good Repair - System Replacements - Exterior Masonry	2016	1,699,824
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000821733	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	1,756,059
						P.S. 226 N	IINISCHOOL Total:	\$3,793,974
10	Bronx	X843		P.S. 246 (POE CENTER)			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000751712	State of Good Repair - Building Upgrade - Elevators and Escalators	2017	2,531,474
						CONVEYING: ELEVATORS		
			X246	DS	F0000797406	State of Good Repair - Building Upgrade - Flood Elimination	2017	2,166,922
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				SC	A0000025015	State of Good Repair - System Replacements - Exterior Masonry	2017	4,267,514
			X246	DS	F0000797408	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	3,811,541
			X246	DS	F0000797414	State of Good Repair - System Replacements - Paved Area-Concrete	2017	512,716
			X246	DS	F0000797407	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,471,256
						Other		
			X246	DS	F0000800265	Classroom Connectivity	2015	53,828
						P.S. 246 (PO	E CENTER) Total:	\$14,815,251
10	Bronx	X852			OANCE ACADE	МҮ		
						Other		
			X308	DS	F0000800201	New/Retrofit Telephone/Intercom Systems	2015	110,599

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						BRONX	DANCE ACADEMY Total:	\$110,599
10	Bronx	X886		P.S. 86 AM	NNEX			
						Other		
			X307	DSF	-0000800202	New/Retrofit Telephone/Intercom Systems	2015	182,846
			X307	DSF	-0000822057	New/Retrofit Telephone/Intercom Systems	2015	182,846
							P.S. 86 ANNEX Total:	\$365,692
10	Bronx	X896		P.S. 279 A	NNEX			
						Other		
			X279	DSF	-0000800266	Classroom Connectivity	2015	7,332
							P.S. 279 ANNEX Total:	\$7,332
11	Bronx	X016		P.S. 16				
				DSF	-0000748202	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,340,029
				DSF	-0000799650	State of Good Repair - Building Upgrade - Lighting	2015	51,407
				DSF	-0000771141	State of Good Repair - System Replacements - Pave Area-Concrete	d 2015	1,448,404
				DSF	-0000817040	SITE:RETAINING WALLS State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	197,169

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X016	DS	SF0000822110	State of Good Repair - System Replacements -	2016	251,951
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			X016	DS	SF0000800173	New/Retrofit Telephone/Intercom Systems	2015	138,817
							P.S. 16 Total:	\$5,427,777
11	Bronx	X019		P.S. 19				
				DS	SF0000793888	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	491,288
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 19 Total:	\$491,288
11	Bronx	X021		P.S. 21				
			X021	DS	SF0000798409	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			X021	DS	SF0000793926	State of Good Repair - Building Upgrade - Climate Control	2018	1,277,027

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
			X021	DS	F0000793930	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			X021	DS	F0000776079	IP Surveillance Camera Installation	2015	481,224
							P.S. 21 Total:	\$6,293,514
11	Bronx	X041		P.S. 41				
			X041	DS	F0000752360	State of Good Repair - Building Upgrade - Boiler Conversion	2017	3,430,683
			X041	DS	F0000752361	State of Good Repair - Building Upgrade - Climate Control	2017	941,244
				DS	F0000799719	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	138,406
			X041	DS	F0000794242	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
						Other		
			X041	DS	F0000800211	Classroom Connectivity	2015	20,667
							P.S. 41 Total:	\$4,566,239
11	Bronx	X068		P.S. 68				
			X068	DS	F0000798401	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,667,715

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
			X068	DS	F0000798404	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
				DS	F0000749082	State of Good Repair - System Replacements - Auditorium Upgrade AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent	2015	1,283,630
						AUDITORIUM:LOCAL SOUND SYSTEM AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Sliding-folding Partition		
			X068	DS	F0000799354	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	393,894
				DS	F0000799847	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
							P.S. 68 Total:	\$7,731,819
11	Bronx	X076		P.S. 76				
			X076	DS	F0000865748	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 76 Total:	\$250,000
11	Bronx	X078		P.S. 78				
			X078	DSF	0000840069	Exterior Masonry	2019	793,966
				DSF	0000818129	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
			X078	DSF	0000865749	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 78 Total:	\$1,145,317
11	Bronx	X083		P.S. 83				
				DSF	0000795028	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,061,877
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000821947	State of Good Repair - System Replacements - Domestic Piping	2016	44,100
			X083	DSF	0000818226	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366

District	Borough	Building ID	Org ID School	Project #	Description	FY - Construction Start	Total
			DSF	-0000822665	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
						P.S. 83 Total:	\$1,507,114
11	Bronx	X087	P.S. 87				
			DSF	-0000795109	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	451,114
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			DSF	-0000818311	State of Good Repair - System Replacements - Toilets-Students	2015	754,054
					FIXTURES:STUDENT:Toilet		
						P.S. 87 Total:	\$1,205,168
11	Bronx	X089	P.S. 89				
			DSF	-0000799352	State of Good Repair - Building Upgrade - Interior Spaces	2016	513,041
					INTERIOR:STAIRS/RAMPS: INTERIOR		
			DSF	-0000799661	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	130,209
			DSF	-0000818346	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X089	DS	F0000800224	Classroom Connectivity	2015	439,816
							P.S. 89 Total:	\$1,157,872
11	Bronx	X097		P.S. 97				
			X097	DS	F0000845630	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2019	500,000
			X097	DS	F0000865750	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 97 Total:	\$750,000
11	Bronx	X103		P.S. 103				
				DS	F0000799664	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	212,737
						Other		
			X103	DS	F0000800229	Classroom Connectivity	2015	381,373
							P.S. 103 Total:	\$594,110
11	Bronx	X105		P.S. 105				
			X105	DS	F0000795434	State of Good Repair - Building Upgrade - Flood Elimination	2018	4,376,858
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000798473	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	962,756
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X105	DS	SF0000818615	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	2,065,485
				DS	SF0000818620	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	459,351
						Other		
			X105	DS	SF0000800232	Classroom Connectivity	2015	427,295
							P.S. 105 Total:	\$8,291,745
11	Bronx	X108		P.S. 108				
			X108	DS	SF0000865751	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 108 Total:	\$250,000
11	Bronx	X111		P.S. 111				
			X111	DS	SF0000798407	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2018	4,500,000
			X111	DS	SF0000795535	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,277,027

X111 DSF0000795543 State of Good Repair - System Replacements - Heating Plant Upgrade 2015 35; Plant Upgrade 11 Bronx X112 P.S. 112 P.S. 111 Total: \$7,109; 11 Bronx X112 P.S. 112 2017 5,058; Conversion 11 Bronx X112 P.S. 112 2017 5,058; Conversion 11 Bronx X112 DSF0000798321 State of Good Repair - Building Upgrade - Boiler Conversion 2017 5,058; Conversion 11 Bronx X112 DSF0000795558 State of Good Repair - Building Upgrade - Boiler Conversion 2017 1,391; Control 11 DSF0000795558 State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM 2017 1,391; Control 11 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781; Fixtures 11 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2017 1,391; Control 12 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781; Fixtures 13 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1	District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
X111 DSF0000795543 State of Good Repair - System Replacements - Heating Plant Upgrade 2015 35. P.S. 111 Total: \$7,109,1 11 Bronx X112 P.S. 112 P.S. 111 Total: \$7,109,1 11 Bronx X112 P.S. 112 2017 5,058,1 12 DSF0000795583 State of Good Repair - Building Upgrade - Boiler Conversion 2017 5,058,1 11 DSF0000795588 State of Good Repair - Building Upgrade - Climate Control 2017 1,391,2 13 DSF0000795588 State of Good Repair - Building Upgrade - Lighting 2016 1,781,3 14 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781,3 15 CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent CLASSROOM/CORRIDOR/ADMINI					DS	F0000818720		2016	1,297,302
Plant Upgrade P.S. 111 Total: \$7,109, 11 Bronx X112 P.S. 112 DSF0000798321 State of Good Repair - Building Upgrade - Boiler Conversion 2017 5,058, HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM 2017 1,391, DSF0000795558 State of Good Repair - Building Upgrade - Climate 2017 1,391, CollMATE CONTROL SYSTEM DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781, Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent SPACE:Lighting:Lighting Fixture - Incandescent Other Other Other Other Other							CLASSROOM/CORRIDOR/ADMINISTRATIVE		
11 Bronx X112 P.S. 112 DSF0000798321 State of Good Repair - Building Upgrade - Boiler Conversion 2017 5,058,000 HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM 2017 1,391,000 DSF0000795558 State of Good Repair - Building Upgrade - Climate Control 2017 1,391,000 CLIMATE CONTROL SYSTEM DSF0000840692 State of Good Repair - Building Upgrade - Lighting Fixtures 2016 1,781,000 CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting Fixture - Incandescent SPACE:Lighting Fixture - Incandescent Uther				X111	DS	F0000795543		2015	35,239
DSF0000798321 State of Good Repair - Building Upgrade - Boiler 2017 5,058; Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM 2017 1,391,4 DSF0000795558 State of Good Repair - Building Upgrade - Climate 2017 1,391,4 CLIMATE CONTROL SYSTEM CLIMATE CONTROL SYSTEM 2016 1,781,4 DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781,4 Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent Other Other Other								P.S. 111 Total:	\$7,109,568
Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM 2017 DSF0000795558 State of Good Repair - Building Upgrade - Climate 2017 1,391, Control CLIMATE CONTROL SYSTEM 2016 1,781, DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781, Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent Other Other Other	11	Bronx	X112		P.S. 112				
DSF0000795558 State of Good Repair - Building Upgrade - Climate 2017 1,391, Control CLIMATE CONTROL SYSTEM DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781, Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent Other					DSI	F0000798321	Conversion HEATING PLANT:BOILER AUXILIARIES	2017	5,058,300
DSF0000840692 State of Good Repair - Building Upgrade - Lighting 2016 1,781,7 Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Incandescent Other					DSI	F0000795558	State of Good Repair - Building Upgrade - Climate Control	2017	1,391,492
					DSI	F0000840692	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,781,313
X112 DSF0000800233 Classroom Connectivity 2015 25,							Other		
				X112	DS	F0000800233	Classroom Connectivity	2015	25,623

P.S. 112 Total: \$8,256,728

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
11	Bronx	X113		I.S. 113				
			X272	DS	F0000822687	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,030,245
				DS	F0000798439	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,568,232
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000821622	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DS	F0000818768	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	418,896
						Other		
			X272	DS	F0000800234	Classroom Connectivity	2015	481,584
							I.S. 113 Total:	\$6,032,193
11	Bronx	X121		P.S. 121				
				DS	F0000822226	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,047,145
			X121	DS	F0000795736	SPACE:LIGHTING:Lighting Fixture - Fluorescent State of Good Repair - System Replacements - Heating Plant Upgrade	2015	36,099

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000818925	State of Good Repair - System Replacements -	2017	159,628
						Toilets-Students		
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
						Fluorescent		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
							P.S. 121 Total:	\$1,242,872
11	Bronx	X127		I.S. 127				
				DSF	0000801085	Educational Enhancements - Educational Enhancements - Accessibility	2016	758,777
				DSF	0000822227	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	882,743
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	-0000799853	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	59,477
							I.S. 127 Total:	\$1,700,997
11	Bronx	X135		I.S. 135				
			X322	DSF	0000822206	State of Good Repair - Building Upgrade - Interior Spaces	2017	3,597,201

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X322	DS	F0000819133	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
			X322	DS	F0000795950	State of Good Repair - System Replacements - Toilets-Students	2015	212,775
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						INTERIOR. TOLET ROOMS - STODENTS	I.S. 135 Total:	\$3,965,342
11	Bronx	X142		I.S. 142				
			X529	DS	F0000799481	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	215,962
				DS	F0000752369	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	2,681,454
			X142	DS	F0000796055	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							I.S. 142 Total:	\$2,932,655
11	Bronx	X144		I.S. 144				
			X144	DS	F0000752363	State of Good Repair - Building Upgrade - Boiler Conversion	2016	5,080,678
			X144	DS	F0000752364	State of Good Repair - Building Upgrade - Climate Control	2016	1,925,175

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X144	DSF	-0000796098	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							I.S. 144 Total:	\$7,041,092
11	Bronx	X160		P.S. 160				
				DSF	-0000796397	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,635,009
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 160 Total:	\$1,635,009
11	Bronx	X175		P.S. 175				
				DSF	F0000798455	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	758,335
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			X175	DSF	-0000796587	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 175 Total:	\$793,574
11	Bronx	X178		P.S. 178		0 //		

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X176	DS	F0000776087	IP Surveillance Camera Installation	2015	763,885
							P.S. 178 Total:	\$763,885
11	Bronx	X181		I.S. 181				
						Other		
			X181	DS	F0000800250	Classroom Connectivity	2015	211,040
							I.S. 181 Total:	\$211,040
11	Bronx	X194		P.S./I.S. 1	194			
			X194	DS	F0000821907	State of Good Repair - System Replacements -	2015	75,222
						Gymnasium Upgrade		
						INTERIOR: GYMNASIUM: Floor Finish		
							P.S./I.S. 194 Total:	\$75,222
11	Bronx	X498		THE LT. (CURTIS MEYRA	N AND JOHN BELLEW EDUCATION COMPLEX		
						Other		
			X498	DS	F0000800258	Classroom Connectivity	2015	310,463
						THE LT. CURTIS MEYRAN AND JOHN BELLEW EDUCATI	ON COMPLEX Total:	\$310,463
12	Bronx	X044		P.S. 44				
				DS	F0000794304	State of Good Repair - System Replacements - Exterior Masonry	2019	5,298,396
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000817479	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING	2019	3,774,223

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
			X044	DS	F0000822073	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2019	1,705,024
						Other		
			X044	DS	F0000800179	New/Retrofit Telephone/Intercom Systems	2015	215,880
			X044	DS	F0000822050	New/Retrofit Telephone/Intercom Systems	2015	215,880
			X044	DS	F0000822161	IP Surveillance Camera Installation	2016	850,574
							P.S. 44 Total:	\$12,059,977
12	Bronx	X047		P.S. 47				
				DS	F0000771636	State of Good Repair - Building Upgrade - Flood Elimination	2015	2,790,644
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DS	F0000821596	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	571,907
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000771639	State of Good Repair - System Replacements - Exterior	2015	3,952,921
						Masonry		
						EXTERIOR:AREAWAY		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000817543	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DS	F0000771638	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	3,589,615
_				DS	F0000771637	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,920,733
							P.S. 47 Total:	\$12,900,626
12	Bronx	X050		P.S. 50				
						Other		
			X050	DS	F0000800180	New/Retrofit Telephone/Intercom Systems	2015	165,218
							P.S. 50 Total:	\$165,218
12	Bronx	X057		P.S. 57				
						Other		
			X057	DS	F0000800183	New/Retrofit Telephone/Intercom Systems	2015	214,220
			X057	DS	F0000822058	New/Retrofit Telephone/Intercom Systems	2015	214,220
							P.S. 57 Total:	\$428,440
12	Bronx	X061		P.S. 61				
				DS	F0000794603	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	869,446

)istrict Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						P.S. 61 Total:	\$869,446
12 Bronx	X066		P.S. 66				
			DSF	0000843909	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,300,935
						P.S. 66 Total:	\$2,300,935
12 Bronx	X067		P.S. 67				
		X372	DSF	0000777273	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	759,606
			DSF	0000794722	<i>State of Good Repair - System Replacements - Heating</i> <i>Plant Upgrade</i> Ventilation	2016	3,179,906
		X067	DSF	0000801053	<i>State of Good Repair - System Replacements - Heating</i> <i>Plant Upgrade</i> Ventilation	2016	1,330,075
					VENTILATION: UNIT VENTILATOR		
			DSF	0000817911	State of Good Repair - System Replacements - Toilets-Students	2015	634,426
					FIXTURES:STUDENT:Toilet		

P.S. 67 Total: \$5,904,013

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
12	Bronx	X077		P.S. 195				
				DSF	50000794912	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,167,857
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
				Der	-0000840063	SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	20.261
				DSr	-0000040003	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	39,261
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						Other		
			X195	DSF	0000800221	Classroom Connectivity	2015	492,037
							P.S. 195 Total:	\$1,699,155
12	Bronx	X092		P.S. 92				
				DSF	F0000772483	State of Good Repair - Building Upgrade - Flood Elimination	2015	942,491
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	-0000799721	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	133,628
				DSF	-0000772486	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY	2015	1,167,670

		Building					FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000799466	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,646,472
				DS	F0000772485	State of Good Repair - System Replacements - Roofs	2015	2,420,861
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
							P.S. 92 Total:	\$6,311,122
12	Bronx	X098		I.S. 98				
			X098	DS	F0000845628	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
				DS	F0000822666	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
				DS	F0000818505	State of Good Repair - System Replacements - Toilets-Students	2015	268,346
						FIXTURES:STUDENT:Toilet		
			X098	DS	F0000822113	State of Good Repair - System Replacements - Toilets-Students	2016	348,435
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
							IS 09 Total	¢2 162 552

I.S. 98 Total: \$3,162,552

12 Bronx X102 P.S. 102

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X531	DS	SF0000799480	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	149,594
				DS	SF0000795381	State of Good Repair - Building Upgrade - Flood Elimination	2019	3,498,130
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	SF0000799663	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	156,000
				DS	SF0000823585	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DS	SF0000844155	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,437,523
						Other		
			X102	DS	6F0000822071	New/Retrofit Telephone/Intercom Systems	2015	321,560
							P.S. 102 Total:	\$5,637,613
12	Bronx	X116		I.S. 216				
				DS	SF0000795636	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,729,083
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		

Other

		Building					FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
			X217	DS	F0000800235	Classroom Connectivity	2015	414,090
							I.S. 216 Total:	\$2,143,173
12	Bronx	X129		I.S. 129 (I	PAIRED W P234	•)		
				DS	F0000821626	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			X129	DS	F0000799854	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
						I.S. 129 (PAIR	ED W P234) Total:	\$568,475
12	Bronx	X134		P.S. 134				
			X134	DS	F0000819122	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation	2019	410,336
						MOTOR STARTER/CONTACTOR		
						VENTILATION: EXHAUST FAN		
						VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
						VENTILATION:UNIT VENTILATOR		
						Other		
			X134	DS	F0000800238	Classroom Connectivity	2015	417,834
							P.S. 134 Total:	\$828,170
12	Bronx	X150		P.S. 150				
			X150	DS	F0000796218	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	31,258

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			X150	DSI	F0000800243	Classroom Connectivity	2015	40,596
							P.S. 150 Total:	\$71,854
12	Bronx	X158		I.S. 158				
			X245	DSI	F0000775850	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,040,087
				DSI	F0000796373	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	2,101,647
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
				DSI	F0000823661	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 158 Total:	\$3,243,085
12	Bronx	X167		P.S. 214				÷,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
			X214	DSI	F0000821737	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	594,964

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X214	DS	F0000865722	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
				DS	F0000799722	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	197,559
				DS	F0000819688	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,628
						Other		
			X214	DS	F0000800249	Classroom Connectivity	2015	236,400
							P.S. 214 Total:	\$3,488,551
12	Bronx	X193		P.S. 211				
			X211	DS	F0000821774	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	65,931
			X318	DS	F0000821775	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	65,931
				DS	F0000799670	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	182,981

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 211 Total:	\$314,843
12	Bronx	X198		P.S. 198				
				DSF	-0000844050	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,956,019
				DSF	-0000796759	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2015	1,491,774
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			X212	DSF	-0000800196	New/Retrofit Telephone/Intercom Systems	2015	258,442
			X212	DSF	-0000800251	Classroom Connectivity	2015	417,998
			X212	DSF	-0000822043	New/Retrofit Telephone/Intercom Systems	2015	258,442
							P.S. 198 Total:	\$5,382,675
75X	Bronx	X012		P.S. 12				
			X012	DSF	-0000865747	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						Other		
			X012	DSF	-0000800172	New/Retrofit Telephone/Intercom Systems	2015	229,108
							P.S. 12 Total:	\$479,108
75X	Bronx	X084		P.S. 811 (OLD 184)			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000795047	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescel		2,137,603
			X811	DS	F0000818244	State of Good Repair - System Replacements - Exteri Masonry EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS		3,953,283
			X811	DS	F0000818243	State of Good Repair - System Replacements - Parap EXTERIOR:COPING EXTERIOR:PARAPETS	ets 2017	1,496,082
			X811	DS	F0000818242	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	4,406,337
			X811	DS	F0000823639	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2017	2,535,446
						F	P.S. 811 (OLD I84) Total:	\$14,528,751
75X	Bronx	X136			(OLD J136) F0000798387	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,513,010

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000795961	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
				DSI	F0000799880	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Flood Elimination	2016	692,852
					F0000705062	INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1 464 205
				DSI	F0000795963	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,464,295
				DSI	F0000799881	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	3,678,703
				SC	A0000026417	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	6,690,290
				DSI	F0000795966	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	4,117,925

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X186	DSI	F0000800239	Classroom Connectivity	2015	13,756
						P.S.	186 (OLD J136) Total:	\$22,398,694
75X	Bronx	X155		P.S. 754 (OLD IS155)			
				DSI	F0000796317	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,911,534
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000819523	State of Good Repair - System Replacements - Heating		155,366
				201	0000010020	Plant Upgrade	2010	100,000
						P.S.	754 (OLD IS155) Total:	\$2,066,900
75X	Bronx	X701		P.S. 723				
			X723	DSI	F0000845609	<i>State of Good Repair - System Replacements - Heating</i> <i>Plant Upgrade</i> Ventilation	2018	247,022
						Other		
			X723	DSI	F0000800259	Classroom Connectivity	2015	505,885
							P.S. 723 Total:	\$752,907
75X	Bronx	X722		P.S. 721 (ОТС)			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000798330	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,450,270
				DSI	-0000797329	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,372,007
				DSI	-0000775994	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	131,603
				DSI	-0000797331	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,206,414
				DSI	-0000775579	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2019	5,025,402
				DSI	-0000776000	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2019	96,975
				DSF	-0000775993	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2019	311,309

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000775995	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2019	717,495
							P.S. 721 (OTC) Total:	\$14,311,475
75X	Bronx	X817		P.S. 811 A	ANNEX			
				DSI	F0000797359	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	310,611
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 811 ANNEX Total:	\$310,611
78X	Bronx	X039		NEW SCH	FOR ARTS AN	ID SCIENCE		
			X332	DSI	F0000798348	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685
			X332	DSI	F0000798350	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762
			X332	DSI	F0000797758	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DSI	F0000820997	State of Good Repair - System Replacements - Toilets-Students	2017	478,885

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						NEW SCH FOR ARTS	AND SCIENCE Total:	\$6,502,571
78X	Bronx	X211		P.U.L.S.E.	HS			
				DSF	0000844097	Domestic Piping	2017	1,132,500
						DOMESTIC WATER SYSTEM		
						FIXTURES:Student:Drinking Fountain		
						FIXTURES:Student:Sink And Fountain Combo Unit		
							P.U.L.S.E. HS Total:	\$1,132,500
78X	Bronx	X362		I.S./H.S. 36	2			
				DSF	0000844729	Educational Enhancements - Educational Enhancements - Accessibility	2018	76,669
						Other		
			X270	DSF	0000800254	Classroom Connectivity	2015	150,670
							I.S./H.S. 362 Total:	\$227,339
78X	Bronx	X392		THE CASIT	A MARIA CEI	NTER FOR ARTS AND EDUCATION		
			X186	DSF	0000844108	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	211,965
						THE CASITA MARIA CENTER FOR ARTS AN	D EDUCATION Total:	\$211,965
78X	Bronx	X400		MORRIS H	S			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000796884	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	60,963
				DSF	-0000799672	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	219,147
				DSF	-0000799858	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,957
				DSF	-0000823662	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			X297	DSF	-0000800255	Classroom Connectivity	2015	256,082
							MORRIS HS Total:	\$699,500
78X	Bronx	X401		BRONX R	EGIONAL HS (OLD 133)		
			X480	DSF	-0000820092	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						BRONX REGIONAL	HS (OLD 133) Total:	\$251 351

BRONX REGIONAL HS (OLD 133) Total: \$251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
	Bronx	X405		HERBER	T H. LEHMAN H	IS		
			X349	DS	F0000823642	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	608,787
				DS	F0000843692	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	692,008
			X405	DS	F0000775949	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2015	5,227,447
				DS	F0000796932	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	3,892,957
				DS	F0000796936	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	12,826,544
				DS	F0000751280	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling	2019	3,358,490
				DS	F0000799673	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	287,934
				DS	F0000796955	State of Good Repair - System Replacements - Domestic Piping	2015	643,112

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
				DSF	0000796941	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	2015	2,937,338
				DSF	0000796942	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	18,081,834
				DSF	0000842055	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	484,569

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799437	State of Good Repair - System Replacements - I Area-Blacktop	Paved 2015	375,561
						SITE:Drainage System for Asphalt SITE:PAVING - STUDENT USE:Asphalt		
				DS	F0000820117	State of Good Repair - System Replacements - Toilets-Students	2017	638,514
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting	ı Fixture -	
						Fluorescent	,	
						TOILET ROOM - STUDENT:Lighting:Lighting) Fixture -	
						Incandescent HE	RBERT H. LEHMAN HS Total:	\$50,055,095
78X	Bronx	X410		WILLIAM	H. TAFT HS			
				DS	F0000820137	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink	2017	319,257
						Other		
				DS	F0000843855	IP Surveillance Camera Installation	2017	476,465
							WILLIAM H. TAFT HS Total:	\$795,722
78X	Bronx	X415		CHRISTO		BUS HS		
				DS	F0000821601	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000796987	State of Good Repair - System Replacements - Exterior Masonry	2016	1,541,117
						EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS		
				DS	F0000755238	State of Good Repair - System Replacements - Parapets	2016	4,343,932
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				DS	F0000796984	State of Good Repair - System Replacements - Roofs	2016	1,473,256
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
				DS	F0000820161	State of Good Repair - System Replacements - Toilets-Students	2016	202,702
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
						Other		
			X415	DS	F0000800197	New/Retrofit Telephone/Intercom Systems	2015	815,542
				DS	F0000843856	IP Surveillance Camera Installation	2017	476,465
						CHRISTOPHER COL	UMBUS HS Total:	\$9,386,250
78X	Bronx	X420		JAMES M	ONROE CAMP	US		
				DS	F0000820176	State of Good Repair - Building Upgrade - Climate Control	2017	1,832,969

District	Borough	Building ID	Org ID	School Projec	# Description	FY - Construction Start	Total
					CLIMATE CONTROL SYSTEM		
				DSF00008221	State of Good Repair - Building Upgrade - Flood Elimination	2017	381,467
					DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
				DSF00007996	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	238,607
			X388	DSF00008201	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
					CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent INTERIOR:CAFETERIA:Floor Finish		
				DSF00008221	2 State of Good Repair - System Replacements - Heating Plant Upgrade	2017	8,678,913
					JAMES MONRO	DE CAMPUS Total:	\$11,665,192
78X	Bronx	X423		JAMES MONROE H	CAMPUS ANNEX		
					Other		
			X242	DSF00008002	Classroom Connectivity	2015	453,710
					JAMES MONROE HS CAM	PUS ANNEX Total:	\$453,710
78X	Bronx	X425		EVANDER CHILDS	i		
				DSF00007997	5 State of Good Repair - Building Upgrade - Lighting Fixtures	2015	112,899
				DSF00008202	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	260,353

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	F0000820215	HEATING PLANT:BOILER SYSTEM State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2018	249,166
			X253	DSF	F0000799993	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	160,553
			X253	DSF	0000865752	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
				DSF	-0000843857	<i>Other</i> IP Surveillance Camera Installation	2017	527,479
					0000040007		ER CHILDS HS Total:	\$1,560,450
78X	Bronx	X430		WALTON	HS			
						Other		
				DSF	0000843858	IP Surveillance Camera Installation	2017	476,465
							WALTON HS Total:	\$476,465
78X	Bronx	X435		THEODOF	RE ROOSEVEL	T EDUCATIONAL CAMPUS		
				DSF	0000821661	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	534,853

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798443	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	936,962
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000775991	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	32,664,769
				DS	F0000774340	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	15,255,435
				DS	F0000774339	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	8,346,872
			X437	DS	F0000820249	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351
				DS	F0000774341	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2015	8,995,386
						Other		
			X434	DS	F0000843859	IP Surveillance Camera Installation	2018	527,479

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						THEODORE ROOSEVELT EDUCATIONA	L CAMPUS Total:	\$67,513,107
78X	Bronx	X440		DEWITT C	LINTON HS			
			X440	DSF	0000799362	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	704,588
			X440	DSF	0000774374	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Gymnasium Upgrade GYMNASIUM:LIGHTING:Lighting Fixture - Fluorescent GYMNASIUM:SCOREBOARD INTERIOR:GYMNASIUM:Floor Finish INTERIOR:GYMNASIUM:Seating INTERIOR:LOCKER ROOM	2015	4,324,214
			X440	DSF	0000777278	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Electrical Systems PANEL BOARD	2016	4,462,026
			X440	DSF	0000777280	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2016	2,611,467

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X440	DS	F0000777281	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,310,813
			X351	DS	F0000798356	SPACE:LIGHTING:Lighting Fixture - Fluorescent State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2018	4,664,685
			X351	DS	F0000797097	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762
				DS	F0000797100	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	2,180,431
				DS	F0000821605	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DS	F0000754569	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	12,471,574
				DS	F0000798647	<i>State of Good Repair - System Replacements - Parapets</i> EXTERIOR:COPING EXTERIOR:PARAPETS	2017	15,110,884

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X440	DS	F0000821913	State of Good Repair - System Replacements - Ro	ofs 2017	4,479,147
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
				DS	F0000820271	State of Good Repair - System Replacements -	2016	101,351
						Toilets-Students		
						FIXTURES:Student:Lavatory/Sink		
						Other		
			X351	DS	F0000800198	New/Retrofit Telephone/Intercom Systems	2015	714,146
			X351	DS	F0000800257	Classroom Connectivity	2015	556,133
						D	EWITT CLINTON HS Total:	\$55,548,457
78X	Bronx	X445		BRONX H	IS OF SCIENCE			
			X445	DS	F0000799896	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,980,710
			X445	DS	F0000844088	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,145,000
				DS	F0000797127	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	116,216
				DS	F0000799723	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	500,470
			X445	DS	F0000820296	State of Good Repair - System Replacements - Hea Plant Upgrade	ating 2018	155,366
			X445	DS	F0000822171	State of Good Repair - System Replacements - Par EXTERIOR:PARAPETS	rapets 2017	3,383,540

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X445	DS	F0000820291	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	7,909,223
						BRONX HS O	SCIENCE Total:	\$15,190,525
78X	Bronx	X450		ADLAI E.	STEVENSON E	DUCATIONAL CAMPUS		
				DS	F0000821580	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	1,440,113
				DS	F0000799901	Safety and Security - Safety and Security - Safety Systems	2015	1,248,314
				DS	F0000799676	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	339,469
				DS	F0000797153	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2015	624,203
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		
						INTERIOR:STRUCTURAL:ROOF STRUCTURE		
			X295	DS	F0000797155	State of Good Repair - System Replacements - Exterior Masonry	2015	1,273,524
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000774426	State of Good Repair - System Replacements -	2015	4,131,241
						Gymnasium Upgrade		
						INTERIOR:GYMNASIUM:Door(s) INTERIOR:GYMNASIUM:Floor Finish		
						INTERIOR:GYMNASIUM:Floor Finish		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:GYMNASIUM:Walls		
				DS	F0000774413	State of Good Repair - System Replacements - Roof	s 2015	10,990,501
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
				DS	F0000820322	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixt	ure -	
						Fluorescent		
						Other		
				DS	F0000843860	IP Surveillance Camera Installation	2017	561,148
				DS	F0000774423	Ansul Systems	2015	649,951
						ADLAI E. STEVENSON EDUC	ATIONAL CAMPUS Total:	\$21,418,092
78X	Bronx	X451		STEVENS	SON HS AF			
			X321	DS	F0000842251	State of Good Repair - Rehabilitation of Physical	2018	217,664
						Education Facilities - Athletic Fields		
						s	TEVENSON HS AF Total:	\$217,664
78X	Bronx	X455		HARRY S	. TRUMAN HS			
				DS	F0000777424	Educational Enhancements - Educational	2015	489,679
						Enhancements - Science Lab Upgrades		
				DS	F0000820334	State of Good Repair - Building Upgrade - Lighting	2016	1,056,547
						Fixtures		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000842273	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	992,272
				DS	F0000820343	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink	2016	202,702
						HARRY S. 1	RUMAN HS Total:	\$2,741,200
78X	Bronx	X460		HS OF LA	W, GOV'T & JL	JSTICE		
				DS	F0000844732	Educational Enhancements - Educational Enhancements - Accessibility	2018	123,062
						HS OF LAW, GOV'T	& JUSTICE Total:	\$123,062
78X	Bronx	X470		SOUTH B		FIONAL CAMPUS (OLD 38)		
				DS	F0000799677	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	221,874
			X473	DS	F0000801047	State of Good Repair - System Replacements - Heating Plant Upgrade	2019	44,432
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT GAS SERVICE:GAS PRESSURE BOOSTER HEATING		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000820364	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351
						SOUTH BRONX EDUCATIONAL CAMPU	S (OLD 38) Total:	\$367,657
78X	Bronx	X471			RONX HS AF =0000820378	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELD:EXTERIOR LIGHTING ATHLETIC FIELD:LOCAL SOUND SYSTEM ATHLETIC FIELD:SCOREBOARD CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:PARAPETS EXTERIOR:STAIRS/RAMPS: EXTERIOR GROUNDING SYSTEM INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS INTERIOR:STRUCTURAL:FLOOR STRUCTURE INTERIOR:STRUCTURAL:ROOF STRUCTURE	2019	11,276,916

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SITE:RETAINING WALLS		
							SOUTH BRONX HS AF Total:	\$11,276,916
78X	Bronx	X475		JOHN F. K	ENNEDY HS			
			X213	DSF	0000821771	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	78,520
			X213	DSF	0000821772	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	78,520
			X546	DSF	0000821773	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	39,865
			X213	DSF	0000843886	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	249,672
			X284	DSF	0000843887	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	41,500

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X397	DS	F0000843888	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	217,914
			X546	DS	F0000843889	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	41,500
			X284	DS	F0000843921	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	216,864
			X477	DS	F0000843922	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	195,996
			X546	DS	F0000843924	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	195,996
			X475	DS	F0000823597	Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2016	4,513,750

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DS	F0000823598	Science Lab Upgrades SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent	2016	3,487,339
			X477	DS	F0000823599	Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2016	6,761,866
			X475	DS	F0000820383	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2019	877,135
				DS	F0000797223	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	117,195
				DS	F0000820380	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,312,909

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X475	DS	F0000799534	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,245,026
				DS	F0000774499	State of Good Repair - System Replacements - Auditorium Upgrade AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging	2016	2,295,407
			X475	DS	F0000797229	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2016	2,791,612
				DS	F0000799859	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
				DS	F0000820386	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2019	2,296,942
			X475	DS	F0000820385	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2019	4,066,391
			X475	DS	F0000820391	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
				DS	F0000777221	System Expansion - New Physical Education Facil Playgrounds	ities - 2016	983,076
						Other		
				DS	F0000800298	IP Surveillance Camera Installation	2015	1,134,816
						JO	HN F. KENNEDY HS Total:	\$33,570,468
78X	Bronx	X476		KENNED	Y HS AF			
			X475	DS	F0000843758	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2016	463,513
							KENNEDY HS AF Total:	\$463,513
78X	Bronx	X600		ALFRED	E. SMITH HS			
			X600	DS	F0000775834	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2019	5,559,317
				DS	F0000799356	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2019	3,125,686
				DS	F0000821609	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X381	DSI	F0000797255	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	56,739
				DSI	F0000799860	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,957
				DSI	F0000820412	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						ALFRED E	SMITH HS Total:	\$9,438,286
78X	Bronx	X650		JANE ADI	DAMS HS			
				DSI	F0000797270	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	535,138
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000820436	State of Good Repair - System Replacements - Auditorium Upgrade	2016	55,581
						INTERIOR: AUDITORIUM: Stage: Stage Curtain Rigging INTERIOR: AUDITORIUM: Stage: Stage Curtains		
						Other		
			X650	DSI	F0000800199	New/Retrofit Telephone/Intercom Systems	2015	287,649
							DDAMS HS Total	\$878,368

JANE ADDAMS HS Total: \$878,368

FY -

						FT -	
	Building					Construction	
Borough	ID	Org ID	School	Project #	Description	Start	Tota
Bronx	X655		SAMUEL	GOMPERS VO	C HS		
		X557	DSF	F0000843925	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
			DSF	-0000798448	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,391,640
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
					Other		
		X208	DSF	-0000800200	New/Retrofit Telephone/Intercom Systems	2015	478,772
		X557	DSF	-0000822041	New/Retrofit Telephone/Intercom Systems	2015	478,772
					SAMUEL GON	IPERS VOC HS Total:	\$2,457,616
Bronx	X660		GRACE H	. DODGE VOC	нѕ		
		X660	DSF	-0000754499	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	3,111,972
			DSF	-0000799678	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	179,762
					GRACE H. D	ODGE VOC HS Total:	\$3,291,734
Bronx	X790		МОТТ НА		ONAL CAMPUS		
_	Bronx	BoroughIDBronxX655SronxX660	BoroughIDOrg IDBronxX655X557X557X557X557StronxX660X208X660X660X660	BoroughIDOrg IDSchoolBronxX655SAMUEL (X557DSFDSFX557DSFDSFX208DSFBronxX660GRACE H X660DSFDSFDSFDSFBronxX660DSF	BoroughIDOrg IDSchoolProject #BronxX655SAMUEL GOMPERS VO X557DSF0000843925DSF0000798448DSF0000798448DSF0000798448DSF0000800200 X557DSF0000800200 DSF0000822041BronxX660GRACE H. DODGE VOC DSF0000754499 DSF0000799678	Borough ID Org ID School Project # Description Bronx X655 SAMUEL GOMPERS VOC HS Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology Bronx X557 DSF0000843925 Educational Enhancements - School Improvement and Restructuring Technology DSF0000798448 State of Good Repair - Building Upgrade - Lighting Fixture - SPACE: LIGHTING: Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE: LIGHTING: Lighting Fixture - Incandescent X208 DSF0000800200 New/Retrofit Telephone/Intercom Systems Bronx X660 GRACE H. DODGE VOC HS X660 DSF0000754499 Educational Enhancements - Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning Bronx X660 DSF0000799678 State of Good Repair - Building Upgrade - Lighting Fixtures	Building Org ID Org ID Org ID Project # Description Construction Start Bronx X655 SAWUEL GOMPERS VOU X557 DSF0000843925 Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology Technology 2016 Bronx SA SAUVEL GOMPERS VOU VENDOUS State of Good Repair - Building Upgrade - Lighting Fixtures 2016 CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent SAUUEL GOMPERS - 2015 Tota X208 DSF0000802001 New/Retrofit Telephone/Intercom Systems 2015 2015 Bronx X660 DSF0000754499 Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning 2015 Brony X660 DSF0000754499 Educational Enhancements - Educational Enhancements - Room Conversions

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			X188	DSI	F0000821767	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	48,201
			X548	DSI	F0000821768	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	39,865
			X188	DSI	F0000865753	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	45,000
			X547	DSI	F0000865754	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	45,000
			X548	DSI	F0000865755	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	45,000
						Other		
			X527	DSI	F0000800261	Classroom Connectivity	2015	208,145
				DSI	F0000800102	IP Surveillance Camera Installation	2015	342,437

MOTT HAVEN EDUCATIONAL CAMPUS Total: \$773,648

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78X	Bronx	X839		BRONX H	IS FOR THE VIS	SUAL ARTS		
				DSI	F0000799486	Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	792,323
				DSI	F0000731467	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,883,633
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						BRONX HS FOR THE	VISUAL ARTS Total:	\$4,675,956
78X	Bronx	X876		BRONX L	EADERSHIP A	CADEMY		
						Other		
			X525	DSI	F0000843791	Classroom Connectivity	2016	243,341
						BRONX LEADERS	HIP ACADEMY Total:	\$243,341
78X	Bronx	X963		CROTON	A ACADEMY T	RANSPORTABLE		
			X321	DSI	F0000821659	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2018	4,125,209
						CROTONA ACADEMY TRA	NSPORTABLE Total:	\$4,125,209
78X	Bronx	X972		SOUNDVI	EW EDUCATIO	DNAL CAMPUS		
						Other		
			X519	DSI	F0000800203	New/Retrofit Telephone/Intercom Systems	2015	268,989
			X519	DSI	F0000822042	New/Retrofit Telephone/Intercom Systems	2015	268,989
						SOUNDVIEW EDUCATIO	NAL CAMPUS Total:	\$537,978

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
13	Brooklyn	K003		P.S. 3				
				DSI	F0000798244	State of Good Repair - Building Upgrade - Boiler Conversion	2016	5,702,850
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000798245	State of Good Repair - Building Upgrade - Climate Control	2016	1,710,912
						CLIMATE CONTROL SYSTEM		
				DSI	F0000755394	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,031,668
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000755393	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	2,078,779
				DSI	F0000801203	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2016	251,351
							P.S. 3 Total:	\$10,775,560
13	Brooklyn	K008		P.S. 8				
	-			DSI	F0000777455	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	64,074

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798390	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	473,782
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 8 Total:	\$537,856
13	Brooklyn	K009		P.S. 9				
			K009	DS	F0000777927	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
			K009	DS	F0000777935	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			K009	DS	F0000865730	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 9 Total:	\$1,609,885
13	Brooklyn	K011		P.S. 11				
				DS	F0000799680	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	227,256
							P.S. 11 Total:	\$227,256
13	Brooklyn	K020		P.S. 20				
	-		K020	DS	F0000824038	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	52,777

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
						HEATING:Heating Coil In Ductwork		
						HEATING:Radiator/Convector/Fin Tube		
						HEATING:Steam Heating		
				_		HEATING:Unit Heater/Cabinet Heater		
			K020	D	SF0000822131	State of Good Repair - System Replacements -	2016	251,351
						Toilets-Students		
							P.S. 20 Total:	\$304,128
13	Brooklyn	K044		P.S. 44				
				D	SF0000710245	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,221,655
						HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System		
				D	SF0000710254	State of Good Repair - Building Upgrade - Climate Control	2017	1,859,418
						CLIMATE CONTROL SYSTEM		
				D	SF0000756027	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,107,769
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K044	D	SF0000801839	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2017	701,631

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						AUXILIARY SIGNAL/BELL SYSTEM		
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		
						SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY		
							P.S. 44 Total:	\$8,890,473
13	Brooklyn	K046		P.S. 46				
			K046	DSF	0000821818	Educational Enhancements - Educational	2017	984,946
						Enhancements - School Improvement and		
						Restructuring		
						Auditorium Upgrade		
						INTERIOR:AUDITORIUM:Stage:Stage		
						INTERIOR: AUDITORIUM: Stage: Stage Curtains		
							P.S. 46 Total:	\$984,946
13	Brooklyn	K054		P.S. 54				
			K054	DSF	0000824489	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	84,844
							P.S. 54 Total:	\$84,844
13	Brooklyn	K056		P.S. 56				
				DSF	0000799685	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	251,424
							P.S. 56 Total:	\$251,424
13	Brooklyn	K067		P.S. 67				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000799686	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	317,015
			K067	DSI	-0000778830	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSI	-0000802160	State of Good Repair - System Replacements - Toilets-Students	2016	202,702
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Incandescent		
						manuescent	P.S. 67 Total:	\$554,980
13	Brooklyn	K093		P.S. 93				
				DSI	-0000799687	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	139,193
			K093	DSI	-0000779133	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 93 Total:	\$174,432
13	Brooklyn	K113		I.S. 113				
				DSI	-0000821885	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	54,859

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
			K113	D	SF0000779463	State of Good Repair - System Replacements -	2016	203,305
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							I.S. 113 Total:	\$258,164
13 E	Brooklyn	K117		I.S. 117				
			K412	D	SF0000777712	Educational Enhancements - Educational	2015	688,237
						Enhancements - Room Conversions/Partitioning		
				D	SF0000802874	State of Good Repair - System Replacements -	2019	533,236
						Cafeteria / Multipurpose Room Upgrade		
						CAFETERIA:LOCAL SOUND SYSTEM		
						INTERIOR:CAFETERIA:Floor Finish		
				D	SF0000757040	State of Good Repair - System Replacements - Exterior Masonry	2016	5,999,378
						EXTERIOR:EXTERIOR WALLS		
				D	SF0000779533	State of Good Repair - System Replacements - Parapets	2016	2,325,193
						EXTERIOR:COPING		,,
						EXTERIOR:PARAPETS		
				D	SF0000779532	State of Good Repair - System Replacements - Roofs	2016	5,188,674
						EXTERIOR:ROOFING:Roofing		
							I.S. 117 Total:	\$14,734,718

13 Brooklyn K258 I.S. 258

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K140	DSF	F0000843992	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	204,500
				DSF	-0000781892	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,277,027
			K140	DSF	-0000827557	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2019	1,352,413
				DSF	-0000781910	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	146,111
						VENTILATION: EXHAUST FAN		
							I.S. 258 Total:	\$2,980,051
13	Brooklyn	K265		I.S. 265				
			K265	DSF	-0000775954	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	861,997
			K265	DSF	-0000775955	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	732,192
			K265	DSF	-0000799495	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	776,041

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K265	DS	F0000843906	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	98,500
				DS	F0000798255	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	4,919,141
				DS	F0000782007	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,875,923
			K265	DS	F0000782017	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							I.S. 265 Total:	\$9,299,057
13	Brooklyn	K270		P.S. 270				
				DS	F0000799556	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	167,596
				DS	F0000799750	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	24,609
			K270	DS	F0000782086	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 270 Total:	\$227,444
13	Brooklyn	K282		P.S. 282				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000805576	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Toilet	P.S. 282 Total:	\$251,351
13	Brooklyn	K287		P.S. 287				
			K287	DSI	-0000843994	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,144
				DSI	-0000798438	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,500,000
				DSI	F0000798441	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
				DSI	-0000805651	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,066,657
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						<u> </u>	P.S. 287 Total:	\$6,951,828
13	Brooklyn	K305		P.S. 305				
				DSI	-0000805916	State of Good Repair - System Replacements - Toilets-Students	2017	159,628

District	Borough	Building ID	Org ID	School Project #	Description	FY - Construction Start	Total
					FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						P.S. 305 Total:	\$159,628
13	Brooklyn	K307		P.S. 307			
			K307	DSF0000798292	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
					HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K307	DSF0000782651	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
					CLIMATE CONTROL SYSTEM		
				DSF0000777710	State of Good Repair - System Replacements - Exterior Masonry	2016	3,040,484
					EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			K307	DSF0000782661	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	60,220
				DSF0000782658	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	3,462,898
				DSF0000782657	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,702,750

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000805961	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						HATOREO.otadont.oma	P.S. 307 Total:	\$15,356,150
13	Brooklyn	K813		DIST. OFF	FICE #13 (OLD	9 AX)		
				DSI	F0000784200	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	305,119
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						DIST. OFFICE #	13 (OLD 9 AX) Total:	\$305,119
14	Brooklyn	K016		P.S. 16				
			K016	DSI	F0000843891	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	79,500
							P.S. 16 Total:	\$79,500
14	Brooklyn	K017		P.S. 17				
			K017	DSI	F0000845625	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	750,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000777457	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	114,150
				DSF	-0000799536	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	113,631
				DSF	F0000799741	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	30,761
			K017	DSF	-0000778097	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM SERVICE SWITCH SWITCHBOARD TRANSFORMER	2019	1,158,768
				DSF	F0000755637	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2019	6,646,015
			K017	DSF	F0000778098	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	191,256

P.S. 17 Total: \$9,004,581

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
14	Brooklyn	K018		P.S. 18				
			K018	DSI	F0000801464	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 18 Total:	\$101,351
14	Brooklyn	K019		P.S. 19				
				DSI	-0000821883	State of Good Repair - Building Upgrade - Climate Control	2015	55,581
						CLIMATE CONTROL SYSTEM		
							P.S. 19 Total:	\$55,581
14	Brooklyn	K023		P.S. 23				
			K023	DSI	-0000778207	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 23 Total:	\$35,263
14	Brooklyn	K031		P.S. 31 (O	LD 126)			
				DSI	-0000777458	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	78,277
				DSI	F0000798403	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	765,261

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescer CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandesce		
			K031	DSF	F0000778318	State of Good Repair - System Replacements - Exter Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	r ior 2017	3,742,376
			K031	DSF	-0000821872	State of Good Repair - System Replacements - Para	pets 2017	834,992
			K031	DSF	F0000801662	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
							P.S. 31 (OLD 126) Total:	\$5,580,534
14	Brooklyn	K033		I.S. 33				
			K368	DSF	-0000844696	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	981,500
			K368	DSF	-0000821753	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,576

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K330	DS	F0000821776	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
			K330	DS	F0000843894	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	233,857
			K368	DS	F0000843895	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	359,160
			K330	DS	F0000843926	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	325,800
			K368	DS	F0000843927	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
				DS	F0000778354	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2016	190,896
			K330	DS	F0000777709	State of Good Repair - System Replacements - Kitchen Areas	2016	2,259,282

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K322	DS	SF0000822133	INTERIOR:KITCHEN/WARMING PANTRY:Floor Finish State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2015	216,633
			1/000	5		Other	00/0	
			K330	D	SF0000821682	Ansul Systems	2016 I.S. 33 Total:	319,164 \$5,065,300
14	Brooklyn	K034		P.S. 34				.,,,
				DS	SF0000798250	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,410,041
				DS	SF0000798252	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,278,574
			K034	DS	SF0000801712	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	1,145,633
				DS	SF0000755905	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:STAIRS/RAMPS: EXTERIOR	2015	785,280
				DS	SF0000801718	State of Good Repair - System Replacements - Toilets-Students	2016	216,964

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet		
							P.S. 34 Total:	\$8,836,492
14	Brooklyn	K049		I.S. 49				
						Other		
				DSF	-0000800059	IP Surveillance Camera Installation	2015	349,471
							I.S. 49 Total:	\$349,471
14	Brooklyn	K050		J.H.S. 50				
			K050	DSF	-0000844694	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	755,000
			K050	DSF	F0000845634	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	150,000
							J.H.S. 50 Total:	\$905,000
14	Brooklyn	K059		P.S. 59				
			K059	DSF	F0000843896	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	79,500
			K059	DSF	F0000843928	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	98,340

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K059	DS	F0000845602	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	116,000
			K059	DS	F0000821897	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	84,254
							P.S. 59 Total:	\$378,094
14	Brooklyn	K071	ID Org ID K059 K059	I.S. 71				
			K071	DS	F0000823625	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,196,535
			K071	DS	F0000844125	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	765,000
			K071	DS	F0000798275	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2018	4,664,685
						HEATING PLANT:BOILER SYSTEM		
			K071	DS	F0000778866	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DS	F0000798383	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,984,724
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000802198	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							I.S. 71 Total:	\$12,036,057
14	Brooklyn	K084		P.S. 84				
				DSF	-0000778990	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,318,994
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
14	Brooklyn	K110		P.S. 110			P.S. 84 Total:	\$1,318,994
				DSF	-0000798408	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	672,187
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 110 Total:	\$672,187
14	Brooklyn	K126		J.H.S. 126	;			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K126	DS	F0000798434	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
			K126	DSI	F0000825410	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	64,162
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System HEATING PLANT:Fuel System		
						HEATING Heating Coil In Ductwork		
						HEATING:Radiator/Convector/Fin Tube		
						HEATING:Unit Heater/Cabinet Heater		
							J.H.S. 126 Total:	\$1,388,784
14	Brooklyn	K132		P.S. 132				
				DS	F0000779724	State of Good Repair - System Replacements - Floors	2016	283,557
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish		
							P.S. 132 Total:	\$283,557
14	Brooklyn	K147		P.S. 147				
				DSI	F0000757389	State of Good Repair - System Replacements - Paved Area-Concrete SITE:SIDEWALKS:DOT Sidewalk	2016	961,678

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K147	DSF	-0000822137	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 147 Total:	\$1,213,029
14	Brooklyn	K157		P.S. 157				
			K157	DSF	F0000780044	State of Good Repair - System Replacements - Toilets-Students	2016	265,563
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 157 Total:	\$265,563
14	Brooklyn	K196		P.S. 196				
				DSF	F0000798388	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,028,343
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000804039	State of Good Repair - System Replacements - Toilets-Students	2016	220,648

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet		
						Other		
			K196	DS	F0000776043	IP Surveillance Camera Installation	2015	572,103
							P.S. 196 Total:	\$1,821,094
14	Brooklyn	K257		P.S. 257				
				DSI	F0000821724	State of Good Repair - System Replacements - Toilets-Students	2016	207,980
						FIXTURES:STUDENT:Toilet		
							P.S. 257 Total:	\$207,980
14	Brooklyn	K297		P.S. 297				
				DSI	F0000799802	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	37,146
				DSI	F0000805806	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						TIXTORES.Student.Onnai	P.S. 297 Total:	\$138,497
14	Brooklyn	K318		I.S. 318				
				DS	F0000844027	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	2,242,012
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K318	DS	F0000782769	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DS	F0000801068	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING	2015	64,864
							I.S. 318 Total:	\$2,342,115
14	Brooklyn	K319		P.S. 319				
				DS	F0000806083	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	240,534
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 319 Total:	\$240,534
14	Brooklyn	K380		P.S. 380				
				DS	F0000806385	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING	2016	124,489
							P.S. 380 Total:	\$124,489
15	Brooklyn	K010		P.S. 10				
				DS	F0000799679	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	295,349
							P.S. 10 Total:	\$295,349

FY -

		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
15	Brooklyn	K015		P.S. 15				
				DSI	F0000755590	State of Good Repair - Building Upgrade - Climate Control	2015	2,617,154
						CLIMATE CONTROL SYSTEM		
				DSI	F0000755592	State of Good Repair - Building Upgrade - Flood Elimination	2015	5,406,952
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	F0000777696	State of Good Repair - Building Upgrade - Interior Spaces	2015	1,668,781
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSI	F0000799892	State of Good Repair - System Replacements -	2015	1,198,236
						Domestic Piping		
						DOMESTIC WATER SYSTEM		
				DSI	F0000755595	State of Good Repair - System Replacements -	2015	1,462,108
						Electrical Systems		
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD	0045	0.040.440
				DSI	F0000777695	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	6,846,140

District	Borough	Building ID	Org ID	School Project #	Description	FY - Construction Start	Total
					HEATING PLANT:BOILER AUXILIARIES		
				D05000770070	HEATING PLANT:BOILER SYSTEM	0045	1 000 000
				DSF0000778072	State of Good Repair - System Replacements - Heating	2015	1,862,039
					Plant Upgrade Ventilation		
					VENTILATION:EXHAUST FAN		
					VENTILATION:METAL DUCTWORK		
					VENTILATION: SUPPLY FAN		
					VENTILATION:UNIT VENTILATOR		
			K015	DSF0000801409	State of Good Repair - System Replacements -	2016	101,351
					Toilets-Students		
					FIXTURES:STUDENT:Lavatory/Sink		
					FIXTURES:STUDENT:Toilet		
					FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
					INTERIOR. TOILET ROOMS - STUDENTS	P.S. 15 Total:	\$21,162,761
15	Brooklyn	K024		P.S. 24			. , ,
10	Breenayn	11021		DSF0000844722	Educational Enhancements - Educational	2018	73,486
				201 0000044722	Enhancements - Accessibility	2010	70,400
				DSF0000823569	State of Good Repair - System Replacements - Heating	2018	74,806
					Plant Upgrade		
					HEATING PLANT:BOILER SYSTEM		
						P.S. 24 Total:	\$148,292
15	Brooklyn	K027		P.S. 27			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798393	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,057,390
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000755806	State of Good Repair - System Replacements - Exterior Masonry	2015	5,005,236
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000755805	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	4,533,363
			K676	DS	F0000801622	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
							P.S. 27 Total:	\$10,755,617
15	Brooklyn	K029		P.S. 29				
				DS	F0000801644	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2016	218,580

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
					-	INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 29 Total:	\$218,580
15	Brooklyn	K032		P.S. 32				
			K032	DSF	0000798271	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,68
			K032	DSF	0000778334	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762
			K032	DSF	0000822132	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	251,35 ⁻
							P.S. 32 Total:	\$6,239,798
15	Brooklyn	K038		P.S. 38				
	,			DSF	0000799682	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	138,52 ⁻
			K038	DSF	0000822134	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351
							P.S. 38 Total:	\$389,872

15 Brooklyn K039 **P.S. 39**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798405	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	241,182
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 39 Total:	\$241,182
15	Brooklyn	K051		I.S. 51				
			K051	DS	F0000798272	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685
			K051	DS	F0000798273	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
				DS	F0000821884	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Climate	2015	49,022
						Control		-,-
						CLIMATE CONTROL SYSTEM		
							I.S. 51 Total:	\$6,037,469
15	Brooklyn	K058		P.S. 58				
			K058	DS	F0000798389	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,513,010
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K058	DS	F0000798396	State of Good Repair - Building Upgrade - Climate Control	2017	1,280,719
							P.S. 58 Total:	\$5,793,729
15	Brooklyn	K088		I.S. 88				
				DS	F0000775609	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,619,327
			K088	DS	F0000775610	State of Good Repair - Building Upgrade - Climate Control	2017	1,881,715
				DS	F0000802365	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
			K088	DS	F0000822135	State of Good Repair - System Replacements - Toilets-Students	2016	251,403
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 88 Total:	\$7,853,796
15	Brooklyn	K094		P.S. 94				
				DS	F0000779148	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,103,898
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000756679	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:STAIRS/RAMPS: EXTERIOR	2015	598,467
				DS	F0000824937	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	38,360
							P.S. 94 Total:	\$1,740,725
15	Brooklyn	K124		P.S. 124				
			K124	DS	F0000825396	Domestic Piping DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain FIXTURES:Student:Sink And Fountain Combo Unit	2017	755,000
			K124	DS	F0000802950	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	966,076
			K124	DS	F0000825394	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2019	1,734,743
			K124	DS	F0000843697	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2019	1,007,118
			K124	DS	F0000825393	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	1,410,560

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K124	DS	F0000779630	State of Good Repair - System Replacements - Toilets-Students	2015	354,935
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:TUINEL		
						INTERIOR: TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
				DS	F0000825397	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 124 Total:	\$6,388,060
15	Brooklyn	K130		P.S. 130				
				DS	F0000779686	State of Good Repair - System Replacements - Exterior Masonry	2017	10,272,577
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000803013	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2017	1,709,914
				DS	F0000803012	State of Good Repair - System Replacements - Roofs	2017	1,251,175
						EXTERIOR:ROOFING:Specialties		.,, 0

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			K130	DS	F0000822051	New/Retrofit Telephone/Intercom Systems	2015	153,565
							P.S. 130 Total:	\$13,387,231
15	Brooklyn	K131		P.S. 131				
				DS	F0000777464	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	161,591
			K131	DS	F0000798264	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,673,992
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K131	DS	F0000798265	State of Good Repair - Building Upgrade - Climate Control	2018	1,326,403
						CLIMATE CONTROL SYSTEM		
				DS	F0000803027	State of Good Repair - Building Upgrade - Flood Elimination	2018	258,442
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000803025	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,186,532
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000779700	State of Good Repair - System Replacements - Exterior Masonry	2018	3,370,825

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000803030	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets	2018	4,935,734
				20		EXTERIOR:COPING EXTERIOR:PARAPETS	2010	4,000,704
				DS	F0000803029	State of Good Repair - System Replacements - Roofs	2018	1,774,483
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
							P.S. 131 Total:	\$17,688,002
15	Brooklyn	K136		I.S. 136				
			K136	DS	F0000803089	State of Good Repair - Building Upgrade - Flood Elimination	2016	87,888
				50	F0000757249	INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	1 011 120
				03	F0000757249	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2010	1,811,138
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DS	F0000775639	State of Good Repair - System Replacements - Domestic Piping	2016	941,625
						DOMESTIC WATER SYSTEM		
			K136	DS	F0000779760	State of Good Repair - System Replacements - Electrical Systems PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,172,661

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
				DSF	-0000752460	IP Surveillance Camera Installation	2015	561,463
							I.S. 136 Total:	\$5,574,775
15	Brooklyn	K154		P.S. 154				
	,			DSF	-0000800302	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN	2015	44,594
						SPACES:Ceiling		
				DSF	-0000798410	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	559,745
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000803335	State of Good Repair - System Replacements - Toilets-Students	2015	136,755
						FIXTURES:STUDENT:Toilet		
							P.S. 154 Total:	\$741,094
15	Brooklyn	K169		P.S. 169				
				DSF	-0000780241	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,390,795
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000844138	State of Good Repair - System Replacements - Heating	2018	53,737
						Plant Upgrade		
						GAS FIRED FURNACE		
							P.S. 169 Total:	\$1,444,532
15	Brooklyn	K172		P.S. 172				
				DSI	F0000780299	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	696,965
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K172	DSI	F0000826042	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	47,738
						GAS SERVICE:Gas Distribution Piping		
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						GAS SERVICE:Gas Meter Room Vent		
						HEATING PLANT:Boiler System HEATING PLANT:Fuel System		
						HEATING PLANT. Fuel System HEATING: Heating Coil In Ductwork		
						HEATING:Radiator/Convector/Fin Tube		
						HEATING:Unit Heater/Cabinet Heater		

P.S. 172 Total: \$744,703

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
15	Brooklyn	K230		P.S. 230				
				DSI	F0000781392	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	865,686
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 230 Total:	\$865,686
15	Brooklyn	K261		P.S. 261				
			K261	DSI	F0000798449	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,667,715
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K261	DSI	F0000798452	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
							P.S. 261 Total:	\$5,992,337
15	Brooklyn	K293		J.H.S. 293	3			
				DSI	F0000821577	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	592,726
				DSI	F0000821655	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Library Upgrades	2016	1,417,753

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K368	DS	F0000821777	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
			K497	DS	F0000843911	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	528,208
			K368	DS	F0000843912	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	125,216
			K368	DS	F0000843995	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
				DS	F0000798444	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,500,000
				DS	F0000798447	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,277,027
				DS	F0000759888	State of Good Repair - System Replacements - Exterior Masonry	2016	6,868,482

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000782463	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	3,510,948
				DS	F0000805764	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	6,064,364
			K129	DS	F0000822139	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2015	265,423
						Other		
			K429	DS	F0000822052	New/Retrofit Telephone/Intercom Systems	2015	301,379
							J.H.S. 293 Total:	\$25,594,958
15	Brooklyn	K321		P.S. 321				
				DS	F0000800269	Educational Enhancements - Educational Enhancements - Accessibility	2017	7,033,396
				DS	F0000806121	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,367,901
			K321	DS	F0000806120	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2017	987,096

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000821725	State of Good Repair - System Replacements - Toilets-Students	2016	171,121
						FIXTURES:STUDENT:Toilet		
			K321	DS	F0000865739	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						Other		
			K321	DS	F0000776049	IP Surveillance Camera Installation	2015	536,966
							P.S. 321 Total:	\$10,346,480
15	15 Brooklyn	K763		P.S. 118	MAURICE SEN	DAK COMMUNITY SCHOOL		
				DS	F0000799768	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	16,220
						P.S. 118 MAURICE SENDAK COMMUNIT	Y SCHOOL Total:	\$16,220
15	Brooklyn	K845		P.S. 295				
				DS	F0000784298	State of Good Repair - Building Upgrade - Flood Elimination	2018	5,380,399
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DS	F0000784296	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	650,119
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000761629	State of Good Repair - Building Upgrade - Reinforcing Support Elements INTERIOR:STRUCTURAL:ROOF STRUCTURE	2018	286,799
				DSI	-0000807597	State of Good Repair - System Replacements - Exterior Masonry	2018	1,021,837
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS		
			K443	DSI	-0000784302	State of Good Repair - System Replacements - Floors INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2018	849,523
				DSI	-0000775989	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:Gymnasium:Flooring	2018	1,483,037
				DSI	F0000807596	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2018	366,144
				DSI	-0000807595	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	316,914
							P.S. 295 Total:	\$10,354,772
15	Brooklyn	K908		P.S. 230 A	NNEX			
				DSI	-0000799763	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	20,694

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Р	.S. 230 ANNEX Total:	\$20,694
16	Brooklyn	K005		P.S. 5				
			K005	DSI	F0000865729	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 5 Total:	\$250,000
16	Brooklyn	K021		P.S. 21				
				DSI	F0000778166	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
			K021	DSI	F0000801519	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			K021	DSI	F0000776035	IP Surveillance Camera Installation	2015	524,918
							P.S. 21 Total:	\$1,903,296
16	Brooklyn	K025		P.S. 25				
			K025	DSI	F0000844693	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	630,000
			K025	DSI	F0000798635	Safety and Security - Safety and Security - Safety Systems	2015	841,309

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
				DSI	-0000798391	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,052,829
				DSI	-0000755763	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2015	3,968,104
				DSI	-0000755762	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	1,794,438
				DSI	-0000755761	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,943,018
							P.S. 25 Total:	\$10,229,698
16	Brooklyn	K026		P.S. 26				
				DSI	-0000801089	Educational Enhancements - Educational Enhancements - Accessibility	2017	8,102,791
			K026	DSI	-0000801599	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2017	2,882,381

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
							P.S. 26 Total:	\$10,985,172
16	Brooklyn	K035		I.S. 35				
				DSF	0000822095	Educational Enhancements - Educational Enhancements - Accessibility	2019	12,138,443
				DSF	0000799537	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	282,264
							I.S. 35 Total:	\$12,420,707
16	Brooklyn	K040		P.S. 40				
				DSF	0000845619	Educational Enhancements - Educational Enhancements - Accessibility	2017	1,500,000
				DSF	0000799683	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	47,990
							P.S. 40 Total:	\$1,547,990
16	Brooklyn	K057		J.H.S. 57				
				DSF	0000778722	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	38,591
				DSF	-0000799538	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	201,478
				DSF	0000802044	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2018	1,525,188

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							J.H.S. 57 Total:	\$1,765,257
16	Brooklyn	K081		P.S. 81				
				DSF	-0000802291	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2016	1,000,318
				DSF	-0000802298	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						Other		
			K081	DSF	-0000776037	IP Surveillance Camera Installation	2015	533,087
							P.S. 81 Total:	\$1,693,033
16	Brooklyn	K243		P.S. 243				
				DSF	-0000759073	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,148,759
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K243	DSF	-0000804935	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							DS 243 Total	\$1 304 125

P.S. 243 Total: \$1,304,125

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
16	Brooklyn	K304		P.S. 304				
				DSF	-0000805894	State of Good Repair - System Replacements - Exterior Masonry	2016	785,991
						EXTERIOR: EXTERIOR WALLS		
				DSF	-0000782597	State of Good Repair - System Replacements - Roofs	2016	3,283,069
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
				DSF	-0000805897	State of Good Repair - System Replacements -	2015	229,817
						Toilets-Students		
						FIXTURES:STUDENT:Toilet		
							P.S. 304 Total:	\$4,298,877
16	Brooklyn	K308		P.S. 308				
						Other		
			K308	DSF	-0000822053	New/Retrofit Telephone/Intercom Systems	2015	222,133
							P.S. 308 Total:	\$222,133
16	Brooklyn	K309		P.S. 309				
				DSF	-0000799559	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	443,870
				DSF	-0000799751	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	34,117
			K309	DSF	-0000865738	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 309 Total:	\$727,987
16	Brooklyn	K324		I.S. 324				
			K267	DSF	50000843913	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	79,500
			K267	DSF	F0000843932	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
							I.S. 324 Total:	\$187,932
16	Brooklyn	K335		P.S. 335				
			K335	DSF	0000845614	Accessibility	2017	1,064,189
			K335	DSF	-0000843638	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
							P.S. 335 Total:	\$1,223,817

17 Brooklyn K002 I.S. 2

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K002	DS	F0000843996	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	89,498
			K002	DS	F0000823764	Safety and Security - Safety and Security - Safety Systems EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS INTERIOR:INTERIOR GUARDS	2015	59,303
				DS	F0000801188	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,805
							I.S. 2 Total:	\$223,606
17	Brooklyn	K006		P.S. 6				
			K006	DS	F0000801233	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	34,946
				DS	F0000801239	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,805
							P.S. 6 Total:	\$109,751
17	Brooklyn	K022		P.S. 22				
	,			DS	F0000732914	State of Good Repair - Building Upgrade - Climate Control	2015	2,415,453

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
						CLIMATE CONTROL SYSTEM		
				DS	F0000755717	State of Good Repair - Building Upgrade - Flood Elimination	2015	217,436
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
							P.S. 22 Total:	\$2,632,889
17	Brooklyn	K061		I.S. 61				
				DS	F0000802105	State of Good Repair - System Replacements - Toilets-Students	2016	216,691
						FIXTURES:STUDENT:Toilet		
							I.S. 61 Total:	\$216,691
17	Brooklyn	K091		P.S. 91				
			K091	DS	F0000824866	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2017	331,953
							P.S. 91 Total:	\$331,953
17	Brooklyn	K092		P.S. 92				
	·			DS	F0000799539	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	327,825
				DS	F0000756631	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,569,836
						FIRE ALARM SYSTEM		
							P.S. 92 Total:	\$1,897,661
17	Brooklyn	K138		PS 138				

17 Brooklyn K138 **P.S. 138**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K138	DSI	-0000845592	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
				DSI	-0000777465	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	204,697
			K138	DSI	-0000822146	State of Good Repair - System Replacements - Toilets-Students	2016	263,433
							P.S. 138 Total:	\$2,768,130
17	Brooklyn	K161		P.S. 161				
			K161	DSI	-0000821778	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	65,931
				DSI	-0000777467	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	221,624
			K161	DSI	F0000803429	State of Good Repair - Building Upgrade - Flood Elimination	2018	2,108,693
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
						INTERIOR.STRUCTURAL. I CONDATION WALLS	P.S. 161 Total:	\$2,396,248
17	Brooklyn	K167		P.S. 167				, _,, _
	Brooklyn		K167		F0000799948	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	49,587

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K532	DSF	-0000799949	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	86,998
				DSF	-0000780235	Safety and Security - Safety and Security - Safety Systems	2015	44,293
						EXTERIOR: DOORS: DOORS AND FRAMES		
			K167	DSF	-0000780227	State of Good Repair - System Replacements - Exterior Masonry	2016	9,378,182
						EXTERIOR: EXTERIOR WALLS		
			K167	DSF	-0000803545	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2019	3,368,952
			K167	DSF	-0000803544	State of Good Repair - System Replacements - Roofs	2019	2,136,042
				20.		EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2010	2,100,012
						·	P.S. 167 Total:	\$15,064,054
17	Brooklyn	K189		P.S. 189				
			K189	DSF	-0000803898	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 189 Total:	\$159,628

17 Brooklyn K191 **P.S. 191**

District	Borough	Building ID	Ora ID	School	Project #	Description	FY - Construction Start	Total
					F0000822221	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,011,489
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K191	DSI	F0000803935	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY	2019	1,881,308
			K191	DSI	F0000826342	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2019	294,244
			K191	DSI	F0000844012	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing	2019	1,023,518
			K191	DSI	F0000803939	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting	2017	159,628
						Fixture - Incandescent	DS 101 Total:	¢4 270 19

P.S. 191 Total: \$4,370,187

17 Brooklyn K210 I.S. 394

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000844089	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	759,000
				DS	F0000798593	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,771,186
						INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DS	F0000799547	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	309,720
							I.S. 394 Total:	\$2,839,906
17	Brooklyn	K221		P.S. 221				
			K221	DS	F0000844134	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	152,169
			K221	DS	F0000798282	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685
			K221	DS	F0000781216	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762
			K221	DS	F0000735778	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	943,384
			K221	DS	F0000781221	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K221	DSF	-0000844745	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	48,801
							P.S. 221 Total:	\$7,168,040
17	Brooklyn	K241		P.S. 241				
				DSF	F0000781591	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	28,524
				DSF	-0000799554	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	148,852
				DSF	F0000804894	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Toilet		
							P.S. 241 Total:	\$428,727
17	Brooklyn	K246		I.S. 246				
				DSF	-0000781675	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,556,977
			K246	DSF	F0000822149	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 246 Total:	\$1,808,328
17	Brooklyn	K249		P.S. 249				
			K249	DSF	0000798267	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,513,010
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K249	DSF	0000781711	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
						CLIMATE CONTROL SYSTEM		
				DSF	0000805018	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	81,924
			K249	DSF	0000805019	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 249 Total:	\$5,982,425
17	Brooklyn	K289		P.S. 289				
				DSF	0000844717	Educational Enhancements - Educational Enhancements - Accessibility	2018	82,038
			K289	DSF	0000798289	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,673,992

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS		
			K289	DS	F0000782382	State of Good Repair - Building Upgrade - Climate Control	2018	1,326,403
						CLIMATE CONTROL SYSTEM		
				DS	F0000799557	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	282,186
				DS	F0000799733	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	32,998
							P.S. 289 Total:	\$6,397,617
17	Brooklyn	K316		P.S. 316				
				DS	F0000782760	Safety and Security - Safety and Security - Safety Systems	2015	31,756
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS		
							P.S. 316 Total:	\$31,756
17	Brooklyn	K320		P.S. 375				
			K352	DS	F0000843993	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	216,816
			K375	DS	F0000844685	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2018	63,568

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
				DS	F0000798261	State of Good Repair - Building Upgrade - Boiler Conversion	2017	6,829,896
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798262	State of Good Repair - Building Upgrade - Climate Control	2017	1,330,140
						CLIMATE CONTROL SYSTEM		
			K352	DS	F0000782802	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 375 Total:	\$8,475,683
17	Brooklyn	K390		I.S. 390				
				DS	F0000843656	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Library Upgrades INTERIOR:LIBRARY:Built-in Furnishing INTERIOR:LIBRARY:Floor Finish INTERIOR:LIBRARY:Walls	2017	1,115,712
			K334	DS	F0000798298	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,513,010
			K334	DS	F0000783145	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863

District	Borough	Building ID	Ora ID	School	Project #	Description	FY - Construction Start	Total
Diotitot	Dorough		0.9.5			CLIMATE CONTROL SYSTEM	Otart	
				DS	F0000783146	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	52,573
			K334	DS	F0000783151	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000799805	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
							I.S. 390 Total:	\$7,006,379
17	Brooklyn	K391		I.S. 391				
	-			DS	F0000777482	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	95,100
				DS	F0000799735	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	46,421
			K356	DS	F0000783170	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000806466	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 391 Total:	\$278,135

17 Brooklyn K397 **P.S. 397**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000783184	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	563,393
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 397 Total:	\$563,393
17	Brooklyn	K398		P.S. 398 (UDC)			
				DS	F0000799560	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	198,530
			K398	DS	F0000845576	State of Good Repair - System Replacements - Domestic Piping Waste System	2018	130,779
			K398	DS	F0000799786	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 398 (UDC) Total:	\$364,572
17	Brooklyn	K399		P.S. 399				
			K399	DS	F0000783207	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 399 Total:	\$35,239
17	Brooklyn	K874		I.S. 340 (C	OLD 249 AX)			
	-		K340	DS	F0000829872	Domestic Piping DOMESTIC WATER SYSTEM	2017	755,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Drinking Fountain		
			K340	DS	F0000807762	State of Good Repair - Building Upgrade - Flood Elimination	2018	1,020,757
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000784452	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	419,290
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K340	DS	F0000761807	State of Good Repair - System Replacements - Exterior	2018	1,618,456
						Masonry		
						EXTERIOR:CHIMNEY		
						EXTERIOR:EXTERIOR WALLS		
						I.S. 340 (O	LD 249 AX) Total:	\$3,813,503
17	Brooklyn	K892		P.S. 221	MINISCHOOL			
				DS	F0000798589	State of Good Repair - Building Upgrade - Low-Voltage	2015	259,855
						Electrical Systems		
						FIRE ALARM SYSTEM		
						P.S. 221 M	NISCHOOL Total:	\$259,855
18	Brooklyn	K068		I.S. 68				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K068	DS	F0000778852	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	57,437
				DSI	F0000799797	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
							I.S. 68 Total:	\$136,743
18	Brooklyn	K114		P.S. 114				
			K114	DS	F0000844103	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	216,926
						GAS SERVICE:Gas Distribution Piping		
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT: Fuel System		
			K114	DSI	F0000822145	State of Good Repair - System Replacements -	2016	251,351
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 114 Total:	\$468,277
18	Brooklyn	K135		P.S. 135				
	-			DSI	F0000803073	State of Good Repair - System Replacements - Toilets-Students	2016	281,470

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet		
							P.S. 135 Total:	\$281,470
18	Brooklyn	K208		P.S. 208				
				DSF	-0000780969	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	566,218
				DSF	-0000798411	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,138,391
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000780973	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2016	1,164,089
			K208	DSF	-0000826670	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing	2017	1,466,692
			K208	DSF	-0000780975	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2015	239,989

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000799939	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	1,280,158
							P.S. 208 Total:	\$5,855,537
18	Brooklyn	K211		I.S. 211				
			K211	DSI	F0000843903	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	175,000
			K211	DSI	F0000843929	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	385,630
				DSI	F0000781022	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	1,535,368
				DSI	F0000799436	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	2,615,124
				DSI	F0000781046	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling	2015	767,876

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DS	F0000781023	INTERIOR:STAIRS/RAMPS: INTERIOR State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,388,374
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000781029	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,455,262
				DSI	F0000781030	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	8,819,390
				DS	F0000804335	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	209,651

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K211	DS	F0000776044	IP Surveillance Camera Installation	2015	637,459
							I.S. 211 Total:	\$17,989,134
18	Brooklyn	K219		P.S. 219				
_			K219	DS	F0000799935	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,875,334
							P.S. 219 Total:	\$1,875,334
18	Brooklyn	K232		I.S. 232				
			K581	DS	F0000804724	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	319,257
							I.S. 232 Total:	\$319,257
18	Brooklyn	K233		P.S. 233				
			K233	DSI	F0000845624	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	750,000
				DS	F0000781448	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	787,714
				DSI	F0000799731	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	39,150

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K233	DSI	F0000804745	State of Good Repair - Building Upgrade - Reinforcing Support Elements INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS	2016	299,374
			K233	DSI	F0000843650	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2016	7,002,012
			K233	DSI	F0000843651	State of Good Repair - System Replacements - Parapets	2019	864,841
			K233	DSI	F0000827141	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing	2019	2,623,350
			K233	DSI	F0000822148	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	206,090
							P.S. 233 Total:	\$12,572,531
18	Brooklyn	K235		P.S. 235				
	,			DS	F0000777476	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	88,901

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K235	DS	F0000799530	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	2,594,717
			K235	DS	F0000804784	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,628
							P.S. 235 Total:	\$2,843,246
18	Brooklyn	K242		P.S. 235 A	ANNEX			
			K235	DS	F0000804911	State of Good Repair - Building Upgrade - Reinforcing Support Elements INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS	2017	1,480,275
			K235	DS	F0000804914	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 235 ANNEX Total:	\$1,639,903
18	Brooklyn	K244		P.S. 244				
	·			DSF	0000781655	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUM PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016 IP	303,008
				DSF	0000799690	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	217,037
				DSF	0000759098	State of Good Repair - System Replacements - Exterio Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	r 2016	5,387,539
				DSF	0000781658	State of Good Repair - System Replacements - Parape EXTERIOR:PARAPETS	ts 2016	1,364,406
				DSF	0000781657	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,683,949
				DSF	0000799878	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	5,006,272
							P.S. 244 Total:	\$13 062 211

P.S. 244 Total: \$13,962,211

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
18	Brooklyn	K252		I.S. 252				
				DSF	-0000844098	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	47,676
				DSF	-0000777477	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	139,262
				DSF	F0000798253	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	13,846,308
				DSF	-0000781767	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,693,094
				DSF	-0000781769	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	833,316
			K588	DSF	-0000805080	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2017	159,628
								#40 740 00

I.S. 252 Total: \$16,719,284

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
18	Brooklyn	K268		P.S. 268				
				DSF	F0000759470	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	971,976
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000799732	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	45,924
			K268	DSF	0000799531	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	1,579,084
							P.S. 268 Total:	\$2,596,984
18	Brooklyn	K272		P.S. 272				
	-			DSF	0000798435	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000782116	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSF	-0000759549	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	132,941

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000799692	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	216,384
			K272	DSF	0000799526	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,743,266
				DSF	0000759552	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2015	2,231,293
			K272	DSF	0000805414	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	38,037
				DSF	0000822654	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
				DSF	60000759551	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	2,382,983
				DSF	0000759550	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	3,599,980
							P.S. 272 Total:	\$16,367,682
18	Brooklyn	K276		P.S. 276				
				DSF	0000759617	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	7,119,061

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000759620	State of Good Repair - Building Upgrade - Flood Elimination	2015	5,141,191
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000777686	State of Good Repair - Building Upgrade - Interior	2015	2,077,549
						Spaces		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Walls		
				DS	F0000805475	State of Good Repair - Building Upgrade - Lighting	2016	1,097,907
				20		Fixtures	20.0	.,,
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000798522	State of Good Repair - Building Upgrade - Low-Voltage	2015	1,194,586
						Electrical Systems		
						FIRE ALARM SYSTEM		
			K276	DS	F0000799527	State of Good Repair - Rehabilitation of Physical	2015	543,126
						Education Facilities - Playground Redevelopment		
				DS	F0000782190	State of Good Repair - System Replacements - Exterior	2015	1,166,455
						Masonry		
						EXTERIOR: EXTERIOR WALLS		
				DS	SF0000759626	State of Good Repair - System Replacements - Heating	2015	4,380,298
						HEATING PLANT:BOILER AUXILIARIES		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000782197	HEATING PLANT:BOILER SYSTEM State of Good Repair - System Replacements - Paved Area-Blacktop	2015	1,465,006
						SITE:PAVING - STUDENT NON-USE:Asphalt SITE:PAVING - STUDENT USE:Asphalt		
				DS	F0000782187	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	4,211,763
							P.S. 276 Total:	\$28,396,942
18	Brooklyn	K279		P.S. 279			0045	4 000 000
				08	F0000777692	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	1,632,323
				DS	F0000799882	State of Good Repair - Building Upgrade - Elevators and Escalators CONVEYING:ELEVATORS	2015	640,098
				DS	F0000777688	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	10,100,542
			K279	DS	F0000777691	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)	2015	1,281,635

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DS	F0000805533	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,109,003
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000782243	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,702,155
						FIRE ALARM SYSTEM		
				DS	\$F0000799884	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	514,856
						SITE:Drainage System for Asphalt SITE:Drainage System for Concrete SITE:PAVING - STUDENT USE:Concrete SITE:PLAYGROUNDS:Play Equipment SITE:PLAYGROUNDS:Safety Surfacing SITE:SEATING:Benches		
				DS	SF0000799883	State of Good Repair - System Replacements -	2015	1,272,256
						Domestic Piping		
			1/070			DOMESTIC WATER SYSTEM	0045	0.000.740
			K279	D	SF0000777689	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,263,742

Tota	FY - Construction Start	Description	Project #	School	Org ID	Building ID	Borough	District
6,993,086	2015	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES	0000759677	DSF	K279			
2,784,596	2015	HEATING PLANT:BOILER SYSTEM State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:HEATING AND VENTILATING UNIT	0000782256	DSF				
\$30,294,292	P.S. 279 Total:							
				I.S. 285		K285	Brooklyn	18
1,336,28	2015	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	0000782314	DSF			·	
2,132,734	2015	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY	0000736829	DSF	K285			
\$3,469,01	I.S. 285 Total:							

18 Brooklyn K860 **P.S. 219 ANNEX**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000761724	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	799,516
						Ρ.	S. 219 ANNEX Total:	\$799,516
19	Brooklyn	K007		P.S. 7				
				DS	F0000844727	Educational Enhancements - Educational Enhancements - Accessibility	2018	74,173
				DS	F0000777901	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	29,642
				DSI	F0000823568	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,806
						TIEATING FLANT.BOILER STSTEM	P.S. 7 Total:	\$178,621
19	Brooklyn	K013		P.S. 13				, , . .
			K013	DSI	F0000843893	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	89,000
				DS	F0000799681	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	126,305
				DSI	F0000799770	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	62,081

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000801363	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
			K013	DS	F0000823910	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Radiator/Convector/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater	2018	189,162
							P.S. 13 Total:	\$621,914
19	Brooklyn	K072		P.S. 72				
			K677	DS	F0000778896	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 72 Total:	\$35,263
19	Brooklyn	K108		P.S. 108				
			K108	DS	F0000802709	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2016	734,546
				DS	F0000775637	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2015	666,238

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K108	DS	SF0000844744	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	47,023
			K108	DS	SF0000823660	State of Good Repair - System Replacements - Toilets-Students	2017	266,407
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 108 Total:	\$1,714,214
19	Brooklyn	K158		P.S. 158				
				DS	SF0000777466	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	110,070
				DS	SF0000799746	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	31,320
				DS	SF0000757554	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	2,238,531
				DS	SF0000825820	State of Good Repair - Building Upgrade - Reinforcing Support Elements INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE	2016	759,738
			K158	DS	SF0000803389	State of Good Repair - System Replacements - Exterior Masonry	2016	201,004

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR: EXTERIOR WALLS		
				DS	SF0000780067	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2016	1,054,928
						MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
				DS	SF0000821660	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2016	841,346
			K158	DS	SF0000757565	State of Good Repair - System Replacements - Kitchen Areas INTERIOR:KITCHEN/WARMING PANTRY:Floor Finish INTERIOR:KITCHEN/WARMING PANTRY:Walls	2016	4,082,774
			K158	DS	SF0000803387	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	260,601
							P.S. 158 Total:	\$9,580,312
19	Brooklyn	K159		P.S. 159				
			K159	DS	SF0000822138	State of Good Repair - System Replacements - Toilets-Students	2016	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 159 Total:	\$251,351
19	Brooklyn	K166		I.S. 166				
			K654	DSF	0000844135	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	82,461
				DSF	0000777470	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	208,365
			K166	DSF	0000782898	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSF	0000803530	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 166 Total:	\$1,669,204
19	Brooklyn	K171		I.S. 171				
				DSF	60000777471	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	99,039
			K171	DSF	0000780281	State of Good Repair - Building Upgrade - Flood Elimination	2018	3,988,545

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			K171	DS	F0000826018	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2018	1,852,015
			K171	DS	F0000826031	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Metal Ductwork VENTILATION:Supply Fan	2018	2,281,578
			K171	DS	F0000826023	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	2,053,897
				DS	F0000803608	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent	2017	159,628
				DS	F0000803605	State of Good Repair - System Replacements - Windows	2018	7,039,153

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:WINDOWS		
						Other		
			K171	DSF	0000776042	IP Surveillance Camera Installation	2015	632,483
							I.S. 171 Total:	\$18,106,338
19	Brooklyn	K174		P.S. 174				
				DSF	60000780317	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	437,908
				DSF	0000799747	INTERIOR:STRUCTURAL:VAULTS-BUNKERS State of Good Repair - Building Upgrade - Lighting Fixtures	2015	30,761
			K174	DSF	⁻ 0000844104	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Exhaust Fan GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System	2018	74,950
				DSF	0000803645	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS	2015	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 174 Total:	\$794,970
19	Brooklyn	K190		P.S. 190				
				DSF	0000780589	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	29,083
							P.S. 190 Total:	\$29,083
19	Brooklyn	K202		P.S. 202				
			K202	DSF	0000799933	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	424,220
			K202	DSF	0000821756	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	101,15
			K202	DSF	0000843901	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	98,50
				DSF	0000799748	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	41,387
							P.S. 202 Total:	\$665,270

19 Brooklyn K213 **P.S. 213**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K213	DSI	-0000843864	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	119,420
							P.S. 213 Total:	\$119,420
19	Brooklyn	K214		P.S. 214				
				DSI	-0000799548	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	121,514
			K214	DSI	-0000822269	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	2,479,154
							P.S. 214 Total:	\$2,600,668
19	Brooklyn	K218		I.S. 218				
				DSI	-0000804473	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			K218	DSI	-0000822130	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 218 Total:	\$784,587
19	Brooklyn	K224		P.S. 224				
	-			DSI	-0000781282	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	34,117
				DSI	F0000799550	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	286,417

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000804578	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,806
							P.S. 224 Total:	\$395,340
19	Brooklyn	K260		P.S. 260				
			K260	DSI	F0000798284	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K260	DSI	F0000781925	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DSI	F0000759360	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	780,335
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 260 Total:	\$6,768,782
19	Brooklyn	K273		P.S. 273				
			K273	DSI	F0000821886	State of Good Repair - Building Upgrade - Climate Control	2015	51,808
				DSI	F0000799693	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	186,995

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K273	DSI	F0000782141	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 273 Total:	\$274,066
19	Brooklyn	K290		P.S. 290				
				DSI	70000782399	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,329,604
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K290	DSI	-0000821978	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,233,988
			K290	DSI	F0000782405	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
						Other		
			K290	DSI	-0000776048	IP Surveillance Camera Installation	2015	504,002
							P.S. 290 Total:	\$3,102,833
19	Brooklyn	K292		I.S. 292				
			K292	DSI	70000798375	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,667,715

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K292	DS	F0000778483	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
				DS	F0000799558	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	415,626
				DS	F0000799749	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	58,166
			K292	DS	F0000782446	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			K292	DS	F0000805747	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							I.S. 292 Total:	\$6,656,758
19	Brooklyn	K302		I.S. 302				
				DS	F0000821663	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	2,357,868
			K302	DS	F0000843816	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,166,744
							I.S. 302 Total:	\$3,524,612
19	Brooklyn	K306		P.S. 306				
	,			DS	F0000799696	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	384,826
			K306	DS	F0000782639	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000828244	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	61,861
			K306	DSF	F0000782640	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting	2016	178,500
						Fixture - Incandescent	P.S. 306 Total:	\$660.4E0
19	Brooklyn	K328		P.S. 328			P.S. 300 Total.	\$660,450
				DSF	-0000806186	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING	2015	67,567
			K328	DSF	-0000865740	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 328 Total:	\$317,567
19	Brooklyn	K345	K345	P.S. 345 DSF	-0000798295	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K345	DS	F0000798296	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DS	F0000844016	System Expansion - New Physical Education Facilities - Playgrounds	2018	1,330,902
							P.S. 345 Total:	\$7,319,349
19	Brooklyn	K346		P.S. 346				
				DS	F0000845615	Educational Enhancements - Educational Enhancements - Accessibility	2018	1,086,756
				DS	F0000799769	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	36,354
			K346	DS	F0000782973	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 346 Total:	\$1,158,373
19	Brooklyn	K798		CESIAH 1	FORO MULLAN	E SCHOOL		
				DS	F0000799761	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	44,743
						CESIAH TORO MULLA	NE SCHOOL Total:	\$44,743
19	Brooklyn	K814		CYPRESS	S HILLS COMM	UNITY SCHOOL		
				DS	F0000799771	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	23,490
						CYPRESS HILLS COMMUNI	TY SCHOOL Total:	\$23,490

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
19	Brooklyn	K848		P.S. 149 A	NNEX			
				DSF	-0000807608	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	214,734
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 149 ANNEX Total:	\$214,734
20	Brooklyn	K048		P.S. 48				
				DSF	-0000778562	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescen	2015 t	777,612
			K048	DSF	-0000778569	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	249,880
							P.S. 48 Total:	\$1,027,49

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K062	DS	F0000799861	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DS	F0000802129	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							I.S. 62 Total:	\$190,605
20	Brooklyn	K104		P.S. 104				
			K104	DS	F0000798257	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,513,010
			K104	DS	F0000798260	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
			K104	DS	F0000802628	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	747,684
				DS	F0000798406	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	748,970
			K104	DS	F0000712695	State of Good Repair - System Replacements - Exterior Masonry	2017	4,745,360

District	Borough	Building ID	Org ID	School F	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
			K104	DSF0000	0802631	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2017	1,241,112
			K104	DSF0000	0802630	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	6,805,615
						Other		
			K104	DSF0000	0776039	IP Surveillance Camera Installation	2015	502,217
							P.S. 104 Total:	\$20,531,831
20	Brooklyn	K105		P.S. 105				
			K105	DSF0000	0779335	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	815,329
				DSF0000	0779333	INTERIOR:STRUCTURAL:VAULTS-BUNKERS State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,184,378
			K105	DSF0000	0779340	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	3,256,127

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K105	DS	F0000779337	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	546,487
							P.S. 105 Total:	\$5,802,321
20	Brooklyn	K112		P.S. 112				
				DS	F0000779438	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	555,166
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K112	DS	F0000844158	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	1,499,740
							P.S. 112 Total:	\$2,054,906
20	Brooklyn	K127		P.S. 127				
				DS	F0000798424	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,338,311
				DS	F0000779662	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,231,142
			K127	DS	F0000802993	State of Good Repair - System Replacements - Heating Plant Upgrade	2019	52,679

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING		
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT:FUEL SYSTEMS		
							P.S. 127 Total:	\$5,622,132
20	Brooklyn	K160		P.S. 160				
				DSI	-0000780092	State of Good Repair - Building Upgrade - Flood	2016	507,349
						Elimination		
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	-0000710359	State of Good Repair - System Replacements - Exterior	2016	5,816,318
						Masonry		
						EXTERIOR: Exterior Walls		
				DSI	-0000799784	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	1,268,059
							P.S. 160 Total:	\$7,591,726
20	Brooklyn	K163		P.S. 163				
				DSI	-0000777469	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	89,407
			K748	DSI	-0000803477	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2017	159,628

	- ·	Building	0 ID		D · · / //		FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Tota
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 163 Total:	\$249,035
20	Brooklyn	K164		P.S. 164				
				DSF	0000798394	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,061,634
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 164 Total:	\$1,061,634
20	Brooklyn	K170		P.S. 170				
				DSF	0000799800	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	132,895
			K170	DSF	0000845579	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	58,253
			K170	DSF	0000845580	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,569
							P.S. 170 Total:	\$346,717
20	Brooklyn	K176		D 8 176				

20 Brooklyn K176 **P.S. 176**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
				DSF	0000799727	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	41,387
							P.S. 176 Total:	\$41,387
20	Brooklyn	K179		P.S. 179				
			K179		F0000803746	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016 P.S. 179 Total:	101,35 \$101,35
20	Brooklyn	K180		P.S. 180				
				DSF	0000799724	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	44,74
			K180	DSF	F0000803764	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	304,05
							P.S. 180 Total:	\$348,79

20 Brooklyn K186 **P.S. 186**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000777473	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	127,946
				DS	F0000758018	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,795,898
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DS	F0000780537	State of Good Repair - System Replacements - Heating <i>Plant Upgrade</i> Ventilation	2015	126,119
						VENTILATION:EXHAUST FAN VENTILATION:SUPPLY FAN		
							P.S. 186 Total:	\$2,049,963
20	Brooklyn	K192		P.S. 192				
				DS	F0000780632	State of Good Repair - Building Upgrade - Flood Elimination	2016	583,022
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000798397	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	913,692
				DS	F0000780635	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY	2016	3,091,050

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000780634	State of Good Repair - System Replacements - Parapets	2016	2,808,764
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				DS	F0000800109	State of Good Repair - System Replacements - Roofs	2016	639,214
						EXTERIOR:ROOFING:Roofing		
			K192	DS	F0000780636	State of Good Repair - System Replacements - Toilets-Students	2016	483,887
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 192 Total:	\$8,519,629
20	Brooklyn	K200		P.S. 200				
				DS	F0000780804	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	968,314
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 200 Total:	\$968.314

P.S. 200 Total: \$968,314

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
20	Brooklyn	K201		I.S. 201				
				DS	F0000780828	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,215,134
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 201 Total:	\$1,215,134
20	Brooklyn	K204		P.S. 204				
				DS	F0000799545	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	287,803
				DS	F0000799729	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	63,731
				DS	F0000799801	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	91,364
							P.S. 204 Total:	\$442,898
20	Brooklyn	K205		P.S. 205				
				DS	F0000799546	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	217,923
							P.S. 205 Total:	\$217,923
20	Brooklyn	K220		I.S. 220				
	-			DS	F0000781208	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2016	3,350,936

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent		
							I.S. 220 Total:	\$3,350,936
20	Brooklyn	K223		I.S. 223	3			
				ſ	DSF0000758723	Educational Enhancements - Educational Enhancements - Science Lab Upgrades CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2018	2,158,489
			K223	[DSF0000821911	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2017	242,965
			K223	Γ	DSF0000865735	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 223 Total:	\$2,651,454
20	Brooklyn	K227		I.S. 227				
				DSF	0000781344	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	1,365,088
						Other		
			K227	DSF	0000776045	IP Surveillance Camera Installation	2015	545,770
							I.S. 227 Total:	\$1,910,858
20	Brooklyn	K229		P.S. 229				
				DSF	0000799552	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	113,172
				DSF	0000799730	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2015	39,710
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	F0000800137	State of Good Repair - System Replacements - Domestic Piping	2015	5,286,184
							P.S. 229 Total:	\$5,439,066
20	Brooklyn	K247		P.S. 247				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000781696	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	935,206
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 247 Total:	\$935,206
20	Brooklyn	K259		I.S. 259				
			K259	DS	F0000798278	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2018	4,513,010
						HEATING PLANT:BOILER SYSTEM		
			K259	DS	F0000798281	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
						CLIMATE CONTROL SYSTEM		
				DS	F0000798415	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	822,761
					F0000781917	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	0.052.945
				05	FUUUU781917	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2016	9,052,845

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000805209	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	2,992,443
				DS	F0000821683	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	1,895,876
				DS	F0000821729	State of Good Repair - System Replacements - Toilets-Students	2016	215,983
						FIXTURES:STUDENT:Toilet	I.S. 259 Total:	\$20,720,781
20	Brooklyn	K314		P.S. 314				<i>\</i> 20,120,101
				DS	F0000844724	Educational Enhancements - Educational Enhancements - Accessibility	2018	65,994
				DS	F0000799734	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	94,660
				DS	F0000798566	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	4,558,994
				DS	F0000799803	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
				DS	F0000806033	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,806
			K503	DS	F0000828341	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	132,377

District	Borough	Building ID	Org ID	School Project #	[#] Description	FY - Construction Start	Total
					Ventilation		
					AIR CONDITIONING: Chilled Water System: Central		
					Station Air Handler		
					MOTOR CONTROL CENTER		
					MOTOR STARTER/CONTACTOR		
					VENTILATION: Exhaust Fan		
					VENTILATION:Heating And Ventilating Unit		
					VENTILATION:Metal Ductwork		
			K503	DSF0000844105		2018	77,777
					Plant Upgrade		
					HEATING PLANT:Boiler System		
				DSF0000801066		2015	495,970
					EXTERIOR:PARAPETS		
				DSF0000782731	State of Good Repair - System Replacements - Roofs	2015	788,448
					EXTERIOR:ROOFING:Roofing		
			K503	DSF0000806034		2016	202,702
					Toilets-Students		
					FIXTURES:STUDENT:Lavatory/Sink		
						P.S. 314 Total:	\$6,571,034
20	Brooklyn	K331		P.S./I.S. 30 MARY WHI	TE OVINGTON		
				DSF0000844721	Educational Enhancements - Educational	2018	88,414
					Enhancements - Accessibility		
					P.S./I.S. 30 MARY WHITE	OVINGTON Total:	\$88,414
20	Brooklyn	K486		I.S. 187			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000783643	State of Good Repair - Building Upgrade - Lighting	2016	1,030,496
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			1/107		F00000004F0	SPACE:LIGHTING:Lighting Fixture - Incandescent	2010	054 054
			K187	DSI	F0000822150	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			K187	DS	F0000776050	IP Surveillance Camera Installation	2015	553,437
							I.S. 187 Total:	\$1,835,284
20	Brooklyn	K807		P.S./ I.S. 1	163			
				DS	F0000800140	State of Good Repair - System Replacements - Domestic Piping	2015	6,075,531
							P.S./ I.S. 163 Total:	\$6,075,531
20	Brooklyn	K940		I.S. 30				
				DS	F0000798402	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	301,714

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K030	DSI	-0000799841	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							I.S. 30 Total:	\$336,953
20	Brooklyn	K971		P.S. 971				
				DSI	-0000799739	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	18,456
							P.S. 971 Total:	\$18,456
21	Brooklyn	K043		I.S. 98				
				DSI	-0000799432	State of Good Repair - Building Upgrade - Climate Control	2015	1,892,838
				DSI	-0000778487	State of Good Repair - Building Upgrade - Flood Elimination	2015	5,037,459
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	-0000799431	State of Good Repair - Building Upgrade - Interior Spaces	2015	3,305,505
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
				DSI	-0000778485	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,963,275
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	-0000799906	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	2,571,322
				DSI	70000799458	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Stage:Stage	2015	447,765
				DSI	-0000821587	State of Good Repair - System Replacements - Auditorium Upgrade	2015	34,204
				DSI	-0000778489	INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING	2015	11,897,526

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799796	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			K098	DS	F0000799874	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
			K098	DS	F0000822141	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351
							I.S. 98 Total:	\$27,515,790
21	21 Brooklyn	K090		P.S. 90				
				DS	F0000756589	State of Good Repair - Building Upgrade - Climate Control	2015	1,092,474
						CLIMATE CONTROL SYSTEM		
				DS	F0000777684	State of Good Repair - Building Upgrade - Flood Elimination	2015	5,141,689
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000777685	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	1,569,653
				DS	F0000756596	State of Good Repair - System Replacements - Electrical Systems	2015	1,548,880

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		
				DSF	F0000756597	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	5,864,338
				DSF	F0000779077	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2015	354,686
			K090	DSF	-0000799875	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DSF	-0000779064	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,282,232
			K090	DSF	F0000823654	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 90 Total:	\$18,048,819
21	Brooklyn	K095		P.S. 95				
				DSF	0000779167	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSF	0000779172	State of Good Repair - System Replacements - Exterior Masonry	2015	3,005,959
						EXTERIOR:AREAWAY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				SCA	0000026515	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	2,455,971
				DSF	0000779171	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,137,270
				DSF	-0000802497	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	251,351
			K095	DSF	F0000822143	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			K095	DS	F0000776038	IP Surveillance Camera Installation	2015	583,827
							P.S. 95 Total:	\$8,962,756
21	Brooklyn	K096		I.S. 96				
			K096	DS	F0000844695	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	604,000
			K096	DS	F0000821754	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	424,102
				DS	F0000799798	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	132,895
							I.S. 96 Total:	\$1,160,997
21	Brooklyn	K097		P.S. 97				
				DS	F0000777461	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	85,670
			K097	DS	F0000799391	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,500,000
			K097	DS	F0000779204	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,277,027
				DS	F0000799799	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306

District	Borough	Building ID	Org ID	Schoo	I Project #	Description	FY - Construction Start	Total
			K097	I	DSF0000802533	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	202,702
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 97 Total:	\$6,144,705
21	Brooklyn	K099		P.S. 99)			
				I	DSF0000779245	Safety and Security - Safety and Security - Safety Systems EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT	2015	223,534
				I	DSF0000756759	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	2,022,668
				I	DSF0000779234	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	3,881,202
			K099	I	DSF0000845631	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	939,133
			K099	I	DSF0000822144	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2015	275,122

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 99 Total:	\$7,341,659
21	Brooklyn	K100		P.S. 100				
	-			DSF	0000799688	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	78,441
				DSF	0000802577	State of Good Repair - System Replacements - Toilets-Students	2015	260,810
						FIXTURES:STUDENT:Toilet		
							P.S. 100 Total:	\$339,251
21	Brooklyn	K101		P.S. 101				
				DSF	0000732197	State of Good Repair - Building Upgrade - Flood Elimination	2015	6,404,994
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	0000799540	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	105,537
			K101	DSF	0000777444	State of Good Repair - System Replacements - Exterior Masonry	2015	7,962,769
			K101	DSF	0000777442	State of Good Repair - System Replacements - Parapets	2015	248,186
			K101	DSF	0000777443	State of Good Repair - System Replacements - Roofs	2015	1,475,639
							P.S. 101 Total:	\$16,197,125
21	Brooklyn	K121		P.S. 121				
				DSF	0000799725	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	16,220

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 121 Total:	\$16,220
21	Brooklyn	K128		P.S. 128 (1	TANDEM BROO	OKLYN STUDIO)		
				DSF	0000777463	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	43,676
				DSF	-0000800301	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2016	1,207,210
			K128	DSF	0000822174	State of Good Repair - System Replacements - Exterior Masonry	2018	1,062,547
			K128	DSF	0000822175	State of Good Repair - System Replacements - Windows	2018	1,716,742
						P.S. 128 (TANDEM BROOKI	YN STUDIO) Total:	\$4,030,175
21	Brooklyn	K153		P.S. 153				
			K153	DSF	0000822147	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
							P.S. 153 Total:	\$251,351
21	Brooklyn	K177		P.S. 177				
				DSF	0000757861	State of Good Repair - System Replacements - Exterior Masonry	2015	4,942,020
						EXTERIOR: EXTERIOR WALLS		
							P.S. 177 Total:	\$4,942,020
21	Brooklyn	K188		P.S. 188				

FY -

						FT -	
	Building					Construction	
Borough	ID	Org ID	School	Project #	Description	Start	Total
		K188	DSF	F0000780542	State of Good Repair - Building Upgrade - Climate Control	2015	1,111,120
					CLIMATE CONTROL SYSTEM		
		K188	DSF	-0000780545	State of Good Repair - Building Upgrade - Flood Elimination	2015	5,437,284
					DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					INTERIOR:STRUCTURAL:FOUNDATION WALLS		
		K188	DSF	-0000780563	State of Good Repair - Building Upgrade - Interior	2015	1,525,080
					INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
			DSF	-0000780543	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	1,874,151
		K188	DSF	F0000780550	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,160,005
	Borough	•	Borough ID Org ID K188 K188 K188	Borough ID Org ID School K188 DSI K188 DSI K188 DSI K188 DSI K188 DSI K188 DSI Borough K188 Borough K188 Borough K188 Borough K188 Borough Borough Borough K188 Borough Borough Borough Borough <td< td=""><td>Borough ID Org ID School Project # K188 DSF0000780542 K188 DSF0000780545 K188 DSF0000780545 K188 DSF0000780545 K188 DSF0000780545 State State State K188 DSF0000780545 State State K188 DSF0000780563 State</td><td>Borough ID Org ID School Project # Description K188 DSF0000780542 State of Good Repair - Building Upgrade - Climate Control Climate CONTROL SYSTEM K188 DSF0000780542 State of Good Repair - Building Upgrade - Flood Elimination DRAINWASTE/VENT AND STORM SYSTEM:SUMP PUMP K188 DSF0000780563 State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:STRUCTURAL:FOUNDATION WALLS K188 DSF0000780563 State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Colling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR DSF0000780543 State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM K188 DSF0000780550 State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH</td><td>BuildingUOrg IDOrg IDOrg IDProject #DescriptionStartBoroughIDOrg IDStoolPoject #State of Good Repair - Building Upgrade - Climate Control2015Climate Control SYSTEMCLIMATE CONTROL SYSTEMCLIMATE CONTROL SYSTEM2015Climate Control SYSTEMDSF0000780545State of Good Repair - Building Upgrade - Flood Elimination2015DRAINWASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLSDSF0000780563State of Good Repair - Building Upgrade - Interior Spaces2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)State of Good Repair - Building Upgrade - Interior SPACES:Door(s)2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)SPACES:Door(s)INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)2015INTERIOR:STAIRS/RAMPS: INTERIORDSF0000780543State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORFIRE ALARM SYSTEM2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems</td></td<>	Borough ID Org ID School Project # K188 DSF0000780542 K188 DSF0000780545 K188 DSF0000780545 K188 DSF0000780545 K188 DSF0000780545 State State State K188 DSF0000780545 State State K188 DSF0000780563 State	Borough ID Org ID School Project # Description K188 DSF0000780542 State of Good Repair - Building Upgrade - Climate Control Climate CONTROL SYSTEM K188 DSF0000780542 State of Good Repair - Building Upgrade - Flood Elimination DRAINWASTE/VENT AND STORM SYSTEM:SUMP PUMP K188 DSF0000780563 State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:STRUCTURAL:FOUNDATION WALLS K188 DSF0000780563 State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Colling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR DSF0000780543 State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM K188 DSF0000780550 State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	BuildingUOrg IDOrg IDOrg IDProject #DescriptionStartBoroughIDOrg IDStoolPoject #State of Good Repair - Building Upgrade - Climate Control2015Climate Control SYSTEMCLIMATE CONTROL SYSTEMCLIMATE CONTROL SYSTEM2015Climate Control SYSTEMDSF0000780545State of Good Repair - Building Upgrade - Flood Elimination2015DRAINWASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLSDSF0000780563State of Good Repair - Building Upgrade - Interior Spaces2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)State of Good Repair - Building Upgrade - Interior SPACES:Door(s)2015INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)SPACES:Door(s)INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)2015INTERIOR:STAIRS/RAMPS: INTERIORDSF0000780543State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORFIRE ALARM SYSTEM2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems2015INTERIOR:STAIRS/RAMPS: INTERIORState of Good Repair - System Replacements - Electrical Systems

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000780560	<i>State of Good Repair - System Replacements - Heating</i> <i>Plant Upgrade</i> Ventilation	2015	1,692,762
						VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
			K188	DS	F0000798612	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	4,574,714
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
							P.S. 188 Total:	\$18,375,116
21	Brooklyn	K199		P.S. 199				
				DS	F0000780783	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	945,916
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						or AGE.EIGHTING.Eighting Fixture - Fidorescent	P.S. 199 Total:	\$945,916
21	Brooklyn	K212		P.S. 212				
	·		K212	DS	F0000804352	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS	2016	5,540,552
			K212	DS	F0000804351	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING	2016	1,616,004

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
			K212	DS	F0000804350	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,054,645
			K212	DS	F0000822685	State of Good Repair - System Replacements - Windows	2019	6,640,839
						EXTERIOR:WINDOWS	P.S. 212 Total:	\$15,852,040
21	Brooklyn	K215		P.S. 215			P.S. 212 Total.	φ13,032,040
				DS	F0000798398	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	808,426
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 215 Total:	\$808,426
21	Brooklyn	K216		P.S. 216				
				DS	F0000781136	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN	2016	374,487

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
				DSF	-0000781122	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2016	1,498,275
							P.S. 216 Total:	\$1,872,762
21	Brooklyn	K225		P.S. 225				
			K225	DSF	-0000735855	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	1,727,398
				DSF	-0000799551	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	460,877
			K225	DSF	-0000758755	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2017	3,424,686
			K225	DSF	-0000758754	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	4,054,372
			K225	DSF	-0000775945	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,961,803

		Devilation of					FY -	
District	Borough	Building ID	Org ID	School	Project #	Description	Construction Start	Total
							P.S. 225 Total:	\$11,629,136
21	Brooklyn	K226		P.S. 226				
				DSF	0000777475	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	76,054
							P.S. 226 Total:	\$76,054
21	Brooklyn	K228		I.S. 228				
				DSF	0000821597	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DSF	0000844008	State of Good Repair - System Replacements - Domestic Piping	2018	186,253
			K228	DSF	0000804663	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:TOIlet		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 228 Total:	\$820,840
21	Brooklyn	K238		P.S. 238				
				DSF	0000799876	State of Good Repair - System Replacements - Exterior Masonry	2018	4,458,576
				DSF	0000804821	State of Good Repair - System Replacements - Parapets	2018	802,718

Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					EXTERIOR:PARAPETS		
		K238	DS	SF0000804826	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
					FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting		
					Fixture - Fluorescent		
						P.S. 238 Total:	\$5,420,922
Brooklyn	K239		I.S. 239				
		K239	DS	F0000781545	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP	2015	4,580,129
					PUMP		
					INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			De	5F0000798613	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	2,670,850
		Borough ID	Borough ID Org ID K238 Brooklyn K239	Borough ID Org ID School K238 DS Brooklyn K239 I.S. 239 K239 DS	Borough ID Org ID School Project # K238 DSF0000804826 Brooklyn K239 I.S. 239	Borough ID Org ID School Project # Description K238 DSF0000804826 EXTERIOR:PARAPETS State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:URAL:STUDENT:LightING:Lighting FIXTURES:STUDENT:LightING:Lighting Brooklyn K239 I.S. 239 K239 DSF0000781545 State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS DSF0000798613 State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Celling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN	Building BoroughOrg IDOrg IDSchoolProject #DescriptionConstruction StateBoroughIDOrg IDSchoolProject #DescriptionSchoolSchoolSchoolK238DSF000804826State of Good Repair - System Replacements - Toilets-Students2017FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Ional TOILET ROOM - STUDENT:Lighting Fixture - FluorescentP.S. 238BrooklynK239IS. 239State of Good Repair - Building Upgrade - Flood Elimination2015DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS2015DSF0000798613State of Good Repair - Building Upgrade - Interior Spaces2015INTERIOR:STRUCTURAL:VAULTS-BUNKERS SPACES:Celling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Colling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls2015

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K239	DS	F0000798614	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	566,877
			K239	DS	F0000781544	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2015	7,108,392
			K239	DS	F0000781551	INTERIOR:STRUCTURAL:FLOOR STRUCTURE State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	2015	2,849,820
			K239	DS	F0000798615	SWITCHBOARD State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	7,934,616
				DS	F0000804851	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	567,138
							I.S. 239 Total:	\$26,277,822
21	Brooklyn	K253		P.S. 253				
			K253	DS	F0000781795	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1,562,796

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K253	DSI	F0000798623	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	4,026,063
				DS	F0000781804	State of Good Repair - System Replacements - Paved Area-Blacktop	2015	2,175,809
						SITE:Drainage System for Asphalt SITE:PAVING - STUDENT NON-USE:Asphalt SITE:PAVING - STUDENT USE:Asphalt		
							P.S. 253 Total:	\$7,764,668
21	Brooklyn	K281		I.S. 281				
				DS	F0000821589	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	411,964
				DSI	F0000799408	State of Good Repair - Building Upgrade - Elevators and Escalators CONVEYING:ASH HOIST CONVEYING:SIDEWALK ELEVATOR	2015	1,124,438
				DSI	F0000805551	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	355,875
				DS	F0000799694	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	168,902
				DSI	F0000805550	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems AUXILIARY SIGNAL/BELL SYSTEM	2015	1,693,542

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K281	DS	F0000821625	FIRE ALARM SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
						Other		
			K281	DS	F0000776047	IP Surveillance Camera Installation	2015	676,885
							I.S. 281 Total:	\$4,964,842
21	Brooklyn	K288		P.S. 288				
				DS	F0000782368	State of Good Repair - Building Upgrade - Climate Control	2015	984,183
						CLIMATE CONTROL SYSTEM		
				DS	F0000799415	State of Good Repair - Building Upgrade - Flood Elimination	2015	2,538,164
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799413	State of Good Repair - Building Upgrade - Interior Spaces	2015	2,385,133
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799414	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD	2015	1,215,403
				DS	F0000782372	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	9,903,172
			K288	DS	F0000799834	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
			K288	DS	F0000805675	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,628
							P.S. 288 Total:	\$17,220,922
21	Brooklyn	K303	K303	I.S. 303 DS	F0000822168	Educational Enhancements - Educational Enhancements - Library Upgrades	2016	437,111

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:LIBRARY:Ceiling INTERIOR:LIBRARY:Walls		
				DS	SF0000759997	State of Good Repair - Building Upgrade - Climate Control	2015	1,335,442
						CLIMATE CONTROL SYSTEM		
				DS	SF0000777693	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,453,198
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	SF0000777694	State of Good Repair - Building Upgrade - Interior Spaces	2015	1,889,044
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DS	F0000799695	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	664,006
				DS	SF0000760001	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,152,855
				DS	SF0000760002	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	9,686,410

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000782591	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	682,433
						MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR		
			K303	DS	F0000799862	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							I.S. 303 Total:	\$19,335,738
21	Brooklyn	K329		P.S. 329				
				DS	F0000799460	State of Good Repair - Building Upgrade - Air Conditioning Retrofit	2015	1,849,613
				DS	F0000799430	State of Good Repair - Building Upgrade - Climate Control	2015	932,187
				DS	F0000799456	State of Good Repair - Building Upgrade - Elevators and Escalators	2015	360,341
						CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR		
				DS	F0000799429	State of Good Repair - Building Upgrade - Flood Elimination	2015	11,013,027

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799425	State of Good Repair - Building Upgrade - Interior Spaces	2015	2,658,155
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
				DS	F0000806200	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,451,995
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000799923	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment SITE:PLAYGROUNDS:Fence	2015	724,814
						SITE:PLAYGROUNDS:Play Equipment SITE:PLAYGROUNDS:Safety Surfacing SITE:SEATING:Benches		
				DS	F0000782913	State of Good Repair - System Replacements - Domestic Piping Waste System	2015	1,851,432

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE		
						TRAP		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:INTERIOR FLOOR DRAIN		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE / WASTE PIPING		
						DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
				DSF	0000782900	State of Good Repair - System Replacements -	2015	1,867,928
						Electrical Systems		
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
				DSF	0000782901	State of Good Repair - System Replacements - Heating	2015	7,707,390
						Plant Upgrade		
						GAS SERVICE: GAS DISTRIBUTION PIPING		
						GAS SERVICE: GAS METER ROOM VENT		
						HEATING PLANT: FUEL SYSTEMS		
				DSF	0000782912	State of Good Repair - System Replacements - Heating	2015	720,655
						Plant Upgrade		
						Ventilation		
						AIR CONDITIONING: CHILLED WATER		
						SYSTEM:Central Station Air Handler		
						AIR CONDITIONING:CHILLED WATER SYSTEM:Fan		
						Coil Unit		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:UNIT VENTILATOR		
			K329	DS	F0000799840	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
			K329	DS	F0000806207	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,628
22	Brooklyn	K014		I.S. 14			P.S. 329 Total:	\$31,332,404
22	ыоокіуп	K014	K014	DSI	F0000821955 F0000798243	Room Conversions/Partitioning State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS	2016 2017	2,824,151 9,475,419

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000778032	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	2,871,286
			K014	DS	F0000801384	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2017	719,588
				DS	F0000799790	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	58,183
			K014	DS	F0000801393	State of Good Repair - System Replacements - Auditorium Upgrade AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent AUDITORIUM:THEATER LIGHTING SYSTEM:Dimming System AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Ceiling INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains INTERIOR:AUDITORIUM:Walls	2019	95,762

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:AUDITORIUM:Window Curtains/Shades/Blinds		
				DS	F0000821945	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	43,033
			K014	DS	F0000823943	State of Good Repair - System Replacements - Domestic Piping Waste System	2018	160,095
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
				DS	F0000801388	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2016	189,258
							I.S. 14 Total:	\$16,436,775
22	Brooklyn	K052		P.S. 52				
				DS	F0000798417	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,277,027
				DS	F0000756171	State of Good Repair - System Replacements - Exterior Masonry	2015	2,027,765
				SC	A0000025073	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets	2015	4,609,812
				DS	F0000756169	State of Good Repair - System Replacements - Roofs	2015	1,032,954

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
	-					EXTERIOR:ROOFING:Roofing		
				DO		EXTERIOR:ROOFING:Specialties	0040	470.000
				DSI	F0000801977	State of Good Repair - System Replacements - Toilets-Students	2016	178,920
						FIXTURES:STUDENT:Toilet		
						Other		
			K052	DSI	F0000776036	IP Surveillance Camera Installation	2015	570,246
							P.S. 52 Total:	\$9,696,724
22	Brooklyn	K078		I.S. 78				
			K078	DSI	F0000845583	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	126,000
			K078	DSI	F0000778955	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,324,622
			K078	DSI	F0000821898	State of Good Repair - System Replacements - Auditorium Upgrade	2016	82,773
			K078	DSI	F0000822142	INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging State of Good Repair - System Replacements - Toilets-Students	2016	283,231
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 78 Total:	\$1.816.626

I.S. 78 Total: \$1,816,626

FY -

						FT -		
	Building						Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Tota
22	Brooklyn	K119		P.S. 119				
			K119	DSF	0000798251	State of Good Repair - Building Upgrade - Boiler Conversion	2017	7,032,46
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000779550	State of Good Repair - Building Upgrade - Climate Control	2017	1,269,28
						CLIMATE CONTROL SYSTEM		
				DSF	0000757056	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	892,93
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DSF	0000757060	State of Good Repair - System Replacements - Domestic Piping	2015	633,17
						DOMESTIC WATER SYSTEM		
			K119	DSF	0000802881	State of Good Repair - System Replacements - Toilets-Students	2016	101,35
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							P.S. 119 Total:	\$9,929,21
22	Brooklyn	K139		P.S. 139				
	2			DSF	0000779810	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,045,948

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K139	DSF	0000803155	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 139 Total:	\$1,205,576
22	Brooklyn	K152		P.S. 152				
				DSF	0000799726	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	49,218
				DSF	0000803297	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2019	1,661,697
						AUXILIARY SIGNAL/BELL SYSTEM		
						PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY		
			K315	DSF	0000822188	State of Good Repair - Rehabilitation of Physical	2017	1,622,117
						Education Facilities - Playground Redevelopment		
								¢0,000,000

P.S. 152 Total: \$3,333,032

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
22	Brooklyn	K193		P.S. 193				
			K193	DSI	F0000821910	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,694,341
			K193	DSF	F0000803976	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
							P.S. 193 Total:	\$1,853,969
22	Brooklyn	K194		P.S. 194				
			K194	DSI	-0000799529	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	1,205,629
				SC/	40000026654	State of Good Repair - System Replacements - Exterior Masonry	2016	1,415,978
				DSI	-0000780676	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	1,604,566
				DSI	=0000799794	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,490,493
				DSI	-0000799793	State of Good Repair - System Replacements - Windows	2016	521,756
						EXTERIOR:WINDOWS		

P.S. 194 Total: \$7,238,422

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
22	Brooklyn	K195		P.S. 195				
				DSF	0000780694	State of Good Repair - Building Upgrade - Climate Control	2015	703,648
						CLIMATE CONTROL SYSTEM		
				DSF	0000799411	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,808,250
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					-0000700440	INTERIOR:STRUCTURAL:FOUNDATION WALLS	0045	004.000
				DSF	0000799410	State of Good Repair - Building Upgrade - Interior Spaces	2015	334,836
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
				DSF	0000780696	State of Good Repair - Building Upgrade - Lighting	2016	722,217
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000780701	State of Good Repair - System Replacements - Electrical Systems	2015	1,658,818

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						LIGHTNING PROTECTION PANEL BOARD SERVICE SWITCH SWITCHBOARD		
				DSI	F0000800314	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2015	1,257,857
				DSI	F0000800325	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING	2015	4,039,724
							P.S. 195 Total:	\$12,525,350
22	Brooklyn	K197		P.S. 197				
				DSI	F0000799544	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	207,099
							P.S. 197 Total:	\$207,099
22	Brooklyn	K198		P.S. 198				
				DSI	F0000735361	State of Good Repair - Building Upgrade - Elevators and Escalators CONVEYING:ELEVATORS	2015	1,180,927
			K198	DS	F0000799532	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,616,808
				DSI	F0000758236	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY	2015	2,893,375

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS		
				DS	F0000780761	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	749,161
				DS	F0000780760	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,580,979
						EXTERIOR:ROOFING:Specialties		
				DS	F0000758235	State of Good Repair - System Replacements - Windows	2015	2,226,724
						EXTERIOR:WINDOWS		
							P.S. 198 Total:	\$10,247,974
22	Brooklyn	K203		P.S. 203				
				DS	F0000799728	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	40,269
							P.S. 203 Total:	\$40,269
22	Brooklyn	K206		P.S. 206				
			K206	DS	F0000735507	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,324,096
						FIRE ALARM SYSTEM		
							P.S. 206 Total:	\$1,324,096
22	Brooklyn	K207		P.S. 207				
				DS	F0000777474	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	102,818

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000780964	State of Good Repair - System Replacements - Domestic Piping Waste System	2019	396,667
						DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
			K207	DS	F0000804258	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 207 Total:	\$600,836
22	Brooklyn	K217		P.S. 217				
			K217	DS	F0000804446	State of Good Repair - Building Upgrade - Flood Elimination	2016	555,867
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799549	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	134,913
			K217	DS	F0000758598	State of Good Repair - System Replacements - Exterior Masonry	2015	2,312,747

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR: EXTERIOR WALLS		
			K217	DS	F0000801043	State of Good Repair - System Replacements - Kitchen Areas	2015	34,616
						INTERIOR:KITCHEN/WARMING PANTRY:Ceiling		
			K217	DS	F0000781142	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	3,263,273
			K217	DS	F0000781143	State of Good Repair - System Replacements - Windows	2016	6,164,034
						EXTERIOR:WINDOWS		
							P.S. 217 Total:	\$12,465,450
22	Brooklyn	K234		I.S. 234				
				DS	F0000822243	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	31,252
						Other		
			K234	DS	F0000776046	IP Surveillance Camera Installation	2015	626,156
							I.S. 234 Total:	\$657,408
22	Brooklyn	K236		P.S. 236				
			K236	DS	F0000844159	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	3,040,850
							P.S. 236 Total:	\$3,040,850
22	Brooklyn	K240		I.S. 240				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000781566	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,198,508
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K240	DS	F0000804879	State of Good Repair - System Replacements - Auditorium Upgrade	2016	139,067
						INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
				DS	F0000821630	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
							I.S. 240 Total:	\$1,870,811
22	Brooklyn	K251		P.S. 251				
				DS	F0000781763	Safety and Security - Safety and Security - Safety Systems	2015	260,562
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
			K251	DS	F0000798442	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,500,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K251	DS	F0000781746	State of Good Repair - Building Upgrade - Climate Control	2018	1,277,027
						CLIMATE CONTROL SYSTEM		
				DS	F0000805048	State of Good Repair - Building Upgrade - Lighting	2016	1,231,738
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000759195	State of Good Repair - System Replacements - Exterior	2015	2,298,551
						Masonry		
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000759194	State of Good Repair - System Replacements - Parapets	2015	2,285,886
						EXTERIOR:PARAPETS		
				DS	F0000759193	State of Good Repair - System Replacements - Roofs	2015	2,966,305
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
				DS	F0000798646	State of Good Repair - System Replacements -	2015	472,858
						Windows		
						EXTERIOR:WINDOWS		
							P.S. 251 Total:	\$15,292,927
22	Brooklyn	K254		P.S. 254				
	-		K254	DS	F0000781813	State of Good Repair - Building Upgrade - Climate Control	2015	613,490

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
			K254	DS	SF0000781814	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,588,216
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			K254	DS	SF0000798618	State of Good Repair - System Replacements -	2015	138,364
						Electrical Systems		
						GROUNDING SYSTEM PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
				DS	SF0000781824	State of Good Repair - System Replacements - Heating	2016	1,565,287
						Plant Upgrade		
						Ventilation VENTILATION:EXHAUST FAN		
						VENTILATION.EXHAUST FAN		
						VENTILATION:SUPPLY FAN		
						VENTILATION: UNIT VENTILATOR		
			K254	DS	SF0000798617	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	3,939,448
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	SF0000781815	State of Good Repair - System Replacements - Roofs	2016	1,449,217
				2.		EXTERIOR:ROOFING:Roofing		.,,

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000801067	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Specialties	2019	667,382
							P.S. 254 Total:	\$9,961,404
22	Brooklyn	K255	I	P.S. 255				
				DSI	-0000799691	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	144,180
							P.S. 255 Total:	\$144,180
22	Brooklyn	K269		P.S. 269				
	5			DSI	F0000799555	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	789,524
				DSI	-0000736572	State of Good Repair - System Replacements - Exterior Masonry	2015	3,553,375
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DSI	-0000782062	State of Good Repair - System Replacements - Parapets	2015	2,026,703
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				DSI	-0000782061	State of Good Repair - System Replacements - Roofs	2015	2,145,406
						EXTERIOR:ROOFING:Roofing		
							P.S. 269 Total:	\$8,515,008
22	Brooklyn	K277	I	P.S. 277				
				DSI	F0000777478	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	103,889

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798258	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	4,513,010
				DS	F0000798259	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,280,719
			K277	DS	F0000782213	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 277 Total:	\$5,932,857
22	Brooklyn	K278		I.S. 278				
			K278	DS	F0000821903	State of Good Repair - System Replacements - Auditorium Upgrade	2016	101,295
			K278	DS	F0000827876	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump	2018	117,518
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
							I.S. 278 Total:	\$218,813
22	Brooklyn	K312		P.S. 312				
				DS	F0000782718	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	620,787

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			K312	DSI	-0000799863	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	55,949
							P.S. 312 Total:	\$676,736
22	Brooklyn	K395		P.S./I.S. 3	95			
				DSI	-0000799736	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	115,120
			K109	DSI	F0000797530	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	1,837,949
			K109	DSI	F0000801050	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,032,304
			K109	DSI	-0000801049	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,416,380
							P.S./I.S. 395 Total:	\$4,401,753
22	Brooklyn	K776		PS 152 AI				
				DSI	-0000797971	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	889,262

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							PS 152 ANNEX Total:	\$889,262
22	Brooklyn	K849		P.S. 134				
				DSF	0000799576	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	518,223
				DSF	0000807626	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:EXTERIOR WALLS	2015	428,751
				DSF	0000807625	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	s 2015	191,200
				DSF	0000784330	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,044,486
				DSF	0000821635	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	178,783
						Other		
			K134	DSF	0000822060	New/Retrofit Telephone/Intercom Systems	2015	135,928
							P.S. 134 Total:	\$2,497,371
22	Brooklyn	K864		P.S. 361 (0	OLD 89)			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K361	DS	F0000822151	State of Good Repair - System Replacements - Toilets-Students	2015	173,890
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Р	.S. 361 (OLD 89) Total:	\$173,890
22	Brooklyn	K905		DISTRICT	22 ECOLOGY	CENTER		
			KADM	DS	F0000822093	State of Good Repair - System Replacements - Windows	2015	199,546
						EXTERIOR:WINDOWS		
						DISTRICT 22 EC	OLOGY CENTER Total:	\$199,546
22	Brooklyn	K995		LEARNIN	G SUPPORT C	ENTER		
				DS	F0000799740	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	28,524
			K602	DS	F0000799842	State of Good Repair - System Replacements - Heatin Plant Upgrade	g 2015	35,239
						LEARNING SU	PPORT CENTER Total:	\$63,763
23	Brooklyn	K041		P.S. 41				
				DSI	F0000775935	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	10,795,527
				DS	F0000801809	State of Good Repair - System Replacements - Heatin Plant Upgrade	g 2018	245,771

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000822660	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
				DS	F0000801810	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	234,971
							P.S. 41 Total:	\$11,431,635
23	Brooklyn	K055		I.S. 55				
				DS	F0000844720	Educational Enhancements - Educational Enhancements - Accessibility	2017	544,647
							I.S. 55 Total:	\$544,647
23	Brooklyn	K073		P.S. 73				
			K073	DS	F0000821912	State of Good Repair - Building Upgrade - Flood Elimination	2016	762,305
			K073	SC	A0000028933	State of Good Repair - System Replacements - Exterior Masonry	2016	10,034,184
				DS	F0000823570	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,806
			K073	DS	F0000802236	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	440,528
			K073	DS	F0000802235	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	2,640,021

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K073	DS	F0000778918	State of Good Repair - System Replacements -	2015	348,805
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 73 Total:	\$14,300,649
23	Brooklyn	K137		P.S. 137				
				DS	F0000779774	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	554,764
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000821942	State of Good Repair - System Replacements - Exterior Masonry	2019	5,509,368
				DS	F0000843959	State of Good Repair - System Replacements - Roofs	2019	208,644
						EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties		
				DS	F0000803113	State of Good Repair - System Replacements - Toilets-Students	2015	227,181
						FIXTURES:STUDENT:Toilet		
							P.S. 137 Total:	\$6,499,957

P.S. 137 Total: \$6,499,957

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
23	Brooklyn	K150		P.S. 150				
			K150	DSF	-0000843900	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	79,500
				DSF	-0000822242	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2016	38,753
				DSF	-0000822652	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
				DSF	-0000803265	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
			K150	DSF	-0000822129	State of Good Repair - System Replacements - Toilets-Students	2015	371,300
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 150 Total:	\$836,675
23	Brooklyn	K155		P.S. 155				
			K155	DSF	-0000780027	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	189,364

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 155 Total:	\$189,364
23	Brooklyn	K165		P.S. 165				
			K165	DSI	F0000825934	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2017	149,889
				DSI	F0000803510	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	163,847
				DSI	F0000803511	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2016	304,358
			K165	DSI	F0000823663	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal	2016	101,351
						INTERIOR: TOILET ROOMS - STUDENTS		
			K165	DSI	F0000865732	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 165 Total:	\$969,445
23	Brooklyn	K178		P.S. 178				
-	,	-		DSI	F0000844145	Domestic Piping	2018	1,528,035

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain FIXTURES:Student:Sink And Fountain Combo Unit		
			K077	DS	F0000826122	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2018	241,673
				DS	F0000780383	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,152,041
			K077	DS	F0000826128	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2018	1,766,746
				DS	F0000803719	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING	2018	92,805

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			K077	DS	F0000826126	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	262,252
			K077	DS	F0000757881	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	2,707,184
			K077	DS	F0000826127	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2018	2,684,623
			K178	DS	F0000865733	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 178 Total:	\$10,685,359
23	Brooklyn	K183		P.S. 183				
				DS	F0000757961	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2015	9,519,823
				DS	F0000780472	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING	2015	35,810
				DS	F0000822653	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	163,847

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				D	SF0000823584	State of Good Repair - System Replacements - Heating	2016	38,582
						Plant Upgrade		
						GAS SERVICE: GAS DISTRIBUTION PIPING		
						GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT		
						HEATING		
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT: FUEL SYSTEMS		
			K446	D	SF0000865734	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 183 Total:	\$10,008,062
23	Brooklyn	K184		P.S. 184	Ļ			
				D	SF0000777472	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	195,009
				D	SF0000844133	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	51,529
							P.S. 184 Total:	\$246,538
23	Brooklyn	K263		P.S./I.S.	323			
				D	SF0000821624	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			K140	D	SF0000822114	State of Good Repair - System Replacements - Exterior Masonry	2017	1,332,497
						EXTERIOR: AWNINGS AND CANOPIES		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR SOFFITS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			K323	DS	F0000805288	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2018	155,366
			K323	DS	F0000865736	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S./I.S. 323 Total:	\$2,271,099
23	Brooklyn	K271		I.S. 271				
			K522	DS	F0000843916	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	310,139
			K644	DS	F0000843930	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	140,283
			K522	DS	F0000798283	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,513,010

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K522	DS	F0000798285	State of Good Repair - Building Upgrade - Climate Control	2017	1,280,719
			K522	DS	F0000782104	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							I.S. 271 Total:	\$6,279,414
23	Brooklyn	K275		I.S. 275				
			K647	DS	F0000843917	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	51,000
			K518	DS	F0000798457	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,500,000
			K518	DS	F0000798461	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,277,027
			K518	DS	F0000782173	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	55,273
							I.S. 275 Total:	\$5,883,300
23	Brooklyn	K284		P.S. 284				
			K284	DS	F0000827950	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:STAIRS/RAMPS: INTERIOR	2018	347,607

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798400	State of Good Repair - Building Upgrade - Lighting	2015	437,644
						Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K284	DS	F0000822117	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2016	1,446,306
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
							P.S. 284 Total:	\$2,231,557
23	Brooklyn	K298		P.S. 298				
			K298	DS	F0000828138	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	55,106
						GAS SERVICE: Gas Distribution Piping		
						GAS SERVICE:Gas Meter Room Vent		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System HEATING PLANT:Fuel System		
							P.S. 298 Total:	\$55,106
23	Brooklyn	K327		P.S. 327 (TANDEM K396	-D75)		
			K327	DS	F0000782865	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			K396	DS	F0000828470	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	354,180

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000806167	AIR CONDITIONING:Chilled Water System:Backflow Preventer AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller AIR CONDITIONING:Packaged / Rooftop Unit State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal	2016	101,351
						P.S. 327 (TANDEM	K396-D75) Total:	\$490,794
23	Brooklyn	K332		P.S. 332				
			K401	DSF	F0000843914	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	98,500
			K401	DSF	-0000843934	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	216,864
			K332	DSF	-0000782921	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING	2015	35,263

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
				DS	F0000806225	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
							P.S. 332 Total:	\$596,398
23	Brooklyn	K808		LEARNIN	IG SUPPORT C	ENTER		
			K601	DS	F0000844682	Domestic Piping	2017	755,000
						LEARNING SUPPO	RT CENTER Total:	\$755,000
23	Brooklyn	K854 P.S. 178 AX (BED STUY ECC 1)						
			K178	DS	F0000865743	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						P.S. 178 AX (BED S	TUY ECC 1) Total:	\$250,000
32	Brooklyn	K045		P.S. 45				
				DS	F0000798385	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	667,560
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000799742	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	39,710
				DS	F0000801865	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
			K045	DS	F0000778533	State of Good Repair - System Replacements - Toilets-Students	2016	152,812

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 45 Total:	\$1,015,448
32	Brooklyn	K075		P.S. 75				
				DSF	0000778935	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	954,799
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	0000778943	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,810
						HEATING PLANT:BOILER SYSTEM		
							P.S. 75 Total:	\$990,609
32	Brooklyn	K086		P.S. 86				
	·		K086	DSF	0000779033	State of Good Repair - System Replacements - Toilets-Students	2015	641,371
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							P.S. 86 Total:	\$641,371
32	Brooklyn	K106		P.S. 106				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K106	DSI	F0000822136	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	348,286
							P.S. 106 Total:	\$348,286
32	Brooklyn	K111		I.S. 111				
			K347	DS	F0000821837	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	1,159,452
			K347	DSI	F0000843897	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	51,000
			K349	DSI	F0000843898	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	320,544
			K347	DSI	F0000843933	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	196,195
			K347	DS	F0000844736	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	270,000
				DSI	F0000802752	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2017	2,652,871

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:EMERGENCY GAS SHUT-OFF VALVE SCIENCE DEMO ROOM:EMERGENCY SHUT-OFF POWER		
				DSF	-0000821904	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2017	1,159,817
				DSF	0000777462	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	117,773
				DSF	-0000799689	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	291,500
				DSF	0000821628	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
							I.S. 111 Total:	\$6,752,388
32	Brooklyn	K116		P.S. 116				
			K116	DSF	0000798277	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			K116	DSF	-0000779508	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799541	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	91,058
				DS	F0000799743	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	17,338
							P.S. 116 Total:	\$6,096,843
32	Brooklyn	K123		P.S. 123				
				DS	F0000757105	State of Good Repair - Building Upgrade - Flood Elimination	2015	177,496
				DS	F0000799744	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - Building Upgrade - Lighting Fixtures	2015	31,320
				DS	F0000757104	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	1,309,338
				DS	F0000757108	PUBLIC ADDRESS SYSTEM State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	4,317,547
				DS	F0000757112	State of Good Repair - System Replacements - Floors INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2015	1,331,918
				DS	F0000779611	State of Good Repair - System Replacements - Paved Area-Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways	2015	1,346,407

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000753103	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	5,260,352
						Other		
			K123	DS	F0000776040	IP Surveillance Camera Installation	2015	572,190
							P.S. 123 Total:	\$14,346,568
32	Brooklyn	K145		P.S. 145				
				DS	F0000844723	Educational Enhancements - Educational Enhancements - Accessibility	2018	79,916
				DS	F0000779855	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	39,150
				DS	F0000779864	State of Good Repair - System Replacements - Floors INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish	2016	393,204
			K145	DS	F0000822127	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2015	205,220
			K145	DS	F0000865731	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 145 Total:	\$967,490
32	Brooklyn	K151		P.S. 151				
				DS	F0000803286	State of Good Repair - System Replacements - Toilets-Students	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
						Fluorescent		
							P.S. 151 Total:	\$159,628
32	Brooklyn	K162		I.S. 162				
			DSF0000780130			State of Good Repair - Building Upgrade - Lighting Fixtures	2016	847,258
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 162 Total:	\$847,258
32	Brooklyn	K291		I.S. 291				
			K291	DS	F0000844680	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,919,517
				DS	F0000777479	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	255,312
				DS	F0000798386	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	490,997
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000805726	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							I.S. 291 Total:	\$3,825,454
32	Brooklyn	K296		I.S. 296				
			K296	DS	F0000843931	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	108,432
							I.S. 296 Total:	\$108,432
32	Brooklyn	K299		P.S. 299				
			K299	DS	F0000865737	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 299 Total:	\$250,000
32	Brooklyn	K376		P.S. 3764	N N			
				DS	F0000823571	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
						HEATING PLANT:BOILER SYSTEM		
							P.S. 376A Total:	\$74,806

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
32	Brooklyn	K377		P.S. 377				
				DSI	F0000799759	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	38,032
				DSI	F0000821709	State of Good Repair - System Replacements - Exterior Masonry	2016	157,809
						EXTERIOR: EXTERIOR WALLS		
				DSI	F0000783062	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	1,005,616
				DSI	F0000806361	State of Good Repair - System Replacements - Roofs	2016	2,627,659
						EXTERIOR:ROOFING:Roofing		
				DSI	F0000783063	State of Good Repair - System Replacements - Windows	2016	2,796,339
						EXTERIOR: WINDOWS		
							P.S. 377 Total:	\$6,625,455
32	Brooklyn	K383		I.S. 383				
	-			DSI	F0000844725	Educational Enhancements - Educational	2018	85,004
						Enhancements - Accessibility		
							I.S. 383 Total:	\$85,004
32	Brooklyn	K384		P.S. 384				
				DSI	F0000777481	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	184,094
				DSI	F0000783126	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,263,982

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 384 Total:	\$1,448,076
32	Brooklyn	K865		SECOND C	OPPORTUNITY	' SCHOOL		
				DSF	0000776207	Safety and Security - Safety and Security - Code Compliance	2019	8,152,314
				DSF	0000784416	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	982,181
				DSF	0000807731	State of Good Repair - System Replacements - HeatingPlant UpgradeGAS SERVICE:GAS DISTRIBUTION PIPINGGAS SERVICE:GAS METER ROOM EXHAUST FANGAS SERVICE:GAS METER ROOM VENTGAS SERVICE:GAS PRESSURE BOOSTERHEATINGHEATING PLANT:BOILER AUXILIARIESHEATING PLANT:BOILER SYSTEMHEATING PLANT:FUEL SYSTEMS	2016	35,119

District	Borough	Building ID	Org ID Schoo	I Project #	Description HEATING:HYDRONIC HEATING:Hydronic Hot Water	FY - Construction Start	Total
					Distribution: Piping, Pumps and Auxiliaries		
					SECOND OPPORTUNIT	Y SCHOOL Total:	\$9,169,614
33K	Brooklyn	K801	CENT	HEADQTRS (65 C	OURT)		
			I	DSF0000784115	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	74,978
				DSF0000784127	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation AIR CONDITIONING:CHILLED WATER SYSTEM:Central Station Air Handler AIR CONDITIONING:CHILLED WATER SYSTEM:Fan Coil Unit MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK	2015	114,611,897
					CENT HEADQTRS (65 COURT) Total:	\$114,686,875
33K	Brooklyn	K802		HEADQTRS (131 DSF0000798423	LIV) State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,018,850

District	Borough	Building ID	Org ID	School	Project #	Description CLASSROOM/CORRIDOR/ADMINISTRATIVE	FY - Construction Start	Total
						SPACE:LIGHTING:Lighting Fixture - Incandes	cent	
						CENT F	IEADQTRS (131 LIV) Total:	\$1,018,850
33K	Brooklyn	K986		DIV. OF IN	STR. & INFO	ТЕСН.		
				DSF	0000799766	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	44,743
						DIV. OF INS	STR. & INFO. TECH. Total:	\$44,743
75K	Brooklyn	K085		P.S. 753 (C	OLD P85/STER	LING HS)		
				DSF	0000798249	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	6,879,031
				DSF	0000779005	State of Good Repair - Building Upgrade - Climate Control	2017	2,435,273
				-	0000779007	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluoresc CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandes	ent	984,866
				DSF	0000733730	State of Good Repair - Building Upgrade - Low-Vo. Electrical Systems FIRE ALARM SYSTEM	Itage 2015	1,100,298

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K753	DS	F0000779013	PUBLIC ADDRESS SYSTEM State of Good Repair - System Replacements - Heating	2015	35,239
						Plant Upgrade		
				DS	F0000779019	State of Good Repair - System Replacements - Kitchen Areas	2015	512,908
						KITCHEN		
						P.S. 753 (OLD P85/ST	ERLING HS) Total:	\$11,947,615
75K	Brooklyn	K148		P.S. 373 (OLD P148)			
				DS	F0000757397	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,107,551
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799542	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	126,109
				DS	F0000799745	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	36,354
				DS	F0000713258	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2015	2,215,831
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		
				DS	F0000757401	State of Good Repair - System Replacements - Exterior Masonry	2015	3,994,995
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000757400	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	3,663,538

Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
		K373	DSF	-0000803236	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
					INTERIOR:TOILET ROOMS - STUDENTS		
			DSF	-0000822128	State of Good Repair - System Replacements - Toilets-Students	2016	264,488
					FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
					Other		
		K373	DSF	-0000776041	IP Surveillance Camera Installation	2015	595,103
						P.S. 373 (OLD P148) Total:	\$12,105,320
Brooklyn	K286		P.S. 811 (OLD P286)			
·		K811	DSF	-0000798287	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
					HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
		K811	DSF	-0000798290	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
					CLIMATE CONTROL SYSTEM		
			DSF	-0000827972	State of Good Repair - Building Upgrade - Elevator and Escalators CONVEYING:Elevator	rs 2018	274,054
		Borough ID	Borough ID Org ID K373 K373 Brooklyn K286 K811	BoroughIDOrg IDSchoolK373DSIDSIBrooklynK286K373DSIBrooklynK286P.S. 811 (DSIK811DSIDSIDSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynK286DSIBrooklynBrooklynBrooklynBrooklynK286BrooklynBrooklynK286BrooklynBrooklynK286BrooklynBrooklynK286BrooklynBroo	BoroughIDOrg IDSchoolProject #K373DSF0000803236DSF0000822128DSF0000822128K373DSF0000776041BrooklynK286P.S. 811 (OLD P286) DSF0000798287	BoroughIDOrg IDSchoolProject #DescriptionK373DSF0000803236State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:UrinalBrooklynK286P.S. 811 (OLD P286) K811State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEMK811DSF0000798290State of Good Repair - Building Upgrade - Climate Control ClIMATE CONTROL SYSTEM	Building BoroughIDOrg IDSchoolProject #DescriptionConstruction StateBoroughIDVar IDSchoolProject #DescriptionState

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K811	DSI	F0000827979	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	56,227
						P.S. 811	(OLD P286) Total:	\$6,318,728
75K	Brooklyn	K369		P.S. 369 (соу сох ѕсн	OOL)		
				DSI	F0000798412	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	557,121
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
				DSI	F0000799767	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - Building Upgrade - Lighting Fixtures	2015	15,660
						P.S. 369 (COY CC	X SCHOOL) Total:	\$572,781
75K	Brooklyn	K370		P.S. 370				
				DSI	F0000799697	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	168,082
							P.S. 370 Total:	\$168,082
75K	Brooklyn	K371		P.S. 371 (OLD 615)			
				DSI	F0000777480	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2016	97,241
				DSI	F0000783026	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,209,203

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			K371	DS	F0000806334	State of Good Repair - System Replacements - Paved Area-Blacktop	2016	1,484,348
						SITE:Drainage System for Asphalt		
						P.S.	371 (OLD 615) Total:	\$2,790,792
75K	Brooklyn	K722		P.S. 721	отс			
	·		K721	DS	F0000807390	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	26,35 ⁻
						DUAL TEMPERATURE SYSTEM (CHILLED AND HO	т	
						WATER) DUAL TEMPERATURE SYSTEM (CHILLED AND HO	т	
						WATER):Dual Temperature Distribution: Piping, Pumps and Auxiliaries		
							P.S. 721 OTC Total:	\$26,351
75K	Brooklyn	K834		P.S. 372 (OUR LADY OF	PEACE)		
			K418	DS	F0000821881	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2019	814,060
						PUBLIC ADDRESS SYSTEM		
			K418	DS	F0000784250	State of Good Repair - System Replacements - Toilets-Students	2015	230,440
						FIXTURES:STUDENT:Lavatory/Sink		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						P.S. 372 (OUR LAI	OY OF PEACE) Total:	\$1,044,500
75K	Brooklyn	K843		P.S. 4 (EC	C)			
				DSF	0000784282	State of Good Repair - Building Upgrade - Lighting	2015	344,366
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 4 (ECC) Total:	\$344,366
75K	Brooklyn	K877		P.S. 369 A	X-(OL 396X/FL	TB TN HL)		
				DSF	0000777494	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	34,765
				DSF	0000784472	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	280,545
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						P.S. 369 AX-(OL 396)	K/FLTB TN HL) Total:	\$315,310
75K	Brooklyn	K902		P.S. 77 AN	INEX			
				DSF	0000738916	Safety and Security - Safety and Security - Safety Systems EXTERIOR:DOORS:DOOR HARDWARE	2016	176,804

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS		
				DS	F0000799577	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	542,246
				DS	F0000761845	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	1,402,091
				DS	F0000717681	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2016	17,905,906
				DS	F0000738917	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	3,915,516
				DS	F0000761860	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System AIR CONDITIONING:CHILLED WATER SYSTEM:Packaged Air Cooled Chiller	2016	5,524,516
				DS	F0000738909	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	4,656,317
				DS	F0000738911	State of Good Repair - System Replacements - Paved Area-Concrete SITE:Drainage System for Concrete	2016	1,256,005
				DS	F0000738908	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	5,593,194

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000775578	State of Good Repair - System Replacements - Windows	2016	4,541,359
						EXTERIOR:WINDOWS		
							P.S. 77 ANNEX Total:	\$45,513,954
78K	Brooklyn	K175		TEACHER	RS PREP HS(OI	L REDIRECTION)		
				DS	F0000780331	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,072,359
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - HID		
				DS	F0000777264	State of Good Repair - Building Upgrade - Low-Voltage	2016	2,552,481
						Electrical Systems		
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		
						TEACHERS PREP HS(OL	REDIRECTION) Total:	\$3,624,840
78K	Brooklyn	K313		ADAMS S	TREET EDUCA	TIONAL CAMPUS		
				DS	F0000844726	Educational Enhancements - Educational Enhancements - Accessibility	2018	69,802
						ADAMS STREET EDUCAT	ONAL CAMPUS Total:	\$69,802
78K	Brooklyn	K400		LAFAYET	TE EDUCATIO	NAL CAMPUS		
	-			DS	F0000798621	State of Good Repair - Building Upgrade - Flood Elimination	2016	4,728,267

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			K337	DS	F0000821920	State of Good Repair - Building Upgrade - Flood Elimination	2016	2,610,031
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
				DS	F0000798619	State of Good Repair - Building Upgrade - Interior Spaces	2016	4,002,297
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DS	F0000798418	INTERIOR:STAIRS/RAMPS: INTERIOR State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,815,020
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000800061	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	1,443,549

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000821919	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	1,861,078
				DS	F0000798620	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	8,034,565
						LAFAYETTE EDUCATION/	AL CAMPUS Total:	\$24,494,807
78K	Brooklyn	K405		MIDWOO	D HS			
				DS	F0000799561	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	444,400
			K405	DS	F0000760638	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	3,114,954
				DS	F0000777218	State of Good Repair - System Replacements - Auditorium Upgrade AUDITORIUM:THEATER LIGHTING SYSTEM:Dimming System	2015	427,313
				DS	F0000783257	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK	2015	487,067

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						VENTILATION:SUPPLY FAN		
							MIDWOOD HS Total:	\$4,473,734
78K	Brooklyn	K406		MIDWOOD) HS AF (MAIN)			
				DSF	0000755235	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2017	7,195,303
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEA NG WALLS	રા	
			K405	DSF	0000783260	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2017	19,675,607
						ATHLETIC FIELD: EXTERIOR LIGHTING		
						ATHLETIC FIELD:LOCAL SOUND SYSTEM ATHLETIC FIELD:SCOREBOARD		
						ATHLETIC FIELDS:FIXED EQUIPMENT		
						ATHLETIC FIELDS: PLAYING SURFACE		
						ATHLETIC FIELDS:SEATING		
						MIDWOO	D HS AF (MAIN) Total:	\$26,870,910
78K	Brooklyn	K410		ABRAHAN	I LINCOLN HS			
			K410	DSF	0000798652	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	2,651,038
				DSF	0000737753	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,435,580
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMI PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	SF0000799403	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	2,360,943
				DS	SF0000799402	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	1,080,143
				DS	SF0000799562	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	406,767
			K410	DS	SF0000737750	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	2,236,225
				DS	SF0000783265	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs INTERIOR:STRUCTURAL:FLOOR STRUCTURE	2015	127,275
				DS	SF0000783273	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	2015	1,444,749

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWITCHBOARD		
				DS	F0000783272	State of Good Repair - System Replacements - Exterior Masonry	2015	993,647
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000783284	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2015	1,001,426
				DS	F0000783270	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,297,352
				DS	F0000783269	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	10,002,181
				DS	F0000737755	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2015	25,515,046
						Other		
				DS	F0000843844	IP Surveillance Camera Installation	2018	448,918
						ABRAHAM I	INCOLN HS Total:	\$51,001,290
78K	Brooklyn	K411		LINCOLN	HS AF			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799406	State of Good Repair - Building Upgrade - Flood Elimination	2015	640,541
			K410	DS	F0000799404	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - Building Upgrade - Interior Spaces	2015	69,490
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSI	F0000800327	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	444,706
				DSI	F0000783287	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELD:EXTERIOR LIGHTING ATHLETIC FIELD:SCOREBOARD ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING	2015	3,190,710
				DS	F0000799405	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD	2015	59,747

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							LINCOLN HS AF Total:	\$4,405,194
78K	Brooklyn	K415		SAMUEL	J. TILDEN EDU	CATIONAL CAMPUS		
				DSI	F0000798414	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	641,387
						Other		
				DSI	F0000843845	IP Surveillance Camera Installation	2018	448,918
						SAMUEL J. TILDEN EDUCA	TIONAL CAMPUS Total:	\$1,090,305
78K	Brooklyn	K422		SPRING C	REEK EDUCA	TIONAL CAMPUS		
				DSI	F0000799760	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	40,828
						SPRING CREEK EDUCA	TIONAL CAMPUS Total:	\$40,828
78K	Brooklyn	K425		JAMES M	ADISON HS			
				DSI	F0000799564	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	371,065
				DSI	F0000799898	State of Good Repair - Building Upgrade - Low-Voltag Electrical Systems PUBLIC ADDRESS SYSTEM	ge 2015	1,238,329
				DSI	F0000753104	State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools INTERIOR:POOLS	2018	7,608,810

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000806647	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Stage:Stage INTERIOR:AUDITORIUM:Stage:Stage Curtains	2016	105,823
				DS	F0000752896	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	666,916
			K425	DS	F0000806643	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	125,412
						JAMES	MADISON HS Total:	\$10,116,355
78K	Brooklyn	K430		BROOKL	YN TECH HS			
				DS	F0000844718	Educational Enhancements - Educational Enhancements - Accessibility	2018	142,882
				DS	F0000777483	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	516,967
				DS	F0000799698	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,201,381
				DS	F0000760755	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	4,892,454

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DS	F0000806678	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade INTERIOR:CAFETERIA:Floor Finish INTERIOR:CAFETERIA:Sliding-folding Partition INTERIOR:MULTI-PURPOSE ROOM:Floor Finish	2019	533,236
				DS	F0000806665	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	260,353
				DS	F0000806675	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2018	955,983
			K430	DS	F0000823609	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT GAS SERVICE:GAS PRESSURE BOOSTER HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS	2016	112,271
				DS	F0000828951	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System	2018	100,100

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K430	DS	F0000822140	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	260,419
				DO		Other Associ Constants	0045	4 440 005
				05	F0000777292	Ansul Systems BROOKLY	2015 N TECH HS Total:	
78K	Brooklyn	K435		THOMAS	JEFFERSON H	S		¥ -) -)
				DS	F0000821604	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DS	F0000806688	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	74,806
			K502	DS	F0000823618	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:FUEL SYSTEMS	2016	38,342

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K504	DS	F0000865741	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						Other		
				DS	F0000843846	IP Surveillance Camera Installation	2018	448,918
						THOMAS JEFF	ERSON HS Total:	\$1,345,302
78K	Brooklyn	K440		PROSPE	СТ НЕІGHTS HS			
	·			DS	F0000777484	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	238,176
		K524 DSF0000828988	F0000828988	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	2,061,760		
				DS	F0000798419	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	865,050
			K524	DS	F0000828992	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR	2017	8,363,175

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K524	DS	F0000843949	State of Good Repair - System Replacements - Parapets	2017	5,849,355
			K524	DS	F0000828990	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Specialties	2017	5,076,796
			K524	DS	F0000828991	State of Good Repair - System Replacements - Windows	2017	4,270,505
						EXTERIOR:WINDOWS		
						PROSPECT F	HEIGHTS HS Total:	\$26,724,817
78K	Brooklyn	K445			RECHT HS			
			K445	DS	F0000775948	State of Good Repair - Building Upgrade - Flood Elimination	2018	2,732,599
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					F0000799565	INTERIOR:STRUCTURAL:FOUNDATION WALLS	2045	E07 044
				03	F0000799505	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	597,214
				DS	F0000783448	State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools FIXTURES:STUDENT:Locker Room Shower INTERIOR:POOLS INTERIOR:SHOWER ROOM LOCKER ROOM:LIGHTING:Lighting Fixture - Fluorescent LOCKER ROOM:LIGHTING:Lighting Fixture - Incandescent SWIMMING POOL	2018	7,503,457

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWIMMING POOL:LIGHTING:Lighting Fixture - Fluorescent		
			K445	DS	\$F0000829026	State of Good Repair - System Replacements - Domestic Piping Waste System	2018	122,537
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewag Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	je	
				DS	F0000822655	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310
						NEW	UTRECHT HS Total:	\$11,267,117
78K	Brooklyn	K446		NEW UT	RECHT HS AF			
			K445	DS	F0000783461	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELDS:PLAYING SURFACE	2018	7,376,059
							RECHT HS AF Total:	\$7,376,059
78K	Brooklyn	K450		GRAND	STREET CAMPL	JS (OLD E.D.HS)		
-	,				SF0000775794	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	371,140
			K478	DS	F0000799897	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	618,300
				DS	F0000777485	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	370,607

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798454	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,500,000
				DS	F0000783462	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,277,027
				DS	F0000783464	State of Good Repair - Building Upgrade - Lighting	2015	72,475
				DS	F0000806775	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			K474	DS	F0000783472	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000799806	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			K474	DS	F0000865742	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						GRAND STREET CAMPUS (O	LD E.D.HS) Total:	\$8,107,354
78K	Brooklyn	K455		BOYS &	GIRLS HS			
			K455	DS	F0000844703	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2018	75,230
				DS	F0000844051	Technology	2018	505,376

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000844052	Science Lab Upgrades	2018	1,080,100
				DSF	0000844053	Science Lab Upgrades	2019	250,300
				DSF	0000777486	Safety and Security - Safety and Security - Emergen Lighting and Fire Safety Retrofits	cy 2015	374,748
				DSF	60000821598	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
							BOYS & GIRLS HS Total:	\$2,818,990
78K	Brooklyn	K458		BOYS HS	(OLD)			
				DSF	0000799787	Miscellaneous	2015	654,063
			K373	DSF	0000775845	Safety and Security - Safety and Security - Code Compliance	2019	7,881,361
				DSF	0000799566	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	166,791
							BOYS HS (OLD) Total:	\$8,702,215
78K	Brooklyn	K460		JOHN JAY		AL CAMPUS		
	-		K462	DSF	0000800274	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	579,326
			K462	DSF	0000800275	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	968,894
			K464	DSF	0000822220	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	583,953

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K462	DS	F0000798587	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2015	2,175,385
				DS	F0000777487	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	279,501
				DS	F0000799567	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	256,189
			K462	DS	F0000783558	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING	2019	6,559,463
			K462	DS	F00007999999	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	94,353
						Other		
			K462	DS	F0000822035	New/Retrofit Telephone/Intercom Systems	2015	781,853
						JOHN JAY EDUCATION	AL CAMPUS Total:	\$12,278,917
78K	Brooklyn	K465			S HALL CAMPL F0000783561	JS State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,565,219

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000806872	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DSF	0000806855	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	28,547
						Other		
				DSF	0000843847	IP Surveillance Camera Installation	2018	561,148
						ERASMUS HAL	L CAMPUS Total:	\$2,688,150
78K	Brooklyn	K470		GEORGE	W. WINGATE H	IS		
				DSF	0000777488	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	232,357
				DSF	0000821588	State of Good Repair - System Replacements - Auditorium Upgrade	2019	182,127
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
			K544	DSF	0000806875	State of Good Repair - System Replacements - Exterior Masonry	2015	23,648
						EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS		
				DSF	0000806877	State of Good Repair - System Replacements - Toilets-Students	2015	201,333

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet		
						GEORGE	V. WINGATE HS Total:	\$639,465
78K	Brooklyn	K480		BUSHWIC	K EDUCATION	IAL CAMPUS		
			K549	DSF	0000822683	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,838,406
			K168	DSF	0000752880	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2018	2,443,940
						PUBLIC ADDRESS SYSTEM		
				DSF	0000800336	State of Good Repair - Rehabilitation of Physical Education Facilities - Swimming Pools	2015	104,729
						SWIMMING POOL		
			K549	DSF	0000844037	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	119,876
						BUSHWICK EDUCAT	ONAL CAMPUS Total:	\$4,506,951
78K	Brooklyn	K485		TELECOM	. ARTS & TEC	Н.		
			K485	DSF	0000665737	Safety and Security - Safety and Security - Code Compliance	2019	7,666,864
				DSF	0000783627	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	56,488
				DSF	0000799699	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	442,565
			K485	DSF	0000738056	State of Good Repair - System Replacements - Roofs EXTERIOR:PLAZA DECK	2015	1,914,576

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing		
				DS	F0000783631	State of Good Repair - System Replacements - Windows	2015	261,303
						EXTERIOR:WINDOWS		
						TELECOM. A	RTS & TECH. Total:	\$10,341,796
78K	Brooklyn	K490		FORT HA	MILTON HS			
				DS	F0000798422	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	678,369
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K490	DS	F0000799401	State of Good Repair - System Replacements - Heating Plant Upgrade	2019	1,891,281
				DS	F0000806960	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						FORT H	AMILTON HS Total:	\$2,671,001
78K	Brooklyn	K495		FRANK J	. MACCHIAROL	A EDUCATIONAL COMPLEX		
	-		K495	DS	F0000822176	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	1,873,829
				DS	F0000799568	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	244,713

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K495	DS	F0000806979	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
						Other		
				DS	F0000843848	IP Surveillance Camera Installation	2017	527,479
						FRANK J. MACCHIAROLA EDUCATIONAL	COMPLEX Total:	\$2,801,387
78K	Brooklyn	K500		CANARS	IE HS			
	·			DS	F0000777489	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	252,267
				DS	F0000761082	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,145,139
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000806993	State of Good Repair - Building Upgrade - Climate Control	2017	1,093,699
						CLIMATE CONTROL SYSTEM		
				DS	F0000829257	State of Good Repair - Building Upgrade - Flood Elimination	2017	2,921,000
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799569	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	285,334
			K617	DS	F0000821603	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000843849	IP Surveillance Camera Installation	2017	448,918
							CANARSIE HS Total:	\$9,679,593
78K	Brooklyn	K505		FRANKLI	N D. ROOSEVE	ILT HS		
				DSF	-0000783734	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	98,995
				DSF	-0000799570	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	303,877
			K505	DSF	-0000783739	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	-0000807028	State of Good Repair - System Replacements - Toilets-Students	2015	251,714
						FIXTURES:STUDENT:Toilet		
						FRANKLIN D. F	OOSEVELT HS Total:	\$689,849
78K	Brooklyn	K515		SOUTH SI	HORE EDUCAT	FIONAL COMPLEX		
				DSF	-0000799895	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	716,112
				DSF	-0000821664	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	366,676
			K578	DSF	-0000822684	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,242,681
			K578	DSF	-0000821755	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2015	75,470

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Technology		
			K567	DS	F0000821779	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	85,414
			K637	DS	F0000821780	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
			K637	DS	F0000844127	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	50,324
			K637	DS	F0000844128	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	94,204
			K567	DS	F0000845635	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	127,000
			K576	DS	F0000845637	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	89,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K637	DSI	F0000845638	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	92,000
				DS	F0000799571	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	538,800
				DS	F0000821599	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
						Other		
				DSI	F0000843850	IP Surveillance Camera Installation	2017	604,000
						SOUTH SHORE EDUCATION	AL COMPLEX Total:	\$6,649,917
78K	Brooklyn	K516		SOUTH S	HORE HS AF			
				DSI	F0000807062	Athletic Fields ATHLETIC FIELD:SCOREBOARD CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent DOMESTIC WATER SYSTEM DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING EMERGENCY LIGHTING EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:LINTELS EXTERIOR:EXTERIOR WALLS FIRE ALARM SYSTEM	2019	2,582,312

District	Borough	Building ID	Org ID	School Project #	Description	FY - Construction Start	Total
					GAS FIRED FURNACE		
					GROUNDING SYSTEM		
					INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
					LIGHTING - SECURITY LIGHTS		
					LOCKER ROOM:LIGHTING:Lighting Fixture -		
					Fluorescent		
					MOTOR STARTER/CONTACTOR		
					PANEL BOARD		
					SECURITY:INTRUSION ALARM		
					SERVICE SWITCH		
					SITE:FENCES		
					SITE:PAVING - STUDENT USE:Asphalt		
					SITE:SITE WALLS (NOT RETAINING WALLS)		
					TELEPHONE		
					TOILET ROOM - STAFF:LIGHTING:Lighting Fixture -		
					TOILET ROOM - STUDENT:LIGHTING:Lighting		
					Fixture - Fluorescent		
			K566	DSF0000844106	State of Good Repair - Rehabilitation of Physical	2018	102,378
					Education Facilities - Athletic Fields		
					SOUTH S	HORE HS AF Total:	\$2,684,690
78K	Brooklyn	K520		PACIFIC ALT HS			
	,			DSF0000775823	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	289,177
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandesce	nt	
							PACIFIC ALT HS Total:	\$289,177
78K	Brooklyn	K525		EDWARD	R. MURROW H	IS		
				DSF	0000799572	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	484,416
				DSF	0000821627	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			K525	DSF	0000783788	State of Good Repair - System Replacements - Heatiı Plant Upgrade	ng 2015	35,263
				DSF	0000807073	State of Good Repair - System Replacements - Heatiı Plant Upgrade	ng 2018	311,310
			K525	DSF	0000807084	State of Good Repair - System Replacements - Heatin Plant Upgrade Air Conditioning Split System AIR CONDITIONING:CONDENSER WATER PUM	-	46,990
			K525	DSF	0000822661	State of Good Repair - System Replacements - Heatin Plant Upgrade		155,366
			K525	DSF	0000829347	State of Good Repair - System Replacements - Heatin Plant Upgrade Air Conditioning Split System AIR CONDITIONING:Cooling Tower	ng 2018	465,455
			K525	DSF	0000865719	State of Good Repair - System Replacements - Heatin Plant Upgrade	ig 2018	203,929

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Air Conditioning Split System		
						EDWAR	RD R. MURROW HS Total:	\$2,235,965
78K	Brooklyn	K540		JOHN DE	WEY HS			
				DSF	-0000799407	State of Good Repair - Building Upgrade - Interior Spaces	2015	238,634
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	I	
						INTERIOR:STAIRS/RAMPS: INTERIOR		
				DSF	-0000799573	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	398,010
				DSF	-0000783809	State of Good Repair - System Replacements - Electrical Systems	2015	3,141,412
						EMERGENCY GENERATOR SET GROUNDING SYSTEM		
						PANEL BOARD		
						Other		
				DSF	-0000843851	IP Surveillance Camera Installation	2017	476,465
							JOHN DEWEY HS Total:	\$4,254,521
78K	Brooklyn	K580		GEORGE	WESTINGHOU	SE VOC HS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K605	DS	F0000798585	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,073,782
				DS	F0000783843	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Library Upgrades INTERIOR:LIBRARY:Door(s) INTERIOR:LIBRARY:Floor Finish LIBRARY:LIGHTING:Lighting Fixture - Fluorescent	2016	1,452,599
				DS	F0000798586	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2016	1,458,857
			K605	DS	F0000807133	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,025,104
			K605	DS	F0000807137	State of Good Repair - System Replacements - Exterior Masonry	2016	668,667
				DS	F0000821922	State of Good Repair - System Replacements - Parapets	2016	7,944,686
			K605	DS	F0000807135	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	3,073,660
						Other		
			K008	DS	F0000822044	New/Retrofit Telephone/Intercom Systems	2015	448,371
						GEORGE WESTINGHOUS	E VOC HS Total:	\$17,145,726
78K	Brooklyn	K590			COLLEGE HS			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	F0000844719	Educational Enhancements - Educational Enhancements - Accessibility	2017	578,037
						MIDDLE	COLLEGE HS Total:	\$578,037
78K	Brooklyn	K600		CLARA B	ARTON HS			
				DSF	F0000783849	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	2,247,372
			K600	DSF	50000807157	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS	2017	6,425,982
			K600	DSF	0000783858	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			K600	DSF	-0000807155	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	3,220,222
						CLARA	BARTON HS Total:	\$11,928,839
78K	Brooklyn	K610			FIVE TRADES 1 F0000783877	VOC HS State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,545,646

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						AUTOMOTIVE TRAD	ES VOC HS Total:	\$1,545,646
78K	Brooklyn	K615		E NY VOC	HS OF TRANS	SIT TECH.		
				DSF	0000783901	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,649,232
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - HID		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000807212	State of Good Repair - System Replacements -	2015	101,351
						Toilets-Students		
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
						Fluorescent		
						E NY VOC HS OF TRA	NSIT TECH. Total:	\$1,750,583
78K	Brooklyn	K620		WILLIAM E	E. GRADY VOO	CHS		
				DSF	0000777492	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	174,969

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000783923	State of Good Repair - Building Upgrade - Climate Control	2015	2,362,707
						CLIMATE CONTROL SYSTEM		
				DS	F0000799434	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,732,588
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000783925	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,976,141
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000799947	State of Good Repair - Rehabilitation of Physical	2015	10,834,539
						Education Facilities - Athletic Fields		
						SITE:Drainage System for Asphalt SITE:Drainage System for Soil SITE:PAVING - STUDENT NON-USE:Asphalt		
				DS	F0000799459	State of Good Repair - System Replacements -	2015	329,643
						Domestic Piping		
						DOMESTIC WATER SYSTEM FIXTURES:STUDENT:Drinking Fountain FIXTURES:STUDENT:Sink And Fountain Combo Unit		
				DS	F0000783933	State of Good Repair - System Replacements - Electrical Systems	2015	1,463,881

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						GROUNDING SYSTEM PANEL BOARD		
						SERVICE SWITCH		
						SWITCHBOARD		
				DSF	0000783934	State of Good Repair - System Replacements - Heating	2015	7,098,488
						Plant Upgrade		
						HEATING		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT:FUEL SYSTEMS		
						HEATING:HYDRONIC HEATING:Hydronic Hot Water		
						Distribution: Piping, Pumps and Auxiliaries		
						WILLIAM E. G	RADY VOC HS Total:	\$27,972,956
78K	Brooklyn	K625		ROBESON	HS COMP&B	US TC (A HML)		
				DSF	0000783952	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	60,963
				DSF	0000799574	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	209,929
						ROBESON HS COMP&B	US TC (A HML) Total:	\$270,892
78K	Brooklyn	K650		HARRY VA	ANARSDALE V	/OC HS(WHITNEY)		
			K488	DSF	0000798299	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			K488	DS	F0000798302	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
				DS	F0000822222	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,552,102
				DS	F0000783976	SPACE:LIGHTING:Lighting Fixture - Fluorescent State of Good Repair - System Replacements - Exterior Masonry	2016	6,407,555
				DS	F0000807294	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2016	172,355
				DS	F0000783974	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	841,015
				DS	F0000761351	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	4,188,698
				DS	F0000783975	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	3,342,099
						HARRY VANARSDALE VOC H	IS(WHITNEY) Total:	\$22,492,271
78K	Brooklyn	K655		BKLYN H	S OF THE ART	S (OL S J HL)		
				DS	F0000822691	Auditorium Upgrade	2016	559,761

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000777490	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	233,582
				DS	F0000799700	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	234,212
			K656	DS	F0000752882	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	1,703,294
				DS	F0000761374	State of Good Repair - System Replacements - Exterior Masonry	2016	6,548,062
			K656	DS	F0000784010	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN VENTILATION:UNIT VENTILATOR	2016	117,290
			K656	DS	F0000823619	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM EXHAUST FAN GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	84,474

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT: FUEL SYSTEMS		
			K656	DS	F0000799355	State of Good Repair - System Replacements - Kitchen Areas	2016	170,053
				DS	F0000807302	State of Good Repair - System Replacements - Roofs	2016	1,819,177
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
						BKLYN HS OF THE ARTS	(OL S J HL) Total:	\$11,469,905
78K	Brooklyn	K656		BKLYN H	S OF THE ART	S AX (S J HL)		
					F0000798263	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,673,992
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000784013	State of Good Repair - Building Upgrade - Climate Control	2018	1,326,403
						CLIMATE CONTROL SYSTEM		
				DS	F0000784015	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	909,424
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			K656	DS	F0000784014	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	1,299,932
				DS	F0000784033	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers	2016	3,666,035

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:DELUGE		
						VALVE		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:ROOF		
						TANK		
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:SIAMESE		
						CONNECTION		
						SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:SPRINKLER HEAD		
						SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:SPRINKLER PIPING		
						SPRINKLERS, STANDPIPE, FIRE		
						SYSTEM:STANDPIPE SYSTEM		
						BKLYN HS OF THE ARTS	AX (S J HL) Total:	\$11,875,786
78K	Brooklyn	K660		WILLIAM MAX	XWELL CTE	E HS		
				DSF000	00784036	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	79,664
				DSF000	0799575	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	139,351
						WILLIAM MAXWE	LL CTE HS Total:	\$219,015
78K	Brooklyn	K721		BROOKLYNS	STUDIO (TA	ANDEM K128)		
	-				00777491	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	41,235
			K771	DSF000	0784059	State of Good Repair - System Replacements - Exterior Masonry	2018	1,286,449

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			K690	DS	SF0000822173	State of Good Repair - System Replacements - Roofs	2018	1,061,773
						EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
				DS	SF0000807364	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2018	3,783,473
						BROOKLYN STUDIO (TAI	NDEM K128) Total:	\$6,172,930
78K	Brooklyn	K728		LIBERA		PLUS H.S.		
			K728	DS	SF0000821869	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,042,032
				DS	SF0000821823	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2016	TBD
						LIBERATION DIPLOM	A PLUS H.S. Total:	\$2,042,032
78K	Brooklyn	K778		EL PUEN	NTE HS			
	-		K685	DS	SF0000822118	Exterior Masonry	2018	1,401,009
				DS	SF0000797940	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	980,472
			K685	DS	SF0000797939	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2018	1,421,137

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
				DS	F0000797941	State of Good Repair - System Replacements - Windows	2018	822,115
						EXTERIOR:WINDOWS		
							EL PUENTE HS Total:	\$4,624,733
78K	Brooklyn	K781		WEST BR	ROOKLYN COM	MUNITY HS		
				DS	F0000797988	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	74,978
						WEST BROOKLY	N COMMUNITY HS Total:	\$74,978
78K	78K Brooklyn	K804		COBBLE	HILL SCL OF A	MR STD (OL6)		
			K519	DS	F0000784168	State of Good Repair - System Replacements - Toilets-Students	2016	265,819
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		* 005 040
						COBBLE HILL SCL	OF AMR STD (OL6) Total:	\$265,819
78K	Brooklyn	K806		METROP	OLITAN CORPO	DRATE ACAD.		
			K530	DS	F0000843639	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						METROPOLITAN CORI	PORATE ACAD. Total:	\$101,351
78K	Brooklyn	K824		W.E.B. DU	JBOIS HS			
				DSF	-0000784233	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	601,585
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						W.E	E.B. DUBOIS HS Total:	\$601,585
78K	Brooklyn	K907		BROWNS	VILLE DIPLOM	A PLUS HS		
				DSF	-0000784507	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	29,642
						BROWNSVILLE DIP	LOMA PLUS HS Total:	\$29,642
78K	Brooklyn	K914		BENJAMI	N BANNEKER	ACADEMY		
				DSF	-0000799764	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	47,540
						BENJAMIN BANNE	KER ACADEMY Total:	\$47,540
78K	Brooklyn	K917		BKLYN C	OLL ACAD (BR	RIDGES TO K)		
				DSF	-0000784545	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	637,047
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	-0000799738	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	17,897

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Tota
						BKLYN COLL	ACAD (BRIDGES TO K) Total:	\$654,944
78K	Brooklyn	K932		HIGH SCHO		SION CENTER		
			X695	DSF00	00843640	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
						HIGH SCHOOL	SUSPENSION CENTER Total:	\$101,351
78K	Brooklyn	K994		BEDFORD A	CADEMY			
						Other		
				DSF00	00799914	IP Surveillance Camera Installation	2015	509,422
							BEDFORD ACADEMY Total:	\$509,422

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
01	Manhattan	M015		P.S. 15				
			M015	DSI	F0000798463	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,667,715
						HEATING PLANT:BOILER SYSTEM		
			M015	DSI	F0000784786	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
					F0000700004	CLIMATE CONTROL SYSTEM	2045	000 500
				DSI	F0000798364	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	886,508
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000739189	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,555,534
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			M015	DS	F0000843821	State of Good Repair - System Replacements - Domestic Piping	2018	63,617
			M015	DS	F0000784791	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSI	F0000808159	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	81,924

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M015	DS	SF0000808160	State of Good Repair - System Replacements - Toilets-Students	2016	50,675
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 15 Total:	\$8,665,858
01	Manhattan	M019		P.S. 19				· - , ,
				DS	SF0000808194	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,180,977
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	SF0000808201	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							P.S. 19 Total:	\$1,282,328
01	Manhattan	M025		J.H.S. 25	5			
				DS	SF0000822234	Miscellaneous	2015	305,531

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000808252	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,956,291
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000808257	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310
			M515	DS	F0000822662	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
						Other		
			M515	DS	F0000843786	Classroom Connectivity	2016	146,146
							J.H.S. 25 Total:	\$2,874,644
01	Manhattan	M034		P.S. 34				
				DS	F0000798459	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798462	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DS	F0000808331	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 34 Total:	\$5,932,393
01	Manhattan	M056		J.H.S. 56				

01 Manhattan M056 J.H.S. 56

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M292	DS	F0000822689	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,772,223
				DS	F0000785220	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,980,571
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							J.H.S. 56 Total:	\$4,752,794
01	Manhattan	M060		J.H.S. 60				
			M450	DS	F0000785275	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2015	1,601,892
				DS	F0000762652	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	4,932,815
			M450	DS	F0000785277	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	922,225
			M450	DS	F0000799353	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	1,404,897

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M330	DS	F0000808643	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2016	101,351
							J.H.S. 60 Total:	\$8,963,180
01	Manhattan	M061		P.S. 61				
				DS	F0000785290	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,065,563
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M315	DS	F0000762665	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	1,932,422
				DS	F0000775645	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	794,651
				DS	F0000785297	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2016	1,022,161

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M361	DS	F0000843975	State of Good Repair - System Replacements - Exterior Masonry	2018	184,124
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
			M315	DS	F0000808659	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		¢E 100 070
							P.S. 61 Total:	\$5,100,272
01	Manhattan	M063		P.S. 63				
			M063	DS	F0000808675	State of Good Repair - System Replacements - Toilets-Students	2016	50,675
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							P.S. 63 Total:	\$50,675
01	Manhattan	M064		P.S. 64 (C	DLD 71)			
			M064	DS	F0000785332	State of Good Repair - System Replacements - Toilets-Students	2015	535,396
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			M839	DSI	F0000822021	New/Retrofit Telephone/Intercom Systems	2015	210,552
			M064	DSI	F0000776052	IP Surveillance Camera Installation	2015	568,414
							P.S. 64 (OLD 71) Total:	\$1,314,362
01	Manhattan	M110		P.S. 110				
				DSI	F0000809086	State of Good Repair - System Replacements - Toilets-Students	2015	391,336
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							P.S. 110 Total:	\$391,336
01	Manhattan	M134		P.S. 134				
			M134	DSI	F0000831482	Safety and Security - Safety and Security - Safety Systems	2018	156,875
						EXTERIOR:DOORS:DOORS AND FRAMES EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
				DSI	F0000798307	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	935,877
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescen	t	
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandesce	nt	

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M134	DS	F0000809418	State of Good Repair - System Replacements - Toilets-Students	2015	195,802
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 134 Total:	\$1,288,554
01	Manhattan	M137		P.S. 137				
			M184	DS	F0000786134	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000799815	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			M184	DS	F0000786136	State of Good Repair - System Replacements - Toilets-Students	2015	428,606
						FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
			M184	DS	F0000809459	State of Good Repair - System Replacements - Toilets-Students	2015	201,331
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							D.C. 427 Total	¢744 506

P.S. 137 Total: \$744,506

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
01	Manhattan	M140		P.S. 140				
				DSF	-0000799775	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	51,547
							P.S. 140 Total:	\$51,547
01	Manhattan	M142		P.S. 142				
				DSF	-0000799587	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	140,085
			M142	DSF	-0000809493	State of Good Repair - System Replacements - Paved Area-Blacktop	2018	3,075,524
						SITE: PAVING - STUDENT USE: Asphalt		
							P.S. 142 Total:	\$3,215,609
01	Manhattan	M188		P.S. 188				
				DSF	-0000777498	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	160,453
				DSF	-0000799593	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	144,096
				DSF	F0000809940	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	266,101
						Other		
			M188	DSF	-0000843783	Classroom Connectivity	2016	233,060

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 188 Total:	\$803,710
02	Manhattan	M001		P.S. 1				
				DSF	0000784576	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	818,487
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M001	DSF	0000761938	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	1,417,831
				DSF	0000775641	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	851,441
				DSF	0000784587	State of Good Repair - System Replacements - Kitchen Areas KITCHEN	2016	133,134
			M001	DSF	F0000807952	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2016	101,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 1 Total:	\$3,322,244
02	Manhattan	M002		P.S. 2				
				DSF	0000799701	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	220,834
			M002	DSF	0000807970	State of Good Repair - System Replacements - Toilets-Students	2016	50,675
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 2 Total:	\$271,509
02	Manhattan	M003		P.S. 3				
				DSF	0000799772	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	31,320
			M003	DSF	0000807990	State of Good Repair - System Replacements - Toilets-Students	2016	50,675
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						TIXTORES.STODENT.OIIIa		¢04.005
							P.S. 3 Total:	\$81,995

02 Manhattan M006 **P.S. 6**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000821593	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	797,041
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 6 Total:	\$797,041
02	Manhattan	M011		P.S. 11				
			M011	DS	F0000762105	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2015	1,996,546
				DS	F0000821721	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	632,092
							P.S. 11 Total:	\$2,628,638
02	Manhattan	M017		I.S. 17				
			M212	DS	F0000808176	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	2,906,243

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000799773	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	31,880
			M212	DSI	F0000808180	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2017	2,022,419
				DSI	F0000823573	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DSI	F0000808179	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	260,302
			M212	DSI	F0000822122	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	875,992
			M212	DSI	F0000784813	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	223,391
			M212	DSF	F0000808181	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	79,814

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000822121	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2017	272,086
							I.S. 17 Total:	\$6,746,933
02	Manhattan	M033		P.S. 33 DSI	-0000799808	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	42,129
			M033	DSI	F0000784943	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	237,270
				DSI	F0000808310	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	894,673
							P.S. 33 Total:	\$1,174,072
02	Manhattan	M040		P.S. 40 DSI	-0000798365	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	856,241

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			M040	DS	F0000822045	New/Retrofit Telephone/Intercom Systems	2015	201,694
							P.S. 40 Total:	\$1,057,935
02	Manhattan	M041		P.S. 41				
			M041	DS	F0000808375	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 41 Total:	\$101,351
02	Manhattan	M042		P.S. 42				
			M042	DS	F0000808393	State of Good Repair - System Replacements -	2016	50,675
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						Other		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M042	DSF	-0000822065	New/Retrofit Telephone/Intercom Systems	2015	240,989
							P.S. 42 Total:	\$291,664
02	Manhattan	M047		J.H.S. 47 (SCH FOR THE	DEAF)		
				DSF	-0000785113	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,449,229
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000785119	State of Good Repair - System Replacements - Exterior Masonry	2018	567,532
			M047	50	A0000030133	EXTERIOR:EXTERIOR WALLS	2018	1 655 060
						State of Good Repair - System Replacements - Parapets		1,655,969
			M047	DSF	F0000808489	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	251,351
			M047	DSF	-0000823645	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
				DSF	-0000801088	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2018	1,312,100

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			M347	DS	F0000776051	IP Surveillance Camera Installation	2015	796,299
						J.H.S. 47 (SCH FOR	THE DEAF) Total:	\$6,192,108
02	Manhattan	M070		I.S. 70				
			M414	DS	F0000821970	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,336,751
				DS	F0000798359	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	585,395
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			M312	DS	F0000808720	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2017	1,395,806
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DS	F0000799809	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
			M312	DS	F0000799864	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							I.S. 70 Total:	\$4,415,149
02	Manhattan	M089		P.S./I.S. 8	39			
			M089	DS	F0000842684	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Floor Finish	2018	213,850

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	F0000799812	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
				DSF	F0000823574	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							P.S./I.S. 89 Total:	\$350,614
02	Manhattan	M104		I.S. 104				
				DSF	F0000785700	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,396,094
			M104	DSF	-0000785705	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	63,765
							I.S. 104 Total:	\$1,459,859
02	Manhattan	M111		P.S. 111				
			M111	DSF	-0000809099	State of Good Repair - System Replacements - Toilets-Students	2015	209,220
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P S 111 Total	\$209 220

P.S. 111 Total: \$209,220

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
02	Manhattan	M116		P.S. 116					
				DSI	F0000775600	State of Good Repair - Building Upgrade - Boiler Conversion	2015	3,935,492	
				DSI	F0000776204	State of Good Repair - Building Upgrade - Climate Control	2015	1,548,886	
				DSI	F0000799583	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	174,244	
							P.S. 116 Total:	\$5,658,622	
02	Manhattan	M124		P.S. 124 (ECF)				
					DSI	F0000785900	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,443,346
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent			
			M124	DSF	F0000831317	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2018	82,682	
						Other			
			M124	DSI	F0000776056	IP Surveillance Camera Installation	2015	645,606	

						FY -	
District	Danauah	Building		Cabaal Dusiaa	# Description	Construction	Tatal
District	Borough	ID	Org ID	School Projec	# Description	Start	Total
						P.S. 124 (ECF) Total:	\$2,171,634
02	Manhattan	M126		P.S. 126			
			M126	DSF00008437	3 State of Good Repair - System Replacements - Domestic Piping	2016	35,401
						P.S. 126 Total:	\$35,401
02	Manhattan	M130		P.S. 130			
				DSF00007860	9 State of Good Repair - Building Upgrade - Reinforcing Support Elements	2017	1,402,336
					INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEA NG WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE	RI	
				DSF00007998		2015	79,306
						P.S. 130 Total:	\$1,481,642
02	Manhattan	M131		I.S. 131			
				DSF00007774	7 Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	125,378
				DSF00008216	6 State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			M131	DSF00007860	Toilets-Students	2015	119,582
					FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							I.S. 131 Total:	\$778,196
02	Manhattan	M158		P.S. 158				
				DSF	0000775978	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2015	959,223
				DSF	0000763742	State of Good Repair - Building Upgrade - Flood Elimination	2015	2,272,970
				SCA	0000024913	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - System Replacements - Exterior Masonry	2015	20,040,497
				DSF	0000763744	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	3,916,082
				DSF	0000763743	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,604,635
				DSF	0000777440	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2015	3,912,312
							P.S. 158 Total:	\$33,705,719
02	Manhattan	M167		I.S. 167				
-					0000786448	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,096,706

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000821602	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				SC	A0000024953	State of Good Repair - System Replacements - Exterior Masonry	2016	4,481,397
				DS	F0000786449	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	1,786,456
				DS	F0000786456	State of Good Repair - System Replacements - Paved Area-Concrete SITE:PAVING - STUDENT NON-USE:Concrete	2016	366,489
				DS	F0000809787	SITE:SIDEWALKS:Site Sidewalk and Walkways State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2015	217,725
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
				DS	F0000799887	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	558,689
							I.S. 167 Total:	\$9,040,698
02	Manhattan	M183		P.S. 183 DS	F0000844146	Domestic Piping	2017	1,510,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
				DS	F0000798268	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,513,010
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798269	State of Good Repair - Building Upgrade - Climate Control	2017	1,280,719
						CLIMATE CONTROL SYSTEM		
				DS	F0000777289	State of Good Repair - Building Upgrade - Flood Elimination	2015	374,348
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	F0000786577	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	19,575
				DS	F0000799592	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	15,040
				DS	F0000753130	State of Good Repair - System Replacements - Exterior Masonry	2015	13,129,556
				DS	F0000777290	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,107,050
				DSI	F0000799938	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	878,450
							P.S. 183 Total:	\$22,827,748

02 Manhattan M198 **P.S. 198**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M198	DS	F0000775602	State of Good Repair - Building Upgrade - Boiler Conversion	2015	4,484,713
			M198	DS	F0000764140	State of Good Repair - Building Upgrade - Climate Control	2015	1,545,131
						CLIMATE CONTROL SYSTEM		
				DS	F0000786769	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2019	162,854
				DS	F0000786768	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2019	580,657
				DS	F0000786770	State of Good Repair - System Replacements - Windows	2019	9,777,265
						EXTERIOR:WINDOWS		
							P.S. 198 Total:	\$16,550,620
02	Manhattan	M234		P.S. 234				
			M234	SC	A0000027772	State of Good Repair - System Replacements - Paved Area-Concrete	2016	1,027,547
							P.S. 234 Total:	\$1,027,547
02	Manhattan	M660		SCHL OF	THE FUTURE (OLD BACON)		
				DS	F0000810787	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	152,027

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SCHL OF THE FUTURE (O	LD BACON) Total:	\$152,027
02	Manhattan	M777		FIT				
				[DSF0000844033	Educational Enhancements - Educational Enhancements - Library Upgrades	2016	701,240
				[DSF0000844034	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	276,130
				[DSF0000843923	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2017	8,905,556
			M000	[DSF0000843776	State of Good Repair - System Replacements - Domestic Piping	2017	516,486
			M000	[DSF0000843775	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2017	2,997,049
			M000	[DSF0000843777	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation	2017	423,784
			M000	[DSF0000843778	<i>State of Good Repair - System Replacements - Heating Plant Upgrade</i> Ventilation	2017	2,333,039
				[DSF0000843779	State of Good Repair - System Replacements - Heating Plant Upgrade	2017	251,818
			M000	[DSF0000843780	State of Good Repair - System Replacements - Heating <i>Plant Upgrade</i> Ventilation	2017	481,204

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000844030	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2016	801,137
				DSI	F0000844031	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2016	780,000
				DSI	F0000844035	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2017	4,611,115
							FIT Total:	\$23,078,558
03	Manhattan	M009		P.S. 9				
				DS	F0000799578	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	142,240
							P.S. 9 Total:	\$142,240
03	Manhattan	M044		I.S. 44				
			M452	DSI	F0000821820	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	548,388
				DSI	F0000798300	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,204,639

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M245	DS	F0000739460	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,873,974
						FIRE ALARM SYSTEM		
						PUBLIC ADDRESS SYSTEM		
			M245	DS	F0000808430	State of Good Repair - System Replacements -	2016	200,675
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 44 Total:	\$3,827,676
03	Manhattan	M054		I.S. 54				
				DS	F0000808563	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,334,656
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000785205	State of Good Repair - System Replacements - Exterior	2017	1,355,149
						Masonry		
						EXTERIOR:AREAWAY		
						EXTERIOR: EXTERIOR WALLS		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
							I.S. 54 Total:	\$2,689,805
03	Manhattan	M075		P.S. 75				
			M075	DS	F0000823602	Heating Plant Upgrade	2016	1,124,832

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000775607	State of Good Repair - Building Upgrade - Boiler Conversion	2016	7,701,559
				DS	F0000775608	State of Good Repair - Building Upgrade - Climate Control	2016	1,098,741
				DS	F0000822223	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,149,109
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			M075	DS	F0000785406	State of Good Repair - System Replacements - Toilets-Students	2016	179,036
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 75 Total:	\$11,253,277
03	Manhattan	M076		P.S. 76				
			M076	DS	F0000785426	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	107,242
			M076	DS	F0000808779	State of Good Repair - System Replacements - Toilets-Students	2017	79,814

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 76 Total:	\$187,056
03	Manhattan	M084		P.S. 84				
			M084	DSF	0000830924	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping	2018	116,681
						Other		
			M084	DSF	0000822054	New/Retrofit Telephone/Intercom Systems	2015	225,628
			M084	DSF	0000776053	IP Surveillance Camera Installation	2015	513,282
							P.S. 84 Total:	\$855,591
03	Manhattan	M087		P.S. 87				
				DSF	0000830939	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Ceiling	2018	109,534
			M087	DSF	0000808861	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 87 Total:	\$269,162
03	Manhattan	M088		I.S. 88				
			M415	DSF	0000776027	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	459,463
			M415	DSF	0000843672	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	1,721,746
				DSF	0000843673	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Gymnasium Upgrade INTERIOR:GYMNASIUM:Seating	2016	159,628
			M415	DSF	0000843874	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	392,199
			M860	DSF	0000843875	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	499,784
				DSF	0000843677	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2018	2,487,087
				DSF	0000799581	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	113,645

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000830960	State of Good Repair - System Replacements - Domestic Piping Waste System	2016	47,751
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
							I.S. 88 Total:	\$5,881,303
03	Manhattan	M113		P.S. 241				
				DS	F0000731099	State of Good Repair - Building Upgrade - Boiler Conversion	2016	4,937,187
						HEATING PLANT:BOILER AUXILIARIES		
				DS	F0000718946	State of Good Repair - Building Upgrade - Climate Control	2016	1,279,127
						CLIMATE CONTROL SYSTEM		
			M241	DS	F0000785769	State of Good Repair - Building Upgrade - Flood Elimination	2017	1,737,340
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799582	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	166,933
			M241	DS	F0000823647	State of Good Repair - System Replacements - Toilets-Students	2016	101,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 241 Total:	\$8,221,938
03	Manhattan	M118		I.S. 118				
				DSI	-0000844706	Educational Enhancements - Educational Enhancements - Accessibility	2018	155,524
				DSI	-0000821969	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	370,920
				DSI	-0000799584	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	416,617
				DSI	-0000763233	State of Good Repair - System Replacements - Exterior Masonry	2017	7,449,703
						EXTERIOR: EXTERIOR WALLS		
				DSI	-0000763232	State of Good Repair - System Replacements - Parapets	2017	3,334,551
						EXTERIOR:PARAPETS		
				DSI	-0000763231	State of Good Repair - System Replacements - Roofs	2017	4,493,805
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
							I.S. 118 Total:	\$16,221,120
03	Manhattan	M144		P.S. 242 (OLD P144)			
				DSI	-0000799959	Educational Enhancements - Educational Enhancements - Accessibility	2016	365,826
			M242	DSI	-0000798379	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
			M242	DS	F0000798381	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
			M242	DS	F0000786204	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						P.S. 242	(OLD P144) Total:	\$6,389,536
03	Manhattan	M149		P.S. 149 ((TANDEM M207)			
			M811		F0000843671	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	1,116,686
			M149	DS	F0000843760	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	772,726
				DS	F0000786253	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	870,905
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M149	DS	F0000822115	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	251,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M149	DSF	-0000823650	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						P.S. 149 (TA	NDEM M207) Total:	\$3,113,019
03	Manhattan	M163		P.S. 163				
				DSF	-0000799702	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	130,826
			M163	DSF	-0000822265	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	2,317,918
							P.S. 163 Total:	\$2,448,744
03	Manhattan	M165		P.S. 165				
				DSF	-0000777681	State of Good Repair - System Replacements - Exterior Masonry	2016	6,899,055
				DSF	-0000799928	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	1,245,686
							P.S. 165 Total:	\$8,144,741
03	Manhattan	M166		P.S. 166				
				DSF	-0000786434	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	39,363
				DSF	-0000799590	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	138,300
				DSF	-0000752875	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	2,279,253

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			M166	DSI	-0000776057	IP Surveillance Camera Installation	2015	542,133
							P.S. 166 Total:	\$2,999,049
03	Manhattan	M191		P.S. 191				
			M191	DSI	-0000786671	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSI	-0000809992	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	163,847
							P.S. 191 Total:	\$199,110
03	Manhattan	M199		P.S. 199				
				DSI	-0000799594	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	597,624
							P.S. 199 Total:	\$597,624
03	Manhattan	M207		P.S. 207 (TANDEM M149)			
				DSI	-0000798362	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,156,108
						P.S. 207 (TAI	NDEM M149) Total:	\$1,156,108
03	Manhattan	M208		P.S. 208 (TANDEM M185)			
				DSI	-0000764203	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AWNINGS AND CANOPIES	2015	3,399,748

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS		
				DS	F0000764202	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	3,407,099
				DS	F0000764201	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	5,328,336
				DS	F0000799479	State of Good Repair - System Replacements - Windows	2015	879,098
						EXTERIOR:WINDOWS		\$13,014,281
04	Manhattan	M045		I.S. 45		P.3. 200 (IAN	DEM M185) Total:	φ13,014,201
			M138	DS	F0000823630	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,079,328
			M409	DS	F0000844114	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	906,000
			M409	DS	F0000808442	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS	2019	1,771,128
				DS	F0000785076	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,829,838

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M409	DSF	0000830519	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS	2019	503,588
			M045	DSF	0000808446	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	101,351
04	Manhattan	M050		P.S. 50 (U	DC & ECF)		I.S. 45 Total:	\$8,191,233
			M050	•	0000821759	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	138,385

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000785154	State of Good Repair - Building Upgrade - Lighting	2015	1,519,731
						Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M050	DSI	F0000808528	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						P.S. 50	(UDC & ECF) Total:	\$1,759,467
04	Manhattan	M072		P.S. 72				
				DSI	F0000821804	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2017	1,152,764
				DS	F0000762771	State of Good Repair - Building Upgrade - Flood Elimination	2016	239,355
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000785379	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	943,554
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M072	DS	\$F0000739811	State of Good Repair - System Replacements - Auditorium Upgrade AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Fluorescent AUDITORIUM:HOUSE LIGHTING:Lighting Fixture - Incandescent AUDITORIUM:LOCAL SOUND SYSTEM AUDITORIUM:PROJECTION SYSTEM AUDITORIUM:THEATER LIGHTING SYSTEM:Theater Lighting INTERIOR:AUDITORIUM:Fixed Seating INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Floor Finish INTERIOR:AUDITORIUM:Window Curtains/Shades/Blinds	2016	1,531,989
				DS	F0000762786	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent CAFETERIA:LOCAL SOUND SYSTEM INTERIOR:CAFETERIA:Fixed Equipment INTERIOR:CAFETERIA:Floor Finish	2016	423,597
				DS	F0000762773	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2016	12,950,115

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000762772	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	3,130,757
				DS	F0000801023	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	833,410
				DS	F0000801070	System Expansion - New Physical Education Facilities - Playgrounds	2016	834,261
							P.S. 72 Total:	\$22,039,802
04	Manhattan	M083		P.S. 83				
				DS	F0000822096	Educational Enhancements - Educational Enhancements - Accessibility	2019	9,036,891
			M083	DS	F0000739877	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2015	1,741,512
						PUBLIC ADDRESS SYSTEM		
			M083	DS	F0000830899	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	67,371
			M083	DS	F0000808827	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	159,628
						Other		
			M083	DS	F0000822061	New/Retrofit Telephone/Intercom Systems	2015	207,083

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 83 Total:	\$11,212,485
04	Manhattan	M096		P.S. 96				
				DSF	-0000821841	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	534,006
							P.S. 96 Total:	\$534,006
04	Manhattan	M099		I.S. 99				
				DSF	-0000808993	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	143,228
						Other		
			M635	DSF	-0000822062	New/Retrofit Telephone/Intercom Systems	2015	188,176
							I.S. 99 Total:	\$331,404
04	Manhattan	M101		P.S. 101				
			M811	DSF	-0000844090	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	755,000
			M811	DSF	-0000821758	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	154,123

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M375	DSF	F0000843877	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	98,035
			M375	DSF	F0000845620	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	80,000
						Other		
			M375	DSF	-0000776055	IP Surveillance Camera Installation	2015	687,090
							P.S. 101 Total:	\$1,774,248
04	Manhattan	M102		P.S. 102				
			M102	DSF	-0000798322	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,673,992
			M102	DSF	-0000798335	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,326,403
				DSF	-0000798366	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	888,240
			M102	DSF	-0000809022	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2017	1,472,778

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		
			M102	DS	F0000785684	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 102 Total:	\$8,396,676
04	Manhattan	M108		P.S. 108				
				DS	F0000798339	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	5,819,466
				DS	F0000798341	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2017	1,632,436
				DS	F0000831121	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2017	1,118,333
				DS	F0000844074	State of Good Repair - System Replacements - Kitchen Areas	2017	335,220
							P.S. 108 Total:	\$8,905,455
04	Manhattan	M112		P.S. 112 (TANDEM M206)			
				DS	F0000752353	State of Good Repair - Building Upgrade - Climate Control	2015	668,464
				DS	F0000799443	State of Good Repair - Building Upgrade - Flood Elimination	2015	4,184,768

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000799440	State of Good Repair - Building Upgrade - Interior Spaces	2015	1,409,377
				DSF	-0000799442	State of Good Repair - System Replacements - Electrical Systems	2015	561,960
				DSF	-0000799441	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	6,000,860
						P.S. 112 (T	ANDEM M206) Total:	\$12,825,429
04	Manhattan	M117		J.H.S. 117	,			
			M138	DSF	-0000844094	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	65,300
				DSF	-0000785833	Educational Enhancements - Educational Enhancements - Science Lab Upgrades INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:EMERGENCY GAS SHUT-OFF VALVE SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2018	1,799,898

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798304	State of Good Repair - Building Upgrade - Lighting	2015	1,583,157
						Fixtures		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000799469	State of Good Repair - System Replacements - Exterior	2015	1,349,219
						Masonry		
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000763210	State of Good Repair - System Replacements - Parapets	2015	4,317,075
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
				DS	F0000763209	State of Good Repair - System Replacements - Roofs	2015	4,968,390
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						Other		
			M012	DS	F0000822063	New/Retrofit Telephone/Intercom Systems	2015	268,821
							J.H.S. 117 Total:	\$14,351,860
04	Manhattan	M121		P.S. 38 (C	DLD M121)			
				DS	F0000785861	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	743,456
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M038	D	SF0000809210	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						F	P.S. 38 (OLD M121) Total:	\$994,807
04	Manhattan	M146		P.S. 146				
					SF0000809566	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	138,732
			M146	D	SF0000823649	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 146 Total:	\$298,360
04	Manhattan	M155		P.S. 155				
			M155	D	SF0000786334	State of Good Repair - System Replacements - Heat Plant Upgrade	ing 2015	35,263
			M155	D	SF0000809665	State of Good Repair - System Replacements - Toilets-Students	2017	159,628

		Duilding					FY -	
District	Borough	Building ID	Org ID	School	Project #	Description	Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 155 Total:	\$194,891
04	Manhattan	M171		P.S. 171				
			M171	DS	F0000844009	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	59,146
			M171	DSI	F0000786496	State of Good Repair - System Replacements - Toilets-Students	2015	170,564
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
				DS	F0000821722	State of Good Repair - System Replacements - Toilets-Students	2015	95,106
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 171 Total:	\$324,816
04	Manhattan	M206		P.S. 206 (TANDEM M112)			

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M206	DSF	0000843785	Classroom Connectivity	2016	52,261
						P.S. 206	(TANDEM M112) Total:	\$52,261
05	Manhattan	M010		I.S. 10 (TA	NDEM M200)			
				DSF	F0000762099	Educational Enhancements - Educational Enhancements - Science Lab Upgrades CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE LAB:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture Fluorescent SCIENCE LAB SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture Fluorescent	ent e -	5,824,318
				DSF	0000798266	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,673,992
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	F0000784731	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,326,403

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799579	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	685,105
				DS	F0000799807	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	132,895
						I.S. 10 (TAN	IDEM M200) Total:	\$12,642,713
05	Manhattan	M030		P.S. 30				
			M138	DS	F0000777288	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	298,748
			M138	DS	F0000821750	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	71,934
			M030	DS	F0000843867	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	136,500
			M138	DS	F0000843872	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	241,539
				DS	F0000798360	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,723,395

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 30 Total:	\$2,472,116
05	Manhattan	M036		P.S. 36				
				DSF	0000798361	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,021,467
			M036	DSF	0000808345	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,628
							P.S. 36 Total:	\$1,181,095
05	Manhattan	M043		I.S. 172 (O	LD 43)			
			M286	DSF	0000821821	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	568,384
			M367	DSF	0000821822	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	528,592

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M410	DSF	-0000821824	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	541,252
			M286	DSF	-0000844156	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	755,000
				DSF	-0000799483	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	3,022,864
			M286	DSF	-0000821760	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	46,759
			M369	DSF	-0000821761	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	46,759
			M286	DSF	-0000845584	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	59,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M367	DS	SF0000865727	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	85,000
			M367	DS	SF0000865728	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	70,000
				DS	F0000821613	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DS	SF0000739453	State of Good Repair - System Replacements - Gymnasium Upgrade	2015	1,334,450
						FIXTURES:STUDENT:Locker Room Shower GYMNASIUM:LIGHTING:Lighting Fixture - HID GYMNASIUM:SCOREBOARD INTERIOR:GYMNASIUM:Floor Finish		
							I.S. 172 (OLD 43) Total:	\$7,591,296
05	Manhattan	M046		P.S. 46				
_				DS	SF0000799580	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	186,539
							P.S. 46 Total:	\$186,539
05	Manhattan	M092		P.S. 92				
			M092	DS	SF0000823646	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	732,879

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M092	DSI	F0000801028	Interior Spaces	2018	1,787,859
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
			M092	DSI	F0000808919	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 92 Total:	\$2,772,089
05	Manhattan	M123		P.S. 123				
			M123	DSI	F0000785880	State of Good Repair - Building Upgrade - Flood Elimination	2017	6,091,603
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			M123	DSI	F0000823648	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 123 Total:	\$6,251,231

05 Manhattan M125 **P.S. 125**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000844705	Educational Enhancements - Educational Enhancements - Accessibility	2018	121,533
			M362	DSF	-0000798164	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	557,081
				DSF	-0000785922	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	865,582
				DSF	-0000799813	SPACE:LIGHTING:Lighting Fixture - Fluorescent State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			M125	DSF	-0000809264	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 125 Total:	\$1,778,868
05	Manhattan	M129		P.S. 129				
				DSF	-0000821657	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2017	1,258,549
			M129	DSF	-0000809324	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,628

P.S. 129 Total: \$1,418,177

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
05	Manhattan	M133		P.S. 133				
			M133	DSI	F0000763455	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,200,047
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
			M133	DSI	F0000809404	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 133 Total:	\$1,359,675
05	Manhattan	M161		P.S. 161				
			M161	DSI	F0000786370	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 161 Total:	\$35,263
05	Manhattan	M175		P.S. 175				
			M175	DSI	F0000798456	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			M175	DSI	F0000786533	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,277,027

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000786534	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,276,988
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000799817	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
			M175	DSI	F0000809867	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 175 Total:	\$7,271,339
05	Manhattan	M194		P.S. 194				
				DSI	F0000786707	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	756,323
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 194 Total:	\$756,323
05	Manhattan	M195		TERENCE	D. TOLBERT I	EDUCATION COMPLEX		
			M514	DSI	F0000844165	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	755,000
						TERENCE D. TOLBERT EDUCATIO	N COMPLEX Total:	\$755,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
05	Manhattan	M197		P.S. 197				
				DS	F0000764120	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,630,095
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000764126	State of Good Repair - System Replacements -	2016	1,700,578
						Electrical Systems		
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH SWITCHBOARD		
			M197	De	F0000810070		2017	70 914
			W197	03	F0000810070	State of Good Repair - System Replacements - Toilets-Students	2017	79,814
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 197 Total:	\$3,410,487
							F.S. 197 Total.	φ3,410,407
06	Manhattan	M004		P.S. 4				
				DS	F0000777247	State of Good Repair - System Replacements - Exterior Masonry	2015	3,231,208
						EXTERIOR: EXTERIOR WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000784636	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	2,285,140
				DSI	F0000784635	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,556,663
							P.S. 4 Total:	\$7,073,011
06	Manhattan	M005		P.S. 5				
			M005	DSI	F0000799525	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	1,503,952
				DSI	F0000808017	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	2016	50,593
				DSI	F0000823572	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DSI	F0000800299	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	5,358,741
				DSI	F0000800300	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	4,832,298
				DSI	F0000821734	State of Good Repair - System Replacements - Windows	2016	3,520,403
						EXTERIOR:WINDOWS		

P.S. 5 Total: \$15,340,793

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
06	Manhattan	M028		P.S. 28				
				DS	F0000808268	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,370,330
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 28 Total:	\$1,370,330
06	Manhattan	M048		P.S. 48				
				DS	F0000821791	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,577,306
			M048	DS	F0000821796	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	1,429,113
			M048	DS	F0000865720	State of Good Repair - System Replacements - Domestic Piping	2018	55,096
							P.S. 48 Total:	\$5,061,515
06	Manhattan	M052		I.S. 52				
			M052	DS	F0000800194	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	950,720
				DS	F0000799484	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	2016	2,102,322

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWITCHBOARD		
				D	SF0000785181	State of Good Repair - Building Upgrade - Flood Elimination	2018	1,960,591
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				D	SF0000785179	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,243,847
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				D	SF0000785184	State of Good Repair - System Replacements - Exterior	2018	1,035,901
						Masonry		
						EXTERIOR: EXTERIOR WALLS		
			M052	D	SF0000808550	State of Good Repair - System Replacements -	2015	193,921
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						INTERIOR:TOILET ROOMS - STUDENTS		* 7 407 000
							I.S. 52 Total:	\$7,487,302
06	Manhattan	M090		I.S. 90				
				D	SF0000844707	Educational Enhancements - Educational Enhancements - Accessibility	2018	82,882

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M319	DS	F0000821762	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
			M324	DS	F0000821763	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
			M138	DS	F0000821764	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
				DS	F0000844130	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	119,189
			M319	DS	F0000844136	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	303,814
			M319	DS	F0000845597	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2017	47,000
				DS	F0000799955	State of Good Repair - System Replacements - Heating Plant Upgrade	2019	390,951

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Ventilation		
						VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK		
				DSF	-0000808901	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							I.S. 90 Total:	\$1,123,642
06	Manhattan	M093		P.S./I.S. 2 [,]	10			
						Other		
			M210	DSF	-0000843782	Classroom Connectivity	2016	170,802
							P.S./I.S. 210 Total:	\$170,802
06	Manhattan	M098		P.S. 98				
				DSF	-0000785618	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	435,066
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						<u> </u>	P.S. 98 Total:	\$435,066
06	Manhattan	M115		P.S. 115				
			M115	DSF	-0000799499	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	901,674
				DSF	-0000809132	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,190,752

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000809139	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
			M115	DS	F0000809140	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			M115	DS	F0000822066	New/Retrofit Telephone/Intercom Systems	2015	170,969
							P.S. 115 Total:	\$2,760,517
06	Manhattan	M128		P.S. 128				
				DS	F0000775601	State of Good Repair - Building Upgrade - Boiler Conversion	2017	4,933,451
				DS	F0000763346	State of Good Repair - Building Upgrade - Climate Control	2017	1,493,231
						CLIMATE CONTROL SYSTEM		
							P.S. 128 Total:	\$6,426,682
06	Manhattan	M132		P.S. 132				
			M132	DS	F0000809387	State of Good Repair - System Replacements - Fencing SITE:FENCES	2016	2,264,907

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000823575	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DSF	-0000786055	State of Good Repair - System Replacements - Toilets-Students	2015	4,722,180
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 132 Total:	\$7,061,893
06	Manhattan	M143		I.S. 143				
				DSF	-0000763579	Educational Enhancements - Educational Enhancements - Science Lab Upgrades CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE PREP ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM:EMERGENCY SHUT-OFF POWER SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2016	3,023,744
				DSF	-0000786181	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	2,062,936

		Duilding				FY -	
District	Borough	Building ID	Org ID	School Project #	Description	Construction Start	Total
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M143	DSF0000786187	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	397,277
			M143	DSF0000809511	TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent State of Good Repair - System Replacements -	2015	251,351
					Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
					Other		
			M143	DSF0000822067	New/Retrofit Telephone/Intercom Systems	2015	282,827
						I.S. 143 Total:	\$6,018,135
06	Manhattan	M152		P.S. 152			
			M152	DSF0000786275	State of Good Repair - Building Upgrade - Flood Elimination	2018	3,048,410

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DS	SF0000799588	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	280,740
			M152	DS	SF0000740683	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,487,934
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER ALARM VALVE ASSEMBLY		
			M152	DS	SF0000809604	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 152 Total:	\$4,976,712
06	Manhattan	M153		P.S. 153				
				DS	SF0000786294	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,672,663
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000799816	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
							P.S. 153 Total:	\$1,751,969
06	Manhattan	M164		I.S. 164				
				DSI	F0000799589	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	263,249
			M326	DSI	F0000809737	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,628
						Other		
			M326	DS	F0000843784	Classroom Connectivity	2016	434,129
							I.S. 164 Total:	\$857,006
06	Manhattan	M173		P.S. 173				
				DSI	F0000809852	State of Good Repair - System Replacements - Paved Area-Concrete SITE:RETAINING WALLS	2016	73,949
						Other		
			M173	DSI	F0000822059	New/Retrofit Telephone/Intercom Systems	2015	235,850

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 173 Total:	\$309,799
06	Manhattan	M178		P.S. 178				
				DSF	0000821714	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	49,931
						HEATING PLANT:BOILER SYSTEM		
				DSF	0000823576	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							P.S. 178 Total:	\$124,737
06	Manhattan	M187		P.S./I.S. 18	37			
				DSF	0000786591	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	571,312
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M187	DSF	0000809923	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S./I.S. 187 Total:	\$822,663

06 Manhattan M189 **P.S. 189**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
			M189	DSF	F0000821906	State of Good Repair - System Replacements - Heating Plant Upgrade GAS FIRED FURNACE GAS SERVICE:GAS DISTRIBUTION PIPING HEATING	2015	29,907
			M189	DSF	-0000809958	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2017	159,628
							P.S. 189 Total:	\$189,535
06	Manhattan	M192		P.S. 192				
			M192	DSF	-0000821879	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	410,407
				DSF	-0000821805	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2018	1,477,868
				DSF	F0000786685	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,005,522
							P.S. 192 Total:	\$2,893,797

06 Manhattan M218 I.S. 218

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M218	DS	F0000810159	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							I.S. 218 Total:	\$155,366
06	Manhattan	M528		I.S. 528				
				DS	F0000764641	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2015	1,277,397
							I.S. 528 Total:	\$1,277,397
06	Manhattan	M859		I.S. 143 M	IINISCHOOL			
						Other		
			M971	DS	F0000843781	Classroom Connectivity	2016	164,862
						I.S. 143	MINISCHOOL Total:	\$164,862
06	Manhattan	M898		P.S. 18				
				DS	F0000787656	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	529,671
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			M018	DS	F0000823653	State of Good Repair - System Replacements -	2017	159,628
						Toilets-Students FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 18 Total:	\$689,299
75M	Manhattan	M058		P.S. 35 (O	LD 58/MNHT H	S)		
				DSF	-0000799774	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	36,552
				DSF	-0000808623	State of Good Repair - System Replacements - Toilets-Students	2015	530,598
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						P.S. 35 (OLD 5	8/MNHT HS) Total:	\$567,150
75M	Manhattan	M079		P.S. 79 (M	ULT. HANDICA	AP)		
				DSF	-0000777495	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2016	87,219
				DSF	-0000785434	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,134,861
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			M079	DSF	-0000785442	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	-0000799810	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	42,129

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						P.S. 79 (MUL	T. HANDICAP) Total:	\$1,299,472
75M	Manhattan	M169		P.S. 169 (ECF)			
				DS	F0000786468	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	973,675
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000831867	State of Good Repair - System Replacements - Roofs	2017	37,247
						1	P.S. 169 (ECF) Total:	\$1,010,922
75M	Manhattan	M751		P.S. 751 (CAR.DEV/OLD	25)		
				DS	F0000787504	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	534,821
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						P.S. 751 (CAR	R.DEV/OLD 25) Total:	\$534,821
75M	Manhattan	M841		P.S. 811 (OLD P148/LIVII	NGS HS)		
			M811	DS	F0000798306	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M811	DS	F0000798309	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
						P.S. 811 (OLD P14	8/LIVINGS HS) Total:	\$5,988,447
78M	Manhattan	M066		RICHARE	O R GREEN HS	OF TEACHING		
				DS	F0000785343	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	745,017
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						RICHARD R GREEN HS	OF TEACHING Total:	\$745,017
78M	Manhattan	M081		MID MAN	ADULT LRNG	CTR (81)		
				DS	F0000799500	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	638,118
			K755	DS	F0000799521	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	400,808
			K755	DS	F0000799950	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	308,169
			M984	DS	F0000822215	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,797,033
			K755	DS	F0000845616	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2018	798,142

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799811	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
				DS	F0000808808	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	55,596
						HEATING PLANT:BOILER SYSTEM		
						MID MAN ADULT LRN	G CTR (81) Total:	\$5,059,824
78M	Manhattan	M097		BARD CO	OLLEGE HS (OL	D M097)		
				DS	F0000808949	State of Good Repair - Building Upgrade - Flood Elimination	2016	2,678,713
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000798378	State of Good Repair - Building Upgrade - Lighting	2016	899,404
				20		Fixtures	2010	000,101
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000798565	State of Good Repair - System Replacements - Exterior Masonry	2016	1,643,874
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000821636	State of Good Repair - System Replacements - Exterior Masonry	2016	2,772,665
						EXTERIOR:EXTERIOR WALLS		
				DS	F0000808952	State of Good Repair - System Replacements - Parapets	2016	1,430,264

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:PARAPETS		
				DS	F0000808951	State of Good Repair - System Replacements - Roofs	2016	929,689
						EXTERIOR:PLAZA DECK		
						EXTERIOR:ROOFING:Roofing		
			MCOC			EXTERIOR:ROOFING:Specialties	0040	404.054
			M696	05	F0000808955	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						Other		
			M696	DS	F0000776054	IP Surveillance Camera Installation	2015	482,574
						BARD COLLEGE HS	(OLD M097) Total:	\$10,938,534
78M	Manhattan	M136		I.S. 136				
				DS	F0000799586	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	133,946
				DS	F0000821612	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	501,072
			M148	DS	F0000786109	State of Good Repair - System Replacements - Toilets-Students	2015	161,366
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							I.S. 136 Total:	\$796,384
78M	Manhattan	M435		MANHTN C	T FOR MATH	& SCI. HS		
				DSF	0000821616	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			M435	DSF	0000810214	State of Good Repair - System Replacements - Toilets-Students	2015	125,675
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						MANHTN CT FOR MAT	TH & SCI. HS Total:	\$658,911
78M	Manhattan	M440		BAYARD R		ATIONAL COMP		
				DSF	0000777499	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	115,978
				DSF	0000799595	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	442,741
				DSF	0000799776	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	84,453
			M313	DSF	0000832320	State of Good Repair - System Replacements - Domestic Piping Waste System	2018	116,944

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
				DSF	-0000822656	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310
						BAYARD RUSTIN EDUCATIO	NAL COMP Total:	\$1,071,426
78M	Manhattan	M445		SEWARD	PARK HS			
				DSF	-0000799777	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	123,714
				DSF	-0000821619	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			M294	DSF	-0000799788	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	F0000832328	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING:Heating Coil In Ductwork HEATING:Radiator/Convector/Fin Tube HEATING:Steam supplied by External Sources	2015	80,027
						SEWAR	D PARK HS Total:	\$772,240
78M	Manhattan	M446		UNIVERSI		RHOOD		
			M448	DSF	-0000741361	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	2,545,594

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						PUBLIC ADDRESS SYSTEM		
			M448	DS	F0000786971	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	y 2016	2,254,380
						MOTOR STARTER/CONTACTOR VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
			M448	DS	F0000786964	State of Good Repair - System Replacements -	2015	147,921
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							EIGHBORHOOD Total:	\$4,947,895
78M	Manhattan	M451		LIBERTY	HS			
				DS	F0000799597	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	106,335
							LIBERTY HS Total:	\$106,335
78M	Manhattan	M460		WASHING	GTON IRVING HS	3		
			M374	DS	F0000775870	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	483,276

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M460	DS	F0000798601	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	7,642,226
			M460	DS	F0000799937	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	501,950
			M374	DS	F0000844086	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,132,500
			M460	DS	F0000777270	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2015	3,139,392
				DS	F0000799953	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2016	1,011,588
				DS	F0000799598	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	542,700
				DS	F0000799778	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	120,248
				DS	F0000810292	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM	2018	2,052,910
				DS	F0000821608	PUBLIC ADDRESS SYSTEM State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M374	DS	6F0000832371	State of Good Repair - System Replacements - Electrical Systems PANEL BOARD TRANSFORMER	2018	8,264,143
				DS	\$F0000764372	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2016	27,343,786
				DS	F0000821658	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Floor Finish	2016	558,005
			M174	DS	F0000786997	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000810308	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	95,270
				DS	F0000786994	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	8,661,748
				DS	F0000786993	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	5,752,542
				DS	F0000799952	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2016	11,812,472
						Other		
				DS	SF0000843852	IP Surveillance Camera Installation	2017	550,186

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						WASHINGTON	IRVING HS Total:	\$80,233,441
78M	Manhattan	M465		G. WASHI	NGTON HS ED	UC. CAMPUS		
				DSF	-0000777500	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	244,734
				DSF	-0000799599	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	583,830
			M463	DSF	-0000787010	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	120,339
				DSF	-0000821611	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	501,072
			M462	DSF	-0000787021	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	-0000799818	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
				DSF	-0000810324	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	260,353
						HEATING PLANT:BOILER SYSTEM		
						G. WASHINGTON HS EDU	C. CAMPUS Total:	\$1,807,549
78M	Manhattan	M470		LOUIS D.	BRANDEIS HS			
				DSF	-0000764420	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2019	1,406,504

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000764431	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2019	832,078
						LOUIS D. BR	ANDEIS HS Total:	\$2,238,582
78M	Manhattan	M475		HEALTH	PROFESSIONS	HS (OL STY)		
				DSI	F0000800337	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	949,686
				DSI	F0000777501	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	234,070
				DSI	F0000799600	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	274,687
			M407	DSI	F0000787067	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						HEALTH PROFESSIONS H	IS (OL STY) Total:	\$1,493,706
78M	Manhattan	M477		STUYVES	SANT HS (NEW)			
				DSI	F0000822667	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2019	91,249
							T HS (NEW) Total:	\$91,249
78M	Manhattan	M480		JULIA RIC	CHMAN ED. CO		- (/ ••••••	+,
				DSI	F0000799601	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	474,337

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						JULIA RICHMAN E	D. COMPLEX Total:	\$474,337
78M	Manhattan	M485		FIORELLO	O LAGUARDIA	HS		
			M485	DSI	F0000741529	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	3,546,200
				DSI	F0000741533	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	5,728,881
			M485	DSI	F0000832506	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	1,159,915
						AIR CONDITIONING:Cooling Tower		
						FIORELLO LA	GUARDIA HS Total:	\$10,434,996
78M	Manhattan	M488		MIDTOWN	N EAST CAMPL	JS		
				DSI	F0000844704	Educational Enhancements - Educational Enhancements - Accessibility	2018	121,657
						Other		
				DSI	F0000799890	IP Surveillance Camera Installation	2016	115,145
						MIDTOWN E	AST CAMPUS Total:	\$236,802
78M	Manhattan	M490		MARTIN L	UTHER KING,	JR. HS		
				DSI	F0000799602	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	810,765

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M494	DSI	F0000844150	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2018	81,849
						Other		
			M494	DSI	F0000822038	New/Retrofit Telephone/Intercom Systems	2015	577,636
						MARTIN LUTH	ER KING, JR. HS Total:	\$1,470,250
78M	Manhattan	M495		PARK EA	ST HS			
				DSI	F0000787172	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	581,180
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescen		
							PARK EAST HS Total:	\$581,180
78M	Manhattan	M501		ARTHUR	SCHOMBURG	HS (IS 201)		
			M157	DSI	F0000844115	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	906,000
				DSI	F0000798316	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	518,789
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescen	t	

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799819	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			M469	DS	F0000832581	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation AIR CONDITIONING:Chilled Water System:Central	2019	222,514
						Station Air Handler MOTOR STARTER/CONTACTOR VENTILATION:Exhaust Fan VENTILATION:Heating And Ventilating Unit VENTILATION:Metal Ductwork		
			M157	DS	F0000821723	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2015	364,000
						ARTHUR SCHOMBURG	G HS (IS 201) Total:	\$2,090,609
78M	Manhattan	M510		FORSYT	HS (AUXSVC-	OLD 91)		
				DS	F0000821670	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	880,758
				DS	F0000787219	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,148,453

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000822657	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	163,847
			M458	DS	F0000810542	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			M650	DS	F0000822064	New/Retrofit Telephone/Intercom Systems	2015	239,755
						FORSYTH HS (AUXS	SVC-OLD 91) Total:	\$2,684,164
78M	Manhattan	M520		MURRY E	BERGTRAUM H	S (ECF)		
			M520	DS	F0000775972	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,170,725
				DS	F0000821817	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,013,577
				DS	F0000821819	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	722,930
			M520	DS	F0000787251	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Library Upgrades	2018	2,400,880

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:LIBRARY:Built-in Furnishing		
						INTERIOR:LIBRARY:Ceiling INTERIOR:LIBRARY:Floor Finish		
						INTERIOR:LIBRARY:Walls		
						LIBRARY:LIGHTING:Lighting Fixture - Fluorescent		
						LIBRARY:RACEWAY WITH RECEPTACLES		
				DS	F0000810567	Educational Enhancements - Educational	2018	6,795,072
						Enhancements - School Improvement and		
						Restructuring		
						Science Lab Upgrades		
						CENTRAL ACID WASTE NEUTRALIZING TANK		
						INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment		
						INTERIOR:SCIENCE LAB:Fixed Equipment		
						SCIENCE DEMO ROOM		
						SCIENCE DEMO ROOM: EMERGENCY GAS		
						SHUT-OFF VALVE		
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent		
						SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture -		
						SCIENCE DEMO ROOM:POWER SUPPLY		
						SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE		
						SCIENCE LAB: EMERGENCY SHUT-OFF POWER		
						SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent		
						SCIENCE LAB:LIGHTING:Lighting Fixture -		
						meanuescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SCIENCE LAB:POWER SUPPLY SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent		
			M520	DSF	0000832617	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM SPRINKLERS, STANDPIPE, FIRE SYSTEM:Wet Sprinkler Alarm Valve Assembly	2018	656,840
						MURRY BERGTRAL	IM HS (ECF) Total:	\$13,760,024
78M	Manhattan M535	M535		PARK WE	ST HS (ECF)			
			M288	DSF	0000798653	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,290,376
			M138	DSF	0000844093	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2016	141,300
				DSF	0000821623	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				SCA	0000019673	State of Good Repair - System Replacements - Exterior Masonry	2015	2,033,022
			M288	DSF	0000787281	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							ST US (ECE) Total	\$5.022.107

PARK WEST HS (ECF) Total: \$5,033,197

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78M	Manhattan	M540		A. PHILLI	P RANDOLPH	HS		
				DS	F0000821667	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	649,012
				DSI	F0000822224	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,454,661
							DOLPH HS Total:	\$2,103,673
78M	Manhattan	M600		FASHION		/OC HS		
	ow wamatan			DS	F0000822154	Educational Enhancements - Educational Enhancements - Accessibility	2017	3,037,158
			M600	DSI	F0000741739	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2015	3,054,748
			M600	DS	F0000810647	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
						FASHION INDUSTRI	ES VOC HS Total:	\$6,247,272
78M	Manhattan	M615		CHELSEA	VOC HS			
			M615	DSI	F0000810662	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2017	2,091,720

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000775646	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2015	1,211,259
						Other		
			M615	DSI	F0000822211	Ansul Systems	2017	238,041
							CHELSEA VOC HS Total:	\$3,541,020
78M	Manhattan	M620		NORMAN	THOMAS HS (ECF)		
			M432	DSI	F0000799488	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	447,399
			M427	DSI	F0000800277	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	714,879
			M500	DSI	F0000800278	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	722,344
				DSI	F0000821880	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	521,265
			M500	DSI	F0000821757	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	39,580
				DSI	F0000800280	Educational Enhancements - Educational Enhancements - Science Lab Upgrades	2019	2,093,745
				DSI	F0000798363	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,064,910

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000832752	State of Good Repair - System Replacements - Electrical Systems	2017	232,738
						EMERGENCY GENERATOR SET		
			M427	DSI	F0000787375	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						NORMAN THOM	AS HS (ECF) Total:	\$5,872,123
78M	Manhattan	M625		HS OF GF	RAPHIC COMM	UNICATION ARTS		
			M625	DSI	F0000798598	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	389,333
				DSI	F0000799492	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	287,010
			M507	DSI	F0000799519	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	379,825
			M393	DSI	F0000799520	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	386,134
				DSI	F0000821668	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	470,523
				DSI	F0000821669	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	326,771

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M139	DS	F0000844116	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,510,000
			M625	DS	F0000777537	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Cafeteria / Multipurpose Room Upgrade	2015	4,670,428
				DS	F0000752355	State of Good Repair - Building Upgrade - Boiler Conversion	2016	7,880,247
				DS	F0000752354	State of Good Repair - Building Upgrade - Climate Control	2016	3,137,085
				DS	F0000754491	State of Good Repair - System Replacements - Roofs EXTERIOR:PLAZA DECK	2015	2,134,718
						HS OF GRAPHIC COMMUNI	CATION ARTS Total:	\$21,572,074
78M	Manhattan	M641		CITY AS	SCHOOL (OLD	95)		
			M560	DS	F0000832800	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM	2018	115,754
						SYSTEM:Sewage/Waste/Vent Piping		
						CITY AS SCH	OOL (OLD 95) Total:	\$115,754
78M	Manhattan	M645			HATTAN VOC/	TECH HS		
				DS	F0000787432	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	810,564

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			M655	DSF00	000776058	IP Surveillance Camera Installation	2015	647,881
						OLD MANHATTAN VO	C/TECH HS Total:	\$1,458,445
78M	Manhattan	M661			P NIGHT&DA	Y (OL BACN X)		
				DSF00	000799604	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	94,884
			M575	DSF00	000799789	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			M575	DSF00	000776059	IP Surveillance Camera Installation	2015	510,474
						MNHT COMP NIGHT&DAY (C	DL BACN X) Total:	\$640,621
78M	Manhattan	M833		HS FOR ECO	ONOMICS &	FINANCE		
				DSF00	000787523	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,018,941
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			M489	DS	F0000787531	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						HS FOR ECONOMI	CS & FINANCE Total:	\$1,054,204
78M	Manhattan	M834		HS FOR E		AL STUDIES		
				DSI	F0000832950	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	560,295
						AIR CONDITIONING:Cooling Tower		¢500.005
						HS FOR ENVIRONMEN	VIAL STUDIES TOTAL:	\$560,295
78M	Manhattan	M837		ISHS @ N	1837			
			M479	DS	F0000731146	Code Compliance	2015	1,495,423
							ISHS @ M837 Total:	\$1,495,423
78M	Manhattan	M876		GREGOR	IO LUPERON P	PREP. SCHOOL		
			M552	DSI	F0000843958	State of Good Repair - System Replacements - Exterior Masonry	2019	925,781
			M552	DSI	F0000843957	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2019	506,074
						GREGORIO LUPERON P	PER SCHOOL Total	\$1,431,855
								ψ1, 4 01,000
78M	Manhattan	M894			EADERSHIP &			
			M425	DSI	F0000810975	State of Good Repair - Building Upgrade - Elevators and Escalators	2015	308,374

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR		
			M425	DS	F0000787642	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSI	F0000799820	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
						HS FOR LEADERSHIP & P	UBLIC SER Total:	\$405,595
78M	Manhattan	M911		HARLEM	RENAISSANCE	E HS (OLD M24)		
				DSI	F0000798465	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000787677	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSI	F0000787678	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	758,830
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						HARLEM RENAISSANCE HS	6 (OLD M24) Total:	\$6,535,857
7014	NA	14000		- · · · ·				

78M Manhattan M920

SATELLITE ACADEMY

		Building					FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
				DS	F0000821788	Educational Enhancements - Educational	2015	1,063,400
						Enhancements - Room Conversions/Partitioning	g	
							SATELLITE ACADEMY Total:	\$1,063,400
84M	Manhattan	M908		HARLEM	PROMISE ACA	DEMY CHARTER		
			M284	DS	F0000822180	Educational Enhancements - Educational	2017	1,000,000
						Enhancements - Room Conversions/Partitioning	g	
						HARLEM PROMISE	E ACADEMY CHARTER Total:	\$1,000,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
24	Queens	Q005		I.S. 5				
				DS	F0000800040	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2016	2,236,676
				DS	F0000800039	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2016	3,779,192
						VENTILATION:METAL DUCTWORK		
							I.S. 5 Total:	\$6,015,868
24	Queens	Q007		P.S. 7				
				DS	F0000811071	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,805
							P.S. 7 Total:	\$74,805
24	Queens	Q012		P.S. 12				
				DS	F0000798344	State of Good Repair - Building Upgrade - Boiler Conversion	2016	5,229,748
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000787816	State of Good Repair - Building Upgrade - Climate Control	2016	1,634,603
						CLIMATE CONTROL SYSTEM		
				DS	F0000799783	State of Good Repair - System Replacements - Electrical Systems SERVICE SWITCH	2016	874,992

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SWITCHBOARD		
			Q012	DSI	F0000799865	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
			Q012	DSI	F0000843641	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
			Q012	DSI	F0000865744	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
						Other		
			Q012	DSI	F0000843797	Classroom Connectivity	2016	41,085
							P.S. 12 Total:	\$8,225,295
24	Queens	Q013		P.S. 13				
				DSI	F0000775628	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	891,328
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 13 Total:	\$891,328

24 Queens Q014 P.S. 14

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000765246	State of Good Repair - System Replacements - Exterior Masonry	2016	773,469
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000765245	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	9,390,032
				DS	F0000765244	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	3,037,155
				DS	F0000811184	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2015	163,577
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			Q014	DS	F0000843642	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
						Other		
			Q014	DS	F0000776062	IP Surveillance Camera Installation	2015	637,337
							P.S. 14 Total:	\$14,161,198
24	Queens	Q049		P.S. 49				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799779	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	32,439
						Other		
			Q049	DS	F0000843796	Classroom Connectivity	2016	307,542
							P.S. 49 Total:	\$339,981
24	Queens	Q058		P.S. 58	F0000844716	Educational Enhancements - Educational	2018	62,780
				50	10000044710	Enhancements - Accessibility	2010	02,700
						Other		
			Q058	DS	F0000776065	IP Surveillance Camera Installation	2015	375,423
							P.S. 58 Total:	\$438,203
24	Queens	Q068		P.S. 68				
				DS	F0000788656	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	679,294
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						Other		
			Q068	DS	F0000776066	IP Surveillance Camera Installation	2015	643,574
							P.S. 68 Total:	\$1,322,868
24	Queens	Q071		P.S. 71				
					F0000822249	Accessibility	2016	700,774

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000812031	State of Good Repair - System Replacements - Toilets-Students	2015	302,027
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 71 Total:	\$1,002,801
24	Queens	Q073		I.S. 73				
				DS	F0000799610	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	235,114
				DS	F0000812069	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							I.S. 73 Total:	\$394,742
24	Queens	Q081		P.S. 81				
			Q081	DS	F0000844057	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	2,595,652
				DS	F0000812197	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	101,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							P.S. 81 Total:	\$2,697,003
24	Queens	Q087		P.S. 87				
				DSF	0000788975	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	919,970
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q087	DSF	0000843644	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 87 Total:	\$1,079,598
24	Queens	Q089		P.S. 89				
			Q089	DSF	0000812320	State of Good Repair - System Replacements -	2015	83,783
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						Other		
			Q089	DSI	-0000775700	IP Surveillance Camera Installation	2015	544,715
							P.S. 89 Total:	\$628,498
24	Queens	Q091		P.S. 91				
				DSI	-0000798294	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	846,304
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q091	DSF	-0000843645	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	101,351
			Q091	DSI	-0000865745	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S. 91 Total:	\$1,197,655
24	Queens	Q093	Q093	I.S. 93 DSI	-0000821618	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q093	DS	F0000789066	State of Good Repair - System Replacements - Exterior	2016	2,567,624
						Masonry EXTERIOR:AREAWAY		
						EXTERIOR: AREAWAY EXTERIOR: AWNINGS AND CANOPIES		
						EXTERIOR: CHIMNEY		
			Q093	DS	F0000812370	State of Good Repair - System Replacements - Parapets	2016	1,056,449
						EXTERIOR:PARAPETS		
			Q093	DS	F0000789064	State of Good Repair - System Replacements - Roofs	2016	3,241,359
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
			Q093	DS	F0000812371	State of Good Repair - System Replacements -	2016	1,037,489
						Windows		
						EXTERIOR:WINDOWS		
						Other		
				DS	F0000775701	IP Surveillance Camera Installation	2015	589,974
							I.S. 93 Total:	\$9,026,131
24	Queens	Q102		P.S./I.S. 1	02			
			Q102	DS	F0000730986	Accessibility	2017	3,491,655
			Q102	DS	F0000865746	System Expansion - New Physical Education Facilities - Playgrounds	2018	250,000
							P.S./I.S. 102 Total:	\$3,741,655
24	Queens	Q119		I.S. 119				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q119	DS	F0000844123	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	580,495
				DS	F0000789466	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,029,988
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 119 Total:	\$1,610,483
24	Queens	Q125		I.S. 125				
				DS	F0000777509	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	151,103
				DS	F0000799888	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	590,676
							I.S. 125 Total:	\$741,779
24	Queens	Q143		P.S. 143				
				DS	F0000789897	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,049,766
				DS	F0000799826	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 143 Total:	\$1,111,724
24	Queens	Q153		P.S. 153				
				DSF	-0000799618	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	201,889
						Other		
			Q153	DSF	0000776069	IP Surveillance Camera Installation	2015	605,212
							P.S. 153 Total:	\$807,101
24	Queens	Q199		P.S. 199				
				DSF	F0000798372	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,845,438
				DSF	-0000790833	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate Control	2019	1,375,057
			Q199	DSF	F0000843655	CLIMATE CONTROL SYSTEM State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,349,083
						Other		
			Q199	DSF	0000776072	IP Surveillance Camera Installation	2015	586,285
							P.S. 199 Total:	\$8,155,863
24	Queens	Q229		P.S. 229				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000791281	State of Good Repair - Building Upgrade - Lighting	2015	1,429,883
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			Q229	DS	F0000776074	IP Surveillance Camera Installation	2015	654,471
							P.S. 229 Total:	\$2,084,354
24	Queens	Q239		P.S. 239				
				DS	F0000844712	Educational Enhancements - Educational Enhancements - Accessibility	2018	47,609
							P.S. 239 Total:	\$47,609
24	Queens	Q269		P.S./I.S. 2	269			
						Other		
			Q211	DS	F0000843795	Classroom Connectivity	2016	165,456
							P.S./I.S. 269 Total:	\$165,456
24	Queens	Q721		P.S. 16 (0	OLD Q721 SPED))		
				DS	F0000799638	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	147,481
				DS	F0000823652	State of Good Repair - System Replacements - Toilets-Students	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:TOILET ROOMS - STUDENTS		
						P.S. 16 (OLD	Q721 SPED) Total:	\$307,109
24	Queens	Q848		P.S. 81 AN	NEX (OLD 75)			
			Q081		0000815382	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							NEX (OLD 75) Total:	\$101,351
24	Queens	Q849		I.S. 77				
				DSF	0000798430	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	881,235
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							I.S. 77 Total:	\$881,235
24	Queens	Q877		51ST AVE		(
				DSF	0000792212	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	314,538
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						Other		

Other

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				D	SF0000799915	IP Surveillance Camera Installation	2015	450,875
						51ST AVENUE	ACADEMY Total:	\$765,413
25	Queens	Q020		P.S. 20				
				D	SF0000765327	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2019	1,848,846
						FIRE ALARM SYSTEM		
				D	SF0000787947	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation AIR CONDITIONING:CHILLED WATER SYSTEM:Central Station Air Handler MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN	2019 P.S. 20 Total:	3,696,044
25	Queens	Q021		P.S. 21				, - , - ,
20	Quoono		Q021		SF0000823566	State of Good Repair - Building Upgrade - Interior Spaces	2017	297,925
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						Other		
			Q021	D	SF0000776063	IP Surveillance Camera Installation	2015	655,288

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 21 Total:	\$953,213
25	Queens	Q022		P.S. 22				
				DSF	-0000765357	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	999,542
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q022	DSF	-0000787973	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			Q022	DSF	-0000843793	Classroom Connectivity	2016	263,344
							P.S. 22 Total:	\$1,298,149
25	Queens	Q024		P.S. 24				
				DSF	-0000799607	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	137,474
						Other		
			Q024	DSF	-0000776064	IP Surveillance Camera Installation	2015	592,065
							P.S. 24 Total:	\$729,539
25	Queens	Q025		J.H.S. 25				
				DSF	-0000788018	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,974,692

		Building					FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000811344	State of Good Repair - System Replacements - Toilets-Students	2015	168,904
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							J.H.S. 25 Total:	\$2,143,596
25	Queens	Q029		P.S. 29				
				DS	F0000798481	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	282,112
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 29 Total:	\$282,112
25	Queens	Q032		P.S. 32				
				DS	F0000788106	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DS	F0000799704	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	115,274

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000811427	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
							P.S. 32 Total:	\$1,551,929
25	Queens	Q079		P.S. 79				
				DS	F0000788834	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,297,642
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
				DS	F0000743236	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Domestic Piping	2016	620,919
						DOMESTIC WATER SYSTEM		
			Q079	DS	F0000788841	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 79 Total:	\$1,953,824
25	Queens	Q107		P.S. 107				
			Q107	DS	F0000843809	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	1,269,271
				DS	F0000789285	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,354,200

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q107	DS	F0000789291	State of Good Repair - System Replacements -	2015	116,203
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 107 Total:	\$2,739,674
							F.S. 107 Total.	φ2,739,074
25	Queens	Q120		P.S. 120				
				DS	F0000799612	State of Good Repair - Building Upgrade - Lighting	2016	268,560
						Fixtures		
						Other		
			Q120		F0000776067	IP Surveillance Camera Installation	2015	560.040
			QIZU	De	F0000776067	IP Surveillance Camera Installation		569,049
							P.S. 120 Total:	\$837,609
25	Queens	Q129		P.S. 129				
				DS	F0000798491	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	695,294

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000823644	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
				DSI	F0000775702	IP Surveillance Camera Installation	2015	531,753
							P.S. 129 Total:	\$1,386,675
25	Queens	Q130		P.S. 130				
				DSI	F0000766962	State of Good Repair - Building Upgrade - Flood Elimination	2015	848,332
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	F0000798493	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,060,139
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
				DS	F0000766966	State of Good Repair - System Replacements - Exterior Masonry	2015	2,632,07
						EXTERIOR:CHIMNEY EXTERIOR:CORNICE EXTERIOR:EXTERIOR WALLS		
				DS	F0000799824	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,95
				DS	F0000766965	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	1,687,70
				DS	F0000766964	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	1,913,34
				DS	F0000812959	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2017	159,62
							P.S. 130 Total:	\$8,363,18
25	Queens	Q154		P.S. 154				
				DS	F0000799619	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	248,91
							P.S. 154 Total:	\$248,91

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
25	Queens	Q164		P.S. 164				
				DSF	-0000791083	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSF	-0000790290	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,024,492
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q164	DSF	0000822212	State of Good Repair - System Replacements - Domestic Piping	2016	69,686
						DOMESTIC WATER SYSTEM FIXTURES:STUDENT:Drinking Fountain FIXTURES:STUDENT:Sink And Fountain Combo Unit		
				DSF	-0000813581	State of Good Repair - System Replacements -	2017	159,628
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		

P.S. 164 Total: \$2,530,833

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
25	Queens	Q169		P.S. 169				
			Q169	DSF	-0000790351	State of Good Repair - Building Upgrade - Flood Elimination	2016	941,526
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
							P.S. 169 Total:	\$941,526
25	Queens	Q184		P.S. 184				
				DSF	0000798371	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,811,82
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000790584	State of Good Repair - Building Upgrade - Climate Control	2017	1,534,09
						CLIMATE CONTROL SYSTEM		
				DSF	0000790586	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	735,908
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
		DSF0000790598 State of Good Repair - System Replacements - Auditorium Upgrade	State of Good Repair - System Replacements -	2016	1,404,77			
						INTERIOR: AUDITORIUM: Floor Finish		
							P.S. 184 Total:	\$9,486,605

25 Queens Q185 J.H.S. 185

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000844709	Educational Enhancements - Educational Enhancements - Accessibility	2018	90,965
				DSI	-0000767875	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2015	1,625,115
			Q185	DSI	-0000813893	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Toilets-Students	2015	184,248
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
				DSI	-0000822107	System Expansion - New Physical Education Facilities - Playgrounds	2016	1,423,194
							J.H.S. 185 Total:	\$3,323,522
25	Queens	Q189		J.H.S. 189)			
				DSI	-0000799827	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	96,654
						Other		
			Q263	DSI	-0000776071	IP Surveillance Camera Installation	2015	642,618
							J.H.S. 189 Total:	\$739,272

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total	
25	Queens	Q193		P.S. 193					
				DSI	F0000790733	State of Good Repair - Building Upgrade - Flood Elimination	2017	1,111,419	
							DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS			
				DS	F0000790732	State of Good Repair - Building Upgrade - Lighting	2015	825,968	
						Fixtures			
						CLASSROOM/CORRIDOR/ADMINISTRATIVE			
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE			
						SPACE:LIGHTING:Lighting Fixture - Incandescent			
			Q193	DSI	F0000843951	State of Good Repair - Rehabilitation of Physical	2019	1,490,923	
						Education Facilities - Playground Redevelopment			
						Other			
				DS	F0000775707	IP Surveillance Camera Installation	2015	534,919	
							P.S. 193 Total:	\$3,963,229	
25	Queens	Q194		J.H.S. 194	4				
				DSI	F0000798297	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,904,981	
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM			
				DS	F0000790753	State of Good Repair - Building Upgrade - Climate Control	2017	1,452,385	

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLIMATE CONTROL SYSTEM		
			Q194	DS	F0000790759	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000799828	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	101,610
							J.H.S. 194 Total:	\$7,494,239
25	Queens	Q201		P.S. 201				
			Q201	DS	F0000798431	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,667,715
			Q201	DS	F0000790872	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,324,622
				DS	F0000790873	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	926,785
						SFACE.LIGHTING.Lighting Fixture - incandescent	P.S. 201 Total:	\$6,919,122
25	Queens	Q209	Q209	P.S. 209	F0000798334	State of Good Repair - Building Upgrade - Boiler	2018	4,664,685
			Q200	00	1 00007 90004	Conversion	2010	4,004,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q209	DS	F0000791009	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
							P.S. 209 Total:	\$5,988,447
25	Queens	Q214		P.S. 214				
				DS	F0000798485	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798486	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
			Q214	DS	F0000812865	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,458,287
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			Q214	DS	F0000814328	State of Good Repair - System Replacements - Exterior Masonry	2016	6,118,559
			Q214	DS	F0000745395	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	2,069,212
			Q214	DS	F0000814327	State of Good Repair - System Replacements - Roofs	2016	4,102,398

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
						Other		
			Q214	DS	F0000822055	New/Retrofit Telephone/Intercom Systems	2015	160,427
							P.S. 214 Total:	\$19,685,910
25	Queens	Q219		P.S. 219				
				DS	F0000814406	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,472,083
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			Q219	DS	F0000745480	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2019	270,452
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DSI	F0000814419	State of Good Repair - System Replacements - Domestic Piping Waste System	2016	31,899
						DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP		
						DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE EJECTOR PUMP		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
			Q219	DS	F0000791153	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DS	F0000799467	State of Good Repair - System Replacements - Kitchen Areas	2019	1,503,798
						Other		
			Q219	DS	F0000822039	New/Retrofit Telephone/Intercom Systems	2015	203,052
							P.S. 219 Total:	\$3,516,523
25	Queens	Q237		J.H.S. 237	7			
				DS	F0000799830	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	161,966
			Q237	DS	F0000814588	State of Good Repair - System Replacements - Toilets-Students	2016	160,184
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							J.H.S. 237 Total:	\$322,150
25	Queene	0242		D C 242				<i>4022</i> ,100
25	Queens	Q242		P.S. 242 -			0040	4 0 40 700
				DS	F0000799392	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,343,793

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUM PUMP	P	
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	F0000797681	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	161,868
							P.S. 242 - (ECC) Total:	\$1,505,661
25	Queens	Q499		P.S./I.S. 4	99			
						Other		
			Q499	DSF	-0000776077	IP Surveillance Camera Installation	2015	572,715
							P.S./I.S. 499 Total:	\$572,715
26	Queens	Q026		P.S. 26				
			Q026	DSF	-0000798312	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q026	DSF	-0000798314	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DSF	-0000788039	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,204,593
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 26 Total:	\$7,193,040
26	Queens	Q031		P.S. 31				
			Q031	DSF	-0000843954	State of Good Repair - Building Upgrade - Climate Control	2019	627,969
						CLIMATE CONTROL SYSTEM		
							P.S. 31 Total:	\$627,969
26	Queens	Q041		P.S. 41				
				DSF	-0000798483	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	760,788
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	-0000811593	State of Good Repair - System Replacements - Toilets-Students	2015	217,150
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							P.S. 41 Total:	\$977,938
26	Queens	Q046		P.S. 46				
				DSF	-0000798471	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,500,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
				DS	F0000788342	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DS	F0000798319	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	616,913
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 46 Total:	\$6,393,940
26	Queens	Q067		J.H.S. 67				
				DS	F0000788635	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,549,984
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000811959	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	308,282
			Q067	DS	F0000834056	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	68,047
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Meter Room Vent HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Heating Coil In Ductwork		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:Radiator/Convector/Fin Tube HEATING:Steam Heating HEATING:Unit Heater/Cabinet Heater		
							J.H.S. 67 Total:	\$1,926,313
26	Queens	Q074		I.S. 74				
				DSF	0000788769	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,149,214
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000812090	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
						Fluorescent		
							I.S. 74 Total:	\$1,308,842
26	Queens	Q094		P.S. 94				
				DSF	0000789084	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	724,344

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q094	DS	SF0000812391	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
			Q094	DS	SF0000843646	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 94 Total:	\$1,135,323
26	Queens	Q098		P.S. 98				
			Q098	DS	SF0000799461	State of Good Repair - System Replacements - Paved Area-Concrete	2016	868,437
						SITE:RETAINING WALLS SITE:STAIRS/RAMPS: EXTERIOR		
							P.S. 98 Total:	\$868,437
26	Queens	Q115		THE JAN	IES J. AMBROS	ESCHOOL		
				DS	SF0000798279	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,898,731

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798280	State of Good Repair - Building Upgrade - Climate Control	2017	1,696,820
				DS	F0000812703	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						THE JAMES J. AMBRO	SE SCHOOL Total:	\$7,755,179
26	Queens	Q133		P.S. 133				
				DS	F0000789714	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	925,080
			Q133	DS	F0000813021	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2016	251,351

P.S. 133 Total: \$1,176,431

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
26	Queens	Q158		J.H.S. 158	3			
			Q158	DSI	F0000798440	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q158	DSI	F0000790180	State of Good Repair - Building Upgrade - Climate Control	2018	1,277,027
						CLIMATE CONTROL SYSTEM		
						Other		
			Q158	DSI	F0000776070	IP Surveillance Camera Installation	2015	563,612
							J.H.S. 158 Total:	\$6,340,639
26	Queens	Q159		P.S. 159				
				DSI	F0000790203	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	905,381
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q159	DSI	F0000790210	State of Good Repair - System Replacements -	2016	387,757
						Toilets-Students FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 159 Total:	\$1,293,138
26	Queens	Q162		P.S. 162				
				DSF	-0000798369	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,513,010
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000798370	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
						CLIMATE CONTROL SYSTEM		
				DSF	0000790250	State of Good Repair - Building Upgrade - Flood Elimination	2016	2,072,864
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DSF	0000790253	State of Good Repair - System Replacements - Exterior Masonry	2016	5,578,041
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DSF	0000790252	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	2,201,999
				DSF	0000800283	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,353,525
							D S 162 Total:	\$16 047 302

P.S. 162 Total: \$16,947,302

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
26	Queens	Q172		J.H.S. 172				
				DSF	0000813679	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
							J.H.S. 172 Total:	\$245,771
26	Queens	Q173		P.S. 173				
				DSF	0000790406	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,013,251
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 173 Total:	\$1,013,251
26	Queens	Q179		P.S. 179				
			Q004	DSF	0000790529	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 179 Total:	\$35,239
26	Queens	Q186		P.S. 186				
				DSF	0000800305	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	534,184
			Q186	DSF	0000798328	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q186	DS	SF0000790626	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
				DS	SF0000813911	CLIMATE CONTROL SYSTEM State of Good Repair - System Replacements - Heating Plant Upgrade	2018	81,924
							P.S. 186 Total:	\$6,604,555
26	Queens	Q188		P.S. 188				
				DS	SF0000777513	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	41,084
				DS	SF0000798329	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	717,110
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						<u> </u>	P.S. 188 Total:	\$758,194
26	Queens	Q191		P.S. 191				
			Q191	DS	SF0000798426	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,500,000
			Q191	DS	SF0000798428	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,277,027

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	F0000813971	State of Good Repair - Building Upgrade - Lighting	2016	881,396
						Fixtures		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 191 Total:	\$6,658,423
26	Queens	Q205		P.S. 205				
				DSF	F0000798368	State of Good Repair - Building Upgrade - Boiler Conversion	2017	7,216,636
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	F0000789227	State of Good Repair - Building Upgrade - Climate Control	2017	1,974,955
						CLIMATE CONTROL SYSTEM		
			Q205	DSF	F0000836272	State of Good Repair - Building Upgrade - Flood Elimination	2018	751,773
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sump Pump		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	F0000814216	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,171,611
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	F0000814224	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	163,847

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q205	DSI	F0000822663	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 205 Total:	\$11,434,188
26	Queens	Q213		P.S. 213				
			Q213	DSI	F0000814311	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 213 Total:	\$155,366
26	Queens	Q216		J.H.S. 216	5			
				DSI	F0000798301	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,570,522
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000791100	State of Good Repair - Building Upgrade - Climate Control	2017	1,597,825
						CLIMATE CONTROL SYSTEM		
				DSI	F0000799623	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	183,702
			Q216	DSI	F0000814383	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade CAFETERIA:LOCAL SOUND SYSTEM INTERIOR:CAFETERIA:Floor Finish	2019	501,072
			Q216	DSI	F0000791108	INTERIOR:CAFETERIA:Walls State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q216	DS	F0000814370	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							J.H.S. 216 Total:	\$8,139,735
27	Queens	Q042		P.S. 42				
				DS	F0000799428	State of Good Repair - Building Upgrade - Climate Control	2015	1,491,300
						CLIMATE CONTROL SYSTEM		
				DS	F0000788293	State of Good Repair - Building Upgrade - Flood Elimination	2015	4,227,913
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000788302	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN	2015	2,618,473
						SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799608	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	434,765
				DS	F0000799439	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING	2015	740,833
				DS	F0000799919	State of Good Repair - System Replacements - Electrical Systems PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,360,111
				DS	F0000788296	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS HEATING:HYDRONIC HEATING:Backflow Preventer	2015	7,141,484

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING:HYDRONIC HEATING:Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
				DS	F0000799438	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	2,107,382
						MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
							P.S. 42 Total:	\$21,122,261
27	Queens	Q043		P.S. 43				
				DS	F0000788303	State of Good Repair - Building Upgrade - Climate Control	2015	1,794,296
				DS	F0000799416	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Elevators and Escalators	2015	730,704
			Q043	DS	F0000844151	CONVEYING:ELEVATORS State of Good Repair - Building Upgrade - Elevators and Escalators	2018	69,176
				DS	F0000798639	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP	2015	3,723,457
						PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798637	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2015	2,553,352
				DS	F0000798638	INTERIOR:STAIRS/RAMPS: INTERIOR State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	6,590,130
				DS	F0000788306	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	4,460,917
							P.S. 43 Total:	\$19,922,032
27	Queens	Q047		P.S. 47				
				DS	F0000788356	State of Good Repair - Building Upgrade - Climate Control	2015	753,730
				DS	F0000799398	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,483,177
				DS	F0000788371	State of Good Repair - Building Upgrade - Interior Spaces	2015	332,529

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
				DS	F0000788362	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	261,795
				DS	F0000788370	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation MOTOR STARTER/CONTACTOR VENTILATION:EXHAUST FAN VENTILATION:METAL DUCTWORK	2015	660,998
	_						P.S. 47 Total:	\$5,492,229
27	Queens	Q053	Q053	I. S. 53 DS	F0000844124	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,510,000
				DS	F0000777506	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	122,784
			Q053	DS	F0000822674	State of Good Repair - Building Upgrade - Flood Elimination	2019	1,790,786

District Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
					DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
					INTERIOR:STRUCTURAL:FOUNDATION WALLS		
			DSF000	0788432	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	2,002,429
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
		Q053	DSF000	0822673	State of Good Repair - System Replacements - Exterior	2019	6,643,888
					Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
		Q053	DSF000	0822675	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2019	3,487,308
		Q053	DSF000	0811759	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2019	6,782,748
		Q053	DSF000	0822676	State of Good Repair - System Replacements - Windows	2019	4,855,882
					EXTERIOR:WINDOWS		

I.S. 53 Total: \$27,195,825

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
27	Queens	Q056		P.S. 56 (O	DLD R HILL AX)			
				DSI	F0000765864	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,071,417
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSI	F0000799468	State of Good Repair - System Replacements - Exterior Masonry	2015	1,370,050
						EXTERIOR: EXTERIOR WALLS		
				DSI	F0000765865	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	951,932
				DSI	F0000788490	State of Good Repair - System Replacements - Roofs	2015	206,112
				201		EXTERIOR:ROOFING:Roofing	2010	200,112
						EXTERIOR:ROOFING:Specialties		
			Q056	DSI	F0000788493	State of Good Repair - System Replacements -	2015	144,390
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		<u> </u>
						P.S. 56 (OLD	R HILL AX) Total:	\$3,743,901
27	Queens	Q060		P.S. 60				
				DSI	F0000777507	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	118,081

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	SF0000811856	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 60 Total:	\$277,709
27	Queens	Q063		P.S. 63				
			Q063	DS	SF0000788585	State of Good Repair - Building Upgrade - Flood Elimination	2017	3,721,417
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
				DS	SF0000811913	State of Good Repair - System Replacements - Auditorium Upgrade	2016	196,875
						INTERIOR:AUDITORIUM:Fixed Seating		
			Q063	DS	SF0000811907	State of Good Repair - System Replacements - Exterior Masonry	2017	3,489,883
						EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:CORNICE		
						EXTERIOR:EXTERIOR WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000811906	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	361,242
			Q063	DSF	-0000811905	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,240,423
				DSF	-0000823656	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	50,675
						Other		
			Q063	DSF	-0000775699	IP Surveillance Camera Installation	2015	587,324
							P.S. 63 Total:	\$9,647,839
27	Queens	Q064		P.S. 64				
			Q064	DSF	-0000834021	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:Boiler System	2017	755,000
				DSF	-0000811925	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 64 Total:	\$914,628

27 Queens Q066 **P.S. 66**

-	ID	Org ID	School	Project #	Description	Construction Start	Total
		Q066	DS	SF0000788621	State of Good Repair - System Replacements -	2015	251,453
					•		
					FIXTURES:STUDENT:Urinal		
					INTERIOR:TOILET ROOMS - STUDENTS		
					Fixture - Fluorescent		
						P.S. 66 Total:	\$251,453
Queens	Q090		P.S. 90				
		Q090	DS	SF0000812341	State of Good Repair - System Replacements - Toilets-Students	2015	230,626
					FIXTURES:STUDENT:Lavatory/Sink		
					FIXTURES:STUDENT:Toilet		
					INTERIOR: TOILET ROOMS - STUDENTS		
						P.S. 90 Total:	\$230,626
Queens	Q097		P.S. 97				
			DS	SF0000789138	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,032,540
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
			Q090	Q090 DS Queens Q097 P.S. 97	Q090 DSF0000812341	Queens Q090 P.S. 90 Queens Q090 P.S. 90 Queens Q090 DSF0000812341 State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lighting Fixture - Fluorescent Queens Q097 P.S. 97 DSF0000789138 State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	Augeens Q090 P.S. 90 P.S. 90 Queens Q097 P.S. 97 P.S. 90 Queens Q097 P.S. 97 P.S. 90 Queens Q097 P.S. 97 P.S. 90 Total: Queens Q097 P.S. 97 P.S. 90 Queens Q097 P.S. 97 P.S. 90 Total: Queens Q097 P.S. 97 P.S. 90 Total: Queens Q097 P.S. 97 P.S. 90 Total: Queens Q097 P.S. 97

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 97 Total:	\$1,032,540
27	Queens	Q100		P.S. 100				
			Q100	DSF	0000732406	Code Compliance	2018	501,268
				DSF	0000844084	State of Good Repair - Building Upgrade - Elevators and Escalators	2018	349,842
						CONVEYING:Elevator INTERCOM SYSTEM:Elevator		
			Q100	DSF	0000812496	State of Good Repair - System Replacements - Toilets-Students	2015	267,919
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
				DSF	0000823657	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
							P.S. 100 Total:	\$1,278,657
27	Queens	Q105		P.S. 105				
				DSF	0000789244	State of Good Repair - Building Upgrade - Climate Control	2015	1,487,180
						CLIMATE CONTROL SYSTEM		
				DSF	0000799426	State of Good Repair - Building Upgrade - Flood Elimination	2015	6,847,080
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			Q105	DS	F0000822165	State of Good Repair - Building Upgrade - Interior Spaces	2015	1,752,875
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
				DS	F0000789257	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Floor Finish	2015	167,563
				DS	F0000799444	State of Good Repair - System Replacements - Domestic Piping FIXTURES:STUDENT:Drinking Fountain FIXTURES:STUDENT:Sink And Fountain Combo Unit	2015	1,513,204
				DS	F0000789250	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD	2015	2,005,670
				DS	F0000789251	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT	2015	8,406,416

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			Q105	DS	F0000822167	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	1,618,043
						MOTOR STARTER/CONTACTOR		
			Q105	DS	F0000822164	State of Good Repair - System Replacements - Paved Area-Blacktop	2015	3,640,592
						SITE:Drainage System for Asphalt SITE:Playgrounds:Pavement		
				DS	F0000812555	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 105 Total:	\$27,539,974
27	Queens	Q106		P.S. 106				
				DS	F0000789267	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,619,719
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000789283	State of Good Repair - Building Upgrade - Interior	2015	4,083,549
						Spaces		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Walls		
						INTERIOR:STAIRS/RAMPS: INTERIOR		
				DSI	F0000798643	State of Good Repair - System Replacements - Heating	2015	1,364,457
						Plant Upgrade		
						HEATING PLANT:BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
				DSI	F0000812571	State of Good Repair - System Replacements -	2016	101,351
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		<u></u>
							P.S. 106 Total:	\$7,169,076
27	Queens	Q108		P.S. 108				
				DS	F0000812606	State of Good Repair - System Replacements -	2015	240,069
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 108 Total:	\$240,069
27	Queens	Q114		P.S. 114				
			Q114	DSF	0000798628	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	1,349,195
			Q114	DSF	0000798627	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	4,459,520
			Q114	DSF	0000798625	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	1,358,445
				DSF	0000798634	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	484,438
				DSF	0000799929	State of Good Repair - System Replacements - Domestic Piping	2015	450,523

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
			Q114	D	SF0000789386	State of Good Repair - System Replacements - Electrical Systems	2015	3,336,976
						GROUNDING SYSTEM		
						PANEL BOARD		
						SERVICE SWITCH SWITCHBOARD		
				D	SF0000789394	State of Good Repair - System Replacements - Heating	2015	1,377,529
						Plant Upgrade		.,,
						Ventilation		
						VENTILATION: EXHAUST FAN		
						VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
						VENTILATION.SUPPLY PAN VENTILATION:UNIT VENTILATOR		
			Q114	D	SF0000798626	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	6,625,413
						HEATING PLANT:BOILER SYSTEM		
							P.S. 114 Total:	\$19,442,039
27	Queens	Q123		P.S. 123	•			
				D	SF0000798490	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	278,037
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q123	DSF	-0000821930	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,814,256
							P.S. 123 Total:	\$2,092,293
27	Queens	Q124		P.S. 124				
			Q124	DSF	-0000798317	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2017	4,500,000
			Q124	DSF	-0000789560	HEATING PLANT:BOILER SYSTEM State of Good Repair - Building Upgrade - Climate	2017	1,277,027
						Control CLIMATE CONTROL SYSTEM		
				DSF	F0000789561	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	953,419
			Q124	DSF	F0000799994	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	114,025

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000821720	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2016	215,833
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 124 Total:	\$7,060,304
27	Queens	Q137		M.S. 137				
				DSF	-0000823577	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							M.S. 137 Total:	\$74,806
27	Queens	Q146		P.S. 146				
				DSF	F0000799395	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	4,613,157
				DSF	F0000789978	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)	2015	1,258,964

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
				DS	F0000799615	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	381,290
				DS	SF0000789964	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	602,544
				DS	6F0000789974	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK	2015	2,197,565
				DS	F0000813260	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,628
				DS	SF0000799397	System Expansion - New Physical Education Facilities - Playgrounds	2015	427,994

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 146 Total:	\$9,641,142
27	Queens	Q155		P.S. 155				
				DSF	0000799620	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	175,976
			Q155	DSF	0000844160	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	3,040,850
				DSF	0000813418	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,628
						Other		
				DSF	0000775704	IP Surveillance Camera Installation	2015	523,215
							P.S. 155 Total:	\$3,899,669
27	Queens	Q180		I.S. 323 (O	LD IS 180)			
				DSF	0000775971	Air Conditioning Retrofit	2015	5,474,716
				DSF	0000767810	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	4,167,956
				DSF	0000777687	State of Good Repair - Building Upgrade - Flood Elimination	2015	4,878,853

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000767826	State of Good Repair - Building Upgrade - Interior Spaces	2015	2,309,088
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DS	F0000799995	State of Good Repair - Building Upgrade - Interior Spaces	2015	600,369
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
				DS	F0000798286	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,283,921
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000767812	State of Good Repair - System Replacements - Electrical Systems	2015	1,550,947
						GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000767813	State of Good Repair - System Replacements - Heat Plant Upgrade	ting 2015	6,960,419
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000813825	State of Good Repair - System Replacements - Toilets-Students	2017	79,814
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
						Ι.	S. 323 (OLD IS 180) Total:	\$27,306,083
27	Queens	Q183		P.S. 183				
				DS	F0000799433	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,205,158
						DRAIN/WASTE/VENT AND STORM SYSTEM:SU PUMP		
				DS	F0000799424	INTERIOR:STRUCTURAL:FOUNDATION WALL: State of Good Repair - Building Upgrade - Interior	S 2015	427,090
				50	10000100424	Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	1	421,030

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000790575	State of Good Repair - System Replacements - Electrical Systems	2015	426,751
						GROUNDING SYSTEM PANEL BOARD		
				DS	F0000790576	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	596,429
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q183	DS	F0000799867	HEATING PLANT:FUEL SYSTEMS State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							P.S. 183 Total:	\$4,690,667
27	Queens	Q197		P.S. 197				
				DS	F0000814075	State of Good Repair - System Replacements - Toilets-Students	2015	188,377
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			Q197	DS	F0000843798	Classroom Connectivity	2016	337,645
							P.S. 197 Total:	\$526,022

Q - 62 of 146

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
27	Queens	Q198		I.S. 198				
				DS	F0000799423	State of Good Repair - Building Upgrade - Climate Control	2015	2,093,115
						CLIMATE CONTROL SYSTEM		
				DS	F0000799422	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,040,264
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799622	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	195,801
				DS	F0000799419	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2015	2,303,992
						INTERIOR:STRUCTURAL:FLOOR STRUCTURE		
				DS	F0000799421	State of Good Repair - System Replacements -	2015	1,737,005
						Electrical Systems		
						GROUNDING SYSTEM		
						PANEL BOARD SERVICE SWITCH		
						SWITCHBOARD		
						TRANSFORMER		
				DS	F0000790816	State of Good Repair - System Replacements - Heating	2015	7,857,703
						Plant Upgrade		
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER AUXILIARIES		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
							I.S. 198 Total:	\$17,227,880
27	Queens	Q202		I.S. 202				
				DSF	0000777515	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	180,851
				DSF	0000814178	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING	2016	31,486
			Q202	DSF	0000790901	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							I.S. 202 Total:	\$247,600
27	Queens	Q207		P.S. 207				
				DSF	0000768243	State of Good Repair - Building Upgrade - Climate Control	2015	963,576
						CLIMATE CONTROL SYSTEM		
				DSF	0000768245	State of Good Repair - Building Upgrade - Flood Elimination	2015	2,157,160
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	0000777683	State of Good Repair - Building Upgrade - Interior Spaces	2015	921,199

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSF	0000768244	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems PUBLIC ADDRESS SYSTEM	2015	249,858
				DSF	0000768247	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	3,856,859
				DSF	0000799891	State of Good Repair - System Replacements - Paved Area-Blacktop SITE:PAVING - STUDENT USE:Asphalt	2015	242,959
						Other		
			Q207	DSF	0000776073	IP Surveillance Camera Installation	2015	500,365
							P.S. 207 Total:	\$8,891,976
27	Queens	Q210		I.S. 210				
				DSF	0000798476	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	1,005,629

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000791033	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	647,144
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			Q210	DS	F0000814295	State of Good Repair - System Replacements -	2016	101,351
						Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS		
						INTERIOR. TOLET ROOMS - STUDENTS	I.S. 210 Total:	\$1,754,124
27	Queens	Q215		P.S. 215				¢1,101,121
21	Queens	QZIO			F0000791085	State of Good Repair - Building Upgrade - Lighting	2015	981,629
					0000791005	Fixtures	2013	901,029
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q215	DS	F0000745409	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,564,886
						AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
				DS	F0000814351	State of Good Repair - System Replacements - Toilets-Students	2015	203,190

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							P.S. 215 Total:	\$2,749,705
27	Queens	Q223		P.S. 223				
			Q223	DSF00	000798337	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,664,685
			Q223	DSF00	000791203	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762
			Q223	DSF00	000791211	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 223 Total:	\$6,023,710
27	Queens	Q225		P.S. 225				
				DSF00	000791225	State of Good Repair - Building Upgrade - Climate Control	2015	751,908
				DSF00	000791229	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	3,531,121

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000800307	State of Good Repair - Building Upgrade - Interior Spaces	2015	826,414
				DS	F0000814477	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,364,268
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000791231	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	1,684,031
				DS	F0000791232	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	1,776,373
							P.S. 225 Total:	\$9,934,115
27	Queens	Q226		I. S. 226 DS	F0000821696	State of Good Repair - Building Upgrade - Low-Voltage	2016	1,354,182
			Q226	DS	F0000800309	Electrical Systems PUBLIC ADDRESS SYSTEM State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	5,051,035

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 226 Total:	\$6,405,217
27	Queens	Q232		P.S. 232				
				DSF	0000799626	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	134,934
			Q232	DSF	0000791320	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	154,196
						Other		
			Q232	DSF	0000776076	IP Surveillance Camera Installation	2015	552,822
							P.S. 232 Total:	\$841,952
27	Queens	Q254		P.S. 254				
			Q254	DSF	F0000820911	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2019	2,759,016
			Q254	DSF	0000820910	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2019	3,828,535
			Q254	DSF	-0000820913	State of Good Repair - System Replacements - Paved Area-Concrete SITE:RETAINING WALLS	2019	1,472,923
			Q254	DSF	0000797689	State of Good Repair - System Replacements - Roofs	2019	3,636,640

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing		
						Other		
			Q254	DS	F0000822068	New/Retrofit Telephone/Intercom Systems	2015	206,252
							P.S. 254 Total:	\$11,903,366
27	Queens	Q806		P.S. 106	MINISCHOOL			
				DS	F0000798645	State of Good Repair - System Replacements - Paved Area-Blacktop	2017	3,390,497
						P.S. 1	06 MINISCHOOL Total:	\$3,390,497
27	Queens	Q907		P.S. 43 A	NNEX			
				DS	F0000800332	State of Good Repair - Building Upgrade - Flood Elimination	2015	3,964,788
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000800331	State of Good Repair - Building Upgrade - Interior Spaces	2015	481,370
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
							P.S. 43 ANNEX Total:	\$4,446,158
28	Queens	Q003		P.S. 303				
				DS	F0000799606	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	125,625
							P.S. 303 Total:	\$125,625
28	Queens	Q008		J.H.S. 8				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q008	DS	F0000823629	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,417,296
				DS	F0000787765	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Walls	2015	228,079
							J.H.S. 8 Total:	\$2,645,375
28	Queens	Q030		P.S. 30				
			Q030	DS	F0000788068	State of Good Repair - Building Upgrade - Flood Elimination	2016	2,084,901
				DO	F0000700700	INTERIOR:STRUCTURAL:FOUNDATION WALLS	0045	454 000
				DS	F0000799703	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	151,996
			Q030	DS	F0000800310	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,346,345
			Q030	DS	F0000821679	State of Good Repair - System Replacements - Exterior Masonry	2017	2,553,299
						EXTERIOR: EXTERIOR WALLS		
			Q030	DS	F0000811388	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
				DS	F0000799997	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	4,992,968
			Q030	DS	F0000811385	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	6,503,429

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000811390	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	101,351
							P.S. 30 Total:	\$17,889,655
28	Queens	Q040		P.S. 40				
			Q040	DSF	F0000800317	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2019	2,064,155
			Q040	DSF	-0000811574	State of Good Repair - System Replacements - Toilets-Students	2015	223,459
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 40 Total:	\$2,287,614
28	Queens	Q048		P.S. 48				
				DSF	F0000408987	State of Good Repair - Building Upgrade - Flood Elimination	2019	4,996,744
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	-0000788373	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	732,402
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q075	DS	F0000801073	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2016	137,781
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		
							P.S. 48 Total:	\$5,866,927
28	Queens	Q054		P.S. 54				
				DS	F0000811776	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						TATOREO.OTODENT.Onnal	P.S. 54 Total:	\$159,628
28	Queens	Q055		P.S. 55				
				DS	F0000788465	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
				DS	F0000788467	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Lighting	2016	783,625
				20		Fixtures	2010	100,020
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q055	DSF	0000754451	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2015	1,816,829
							P.S. 55 Total:	\$3,877,481
28	Queens	Q072		J.H.S. 72				
				DSF	0000821665	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	438,584
				DSF	0000812057	Educational Enhancements - Educational Enhancements - Science Lab Upgrades CENTRAL ACID WASTE NEUTRALIZING TANK INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment SCIENCE DEMO ROOM SCIENCE DEMO ROOM:LIGHTING:Lighting Fixture - Fluorescent SCIENCE LAB SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE LAB:EMERGENCY SHUT-OFF POWER SCIENCE LAB:LIGHTING:Lighting Fixture - Fluorescent SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Fluorescent	2019	1,753,778
				DSF	0000777508	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	213,046
							LUC 72 Total	¢0 405 400

J.H.S. 72 Total: \$2,405,408

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
28	Queens	Q080		P.S. 80				
				DS	F0000788856	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,110,310
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q080	DS	F0000788862	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000812178	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 80 Total:	\$1,246,924
28	Queens	Q082		P.S. 82				
				DS	F0000788896	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	413,618
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 82 Total:	\$413,618
28	Queens	Q099		P.S. 99				
			Q099	DSF	-0000789167	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
			Q099	DSF	-0000789174	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			Q099	DSF	-0000834578	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2016	56,396
						AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Water		
						Cooled Chiller AIR CONDITIONING:Condenser Water Piping		
						AIR CONDITIONING:Condenser Water Pump		
						AIR CONDITIONING:Cooling Tower		
						AIR CONDITIONING:Return Fan		
							P.S. 99 Total:	\$1,416,281
28	Queens	Q101		P.S. 101				
				DSF	-0000789202	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	735,502
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 101 Total:	\$735,502
28	Queens	Q117		P.S. 117				
				DSF	0000798488	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	975,320
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 117 Total:	\$975,320
28	Queens	Q121		P.S. 121				
			Q121	DSF	0000822677	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs	2016	177,263
			Q121	DSF	0000821931	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	1,392,492
						Other		
			Q121	DSF	0000843794	Classroom Connectivity	2016	266,427
							P.S. 121 Total:	\$1,836,182
28	Queens	Q139		P.S. 139				
			Q139	DSF	0000789815	State of Good Repair - Building Upgrade - Flood Elimination	2017	933,675

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:VAULTS-BUNKERS		
			Q139	DSI	-0000821927	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	1,444,675
							P.S. 139 Total:	\$2,378,350
28 (Queens	Q140		P.S. 140				
				DSI	-0000789829	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	1,460,950
						SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q140	DSI	-0000813129	State of Good Repair - System Replacements - Toilets-Students	2015	201,959
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Tollet		
						INTERIOR: TOILET ROOMS - STUDENTS		
							P.S. 140 Total:	\$1,662,909

28 Queens Q157 J.H.S. 157

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q157	DSI	F0000813455	State of Good Repair - System Replacements -	2015	242,368
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							J.H.S. 157 Total:	\$242,368
	_							<i>\\\\\\\\\\\\\</i>
28	Queens	Q160		P.S. 160				
				DSI	F0000813516	State of Good Repair - Building Upgrade - Flood	2018	1,447,381
						Elimination		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000790225	State of Good Repair - Building Upgrade - Lighting	2016	1,019,001
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent	0040	0.000.000
				03	F0000801051	State of Good Repair - System Replacements - Exterior Masonry	2018	6,206,603
						EXTERIOR:CHIMNEY		
						EXTERIOR:CHIMINET		
				ופח	F0000822251	State of Good Repair - System Replacements - Parapets	2018	3,272,060
				00	0000022201	EXTERIOR:COPING	2010	3,272,000
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				ופח	F0000822250	State of Good Repair - System Replacements - Roofs	2018	1,317,319
				03	0000022200	State of Sood Repail - System Replacements - Rools	2010	1,517,519

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Roofing		
							P.S. 160 Total:	\$13,262,364
28	Queens	Q174		P.S. 174				
				DSF	-0000798484	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,500,000
				DSF	-0000790426	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
				DSF	-0000799621	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Lighting Fixtures	2015	251,528
			Q174	DSF	-0000790435	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 174 Total:	\$6,063,818
28	Queens	Q175		P.S. 175				
				DSF	-0000790447	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	785,186
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	-0000790452	State of Good Repair - System Replacements - Exterior Masonry	2019	367,320

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000767727	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	3,815,504
				DS	F0000767726	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	2,742,785
				DS	F0000767728	State of Good Repair - System Replacements - Windows	2015	2,891,276
						EXTERIOR:WINDOWS		
							P.S. 175 Total:	\$10,602,071
28	Queens	Q190		J.H.S. 19	0			
				DS	F0000844711	Educational Enhancements - Educational Enhancements - Accessibility	2017	566,169
				DS	F0000777514	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	132,339
							J.H.S. 190 Total:	\$698,508
28	Queens	Q196		P.S. 196				
			Q196	DS	F0000798331	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q196	DS	F0000798333	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2018	1,323,762

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798336	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	546,855
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
				DS	F0000745120	SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Exterior Masonry	2015	2,415,186
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			Q196	DS	F0000799792	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000745119	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,995,760
				DS	F0000745118	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,134,166
							P.S. 196 Total:	\$13,115,677
28	Queens	Q206		P.S. 206				
				DS	F0000790975	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	555,779
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000814242	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 206 Total:	\$711,145
28	Queens	Q217		I.S. 217				
				DSF	-0000798373	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,845,438
				DSF	-0000791125	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,375,057
				DSF	-0000814392	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2015	176,388
							I.S. 217 Total:	\$6,396,883
28	Queens	Q220		P.S. 220				
			Q220	DSF	-0000798420	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	4,500,000
			Q220	DSF	F0000791166	State of Good Repair - Building Upgrade - Climate Control	2018	1,277,027

Borough Queens	Building ID Q015	Org ID	School P.S. 15	Project #	Description CLIMATE CONTROL SYSTEM	Construction Start P.S. 220 Total:	Total \$5,777,027
		Org ID		Project #	•		
Queens	Q015		P.S. 15		CLIMATE CONTROL SYSTEM	P.S. 220 Total:	\$5 777 027
Queens	Q015		P.S. 15			P.S. 220 Total:	\$5 777 027
Queens	Q015		P.S. 15				ψ5,777,027
			DSI	-0000787871	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescen	2016 t	1,013,168
					Other		
		Q015	DSI	-0000843792	Classroom Connectivity	2016	247,027
						P.S. 15 Total:	\$1,260,195
Queens	Q033		P.S. 33				
		Q033				2016 t 2019	1,232,580
G	ueens	ueens Q033	ueens Q033	ueens Q033 P.S. 33 DSI	Q033 P.S. 33 DSF0000788132	SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent Other Q015 DSF0000843792 Classroom Connectivity Rueens Q033 P.S. 33 DSF0000788132 State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent 2015 DSF0000843792 Classroom Connectivity 2016 P.S. 15 Total: DSF0000788132 State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent Q033 DSF0000843952 State of Good Repair - Rehabilitation of Physical 2019

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000811451	State of Good Repair - System Replacements - Exterior Masonry	2017	5,543,077
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000788138	State of Good Repair - System Replacements - Parapets	2017	657,388
						EXTERIOR:COPING EXTERIOR:PARAPETS		
				DS	F0000788137	State of Good Repair - System Replacements - Roofs	2017	5,169,615
						EXTERIOR:ROOFING:Roofing		
							P.S. 33 Total:	\$14,102,967
29	Queens	Q034		P.S. 34				
				DS	F0000788154	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	847,197
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						Other		
			Q034	DS	F0000843800	Classroom Connectivity	2016	307,493
							P.S. 34 Total:	\$1,154,690
29	Queens	Q036		P.S. 36				
			Q233	DS	F0000798270	<i>State of Good Repair - Building Upgrade - Boiler</i> <i>Conversion</i> HEATING PLANT:BOILER AUXILIARIES	2018	4,513,010

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
			Q036	DS	F0000788193	State of Good Repair - Building Upgrade - Climate Control	2018	1,227,863
						CLIMATE CONTROL SYSTEM		
				DS	F0000788195	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	737,345
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000811514	State of Good Repair - System Replacements -	2017	159,628
						Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 36 Total:	\$6,637,846
29	Queens	Q037		P.S. 37				
				DS	F0000798349	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES	2019	4,845,438

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM		
				DS	F0000788217	State of Good Repair - Building Upgrade - Climate Control	2019	1,375,057
						CLIMATE CONTROL SYSTEM		
				DS	F0000811529	State of Good Repair - Building Upgrade - Elevators and Escalators	2018	278,386
						CONVEYING:ASH HOIST CONVEYING:ELEVATORS		
				DS	F0000777242	State of Good Repair - Building Upgrade - Flood Elimination	2018	6,618,800
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000788218	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2018	1,293,508
			Q037	DS	F0000811536	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
							P.S. 37 Total:	\$14,566,555
29	Queens	Q038		P.S. 38				
			Q038	DS	F0000800311	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	2,117,353
							P.S. 38 Total:	\$2,117,353
29	Queens	Q052		P.S. 52				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q052	DS	SF0000788418	State of Good Repair - Building Upgrade - Flood Elimination	2018	1,667,321
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	SF0000788417	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	973,648
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
			0050		500000000000	SPACE:LIGHTING:Lighting Fixture - Incandescent	0047	4 500 544
			Q052	De	SF0000821932	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	1,563,544
				DS	SF0000811745	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 52 Total:	\$4,364,141
29	Queens	Q059		I.S. 59				
				DS	SF0000801064	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	742,945
			Q176	DS	SF0000821781	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring	2015	35,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
						Technology		
			Q059	DS	F0000845587	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2018	355,00
				DS	F0000798357	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	695,484
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 59 Total:	\$1,828,429
29	Queens	Q095		P.S. 95				
				DS	F0000799705	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	146,28
				DS	F0000812410	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent	2017	159,62
							P.S. 95 Total:	\$305,90

29 Queens Q109 I.S. 109

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000799611	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	224,576
							I.S. 109 Total:	\$224,576
29	Queens	Q116		P.S. 116				
				DSF	-0000789417	State of Good Repair - Building Upgrade - Reinforcing Cinder Concrete Slabs INTERIOR:STRUCTURAL:FLOOR STRUCTURE	2016	1,045,111
				DSF	-0000766746	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2016	5,454,831
				DSF	-0000800108	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	3,452,395
				DSF	-0000789420	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	1,445,971
			Q116	DSF	-0000789425	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting	2015	307,550
						Fixture - Incandescent	D S 116 Total	

P.S. 116 Total: \$11,705,858

29 Queens Q118 P.S. 118

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000789451	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,005,112
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000799822	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	103,825
				DSI	F0000812756	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Incandescent		
							P.S. 118 Total:	\$1,268,565
29	Queens	Q131		P.S. 131				
				DSI	F0000789668	State of Good Repair - Building Upgrade - Flood Elimination	2016	3,989,973
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000812978	State of Good Repair - System Replacements - Exterior Masonry	2019	2,651,900
						EXTERIOR:EXTERIOR WALLS EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DSI	F0000812977	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2019	808,483
				DSI	F0000812976	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2019	2,910,410
							P.S. 131 Total:	\$10,360,766
29	Queens	Q132		P.S. 132				
				DSI	F0000789691	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	692,559
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 132 Total:	\$692,559
29	Queens	Q134		P.S. 134				
				DSI	F0000789732	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	947,743

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 134 Total:	\$947,743
29	Queens	Q136		P.S. 136				
				DSF	0000789771	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,178,619
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						of Aceleton Antonio Lighting Plataro - Incula cocont	P.S. 136 Total:	\$1,178,619
29	Queens	Q147		P.S. 147				
				DSF	0000789981	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,351,508
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 147 Total:	\$1,351,508
29	Queens	Q156		P.S. 156				
				DSF	0000790141	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2015	945,473

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q156	DS	F0000843953	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2018	4,784,945
							P.S. 156 Total:	\$5,730,418
29	Queens	Q176		P.S. 176 DS	F0000777287	System Expansion - New Physical Education Facilities - Playgrounds	2019	4,220,000
							P.S. 176 Total:	\$4,220,000
29	Queens	Q181		P.S. 181				
			Q181	DS	F0000798436	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,667,715
			Q181	DS	F0000790464	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,324,622
				DS	F0000844112	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	548,122
				DS	F0000821590	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls	2017	5,513,986

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000798325	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	696,729
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000835911	State of Good Repair - System Replacements - Exterior Masonry	2017	2,097,580
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY		
				DS	F0000844111	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2017	1,972,092
				DS	F0000835909	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2017	1,041,491
							P.S. 181 Total:	\$17,862,337
29	Queens	Q192		I.S. 192				
				DS	F0000821676	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,328,247
				DS	F0000798358	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	850,623
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							I.S. 192 Total:	\$2,178,870
29	Queens	Q195		P.S. 195				
				DSF	0000777702	State of Good Repair - Building Upgrade - Climate Control	2015	168,594
						CLIMATE CONTROL SYSTEM		
				DSF	0000777697	State of Good Repair - Building Upgrade - Flood Elimination	2015	2,690,974
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	0000777701	State of Good Repair - Building Upgrade - Interior Spaces	2015	834,157
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSF	0000798332	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	678,186
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DSF	0000777700	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2015	454,360
						INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000777698	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM	2015	939,348
						PANEL BOARD SERVICE SWITCH SWITCHBOARD		
				DS	F0000777699	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2015	2,969,882
				DS	F0000814054	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	477,937
							P.S. 195 Total:	\$9,213,438
29	Queens	Q231		I.S. 231 (T	ANDEM Q251)			
_				DS	F0000799625	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	206,322
						I.S. 231 (TA	NDEM Q251) Total:	\$206,322
29	Queens	Q238		I.S. 238				
				DS	F0000777516	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	115,091

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000814600	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,928,906
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
			Q238	DS	F0000814621	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
						CAFETERIA:LIGHTING:Lighting Fixture - Fluorescent INTERIOR:CAFETERIA:Ceiling INTERIOR:CAFETERIA:Floor Finish		
			Q238	DS	F0000791361	State of Good Repair - System Replacements - Toilets-Students	2015	180,263
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							I.S. 238 Total:	\$2,757,496
29	Queens	Q268		P.S. 268				
				DS	F0000844715	Educational Enhancements - Educational Enhancements - Accessibility	2018	48,077
							P.S. 268 Total:	\$48,077
29	Queens	Q270		P.S. 270				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q270	DSI	F0000797701	State of Good Repair - System Replacements - Exterior	2017	864,322
						Masonry		
						EXTERIOR: AWNINGS AND CANOPIES		
						EXTERIOR: CHIMNEY		
			Q270	ופח	F0000800111	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Parapets	2017	3,576,178
				_				
			Q270	DSI	F0000820925	State of Good Repair - System Replacements - Roofs	2017	2,482,183
						EXTERIOR:ROOFING:Roofing		
						EXTERIOR:ROOFING:Specialties		
							P.S. 270 Total:	\$6,922,683
29	Queens	Q836		P.S. 36 MI	INISCHOOL			
			Q036	DSI	F0000822094	State of Good Repair - System Replacements - Roofs	2016	292,126
						EXTERIOR:ROOFING:Roofing		
						P.S. 36 N	IINISCHOOL Total:	\$292,126
29	Queens	Q892		P.S. 892				
			Q360	DSI	F0000844010	Playground Redevelopment	2017	374,337
							P.S. 892 Total:	\$374,337
30	Queens	Q002		P.S. 2				
				DSI	F0000787698	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,012,165
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Tota
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q002	DSF	0000811038	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 2 Total:	\$1,263,516
30	Queens	Q010		I.S. 10				
				DSF	0000777505	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	108,093
				DSF	0000787795	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,031,993
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q010	DSF	0000742213	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,761,261
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
							I.S. 10 Total:	\$2,901,347

30 Queens Q011 **P.S. 11**

Q - 100 of 146

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799821	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
							P.S. 11 Total:	\$61,958
30	Queens	Q069		P.S. 69				
				DS	F0000799609	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	122,683
							P.S. 69 Total:	\$122,683
30	30 Queens	Q070		P.S. 70				
				DS	F0000788685	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,068,112
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent	P.S. 70 Total:	\$1,068,112
30	Queens	Q084		P.S. 84				
				DS	F0000812234	State of Good Repair - System Replacements - Toilets-Students	2015	176,454
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
			Q084	DS	F0000843643	State of Good Repair - System Replacements - Toilets-Students	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 84 Total:	\$336,082
30	Queens	Q085		P.S. 85				
				DSF	0000788936	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2016	850,806
			Q085	DSF	0000752879	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	916,402
				DSF	0000775650	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	684,752
				DSF	0000800060	State of Good Repair - System Replacements - Electrical Systems	2016	1,588,372
				DSF	0000834339	State of Good Repair - System Replacements - Toilets-Students FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet	2017	159,628

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:Student:Urinal TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
							P.S. 85 Total:	\$4,199,960
30	Queens	Q111		P.S. 111				
			Q111	DSF	0000821782	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	35,000
				DSF	0000812649	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:Student:Lavatory/Sink FIXTURES:Student:Toilet FIXTURES:Student:Urinal		
							P.S. 111 Total:	\$194,628
30	Queens	Q112		P.S. 112				
				DSF	0000789357	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	730,498
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 112 Total:	\$730,498
30	Queens	Q122		P.S. 122				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000789518	State of Good Repair - Building Upgrade - Lighting	2015	1,286,871
						Fixtures		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 122 Total:	\$1,286,871
30	Queens	Q126		I.S. 126				
				DS	F0000789593	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DS	F0000799613	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	276,331
				DS	F0000799823	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
			Q126	DS	F0000812900	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
			Q126	DS	F0000843801	Classroom Connectivity	2016	398,364
							IS 126 Total	\$2 265 031

I.S. 126 Total: \$2,265,031

FY -

District	Porough	Building ID		School	Droiget #	Description	Construction	Total
	Borough		Orgin		Project #	Description	Start	TOLAI
30	Queens	Q127		P.S. 127				
				DSF	-0000798478	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,068,056
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q127	DSF	-0000722711	State of Good Repair - System Replacements - Exterior	2015	8,607,653
						Masonry		
						EXTERIOR: EXTERIOR WALLS		
				DSF	-0000753074	State of Good Repair - System Replacements - Parapets	2015	3,027,703
						EXTERIOR:COPING		
						EXTERIOR:PARAPETS		
							P.S. 127 Total:	\$12,703,412
30	Queens	Q141		I.S. 141				
				DSF	-0000799614	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	236,013
			Q141	DSF	-0000789856	State of Good Repair - System Replacements - Toilets-Students	2015	215,781
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
							I.S. 141 Total:	\$451,794
30	Queens	Q145		I.S. 145				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000777511	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2016	165,469
				DSF	0000798276	State of Good Repair - Building Upgrade - Boiler Conversion	2017	5,935,962
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000789941	State of Good Repair - Building Upgrade - Climate Control	2017	3,182,259
						CLIMATE CONTROL SYSTEM		
							I.S. 145 Total:	\$9,283,690
30	Queens	Q148		P.S. 148				
				DSF	0000813299	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	251,351
						Other		
			Q148	DSF	0000776068	IP Surveillance Camera Installation	2015	581,535
							P.S. 148 Total:	\$832,886
30	Queens	Q149		P.S. 149				
				DSF	0000844710	Educational Enhancements - Educational Enhancements - Accessibility	2018	82,694

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000777512	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	130,336
				DS	F0000799616	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	222,239
							P.S. 149 Total:	\$435,269
30	Queens	Q150		P.S. 150				
				DS	F0000813332	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
_						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
							P.S. 150 Total:	\$159,628
30	Queens	Q151		P.S. 151				
				DS	F0000790055	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2017	1,738,912
				DS	F0000799617	State of Good Repair - Building Upgrade - Lighting	2015	117,661
				DS	F0000813349	State of Good Repair - System Replacements - Exterior Masonry	2017	1,486,716
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
				DS	F0000813348	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2017	1,513,662

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000813347	State of Good Repair - System Replacements - Roofs	2017	2,171,776
						EXTERIOR:ROOFING:Roofing		
			Q151	DS	F0000822119	State of Good Repair - System Replacements - Toilets-Students	2016	251,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 151 Total:	\$7,280,078
30	Queens	Q152		P.S. 152				
			Q152	DS	F0000790080	State of Good Repair - System Replacements - Toilets-Students	2016	216,539
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
							P.S. 152 Total:	\$216,539
30	Queens	Q166		P.S. 166				
				DS	F0000798494	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	902,934
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 166 Total:	\$902,934
30	Queens	Q171		P.S. 171				
				DSF	0000798323	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,013,513
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 171 Total:	\$1,013,513
30	Queens	Q204		I.S. 204				
				DSF	0000799829	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	96,654
							I.S. 204 Total:	\$96,654
30	Queens	Q227		I.S. 227				
				DSF	0000801062	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,186,978
				DSF	0000801065	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,709,476
				DSF	0000799624	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	204,034
							IS 227 Total:	\$3 100 488

I.S. 227 Total: \$3,100,488

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
30	Queens	Q230		I.S. 230				
			Q230	DS	F0000821607	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DS	F0000823578	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
						Other		
			Q230	DS	F0000776075	IP Surveillance Camera Installation	2015	410,384
							I.S. 230 Total:	\$1,018,426
30	30 Queens	Q234		P.S. 234				
				DS	F0000823579	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							P.S. 234 Total:	\$74,806
30	Queens	Q292		P.S. 92				
				DS	F0000791379	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	29,642
				DS	F0000745712	State of Good Repair - System Replacements - Windows	2015	4,433,684
						EXTERIOR:WINDOWS		
							P.S. 92 Total:	\$4,463,326
33Q	Queens	Q800			INISTRATIVE /	STUDENT SERVICES		
				DS	F0000777531	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	155,160

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000792074	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,181,102
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						DOE ADMINISTRATIVE / STUDEN	T SERVICES Total:	\$1,336,262
33Q	Queens	Q801		OSSS / D	SF			
			QSFS	DS	F0000801052	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	45,457
				DS	F0000769303	State of Good Repair - Building Upgrade - Climate Control	2017	7,056,383
						CLIMATE CONTROL SYSTEM		
				DS	F0000799912	State of Good Repair - Building Upgrade - Elevators and Escalators	2017	1,492,522
				DS	F0000769305	State of Good Repair - Building Upgrade - Flood Elimination	2017	9,412,619
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000769320	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s)	2017	2,350,098

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSI	F0000822125	State of Good Repair - Building Upgrade - Interior Spaces	2017	506,828
				DSI	F0000822124	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2017	869,657
				DSI	F0000822123	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER HEAD	2017	13,296,737
				DSI	F0000769310	State of Good Repair - System Replacements - Electrical Systems PANEL BOARD TRANSFORMER	2017	16,055,270
				DSI	F0000799911	State of Good Repair - System Replacements - Electrical Systems	2017	385,924
				DSI	F0000769311	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2017	27,954,578
			Q974	DSI	F0000799869	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239

OSSS / DSF Total: \$79,461,312

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
33Q	Queens	Q998		NYC SCH	OOL CONSTR.	AUTHORITY		
				DSI	F0000844041	Domestic Piping	2017	15,465,962
				DSI	F0000844121	Domestic Piping	2017	2,618,148
						NYC SCHOOL CONSTR.	AUTHORITY Total:	\$18,084,110
75Q	Queens	Q009		P.S. 9 (W	REED SCHOOL	_)		
				DSI	F0000799910	Educational Enhancements - Educational Enhancements - Accessibility	2016	1,709,258
				DSI	F0000720930	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	1,136,842
				DSI	F0000787775	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	578,345
			Q009	DSI	F0000811101	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2016	490,872
				DSI	F0000720934	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2015	5,915,777
				DSI	F0000720933	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	3,074,959

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						P.S. 9 (W REE	D SCHOOL) Total:	\$12,906,053
75Q	Queens	Q075		P.S. 75 (R	PEARY SCHO	OL)		
				DSF	-0000798274	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	4,699,674
				DSF	-0000788791	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2016	1,318,408
				DSF	-0000788792	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent	2015	1,256,527
			Q075	DSF	-0000788798	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DSF	-0000843715	System Expansion - New Physical Education Facilities - Playgrounds	2016	1,575,274
						P.S. 75 (R PEAR	Y SCHOOL) Total:	\$8,885,122
75Q	Queens	Q142		•	OLD J142) =0000777510	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	129,080

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000789870	State of Good Repair - Building Upgrade - Lighting	2016	1,467,892
				DSI	F0000799825	Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			Q752	DSI	F0000843803	<i>Other</i> Classroom Connectivity	2016	455,487
						P.S. 75	2 (OLD J142) Total:	\$2,131,765
75Q	Queens	Q177		P.S. 177				
				DSI	F0000798293	State of Good Repair - Building Upgrade - Boiler Conversion	2017	7,998,855
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	F0000790486	State of Good Repair - Building Upgrade - Climate Control	2017	1,423,116
						CLIMATE CONTROL SYSTEM		
				DSI	F0000790487	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,336,104
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q177	DS	F0000790493	CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			o /			Other		
			Q177	DS	F0000843802	Classroom Connectivity	2016 P.S. 177 Total:	356,146 \$11 149 484
75Q	Queens	Q722	Q721		KENNEDY JR . 5 5F0000815284	SCHOOL State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES	2019	4,665,952
						EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER EXTERIOR:STAIRS/RAMPS: EXTERIOR		
				DS	F0000823580	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
				DS	F0000792064	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	41,775
			Q721	DS	F0000815282	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2019	2,271,132

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:ROOFING:Specialties		
						JOHN F. KENNEDY	JR. SCHOOL Total:	\$7,053,665
75Q	Queens	Q811		P.S. 811 (0	OLD 187)			
				DSF	0000777532	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	111,721
				DSF	0000798374	State of Good Repair - Building Upgrade - Boiler Conversion	2017	6,887,557
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000792110	State of Good Repair - Building Upgrade - Climate Control	2017	1,359,038
						CLIMATE CONTROL SYSTEM		
				DSF	0000792112	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,179,161
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						P.S. 8	311 (OLD 187) Total:	\$9,537,477
78Q	Queens	K420		FRANKLIN	N K. LANE HS			
				DSF	0000844728	Educational Enhancements - Educational Enhancements - Accessibility	2017	524,121
				DSF	0000821839	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	2,067,563

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799563	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	422,766
			K618	DS	F0000783323	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2016	868,569
			K583	DS	F0000799866	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DS	F0000821798	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER SYSTEM	2018	260,353
				DS	F0000821905	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	88,231
				DS	F0000806620	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	251,351
						Other		
				DS	F0000843861	IP Surveillance Camera Installation	2017	527,479
						FRANKL	N K. LANE HS Total:	\$5,045,672
78Q	Queens	Q023		QUEENS	ACADEMY HS			
				DS	F0000787986	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,551,338

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000787985	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	540,033
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000800271	State of Good Repair - System Replacements - Exterior	2016	402,333
						Masonry		
						EXTERIOR: EXTERIOR WALLS		
				DS	F0000800270	State of Good Repair - System Replacements - Roofs	2016	344,990
						EXTERIOR:ROOFING:Roofing		
						QUEENS A	CADEMY HS Total:	\$2,838,694
78Q	Queens	Q400		AUGUST	MARTIN HS			
			Q400	DS	F0000799365	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	313,111
			Q400	DS	F0000799367	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	274,688
				DS	F0000843890	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,136,140
				DS	F0000843675	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Library Upgrades	2018	1,722,742

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000777517	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	222,510
				DSI	F0000798303	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,845,438
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798305	State of Good Repair - Building Upgrade - Climate Control	2019	1,375,057
						CLIMATE CONTROL SYSTEM		
			Q400	DSI	F0000799996	State of Good Repair - System Replacements - Toilets-Students	2016	195,11 <i>1</i>
						FIXTURES:STUDENT:Toilet INTERIOR:TOILET ROOMS - STUDENTS		
						AUGUS	ST MARTIN HS Total:	\$11,084,797
78Q	Queens	Q405		BAYSIDE	HS			
				DS	F0000799627	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	620,686
			Q495	DSI	F0000821803	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2018	2,084,380
			Q495	DSI	F0000791438	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
							BAYSIDE HS Total:	\$2,740,305
78Q	Queens	Q410		BEACH C	HANNEL EDUC	CATIONAL CAMPUS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000777518	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	234,221
				DSF	-0000791453	State of Good Repair - Building Upgrade - Climate Control	2015	2,515,576
				DSF	F0000799435	CLIMATE CONTROL SYSTEM State of Good Repair - Building Upgrade - Flood Elimination	2015	8,020,814
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	-0000799931	State of Good Repair - Building Upgrade - Interior Spaces	2015	839,007
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls		
				DSF	0000799628	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	745,060
				DSF	-0000791459	State of Good Repair - System Replacements - Domestic Piping	2015	1,519,885
				DSF	-0000791457	DOMESTIC WATER SYSTEM State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH	2015	2,489,406

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799946	State of Good Repair - System Replacements - Electrical Systems	2015	548,590
						EMERGENCY GENERATOR SET		
				DS	F0000791458	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	12,669,621
						GAS SERVICE: GAS DISTRIBUTION PIPING HEATING PLANT: BOILER AUXILIARIES		
						HEATING PLANT:BOILER SYSTEM		
						HEATING PLANT: FUEL SYSTEMS		
				DS	F0000814698	State of Good Repair - System Replacements -	2015	236,967
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
						Other		
				DS	F0000843862	IP Surveillance Camera Installation	2017	604,000
						BEACH CHANNEL EDUCATION	AL CAMPUS Total:	\$30,423,147
78Q	Queens	Q411		BEACH C	CHANNEL HS AI	=		
			Q410	DS	F0000843700	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2017	4,838,029
						ATHLETIC FIELDS: FIXED EQUIPMENT		
						ATHLETIC FIELDS: PLAYING SURFACE		
						ATHLETIC FIELDS:SEATING		

District	Borough	Building ID	Ora ID	School	Project #	Description	FY - Construction Start	Total
			g		,	SITE:Drainage System for Asphalt	otart	
						SITE:Drainage System for Soil		
						SITE:DRINKING FOUNTAINS		
						SITE:FENCES		
						SITE: IRRIGATION SYSTEM		
						SITE:PAVING - STUDENT NON-USE:Asphalt		
						SITE:RETAINING WALLS		
						SITE:SIDEWALKS:DOT Sidewalk		
						SITE:SITE WALLS (NOT RETAINING WALLS)		
						BEACH CHA	NNEL HS AF Total:	\$4,838,029
78Q	Queens	Q415		BENJAMI	N N. CARDOZC) HS		
			Q415	DSF	0000845618	Educational Enhancements - Educational	2018	543,378
						Enhancements - Accessibility		
				DSF	0000777519	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	187,337
				DSF	0000791475	State of Good Repair - Building Upgrade - Flood Elimination	2016	753,212
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	0000799706	State of Good Repair - Building Upgrade - Lighting	2015	221,202
						Fixtures		, -
				DSF	0000799831	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	54,522
			Q415	DSF	0000814720	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						BENJAMIN N. CA	ARDOZO HS Total:	\$1,915,017
78Q	Queens	Q420		SPRINGFI	ELD GARDEN	S HS		
				DSF	0000777520	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	153,812
				DSF	0000799629	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	241,825
			Q265	DSF	50000814742	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:EXTERIOR WALLS	2017	8,223,950
				DSF	-0000814748	State of Good Repair - System Replacements - Paved Area-Concrete SITE:Drainage System for Concrete SITE:PAVING - STUDENT NON-USE:Concrete SITE:SIDEWALKS:Site Sidewalk and Walkways SITE:SITE WALLS (NOT RETAINING WALLS)	2017	544,303
			Q265	DSF	-0000822213	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2017	314,528
						SPRINGFIELD G	ARDENS HS Total:	\$9,478,418
78Q	Queens	Q421			ELD GDNS HS 50000791517	AF State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELDS:FIXED EQUIPMENT	2016	10,936,834

District	Borough	Building ID	Org ID	School Project #	Description	FY - Construction Start	Total
					ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING		
					SITE:Drainage System for Asphalt SITE:Drainage System for Soil		
					SITE:PAVING - STUDENT USE:Asphalt		
					SITE:PAVING - STUDENT USE:Concrete		
					SITE:SIDEWALKS:DOT Sidewalk		
					SITE:SITE WALLS (NOT RETAINING WALLS)		
					SITE:STAIRS/RAMPS: EXTERIOR		
			Q283	DSF0000844738	State of Good Repair - System Replacements - Paved	2017	171,608
					Area-Concrete		
					SPRINGFIELD	GDNS HS AF Total:	\$11,108,442
78Q	Queens	Q425		JOHN BOWNE HS			
				DSF0000799630	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	198,117
				DSF0000799780	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	195,881
			Q425	DSF0000791523	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF0000814775	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2016	159,231
					JOHN	BOWNE HS Total:	\$588,492
78Q	Queens	Q430		FRANCIS LEWIS HS			

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000799991	State of Good Repair - Building Upgrade - Flood Elimination	2018	3,026,065
				DSI	-0000799631	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - Building Upgrade - Lighting Fixtures	2015	217,231
				DSI	-0000791538	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	1,582,790
						PUBLIC ADDRESS SYSTEM		
						FRANC	S LEWIS HS Total:	\$4,826,086
78Q	Queens	Q435			AN BUREN HS			
				DSI	-0000843892	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	2,137,957
				DSI	F0000777521	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	187,317
			Q435	DSI	F0000798416	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q435	DSI	-0000791562	State of Good Repair - Building Upgrade - Climate Control	2018	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSI	-0000799707	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	659,133

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	-0000745890	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	3,217,981
						FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM		
						MARTIN VAN I	BUREN HS Total:	\$11,979,415
78Q	Queens	Q440		FOREST H	HILLS HS			
				DSF	F0000844713	Educational Enhancements - Educational Enhancements - Accessibility	2017	548,945
				DSF	-0000777522	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	72,483
				DSF	-0000799781	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	92,283
				DSF	-0000791598	State of Good Repair - System Replacements - Auditorium Upgrade	2016	117,747
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
			Q440	DSF	-0000791591	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						GAS SERVICE:GAS DISTRIBUTION PIPING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
				DSF	F0000814835	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310

FOREST HILLS HS Total: \$1,178,031

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
78Q	Queens	Q441		FOREST	HILLS HS AF			
				DSI	F0000814851	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields SITE:FENCES	2017	336,927
							OREST HILLS HS AF Total:	\$336,927
78Q	Queens	Q445		WILLIAM	C. BRYANT HS			
				DSI	-0000791625	Safety and Security - Safety and Security - Safety Systems	2015	284,331
						EXTERIOR:DOORS:DOORS AND FRAMES INTERIOR:INTERIOR GUARDS		
				DSI	-0000798489	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSI	-0000791607	State of Good Repair - Building Upgrade - Climat Control	e 2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSI	-0000799708	State of Good Repair - Building Upgrade - Lightin Fixtures	ig 2015	204,156
			Q445	DSI	-0000821933	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopmen	2017 t	3,083,807
				DSI	-0000791621	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Stage:Stage Curtain	2019 Rigging	236,705

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:AUDITORIUM:Stage:Stage Curtains		
				DS	F0000836991	State of Good Repair - System Replacements - Gymnasium Upgrade	2018	85,996
						INTERIOR:GYMNASIUM:Seating		
				DS	F0000814859	State of Good Repair - System Replacements - Toilets-Students	2015	189,334
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
				00	F0000022651	FIXTURES:STUDENT:Urinal	2010	105 010
				D8	F0000823651	State of Good Repair - System Replacements - Toilets-Students	2016	185,810
						WILLI	AM C. BRYANT HS Total:	\$10,047,166
78Q	Queens	Q446		BRYANT	HS AF			
			Q445	DS	F0000836932	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2016	27,027
						ATHLETIC FIELDS:PLAYING SURFACE		
							BRYANT HS AF Total:	\$27,027
78Q	Queens	Q450		NEWCON	IERS HIGH SCH	HOOL (OLD LIC)		
			Q555	DS	F0000845578	Domestic Piping	2017	755,000
						DOMESTIC WATER SYSTEM FIXTURES:Student:Drinking Fountain		
				DS	F0000791632	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,567,655

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF	0000799832	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	61,958
						NEWCOMERS HIGH SCHOO	L (OLD LIC) Total:	\$2,384,613
78Q	Queens	Q452		LONG ISL	AND CITY HS	(NEW)		
				DSF	0000822192	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Kitchen Areas	2019	2,073,193
				DSF	0000768897	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	13,757,882
			Q450	DSF	F0000814902	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	2,412,773
				DSF	0000745990	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems	2015	9,759,978
			Q450	DSF	0000814906	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:EXTERIOR WALLS	2018	1,958,604

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000799462	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	43,036
				DSI	F0000814908	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
			Q450	DSI	F0000791664	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2018	8,677,307
			Q450	DSI	F0000814904	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	5,585,561
						LONG ISLAND CITY	(HS (NEW) Total:	\$44,343,140
78Q	Queens	Q455		NEWTOW	/N HS			
			Q455	DSI	F0000799498	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2015	2,659,389
				DS	F0000791680	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	164,015
				DS	F0000799632	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	254,269
			Q455	DSI	F0000791687	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal	2016	167,466

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
							NEWTOWN HS Total:	\$3,245,139
78Q	Queens	Q460		FLUSHING	HS			
				DSF	0000777523	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	135,614
				DSF	0000799709	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	228,803
			Q460	DSF	0000791726	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	0000799833	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	191,072
				DSF	0000814966	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent		
							FLUSHING HS Total:	\$692,103
78Q	Queens	Q465		FAR ROCK	AWAY HS			
				DSF	0000821672	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,949,276

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000821673	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	903,006
				DS	F0000777524	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	218,323
				DS	F0000799633	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	515,894
				DS	F0000791745	State of Good Repair - Building Upgrade - Reinforcing Support Elements INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE	2018	1,066,009
			Q260	DS	F0000821629	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			Q260	SC	A0000026014	State of Good Repair - System Replacements - Exterior Masonry	2018	4,757,163
				DS	F0000791747	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	8,654,549
				DS	F0000791746	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2018	5,948,474
			Q260	DS	F0000791751	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet	2016	193,861

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
				DS	F0000791748	State of Good Repair - System Replacements - Windows	2018	2,817,515
						EXTERIOR:WINDOWS		
						Other		
				DS	F0000843853	IP Surveillance Camera Installation	2017	448,918
						FAR RO	CKAWAY HS Total:	\$28,006,224
78Q	Queens	Q470		JAMAICA	A HS			
				DS	F0000777525	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	183,741
				DS	F0000798427	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	539,050
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q470	DS	F0000821614	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			Q470	DS	F0000845574	State of Good Repair - System Replacements - Exterior Masonry	2018	787,500
				DS	F0000815011	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink	2016	101,351

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
							JAMAICA HS Total:	\$2,144,878
78Q	Queens	Q475		RICHMON	D HILL HS			
			Q475	DSF	0000799973	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,083,087
			Q475	DSF	0000799974	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	371,385
				DSF	0000843980	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	168,918
			Q475	DSF	0000799975	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Technology	2015	119,385
			Q475	DSF	0000844147	Safety and Security - Safety and Security - Code Compliance	2019	93,914
				DSF	0000777526	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	198,348
				DSF	0000799634	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	615,907
				DSF	0000799900	State of Good Repair - Building Upgrade - Reinforcing Support Elements	2015	2,240,803
			Q475	DSF	0000800122	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2016	5,719,519

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q475	DSI	F0000821610	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			Q475	DSI	F0000791801	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000815038	State of Good Repair - System Replacements - Toilets-Students	2016	1,051,783
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent		
						RICH	MOND HILL HS Total:	\$12,231,548
78Q	Queens	Q480		JOHN AD	AMS HS			
			Q480	DS	F0000799368	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	1,080,713
			Q480	DS	F0000844122	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,132,500
				DSI	F0000777527	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	189,781
				DSI	F0000799635	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	227,206
			Q480	DS	F0000845623	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2017	7,500,000

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q480	DSF	-0000823638	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	528,638
			Q480	DSF	-0000791830	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
				DSF	-0000843854	IP Surveillance Camera Installation	2017	476,465
						J	OHN ADAMS HS Total:	\$11,170,566
78Q	Queens	Q485		GROVER	CLEVELAND H	S		
			Q485	DSF	-0000791848	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,145,754
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUN PUMP	Ρ	
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	-0000799636	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	218,798
				DSF	-0000815083	State of Good Repair - System Replacements - Heating Plant Upgrade	2 018	260,353
						HEATING PLANT:BOILER SYSTEM		
				DSF	-0000822658	State of Good Repair - System Replacements - Heating Plant Upgrade	g 2018	311,310
						GROVER	CLEVELAND HS Total:	\$1,936,215
78Q	Queens	Q488		CLEVELA	ND HS AF NO.	2		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	-0000769098	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2016	11,297,386
						CLEVELAND H	S AF NO. 2 Total:	\$11,297,386
78Q	Queens	Q490		CAMPUS	MAGNET HS (.	JACKSON)		
				DSI	F0000843982	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,200,646
				DSI	-0000777528	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	154,179
						CAMPUS MAGNET HS (JACKSON) Total:	\$1,354,825
78Q	78Q Queens	Q505		HILLCRE	ST HS			
			Q505	DSI	F0000843728	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,178,000
				DSI	-0000777529	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	248,363
				DSI	-0000791893	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	3,661,759
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			Q505	DSI	F0000821631	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			Q505	DSI	F0000791900	State of Good Repair - System Replacements - Heating Plant Upgrade	g 2015	35,263
							HILLCREST HS Total:	\$5,656,621
78Q	Queens	Q515		TOWNSE	ND HARRIS HS			
				DSI	F0000844714	Educational Enhancements - Educational Enhancements - Accessibility	2018	123,530
						TOWNS	END HARRIS HS Total:	\$123,530
78Q	Queens	Q566		QNS HS C	OF TEACH., LIB	ARTS&SCI		
				DSI	F0000844708	Educational Enhancements - Educational Enhancements - Accessibility	2018	64,902
						QNS HS OF TEACH.	, LIB. ARTS&SCI Total:	\$64,902
78Q	Queens	Q567		GLEN OA	KS CAMPUS F	ACILITY		
				DSI	F0000754249	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2015	20,278,410
						GLEN OAKS CA	MPUS FACILITY Total:	\$20,278,410
78Q	Queens	Q570		FRANK S	INATRA HIGH S	SCHOOL		
						Other		
			Q501	DS	F0000843799	Classroom Connectivity	2016	107,662
						FRANK SINATRA	A HIGH SCHOOL Total:	\$107,662
78Q	Queens	Q595		AUX. SEF	RV JAMAICA L	EARN CT		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000791938	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	504,928
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescen CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandesce		
				DS	F0000815168	State of Good Repair - System Replacements - Toilets-Students	2016	103,215
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						AUX. SERV JA	MAICA LEARN CT Total:	\$608,143
78Q	Queens	Q600		QUEENS	VOC HS			
			Q600	DS	F0000801044	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE EJECTOR PUMP	2015	28,794
							QUEENS VOC HS Total:	\$28,794
78Q	Queens	Q610		Ανιατιο	NHS			
				DS	F0000799902	Educational Enhancements - Educational Enhancements - Accessibility	2016	1,688,438
			Q610	DS	F0000798342	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			Q610	DS	F0000798343	State of Good Repair - Building Upgrade - Climate	2018	1,323,762
			dono	20		Control	2010	1,020,102
						CLIMATE CONTROL SYSTEM		
				DS	F0000769187	State of Good Repair - Building Upgrade - Flood Elimination	2016	672,156
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000791966	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,164,628
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - HID CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DS	F0000769206	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers SPRINKLERS, STANDPIPE, FIRE SYSTEM:DELUGE VALVE SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER HEAD	2016	3,021,023

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING SPRINKLERS, STANDPIPE, FIRE SYSTEM:STANDPIPE SYSTEM		
				DSF	0000769191	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:AWNINGS AND CANOPIES EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS	2016	3,486,703
				DSF	0000769202	State of Good Repair - System Replacements - Gymnasium Upgrade FIXTURES:STUDENT:Locker Room Shower GYMNASIUM:LIGHTING:Lighting Fixture - HID GYMNASIUM:LIGHTING:Lighting Fixture - Incandescent GYMNASIUM:LOCAL SOUND SYSTEM GYMNASIUM:SCOREBOARD INTERIOR:GYMNASIUM:Floor Finish	2016	1,676,846
				DSF	0000769190	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	5,953,711
				DSF	0000769189	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2016	6,157,851

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000791972	State of Good Repair - System Replacements - Windows	2016	1,198,361
						EXTERIOR:WINDOWS	AVIATION HS Total:	\$31,008,164
78Q	Queens	Q620		THOMAS	A. EDISON VO	C HS		
				DSI	F0000800338	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	740,211
				DSI	F0000777530	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	204,535
				DSI	F0000799637	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	301,702
				DSI	F0000769212	State of Good Repair - System Replacements - Exterior Masonry	2015	6,665,187
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS		
			Q620	DSI	F0000799868	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
				DSI	F0000769211	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2015	5,245,820
				DSI	F0000791991	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties	2015	2,564,827

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						THOMAS A. EDIS	ON VOC HS Total:	\$15,757,521
78Q	Queens	Q680		YOUNG W	OMENS' LEAD	DERSHIP SCHOOL		
				DSF	0000822241	State of Good Repair - System Replacements - Heating Plant Upgrade	2016	32,929
						HEATING PLANT:BOILER SYSTEM		
						YOUNG WOMENS' LEADERSH	IIP SCHOOL Total:	\$32,929
78Q	Queens	Q690		HS FOR L	AW ENFORCE	MENT		
				DSF	-0000800326	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers	2015	66,867
						HS FOR LAW ENF	ORCEMENT Total:	\$66,867
78Q	Queens	Q707		R. F. KEN	NEDY COMM.	MIDDLE/HS		
				DSF	0000792029	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	490,944
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
						R. F. KENNEDY COMM.	MIDDLE/HS Total:	\$490,944
78Q	Queens	Q725		HS FOR I		ТЕСН		
				DSF	0000799782	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	76,852

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HS FOR INFORM	ATION TECH Total:	\$76,852
78Q	Queens	Q744		ELMHUR	ST EDUCATION	NAL CAMPUS		
			Q296	DS	F0000799518	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	313,851
			Q744	DS	F0000823567	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	3,283,936
						ELMHURST EDUCATION	AL CAMPUS Total:	\$3,597,787
78Q	Queens	Q798		BACCAL	AUREATE SCL	FOR GLOBAL ED		
			Q580	DS	F0000843905	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System AIR CONDITIONING:Condenser Water Piping AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Cooling Tower AIR CONDITIONING:Packaged / Rooftop Unit AIR CONDITIONING:Return Fan	2016	219,418
						BACCALAUREATE SCL FOR	GLOBAL ED Total:	\$219,418
78Q	Queens	Q859		_	3 / ROC C F0000799710 F0000844132	State of Good Repair - Building Upgrade - Lighting Fixtures State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2015 2018	197,392 185,522

		Building						FY - Construction	
District	Borough	ID	Org ID	School	Project #	Description		Start	Total
						AIR CONDITI	ONING:COOLING TOWER		
								REGION 3 / ROC C Total:	\$382,914
78Q	Queens	Q891		R. F. WAG	GNER SEC SCL	ARTS & TECH			
				DS	F0000821790		ncements - Educational oom Conversions/Partitioning	2016	476,212
							R. F. WAGNER SEC	C SCL ARTS & TECH Total:	\$476,212

District	Borough	Building ID	Org ID Sci	hool Project #	Description	FY - Construction Start	Total
31	Staten Island	R001	P.S	6. 1			
				DSF0000792253	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	848,179
					CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSF0000792257	State of Good Repair - System Replacements - Exterior	2018	10,792,221
					Masonry		
					EXTERIOR:EXTERIOR WALLS		
				DSF0000792256	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2018	1,427,859
				DSF0000815507	State of Good Repair - System Replacements - Roofs	2018	1,439,795
					EXTERIOR:ROOFING:Roofing EXTERIOR:ROOFING:Specialties		
				DSF0000821810	State of Good Repair - System Replacements - Windows	2018	2,011,059
					EXTERIOR:WINDOWS		
						P.S. 1 Total:	\$16,519,113
31	Staten Island	R002	I.S.	. 2			
				DSF0000799449	State of Good Repair - Building Upgrade - Climate Control	2015	1,093,713
					CLIMATE CONTROL SYSTEM		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	6F0000799448	State of Good Repair - Building Upgrade - Flood Elimination DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP INTERIOR:STRUCTURAL:FOUNDATION WALLS	2015	2,303,633
				DS	SF0000799445	State of Good Repair - Building Upgrade - Interior Spaces INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR	2015	586,787
				DS	F0000799639	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	512,049
				DS	F0000799753	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	70,292
				DS	SF0000799447	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	742,351
				DS	6F0000799446	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING	2015	6,342,189

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
				DS	F0000815530	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Toilet	2015	251,351
							I.S. 2 Total:	\$11,902,365
31	Staten Island	R003		P.S. 3				
				DS	F0000798310	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,845,438
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DS	F0000798311	State of Good Repair - Building Upgrade - Climate Control	2019	1,375,057
						CLIMATE CONTROL SYSTEM		
							P.S. 3 Total:	\$6,220,495
31	Staten Island	R004		P.S. 4				
			R004	DS	F0000792298	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
							P.S. 4 Total:	\$35,263
31	Staten Island	R006		P.S. 6				
				DS	F0000797735	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	45,924

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R006	D	SF0000843899	State of Good Repair - System Replacements - Heating Plant Upgrade DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER):Dual Temperature Distribution: Piping, Pumps and Auxiliaries GAS SERVICE:Gas Distribution Piping HEATING PLANT:Boiler Auxiliaries HEATING PLANT:Boiler System HEATING PLANT:Fuel System HEATING:Hydronic Heating:Backflow Preventer HEATING:Hydronic Heating:Hydronic Hot Water	2016	41,118
						Distribution: Piping, Pumps and Auxiliaries	P.S. 6 Total:	\$87,042
31	Staten Island	R007		I.S. 7				<i>••••</i> ,••=
				D	SF0000799640	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	227,592
				D	SF0000815617	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
							I.S. 7 Total:	\$760,828
31	Staten Island	R008		P.S. 8				
				D	SF0000799711	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	134,742
				D	SF0000775655	State of Good Repair - System Replacements - Domestic Piping	2015	992,759

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
			R008	DSF	-0000815624	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 8 Total:	\$1,228,852
31	Staten Island	R011		P.S. 11				
			R011	DSF	-0000815645	State of Good Repair - System Replacements - Toilets-Students	2018	1,481,402
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 11 Total:	\$1,481,402
31	Staten Island	R016		P.S. 16				
			R016	DSF	0000777539	State of Good Repair - Building Upgrade - Flood Elimination	2015	1,527,581
							P.S. 16 Total:	\$1,527,581
31	Staten Island	R018		P.S. 18				
				DSF	0000815705	State of Good Repair - System Replacements - Toilets-Students	2017	159,628
						FIXTURES:STUDENT:Lavatory/Sink		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 18 Total:	\$159,628
31	Staten Island	R019		P.S. 19				
				DSF	0000746802	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,708,829
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DSF	0000799641	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	122,122
				DSF	0000792471	State of Good Repair - System Replacements - Exterior Masonry	2016	12,311,289
						EXTERIOR: EXTERIOR WALLS		
				DSF	0000746804	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	3,705,761
				DSF	0000769753	State of Good Repair - System Replacements - Windows	2016	991,848
						EXTERIOR:WINDOWS		
							P.S. 19 Total:	\$18,839,849
31	Staten Island	R020		P.S. 20				
			R020	DSF	0000798413	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,667,715

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			R020	DS	SF0000792488	State of Good Repair - Building Upgrade - Climate Control	2019	1,324,622
						CLIMATE CONTROL SYSTEM		
				DS	SF0000792489	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	702,686
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 20 Total:	\$6,695,023
31	Staten Island	R021		P.S. 21				
•				-	SF0000792507	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	361,579
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R021	DS	SF0000837807	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2016	91,362
			R021	DS	SF0000843976	AIR CONDITIONING:Packaged / Rooftop Unit State of Good Repair - System Replacements - Heating Plant Upgrade	2016	35,977

District	Borough	Building ID	Ora ID	School	Project #	Description	FY - Construction Start	Total
District	Dorough		Orgib	0011001		GAS SERVICE:Gas Distribution Piping	Start	Total
						GAS SERVICE:Gas Meter Room Exhaust Fan		
						GAS SERVICE:Gas Meter Room Vent		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT:Fuel System		
				DSF	-0000815763	State of Good Repair - System Replacements -	2016	251,351
						Toilets-Students		
						FIXTURES:STUDENT:Toilet		
							P.S. 21 Total:	\$740,269
31	Staten Island	R023		P.S. 23				
				DSF	-0000799791	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	45,771
							P.S. 23 Total:	\$45,771
31	Staten Island	R024		I.S. 24				
				DSF	-0000799835	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
				DSF	-0000837849	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	48,583
						HEATING PLANT:Boiler System		
							I.S. 24 Total:	\$127,889

31 Staten Island R026 **P.S. 26**

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000815840	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 26 Total:	\$101,351
31	Staten Island	R027		I.S. 27				
			R027	DS	F0000792611	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			R027	DS	F0000822152	State of Good Repair - System Replacements - Toilets-Students	2015	251,351
						INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 27 Total:	\$286,614
31	Staten Island	R029		P.S. 29				
				DS	F0000769913	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2015	1,688,051
				DS	F0000799712	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	107,390
			R029	DS	F0000822179	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY	2018	3,015,877

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:CORNICE EXTERIOR:EXTERIOR SOFFITS EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
				DSF	0000799836	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			R029	DSF	-0000843919	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	1,149,495
			R029	DSF	F0000843918	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	1,312,758
							P.S. 29 Total:	\$7,352,877
31	Staten Island	R030		P.S. 30				
				DSF	0000792650	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,026,913
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
							P.S. 30 Total:	\$1,026,913
31	Staten Island	R031		P.S. 31				
				DSF	F0000815908	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,332,829

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 31 Total:	\$1,332,829
31	Staten Island	R032		P.S. 32				
			R032	DSF	0000792692	State of Good Repair - Building Upgrade - Flood Elimination INTERIOR:STRUCTURAL:FOUNDATION WALLS	2018	1,569,282
			R032	DSF	0000815933	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2018	492,915
			R032	DSF	0000837971	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOF:Roofing EXTERIOR:ROOF:Specialties	2018	769,378
				DSF	0000815936	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Fluorescent TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2015	217,625

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 32 Total:	\$3,049,200
31	Staten Island	R034		I.S. 34 (OL	D TOTTENVIL	LE)		
				DSF	0000776033	Educational Enhancements - Educational Enhancements - Accessibility	2016	12,940,259
			R034	DSF	0000775996	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	669,852
				DSF	0000792723	Educational Enhancements - Educational Enhancements - Science Lab Upgrades INTERIOR:SCIENCE DEMO ROOM:Fixed Equipment INTERIOR:SCIENCE LAB:Fixed Equipment SCIENCE DEMO ROOM SCIENCE LAB SCIENCE LAB SCIENCE LAB:EMERGENCY GAS SHUT-OFF VALVE SCIENCE PREP ROOM SCIENCE PREP ROOM:LIGHTING:Lighting Fixture - Incandescent	2015	1,663,747
				DSF	-0000798376	State of Good Repair - Building Upgrade - Boiler Conversion HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2019	4,845,438
				DSF	60000792707	State of Good Repair - Building Upgrade - Climate Control CLIMATE CONTROL SYSTEM	2019	1,375,057
				DSF	0000799755	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	64,668

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000792708	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems FIRE ALARM SYSTEM	2016	1,435,518
			R034	DS	F0000838002	State of Good Repair - System Replacements - Domestic Piping Waste System	2018	173,201
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage Ejector Pump DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
						I.S. 34 (OLD TOT	TENVILLE) Total:	\$23,167,740
31	Staten Island	R035		P.S. 35				
				DSI	F0000815965	State of Good Repair - Building Upgrade - Climate Control	2016	887,984
						CLIMATE CONTROL SYSTEM		
				DS	F0000798338	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	386,581
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	F0000792734	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING HEATING PLANT:BOILER AUXILIARIES	2016	4,037,259

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
			R035	DS	F0000815971	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 35 Total:	\$5,413,175
31	Staten Island	R036		P.S. 36				
				DS	F0000792744	State of Good Repair - Building Upgrade - Climate Control	2015	1,342,318
						CLIMATE CONTROL SYSTEM		
				DS	F0000770036	State of Good Repair - Building Upgrade - Flood Elimination	2015	566,836
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799713	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	325,729
				DS	F0000770040	State of Good Repair - System Replacements - Exterior Masonry	2015	1,649,181
						EXTERIOR:AREAWAY EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR SOFFITS		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:EXTERIOR WALLS EXTERIOR:LOUVER		
				DS	SF0000770042	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	7,440,464
				DS	SF0000792760	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation VENTILATION:HEATING AND VENTILATING UNIT	2015	3,451,666
				DS	F0000843714	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	80,027
				DS	\$F0000770037	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	4,919,747
				DS	\$F0000770039	State of Good Repair - System Replacements - Windows EXTERIOR:WINDOWS	2015	4,334,439
						Other		
				DS	F0000775856	IP Surveillance Camera Installation	2015	617,897
							P.S. 36 Total:	\$24,728,304

31 Staten Island R039 P.S. 39

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R039	DSI	F0000823620	State of Good Repair - Building Upgrade - Flood Elimination	2019	52,129
							P.S. 39 Total:	\$52,129
31	Staten Island	R041		P.S. 41				
				DSI	F0000799714	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	143,793
			R041	DSI	F0000843971	State of Good Repair - Building Upgrade - Low-Voltage Electrical Systems AUXILIARY SIGNAL/BELL SYSTEM FIRE ALARM SYSTEM PUBLIC ADDRESS SYSTEM	2017	581,057
			R041	DSI	F0000816045	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM LIGHTNING PROTECTION PANEL BOARD SERVICE SWITCH SWITCHBOARD	2017	1,456,267
			R041	DSI	F0000792820	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal TOILET ROOM - STUDENT:LIGHTING:Lighting Fixture - Incandescent	2016	197,941

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 41 Total:	\$2,379,058
31	Staten Island	R042		P.S. 42				
				DSF	-0000792840	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	63,014
			R042	DSF	-0000816066	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2018	155,366
						HEATING PLANT:FUEL SYSTEMS	P.S. 42 Total:	\$218,380
31	Staten Island	R043		JEROME	PARKER CAMI	PUS	P.S. 42 Total:	ΦΖ ΙΟ, 300
				DSF	-0000801048	Playground Redevelopment SITE:Drainage System for Asphalt SITE:Drainage System for Concrete	2016	1,587,500
			R047	DSF	-0000799795	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						Other		
			R047	DSF	-0000843804	Classroom Connectivity	2016	330,901
						JEROME PARKE	R CAMPUS Total:	\$1,953,664
31	Staten Island	R044		P.S. 44				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000816080	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	1,137,782
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
				DS	F0000704503	State of Good Repair - System Replacements - Exterior Masonry	2016	9,077,574
						EXTERIOR: Exterior Walls		
				DS	F0000816083	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	444,853
				DS	F0000821741	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	1,851,207
				DS	F0000821742	State of Good Repair - System Replacements - Windows	2016	1,308,392
						EXTERIOR:WINDOWS		
						Other		
			R044	DS	F0000843807	Classroom Connectivity	2016	333,921
							P.S. 44 Total:	\$14,153,729
31	Staten Island	R045		P.S. 45				
				DS	F0000792874	State of Good Repair - Building Upgrade - Flood Elimination	2016	1,568,044
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799642	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	131,093

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000792877	State of Good Repair - System Replacements - Exterior Masonry	2016	5,719,207
			R045	DSF	-0000843946	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Heating Plant Upgrade	2018	75,878
				DSF	0000770166	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2016	4,765,489
				DSF	0000770165	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2016	2,598,430
						Other		
				DSF	0000775711	IP Surveillance Camera Installation	2015	497,786
							P.S. 45 Total:	\$15,355,927
31	Staten Island	R046		P.S. 46				
				DSF	-0000822659	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	245,771
				DSF	-0000816116	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal		
						INTERIOR:TOILET ROOMS - STUDENTS		
							D.C. AC Total	¢247 400

P.S. 46 Total: \$347,122

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
31	Staten Island	R048		P.S. 48				
			R048	DSI	F0000798346	State of Good Repair - Building Upgrade - Boiler Conversion	2018	4,664,685
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
			R048	DSI	F0000792908	State of Good Repair - Building Upgrade - Climate Control	2018	1,323,762
						CLIMATE CONTROL SYSTEM		
				DSI	F0000681389	State of Good Repair - System Replacements - Paved	2017	843,813
						Area-Concrete		
						SITE:Retaining Walls		
							P.S. 48 Total:	\$6,832,260
31	Staten Island	R049		I.S. 49				
				DSI	F0000821615	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
				DSI	F0000816149	State of Good Repair - System Replacements - Toilets-Students	2015	236,503
						FIXTURES:STUDENT:Toilet		
							I.S. 49 Total:	\$769,739
31	Staten Island	R051		I.S. 51				
				DSI	F0000775659	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2015	844,001

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R051	DS	F0000838238	State of Good Repair - System Replacements - Domestic Piping Waste System	2015	134,666
						DRAIN/WASTE/VENT AND STORM SYSTEM:Sewage/Waste/Vent Piping		
							I.S. 51 Total:	\$978,667
31	Staten Island	R052		P.S. 52				
				DS	F0000799454	State of Good Repair - Building Upgrade - Climate Control	2015	1,439,896
						CLIMATE CONTROL SYSTEM		
			R052 DSF0000747329 State of Good Repair - Building Upgrade - Flood 2015 Elimination	1,050,238				
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799453	State of Good Repair - Building Upgrade - Flood Elimination	2015	4,675,977
						DRAIN/WASTE/VENT AND STORM SYSTEM:SUMP PUMP		
						INTERIOR:STRUCTURAL:FOUNDATION WALLS		
				DS	F0000799451	State of Good Repair - Building Upgrade - Interior	2015	1,888,000
						Spaces		
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN		
						SPACES:Ceiling		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STAIRS/RAMPS: INTERIOR		
				DS	F0000822225	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	884,479
				DS	F0000799455	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment SITE:PLAYGROUNDS:Safety Surfacing	2015	592,956
				DS	F0000799452	State of Good Repair - System Replacements - Electrical Systems GROUNDING SYSTEM PANEL BOARD SERVICE SWITCH SWITCHBOARD	2015	2,260,775
				DS	F0000792985	State of Good Repair - System Replacements - Heating Plant Upgrade GAS SERVICE:GAS DISTRIBUTION PIPING HEATING HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS	2015	8,011,137
				DS	F0000792994	State of Good Repair - System Replacements - Heating Plant Upgrade Ventilation	2015	1,348,908

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						VENTILATION:EXHAUST FAN VENTILATION:HEATING AND VENTILATING UNIT VENTILATION:METAL DUCTWORK VENTILATION:SUPPLY FAN		
						VENTILATION:UNIT VENTILATOR		
							P.S. 52 Total:	\$22,152,366
31	Staten Island	R053		P.S. 53				
			R053	DSF	0000793004	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	0000799837	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
			R053	DSF	0000816209	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
						GAS SERVICE:GAS DISTRIBUTION PIPING GAS SERVICE:GAS METER ROOM VENT HEATING		
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM HEATING PLANT:FUEL SYSTEMS		
						Other		
				DSF	0000775712	IP Surveillance Camera Installation	2015	425,214
							P.S. 53 Total:	\$695,149
31	Staten Island	R054		P.S. 54				

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000793018	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,039,570
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R054	DS	F0000793020	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			R054	DS	F0000816224	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							P.S. 54 Total:	\$1,176,184
31	Staten Island	R055		P.S. 55				
				DS	F0000799715	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	200,888
			R055	DS	F0000793042	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DS	F0000799838	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
							P.S. 55 Total:	\$315,457
21	Staton Island	D057		D S 57				

31 Staten Island R057 P.S. 57

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSF	0000799877	Safety and Security - Safety and Security - Code Compliance	2017	688,655
			R057	DSF	0000822153	State of Good Repair - System Replacements - Toilets-Students INTERIOR:TOILET ROOMS - STUDENTS	2016	191,062
						Other		
			R057	DSF	0000843808	Classroom Connectivity	2016	332,755
							P.S. 57 Total:	\$1,212,472
31	Staten Island	R058		P.S. 58				
				DSF	0000844733	Educational Enhancements - Educational Enhancements - Accessibility	2018	42,427
				DSF	0000799756	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	63,731
				DSF	0000823581	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							P.S. 58 Total:	\$180,964
31	Staten Island	R060		P.S. 60				
			R060	DSF	0000793094	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2015	1,527,744
							P.S. 60 Total:	\$1,527,744
31	Staten Island	R061		15 61				

31 Staten Island R061 I.S. 61

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DS	F0000799643	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	155,080
				DS	F0000821620	State of Good Repair - System Replacements - Cafeteria / Multipurpose Room Upgrade	2019	533,236
			R061	DS	F0000816314	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							I.S. 61 Total:	\$789,667
31	Staten Island	R069		P.S. 69				
				DS	F0000799644	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	155,057
							P.S. 69 Total:	\$155,057
31	Staten Island	R072		I.S. 72				
				DS	F0000799757	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	89,037
			R072	DS	F0000816367	State of Good Repair - System Replacements - Domestic Piping Waste System DRAIN/WASTE/VENT AND STORM SYSTEM:HOUSE TRAP	2016	94,828

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:INTERIOR FLOOR DRAIN		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE / WASTE PIPING		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:SEWAGE EJECTOR PUMP		
						DRAIN/WASTE/VENT AND STORM SYSTEM:VENT PIPING		
			R072	DSF	0000799871	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,239
			R072	DSF	-0000816353	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	155,366
			R072	DSF	0000816355	State of Good Repair - System Replacements -	2017	159,628
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						INTERIOR: TOILET ROOMS - STUDENTS		
							I.S. 72 Total:	\$534,098
31	Staten Island	R075		I.S. 75				
			R075	DSF	0000799934	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	320,734
				DSF	0000777533	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	73,990

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
				DSI	F0000816378	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
							I.S. 75 Total:	\$469,530
31	Staten Island	R826		P.S. 3 AN	NEX			
				DSI	F0000798340	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	413,948
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent		
							P.S. 3 ANNEX Total:	\$413,948
31	Staten Island	R829		ARTHUR	D. PHILLIPS SO	CHOOL		
			R065	DSI	F0000843902	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	68,316
						GAS SERVICE:Gas Distribution Piping GAS SERVICE:Gas Pressure Booster		
						ARTHUR D. PHIL	LIPS SCHOOL Total:	\$68,316
31	Staten Island	R831		P.S. 74				
				DSI	F0000821889	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System AIR CONDITIONING:CONDENSER WATER PUMP	2015	33,154
						Other		
			R074	DSI	F0000843806	Classroom Connectivity	2016	364,069

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 74 Total:	\$397,223
31	Staten Island	R844		P.S. 36 AN	NNEX			
				DSF	-0000798347	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	155,450
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescen	t	
							P.S. 36 ANNEX Total:	\$155,450
31	Staten Island	R848		P.S. 42 AM	NNEX			
			R042	DSF	-0000793508	State of Good Repair - System Replacements -	2016	368,977
						Toilets-Students		
						FIXTURES:STUDENT:Lavatory/Sink		
						FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal		
						TOILET ROOM - STUDENT:LIGHTING:Lighting		
						Fixture - Fluorescent		
							P.S. 42 ANNEX Total:	\$368,977
31	Staten Island	R861		ELIZABET	TH A. CONNEL	LY CAMPUS		
						Other		
			R861	DSF	-0000843805	Classroom Connectivity	2016	236,923
						ELIZABETH A. CON	NELLY CAMPUS Total:	\$236,923

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
31	Staten Island	R880		P.S. 80 (P	ETR COMPL-B	LDG B)		
				DSI	F0000843991	Technology	2019	2,675
				DSI	F0000843727	Safety and Security - Safety and Security - Code Compliance	2015	40,896
				DSI	F0000770810	State of Good Repair - System Replacements - Auditorium Upgrade	2015	898,351
				DSI	F0000793531	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System AIR CONDITIONING:PACKAGED TERMINAL A/C	2015	131,887
			R080	DSI	F0000838758	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System AIR CONDITIONING:Chilled Water System:Absorption Chiller AIR CONDITIONING:Chilled Water System:Chilled Water Distribution: Piping, Pumps and Auxiliaries AIR CONDITIONING:Chilled Water System:Packaged Air Cooled Chiller AIR CONDITIONING:Condenser Water Piping AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Condenser Water Pump AIR CONDITIONING:Packaged Terminal A/C AIR CONDITIONING:Packaged Terminal A/C AIR CONDITIONING:Return Fan	2018	523,729

P.S. 80 (PETR COMPL-BLDG B) Total: \$1,597,538

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
75R	Staten Island	R025		P.S. 25 AI	NNEX (OLD 4)			
				DSI	F0000792581	State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE	2016	262,892
						SPACE:LIGHTING:Lighting Fixture - Incandescent	INEX (OLD 4) Total:	\$262,892
75R	Staten Island	R040		P.S. 373 (DSI	OLD P40) F0000770084	State of Good Repair - Building Upgrade - Flood Elimination	2015	229,858
				DSI	F0000754447	INTERIOR:STRUCTURAL:FOUNDATION WALLS State of Good Repair - System Replacements - Exterior Masonry	2015	2,336,290
			R373	DSI	F0000816029	EXTERIOR:EXTERIOR WALLS State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628
				ופח	F0000775710	<i>Other</i> IP Surveillance Camera Installation	2015	413,727

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							P.S. 373 (OLD P40) Total:	\$3,139,503
75R	Staten Island	R722		P.S. 722 (0	OTC)			
				DSF	0000777261	Educational Enhancements - Educational Enhancements - Accessibility	2016	1,797,996
			R721	DSF	0000844119	Heating Plant Upgrade HEATING PLANT:Boiler System	2016	1,868,455
				DSF	0000770715	Safety and Security - Safety and Security - Safety Systems EXTERIOR:DOORS:DOOR HARDWARE EXTERIOR:DOORS:DOORS AND FRAMES	2016	988,481
			R721	DSF	0000732118	State of Good Repair - Building Upgrade - Air Conditioning Retrofit	2016	10,942,005
				DSF	0000770703	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	1,855,024
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluoresce CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandes		
			R721	DSF	0000770711	State of Good Repair - System Replacements - Domestic Piping DOMESTIC WATER SYSTEM	2016	1,347,935
			R721	DSF	0000770718	State of Good Repair - System Replacements - Domestic Piping Waste System	2015	1,473,611

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DRAIN/WASTE/VENT AND STORM SYSTEM:SEWAGE / WASTE PIPING		
				DS	F0000770719	State of Good Repair - System Replacements - Domestic Piping Fire System Sprinklers SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER HEAD SPRINKLERS, STANDPIPE, FIRE SYSTEM:SPRINKLER PIPING	2015	1,769,414
			R721	DS	F0000843947	State of Good Repair - System Replacements - Domestic Piping	2016	75,852
				DS	F0000726449	State of Good Repair - System Replacements - Exterior Masonry EXTERIOR:CHIMNEY EXTERIOR:EXTERIOR WALLS	2016	2,057,350
				DS	F0000770710	State of Good Repair - System Replacements - Heating Plant Upgrade HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM	2016	4,663,510
				DS	F0000726448	State of Good Repair - System Replacements - Parapets EXTERIOR:PARAPETS	2016	1,790,287
				DS	F0000770705	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2015	239,581
				DS	F0000770707	State of Good Repair - System Replacements - Windows	2016	2,481,999

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						EXTERIOR:WINDOWS		
							P.S. 722 (OTC) Total:	\$33,351,500
75R	Staten Island	R818		P.S. 37 TR		E		
				DSF	0000800333	System Expansion - New Construction-Additional Capacity - Transportables Interior Spaces	2015	91,487
						P.S. 37	TRANSPORTABLE Total:	\$91,487
75R	Staten Island	R825		P.S. 25 (M		ΓΟ)		
				•	0000799758	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	19,575
						P.S. 25 (MOUNT LORETTO) Total:	\$19,575
75R	Staten Island	R840		P.S. 37 (O	DLD I24X)			
				DSF	0000798492	State of Good Repair - Building Upgrade - Boiler Conversion	2019	4,500,000
						HEATING PLANT:BOILER AUXILIARIES HEATING PLANT:BOILER SYSTEM		
				DSF	0000793471	State of Good Repair - Building Upgrade - Climate Control	2019	1,277,027
						CLIMATE CONTROL SYSTEM		
				DSF	0000793472	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	780,030
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluoresce	nt	

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R037	DS	F0000793476	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						P.S. 37	' (OLD I24X) Total:	\$6,592,320
75R	Staten Island	R843		P.S. 37 M	INISCHOOL (OI	LD P32)		
				DS	F0000798345	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	242,420
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						P.S. 37 MINISCHOO	L (OLD P32) Total:	\$242,420
78R	Staten Island	R435		NEW DO	RP HS (NEW)			
			R440	DS	F0000844153	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2017	1,132,500
				DS	F0000777534	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	339,386
			R440	DS	F0000816406	State of Good Repair - Building Upgrade - Climate Control	2016	123,078
						CLIMATE CONTROL SYSTEM		
				DS	F0000793212	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	157,655
				DS	F0000838464	State of Good Repair - System Replacements - Gymnasium Upgrade INTERIOR:GYMNASIUM:Floor Finish	2018	472,461

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
			R440	DSI	-0000793217	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
						NEW DORF	PHS (NEW) Total:	\$2,260,343
78R	Staten Island	R436		NEW DOF	RP HS AF (NEW	0		
				DSI	-0000801024	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELDS:PLAYING SURFACE	2016	8,880,771
						NEW DORP HS	SAF (NEW) Total:	\$8,880,771
78R	Staten Island	R440			SLAND TECHN F0000798351	IICAL HS State of Good Repair - Building Upgrade - Lighting Fixtures CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent	2016	1,660,412
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
				DSI	-0000793248	State of Good Repair - System Replacements - Auditorium Upgrade INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging	2015	121,621
			R605	DSI	F0000816436	State of Good Repair - System Replacements - Toilets-Students FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS	2017	159,628

District	Baraugh	Building		Sahaal	Droigot #	Description	FY - Construction	Total
District	Borough	ID		School	Project #	Description	Start	Total
						STATEN ISLAND TEC	HNICAL HS Total:	\$1,941,661
78R	Staten Island	R445		PORT RIC	CHMOND HS			
				DS	F0000800120	Educational Enhancements - Educational Enhancements - Accessibility	2015	390,487
			R445	DS	F0000775992	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2015	796,369
				DS	F0000799645	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	165,896
			R445	DSI	F0000821801	State of Good Repair - Rehabilitation of Physical Education Facilities - Playground Redevelopment	2018	2,032,388
			R445	DSI	F0000838507	State of Good Repair - System Replacements - Heating Plant Upgrade Air Conditioning Split System	2018	386,156
						PORT RIC	HMOND HS Total:	\$3,771,296
78R	Staten Island	R446		PORT RIC	CHMOND HS AF			
				DSI	F0000843757	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields ATHLETIC FIELD:Scoreboard ATHLETIC FIELDS:FIXED EQUIPMENT ATHLETIC FIELDS:PLAYING SURFACE ATHLETIC FIELDS:SEATING CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:Lighting:Lighting Fixture - Fluorescent CLIMATE CONTROL SYSTEM	2018	11,566,514

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						DOMESTIC WATER SYSTEM		
						DRAIN/WASTE/VENT AND STORM		
						SYSTEM:Sewage/Waste/Vent Piping		
						EMERGENCY LIGHTING		
						EXIT LIGHT		
						EXTERIOR:AREAWAY		
						EXTERIOR:CHIMNEY		
						EXTERIOR:COPING		
						EXTERIOR: DOORS: DOORS AND FRAMES		
						EXTERIOR:DOORS:LINTELS		
						EXTERIOR:DOORS:TRANSOM/SIDE LIGHT		
						EXTERIOR: EXTERIOR WALLS		
						EXTERIOR:LOUVER		
						EXTERIOR:PARAPETS		
						EXTERIOR:ROOF:Roofing		
						EXTERIOR:STAIRS/RAMPS: EXTERIOR		
						EXTERIOR:WINDOWS		
						FIXTURES:Staff And Other		
						FIXTURES:Student:Lavatory/Sink		
						FIXTURES:Student:Toilet		
						FIXTURES:Student:Urinal		
						GROUNDING SYSTEM		
						HEATING PLANT:Boiler Auxiliaries		
						HEATING PLANT:Boiler System		
						HEATING PLANT: Fuel System		
						HEATING:Radiator/Convector/Fin Tube		
						HEATING:Steam Heating		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Ceiling INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Door(s) INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Floor Finish INTERIOR:CLASSROOMS/CORRIDORS/ADMIN SPACES:Walls INTERIOR:STRUCTURAL:COLUMNS/BEAMS/BEARI NG WALLS INTERIOR:STRUCTURAL:FLOOR STRUCTURE INTERIOR:STRUCTURAL:FLOOR STRUCTURE INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:FOUNDATION WALLS INTERIOR:STRUCTURAL:ROOF STRUCTURE INTERIOR:TOILET ROOMS - STUDENTS MOTOR STARTER/CONTACTOR PANEL BOARD SECURITY:Lighting - Security SITE:Drainage System for Asphalt SITE:Drainage System for Soil SITE:FENCES SITE:IRRIGATION SYSTEM SITE:PAVING:Site Sidewalks & Walkways:Concrete SITE:PAVING:Student Use:Asphalt SITE:PAVING:Student Use:Asphalt SITE:PAVING:Student Use:Pavers SITE:RETAINING WALLS SITE:RETAINING WALLS SITE:STAIRS/RAMPS: EXTERIOR		

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						TELEPHONE SYSTEM		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture - Fluorescent		
						TOILET ROOM - STUDENT:Lighting:Lighting Fixture -		
						Incandescent		
						TRANSFORMER		
						VENTILATION: Exhaust Fan		
						VENTILATION:Metal Ductwork		
						PORT RICH	MOND HS AF Total:	\$11,566,514
78R	Staten Island	R450		CURTIS HS				
				DSFC	0000777535	Safety and Security - Safety and Security - Emergency Lighting and Fire Safety Retrofits	2015	151,742
				DSFC	0000793283	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	149,956
				DSFC	000816488	State of Good Repair - System Replacements - Auditorium Upgrade	2015	27,405
						INTERIOR:AUDITORIUM:Stage:Stage Curtain Rigging INTERIOR:AUDITORIUM:Stage:Stage Curtains		
				DSFC	000816478	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	311,310
							CURTIS HS Total:	\$640,413
78R	Staten Island	R451		CURTIS HS	AF			
			R450	DSF0	0000838534	State of Good Repair - Rehabilitation of Physical Education Facilities - Athletic Fields	2018	116,070

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
							CURTIS HS AF Total:	\$116,070
78R	Staten Island	R455		TOTTENVI	ILLE HS			
				DSF	0000821950	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2016	752,230
				DSF	0000793314	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	4,251,777
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		
			R455	DSF	0000793321	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
			R455	DSF	0000823655	State of Good Repair - System Replacements - Toilets-Students	2016	101,351
						FIXTURES:STUDENT:Lavatory/Sink FIXTURES:STUDENT:Toilet		
						FIXTURES:STUDENT:Urinal INTERIOR:TOILET ROOMS - STUDENTS		
							TTENVILLE HS Total:	\$5,140,621
78R	Staten Island	R460		SUSAN E.	WAGNER HS			
			R460	DSF	0000845613	Educational Enhancements - Educational Enhancements - Room Conversions/Partitioning	2018	2,300,000
			R460	DSF	0000816523	State of Good Repair - Building Upgrade - Elevators and Escalators	2018	343,726

District	Borough	Building ID	Org ID	School	Project #	Description	FY - Construction Start	Total
						CONVEYING:ASH HOIST CONVEYING:ELEVATORS INTERCOM SYSTEM:ELEVATOR		
				DSF	-0000793341	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	279,294
				DSF	-0000799716	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	191,634
				SCA	40000025813	State of Good Repair - System Replacements - Exterior Masonry	2018	15,751,318
			R460	DSF	-0000793350	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	35,263
				DSF	-0000799839	State of Good Repair - System Replacements - Heating Plant Upgrade	2015	79,306
				DSF	-0000793346	State of Good Repair - System Replacements - Parapets EXTERIOR:COPING EXTERIOR:PARAPETS	2018	5,505,663
				DSF	-0000793345	State of Good Repair - System Replacements - Roofs EXTERIOR:ROOFING:Roofing	2018	10,541,793
				DSF	-0000793347	State of Good Repair - System Replacements - Windows	2018	910,491
						EXTERIOR:WINDOWS		
						SUSAN E. V	VAGNER HS Total:	\$35,938,488

78R Staten Island R470

CONCORD HS (OLD 12)

							FY -	
		Building					Construction	
District	Borough	ID	Org ID	School	Project #	Description	Start	Total
				DS	F0000793368	State of Good Repair - Building Upgrade - Lighting Fixtures	2016	573,274
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Fluorescent		
						CLASSROOM/CORRIDOR/ADMINISTRATIVE		
						SPACE:LIGHTING:Lighting Fixture - Incandescent		
						CONCORD	HS (OLD 12) Total:	\$573,274
78R	Staten Island	R600		RALPH	ICKEE VOC HS			
			R600	DS	F0000845617	Educational Enhancements - Educational Enhancements - School Improvement and Restructuring Room Conversions/Partitioning	2018	532,095
				DS	F0000799647	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	117,941
				DS	F0000823582	State of Good Repair - System Replacements - Heating Plant Upgrade	2018	74,806
						RALPH MC	KEE VOC HS Total:	\$724,842
78R	Staten Island	R801		AUX. SEI	RV - ST. GEORG	SE SCHOOL		
				DS	F0000793425	State of Good Repair - Building Upgrade - Lighting Fixtures	2015	248,845
						CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Fluorescent CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE:LIGHTING:Lighting Fixture - Incandescent		

								FY -	
		Building						Construction	
District	Borough	ID	Org ID	School	Project #	Description		Start	Total

AUX. SERV - ST. GEORGE SCHOOL Total: \$248,845